OWNER:	FLEXFLIGHT APS	OPERATOR:	FLEXFLIGHT APS	CAMO:	FLEXFLIGHT APS
ADDRESS:	LUFTHAVNSVEJ 50 ROSKILDE 4000	ADDRESS:	LUFTHAVNSVEJ 50 ROSKILDE 4000	ADDRESS:	LUFTHAVNSVEJ 50 ROSKILDE 4000
OFFICE:		OFFICE:		OFFICE:	
FAX:		FAX:		FAX:	

ANALYST:	ADRIEN LIMMELETTE	+33 1.55.93.47.77 (DIRECT)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU	+33-1.55.93.45.80 (MAIN)	
		WWW.CAMPSYSTEMS.COM	

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT

SERIAL/REGNO: 1761/OY-CBK MODEL: PC-12/47E MANUFACTURER: PILATUS AIRCRAFT LTDX

CERTIFICATION DATE: 04-JAN-2018

LAST ACTUALS:

2406:09	A/C HRS	as of 20-OCT-2026
2723	AFL	as of 20-OCT-2026
793:54	ACH	as of 01-DEC-2025

ENGINE NO. 1

SERIAL/PART: PCE-RY0827/3072955-01 MODEL: PT6A-67P MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 24-NOV-2017

0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:

2406:09	ENG. HRS	as of 20-OCT-2026
2564	ENC	as of 20-OCT-2026

PROPELLER NO. 1

SERIAL/PART: SA259/HC-E5A-3A MODEL: HC-E5A-3A MANUFACTURER: HARTZELL PROPELLER LLC

INSTALLED ON: 14-SEP-2019

500:48 PROP HRS 502 A/C HRS
0 PRC

LAST ACTUALS:

2407:08	PROP HRS	as of 20-OCT-2026

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
00-00/121	AIRCRAFT - AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED							Service ATA:00
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
00-00/122	AIRCRAFT - CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH							Service ATA:00
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
00-00/481	AIRCRAFT-CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION							Service ATA:00
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E072-180528 S	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1							Service ATA:00
	MOS/MSC	14-Dec-18	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2							Service ATA:00
	MOS/MSC	14-Dec-18	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0							Service ATA:00
	MOS/MSC	14-Dec-18	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0							Service ATA:00
	MOS/MSC	02-May-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28							Service ATA:00
	MOS/MSC	03-Sep-19	-					REQUIREMENT CHANGE FORMS
	HRS	496:30						
	ENC	440						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF 00PROC. REF: RCF 00								
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF 00PROC. REF: RCF 00								
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-210412	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 53.0							Service ATA:00
	MOS/MSC	10-Apr-21	-					REQUIREMENT CHANGE FORMS
	HRS	649:48						
	ENC	593						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-210806	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 27							Service ATA:00
	MOS/MSC	28-Jul-21	-					REQUIREMENT CHANGE FORMS
	HRS	714:24						
	ENC	656						
PROC. REF: RCF E072PROC. REF: RCF E072								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-210913	NO. 1 ENGINE - REVIEW SB PT6A-72-14603 REV 30							Service ATA:00
	MOS/MSC	09-Sep-21	-					REQUIREMENT CHANGE FORMS
	HRS	753:06						
	ENC	696						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-211011	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 54.0							Service ATA:00
	MOS/MSC	01-Nov-21	-					REQUIREMENT CHANGE FORMS
	HRS	776:54						
	ENC	740						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-221010	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 56.0							Service ATA:00
	MOS/MSC	24-Nov-22	-					REQUIREMENT CHANGE FORMS
	HRS	1366:06						
	ENC	1829						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-230410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 57.0							Service ATA:00
	MOS/MSC	24-Apr-23	-					REQUIREMENT CHANGE FORMS
	HRS	1458:58						
	ENC	1901						
PROC. REF: RCF E072PROC. REF: RCF E072								
E072-231009	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 58.0							Service ATA:00
	MOS/MSC	09-Nov-23	-					REQUIREMENT CHANGE FORMS
	HRS	1639:26						
	ENC	2003						
PROC. REF: RCF E072PROC. REF: RCF E072								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-240408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 59.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072	PROC. REF: RCF E072							
E072-241007	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 60.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072	PROC. REF: RCF E072							
E072-251006	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 62.0							Service ATA:00
	MOS/MSC	24-Nov-25	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072	PROC. REF: RCF E072							
E072-260406	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM-3038336 REV 63							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E072	PROC. REF: RCF E072							
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04							Service ATA:00
	MOS/MSC	04-Jan-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: RCF P47E	PROC. REF: RCF P47E							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19							Service ATA:00
	MOS/MSC	14-Dec-18	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05							Service ATA:00
	MOS/MSC	14-Dec-18	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20							Service ATA:00
	MOS/MSC	04-Jan-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21							Service ATA:00
	MOS/MSC	12-Jun-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22							Service ATA:00
	MOS/MSC	04-Jan-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-210716	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 25							Service ATA:00
	MOS/MSC	13-Aug-21	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-220520	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 28							Service ATA:00
	MOS/MSC	09-Jun-22	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-220829	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 29							Service ATA:00
	MOS/MSC	21-Sep-22	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-230116	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 30							Service ATA:00
	MOS/MSC	18-Sep-23	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-230607	REVIEW PC-12/47 AMM TEMPLATE CORRECTIONS							Service ATA:00
	MOS/MSC	09-Jun-23	-					REQUIREMENT CHANGE FORMS
	HRS	1474:50						
	AFL	2071						
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-231002	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 31							Service ATA:00
	MOS/MSC	09-Nov-23	-					REQUIREMENT CHANGE FORMS
	HRS	1639:26						
	AFL	2164						
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-240125	REVIEW PC-12/47 AMM TEMPLATE CORRECTIONS							Service ATA:00
	MOS/MSC	EFF	-					
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-240207	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 32							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-240305	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 32 (TR 10-02)							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-240404	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 32 (TR 57-02)							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-260610	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 36 (TR 05-06)							Service ATA:00
	MOS/MSC	06-Jul-26	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF P47EPROC. REF: RCF P47E								
P47E-260831	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 37							Service ATA:00
	MOS/MSC	04-Jan-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
PROC. REF: RCF P47EPROC. REF: RCF P47E								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-191101	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM NO. 147 REV 15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-200501	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 16							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 33							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-200901	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 34							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-200901-1	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-210304	NO. 1 PROPELLER - REVIEW SL HC-SL-61-61Y REV 13							Service ATA:00
	MOS/MSC	10-Apr-21	-					REQUIREMENT CHANGE FORMS
	HRS	648:36						
PE5A-210401	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 TR-011							Service ATA:00
	MOS/MSC	10-Apr-21	-					REQUIREMENT CHANGE FORMS
	HRS	648:36						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-210601	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 36							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-210707	NO. 1 PROPELLER - REVIEW HC-SL-61-61Y REV 14							Service ATA:00
	MOS/MSC	28-Jul-21	-					REQUIREMENT CHANGE FORMS
	HRS	713:12						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-220601	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER ICE PROTECTION SYSTEM MANUAL NO. 180, REVISION 38							Service ATA:00
	MOS/MSC	18-Jul-22	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-220727	NO. 1 PROPELLER - REVIEW AUDIT SUMMARY CHANGE FORM FOR HARTZELL PROPELLER TASKS AND DESCRIPTIONS CHANGES							Service ATA:00
	MOS/MSC		-					AUDIT SUMMARY CHANGE FORM
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-220901	NO. 1 PROPELLER - REVIEW AUDIT SUMMARY CHANGE FORM FOR ADDITION OF RECOMMENDED APPLICATION OF CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service ATA:00
	MOS/MSC	21-Sep-22	-					AUDIT SUMMARY CHANGE FORM
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-221101	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER OWNER'S MANUAL NO. 147, REVISION 19							Service ATA:00
	MOS/MSC	24-Nov-22	-					REQUIREMENT CHANGE FORMS
	HRS	1364:54						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-221201	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL NO. 180, REVISION 39							Service ATA:00
	MOS/MSC	17-Dec-22	-					REQUIREMENT CHANGE FORMS
	HRS	1378:40						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-230501A	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL 180 (30-61-80), TEMPORARY REVISION NO. 012, DATED MAY 2023							Service ATA:00
	MOS/MSC	26-May-23	-					REQUIREMENT CHANGE FORMS
	HRS	1469:14						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-230501B	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL 180 (30-61-80), TEMPORARY REVISION NO. 013, DATED MAY 2023							Service ATA:00
	MOS/MSC	26-May-23	-					REQUIREMENT CHANGE FORMS
	HRS	1469:14						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-230701	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER OWNER'S MANUAL NO. 147, REVISION 20							Service ATA:00
	MOS/MSC	30-Jul-23	-					REQUIREMENT CHANGE FORMS
	HRS	1563:53						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-230901	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL NO. 180, REVISION 41							Service ATA:00
	MOS/MSC	25-Sep-23	-					REQUIREMENT CHANGE FORMS
	HRS	1624:57						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-231201	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL, REVISION 42							Service ATA:00
	MOS/MSC	20-Dec-23	-					REQUIREMENT CHANGE FORMS
	HRS	1660:29						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-231213	NO. 1 PROPELLER - REVIEW HARTZELL SL - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS (SL) HC-SL-61-61Y, REV 15							Service ATA:00
	MOS/MSC	20-Dec-23	-					REQUIREMENT CHANGE FORMS
	HRS	1660:29						
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-240201	NO. 1 PROPELLER - REVIEW HARTZEL PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 43							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-240501	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC. HC-E5A-3A PROPELLER OWNER'S MANUAL (POM) 147 REV 21							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-240918	NO. 1 PROPELLER - REVIEW HC-E5A-3A HARTZELL SERVICE LETTER (SL) HC-SL-61-61Y REV 16							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-241001	NO. 1 PROPELLER - REVIEW HARTZEL PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 44							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-241001B	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC. HC-E5A-3A PROPELLER OWNER'S MANUAL (POM) 147 REV 22							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-250401	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 45							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-250813	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC SERVICE LETTER (SL) HC-SL-61-61Y REV 17							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-250901B	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 46							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-250901C	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC PROPELLER OWNER'S MANUAL (POM) 147 REV 23							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
PE5A-251101	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 47							Service ATA:00
	MOS/MSC	24-Nov-25	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-260201	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 47 (TR 015)							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-260513	NO. 1 PROPELLER - HARTZELL PROPELLER LLC SERVICE LETTER (SL) HC-SL-61-61Y REV R18							Service ATA:00
	MOS/MSC	09-Jun-26	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-260601	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC - PROPELLER OWNER'S MANUAL (POM) NO. 147 REV 24 DATED 01-JUN-2026							Service ATA:00
	MOS/MSC	06-Jul-26	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								
PE5A-260901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER LLC - ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 48							Service ATA:00
	MOS/MSC	05-Oct-26	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF PE5APROC. REF: RCF PE5A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 01 - LIMITATIONS								
FXT-5 FIRST AID KIT U		CHECK VALIDITY OF FIRST AID KIT						Service ATA:01
	MOS	11-Mar-25	12		30-Apr-27 (M)		186 d	CUSTOMER OPERATIONS REQUIREMENT
	HRS	1979:29						
	AFL	2393						
FXT-9 U		PERFORM A READOUT OF THE AIR CONDITIONNING HORAMETER						Service ATA:01
	MOS	01-Dec-25						
	HRS	2149:16	300		2449:16		43:07	
	AFL	2506						
								WO#: FLEX26-1761-18
ATA 04 - LIMITATIONS								
040001		AIRCRAFT LIMIT OF VALIDITY						Component ATA:04
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000		22593:51	
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
040005		AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY						Component ATA:04
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000		22593:51	
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
040005		AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY						Component ATA:04
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000		22593:51	
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-16	UNSCHEDULED INSPECTION - CHECK AFTER A JET BLAST							Service ATA:05
	MOS/MSC	04-Jan-18	A/R					
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-05-50-16-00A-282A-APROC. REF: AMM 12-B-05-50-16-00A-282A-A								
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)							Service ATA:05
	MOS	04-Jan-18						
	HRS	0	25000		25000		22593:51	
	AFL	0	30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-05-10-30-00A-280A-APROC. REF: AMM 12-B-05-10-30-00A-280A-A								
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION							Service ATA:05
	MOS	04-Jan-18						
	HRS	0	25000		25000		22593:51	
	AFL	0	30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-20-40-00-00A-901A-A, AMM 12-B-20-40-00-00A-040A-APROC. REF: AMM 12-B-20-40-00-00A-901A-A, AMM 12-B-20-40-00-00A-040A-A								
05200A	JOB SET UP / CLOSE UP PACKAGE							Package ATA:05
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
								PKG:15
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-05-20-00-00A-913A-APROC. REF: AMM 12-B-05-20-00-00A-913A-A								
05402A	300 HOUR OR 12 MONTHS INSPECTION							Package ATA:05
	MOS	01-Dec-25	12 (+1m/-1m)	Adj -44d	18-Oct-26	18-Nov-26	TOL (+23 d)	
	HRS	2149:16	300 (+30/-30)		2449:16	2479:16	43:07 (+30)	
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-05-40-01-02A-000B-APROC. REF: AMM 12-B-05-40-01-02A-000B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05404A	600 HOUR OR 12 MONTHS INSPECTION							Package ATA:05
	MOS	01-Dec-25	12 (+1m/-1m)	Adj -40d	22-Oct-26	22-Nov-26	TOL (+27 d)	
	HRS	2149:16	600 (+60/-60)		2749:16	2809:16	343:07 (+60)	
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-05-40-01-04A-000B-APROC. REF: AMM 12-B-05-40-01-04A-000B-A								
05405A	1200 HOUR OR 12 MONTH INSPECTION							Package ATA:05
	MOS	01-Dec-25	12 (+1m/-1m)	Adj -40d	22-Oct-26	22-Nov-26	TOL (+27 d)	
	HRS	2149:16	1200 (+120/-120)		3349:16	3469:16	943:07 (+120)	
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-05-40-01-05A-000B-APROC. REF: AMM 12-B-05-40-01-05A-000B-A								
05406A	2400 HOUR OR 24 MONTHS INSPECTION							Package ATA:05
	MOS	01-Dec-25	24 (+1m/-1m)	Adj -40d	22-Oct-27	22-Nov-27	361 d (+31)	
	HRS	2149:16	2400 (+60/-60)		4549:16	4609:16	2143:07 (+60)	
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-05-40-01-06A-000B-APROC. REF: AMM 12-B-05-40-01-06A-000B-A								
05407A U	2000 HOUR - 24 MONTHS - 3200 CYCLES INSPECTION							Package ATA:05
	MOS	01-Dec-25	24		01-Dec-27		401 d	
	HRS	2149:16	2000		4149:16		1743:07	
	AFL	2506	3200		5706		2983	
								PKG:22
05409A U	LANDING GEAR 72M INSPECTION							Package ATA:05
	MOS	30-Nov-23	72		30-Nov-29		1131 d	
	HRS	1639:26						
	AFL	2164						
								PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057010	NO. 1 ENGINE - MINOR INSPECTION							Package ATA:05
	MOS	01-Dec-25	12		01-Dec-26		36 d	
	HRS	2149:16	300 (+10%/-10%)		(2449:16) 2449:16	2479:16	43:07 (+30)	
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 72-00-00, EMM 72-00-00PROC. REF: EMM 72-00-00, EMM 72-00-00								
057011E U	NO. 1 ENGINE - 400H INSPECTION							Package ATA:05
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)	Adj 18:53	(2439:26) 2439:26	2479:26	33:17 (+40)	
	ENC	2259						
								PKG:3 WO#: FLEX26-1761-18
FXT-4 U	DOWNLOAD ECTM DATA AND SEND FOR CAMP TREND							Service ATA:05
	DAYS	10-Sep-26	30		10-Oct-26		OVD	
	HRS	2369:41	50		2419:41		13:32	
	AFL	2703						
								WO#: FLEX26-1761-18
FXT-5 U	INSPECT AND REFURBISH FIRST AID KIT IAW CAT.IDE.A.220 REPLACE ALL CONTENT EXPIRING WITHIN 12 MTH FROM CRS DATE.PUT NEW SEAL ON FIRST AID KIT.RECORD NEW EXPIRATION DATE ON TASKCARD. (EASA)							Service ATA:05
	MOS	04-Mar-26	12		04-Mar-27		129 d	
	HRS	2220:17						
	AFL	2568						
FXT-6 U	PERFORM AIRWORTHINESS REVIEW INSPECTION AND RECOMMANDATION (ARC)							Service ATA:05
	MOS	01-Dec-25	36		04-Jan-29 (M)		801 d	AIRWORTHINESS
	HRS	2149:16						
	AFL	2506						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
FXT-7 U	PERFORM 1ST EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE							Service ATA:05
	MOS	01-Dec-25	36		04-Jan-27 (M)		70 d	AIRWORTHINESS
	HRS	2149:16						
	AFL							
FXT-8 U	PERFORM 2ND EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE							Service ATA:05
	MOS	06-Dec-24	36		04-Jan-28 (M)		435 d	
	HRS	1909						
	AFL							
ATA 06 - DIMENSIONS AND AREAS								
06-00/578 S	ACCESS PANEL, WING: 51LB, 51JB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB,62SB, 62TB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/579 S	ACCESS PANEL, WING: 51LB, 51JB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB,62SB, 62TB - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/582 S	ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/583 S	ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/590 S	ACCESS PANEL, ENGINE: 11BR,21QZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/591 S	ACCESS PANEL, ENGINE: 11BR,21QZ - INSTALL							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/592 S	ACCESS PANEL, ENGINE: 42AT - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/593 S	ACCESS PANEL, ENGINE: 42AT - INSTALL							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 06 - DIMENSIONS AND AREAS

06-00/594 S	ACCESS PANEL, FUSELAGE: 11BL, 21PZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/595 S	ACCESS PANEL, FUSELAGE: 11BL, 21PZ - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/596 S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - OPEN OR REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/597 S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - CLOSE OR INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/598 S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/599 S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/602 S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/603 S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	01-Dec-25						
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/604 S	ACCESS PANEL, FUSELAGE: 11AL,12EL,21QZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 06 - DIMENSIONS AND AREAS

06-00/605 S	ACCESS PANEL, FUSELAGE: 11AL, 12EL,21QZ - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						

PKG:19
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A

06-00/606 S	ACCESS PANEL, WING: 52NB, 52OB, 62NB, 62OB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						

PKG:19
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A

06-00/607 S	ACCESS PANEL, WING: 52NB, 52OB, 62NB, 62OB - INSTALL							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						

PKG:19
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A

06-00/608 S	ACCESS PANEL,FUSELAGE: 11AL, 11AR, 11BR, 11BL, 11BZ, 11DZ, 12AL, 12AR, 12AB, 12AZ, 12BL, 12BR, 12BZ, 12CZ, 12DZ, 12EL, 12EZ, 12FZ, 12GZ, 12HZ, 12IZ, 12JZ, 12KZ, 12LZ, 12MZ, 21GZ, 21HZ,21JZ, 21QZ, 22PZ, 22TZ, 22UZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR							Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/609 S		ACCESS PANEL,FUSELAGE: 11AL, 11AR, 11BR, 11BL, 11BZ, 11DZ, 12AL, 12AR, 12AB, 12AZ, 12BL, 12BR, 12BZ, 12CZ, 12DZ, 12EL, 12EZ, 12FZ, 12GZ, 12HZ, 12IZ, 12JZ, 12KZ, 12LZ, 12MZ, 21GZ, 21HZ,21JZ, 21QZ, 22PZ, 22TZ, 22UZ - CLOSE OR INSTALL					Service	ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/610 S		ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - OPEN OR REMOVE AND EXAMINE					Service	ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/611 S		ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - CLOSE OR INSTALL					Service	ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/612 S		ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE					Service	ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/613 S		ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL						Service ATA:06
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/614 S		ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, , 12EL, 12ER, 12CZ, 12EZ, 12FZ, 21JZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR						Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/615 S		ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, , 12EL, 12ER, 12CZ, 12EZ, 12FZ, 21JZ - CLOSE AND INSTALL						Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/616 S		ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - OPEN OR REMOVE AND EXAMINE						Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/617 S		ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - INSTALL						Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/618 S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/619 S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/620 S	ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - REMOVE AND EXAMINE							Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								
06-00/621 S	ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - INSTALL							Service ATA:06
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-06-20-00-00A-040A-APROC. REF: AMM 12-B-06-20-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 07 - LIFTING AND SHORING								
07-10/160		AIRCRAFT - LOWER TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND						Service ATA:07
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-07-10-00-00A-901A-APROC. REF: AMM 12-B-07-10-00-00A-901A-A								
07-10/161		AIRCRAFT - LIFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND						Service ATA:07
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-07-10-00-00A-901A-APROC. REF: AMM 12-B-07-10-00-00A-901A-A								
ATA 08 - LEVELING AND WEIGHING								
080000		WEIGHT CHECK AIRCRAFT						Service ATA:08
	MOS	24-Apr-25	48		24-Apr-29		911 d	
	HRS	1988:40						
WC#: 08.005	AFL	2397						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10/428 S		EXTERNAL PROTECTIVE COVERS - EXAMINE. REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						Service ATA:10
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 11 - PLACARDS AND MARKINGS								
11-00/220 S		PLACARDS AND MARKINGS - EXAMINE AND ATTACH NEW PLACARDS IF NECESSARY						Service ATA:11
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-11-00-00-00A-040A-A, AMM 12-B-11-00-00-00A-901A-A, AMM 12-B-11-20-00-00A-040A-A, AMM 12-B-11-20-00-00A-901A-A, AMM 12-B-11-30-00-00A-040A-APROC. REF: AMM 12-B-11-00-00-00A-040A-A, AMM 12-B-11-00-00-00A-901A-A, AMM 12-B-11-20-00-00A-040A-A, AMM 12-B-11-20-00-00A-901A-A, AMM 12-B-11-30-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 11 - PLACARDS AND MARKINGS

ATA 12 - SERVICING

12-20/124 S	AIRCRAFT - WASH THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS AS REQUIRED TO PERFORM THE INSPECTION							Service ATA:12
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						

PKG:15 ,17,19,20,21
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-12-20-01-00A-902A-A, AMM 12-B-12-20-01-01A-902A-APROC. REF: AMM 12-B-12-20-01-00A-902A-A, AMM 12-B-12-20-01-01A-902A-A

12-20/125 S	WINDSHIELDS AND WINDOWS - CLEAN							Service ATA:12
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						

PKG:15 ,17,19,20,21
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-12-20-02-00A-902A-APROC. REF: AMM 12-B-12-20-02-00A-902A-A

12-20/126 S	COCKPIT AND CABIN - CLEAN							Service ATA:12
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						

PKG:15 ,17,19,20,21
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-12-20-03-00A-902A-APROC. REF: AMM 12-B-12-20-03-00A-902A-A

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
00-00/45A S	AIRCRAFT - DO THE CORROSION AND CORROSION PROTECTION INSPECTIONS (INTERNAL)							Service ATA:20
	MOS	01-Dec-25	12 (+1m/-1m)					
	HRS	2149:16						
WC#: 20.010	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-20-40-00-00A-901A-APROC. REF: AMM 12-B-20-40-00-00A-901A-A								
00-00/45B	AIRCRAFT - DO THE CORROSION AND CORROSION PROTECTION INSPECTIONS (EXTERNAL)							Service ATA:20
	MOS	21-Apr-26	6 (+10%/-10%)	Adj 3d	24-Oct-26	11-Nov-26	TOL (+16 d)	
	HRS	2255:08						
WC#: 20.011	AFL	2603						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-20-40-00-00A-901A-APROC. REF: AMM 12-B-20-40-00-00A-901A-A								
ATA 21 - AIR CONDITIONING								
21-20/221 S	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE							Service ATA:21
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-20/317 S	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK							Service ATA:21
	MOS	01-Dec-25	12 (+10%/-10%)					AIRWORTHINESS
	HRS	2149:16	3000					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-30/314 S	CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE - CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN							Service ATA:21
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
WC#: 21.030	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-21-30-02-00A-250A-APROC. REF: AMM 12-B-21-30-02-00A-250A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30/46	CABIN POSITIVE PRESSURE RELIEF 1001-1719 - FUNCTIONAL TEST							Service ATA:21
	MOS/MSC	05-Dec-19	N/A					
	HRS	539:30						
WC#: 21.040	AFL	482						
PROC. REF: AMM 12-B-21-30-00-00A-903A-APROC. REF: AMM 12-B-21-30-00-00A-903A-A								
21-30/463	CABIN PRESSURIZATION DUMP CONTROL MSN 1720-9999 - OPERATIONAL TEST							Service ATA:21
	MOS	01-Dec-25	12 (+10%/-10%)	Adj -40d	22-Oct-26	28-Nov-26	TOL (+33 d)	
	HRS	2149:16	600		2749:16		343:07	
	AFL	2506						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-30-00-00A-903B-APROC. REF: AMM 12-B-21-30-00-00A-903B-A								
21-30/464	CABIN PRESSURIZATION MANUAL CONTROL MSN 1720-9999 - OPERATIONAL TEST							Service ATA:21
	MOS	01-Dec-25	12 (+10%/-10%)	Adj -40d	22-Oct-26	28-Nov-26	TOL (+33 d)	
	HRS	2149:16	600		2749:16		343:07	
	AFL	2506						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-30-00-00A-903B-APROC. REF: AMM 12-B-21-30-00-00A-903B-A								
21-30/465	CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE MSN 1720-9999 - FUNCTIONAL TEST							Service ATA:21
	MOS	01-Dec-25	48 (+10%/-10%)	Adj -156d	28-Jun-29	21-Nov-29	976 d (+146)	
	HRS	2149:16	4800		6949:16		4543:07	
	AFL	2506						
PROC. REF: AMM 12-B-21-30-00-00A-903B-APROC. REF: AMM 12-B-21-30-00-00A-903B-A								
21-30/467	CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE MSN 1720-9999 - EXAMINE							Service ATA:21
	MOS	01-Dec-25	48 (+10%/-10%)	Adj 34d	04-Jan-30	28-May-30	1166 d (+144)	
	HRS	2149:16	4800 (+10%/-10%)		6949:16	7429:16	4543:07 (+480)	
	AFL	2506						
PROC. REF: AMM 12-B-21-30-05-00A-310A-APROC. REF: AMM 12-B-21-30-05-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30/468	CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION MSN 1720-9999 - FUNCTIONAL TEST							Service ATA:21
	MOS	01-Dec-25	48		01-Dec-29		1132 d	
	HRS	2149:16	4800		6949:16		4543:07	
	AFL	2506						
PROC. REF: AMM 12-B-21-30-00-00A-903B-APROC. REF: AMM 12-B-21-30-00-00A-903B-A								
21-30/469	CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING MSN 1720-9999 - FUNCTIONAL TEST							Service ATA:21
	MOS	01-Dec-25	48		01-Dec-29		1132 d	
	HRS	2149:16	4800		6949:16		4543:07	
	AFL	2506						
PROC. REF: AMM 12-B-21-30-00-00A-903B-APROC. REF: AMM 12-B-21-30-00-00A-903B-A								
21-30/667	OUTFLOW VALVE MSN 1720-2476 OVERHAUL							Service ATA:21
	MOS	EBT					NEW REQMT	OVERHAUL
	HRS	EBT	4800 (+10%/-10%)		4800 *	5280		
	AFL							
	ACH							
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
21-30/668	OUTFLOW VALVE CONTROLLER MSN 1720-2476 - OVERHAUL							Service ATA:21
	MOS	EBT					NEW REQMT	OVERHAUL
	HRS	EBT	4800 (+10%/-10%)		4800 *	5280		
	AFL							
	ACH							
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
21-40/128	FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH - OPERATIONAL TEST							Service ATA:21
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-21-43-00-00A-903A-APROC. REF: AMM 12-B-21-43-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-40/330 S	CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH - OPERATIONAL TEST							Service ATA:21
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
WC#: 21.140	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-APROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-A								
21-40/331 S	UNDERFLOOR HEATER THERMAL PROTECTION SWITCH - FUNCTIONAL TEST							Service ATA:21
PN:9696781507	MOS	01-Dec-25	12 (+10%/-10%)					
SN:587913	HRS	2149:16	1200 (+10%/-10%)					
WC#: 21.150	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-APROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-A								
21-40/50 S	WATER SEPARATOR CONDENSER - CLEAN							Service ATA:21
PN:PN	MOS	01-Dec-25	12 (+10%/-10%)					
SN:UNKNOWN	HRS	2149:16	1200 (+10%/-10%)					
WC#: 21.080	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-40-03-00A-250A-APROC. REF: AMM 12-B-21-40-03-00A-250A-A								
21-40/51	OVERTEMPERATURE SWITCH - FUNCTIONAL TEST							Service ATA:21
PN:9738132216	MOS	17-Jan-23	60 (+10%/-10%)	Adj 7d	24-Jan-28	24-Jul-28	455 d (+182)	
SN:1177	HRS	1394:09	4800 (+10%/-10%)		6194:09	6674:09	3788 (+480)	
WC#: 21.130	AFL	2020						
PROC. REF: AMM 12-B-21-40-06-00A-903A-APROC. REF: AMM 12-B-21-40-06-00A-903A-A								
21-40/52	DUCT OVERTEMPERATURE SWITCH - FUNCTIONAL TEST							Service ATA:21
PN:9738132214	MOS	17-Jan-23	60 (+10%/-10%)	Adj 7d	24-Jan-28	24-Jul-28	455 d (+182)	
SN:1108	HRS	1394:09	4800 (+10%/-10%)		6194:09	6674:09	3788 (+480)	
WC#: 21.120	AFL	2020						
PROC. REF: AMM 12-B-21-60-05-00A-903A-APROC. REF: AMM 12-B-21-60-05-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-40/55 S		COLD AIR UNIT - ADD OIL						Service ATA:21
	MOS	01-Dec-25						
	HRS	2149:16	600 (+10%/-10%)					
WC#: 21.060	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-40-02-00A-902A-APROC. REF: AMM 12-B-21-40-02-00A-902A-A								
21-40/56 S		HEAT EXCHANGER MATRIX - INSPECT/CHECK						Service ATA:21
	MOS	01-Dec-25						
	HRS	2149:16	600 (+10%/-10%)					
WC#: 21.070	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-40-02-00A-313A-APROC. REF: AMM 12-B-21-40-02-00A-313A-A								
21-50-01-CMM U S		EVAPORATOR MODULE ASSY AIR FILTERS PN 959.90.22.19 REPLACEMENT - POS LH - RH - CTR						Service ATA:21
	MOS	01-Dec-25						
	HRS	2149:16	300					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
21-50/223 S		VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) - EXAMINE						Service ATA:21
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-50/433 S		VAPOR CYCLE COMPRESSOR/CONDENSER MODULE (INCLUDIG MOTOR) (IF INSTALLED) - CLEAN						Service ATA:21
PN:9599022140	MOS	01-Dec-25	12 (+10%/-10%)					
SN:2044	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-50/461 S	VAPOR CYCLE COMPRESSOR MOTOR (CCM P/N 959.90.22.140) (IF INSTALLED) - INSPECT/CHECK							Service ATA:21
PN:9599022140	MOS	01-Dec-25						
SN:2044	HRS	2149:16						
	AFL	2506						
	ACH	793:54	600 (+10%/-10%)					
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-50-03-00A-313A-APROC. REF: AMM 12-B-21-50-03-00A-313A-A								
21-50/462 S	VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CCM P/N 959.90.22.140) (IF INSTALLED) - CHECK FOR TENSION							Service ATA:21
PN:9599022140	MOS	01-Dec-25	12					
SN:2044	HRS	2149:16	600					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-21-50-01-00A-903A-APROC. REF: AMM 12-B-21-50-01-00A-903A-A								
210005	OVERPRESSURE SWITCH							Component ATA:21
PN:9738115105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1573	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-40-07-00A-920A-APROC. REF: AMM 12-B-21-40-07-00A-920A-A								
210010	REFRIGERATION PACK							Component ATA:21
PN:9599020111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2232	HRS	0		TSN 0				
WC#: 21.255	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-40-02-00A-313A-APROC. REF: AMM 12-B-21-40-02-00A-313A-A								
210015	WATER INJECTOR							Component ATA:21
PN:9599020141	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2205	HRS	0		TSN 0				
WC#: 21.370	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210020	DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4962	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-60-04-00A-920A-APROC. REF: AMM 12-B-21-60-04-00A-920A-A								
210025	PRIM SHUT OFF VALVE							Component ATA:21
PN:9599020132	MOS/MSC	24-Apr-25	O/C					
SN:2138	HRS	1988:40						
WC#: 21.290	AFL	2397						
PROC. REF: AMM 12-B-21-40-05-00A-920A-APROC. REF: AMM 12-B-21-40-05-00A-920A-A								
210030	HP SHUT OFF VALVE							Component ATA:21
PN:9599020131	MOS/MSC	24-Apr-25	O/C	TSN 87				
SN:2218	HRS	1988:40		TSN 1988:40				
WC#: 21.280	AFL	2397		TSN 2397				
PROC. REF: AMM 12-B-21-40-04-00A-920A-APROC. REF: AMM 12-B-21-40-04-00A-920A-A								
210035	WATER SEPARATOR ASSY							Component ATA:21
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.220	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-21-40-03-00A-920A-APROC. REF: AMM 12-B-21-40-03-00A-920A-A								
210040	TEMP CONTROL VALVE							Component ATA:21
PN:9599020136	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2217	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-60-02-00A-920A-APROC. REF: AMM 12-B-21-60-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE							Component ATA:21
PN:9599022140	MOS/MSC	01-Dec-25	O/C	TSN 95				
SN:2044	HRS	2149:16		TSN 2149:16				
WC#: 21.380	AFL	2506		TSN 2506				
PROC. REF: AMM 12-B-21-50-01-00A-920A-APROC. REF: AMM 12-B-21-50-01-00A-920A-A								
210046	VAPOR CYCLE COMPRESSOR MOTOR							Component ATA:21
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-21-50-01-00A-920A-APROC. REF: AMM 12-B-21-50-01-00A-920A-A								
210050	CENTER EVAPORATOR MODULE ASSY							Component ATA:21
PN:9599022121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1103	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210055	RIGHT SIDE EVAPORATOR MODULE							Component ATA:21
PN:9599022119	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1267	HRS	0		TSN 0				
WC#: 21.210	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210060	CABIN PRESSURE OUTFLOW VALVE							Component ATA:21
PN:9599091125	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:65053598-00071	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-30-03-00A-920A-APROC. REF: AMM 12-B-21-30-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210065	CABIN PRESSURE RELIEVE VALVE							Component ATA:21
PN:9599091132	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:77-F0774	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210090	OUTFLOW VALVE CONTROLLER							Component ATA:21
PN:9599091147	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:65000052-00058	HRS	0		TSN 0				
WC#: 21.430	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-30-03-00A-920A-A, AMM 12-B-21-30-03-00A-920B-APROC. REF: AMM 12-B-21-30-03-00A-920A-A, AMM 12-B-21-30-03-00A-920B-A								
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER							Component ATA:21
PN:9696781507	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:587913	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-40-01-00A-920A-APROC. REF: AMM 12-B-21-40-01-00A-920A-A								
210135	LEFT SIDE EVAPORATOR MODULE ASSY							Component ATA:21
PN:9599022118	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1214	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210145	CABIN (REAR) ELECTRIC HEATER							Component ATA:21
PN:9696781507	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:587920	HRS	0		TSN 0				
WC#: 21.230	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-40-15-00A-920A-APROC. REF: AMM 12-B-21-40-15-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210170	OVERPRESSURE SWITCH							Component ATA:21
PN:9738115106	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1614	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-40-07-00A-920A-APROC. REF: AMM 12-B-21-40-07-00A-920A-A								
210175	FLOW CONTROL VALVE ACTUATOR							Component ATA:21
PN:9599020160	MOS/MSC	24-Mar-25	O/C	TSN 86				
SN:1816	HRS	1988:17		TSN 1988:17				
WC#: 21.520	AFL	2396		TSN 2396				
PROC. REF: AMM 12-B-21-60-03-01A-920A-APROC. REF: AMM 12-B-21-60-03-01A-920A-A								
210185	INTEG. ECS CONTROL UNIT							Component ATA:21
PN:9599020129	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:812	HRS	0		TSN 0				
WC#: 21.540	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-60-01-00A-920A-APROC. REF: AMM 12-B-21-60-01-00A-920A-A								
210190	FLOOR DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4971	HRS	0		TSN 0				
WC#: 21.550	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-60-04-00A-920A-APROC. REF: AMM 12-B-21-60-04-00A-920A-A								
210195	MIDDLE CONSOLE DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4970	HRS	0		TSN 0				
WC#: 21.560	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210200	FIREWALL 1415-3 SHUT OFF VALVE							Component ATA:21
PN:9633011005	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1001	HRS	0		TSN 0				
WC#: 21.570	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-21-20-01-00A-920A-APROC. REF: AMM 12-B-21-20-01-00A-920A-A								
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH							Component ATA:21
PN:9738132216	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1177	HRS	0		TSN 0				
WC#: 21.580	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210210	OVERTEMP. CONDAIR 1173T08 SWITCH							Component ATA:21
PN:9738132214	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1108	HRS	0		TSN 0				
WC#: 21.590	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210215	DUAL FLAPPER 1.5 IN. CHECK VALVE							Component ATA:21
PN:9633011105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1653B	HRS	0		TSN 0				
WC#: 21.490	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210220	LH DUAL FLAPPER 2.5 IN. CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2940B	HRS	0		TSN 0				
WC#: 21.500	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210225	RH DUAL FLAPPER 2.5 IN. CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2948B	HRS	0		TSN 0				
WC#: 21.500	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210230	DUAL FLAPPER 2.5 IN. SPANT 15 CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2949B	HRS	0		TSN 0				
WC#: 21.510	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
210235	HEAD LINER DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4998	HRS	0		TSN 0				
WC#: 21.600	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 22 - AUTO FLIGHT								
22-10/233 S	PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES - EXAMINE							Service ATA:22
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
22-10/60 S	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK							Service ATA:22
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-10-00-00A-313A-APROC. REF: AMM 12-B-22-10-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-10/60 S		SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK						Service ATA:22
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-10-00-00A-313A-APROC. REF: AMM 12-B-22-10-00-00A-313A-A								
22-10/60 S		SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK						Service ATA:22
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-10-00-00A-313A-APROC. REF: AMM 12-B-22-10-00-00A-313A-A								
22-20/129 S		ANGLE OF ATTACK (AOA) TRANSMITTERS - EXAMINE						Service ATA:22
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-20-02-00A-313A-APROC. REF: AMM 12-B-22-20-02-00A-313A-A								
22-20/130 S		STICK PUSHER SYSTEM - CHECK						Service ATA:22
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-20-00-00A-903A-APROC. REF: AMM 12-B-22-20-00-00A-903A-A								
22-20/226 S		STICK PUSHER SYSTEM - FUNCTIONAL TEST						Service ATA:22
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-22-20-00-00A-903A-APROC. REF: AMM 12-B-22-20-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 22 - AUTO FLIGHT

220045	STICK PUSHER SERVO							Component ATA:22
PN:9786111103	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:81103	HRS	0		TSN 0				
WC#: 22.220	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-22-20-04-00A-920A-APROC. REF: AMM 12-B-22-20-04-00A-920A-A								
220055	STICK PUSHER CAPSTAN							Component ATA:22
PN:9786111124	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:81052	HRS	0		TSN 0				
WC#: 22.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-22-20-06-00A-920A-APROC. REF: AMM 12-B-22-20-06-00A-920A-A								
220060	STICK SHAKER							Component ATA:22
PN:9786111143	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1615	HRS	0		TSN 0				
WC#: 22.230	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-22-20-03-00A-920A-APROC. REF: AMM 12-B-22-20-03-00A-920A-A								
220070	STICK PUSHER							Component ATA:22
PN:9754423104	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:137679	HRS	0		TSN 0				
WC#: 22.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-22-20-04-00A-920A-APROC. REF: AMM 12-B-22-20-04-00A-920A-A								
220085	ELEVATOR KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KSM375-B3510	HRS	0		TSN 0				
WC#: 22.280	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
220090	RUDDER KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KSM375-B3509	HRS	0		TSN 0				
WC#: 22.280	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
220095	AILERON KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KSM375-B3508	HRS	0		TSN 0				
WC#: 22.280	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
220100	RUDDER KSA 2700 SERVO							Component ATA:22
PN:9859912275	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KSA2700-3120	HRS	0		TSN 0				
WC#: 22.260	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
220105	ELEVATOR KSA 2700 SERVO							Component ATA:22
PN:9859912275	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KSA2700-3573	HRS	0		TSN 0				
WC#: 22.250	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
220110	AILERON KSA 2700 SERVO							Component ATA:22
PN:065-00190-0101	MOS/MSC	16-May-24	O/C	TSR 0				
SN:KSA2700-2225	HRS	1761:37		TSR 0				
WC#: 22.240	AFL	2244		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
220115	KMC 9200 VNAV FLIGHT CONTROLLER							Component ATA:22
PN:9859912204	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMC9200-2072	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 23 - COMMUNICATIONS								
23-10/322 S	AUDIO CONTROL PANEL EMERGENCY SWITCH - OPERATIONAL TEST							Service ATA:23
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-23-50-00-00A-903A-APROC. REF: AMM 12-B-23-50-00-00A-903A-A								
23-10/323 S	EMERGENCY FREQUENCY COMM TUNING SWITCH - OPERATIONAL TEST							Service ATA:23
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-23-12-00-00A-903A-APROC. REF: AMM 12-B-23-12-00-00A-903A-A								
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA							Component ATA:23
PN:9848110203	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:310-30450	HRS	0		TSN 0				
WC#: 23.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-23-12-02-00A-920A-APROC. REF: AMM 12-B-23-12-02-00A-920A-A								
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA							Component ATA:23
PN:9848110203	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:310-30460	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-23-12-03-00A-920A-APROC. REF: AMM 12-B-23-12-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA							Component ATA:23
PN:9848110210	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:430-15256	HRS	0		TSN 0				
WC#: 23.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-57-02-00A-920A-APROC. REF: AMM 12-B-34-57-02-00A-920A-A								
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO							Component ATA:23
PN:9859912254	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4798	HRS	0		TSN 0				
WC#: 23.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-23-12-01-00A-920A-APROC. REF: AMM 12-B-23-12-01-00A-920A-A								
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO							Component ATA:23
PN:9859912254	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4792	HRS	0		TSN 0				
WC#: 23.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-23-12-01-00A-920A-APROC. REF: AMM 12-B-23-12-01-00A-920A-A								
230055	PILOT KMA 29 AUDIO/MARKER PANEL							Component ATA:23
PN:066-01181-0101	MOS/MSC	20-Mar-19	O/C	TSR 0				
SN:D0159	HRS	335:42		TSR 0				
WC#: 23.100	AFL	311		TSR 0				
PROC. REF: AMM 12-B-23-50-01-00A-920A-APROC. REF: AMM 12-B-23-50-01-00A-920A-A								
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL							Component ATA:23
PN:066-01181-0101	MOS/MSC	20-Mar-19	O/C	TSR 0				
SN:P02222-Q	HRS	335:42		TSR 0				
WC#: 23.110	AFL	311		TSR 0				
PROC. REF: AMM 12-B-23-50-01-00A-920A-APROC. REF: AMM 12-B-23-50-01-00A-920A-A								
ATA 24 - ELECTRICAL POWER								
24-30/309	GENERATOR 1 (P/N 978.91.23.437) - BRUSH CHECK							Service ATA:24
PN:23085-031	MOS	23-Sep-25						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
SN:P1824	HRS	2134:08	300 (+10%/-10%)		2434:08	2464:08	27:59 (+30)	
WC#: 24.210	AFL	2494						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A								
24-30/311 S	GENERATOR CONTROL UNIT, GCU 1- FUNCTIONAL TEST OF OVER AND UNDER-VOLTAGE TRIP PROTECTION							Service ATA:24
PN:PN	MOS	01-Dec-25	12 (+10%/-10%)					AIRWORTHINESS
SN:UNKNOWN	HRS	2149:16	3000					
WC#: 24.015	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903D-APROC. REF: AMM 12-B-71-00-00-00A-903D-A								
24-30/311 S	GENERATOR CONTROL UNIT, GCU 2- FUNCTIONAL TEST OF OVER AND UNDER-VOLTAGE TRIP PROTECTION							Service ATA:24
PN:PN	MOS	01-Dec-25	12 (+10%/-10%)					AIRWORTHINESS
SN:UNKNOWN	HRS	2149:16	3000					
WC#: 24.025	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903D-APROC. REF: AMM 12-B-71-00-00-00A-903D-A								
24-30/312 S	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST							Service ATA:24
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-24-40-00-00A-903A-APROC. REF: AMM 12-B-24-40-00-00A-903A-A								
24-30/313 S	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST							Service ATA:24
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903D-APROC. REF: AMM 12-B-71-00-00-00A-903D-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30/340		REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY - SET-IMC						Service ATA:24
PN:RG-380E/44	MOS	04-Mar-26	T:12 (+10%/-10%)		04-Mar-27	10-Apr-27	129 d (+37)	
SN:41455684	HRS	2220:17	T:1000 (+10%/-10%)		3220:17	3320:17	814:08 (+100)	
WC#: 24.010	AFL	2568						
PROC. REF: AMM 12-B-24-30-07-00A-920A-APROC. REF: AMM 12-B-24-30-07-00A-920A-A								
24-30/340		REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY - SET-IMC						Service ATA:24
PN:RG-380E/44	MOS	04-Mar-26	T:12 (+10%/-10%)		04-Mar-27	10-Apr-27	129 d (+37)	
SN:70064643	HRS	2220:17	T:1000 (+10%/-10%)		3220:17	3320:17	814:08 (+100)	
WC#: 24.010	AFL	2568						
PROC. REF: AMM 12-B-24-30-07-00A-920A-APROC. REF: AMM 12-B-24-30-07-00A-920A-A								
24-30/473		BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) - SET-IMC						Service ATA:24
PN:23085-031	MOS/MSC	23-Sep-25	N/A					
SN:P1824	HRS	2134:08						
	AFL	2494						
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A								
24-30/474		BRUSH CHECK NO. 2 STARTER GENERATOR (P/N 978.91.23.407) - SET-IMC						Service ATA:24
PN:23085-031	MOS/MSC	30-Nov-23	N/A					
SN:P1014	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A								
24-30/492		OVERHAUL NO. 1 STARTER GENERATOR (P/N 978.9123.407)						Service ATA:24
PN:23085-031	MOS	23-Sep-25						OVERHAUL
SN:P1824	HRS	2134:08	1200 (+10%/-10%)		3334:08	3454:08	927:59 (+120)	
	AFL	2494						
PROC. REF: AMM 12-B-05-10-10-00A-281A-APROC. REF: AMM 12-B-05-10-10-00A-281A-A								
24-30/493		OVERHAUL NO. 2 STARTER GENERATOR (P/N 978.9123.407)						Service ATA:24
PN:23085-031	MOS	30-Nov-23						OVERHAUL
SN:P1014	HRS	1639:26	1200 (+10%/-10%)		2839:26	2959:26	433:17 (+120)	
	AFL	2164						
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30/496	GENERATOR 1 (P/N 978.91.23.437) - OVERHAUL							Service ATA:24
PN:23085-031	MOS/MSC	23-Sep-25	N/A					
SN:P1824	HRS	2134:08						
	AFL	2494						
PROC. REF: AMM 12-B-05-10-10-00A-281A-APROC. REF: AMM 12-B-05-10-10-00A-281A-A								
24-40/229 S	EXTERNAL POWER UNIT (EPU) RECEPTACLE - EXAMINE							Service ATA:24
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-50/70 S	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY - SET-IMC							Service ATA:24
PN:9858314953	MOS	01-Dec-25	12 (+10%/-10%)					
SN:83811	HRS	2149:16						
WC#: 24.050	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-24-52-51-00A-920A-APROC. REF: AMM 12-B-24-52-51-00A-920A-A								
24-60/133 S	COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS - EXAMINE							Service ATA:24
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240005	VOLTAGE REGULATOR 1							Component ATA:24
PN:9882114111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:P4425	HRS	0		TSN 0				
WC#: 24.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-24-30-05-00A-920A-APROC. REF: AMM 12-B-24-30-05-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240010	GENERATOR 1 300A CONTACTOR							Component ATA:24
PN:9740338113	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:718	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240015	GENERATOR 2 300A CONTACTOR							Component ATA:24
PN:9740338113	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:672	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240120								Component ATA:24
PN:9740338152	MOS/MSC	19-Sep-18	O/C					
SN:405	HRS	204:54						
WC#: 90.005	AFL	202						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240135	NO. 1 LEAD ACID BATTERY							Component ATA:24
PN:RG-380E/44	MOS/MSC	04-Mar-26	O/C	TSN 0				
SN:41455684	HRS	2220:17		TSN 0				
WC#: 24.010	AFL	2568		TSN 0				
PROC. REF: AMM 12-B-24-30-07-00A-920A-APROC. REF: AMM 12-B-24-30-07-00A-920A-A								
240140	NO. 2 LEAD ACID BATTERY							Component ATA:24
PN:RG-380E/44	MOS/MSC	04-Mar-26	O/C	TSN 0				
SN:70064643	HRS	2220:17		TSN 0				
WC#: 24.010	AFL	2568		TSN 0				
PROC. REF: AMM 12-B-24-30-07-00A-920A-APROC. REF: AMM 12-B-24-30-07-00A-920A-A								
243010	NO. 2 STARTER-GENERATOR							Component ATA:24
PN:23085-031	MOS/MSC	30-Nov-23	O/C	TSO 0				
SN:P1014	HRS	1639:26		TSO 0				
WC#: 24.215	AFL	2164		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: AMM 12-B-24-30-01-00A-920A-APROC. REF: AMM 12-B-24-30-01-00A-920A-A								
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT							Component ATA:24
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.015	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT							Component ATA:24
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.025	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243080	EMERGENCY POWER SUPPLY							Component ATA:24
PN:9858314953	MOS/MSC	01-Dec-25	O/C	TSN 96				
SN:83811	HRS	2149:16		TSN 2149:16				
WC#: 24.050	AFL	2506		TSN 2506				
PROC. REF: AMM 12-B-24-52-51-00A-920A-APROC. REF: AMM 12-B-24-52-51-00A-920A-A								
243160	NO. 1 STARTER GENERATOR							Component ATA:24
PN:23085-031	MOS/MSC	23-Sep-25	O/C	TSO 0				
SN:P1824	HRS	2134:08		TSO 0				
WC#: 24.205	AFL	2494		TSO 0				
PROC. REF: AMM 12-B-24-30-01-00A-920A-APROC. REF: AMM 12-B-24-30-01-00A-920A-A								
243170	110 VOLT STATIC ,SS50 INVERTER							Component ATA:24
PN:9750215107	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7914	HRS	0		TSN 0				
WC#: 24.220	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-24-60-01-00A-920A-APROC. REF: AMM 12-B-24-60-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER							Component ATA:24
PN:9755085111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N4525	HRS	0		TSN 0				
WC#: 24.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER							Component ATA:24
PN:9755085111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N4528	HRS	0		TSN 0				
WC#: 24.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243190	VOLTAGE REGULATOR 2							Component ATA:24
PN:9882114111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:P4428	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-24-30-06-00A-920A-APROC. REF: AMM 12-B-24-30-06-00A-920A-A								
ATA 25 - EQUIPMENT/FURNISHINGS								
25-10/134 S	EXAMINE CREW SEAT BELTS - SET-IMC							Service ATA:25
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-10/135 S	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED							Service ATA:25
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-10/294	CO-PILOT SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-10/294	CREW SEAT BELTS							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-10/294	PILOT SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-10/296	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION							Service ATA:25
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-25-10-01-00A-920A-APROC. REF: AMM 12-B-25-10-01-00A-920A-A								
25-10/297	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:25
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-25-10-01-00A-920A-APROC. REF: AMM 12-B-25-10-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-10/300 S	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS.							Service ATA:25
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-25-10-01-00A-920A-APROC. REF: AMM 12-B-25-10-01-00A-920A-A								
25-20/136 S	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS - SET-IMC							Service ATA:25
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/137 S	EXAMINE PASSENGER SEATS - FOR EXCUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT							Service ATA:25
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 1 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 2 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-20/295	NO. 3 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 4 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 5 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 6 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	NO. 7 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-20/295	NO. 8 PASSENGER SEAT BELT							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/295	PASSENGER SEAT BELTS							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.010	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-20/298	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION							Service ATA:25
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-A								
25-20/299	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:25
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-A								
25-20/302 S	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION.							Service ATA:25
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60/231 S	OPERATIONAL TEST ELT							Service ATA:25
PN:9851380882	MOS	01-Dec-25	12 (+10%/-10%)					
SN:LX1100622319	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-25-63-00-00A-903A-A, AMM 12-B-25-63-00-00A-903B-APROC. REF: AMM 12-B-25-63-00-00A-903A-A, AMM 12-B-25-63-00-00A-903B-A								
25-60/232 S	EXAMINE ELT INSTALLATION							Service ATA:25
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-62/642	EXAMINE ALL LIFE VESTS							Service ATA:25
PN:PN	MOS	01-Dec-25	12 (+10%/-10%)	Adj -39d	23-Oct-26	29-Nov-26	TOL (+34 d)	
SN:UNKNOWN	HRS	2149:16						
	AFL	2506						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-25-62-00-00A-310A-APROC. REF: AMM 12-B-25-62-00-00A-310A-A								
25-62/643	DISCARD COPILOTS LIFE VEST							Service ATA:25
PN:PN	MOS	04-Jan-18	120		04-Jan-28		435 d	DISCARD
SN:UNKNOWN	HRS							
	AFL							
			Manufacture Date:: 04-Jan-18					
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
25-62/643	DISCARD NO. 1 LIFE VEST							Service ATA:25
PN:PN	MOS	04-Jan-18	120		04-Jan-28		435 d	DISCARD
SN:UNKNOWN	HRS							
	AFL							
			Manufacture Date:: 04-Jan-18					
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62/643	DISCARD NO. 7 LIFE VEST							Service ATA:25
PN:PN	MOS	04-Jan-18	120		04-Jan-28		435 d	DISCARD
SN:UNKNOWN	HRS							
	AFL							
			Manufacture Date:: 04-Jan-18					
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
25-62/643	DISCARD NO. 8 LIFE VEST							Service ATA:25
PN:PN	MOS	04-Jan-18	120		04-Jan-28		435 d	DISCARD
SN:UNKNOWN	HRS							
	AFL							
			Manufacture Date:: 04-Jan-18					
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
25-62/643	DISCARD PILOTS LIFE VEST							Service ATA:25
PN:PN	MOS	04-Jan-18	120		04-Jan-28		435 d	DISCARD
SN:UNKNOWN	HRS							
	AFL							
			Manufacture Date:: 04-Jan-18					
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
25-63/23	ELT BATTERY REPLACEMENT							Component ATA:25
PN:0141823	MOS/MSC	04-Oct-24	DUE	TSN 0	01-May-31 (M)		1648 d	DISCARD
SN:24250182	HRS	1858:38		TSN 0				
WC#: 25.020	AFL	2310		TSN 0				
			Expiry Date: : 01-May-31					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED)							Service ATA:25
PN:9851380881	MOS	04-Jan-18	120 (+6m/-6m)		04-Jan-28	04-Jul-28	435 d (+182)	DISCARD
SN:LX1100496487	HRS	0	16000 (+500/-500)		16000	16500	13593:51 (+500)	
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-70/000-INSP US	CHECK THAT THE BAG IS ALWAYS VACUUMED (IF NOT, SEE NOTE), CHECK GOOD CONDITION, ABSENCE OF DAMAGE, PUNCTURE ON THE BAG AND THE LIFE VEST							Service ATA:25
	MOS	01-Dec-25	12					
	HRS	2149:16						
	AFL	2506						
								PKG:19 WO#: FLEX26-1761-18
250005	REMOTE CONTROL PANEL							Component ATA:25
PN:9851380817	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:TM0000107287	HRS	0		TSN 0				
WC#: 25.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
250010	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:9851380882	MOS/MSC	19-Sep-18	O/C	TSN 2				
SN:LX1100622319	HRS	204:54		TSN 0				
WC#: 25.050	AFL	202		TSN 0				
PROC. REF: AMM 12-B-25-63-00-00A-920A-APROC. REF: AMM 12-B-25-63-00-00A-920A-A								
250021	L/H NO. 1 AFSS PASSENGER SEAT							Component ATA:25
PN:9593001821	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:62998	HRS	0		TSN 0				
WC#: 25.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								
250022	R/H NO. 2 AFSS PASSENGER SEAT							Component ATA:25
PN:9593001822	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:62999	HRS	0		TSN 0				
WC#: 25.125	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
250023	L/H NO. 3 FFSS PASSENGER SEAT							Component ATA:25
PN:9593001835	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:63000	HRS	0		TSN 0				
WC#: 25.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								
250024	R/H NO. 4 FFSS PASSENGER SEAT							Component ATA:25
PN:9593001836	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:63001	HRS	0		TSN 0				
WC#: 25.135	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								
250025	L/H NO. 5 FFSS PASSENGER SEAT							Component ATA:25
PN:9593001837	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:63002	HRS	0		TSN 0				
WC#: 25.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								
250026	R/H NO. 6 FFSS PASSENGER SEAT							Component ATA:25
PN:9593001838	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:63003	HRS	0		TSN 0				
WC#: 25.145	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-21-01-00A-920A-APROC. REF: AMM 12-B-25-21-01-00A-920A-A								
250027	L/H NO. 7 STANDARD PASSENGER SEAT							Component ATA:25
PN:5252212011	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2053	HRS	0		TSN 0				
WC#: 25.150	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-22-01-00A-920A-APROC. REF: AMM 12-B-25-22-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
250028	R/H NO. 8 STANDARD PASSENGER SEAT							Component ATA:25
PN:5252212012	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2084	HRS	0		TSN 0				
WC#: 25.155	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-22-01-00A-920A-APROC. REF: AMM 12-B-25-22-01-00A-920A-A								
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE							Component ATA:25
PN:9851380881	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:LX1100496487	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-63-03-00A-920A-APROC. REF: AMM 12-B-25-63-03-00A-920A-A								
256020	LH BLACK PILOT SEAT							Component ATA:25
PN:9593001165	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:88386	HRS	0		TSN 0				
WC#: 25.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-10-01-00A-920A-APROC. REF: AMM 12-B-25-10-01-00A-920A-A								
256025	RH BLACK CO-PILOT SEAT							Component ATA:25
PN:9593001166	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:88087	HRS	0		TSN 0				
WC#: 25.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-25-10-01-00A-920A-APROC. REF: AMM 12-B-25-10-01-00A-920A-A								
258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)							Service ATA:25
	MOS/MSC		N/A					
	HRS							
WC#: 25.110	AFL							
	ACH							
PROC. REF: AMM 12-B-25-63-00-00A-903A-APROC. REF: AMM 12-B-25-63-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
FX U	REPACK LIFE VEST (INFANT)							Component ATA:25
PN:S-10002-1300-999117	MOS/MSC		120 / ADMIN		24-Aug-28 (M)		668 d	05-60 OPTIONAL EQUIPMENT
SN:8-13-13760-0	HRS							
	AFL							
LIFE VEST INFANT U	INSPECTION/REPACK LIFE VEST							Component ATA:25
PN:S-10002-1300-999117	MOS/MSC		-					
SN:8-13-13760-0	HRS							
	AFL							
PC12A256CA110	PILOT VEST							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
PC12A256CA120	COPILOT VEST							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
PC12A256CA210	NO. 1 VEST							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
PC12A256CA270	NO. 7 VEST							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PC12A256CA280	NO. 8 VEST							Component ATA:25
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A								
ATA 26 - FIRE PROTECTION								
26-20/2	COCKPIT FIRE EXTINGUISHER REPLACEMENT							Component ATA:26
PN:P3APP003010D	MOS	01-Dec-25	120	TSN 0	01-Dec-35		3323 d	LIFE LIMIT
SN:112149	HRS	2149:16		TSN 0				
WC#: 26.010	AFL	2506		TSN 0				
			Manufacture Date:: 01-Dec-25					
PROC. REF: AMM 12-B-26-20-01-00A-920A-APROC. REF: AMM 12-B-26-20-01-00A-920A-A								
26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)							Service ATA:26
PN:P3APP003010D	MOS/MSC	01-Dec-25	N/A					
SN:112149	HRS	2149:16						
WC#: 26.010	AFL	2506						
PROC. REF: AMM 12-B-26-20-00-01A-289A-APROC. REF: AMM 12-B-26-20-00-01A-289A-A								
26-20/515	COCKPIT FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224)							Service ATA:26
PN:P3APP003010D	MOS	01-Dec-25	24 (+10%/-10%)		01-Dec-27	12-Feb-28	401 d (+73)	
SN:112149	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-26-20-00-02A-289A-APROC. REF: AMM 12-B-26-20-00-02A-289A-A								
26-20/516	CABIN FIRE 1.5 KG EXTINGUISHER LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)							Service ATA:26
	MOS	04-Jan-18	144		04-Jan-30		1166 d	LIFE LIMIT
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20/516	COCKPIT FIRE EXTINGUISHER LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)							Service ATA:26
PN:P3APP003010D	MOS	01-Dec-25	144		01-Dec-37		4054 d	LIFE LIMIT
SN:112149	HRS	2149:16						
	AFL	2506						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
260005	FIRE/OVERHEAT DETECTOR							Component ATA:26
PN:9751210012	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:215595	HRS	0		TSN 0				
WC#: 26.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-26-10-01-00A-920A-APROC. REF: AMM 12-B-26-10-01-00A-920A-A								
ATA 27 - FLIGHT CONTROLS								
27-00/138 S	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL							Service ATA:27
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES							Service ATA:27
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 27.255	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK							Service ATA:27
	MOS	18-Oct-22	60 (+10%/-10%)	Adj 74d	31-Dec-27	30-Jun-28	431 d (+182)	
	HRS	1337:54	4800 (+10%/-10%)		6137:54	6617:54	3731:45 (+480)	
WC#: 27.010	AFL	1976						
PROC. REF: AMM 12-B-27-00-00-00A-313A-APROC. REF: AMM 12-B-27-00-00-00A-313A-A								
27-10/139 S	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIMHINGES WITH MINIMUM QUANTITY OFCPC (MAT. NO. P10-001)							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 27 - FLIGHT CONTROLS

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

27-10/234 S		AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

27-10/235 S		EXAMINE AILERON ELECTRICAL BONDING STRAPS						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

27-10/236 S		AILERON CONTROL SYSTEM - INSPECTION/ CHECK						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-27-10-00-00A-313A-APROC. REF: AMM 12-B-27-10-00-00A-313A-A

27-10/237 S		CHECK AILERON CABLE TENSION						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-27-10-00-00A-903A-APROC. REF: AMM 12-B-27-10-00-00A-903A-A

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/238 S	FUNCTIONAL TEST AILERONS							Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-27-10-00-00A-903A-APROC. REF: AMM 12-B-27-10-00-00A-903A-A								
27-10/394	AILERON CONTROL SYSTEM - EXAMINE							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.155	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-10-00-00A-310A-APROC. REF: AMM 12-B-27-10-00-00A-310A-A								
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.160	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-10-09-00A-353A-APROC. REF: AMM 12-B-27-10-09-00A-353A-A								
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.165	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-00-01-00A-353A-APROC. REF: AMM 12-B-27-00-01-00A-353A-A								
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.170	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-00-01-00A-352A-APROC. REF: AMM 12-B-27-00-01-00A-352A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.175	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-10-08-00A-352B-A, AMM 12-B-27-10-08-00A-353A-A, AMM 12-B-27-10-08-00A-353B-APROC. REF: AMM 12-B-27-10-08-00A-352B-A, AMM 12-B-27-10-08-00A-353A-A, AMM 12-B-27-10-08-00A-353B-A								
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.215	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-57-60-06-00A-353A-APROC. REF: AMM 12-B-57-60-06-00A-353A-A								
27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-57-60-06-00A-353A-APROC. REF: AMM 12-B-57-60-06-00A-353A-A								
27-10/444	AILERON FLIGHT CONTROL CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-10-01-00A-920A-APROC. REF: AMM 12-B-27-10-01-00A-920A-A								
27-10/445	AILERON AUTOPILOT CONTROL CABLE REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-10-02-00A-920A-APROC. REF: AMM 12-B-27-10-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/470 S	LUBRICATE AILERON CONTROL SYSTEM BEARINGS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-10-00-00A-901A-APROC. REF: AMM 12-B-27-10-00-00A-901A-A								
27-15/239 S	FUNCTIONAL TEST AILERON TRIM							Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-27-15-00-00A-903A-APROC. REF: AMM 12-B-27-15-00-00A-903A-A								
27-20/140 S	INSPECTION/CHECK RUDDER							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-55-40-00-00A-313A-APROC. REF: AMM 12-B-55-40-00-00A-313A-A								
27-20/240 S	EXAMINE RUDDER STATIC DISCHARGERS							Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-20/241 S	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-20-00-00A-313A-APROC. REF: AMM 12-B-27-20-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20/243 S		CHECK RUDDER CABLE TENSION						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-20-00-00A-903A-APROC. REF: AMM 12-B-27-20-00-00A-903A-A								
27-20/244 S		FUNCTIONAL TEST RUDDER						Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-27-20-00-00A-903A-APROC. REF: AMM 12-B-27-20-00-00A-903A-A								
27-20/245 S		FUNCTIONAL TEST RUDDER TRIM						Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-27-25-00-00A-903A-APROC. REF: AMM 12-B-27-25-00-00A-903A-A								
27-20/246 S		EXAMINE RUDDER ELECTRICAL BONDING STRAPS						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-20/374		RUDDER CONTROL SYSTEM - EXAMINE						Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.180	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-20-00-00A-310A-APROC. REF: AMM 12-B-27-20-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.190	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-20-05-00A-310A-APROC. REF: AMM 12-B-27-20-05-00A-310A-A								
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED							Service ATA:27
	MOS/MSC	06-Feb-19	O/C					
	HRS	292:18		Adj 7:42				
	AFL	271						
PROC. REF: AMM 12-B-27-20-00-00A-903A-APROC. REF: AMM 12-B-27-20-00-00A-903A-A								
27-20/431	RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)							Service ATA:27
PN:PN	MOS/MSC	06-Feb-19	A/R					
SN:UNKNOWN	HRS	292:18		Adj 7:42				
	AFL	271						
PROC. REF: AMM 12-B-27-20-00-00A-903A-APROC. REF: AMM 12-B-27-20-00-00A-903A-A								
27-20/446	RUDDER FLIGHT CONTROL CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-20-01-00A-920A-APROC. REF: AMM 12-B-27-20-01-00A-920A-A								
27-20/447	RUDDER AUTOPILOT CONTROL CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-20-02-00A-920A-APROC. REF: AMM 12-B-27-20-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20/575	REPLACE RUDDER BELLCRANK							Service ATA:27
PN:PN	MOS	04-Jan-18						LIFE LIMIT
SN:UNKNOWN	HRS	0	20000		20000		17593:51	
	AFL	0	27000		27000		24277	
PROC. REF: AMM 12-B-27-20-04-00A-920A-APROC. REF: AMM 12-B-27-20-04-00A-920A-A								
27-30/141 S	EXAMINE ELEVATORS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-30/247 S	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-30/248 S	EXAMINE ELEVATOR STATIC DISCHARGERS							Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-30/249 S	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-30-00-00A-313A-APROC. REF: AMM 12-B-27-30-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30/250 S		CHECK ELEVATOR CABLE TENSION						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-30-00-00A-903A-APROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/251 S		FUNCTIONAL TEST ELEVATOR						Service ATA:27
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-27-30-00-00A-903A-APROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/333		ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED						Service ATA:27
	MOS/MSC	06-Feb-19	O/C					
	HRS	292:18		Adj 7:42				
WC#: 27.150	AFL	271						
PROC. REF: AMM 12-B-27-30-00-00A-903A-APROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/334		CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)						Service ATA:27
PN:PN	MOS/MSC	06-Feb-19	A/R					
SN:UNKNOWN	HRS	292:18		Adj 7:42				
	AFL	271						
PROC. REF: AMM 12-B-27-30-00-00A-903A-APROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/363		ELEVATOR - CONTROL SYSTEM - EXAMINE						Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.195	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-30-00-00A-310A-APROC. REF: AMM 12-B-27-30-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.200	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-00-01-00A-353A-APROC. REF: AMM 12-B-27-00-01-00A-353A-A								
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.205	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-00-01-00A-352A-APROC. REF: AMM 12-B-27-00-01-00A-352A-A								
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 27.210	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-27-30-05-00A-353A-APROC. REF: AMM 12-B-27-30-05-00A-353A-A								
27-30/448	ELEVATOR FLIGHT CONTROL CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-30-01-00A-920A-APROC. REF: AMM 12-B-27-30-01-00A-920A-A								
27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-30-02-00A-920A-APROC. REF: AMM 12-B-27-30-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30/450	STICK PUSHER CABLES REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-30/514 S	EXAMINE - ELEVATOR STOPS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-55-20-01-00A-904B-APROC. REF: AMM 12-B-55-20-01-00A-904B-A								
27-40/1 S	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (CMR)							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					AIRWORTHINESS
	HRS	2149:16	3000					
WC#: 27.021	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-40-00-00A-903A-APROC. REF: AMM 12-B-27-40-00-00A-903A-A								
27-40/142 S	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-40-00-00A-903A-APROC. REF: AMM 12-B-27-40-00-00A-903A-A								
27-40/252 S	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-40-01-00A-313A-APROC. REF: AMM 12-B-27-40-01-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40/26		OVERHAUL PITCH TRIM ACTUATOR						Service ATA:27
PN:978.73.14.203	MOS	09-Jun-26	84	TAC 1	09-May-33		2387 d	OVERHAUL
SN:1156	HRS	2313:14	3400	TAC 0	5713:14		3307:05	
	AFL	2655						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-40/291 S		OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						Service ATA:27
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-40-00-00A-903A-APROC. REF: AMM 12-B-27-40-00-00A-903A-A								
27-40/292 S		FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-40-00-00A-903A-APROC. REF: AMM 12-B-27-40-00-00A-903A-A								
27-40/3		PITCH TRIM ACTUATOR REPLACEMENT						Service ATA:27
PN:978.73.14.203	MOS	09-Jun-26						LIFE LIMIT
SN:1156	HRS	2313:14	20000	TAC 4647:42	17665:32		15259:23	
	AFL	2655	27000	TAC 4576	25079		22356	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-40/307		PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) REPLACEMENT						Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	10000	TSN 0	10000		7593:51	
WC#: 27.036	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-27-40-02-00A-920A-APROC. REF: AMM 12-B-27-40-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/143	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION							Service ATA:27
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/144 S	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/253 S	EXAMINE FLAPS ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/254 S	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/255 S	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-50-00-00A-903A-APROC. REF: AMM 12-B-27-50-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/28	FLAP POWER DRIVE UNIT OVERHAUL							Component ATA:27
PN:9787320003	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:1603	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7593:51 (+500)	
WC#: 27.030	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	10777 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-27-50-01-00A-920A-APROC. REF: AMM 12-B-27-50-01-00A-920A-A								
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT REPLACEMENT							Component ATA:27
PN:9450202205	MOS	04-Jan-18		TSN 0				DISCARD
SN:S7962	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7593:51 (+500)	
WC#: 27.060	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	10777 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT REPLACEMENT							Component ATA:27
PN:9450202206	MOS	04-Jan-18		TSN 0				DISCARD
SN:S7942	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7593:51 (+500)	
WC#: 27.060	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	10777 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT REPLACEMENT							Component ATA:27
PN:9450202205	MOS	04-Jan-18		TSN 0				DISCARD
SN:S7965	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7593:51 (+500)	
WC#: 27.070	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	10777 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT REPLACEMENT							Component ATA:27
PN:9450202206	MOS	04-Jan-18		TSN 0				DISCARD
SN:S7949	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7593:51 (+500)	
WC#: 27.070	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	10777 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/386	FLAP MECHANISM - EXAMINE							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.220	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-00-00A-310A-APROC. REF: AMM 12-B-27-51-00-00A-310A-A								
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 27.225	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-00-00A-353A-APROC. REF: AMM 12-B-27-51-00-00A-353A-A								
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.230	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.235	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.240	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.245	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS							Service ATA:27
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 27.250	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-APROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/414	LEFT HAND FLAP REPLACEMENT							Component ATA:27
PN:5570512025	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:1450M	HRS	0	25000	TSN 0	25000		22593:51	
WC#: 57.060	AFL	0	30000	TSN 0	30000		27277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/414	RIGHT HAND FLAP REPLACEMENT							Component ATA:27
PN:5570512026	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:1450M	HRS	0	25000	TSN 0	25000		22593:51	
WC#: 57.060	AFL	0	30000	TSN 0	30000		27277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/437 S	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)					AIRWORTHINESS
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-51-00-00A-313A-APROC. REF: AMM 12-B-27-51-00-00A-313A-A								
27-50/443	SERVICE FLAP UP AND DOWN LIMIT SWITCHES							Service ATA:27
	MOS	01-Dec-25	12 (+10%/-10%)	Adj -7d	24-Nov-26	30-Dec-26	29 d (+36)	
	HRS	2149:16	300 (+10%/-10%)		2449:16	2479:16	43:07 (+30)	
	AFL	2506						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-07-00A-902A-APROC. REF: AMM 12-B-12-20-07-00A-902A-A								
27-50/451	FLAP TENSION RODS REPLACEMENT							Component ATA:27
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/475	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION							Service ATA:27
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/485	LEFT INBOARD FLAP ACTUATOR REPLACEMENT							Component ATA:27
PN:9787320309	MOS	04-Jan-18		TSN 0				DISCARD
SN:6337	HRS	0	20000	TSN 0	20000		17593:51	
WC#: 27.040	AFL	0	27000	TSN 0	27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485	LEFT OUTBOARD FLAP ACTUATOR REPLACEMENT							Component ATA:27
PN:9787320309	MOS	04-Jan-18		TSN 0				DISCARD
SN:6340	HRS	0	20000	TSN 0	20000		17593:51	
WC#: 27.041	AFL	0	27000	TSN 0	27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485	RIGHT INBOARD FLAP ACTUATOR REPLACEMENT							Component ATA:27
PN:9787320309	MOS	04-Jan-18		TSN 0				DISCARD
SN:6325	HRS	0	20000	TSN 0	20000		17593:51	
WC#: 27.050	AFL	0	27000	TSN 0	27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485	RIGHT OUTBOARD FLAP ACTUATOR REPLACEMENT							Component ATA:27
PN:9787320309	MOS	04-Jan-18		TSN 0				DISCARD
SN:6339	HRS	0	20000	TSN 0	20000		17593:51	
WC#: 27.051	AFL	0	27000	TSN 0	27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/495	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	24 (+10%/-10%)	Adj -40d	22-Oct-27	03-Jan-28	361 d (+73)	
SN:6337	HRS	2149:16	2400 (+10%/-10%)		4549:16	4789:16	2143:07 (+240)	
WC#: 27.040	AFL	2506	3200 (+10%/-10%)		5706	6026	2983 (+320)	
								PKG:22
PROC. REF: AMM 12-B-27-50-03-00A-313A-APROC. REF: AMM 12-B-27-50-03-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/495	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	24 (+10%/-10%)	Adj -40d	22-Oct-27	03-Jan-28	361 d (+73)	
SN:6340	HRS	2149:16	2400 (+10%/-10%)		4549:16	4789:16	2143:07 (+240)	
WC#: 27.041	AFL	2506	3200 (+10%/-10%)		5706	6026	2983 (+320)	
								PKG:22
PROC. REF: AMM 12-B-27-50-03-00A-313A-APROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/495	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	24 (+10%/-10%)	Adj -40d	22-Oct-27	03-Jan-28	361 d (+73)	
SN:6325	HRS	2149:16	2400 (+10%/-10%)		4549:16	4789:16	2143:07 (+240)	
WC#: 27.050	AFL	2506	3200 (+10%/-10%)		5706	6026	2983 (+320)	
								PKG:22
PROC. REF: AMM 12-B-27-50-03-00A-313A-APROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/495	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	24 (+10%/-10%)	Adj -40d	22-Oct-27	03-Jan-28	361 d (+73)	
SN:6339	HRS	2149:16	2400 (+10%/-10%)		4549:16	4789:16	2143:07 (+240)	
WC#: 27.051	AFL	2506	3200 (+10%/-10%)		5706	6026	2983 (+320)	
								PKG:22
PROC. REF: AMM 12-B-27-50-03-00A-313A-APROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/506	OVERHAUL LEFT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	04-Jan-18						OVERHAUL
SN:6337	HRS	0	5000 (+10%/-10%)		5000	5500	2593:51 (+500)	
WC#: 27.040	AFL	0	7000 (+500/-500)		7000	7500	4277 (+500)	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/506	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	04-Jan-18						OVERHAUL
SN:6340	HRS	0	5000 (+10%/-10%)		5000	5500	2593:51 (+500)	
WC#: 27.041	AFL	0	7000 (+500/-500)		7000	7500	4277 (+500)	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/506	OVERHAUL RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	04-Jan-18						OVERHAUL
SN:6325	HRS	0	5000 (+10%/-10%)		5000	5500	2593:51 (+500)	
WC#: 27.050	AFL	0	7000 (+500/-500)		7000	7500	4277 (+500)	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/506	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	04-Jan-18						OVERHAUL
SN:6339	HRS	0	5000 (+10%/-10%)		5000	5500	2593:51 (+500)	
WC#: 27.051	AFL	0	7000 (+500/-500)		7000	7500	4277 (+500)	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50/576 S	LUBRICATE LEFT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	12 (+10%/-10%)					
SN:6337	HRS	2149:16	300 (+10%/-10%)					
WC#: 27.040	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-50-00-00A-902A-APROC. REF: AMM 12-B-27-50-00-00A-902A-A								
27-50/576 S	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	12 (+1m/-1m)					
SN:6340	HRS	2149:16	300 (+10%/-10%)					
WC#: 27.041	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-50-00-00A-902A-APROC. REF: AMM 12-B-27-50-00-00A-902A-A								
27-50/576 S	LUBRICATE RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	12 (+10%/-10%)					
SN:6325	HRS	2149:16	300 (+10%/-10%)					
WC#: 27.050	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-50-00-00A-902A-APROC. REF: AMM 12-B-27-50-00-00A-902A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/576 S	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	01-Dec-25	12 (+10%/-10%)					
SN:6339	HRS	2149:16	300 (+10%/-10%)					
WC#: 27.051	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-27-50-00-00A-902A-APROC. REF: AMM 12-B-27-50-00-00A-902A-A								
270003	HORIZONTAL TAIL ASSY							Component ATA:27
PN:5551012037	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1589	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-55-10-01-00A-920A-APROC. REF: AMM 12-B-55-10-01-00A-920A-A								
270015	ELEVATOR LH ASSY							Component ATA:27
PN:5552012041	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1676	HRS	0		TSN 0				
WC#: 27.015	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-55-20-01-00A-920A-APROC. REF: AMM 12-B-55-20-01-00A-920A-A								
270023	ELEVATOR RH ASSY							Component ATA:27
PN:5552012042	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1671	HRS	0		TSN 0				
WC#: 27.023	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-55-20-01-00A-920A-APROC. REF: AMM 12-B-55-20-01-00A-920A-A								
270025	RUDDER TRIM LINEAR ACTUATOR							Component ATA:27
PN:9787318138	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1675	HRS	0		TSN 0				
WC#: 27.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-25-01-00A-920A-APROC. REF: AMM 12-B-27-25-01-00A-920A-A								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270033	RUDDER ASSY							Component ATA:27
PN:5554012040	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1450M	HRS	0		TSN 0				
WC#: 27.033	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-55-40-01-00A-920A-APROC. REF: AMM 12-B-55-40-01-00A-920A-A								
270035	FLAP CONTROL AND WARNING UNIT							Component ATA:27
PN:9787320017	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:137479	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-05-00A-920A-APROC. REF: AMM 12-B-27-50-05-00A-920A-A								
270045	LH INBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1740113DW	HRS	0		TSN 0				
WC#: 27.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270050	LH ROTATION TRANSMITTER							Component ATA:27
PN:9787320602	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2640	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270060	LH OUTBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1750023DY	HRS	0		TSN 0				
WC#: 27.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270070	RH INBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1750019DW	HRS	0		TSN 0				
WC#: 27.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270075	RH ROTATION,C70016705 TRANSMITTER							Component ATA:27
PN:9787320602	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2633	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270080	KTA2810,TRIM ADAPTER							Component ATA:27
PN:527.40.12.424	MOS/MSC	04-Mar-22	O/C					
SN:N/A	HRS	1045:36						
WC#: 22.135	AFL	1362						
PROC. REF: AMM 12-B-22-10-07-00A-920A-A, AMM 12-B-22-10-07-00A-920B-APROC. REF: AMM 12-B-22-10-07-00A-920A-A, AMM 12-B-22-10-07-00A-920B-A								
270090	AILERON LINEAR ACTUATOR							Component ATA:27
PN:9787318138	MOS/MSC	06-Feb-19	O/C	TSR 0				
SN:122	HRS	292:30		TSR 0				
WC#: 27.140	AFL	271		TSR 0				
PROC. REF: AMM 12-B-27-15-01-00A-920A-APROC. REF: AMM 12-B-27-15-01-00A-920A-A								
270095	RH OUTBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1750053DX	HRS	0		TSN 0				
WC#: 27.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-27-50-06-00A-920A-APROC. REF: AMM 12-B-27-50-06-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274020	PITCH TRIM ACTUATOR							Component ATA:27
PN:978.73.14.203	MOS/MSC	09-Jun-26	H/T	TSO 1				
SN:1156	HRS	2313:14		TSN 4647:42, TSO 0				
	AFL	2655		TSN 4576, TSO 0				
PROC. REF: AMM 12-B-27-40-01-00A-920A-APROC. REF: AMM 12-B-27-40-01-00A-920A-A								
274030	MANUAL PITCH TRIM RELAYS							Component ATA:27
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 28 - FUEL								
28-10/145 S	EXAMINE FUEL TANK FILLER CAPS							Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-10/146 S	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER							Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-28-10-02-00A-901A-APROC. REF: AMM 12-B-28-10-02-00A-901A-A								
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE							Service ATA:28
	MOS	31-Dec-17						
	HRS	0	2400 (+10%/-10%)		2400	2640	TOL (+233:51)	
WC#: 28.029	AFL	0						
	ACH	0						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-28-10-01-00A-903A-APROC. REF: AMM 12-B-28-10-01-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20/147 S		OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-28-20-07-00A-903A-APROC. REF: AMM 12-B-28-20-07-00A-903A-A								
28-20/148 S		REMOVE/CLEAN FUEL FILTER ELEMENT						Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-28-20-01-00A-920A-A, AMM 12-B-28-20-01-00A-250A-APROC. REF: AMM 12-B-28-20-01-00A-920A-A, AMM 12-B-28-20-01-00A-250A-A								
28-20/149 S		OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N)						Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-20/150 S		EXAMINE ENGINE DRIVEN PUMP						Service ATA:28
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20/256 S	FUEL SYSTEM COMPONENTS - EXAMINE AS FAR AS POSSIBLE WITH THOSE ACCESS PANELS OPENED / REMOVED IN THIS INSPECTION PACKAGE							Service ATA:28
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-20/32	ENGINE DRIVEN FUEL PUMP OVERHAUL							Service ATA:28
PN:9688451108	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:B6220	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 28.010	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-28-20-03-00A-920A-APROC. REF: AMM 12-B-28-20-03-00A-920A-A								
280005	LOW PRESSURE FUEL PUMP							Component ATA:28
PN:9688451108	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B6220	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-03-00A-920A-APROC. REF: AMM 12-B-28-20-03-00A-920A-A								
280010	FUEL FLOW TRANSMITTER							Component ATA:28
PN:9753512108	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:AAR0518	HRS	0		TSN 0				
WC#: 28.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-73-30-01-00A-920A-APROC. REF: AMM 12-B-73-30-01-00A-920A-A								
280012	FUEL CONTROL MONITORING UNIT							Component ATA:28
PN:975.37.31.336	MOS/MSC	18-Oct-22	O/C					
SN:125	HRS	1337:54						
WC#: 28.155	AFL	1976						
PROC. REF: AMM 12-B-28-40-04-00A-920A-A, AMM 12-B-73-20-01-00A-920A-APROC. REF: AMM 12-B-28-40-04-00A-920A-A, AMM 12-B-73-20-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280015	FIREWALL FUEL,SHUT-OFF VALVE							Component ATA:28
PN:9638722301	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3836	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-08-00A-920A-APROC. REF: AMM 12-B-28-20-08-00A-920A-A								
280020	MAINTENANCE FUEL SHUT-OFF VALVE							Component ATA:28
PN:9638722301	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3835	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-12-00A-920A-APROC. REF: AMM 12-B-28-20-12-00A-920A-A								
280025	FUEL FILTER ASSY							Component ATA:28
PN:9683521001	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2017FFT1836	HRS	0		TSN 0				
WC#: 28.025	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-01-00A-920A-APROC. REF: AMM 12-B-28-20-01-00A-920A-A								
280030	FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:9738114102	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2949	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-02-00A-920A-APROC. REF: AMM 12-B-28-20-02-00A-920A-A								
280035	EJECTOR,TRANSFER LH PUMP							Component ATA:28
PN:9688471104	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B-6121	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-05-00A-920A-APROC. REF: AMM 12-B-28-20-05-00A-920A-A								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280040	EJECTOR,DELIVERY LH PUMP							Component ATA:28
PN:9688471105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B-6415	HRS	0		TSN 0				
WC#: 28.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-06-00A-920A-APROC. REF: AMM 12-B-28-20-06-00A-920A-A								
280045	FUEL QUANTITY OUTER LH SENSOR							Component ATA:28
PN:9753731253	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2685	HRS	0		TSN 0				
WC#: 28.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280050	FUEL QUANTITY,CENTRAL LH SENSOR							Component ATA:28
PN:975.37.31.252	MOS/MSC	16-Feb-24	O/C	TSN 0				
SN:3848	HRS	1692:52		TSN 0				
WC#: 28.070	AFL	2204		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280055	FUEL QUANTITY,INNER LH SENSOR							Component ATA:28
PN:9753731251	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2599	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280060	FUEL QUANTITY,COLLECTOR LH SENSOR							Component ATA:28
PN:9753731250	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2604	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280065	FUEL,BOOSTER LH PUMP							Component ATA:28
PN:9688411405	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:C-878	HRS	0		TSN 0				
WC#: 28.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-04-00A-920A-APROC. REF: AMM 12-B-28-20-04-00A-920A-A								
280070	EJECTOR,TRANSFER RH PUMP							Component ATA:28
PN:9688471104	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B6122	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-05-00A-920A-APROC. REF: AMM 12-B-28-20-05-00A-920A-A								
280075	EJECTOR,DELIVERY RH PUMP							Component ATA:28
PN:9688471105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B6436	HRS	0		TSN 0				
WC#: 28.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-06-00A-920A-APROC. REF: AMM 12-B-28-20-06-00A-920A-A								
280080	FUEL QUANTITY,COLLECTOR RH SENSOR							Component ATA:28
PN:9753731250	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2613	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280085	FUEL QUANTITY,INNER RH SENSOR							Component ATA:28
PN:9753731251	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2613	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280090	FUEL QUANTITY,CENTRAL RH SENSOR							Component ATA:28
PN:9753731252	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2650	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280095	FUEL QUANTITY,OUTER RH SENSOR							Component ATA:28
PN:975.37.31.253	MOS/MSC	13-Aug-21	O/C	TSN 0				
SN:3351	HRS	714:24		TSN 0				
WC#: 28.060	AFL	659		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-APROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280100	FUEL,BOOSTER RH PUMP							Component ATA:28
PN:9688411405	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:C-901	HRS	0		TSN 0				
WC#: 28.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-28-20-04-00A-920A-APROC. REF: AMM 12-B-28-20-04-00A-920A-A								
280105	TOP CHECK VALVE							Component ATA:28
PN:9630423105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4002	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
280110	BOTTOM CHECK VALVE							Component ATA:28
PN:9630423105	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:4009	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280115	LH FUEL QUANTITY, TANK HARNESS							Component ATA:28
PN:9753731335	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1886	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
280120	RH FUEL QUANTITY, TANK HARNESS							Component ATA:28
PN:9753731335	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1886	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-10/153	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY							Service ATA:29
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-29-00-00-00A-902A-APROC. REF: AMM 12-B-29-00-00-00A-902A-A								
29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED							Service ATA:29
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-29-00-00-00A-902A-APROC. REF: AMM 12-B-29-00-00-00A-902A-A								
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)							Service ATA:29
PN:PN	MOS/MSC	30-Nov-23	N/A					
SN:NOT INSTALLED	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-29-10-02-00A-901A-APROC. REF: AMM 12-B-29-10-02-00A-901A-A								
29-10/259	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL							Service ATA:29
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.							Service ATA:29
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-29-00-00-00A-902A-APROC. REF: AMM 12-B-29-00-00-00A-902A-A								
29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)							Service ATA:29
PN:PN	MOS/MSC	30-Nov-23	N/A					
SN:NOT INSTALLED	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-29-10-02-00A-901A-APROC. REF: AMM 12-B-29-10-02-00A-901A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10/154 S	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-10-00-00A-313A-APROC. REF: AMM 12-B-30-10-00-00A-313A-A								
30-10/155 S	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-20-00-00A-903A-APROC. REF: AMM 12-B-30-20-00-00A-903A-A								
30-10/260 S	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-10-00-00A-903A-A, AMM 12-B-30-10-00-00A-903B-APROC. REF: AMM 12-B-30-10-00-00A-903A-A, AMM 12-B-30-10-00-00A-903B-A								
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1							Service ATA:30
	MOS/MSC	18-Oct-22	A/R	Adj -45d				
	HRS	1337:54						
WC#: 30.010	AFL	1976						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-20/156 U S	EXAMINE DE-ICE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED							Service ATA:30
PN:5302412155	MOS	01-Dec-25	12 (+10%/-10%)					
SN:11112	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-20/261 S	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-20/CUS U	DE-ICE LIP							Component ATA:30
PN:5302412155	MOS/MSC	01-Dec-25	H/T					
SN:11112	HRS	2149:16						
	AFL	2506						
30-30/329 S	FUNCTIONAL TEST PROBES DE-ICE SYSTEM							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-30-20-00A-903A-APROC. REF: AMM 12-B-30-30-20-00A-903A-A								
30-40/262 S	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM							Service ATA:30
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-30-40-00-00A-903A-APROC. REF: AMM 12-B-30-40-00-00A-903A-A								
30-60/158 S	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-60-00-00A-313A-A, AMM 12-B-30-60-00-00A-313B-APROC. REF: AMM 12-B-30-60-00-00A-313A-A, AMM 12-B-30-60-00-00A-313B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-60/159 S	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM							Service ATA:30
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-30-60-00-00A-903A-A, AMM 12-B-30-60-00-00A-903B-A, AMM 12-B-30-60-00-00A-903C-A, AMM 12-B-30-60-00-00A-903D-APROC. REF: AMM 12-B-30-60-00-00A-903A-A, AMM 12-B-30-60-00-00A-903B-A, AMM 12-B-30-60-00-00A-903C-A, AMM 12-B-30-60-00-00A-903D-A								
300005	PROP DE-ICE CONTROLLER							Component ATA:30
PN:9682913227	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:U3963	HRS	0		TSN 0				
WC#: 30.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300010	LPMI LINEAR ACTUATOR							Component ATA:30
PN:9787315302	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D96030	HRS	0		TSN 0				
WC#: 30.150	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300015	REGULATOR-RELIEVER ASSY							Component ATA:30
PN:9598901012	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N171888	HRS	0		TSN 0				
WC#: 30.160	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N172099	HRS	0		TSN 0				
WC#: 30.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-10-02-00A-920A-APROC. REF: AMM 12-B-30-10-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N172096	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-10-02-00A-920A-APROC. REF: AMM 12-B-30-10-02-00A-920A-A								
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N171856	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-10-02-00A-920A-APROC. REF: AMM 12-B-30-10-02-00A-920A-A								
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N171863	HRS	0		TSN 0				
WC#: 30.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-10-02-00A-920A-APROC. REF: AMM 12-B-30-10-02-00A-920A-A								
300045	EMPENAGE PRESSURE GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9070	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300050	WATER SEPARATOR							Component ATA:30
PN:959.90.20.143	MOS/MSC	05-Dec-19	O/C	TSN 0				
SN:UNKNOWN	HRS	539:30		TSN 0				
WC#: 30.060	AFL	482		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300055	DE-ICING SYSTEM TIMER							Component ATA:30
PN:9598901044	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UA146	HRS	0		TSN 0				
WC#: 30.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-60-01-00A-920A-APROC. REF: AMM 12-B-30-60-01-00A-920A-A								
300060	LEFT WINDSHIELD DE ICE CONTROLLER							Component ATA:30
PN:9728132202	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:137589	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-40-01-00A-920A-APROC. REF: AMM 12-B-30-40-01-00A-920A-A								
300065	RIGHT WINDSHIELD DE ICE CONTROLLER							Component ATA:30
PN:9728132202	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:137588	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-40-01-00A-920A-APROC. REF: AMM 12-B-30-40-01-00A-920A-A								
300090	LH HORIZ STAB DE-ICER BOOT							Component ATA:30
PN:9598901041	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEA3500	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-16-01-00A-920A-APROC. REF: AMM 12-B-30-16-01-00A-920A-A								
300095	RH HORIZ STAB DE-ICER BOOT							Component ATA:30
PN:9598901042	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEA2500	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-16-01-00A-920A-APROC. REF: AMM 12-B-30-16-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300100	RH INBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901038	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEB1980	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-14-01-00A-920A-APROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300105	RH OUTBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901040	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEB3430	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-14-01-00A-920A-APROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300110	LH AOA PLATE TEMP CONTROLLER							Component ATA:30
PN:9754421418	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UG271	HRS	0		TSN 0				
WC#: 30.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-30-21-00A-920A-APROC. REF: AMM 12-B-30-30-21-00A-920A-A								
300115	LH INBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901037	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEB1330	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-14-01-00A-920A-APROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300120	LH OUTBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901039	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:NEB4400	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-14-01-00A-920A-APROC. REF: AMM 12-B-30-14-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300125	RH AOA PLATE TEMP CONTROLLER							Component ATA:30
PN:9754421418	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UG273	HRS	0		TSN 0				
WC#: 30.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-30-21-00A-920A-APROC. REF: AMM 12-B-30-30-21-00A-920A-A								
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9085	HRS	0		TSN 0				
WC#: 30.180	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9084	HRS	0		TSN 0				
WC#: 30.180	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9075	HRS	0		TSN 0				
WC#: 30.190	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9074	HRS	0		TSN 0				
WC#: 30.190	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:N171865	HRS	0		TSN 0				
WC#: 30.200	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-30-10-02-00A-920A-APROC. REF: AMM 12-B-30-10-02-00A-920A-A								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-30/421 S	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)							Service ATA:31
PN:985.99.20.146	MOS	09-Jun-26	12 (+10%/-10%)					
SN:002181281	HRS	2313:14	1200 (+10%/-10%)					
	AFL	2655						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-31-30-01-00A-903A-APROC. REF: AMM 12-B-31-30-01-00A-903A-A								
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER							Component ATA:31
PN:9859912178	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMC2210-3060	HRS	0		TSN 0				
WC#: 31.180	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE							Component ATA:31
PN:9859912292	MOS/MSC	20-Mar-19	O/C					
SN:08071428	HRS	335:42						
WC#: 31.240	AFL	311						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE							Component ATA:31
PN:9859912292	MOS/MSC	20-Mar-19	O/C	TSN 0				
SN:1809F872	HRS	335:42		TSN 0				
WC#: 31.270	AFL	311		TSN 0				
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD							Component ATA:31
PN:9859912231	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1702H655	HRS	0		TSN 0				
WC#: 31.160	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310085	OVERHEAD CONTROL BASIC PANEL							Component ATA:31
PN:9728121155	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0797	HRS	0		TSN 0				
WC#: 31.260	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-31-10-00-00A-920A-APROC. REF: AMM 12-B-31-10-00-00A-920A-A								
310090	KMC2220 MF CONTOLLER							Component ATA:31
PN:9859912189	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMC2220-2152	HRS	0		TSN 0				
WC#: 31.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310095	PILOT KMC 2210 DISPLAY CONTROLLER							Component ATA:31
PN:9859912178	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMC2210-3058	HRS	0		TSN 0				
WC#: 31.180	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE							Component ATA:31
PN:9859912190	MOS/MSC	14-Jun-19	O/C					
SN:1707P498	HRS	423:06						
WC#: 31.230	AFL	385						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE							Component ATA:31
PN:9859912190	MOS/MSC	14-Jun-19	O/C					
SN:1706P428	HRS	423:06						
WC#: 31.230	AFL	385						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310105	MODULAR AVIONICS ,12SLOT UNIT							Component ATA:31
PN:9859912147	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:17089420	HRS	0		TSN 0				
WC#: 31.150	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-31-41-00-00A-920A-APROC. REF: AMM 12-B-31-41-00-00A-920A-A								
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD							Component ATA:31
PN:985.99.12.231	MOS/MSC	20-Jul-18	O/C	TSO 0				
SN:1511E279	HRS	143:48		TSO 0				
WC#: 31.160	AFL	155		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310115	NO. 1 LH MAU POWER SUPPLY MODULE							Component ATA:31
PN:0000008480	MOS/MSC	12-Jan-21	O/C					
SN:17055559	HRS	642:24						
WC#: 31.220	AFL	583						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310120	NO. 2 RH MAU POWER SUPPLY MODULE							Component ATA:31
PN:0000008480	MOS/MSC	12-Jan-21	O/C					
SN:16064455	HRS	642:24						
WC#: 31.220	AFL	583						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310125	MAU DUAL GENERIC I/O MODULE							Component ATA:31
PN:9859912252	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:17061953	HRS	0		TSN 0				
WC#: 31.250	AFL	0		TSN 0				
	ACH	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT							Component ATA:31
PN:9859912251	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:17081985	HRS	0		TSN 0				
WC#: 31.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-31-42-00-00A-920A-APROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2890004841	HRS	0		TSN 0				
WC#: 31.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:K9321022A00	MOS/MSC	24-Dec-21	O/C					
SN:1890239526	HRS	907						
WC#: 31.200	AFL	1086						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	06-Feb-19	O/C					
SN:1890383920	HRS	292:30		TSN 0				
WC#: 31.190	AFL	271		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2890004682	HRS	0		TSN 0				
WC#: 31.190	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310155	REV CTL PNL,4-POT DISPLAY							Component ATA:31
PN:9728121120	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0171	HRS	0		TSN 0				
WC#: 31.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE							Component ATA:31
PN:9858314204	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:40505180	HRS	0		TSN 0				
WC#: 31.210	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE							Component ATA:31
PN:9858314204	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:40505178	HRS	0		TSN 0				
WC#: 31.210	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310167	CC-500 CONTROL UNIT							Component ATA:31
PN:9859912202	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:32141	HRS	0		TSN 0				
WC#: 31.280	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310170	CCD INTERNAL ELECTRICAL ASSEMBLY							Component ATA:31
PN:9859912328	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0113	HRS	0		TSN 0				
WC#: 31.290	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310175	REAR CENTRE CONS PNL PC-12 47/E							Component ATA:31
PN:9728121154	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0788	HRS	0		TSN 0				
WC#: 31.300	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310177	MIDDLE CENTRE CONS PANEL							Component ATA:31
PN:9728121146	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0766	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
310180	COCKPIT AREA MICROPHONE							Component ATA:31
PN:9859920137	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00/236229	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-31-30-02-00A-920A-APROC. REF: AMM 12-B-31-30-02-00A-920A-A								
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT							Component ATA:31
PN:985.99.20.146	MOS/MSC	09-Jun-26	O/C	TSN 0				
SN:002181281	HRS	2313:14		TSN 0				
	AFL	2655		TSN 0				
PROC. REF: AMM 12-B-31-30-01-00A-920A-APROC. REF: AMM 12-B-31-30-01-00A-920A-A								
310198 U	MAU FAN ASSY LH							Component ATA:31
PN:9859912181	MOS/MSC	09-May-19	O/C	TSN 0				
SN:42900760	HRS	386:36		TSN 0				
	AFL	352		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310199 U	MAU FAN ASSY RH							Component ATA:31
PN:9859912181	MOS/MSC	14-Jun-19	O/C	TSN 2				
SN:42913921	HRS	423:06		TSN 0				
	AFL	385		TSN 0				
FXT031 U	INSP/CHCK FDR/CVR YEARLY							Service ATA:31
	MOS	21-Apr-26	12		21-Apr-27		177 d	
	HRS	2255:08						
	AFL	2603						
ATA 32 - LANDING GEAR								
32-10/162 S	LUBRICATE MAIN LANDING GEAR							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-04-00A-902A-APROC. REF: AMM 12-B-12-20-04-00A-902A-A								
32-10/163 S	EXAMINE MAIN LANDING GEAR LEGS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-10/164 S	EXAMINE MAIN LANDING GEAR COMPARTMENTS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/165 S	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-10-00-00A-902A-APROC. REF: AMM 12-B-32-10-00-00A-902A-A								
32-10/263 S	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-10/315 S	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
WC#: 32.010	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-10-00-00A-313A-A, AMM 12-B-32-10-00-00A-313B-APROC. REF: AMM 12-B-32-10-00-00A-313A-A, AMM 12-B-32-10-00-00A-313B-A								
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY							Component ATA:32
PN:5321012055	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:SI-1155	HRS	0		TSN 0				
WC#: 32.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY							Component ATA:32
PN:5321012056	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:SI-1156	HRS	0		TSN 0				
WC#: 32.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION (ELECTRO MECHANICAL LANDING GEAR)							Service ATA:32
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION (ELECTRO MECHANICAL LANDING GEAR)							Service ATA:32
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 32.215	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION							Service ATA:32
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION							Service ATA:32
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 32.220	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-10/436 S	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16						
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-APROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/438 S	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-APROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-10/438 S	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-APROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-10/439 S	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/439 S	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/440 S	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/440 S	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS							Service ATA:32
	MOS	04-Jan-18	120		04-Jan-28		435 d	
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS							Service ATA:32
	MOS	04-Jan-18	120		04-Jan-28		435 d	
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-APROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/80 S	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS							Service ATA:32
PN:40-424	MOS/MSC	01-Dec-25	12 (+10%/-10%) / T/C					
SN:3802/3785	HRS	2149:16						
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-06-00A-902A-APROC. REF: AMM 12-B-12-20-06-00A-902A-A								
32-10/80 S	LUBRICATE NOSE WHEEL BEARINGS							Service ATA:32
PN:40-423	MOS/MSC	01-Dec-25	12 (+10%/-10%) / T/C					
SN:1729	HRS	2149:16						
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-06-00A-902A-APROC. REF: AMM 12-B-12-20-06-00A-902A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/80 S	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS							Service ATA:32
PN:40-424	MOS/MSC	01-Dec-25	12 (+10%/-10%) / T/C					
SN:3801/3784	HRS	2149:16						
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-06-00A-902A-APROC. REF: AMM 12-B-12-20-06-00A-902A-A								
32-20/166 S	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-20-00-00A-902A-APROC. REF: AMM 12-B-32-20-00-00A-902A-A								
32-20/167 S	LUBRICATE NOSE LANDING GEAR							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-20-04-00A-902A-APROC. REF: AMM 12-B-12-20-04-00A-902A-A								
32-20/168 S	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING.							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20/169 S	EXAMINE NOSE LANDING GEAR COMPARTMENT							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20/265 S	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20/335	NOSE LANDING GEAR TORQUE TUBE							Component ATA:32
PN:PN	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.190	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20/403	NOSE LANDING GEAR - OVERHAUL							Component ATA:32
PN:PN	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	T:25000 (+500/-500)	TSN 0	25000	25500	22593:51 (+500)	
WC#: 32.200	AFL	0	T:30000 (+500/-500)	TSN 0	30000	30500	27277 (+500)	
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK REPLACEMENT							Component ATA:32
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000		22593:51	
WC#: 32.225	AFL	0	30000	TSN 0	30000		27277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-32-20-05-00A-920A-APROC. REF: AMM 12-B-32-20-05-00A-920A-A								
32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS/MSC	30-Nov-23	N/A					
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-32-30-00-00A-903A-APROC. REF: AMM 12-B-32-30-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30/423	LEFT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR REPLACEMENT							Component ATA:32
PN:9595601823	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:650	HRS	0		TSN 0				
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-APROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-A								
32-30/423	NOSE LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR REPLACEMENT							Component ATA:32
PN:9595601824	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:332	HRS	0		TSN 0				
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-APROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-A								
32-30/423	RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR REPLACEMENT							Component ATA:32
PN:9595601823	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:656	HRS	0		TSN 0				
	AFL	0	30000	TSN 0	30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-APROC. REF: AMM 12-B-32-30-02-00A-920B-A, AMM 12-B-32-30-01-00A-920B-A								
32-30/424 S	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	2000					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-30-10-00A-903A-APROC. REF: AMM 12-B-32-30-10-00A-903A-A								
32-30/425 S	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30/426 S		FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY						Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	2000					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-30-08-00A-903A-APROC. REF: AMM 12-B-32-30-08-00A-903A-A								
32-30/429 S		CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY						Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	2000					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-32-10-06-00A-313A-APROC. REF: AMM 12-B-32-10-06-00A-313A-A								
32-30/435		DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS						Service ATA:32
	MOS	31-Dec-17						DISCARD
	HRS	0						
	AFL	0	12000 (+500/-500)		12000	12500	9277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A								
32-30/435		DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS						Service ATA:32
	MOS	31-Dec-17						DISCARD
	HRS	0						
	AFL	0	12000 (+500/-500)		12000	12500	9277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A								
32-30/435		DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS						Service ATA:32
	MOS	31-Dec-17						DISCARD
	HRS	0						
	AFL	0	12000 (+500/-500)		12000	12500	9277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30/442 S	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-APROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-30/442 S	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	30-Nov-23	72					
	HRS	1639:26						
	AFL	2164						
								PKG:24
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-APROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE							Service ATA:32
	MOS/MSC	04-Jan-18	N/A					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE							Service ATA:32
	MOS/MSC	04-Jan-18	N/A					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-40/171 S	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40/172 S	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-10-04-00A-902A-APROC. REF: AMM 12-B-12-10-04-00A-902A-A								
32-40/173 S	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-40/174 S	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-12-10-04-00A-902A-APROC. REF: AMM 12-B-12-10-04-00A-902A-A								
32-40/175 S	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-40/176 S	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY							Service ATA:32
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 12-B-12-10-02-00A-902A-APROC. REF: AMM 12-B-12-10-02-00A-902A-A								
32-50/404	EXAMINE - NLG STEERING MECHANISM							Service ATA:32
	MOS	04-Jan-18						
	HRS	0	T:32500 (+10%/-10%)		32500	35750	30093:51 (+3250)	
WC#: 32.230	AFL	0	T:42000 (+10%/-10%)		42000	46200	39277 (+4200)	
	ACH	0						
PROC. REF: AMM 12-B-32-50-00-00A-310A-APROC. REF: AMM 12-B-32-50-00-00A-310A-A								
320005	PILOT LH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:6962	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-04-00A-920A-APROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320010	PILOT RH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7021	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-04-00A-920A-APROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320015	PARK BRAKE VALVE							Component ATA:32
PN:9594751121	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3065	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-05-00A-920A-APROC. REF: AMM 12-B-32-40-05-00A-920A-A								
320020	NOSE WHEEL							Component ATA:32
PN:40-423	MOS/MSC	01-Dec-25	O/C					
SN:1729	HRS	2149:16						
WC#: 32.150	AFL	2506						
PROC. REF: AMM 12-B-32-40-02-00A-920A-APROC. REF: AMM 12-B-32-40-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320021	NOSE LANDING GEAR TIRE							Component ATA:32
PN:PN	MOS/MSC	01-Dec-25	O/C					
SN:UNKNOWN	HRS	2149:16						
WC#: 32.155	AFL	2506						
PROC. REF: AMM 12-B-32-40-02-00A-920A-APROC. REF: AMM 12-B-32-40-02-00A-920A-A								
320022	LEFT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:40-424	MOS/MSC	01-Dec-25	O/C					
SN:3802/3785	HRS	2149:16						
WC#: 32.160	AFL	2506						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320023	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:025-350-0	MOS/MSC	01-Dec-25	O/C	TSN 5				
SN:4139T00341	HRS	2149:16		TSN 106:38				
WC#: 32.160	AFL	2506		TSN 73				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
320024	RIGHT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:40-424	MOS/MSC	01-Dec-25	O/C					
SN:3801/3784	HRS	2149:16						
WC#: 32.165	AFL	2506						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320025	SHIMMY DAMPER ASSY							Component ATA:32
PN:532.20.12.215	MOS/MSC	12-Jan-21	O/C	TSR 0				
SN:VLG1070	HRS	642:24		TSR 0				
WC#: 32.100	AFL	583		TSR 0				
PROC. REF: AMM 12-B-32-50-01-00A-920A-APROC. REF: AMM 12-B-32-50-01-00A-920A-A								
320026	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:025-350-0	MOS/MSC	01-Dec-25	O/C	TSN 3				
SN:4311T00154	HRS	2149:16		TSN 15:08				
WC#: 32.165	AFL	2506		TSN 12				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320030	COPILOT LH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1783	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-04-00A-920A-APROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320035	COPILOT RH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7191	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-04-00A-920A-APROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320040	NOSE FOLDING STRUT SPRING PACK ASSY							Component ATA:32
PN:5322012305	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:SI-0118	HRS	0		TSN 0				
WC#: 32.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-50-02-00A-920A-APROC. REF: AMM 12-B-32-50-02-00A-920A-A								
320045	NOSE LANDING GEAR STRUT ASSY							Component ATA:32
PN:532.20.12.044	MOS/MSC	12-Jan-21	O/C	TSN 11, TSR 0				
SN:SI-1269	HRS	642:24		TSN 52, TSR 0				
WC#: 32.090	AFL	583		TSN 56, TSR 0				
PROC. REF: AMM 12-B-32-50-02-00A-920A-APROC. REF: AMM 12-B-32-50-02-00A-920A-A								
320055	RIGHT SHOCK ABSORBER ASSY							Component ATA:32
PN:5321012230	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:SI-0956	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-APROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320060	LH BRAKE ASSY							Component ATA:32
PN:30-244	MOS/MSC	20-Mar-24	O/C	TSO 0				
SN:1915	HRS	1711:29		TSO 0				
WC#: 32.050	AFL	2216		TSO 0				
PROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-APROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-A								
320065	INNER LEFT WHEEL & COVER ASSY							Component ATA:32
PN:9595601503	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3785	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320066	OUTER LEFT WHEEL & COVER ASSY							Component ATA:32
PN:9595601503	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3802	HRS	0		TSN 0				
WC#: 32.205	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320080	LEFT SHOCK ABSORBER ASSY							Component ATA:32
PN:5321012230	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:SI-0959	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-APROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-A								
320085	RH BRAKE ASSY							Component ATA:32
PN:30-244	MOS/MSC	20-Mar-24	O/C	TSO 0				
SN:3828	HRS	1711:29		TSO 0				
WC#: 32.050	AFL	2216		TSO 0				
PROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-APROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320090	INNER RIGHT WHEEL & COVER ASSY							Component ATA:32
PN:9595601503	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3786	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320091	OUTER RIGHT WHEEL & COVER ASSY							Component ATA:32
PN:9595601503	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3803	HRS	0		TSN 0				
WC#: 32.210	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-40-01-00A-920A-APROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH							Component ATA:32
PN:9733033116	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:6571	HRS	0		TSN 0				
WC#: 32.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH							Component ATA:32
PN:9733033116	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:6560	HRS	0		TSN 0				
WC#: 32.175	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH							Component ATA:32
PN:9733033116	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:6567	HRS	0		TSN 0				
WC#: 32.180	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH							Component ATA:32
PN:9733033116	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:6572	HRS	0		TSN 0				
WC#: 32.170	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320140	INTERMEDIATE CABLE ASSY							Component ATA:32
PN:9595601816	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00356	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-APROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-A								
320140	MAIN GEAR CABLE ASSY							Component ATA:32
PN:9595601814	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00390	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-APROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-A								
320140	NOSE GEAR CABLE ASSY							Component ATA:32
PN:9595601815	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00343	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-APROC. REF: AMM 12-B-32-30-10-02A-920A-A, AMM 12-B-32-30-10-03A-920A-A, AMM 12-B-32-30-10-04A-920A-A								
320145	EXTENSION GEAR EMERGENCY HANDLE							Component ATA:32
PN:9595601838	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00336	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-32-30-10-01A-920A-APROC. REF: AMM 12-B-32-30-10-01A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320150	FRONT HIGH CURRENT RELAY							Component ATA:32
PN:9740926112	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:841	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320150	REAR HIGH CURRENT RELAY							Component ATA:32
PN:9740926112	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:840	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320155	LEFT HAND SPRING PACK ASSY							Component ATA:32
PN:5323412120	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:586	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320155	RIGHT HAND SPRING PACK ASSY							Component ATA:32
PN:5323412120	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:593	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320160	MLG L/H WOW NLG UP SWITCH ASSY							Component ATA:32
PN:5326921026	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2606	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320160	MLG R/H WOW NLG UP SWITCH ASSY							Component ATA:32
PN:5326921026	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2610	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
320190	LEFT MAIN LANDING GEAR YOKE FITTING							Component ATA:32
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
320190	RIGHT MAIN LANDING GEAR YOKE FITTING							Component ATA:32
PN:PN	MOS/MSC	04-Jan-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
ATA 33 - LIGHTS								
33-40/177 S	OPERATIONAL TEST EXTERIOR LIGHTING							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-33-40-00-00A-903A-APROC. REF: AMM 12-B-33-40-00-00A-903A-A								
33-41/178 S	EXAMINE LANDING LIGHTS - SET-IMC							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-33-41-01-00A-200B-APROC. REF: AMM 12-B-33-41-01-00A-200B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-42/179 S	EXAMINE TAXI LIGHTS							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-33-42-01-00A-200B-APROC. REF: AMM 12-B-33-42-01-00A-200B-A								
33-43/180 S	EXAMINE NAVIGATION AND STROBE LIGHTS							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-44/181 S	EXAMINE RECOGNITION LIGHTS (IF INSTALLED)							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-33-44-00-00A-903A-APROC. REF: AMM 12-B-33-44-00-00A-903A-A								
33-46/182 S	EXAMINE BEACON LIGHTS (IF INSTALLED)							Service ATA:33
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
330005	DIM UNIT							Component ATA:33
PN:9750215205	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:137704	HRS	0		TSN 0				
WC#: 33.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-10-04-00A-920A-APROC. REF: AMM 12-B-33-10-04-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
330010	DE-ICE LIGHT ASSY							Component ATA:33
PN:9728767111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3906401	HRS	0		TSN 0				
WC#: 33.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY							Component ATA:33
PN:9728787347	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:191113-3-22	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-46-00-00A-920A-APROC. REF: AMM 12-B-33-46-00-00A-920A-A								
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY							Component ATA:33
PN:03-3101-0001	MOS/MSC	12-Jan-21	O/C	TSN 0				
SN:226470-2-48	HRS	642:24		TSN 0				
WC#: 33.040	AFL	583		TSN 0				
PROC. REF: AMM 12-B-33-46-00-00A-920A-APROC. REF: AMM 12-B-33-46-00-00A-920A-A								
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY							Component ATA:33
PN:9728787344	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:189536-4-6	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-43-02-00A-920A-APROC. REF: AMM 12-B-33-43-02-00A-920A-A								
330045	RH WING POWER SUPPLY UNIT							Component ATA:33
PN:9728787179	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:187596-2-7	HRS	0		TSN 0				
WC#: 33.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-43-03-00A-920A-APROC. REF: AMM 12-B-33-43-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY							Component ATA:33
PN:9728787345	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:187596-5-12	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-43-02-00A-920A-APROC. REF: AMM 12-B-33-43-02-00A-920A-A								
330070	NOSE LANDING GEAR TAXI LIGHT							Component ATA:33
PN:9728769429	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:189952-3-2	HRS	0		TSN 0				
WC#: 33.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-42-01-00A-920A-APROC. REF: AMM 12-B-33-42-01-00A-920A-A								
330075	L/H 1X0005287-10 LANDING LIGHT							Component ATA:33
PN:9728769427	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:189952-1-9	HRS	0		TSN 0				
WC#: 33.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-41-01-00A-920A-APROC. REF: AMM 12-B-33-41-01-00A-920A-A								
330076	R/H 1X0005287-10 LANDING LIGHT							Component ATA:33
PN:972.87.69.432	MOS/MSC	10-Dec-24	O/C	TSN 0				
SN:6219858	HRS	1909:27		TSN 0				
WC#: 33.110	AFL	2345		TSN 0				
PROC. REF: AMM 12-B-33-41-01-00A-920A-APROC. REF: AMM 12-B-33-41-01-00A-920A-A								
330085	LEFT HAND RECOGNITION LED LIGHT							Component ATA:33
PN:9728769431	MOS/MSC	04-Jun-25	O/C	TSN 0				
SN:6640840	HRS	2020:33		TSN 0				
	AFL	2418		TSN 0				
PROC. REF: AMM 12-B-33-44-00-00A-920C-APROC. REF: AMM 12-B-33-44-00-00A-920C-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
330085	RIGHT HAND RECOGNITION LED LIGHT							Component ATA:33
PN:9728769428	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:189952-2-9	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-33-44-00-00A-920C-APROC. REF: AMM 12-B-33-44-00-00A-920C-A								
ATA 34 - NAVIGATION								
34-00/183 S	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS							Service ATA:34
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-00/184 S	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT - SET-IMC							Service ATA:34
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11/185 S	EXAMINE PITOT TUBE							Service ATA:34
	MOS	16-Mar-26	12 (+10%/-10%)					
	HRS	2232:24	300 (+10%/-10%)					
	AFL	2584						
								PKG:17 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11/186 S	EXAMINE STATIC PORTS							Service ATA:34
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11/268 S	DRAIN PITOT AND STATIC SYSTEM							Service ATA:34
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-34-11-00-00A-901A-APROC. REF: AMM 12-B-34-11-00-00A-901A-A								
34-11/343 S	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT - RVSM							Service ATA:34
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16						
WC#: 34.565	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-34-11-12-00A-313A-APROC. REF: AMM 12-B-34-11-12-00A-313A-A								
34-11/82 S	LEAK CHECK STATIC SYSTEM - RVSM							Service ATA:34
	MOS	01-Dec-25	24					
	HRS	2149:16						
WC#: 34.010	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-34-11-00-00A-903A-APROC. REF: AMM 12-B-34-11-00-00A-903A-A								
34-25/344 S	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION - RVSM							Service ATA:34
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16						
WC#: 34.570	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-34-14-00-00A-903B-APROC. REF: AMM 12-B-34-14-00-00A-903B-A								
34-26/484 S	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED)							Service ATA:34
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16						
	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-34-26-40-00A-903B-APROC. REF: AMM 12-B-34-26-40-00A-903B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-54/86	FUNCTIONAL TEST NO. 2 TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)							Service ATA:34
	MOS	01-Dec-25	24		01-Dec-27		401 d	
	HRS	2149:16						
	AFL	2506						
PROC. REF: AMM 12-B-34-54-00-00A-903A-A, AMM 12-B-34-54-00-00A-903B-A, AMM 12-B-34-54-10-00A-903A-A, AMM 12-B-34-54-10-00A-903B-APROC. REF: AMM 12-B-34-54-00-00A-903A-A, AMM 12-B-34-54-00-00A-903B-A, AMM 12-B-34-54-10-00A-903A-A, AMM 12-B-34-54-10-00A-903B-A								
34-54/86 S	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) - RVSM							Service ATA:34
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16						
WC#: 34.050	AFL	2506						
								PKG:21
PROC. REF: AMM 12-B-34-54-00-00A-903A-A, AMM 12-B-34-54-00-00A-903B-A, AMM 12-B-34-54-10-00A-903A-A, AMM 12-B-34-54-10-00A-903B-APROC. REF: AMM 12-B-34-54-00-00A-903A-A, AMM 12-B-34-54-00-00A-903B-A, AMM 12-B-34-54-10-00A-903A-A, AMM 12-B-34-54-10-00A-903B-A								
340010	DME/IFF ANTENNA							Component ATA:34
PN:9848110240	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:261-125641	HRS	0		TSN 0				
WC#: 34.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-52-02-00A-920A-APROC. REF: AMM 12-B-34-52-02-00A-920A-A								
340020	MARKER ANTENNA							Component ATA:34
PN:9848110260	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:101-8527	HRS	0		TSN 0				
WC#: 34.100	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-32-01-00A-920A-APROC. REF: AMM 12-B-34-32-01-00A-920A-A								
340055	WITH HARM FILTER,KN63 DME							Component ATA:34
PN:9859911101	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:39718	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-52-01-00A-920A-APROC. REF: AMM 12-B-34-52-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340065	WX-RADAR RT UNIT							Component ATA:34
PN:071-01550-0201	MOS/MSC	19-Jun-26	O/C	TSO 0				
SN:MX4007	HRS	2323:19		TSO 0				
WC#: 34.360	AFL	2661		TSO 0				
PROC. REF: AMM 12-B-34-41-02-00A-920A-APROC. REF: AMM 12-B-34-41-02-00A-920A-A								
340075	WX,VERTICAL ANTENNA							Component ATA:34
PN:9859911504	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:8495	HRS	0		TSN 0				
WC#: 34.370	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-41-12-00A-920A-APROC. REF: AMM 12-B-34-41-12-00A-920A-A								
340080	TRANSPONDER DME/IFF ANTENNA							Component ATA:34
PN:9848110240	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:261-125656	HRS	0		TSN 0				
WC#: 34.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-54-03-00A-920A-APROC. REF: AMM 12-B-34-54-03-00A-920A-A								
340085	ADF,KA44B ANTENNA							Component ATA:34
PN:9859911167	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KA44B-A95022	HRS	0		TSN 0				
WC#: 34.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-53-02-00A-920A-APROC. REF: AMM 12-B-34-53-02-00A-920A-A								
340100	FRONT KA92 ANTENNA							Component ATA:34
PN:9859911200	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:49310926	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-57-02-00A-920A-APROC. REF: AMM 12-B-34-57-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340101	REAR KA92 GPS ANTENNA							Component ATA:34
PN:9859911200	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:49310928	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-57-02-00A-920A-APROC. REF: AMM 12-B-34-57-02-00A-920A-A								
340131	KCM 805 CONFIGURATION MODULE							Component ATA:34
PN:9859911884	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:19877	HRS	0		TSN 0				
WC#: 34.410	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-25-03-00A-920A-APROC. REF: AMM 12-B-34-25-03-00A-920A-A								
340140	RADOME							Component ATA:34
PN:9857900003	MOS/MSC	05-Dec-19	O/C	TSO 1				
SN:549	HRS	539:30		TSO 0				
WC#: 34.420	AFL	482		TSO 0				
PROC. REF: AMM 12-B-34-41-02-00A-920A-A, AMM 12-B-34-41-05-00A-920A-APROC. REF: AMM 12-B-34-41-02-00A-920A-A, AMM 12-B-34-41-05-00A-920A-A								
340145	ANTENNA,VHF NAV COUPLER							Component ATA:34
PN:9848110412	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:9045	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-23-11-03-00A-920A-APROC. REF: AMM 12-B-23-11-03-00A-920A-A								
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA							Component ATA:34
PN:9848129101	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:543-88541	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-42-02-00A-920A-APROC. REF: AMM 12-B-34-42-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA							Component ATA:34
PN:9848129101	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:543-88554	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-42-02-00A-920A-APROC. REF: AMM 12-B-34-42-02-00A-920A-A								
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA							Component ATA:34
PN:9859911869	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:30979	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA							Component ATA:34
PN:9859911869	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:30969	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER							Component ATA:34
PN:9859911524	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KRA405B-19296	HRS	0		TSN 0				
WC#: 34.310	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-42-01-00A-920A-APROC. REF: AMM 12-B-34-42-01-00A-920A-A								
340220	STORMSCOPE WX-500 PROCESSOR							Component ATA:34
PN:9859918006	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:103207	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-41-31-00A-920A-APROC. REF: AMM 12-B-34-41-31-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340235	AOA SENSOR RH UNIT							Component ATA:34
PN:0012AC14	MOS/MSC	18-Jun-25	O/C	TSN 29				
SN:2471	HRS	2021:25		TSN 1001:07				
WC#: 34.330	AFL	2420		TSN 827				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340255	AOA SENSOR LH UNIT							Component ATA:34
PN:9754421423	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1865	HRS	0		TSN 0				
WC#: 34.330	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340265	DME/IFF--ATC DIV. ANTENNA							Component ATA:34
PN:9848110240	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:261-125665	HRS	0		TSN 0				
WC#: 34.500	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-54-03-00A-920A-APROC. REF: AMM 12-B-34-54-03-00A-920A-A								
340280	OUTBOARD KMG 7010 MAGNETOMETER							Component ATA:34
PN:9859912114	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMG7010-5016	HRS	0		TSN 0				
WC#: 34.520	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-APROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-A								
340285	INBOARD KMG 7010 MAGNETOMETER							Component ATA:34
PN:9859912114	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMG7010-5013	HRS	0		TSN 0				
WC#: 34.520	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-APROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340290	KMH920 TAWS B,TCAS 1 UNIT							Component ATA:34
PN:9859911887	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KMH920-B1997	HRS	0		TSN 0				
WC#: 34.545	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340310	NO. 2 KXP 2290 MODE S TRANSPONDER							Component ATA:34
PN:9859912269	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KXP2290A-3691	HRS	0		TSN 0				
WC#: 34.540	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-54-01-00A-920A-APROC. REF: AMM 12-B-34-54-01-00A-920A-A								
340315	NO. 1 KXP 2290 MODE S TRANSPONDER							Component ATA:34
PN:066-01198-0102	MOS/MSC	28-May-26	O/C	TSR 0				
SN:KXP2290A-M1992	HRS	2302:54		TSR 0				
WC#: 34.540	AFL	2649		TSR 0				
PROC. REF: AMM 12-B-34-54-01-00A-920A-APROC. REF: AMM 12-B-34-54-01-00A-920A-A								
340320	LH OAT SENSOR							Component ATA:34
PN:5341312025	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:06219	HRS	0		TSN 0				
WC#: 34.525	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340325	RH OAT SENSOR							Component ATA:34
PN:5341312025	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:06199	HRS	0		TSN 0				
WC#: 34.525	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT							Component ATA:34
PN:9859912272	MOS/MSC	05-Dec-19	O/C					
SN:KSG7200-B1516	HRS	539:30						
WC#: 34.505	AFL	482						
PROC. REF: AMM 12-B-34-25-01-00A-920A-APROC. REF: AMM 12-B-34-25-01-00A-920A-A								
340355	LH NAV/WHITE ANTENNA							Component ATA:34
PN:9848110280	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:168-11917	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
340357	RH NAV/WHITE ANTENNA							Component ATA:34
PN:9848110280	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:168-11918	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341035	NO. 1 KGS200,SBAS GNSSU UNIT							Component ATA:34
PN:9859912253	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KGS200-3162	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-57-01-00A-920A-APROC. REF: AMM 12-B-34-57-01-00A-920A-A								
341037	NO. 2 KGS200,SBAS GNSSU UNIT							Component ATA:34
PN:9859912253	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KGS200-3153	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-57-01-00A-920A-APROC. REF: AMM 12-B-34-57-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341039	MAG-3100 MAGNETOMETER							Component ATA:34
PN:9859003058	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:80935	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-34-26-45-00A-920B-A, AMM 12-B-34-26-45-00A-920C-APROC. REF: AMM 12-B-34-26-45-00A-920B-A, AMM 12-B-34-26-45-00A-920C-A								
341045	ESI-1000 STANDBY SYSTEM							Component ATA:34
PN:9759611247	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:3434	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
FXT-10 U	HEIGHT MONITORING HIGHT MONITORING RVSM CHECK VERIFICATION LINK HTTPS://WWW.EUROCONTROL.INT/RMALIVE/OPERATORLIST.DO							Service ATA:34
	MOS	26-Aug-26	24		26-Aug-28		670 d	RVSM
	HRS	2361:34						
	AFL	2696						
ATA 35 - OXYGEN								
35-10/187 S	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE - SET-IMC							Service ATA:35
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-10/188 S	CHECK OXYGEN SYSTEM CONTENTS - SET-IMC							Service ATA:35
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-10/269 S	EXAMINE OXYGEN PIPELINES AND EQUIPMENT - SET-IMC							Service ATA:35
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-10/458 S	OPERATIONAL TEST CREW OXYGEN SYSTEM - SET-IMC							Service ATA:35
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-35-00-00-00A-903A-A, AMM 12-B-35-00-00-00A-903B-APROC. REF: AMM 12-B-35-00-00-00A-903A-A, AMM 12-B-35-00-00-00A-903B-A								
35-10/6	REAR FUSELAGE OXYGEN CYLINDER REPLACEMENT - SET-IMC							Component ATA:35
PN:895-06077	MOS	18-Oct-22	180	TSO 0	28-Feb-37		3778 d	AIRWORTHINESS
SN:ALT281-53060	HRS	1337:54		TSO 0				
	AFL	1976		TSO 0				
			Manufacture Date:: 28-Feb-22					
PROC. REF: AMM 12-B-35-10-01-00A-920A-APROC. REF: AMM 12-B-35-10-01-00A-920A-A								
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER - SET-IMC							Service ATA:35
PN:895-06077	MOS	25-Jul-22	60		25-Jul-27		272 d	AIRWORTHINESS
SN:ALT281-53060	HRS							
	AFL							
			HydroCheck Date: : 25-Jul-22					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-20/452 S	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED) - SET-IMC							Service ATA:35
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	3000					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-35-00-00-00A-903B-APROC. REF: AMM 12-B-35-00-00-00A-903B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20/453	DISCARD NO. 1 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102296	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 2 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102290	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 3 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102305	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 4 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23103044	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 5 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	OVERHAUL
SN:D23102304	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 6 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102301	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20/453	DISCARD NO. 7 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102299	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 8 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23103038	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/453	DISCARD NO. 9 PASSENGER OXYGEN MASK CARTRIDGE							Service ATA:35
PN:PJ4-330345	MOS	30-Oct-23	72 (+6m/-6m)		30-Oct-29 (M)	30-Apr-30	1100 d (+182)	LIFE LIMIT
SN:D23102292	HRS	1711:29						
	AFL	2216						
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A								
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)							Service ATA:35
	MOS/MSC	06-Feb-19	N/A					
	HRS	292:18						
	AFL	271						
PROC. REF: AMM 12-B-35-00-00-00A-903A-APROC. REF: AMM 12-B-35-00-00-00A-903A-A								
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY							Component ATA:35
PN:9571201210	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B127126	HRS	0		TSN 0				
WC#: 35.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY							Component ATA:35
PN:9571201210	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:B127129	HRS	0		TSN 0				
WC#: 35.040	AFL	0		TSN 0				
	ACH	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350030	PRESSURE,GAGE,OXYGEN SWITCH							Component ATA:35
PN:9738114401	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1597	HRS	0		TSN 0				
WC#: 35.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350035	CONTR,3-POSITION,37071-03 VALVE							Component ATA:35
PN:9633211102	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0576	HRS	0		TSN 0				
WC#: 35.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-04-00A-920A-APROC. REF: AMM 12-B-35-20-04-00A-920A-A								
350050	OXYGEN GAGE ASSY							Component ATA:35
PN:5351212085	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:60291	HRS	0		TSN 0				
WC#: 35.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-05-00A-920A-APROC. REF: AMM 12-B-35-20-05-00A-920A-A								
350055	OXYGEN PRESS TRANSDUCER							Component ATA:35
PN:9571201184	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:8362-2-292	HRS	0		TSN 0				
WC#: 35.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350067	OXYGEN SHUT-OFF VALVE							Component ATA:35
PN:9571212232	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:000237503	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-06-00A-920A-APROC. REF: AMM 12-B-35-20-06-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350071	NO. 1 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16091358	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350072	NO. 2 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16091359	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350073	NO. 3 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16091367	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350074	NO. 4 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16091368	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16091373	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350076	NO. 6 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16100132	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350077	NO. 7 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16100140	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350078	NO. 8 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16100148	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350079	NO. 9 PASSENGER OXYGEN MASK ASSEMBLY							Component ATA:35
PN:9571201215	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:D16100166	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-35-20-03-00A-920A-APROC. REF: AMM 12-B-35-20-03-00A-920A-A								
350080	NO. 1 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102296	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350081	NO. 2 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102290	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350082	NO. 3 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102305	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350083	NO. 4 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23103044	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350084	NO. 5 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102304	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350085	NO. 6 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102301	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350086	NO. 7 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102299	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350087	NO. 8 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23103038	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
350088	NO. 9 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PJ4-330345	MOS/MSC	20-Mar-24	H/T	TSN 0				
SN:D23102292	HRS	1711:29		TSN 0				
	AFL	2216		TSN 0				
PROC. REF: AMM NO REFPROC. REF: AMM NO REF								
ATA 45 - CENTRAL MAINT SYSTEM								
45-45/454 S	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD							Service ATA:45
	MOS	21-Apr-26	12 (+10%/-10%)					
	HRS	2255:08	1200 (+10%/-10%)					
	AFL	2603						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-45-45-00-00A-551A-APROC. REF: AMM 12-B-45-45-00-00A-551A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 46 - INFORMATION SYSTEMS								
46-26/320	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES							Service ATA:46
	MOS	01-Dec-25	12 (+10%/-10%)	Adj -7d	24-Nov-26	30-Dec-26	29 d (+36)	
	HRS	2149:16	300 (+10%/-10%)		2449:16	2479:16	43:07 (+30)	
	AFL	2506						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-46-30-05-00A-903A-A, AMM 12-B-46-30-06-00A-903A-APROC. REF: AMM 12-B-46-30-05-00A-903A-A, AMM 12-B-46-30-06-00A-903A-A								
46-26/321 S	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES							Service ATA:46
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-46-30-02-00A-903A-APROC. REF: AMM 12-B-46-30-02-00A-903A-A								
460105	WIRELESS DATA LOADING DEVICE							Component ATA:46
PN:9759632456	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:2910	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 52 - DOORS								
52-10/189 S	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK							Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-10/190 S	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS							Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10/191 S		PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-10/192 S		EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-10/271 S		EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-10/348		EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR						Service ATA:52
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 52.070	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-52-10-00-00A-310A-APROC. REF: AMM 12-B-52-10-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10/405		EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE						Service ATA:52
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 52.100	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-52-00-01-00A-353A-APROC. REF: AMM 12-B-52-00-01-00A-353A-A								
52-10/406		EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN						Service ATA:52
	MOS	04-Jan-18						
	HRS	0	T:25000 (+500/-500)		25000	25500	22593:51 (+500)	
WC#: 52.110	AFL	0	T:30000 (+500/-500)		30000	30500	27277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-52-10-01-00A-353A-APROC. REF: AMM 12-B-52-10-01-00A-353A-A								
52-10/472		EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)						Service ATA:52
	MOS/MSC		N/A					
	HRS	EFF						
	AFL	EFF						
PROC. REF: AMM 12-B-52-10-06-00A-353A-APROC. REF: AMM 12-B-52-10-06-00A-353A-A								
52-10/88 S		EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED						Service ATA:52
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 52.010	AFL	2506						
								PKG:22
PROC. REF: AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-A, AMM 12-B-52-10-00-00A-313A-APROC. REF: AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-A, AMM 12-B-52-10-00-00A-313A-A								
52-20/272 S		EXAMINE EMERGENCY DOOR (DOOR REMOVED)						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20/273 S		EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-20/349		EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR						Service ATA:52
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 52.080	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-52-20-00-00A-310A-APROC. REF: AMM 12-B-52-20-00-00A-310A-A								
52-30/193 S		EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-30/194 S		EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-52-30-00-00A-313A-APROC. REF: AMM 12-B-52-30-00-00A-313A-A								
52-30/195 S		EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-30/274 S	EXAMINE CARGO DOOR							Service ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR							Service ATA:52
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 52.090	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-52-30-00-00A-310A-APROC. REF: AMM 12-B-52-30-00-00A-310A-A								
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE							Service ATA:52
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 52.120	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-52-30-00-01A-353A-APROC. REF: AMM 12-B-52-30-00-01A-353A-A								
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN							Service ATA:52
	MOS	04-Jan-18						
	HRS	0	T:25000 (+500/-500)		25000	25500	22593:51 (+500)	
WC#: 52.130	AFL	0	T:30000 (+500/-500)		30000	30500	27277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-52-30-01-00A-353A-APROC. REF: AMM 12-B-52-30-01-00A-353A-A								
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS REPLACEMENT							Component ATA:52
PN:PN	MOS	04-Jan-18		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0	13000	TSN 0	13000		10593:51	
WC#: 52.020	AFL	0	17000	TSN 0	17000		14277	
	ACH	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 52 - DOORS

PROC. REF: AMM 12-B-52-30-07-00A-920A-APROC. REF: AMM 12-B-52-30-07-00A-920A-A

52-30/89 S	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM						Service	ATA:52
	MOS	01-Dec-25	24 (+10%/-10%)				SEVERE CORROSION ZONE	
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 52.030	AFL	2506						
								PKG:22

PROC. REF: AMM 12-B-52-30-00-00A-313A-A, AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-APROC. REF: AMM 12-B-52-30-00-00A-313A-A, AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-A

52-70/275 S	OPERATIONAL TEST DOOR WARNING SYSTEM						Service	ATA:52
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18

PROC. REF: AMM 12-B-52-70-00-00A-903A-APROC. REF: AMM 12-B-52-70-00-00A-903A-A

520005	PASSENGER DOOR						Component	ATA:52
PN:5520512043	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 52.050	AFL	0		TSN 0				
	ACH	0						

PROC. REF: AMM 12-B-52-10-01-00A-920A-A, AMM 12-B-52-10-01-00A-920B-APROC. REF: AMM 12-B-52-10-01-00A-920A-A, AMM 12-B-52-10-01-00A-920B-A

520010	FREIGHT OF 10SERIE DOOR ASSY						Component	ATA:52
PN:5520512044	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 52.040	AFL	0		TSN 0				
	ACH	0						

PROC. REF: AMM 12-B-52-30-01-00A-920A-APROC. REF: AMM 12-B-52-30-01-00A-920A-A

520015	EMERGENCY 6 SERIE EXIT						Component	ATA:52
PN:5520512038	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 52.060	AFL	0		TSN 0				
	ACH	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 52 - DOORS

PROC. REF: AMM 12-B-52-20-01-00A-920A-APROC. REF: AMM 12-B-52-20-01-00A-920A-A

ATA 53 - FUSELAGE

53-00/196 S		EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						

PKG:17
WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

53-00/276 S		EXAMINE REAR PRESSURE BULKHEAD						Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

53-00/277 S		EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH FLOOR PANELS REMOVED						Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						

PKG:20
WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

53-00/278 S		EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						

PKG:21

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/279 S		EXAMINE BAGGAGE COMPARTMENT						Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/280 S		EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/324		STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)						Service ATA:53
	MOS/MSC	04-Jan-18	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/337 S		INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-53-20-02-00A-313A-APROC. REF: AMM 12-B-53-20-02-00A-313A-A								
53-00/351		UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION						Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.100	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-10-06-01A-353A-APROC. REF: AMM 12-B-53-10-06-01A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.110	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-10-00-00A-310A-APROC. REF: AMM 12-B-53-10-00-00A-310A-A								
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.120	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-20-00-00A-310A-APROC. REF: AMM 12-B-53-20-00-00A-310A-A								
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.130	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-30-00-00A-310A-APROC. REF: AMM 12-B-53-30-00-00A-310A-A								
53-00/355	EXAMINE - ANTENNA STRUCTURE							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.140	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-00-00-00A-310A-APROC. REF: AMM 12-B-53-00-00-00A-310A-A								
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:28300		28300		25893:51	
WC#: 53.150	AFL	0	T:37000		37000		34277	
	ACH	0						
PROC. REF: AMM 12-B-53-00-00-00A-353A-APROC. REF: AMM 12-B-53-00-00-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.160	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-00-00-00A-353A-APROC. REF: AMM 12-B-53-00-00-00A-353A-A								
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 53.180	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-03-00A-353A-APROC. REF: AMM 12-B-57-00-03-00A-353A-A								
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 53.190	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-53-20-02-00A-353A-APROC. REF: AMM 12-B-53-20-02-00A-353A-A								
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 53.200	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-APROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								
53-00/419	EDDY CURRENT INSPECTION - FRAME 40							Service ATA:53
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 53.210	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-APROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/9		STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (PRE SB 04-009)						Service ATA:53
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	20000		20000		17593:51	
WC#: 53.010	AFL	0	27000		27000		24277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/90 S		EXAMINE FRONT PRESSURE BULKHEAD - EXAMINE WITH INSULATION ON ENGINE SIDE REMOVED. ONLY IF INSULATION ON THE COCKPIT SIDE IS WET, REMOVE THE INSULATION DRY, EXAMINE THE STRUCTURE AND REINSTALL INSULATION						Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 53.030	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/91 S		EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)						Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 53.040	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/92 S		EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED						Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 53.070	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/93 S	EXAMINE STRUCTURE AROUND WINDOWS							Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 53.050	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-00/94 S	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES							Service ATA:53
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 53.060	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-30/342 S	INSPECTION/CHECK STATIC PORTS CRITICAL AREA - RVSM							Service ATA:53
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16						
WC#: 34.575	AFL	2506						
								PKG:20 WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-53-30-01-00A-313A-APROC. REF: AMM 12-B-53-30-01-00A-313A-A								
530070	FUSELAGE AB 1003 TEIL1							Component ATA:53
PN:5530512029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 53.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (PRE SB 04-009)							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	20000		20000		17593:51	
	AFL	0	27000		27000		24277	
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)							Service ATA:55
	MOS/MSC	04-Jan-18	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-10/197 S	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE							Service ATA:55
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-10/319 S	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT							Service ATA:55
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-55-00-00-00A-313A-APROC. REF: AMM 12-B-55-00-00-00A-313A-A								
55-10/415	HORIZONTAL STABILIZER REPLACEMENT							Component ATA:55
PN:PN	MOS	04-Jan-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000		22593:51	
WC#: 55.090	AFL	0	30000	TSN 0	30000		27277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-55-10-01-00A-920A-APROC. REF: AMM 12-B-55-10-01-00A-920A-A								
55-10/638	HORIZONTAL STABILIZER - EXAMINE WITH BORESCOPE							Service ATA:55
	MOS	04-Jan-18	T:240		04-Jan-38		4088 d	
	HRS	0	T:10000		10000		7593:51	
	AFL	0						
PROC. REF: AMM 12-B-55-10-01-00A-312A-APROC. REF: AMM 12-B-55-10-01-00A-312A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10/640	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.139)							Service ATA:55
	MOS	30-Nov-23	72 (+10%/-10%)		30-Nov-29	06-Jul-30	1131 d (+218)	
	HRS	1639:26						
	AFL	2164						
PROC. REF: AMM 12-B-55-00-00-01A-313A-APROC. REF: AMM 12-B-55-00-00-01A-313A-A								
55-10/641	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.158 AND .178)							Service ATA:55
	MOS/MSC	04-Jan-18	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-55-00-00-01A-313A-APROC. REF: AMM 12-B-55-00-00-01A-313A-A								
55-10/96 S	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)							Service ATA:55
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-20/362	EXAMINE LEFT WING ELEVATOR							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.100	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-20-00-00A-310A-APROC. REF: AMM 12-B-55-20-00-00A-310A-A								
55-20/362	EXAMINE RIGHT WING ELEVATOR							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-20-00-00A-310A-APROC. REF: AMM 12-B-55-20-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.110	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-20-01-00A-353A-APROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.120	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-20-01-00A-353A-APROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-20-01-00A-353A-APROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-30/198 S	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.							Service ATA:55
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-55-00-01-00A-664A-APROC. REF: AMM 12-B-55-00-01-00A-664A-A								
55-30/281 S	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS							Service ATA:55
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30/369	EXAMINE - VERTICAL STABILIZER							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.130	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-30-00-00A-310A-APROC. REF: AMM 12-B-55-30-00-00A-310A-A								
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.140	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-APROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.150	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-00-00-00A-353A-APROC. REF: AMM 12-B-55-00-00-00A-353A-A								
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.160	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-30-02-00A-353A-APROC. REF: AMM 12-B-55-30-02-00A-353A-A								
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40							Service ATA:55
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 55.190	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-55-30-03-00A-353A-APROC. REF: AMM 12-B-55-30-03-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40/373	EXAMINE - RUDDER							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.170	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-40-00-00A-310A-APROC. REF: AMM 12-B-55-40-00-00A-310A-A								
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES							Service ATA:55
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 55.180	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-55-40-05-00A-353A-APROC. REF: AMM 12-B-55-40-05-00A-353A-A								
55-40/410	EXAMINE - RUDDER TRIM TAB							Service ATA:55
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 55.200	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-55-40-04-00A-310A-APROC. REF: AMM 12-B-55-40-04-00A-310A-A								
ATA 56 - WINDOWS								
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED							Service ATA:56
	MOS/MSC	04-Jan-18	A/R					AIRWORTHINESS
	HRS	0						
WC#: 56.020	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED							Service ATA:56
	MOS/MSC	04-Jan-18	A/R					
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-56-00-00-00A-313A-APROC. REF: AMM 12-B-56-00-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)							Service ATA:56
PN:9598110109	MOS/MSC	04-Jan-18	A/R					
SN:15196H8811	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-APROC. REF: AMM 12-B-56-11-01-00A-920A-A								
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (RH) (INNER LAMINATION CRACKED)							Service ATA:56
PN:9598110110	MOS/MSC	04-Jan-18	A/R					
SN:16046H1580	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-APROC. REF: AMM 12-B-56-11-01-00A-920A-A								
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)							Service ATA:56
PN:9598110109	MOS/MSC	04-Jan-18	A/R					
SN:15196H8811	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)							Service ATA:56
PN:9598110110	MOS/MSC	04-Jan-18	A/R					
SN:16046H1580	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
56-11/200 S	EXAMINE WINDSHIELD LH AND RH							Service ATA:56
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-56-00-00-00A-313A-APROC. REF: AMM 12-B-56-00-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS							Service ATA:56
	MOS	04-Jan-18	120 (+6m/-6m)		04-Jan-28	04-Jul-28	435 d (+182)	
	HRS	0	11000 (+500/-500)		11000	11500	8593:51 (+500)	
WC#: 56.100	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-56-11-02-00A-313A-APROC. REF: AMM 12-B-56-11-02-00A-313A-A								
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED							Service ATA:56
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 56.110	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-53-10-16-00A-310A-A, AMM 12-B-56-11-01-00A-310A-A, AMM 12-B-56-11-02-00A-310A-APROC. REF: AMM 12-B-53-10-16-00A-310A-A, AMM 12-B-56-11-01-00A-310A-A, AMM 12-B-56-11-02-00A-310A-A								
56-11/517 S	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND							Service ATA:56
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REF, AMM NO REFPROC. REF: GENERIC NO REF, AMM NO REF								
56-20/201 S	EXAMINE COCKPIT AND CABIN WINDOWS							Service ATA:56
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-56-00-00-00A-313A-APROC. REF: AMM 12-B-56-00-00-00A-313A-A								
560015	SIDE,LH WINDOW							Component ATA:56
PN:9598110111	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:15232H2646	HRS	0		TSN 0				
WC#: 56.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-11-02-00A-920A-APROC. REF: AMM 12-B-56-11-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
560020	SIDE,RH WINDOW							Component ATA:56
PN:9598110112	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:15174H6545	HRS	0		TSN 0				
WC#: 56.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-11-02-00A-920A-APROC. REF: AMM 12-B-56-11-02-00A-920A-A								
560025	RH NO 1 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002567849-007	HRS	0		TSN 0				
WC#: 56.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560030	RH NO 2 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002579850-008	HRS	0		TSN 0				
WC#: 56.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560035	RH NO 3 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002551959-002	HRS	0		TSN 0				
WC#: 56.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560040	RH NO 4 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002579849-005	HRS	0		TSN 0				
WC#: 56.070	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
560045	RH NO 5 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002551966-011	HRS	0		TSN 0				
WC#: 56.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560050	LH NO 1 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002579849-003	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560055	LH NO 2 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002579846-003	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560060	LH NO 3 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002551966-004	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560065	LH NO 4 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:0002579850-004	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-20-01-00A-920A-APROC. REF: AMM 12-B-56-20-01-00A-920A-A								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
560070	DV-WINDOW ASSY							Component ATA:56
PN:5561412099	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:17216H2857	HRS	0		TSN 0				
WC#: 56.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-14-01-00A-920A-APROC. REF: AMM 12-B-56-14-01-00A-920A-A								
561010	LEFT HAND WINDSHIELD ASSY, (LH)							Component ATA:56
PN:9598110109	MOS/MSC	04-Jan-18	O/C	TSN 0				AIRWORTHINESS
SN:15196H8811	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-APROC. REF: AMM 12-B-56-11-01-00A-920A-A								
561011	RIGHT HAND WINDSHIELD ASSY, (RH)							Component ATA:56
PN:9598110110	MOS/MSC	04-Jan-18	O/C	TSN 0				AIRWORTHINESS
SN:16046H1580	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-APROC. REF: AMM 12-B-56-11-01-00A-920A-A								
ATA 57 - WINGS								
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE (PRE SB 04-009)							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	20000		20000		17593:51	
WC#: 57.010	AFL	0	27000		27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-040A-APROC. REF: AMM 12-B-57-00-00-00A-040A-A								
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (PRE SB 04-009)							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	20000		20000		17593:51	
WC#: 57.010	AFL	0	27000		27000		24277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-040A-APROC. REF: AMM 12-B-57-00-00-00A-040A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/202 S	EXAMINE WING EXTERNAL SURFACES							Service ATA:57
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/282 S	EXAMINE WING TIP STATIC DISCHARGERS							Service ATA:57
	MOS	01-Dec-25	24 (+10%/-10%)					
	HRS	2149:16	2400 (+10%/-10%)					
	AFL	2506						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/283 S	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS REMOVED							Service ATA:57
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/284 S	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE							Service ATA:57
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)							Service ATA:57
	MOS/MSC	04-Jan-18	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)							Service ATA:57
	MOS/MSC	04-Jan-18	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 57.100	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-310A-APROC. REF: AMM 12-B-57-00-00-00A-310A-A								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-310A-APROC. REF: AMM 12-B-57-00-00-00A-310A-A								
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:30000		30000		27593:51	
WC#: 57.110	AFL	0	T:39000		39000		36277	
	ACH	0						
PROC. REF: AMM 12-B-57-00-03-00A-353A-A, AMM 12-B-57-00-03-01A-353A-APROC. REF: AMM 12-B-57-00-03-00A-353A-A, AMM 12-B-57-00-03-01A-353A-A								
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 57.120	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353C-APROC. REF: AMM 12-B-57-20-10-00A-353C-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353C-APROC. REF: AMM 12-B-57-20-10-00A-353C-A								
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 57.130	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353A-APROC. REF: AMM 12-B-57-20-10-00A-353A-A								
57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353A-APROC. REF: AMM 12-B-57-20-10-00A-353A-A								
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 57.140	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-05-00A-353A-APROC. REF: AMM 12-B-57-20-05-00A-353A-A								
57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-05-00A-353A-APROC. REF: AMM 12-B-57-20-05-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
WC#: 57.150	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353B-APROC. REF: AMM 12-B-57-20-10-00A-353B-A								
57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:25000		25000		22593:51	
	AFL	0	T:30000		30000		27277	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353B-APROC. REF: AMM 12-B-57-20-10-00A-353B-A								
57-00/412	EXAMINE - WING TIPS							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 57.170	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-57-33-00-00A-310A-APROC. REF: AMM 12-B-57-33-00-00A-310A-A								
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES							Service ATA:57
	MOS	04-Jan-18						
	HRS	0	T:25000 (+500/-500)		25000	25500	22593:51 (+500)	
WC#: 57.180	AFL	0	T:30000 (+500/-500)		30000	30500	27277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-57-20-01-00A-353A-APROC. REF: AMM 12-B-57-20-01-00A-353A-A								
57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES							Service ATA:57
	MOS	04-Jan-18						
	HRS	0	T:25000 (+500/-500)		25000	25500	22593:51 (+500)	
	AFL	0	T:30000 (+500/-500)		30000	30500	27277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-57-20-01-00A-353A-APROC. REF: AMM 12-B-57-20-01-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/427		EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6						Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	16000		16000		13593:51	
	AFL	0	22500		22500		19777	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353D-APROC. REF: AMM 12-B-57-20-10-00A-353D-A								
57-00/427		EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6						Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	16000		16000		13593:51	
	AFL	0	22500		22500		19777	
	ACH	0						
PROC. REF: AMM 12-B-57-20-10-00A-353D-APROC. REF: AMM 12-B-57-20-10-00A-353D-A								
57-00/97 S		EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)						Service ATA:57
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 57.020	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/98 S		EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)						Service ATA:57
	MOS	01-Dec-25	24 (+10%/-10%)					SEVERE CORROSION ZONE
	HRS	2149:16	2000 (+10%/-10%)					
WC#: 57.030	AFL	2506						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-00/99		EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED						Service ATA:57
	MOS	04-Jan-18	180 (+6m/-6m)		04-Jan-33	04-Jul-33	2262 d (+181)	
	HRS	0						
WC#: 57.040	AFL	0						
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-313A-APROC. REF: AMM 12-B-57-00-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60/393	EXAMINE - RIGHT WING AILERON							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-57-60-00-00A-310A-APROC. REF: AMM 12-B-57-60-00-00A-310A-A								
57-60/393	EXAMINE -LEFT WING AILERON							Service ATA:57
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:32500		32500		30093:51	
WC#: 57.160	AFL	0	T:42000		42000		39277	
	ACH	0						
PROC. REF: AMM 12-B-57-60-00-00A-310A-APROC. REF: AMM 12-B-57-60-00-00A-310A-A								
57-60/411	EXAMINE - AILERON TRIM TAB							Service ATA:57
	MOS	04-Jan-18						
	HRS	0	T:32500 (+500/-500)		32500	33000	30093:51 (+500)	
WC#: 57.190	AFL	0	T:42000 (+500/-500)		42000	42500	39277 (+500)	
	ACH	0						
PROC. REF: AMM 12-B-57-60-04-00A-310A-APROC. REF: AMM 12-B-57-60-04-00A-310A-A								
570005	AILERON LH 10A SERIE ASSY							Component ATA:57
PN:5570512041	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7014	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-57-60-02-00A-920A-APROC. REF: AMM 12-B-57-60-02-00A-920A-A								
570010	AILERON RH 10A SERIE ASSY							Component ATA:57
PN:5570512042	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7001S	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-57-60-02-00A-920A-APROC. REF: AMM 12-B-57-60-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570050	L/H WING							Component ATA:57
PN:5570512049	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 57.080	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00A-520A-A, AMM 12-B-57-00-00-00A-520B-A, AMM 12-B-57-00-00-00A-720A-A, AMM 12-B-57-00-00-00A-720B-APROC. REF: AMM 12-B-57-00-00-00A-520A-A, AMM 12-B-57-00-00-00A-520B-A, AMM 12-B-57-00-00-00A-720A-A, AMM 12-B-57-00-00-00A-720B-A								
570055	R/H WING							Component ATA:57
PN:5570512050	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:7013	HRS	0		TSN 0				
WC#: 57.090	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-57-00-00-00B-520A-A, AMM 12-B-57-00-00-00B-520B-A, AMM 12-B-57-00-00-00B-720A-A, AMM 12-B-57-00-00-00B-720B-APROC. REF: AMM 12-B-57-00-00-00B-520A-A, AMM 12-B-57-00-00-00B-520B-A, AMM 12-B-57-00-00-00B-720A-A, AMM 12-B-57-00-00-00B-720B-A								
ATA 61 - PROPELLERS/PROPULSORS								
61-20/286 S	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS							Service ATA:61
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
610010	NO. 1 PROPELLER - OVERHAUL							Service ATA:61
	MOS	30-Nov-23	72		30-Nov-29	1131 d		OVERHAUL
	HRS	1643:16	4000		(5643:16) 5642:17	3236:08		
PROC. REF: POM 61-00-47, AMM 12-A-61-10-01-00A-920A-APROC. REF: POM 61-00-47, AMM 12-A-61-10-01-00A-920A-A								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAIL INSPECTION - POM 147 - 5-3.A.(1) TO (7)							Service ATA:61
	MOS	01-Dec-25	12		01-Dec-26	36 d		
	HRS	2150:15	300		(2450:15) 2449:16	43:07		
								WO#: FLEX26-1761-18
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER - POM 147 - 6-2.B.							Service ATA:61
	MOS	01-Dec-25	12		01-Dec-26		36 d	
	HRS	2150:15	400		(2550:15) 2549:16		143:07	
								WO#: FLEX26-1761-18
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
610050	NO. 1 PROPELLER - INSPECT BLADE EXPOSED SECTION USING COIN-TAP - POM 147 - 5-3.C.(1) (A)							Service ATA:61
	MOS	01-Dec-25						
	HRS	2150:15	1200		(3350:15) 3349:16		943:07	
PROC. REF: POM 61-00-47, MRM 61-13-70PROC. REF: POM 61-00-47, MRM 61-13-70								
610060	NO. 1 PROPELLER - INSPECT BLADE EROSION SHIELD USING COIN-TAP - POM 147 - 5-3.C.(1) (B)							Service ATA:61
	MOS	21-Apr-26	12		21-Apr-27		177 d	
	HRS	2256:07	600		(2856:07) 2855:08		448:59	
PROC. REF: POM 61-00-47, MRM 61-13-70PROC. REF: POM 61-00-47, MRM 61-13-70								
611025	NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service ATA:61
	MOS	01-Dec-25	12		01-Dec-26		36 d	
	HRS	2150:15	400		(2550:15) 2549:16		143:07	
								WO#: FLEX26-1761-18
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
611410	NO. 1 PROPELLER - HUB ASSEMBLY							Component ATA:61
PN:PN	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE							Component ATA:61
PN:9682913024	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:B6437	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE							Component ATA:61
PN:9682913024	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:B6293	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE							Component ATA:61
PN:9682913024	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:B6361	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE							Component ATA:61
PN:9682913024	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:B6406	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
611505	NO. 1 PROPELLER - NO. 5 PROPELLER BLADE							Component ATA:61
PN:9682913024	MOS/MSC	10-Oct-17	O/C	TSN 0				
SN:B6463	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
612010	NO. 1 ENGINE - PROPELLER GOVERNOR OVERHAUL							Component ATA:61
PN:3049558-01	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:20938357	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 61-20-00PROC. REF: EMM 61-20-00								
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR OVERHAUL							Component ATA:61
PN:3079148-01	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:20973900	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 61-20-00PROC. REF: EMM 61-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61PR1	NO. 1 PROPELLER							Component ATA:61
PN:HC-E5A-3A	MOS/MSC	14-Sep-19	PP/C					
SN:SA259	HRS	502		TSN 500:48				
WC#: 61.PR1	AFL	446						
PROC. REF: AMM 12-B-61-10-01-00A-920A-A, AMM 12-B-61-10-01-00A-920B-APROC. REF: AMM 12-B-61-10-01-00A-920A-A, AMM 12-B-61-10-01-00A-920B-A								
ATA 71 - POWER PLANT								
71-00/101 S	OPERATIONAL TEST POWER PLANT TORQUE LIMITER							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
WC#: 71.010	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903G-APROC. REF: AMM 12-B-71-00-00-00A-903G-A								
71-00/102 S	OPERATIONAL TEST POWER PLANT PERFORMANCE							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903H-APROC. REF: AMM 12-B-71-00-00-00A-903H-A								
71-00/103	PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS	21-Apr-26						
	HRS	2255:08	150		2405:08		OVD	
WC#: 71.040	AFL	2603						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-250A-APROC. REF: AMM 12-B-71-00-00-00A-250A-A								
71-00/104	PERFORM DESALINATION WASH IAW PILATUS AMM ONLY							Service ATA:71
	DAYS	21-Apr-26						
	HRS	2255:08	150		2405:08		OVD	
	AFL	2603						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-250A-APROC. REF: AMM 12-B-71-00-00-00A-250A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/105	PERFORM TURBINE WASH							Service ATA:71
	MOS	21-Apr-26						
	HRS	2255:08	150		2405:08		OVD	
	AFL	2603						
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-250A-APROC. REF: AMM 12-B-71-00-00-00A-250A-A								
71-00/107 S	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
WC#: 71.030	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-03-00A-250A-APROC. REF: AMM 12-B-71-00-03-00A-250A-A								
71-00/16	ENGINE MOUNTING FRAME (PRE SB 04-009)							Component ATA:71
PN:PN	MOS	04-Jan-18		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17593:51	
WC#: 71.050	AFL	0	27000	TSN 0	27000		24277	
	ACH	0		TSN 0				
PROC. REF: AMM 12-B-71-00-05-00A-920A-APROC. REF: AMM 12-B-71-00-05-00A-920A-A								
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS							Service ATA:71
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	11000		11000		8593:51	
WC#: 71.050	AFL	0						
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-00/204 S	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:71
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
								PKG:15 ,17,19,20,21
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903A-APROC. REF: AMM 12-B-71-00-00-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/205 S	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-00/209 S	ENGINE DRAIN MAST AND TANK - EXAMINE THE DRAIN MAST FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN THE COLLECTOR TANK							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-00/287 S	PERFORM PRE INSPECTION GROUND RUN - NOTE DEFECTS.							Service ATA:71
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
								PKG:15 ,17,19,20,21
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-71-00-00-00A-903A-APROC. REF: AMM 12-B-71-00-00-00A-903A-A								
71-00/301 S	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY.							Service ATA:71
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-54-20-02-00A-664A-APROC. REF: AMM 12-B-54-20-02-00A-664A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/327	ENGINE (POST SB 04-009) MOUNTING FRAME							Component ATA:71
PN:PN	MOS/MSC	04-Jan-18	N/A	TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY OVERHAUL							Component ATA:71
PN:9448121409	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:10140	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 71.063	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-00-00A-920A-BPROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY OVERHAUL							Component ATA:71
PN:9448121409	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:10148	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 71.064	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-00-00A-920A-BPROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY OVERHAUL							Component ATA:71
PN:9448121409	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:10172	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 71.061	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-00-00A-920A-BPROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY OVERHAUL							Component ATA:71
PN:9448121409	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:10173	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 71.060	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-00-00A-920A-BPROC. REF: AMM 12-B-71-00-00-00A-920A-B								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY OVERHAUL							Component ATA:71
PN:9448121409	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:10151	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 71.062	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-00-00A-920A-BPROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION							Service ATA:71
	MOS	04-Jan-18						AIRWORTHINESS
	HRS	0	T:26600		26600		24193:51	
WC#: 71.130	AFL	0	T:35000		35000		32277	
	ACH	0						
PROC. REF: AMM 12-B-71-00-05-00A-352A-APROC. REF: AMM 12-B-71-00-05-00A-352A-A								
71-00/476	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY							Service ATA:71
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-10/207 S	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001							Service ATA:71
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
								PKG:15 ,17,19,20,21
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-10/208	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR							Service ATA:71
	MOS/MSC	01-Dec-25	A/R					
	HRS	2149:16						
	AFL	2506						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710011	NO. 1 ENGINE - OVERHAUL							Service ATA:71
	MOS	10-Sep-17						OVERHAUL
	HRS	0	3500 (+200)		(3500) 3500	3700	1093:51 (+200)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
710019 S	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPESSOR ROTOR WITH A MIRROR OR A BORESCOPE - EMM TABLE 601-2-A							Service ATA:71
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 72-30-05PROC. REF: EMM 72-30-05								
710021	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:71
	MOS	18-Oct-22						
	HRS	1337:54	2000 (+50)		(3337:54) 3337:54	3387:54	931:45 (+50)	
	ENC	1821						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
710031 S	NO. 1 ENGINE - BORESCOPE HOT SECTION (PERFORM IN CONJUNCTION WITH FUEL NOZZLES TEST) - EMM TABLE 601-2-B							Service ATA:71
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)					
	ENC	2259						
								PKG:3 WO#: FLEX26-1761-18
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES - EMM TABLE 601-2-C							Service ATA:71
	MOS/MSC	10-Sep-17	N/A					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS/MSC	10-Sep-17	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00	PROC. REF: EMM 71-00-00							
710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	10-Sep-17	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00	PROC. REF: EMM 71-00-00							
710055	(WELDED) ENGINE MOUNT							Component ATA:71
PN:5712012036	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1510	HRS	0		TSN 0				
WC#: 71.120	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-71-00-05-00A-920A-A	PROC. REF: AMM 12-B-71-00-05-00A-920A-A							
710070 S	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION - EMM TABLE 601-3-B-(7)							Service ATA:71
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 71-00-00	PROC. REF: EMM 71-00-00							
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE							Service ATA:71
	MOS/MSC	28-Jun-21	A/R					
	HRS	657:30						
	ENC	601						
PROC. REF: EMM 72-00-00	PROC. REF: EMM 72-00-00							
71EN1	NO. 1 ENGINE							Component ATA:71
PN:PT6A-67P	MOS/MSC		E/C					
SN:PCE-RY0827	HRS							
WC#: 71.EN1	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 12-B-71-00-00-00A-920A-APROC. REF: AMM 12-B-71-00-00-00A-920A-A								
ATA 72 - ENGINE								
720010	NO. 1 ENGINE - GAS GENERATOR MODULE OVERHAUL							Component ATA:72
PN:PN	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+200)	TSN 0	(3500) 3500	3700	1093:51 (+200)	
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL - EMM TABLE 601-3-A-(1)							Service ATA:72
	MOS/MSC	01-Dec-25	BF/F					
	HRS	2149:16						
	ENC	2347						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP - EMM TABLE 601-3-A-(3)							Service ATA:72
	MOS/MSC	01-Dec-25	BF/F					
	HRS	2149:16						
	ENC	2347						
PROC. REF: EMM 72-60-00PROC. REF: EMM 72-60-00								
720030 S	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT - EMM TABLE 601-1-A-(1)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720040 S	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION - EMM TABLE 601-1-A-(2)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720050 S	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES - EMM TABLE 601-1-G-(1)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720070 S	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE - EMM TABLE 601-1-G-(2)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES							Service ATA:72
	MOS/MSC	08-Aug-22	A/R					
	HRS	1332:12						
	ENC	1800						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS - EMM TABLE 601-1-F							Service ATA:72
	MOS/MSC	10-Dec-24	BF/F					
	HRS	1909:27						
	ENC	2186						
PROC. REF: EMM 72-11-00PROC. REF: EMM 72-11-00								
722010 S	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS - EMM TABLE 601-1-B-(1)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-20-00, EMM 72-20-00PROC. REF: EMM 72-20-00, EMM 72-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
722020 S	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITHBORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACEAREAS AND STRUTS FOR CORROSION - EMM TABLE 601-1-B-(2)							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR REPLACEMENT							Component ATA:72
PN:3042701	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:MCAKAXRR221	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT REPLACEMENT							Component ATA:72
PN:3043063	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:PKAAA720208	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723026 S	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION - EMM TABLE 601-1-C							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR REPLACEMENT							Component ATA:72
PN:3040942	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:MCAKAXRK209	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723036 S	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS - EMM TABLE 601-1-D							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 72-30-04, EMM 72-30-01, EMM 72-30-02PROC. REF: EMM 72-30-04, EMM 72-30-01, EMM 72-30-02								
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR REPLACEMENT							Component ATA:72
PN:3040933	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:MCAKAXRR058	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR REPLACEMENT							Component ATA:72
PN:3040944	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:EAAE000F365	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER REPLACEMENT							Component ATA:72
PN:3036898	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:FRAEPWEK86	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24159 (M)		21436	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	10-Sep-17	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
724060	NO. 1 ENGINE - HIGH TORQUE INDICATION AT LOW POWER							Service ATA:72
	MOS/MSC	10-Sep-17	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK REPLACEMENT							Component ATA:72
PN:3053740-01	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:YUAB001J398	HRS	0		TSN 0				
	ENC	0		TSN 0	(8000) 8159 (M)		5436	
	ACCCYC	0	8000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES							Service ATA:72
	MOS	10-Sep-17						LIFE LIMIT
	HRS	0	5000		(5000) 5000		2593:51	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725026 S	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION - EMM TABLE 601-1-E							Service ATA:72
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-50-05PROC. REF: EMM 72-50-05								
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK REPLACEMENT							Component ATA:72
PN:3037312	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:A004403E	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15159 (M)		12436	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK REPLACEMENT							Component ATA:72
PN:3037313	MOS	10-Sep-17		TSN 0				LIFE LIMIT
SN:YUAB001J608	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15159 (M)		12436	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725122	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	10-Sep-17	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726010	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3059343-01	MOS/MSC	10-Sep-17	O/C	TSN 0				
SN:PKAAA724914	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726020		NO. 1 ENGINE - POWER SECTION MODULE OVERHAUL						Component ATA:72
PN:PN	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+200)	TSN 0	(3500) 3500	3700	1093:51 (+200)	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 73 - ENGINE FUEL AND CONTROL								
731010		NO. 1 ENGINE - FUEL PUMP OVERHAUL						Component ATA:73
PN:3040760	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:015409	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731025 S		NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (PERFORM IN CONJUNCTION WITH BOROSCOPE HOT SECTION) (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) - EMM TABLE 601-3-B-(9)-(B)						Service ATA:73
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)					
	ENC	2259						
								PKG:3
								WO#: FLEX26-1761-18
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
731030		NO. 1 ENGINE - OVERTORQUE LIMITER OVERHAUL						Component ATA:73
PN:3055748-01	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:C51726	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731031 S		NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE - EMM TABLE 601-3-B-(1)						Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731035		NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION - EMM TABLE 601-3-B-(11)						Service ATA:73
	MOS	30-Nov-23						
	HRS	1639:26	1750 (+100)		(3389:26) 3389:26	3489:26	983:17 (+100)	
	ENC	2003						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731040		NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN - EMM TABLE 601-3-B-(2)						Service ATA:73
PN:3040760	MOS	04-Mar-26						
SN:015409	HRS	2220:17	600 (+10%/-10%)		(2820:17) 2820:17	2880:17	414:08 (+60)	
	ENC	2409						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731045 S		NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION - EMM TABLE 601-3-B-(10)						Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								
731052		NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. - EMM TABLE 601-3-B-(4)-(B)						Service ATA:73
	MOS/MSC	10-Sep-17	N/A					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER - EMM TABLE 601-3-B-(3)							Service ATA:73
PN:PN	MOS	04-Mar-26						REPLACE
SN:UNKNOWN	HRS	2220:17	600 (+10%/-10%)		(2820:17) 2820:17	2880:17	414:08 (+60)	
	ENC	2409						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731056 S	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS - EMM TABLE 601-3-D-(1)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731060	NO. 1 ENGINE - OIL TO FUEL HEATER OVERHAUL							Component ATA:73
PN:3057249-01	MOS	10-Sep-17		TSN 0				
SN:WA56118	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								
731065 S	NO. 1 ENGINE - EXAMINE FILTER BOWL - EMM TABLE 601-3-D-(4)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE OVERHAUL							Component ATA:73
PN:3038472	MOS	10-Sep-17		TSN 0				
SN:U0847	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731085 S	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE - EMM TABLE 601-3-B -(5)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-10-06PROC. REF: EMM 73-10-06								
731090	NO. 1 ENGINE - FUEL CONTROL UNIT OVERHAUL							Component ATA:73
PN:3119892-10	MOS	10-Sep-17		TSN 0				OVERHAUL
SN:21002003	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
731091 S	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE - EMM TABLE 601-3-B-(8)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731100 S	NO. 1 ENGINE - CLEAN P3 FILTER - EMM TABLE 601-3-D-(2)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								
731150 S	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION - EMM TABLE 601-3-B-(3)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER							Component ATA:73
PN:PN	MOS/MSC	04-Mar-26	H/T	TSN 0				
SN:UNKNOWN	HRS	2220:17		TSN 0				
	ENC	2409		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
732020 S	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES - SET-IMC - EMM TABLE 601-3-B-(6)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
733020	NO. 1 ENGINE - REPLACE P3 FILTER - EMM TABLE 601-3-D-(5)							Service ATA:73
	MOS	30-Nov-23						
	HRS	1639:26	900 (+10%/-10%)		(2539:26) 2539:26	2629:26	133:17 (+90)	
	ENC	2003						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								
733060	NO. 1 ENGINE - FORWARD FUEL DRAIN VALVE							Component ATA:73
PN:PN-UNKNOWN	MOS/MSC	13-Jul-18	O/C					
SN:UNKNOWN	HRS	135:54						
	ENC	119						
PROC. REF: EMM 73-10-06PROC. REF: EMM 73-10-06								
733070 S	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY - EMM TABLE 601-3-D-(3)							Service ATA:73
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2 WO#: FLEX26-1761-18
PROC. REF: EMM 73-10-07, EMM 73-10-07PROC. REF: EMM 73-10-07, EMM 73-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-00/288 S	OPERATIONAL TEST IGNITION SYSTEM - SET-IMC							Service ATA:74
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-74-00-00-00A-903A-APROC. REF: AMM 12-B-74-00-00-00A-903A-A								
740010	NO. 1 ENGINE - IGNITION EXCITER OVERHAUL							Component ATA:74
PN:3035889	MOS	10-Sep-17		TSN 0				
SN:NNA17240233	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								
740015 S	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION - SET-IMC - EMM TABLE 601-3-C-(1)							Service ATA:74
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)					
	ENC	2259						
								PKG:3
								WO#: FLEX26-1761-18
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								
740025 S	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION - SET-IMC - EMM TABLE 601-3-C-(3)							Service ATA:74
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)					
	ENC	2259						
								PKG:3
								WO#: FLEX26-1761-18
PROC. REF: EMM 74-20-00PROC. REF: EMM 74-20-00								
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG							Component ATA:74
PN:CH34055	MOS/MSC	04-Jun-25	O/C	TSN 0				
SN:NSN	HRS	2020:33		TSN 0				
	ENC	2259		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742010 S	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION - SET-IMC - EMM TABLE 601-3-C-(2)							Service ATA:74
	MOS	04-Jun-25						
	HRS	2020:33	400 (+10%/-10%)					
	ENC	2259						
								PKG:3
								WO#: FLEX26-1761-18
PROC. REF: EMM 74-20-00PROC. REF: EMM 74-20-00								
ATA 75 - AIR								
750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE OVERHAUL							Component ATA:75
PN:3059835-01	MOS	10-Sep-17		TSN 0				
SN:AHX1001229	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	1093:51 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-00PROC. REF: EMM 75-30-00								
ATA 76 - ENGINE CONTROLS								
76-00/210 S	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT							Service ATA:76
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
76-00/211 S	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM)							Service ATA:76
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-00/212 S		OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE.						Service ATA:76
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-76-10-00-00A-903A-APROC. REF: AMM 12-B-76-10-00-00A-903A-A								
76-00/303 S		OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE						Service ATA:76
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-76-10-00-00A-903A-A, AMM 12-B-76-20-00-00A-903A-APROC. REF: AMM 12-B-76-10-00-00A-903A-A, AMM 12-B-76-20-00-00A-903A-A								
76-00/304 S		EXAMINE COCKPIT CONTROL QUADRANT						Service ATA:76
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
76-10/117 S		FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES						Service ATA:76
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	3000 (+10%/-10%)					
WC#: 76.010	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-76-10-02-00A-903A-APROC. REF: AMM 12-B-76-10-02-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760015	MANUAL OVERRIDE CABLE ASSY.							Component ATA:76
PN:9419411417	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00148	HRS	0		TSN 0				
WC#: 76.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-76-20-00-04A-920A-APROC. REF: AMM 12-B-76-20-00-04A-920A-A								
760020	CONDITION CABLE ASSY.							Component ATA:76
PN:9419411418	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00083	HRS	0		TSN 0				
WC#: 76.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
760025	POWER CONTROL CABLE ASSY.							Component ATA:76
PN:9419411419	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:00152	HRS	0		TSN 0				
WC#: 76.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-76-10-04-00A-920A-APROC. REF: AMM 12-B-76-10-04-00A-920A-A								
761011 S	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES - EMM TABLE 601-1-A-(4)							Service ATA:76
	MOS	01-Dec-25	12 (+30d/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER							Component ATA:77
PN:9752115206	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:8032-2-190	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-77-40-03-00A-920A-APROC. REF: AMM 12-B-77-40-03-00A-920A-A								
770025	DIFFERENTIAL PRESSURE TRANSDUCER							Component ATA:77
PN:9752115219	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:10658712	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS							Component ATA:77
PN:3043825-01	MOS/MSC	10-Sep-17	O/C	TSN 0				
SN:NRA102260	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
ATA 78 - EXHAUST								
78-00/214 S	EXAMINE EXHAUST STUBS							Service ATA:78
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 79 - OIL								
79-00/422 S	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK							Service ATA:79
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	600 (+10%/-10%)					
	AFL	2506						
								PKG:19
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-79-30-06-00A-903A-APROC. REF: AMM 12-B-79-30-06-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20/289 S	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT							Service ATA:79
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	1200 (+10%/-10%)					
	AFL	2506						
								PKG:20
								WO#: FLEX26-1761-18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-20/290 S	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM - SET-IMC							Service ATA:79
	MOS	01-Dec-25	12 (+10%/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	AFL	2506						
								PKG:17
								WO#: FLEX26-1761-18
PROC. REF: AMM 12-B-79-30-01-00A-903A-APROC. REF: AMM 12-B-79-30-01-00A-903A-A								
79-20/43	OIL COOLER OVERHAUL							Component ATA:79
PN:9683214102	MOS	04-Jan-18		TSN 0				OVERHAUL
SN:T1789	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	1093:51 (+350)	
WC#: 79.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-79-20-02-00A-920A-APROC. REF: AMM 12-B-79-20-02-00A-920A-A								
790005	TEMPERATURE BULB							Component ATA:79
PN:9751120101	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:218278	HRS	0		TSN 0				
WC#: 79.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
790020	PRESSURE,GAGE SWITCH							Component ATA:79
PN:9738114305	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1702	HRS	0		TSN 0				
WC#: 79.030	AFL	0		TSN 0				
	ACH	0						
PROC. REF: AMM 12-B-79-30-04-00A-920A-APROC. REF: AMM 12-B-79-30-04-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM							Service ATA:79
	MOS/MSC	10-Sep-17	A/R					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
790025	THERMAL ACTUATOR							Component ATA:79
PN:9787301002	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1980	HRS	0		TSN 0				
WC#: 79.040	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
790031 S	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR - SET-IMC - EMM TABLE 601-3-A-(7)							Service ATA:79
	MOS	01-Dec-25	12 (+30d/-10%)					
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
790040 S	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR - SET-IMC - EMM TABLE 601-3-A-(8)							Service ATA:79
	MOS	01-Dec-25	12 (+1m/-1m)					
	HRS	2149:16	600 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT - EMM TABLE 601-3-A-(6)							Service ATA:79
	MOS	30-Nov-23						
	HRS	1639:26	900 (+10%/-10%)		(2539:26) 2539:26	2629:26	133:17 (+90)	
	ENC	2003						
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790060 S	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN - EMM TABLE 601-3-A-(4)							Service ATA:79
	MOS	01-Dec-25						
	HRS	2149:16	300					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
790070 S	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN - EMM TABLE 601-3-A-(10)							Service ATA:79
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-60-00PROC. REF: EMM 72-60-00								
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE - EMM TABLE 601-3-A-(5)							Service ATA:79
	MOS	01-Dec-25	12		01-Dec-26		36 d	
	HRS	2149:16	300 (+10%/-10%)		(2449:16) 2449:16	2479:16	43:07 (+30)	
	ENC	2347						
								WO#: FLEX26-1761-18
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING - EMM TABLE 601-3-A-(2)							Service ATA:79
	MOS	01-Dec-25	12		01-Dec-26		36 d	
	HRS	2149:16	300 (+10%/-10%)		(2449:16) 2449:16	2479:16	43:07 (+30)	
	ENC	2347						
								WO#: FLEX26-1761-18
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
790091 S	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS - EMM TABLE 601-1-A-(3)							Service ATA:79
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 79 - OIL

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

790093 S	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS - EMM TABLE 601-3-A-(9)							Service ATA:79
	MOS	01-Dec-25						
	HRS	2149:16	300 (+10%/-10%)					
	ENC	2347						
								PKG:2
								WO#: FLEX26-1761-18

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER							Component ATA:79
PN:9752115214	MOS/MSC	10-Sep-17	O/C	TSN 0				
SN:8292-5-384	HRS	0		TSN 0				
	ENC	0		TSN 0				

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

ATA 91 - UNKNOWN

910010	LEFT HD POWER JCT BOX							Component ATA:91
PN:9740338144	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:1039	HRS	0		TSN 0				
	AFL	0		TSN 0				
	ACH	0						

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

910015	KBT 300 TTP BUS RES, A-157 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KBT300-4421	HRS	0		TSN 0				
WC#: 90.015	AFL	0		TSN 0				
	ACH	0						

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

910020	KBT 300 TTP BUS RES, A-175 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KBT300-4466	HRS	0		TSN 0				
WC#: 90.025	AFL	0		TSN 0				
	ACH	0						

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 91 - UNKNOWN								
910025	KBT 300 TTP BUS RES, A-174 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KBT300-4454	HRS	0		TSN 0				
WC#: 90.020	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
910035	CO-PILOT RIGHT HD POWER,FE1549R JUNCTION BOX							Component ATA:91
PN:9740338145	MOS/MSC	20-Mar-19	O/C					
SN:225	HRS	335:42						
WC#: 90.030	AFL	311						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
910040	KBT 300 TTP BUS RES, A-156 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	04-Jan-18	O/C	TSN 0				
SN:KBT300-4429	HRS	0		TSN 0				
WC#: 90.010	AFL	0		TSN 0				
	ACH	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS