

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: PIERRE BOUSQUET +33 (0) 1.55.93.45.80 (OFFICE)
EMAIL: PIERRE.BOUSQUET@CAMPSYSTEMS.EU +33 (0) 1.53.01.66.18 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 522/LX-JFH **MODEL:** PC12 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 28-OCT-2003	8139 A/C HRS as of 07-OCT-2018	A/C HRS as of ___/___/___
	7282 AFL as of 07-OCT-2018	AFL as of ___/___/___
	949:24 ACH as of 03-AUG-2018	ACH as of ___/___/___
	6883 FLTS as of 07-OCT-2018	FLTS as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0796/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 30-JUL-2018	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 8020:35 A/C HRS	118:25 ENG. HRS as of 07-OCT-2018	ENG. HRS as of ___/___/___
0 ENC	107 ENC as of 07-OCT-2018	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: KX-738/HC-E4A-3D/E10477SK **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 09-DEC-2015	LAST ACTUALS	CURRENT ACTUAL
2427:05 PROP HRS 6419:30 A/C HRS	4146:35 PROP HRS as of 07-OCT-2018	PROP HRS as of ___/___/___



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05JFL02	ANNUAL INSPECTION							
	PKG 2	MOS	12			03-AUG-2018	03-AUG-2019	03-SEP-2019
		HRS/MSC				8020:35		
	REF:	AFL				7175		
05JFL03	150 HOURS INSPECTION							
	PKG 4 in PKG 2	MOS	12			03-AUG-2018	03-AUG-2019	
		HRS/MSC	150		4:40	8020:35	8175:15	8190:15
	REF:	AFL				7175		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0796 Part # 3042200								
+ 057010	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 2	MOS				24-MAY-2018		
		HRS/MSC	300			0	(300) 8320:35	
	REF: See Workcard	ENC				0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED PKG 2,4 REF:	MOS HRS/MSC AFL	12 100	+1m/-1m			PKG 03-AUG-2018 8020:35 7175		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL REF:	MOS HRS/MSC AFL	-				29-AUG-2018 8035:20 7227		
00JFL60	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 0 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL REF:	MOS HRS/MSC AFL	-				13-APR-2017 7080:50 6348		
00JFL61	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 1 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL REF:	MOS HRS/MSC AFL	-				22-MAR-2018 7729:20 6916		
00JFL62	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 2 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL REF:	MOS HRS/MSC AFL	-				03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL63	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 3 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - AFL							
	REF:								
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF	MOS					04-MAY-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-160717	REVIEW PILATUS PC12 AMM REV 32	MOS					23-NOV-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS					07-FEB-2017		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS					29-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
	NEW REQUIREMENT ADDED ON 03-OCT-2018 (EFFECTIVE: 17-SEP-2018). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180821	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM	REV 47.2			(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
NEW REQUIREMENT ADDED ON 21-SEP-2018 (EFFECTIVE: 21-AUG-2018). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.									
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX-738 Part # HC-E4A-3D/E10477SK									
P019-150423	NO. 1 PROPELLER - REVIEW	HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						10-SEP-2015 2302:25	
P019-150901	NO. 1 PROPELLER - REVIEW	HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -					(EBT)		
P019-160201 (s)	NO. 1 PROPELLER - REVIEW	HARTZWELL PROPELLER HC-E4A-3 POM REV 22							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						31-JAN-2017	
P019-160801	NO. 1 PROPELLER - REVIEW	HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						16-SEP-2016	
P019-171001	NO. 1 PROPELLER - REVIEW	HARTZELL HC-E4A-3 POM 149 REV 23							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						22-FEB-2018	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-180301	NO. 1 PROPELLER - REVIEW	HARTZELL HC-34A-3	POM 147	REV 14			(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
P019-180701	NO. 1 PROPELLER - REVIEW	HC-E4A-3	POM 149	REV 24			(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05JFL11	- AIRWORTHINESS REVIEW CERTIFICATE							06-NOV-2017 7571:50 6764	14-NOV-2018 M
REF:		MOS HRS/MSC AFL	DUE						
05JFL12	- CERTIFICATE OF REGISTRATION						15-JAN-2008		
REF:		MOS HRS/MSC AFL	A/R						
05JFL13	- NOISE CERTIFICATE						25-SEP-2006		
REF:		MOS HRS/MSC AFL	A/R						
05JFL14	- AIRCRAFT STATION LICENCE						18-JAN-2018		31-DEC-2018 M
REF:		MOS HRS/MSC AFL	DUE						



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING								
		MOS					03-AUG-2018		
	REF:	HRS/MSC	150	+10%/-10%		12:05	8020:35	8182:40	8197:40
		AFL					7175		
		ACH	150	+10%/-10%			949:24	1099:24	1114:24

CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 4 ,2	MOS					03-AUG-2018		
	REF:	HRS/MSC	100				8020:35		
		AFL					7175		

06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 4 ,2	MOS					03-AUG-2018		
	REF: AMM 06-20-00	HRS/MSC	100				8020:35		
		AFL					7175		

06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR.						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF: AMM 06-20-00	HRS/MSC					8020:35		
		AFL					7175		

06-00/219 (s)	CLOSE ACCESS PANELS 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC					8020:35		
		AFL					7175		

CHAPTER 07 LIFTING AND SHORING



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 2 REF: AMM 07-10-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 2 REF: AMM 07-10-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST REF:	MOS HRS/MSC AFL	60	+1m/-1m			25-MAR-2016 6551 5845	25-MAR-2021	25-APR-2021
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6) REF:	MOS HRS/MSC AFL	-				02-FEB-2017 6980:50 6255		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 2,4 REF:	MOS HRS/MSC AFL	12 100	+10%/-10% +10/-10			PKG 03-AUG-2018 8020:35 7175		
CHAPTER 11 PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
CHAPTER 12 SERVICING									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS PKG 2,4 REF: AMM 12-20-01	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 2,4 REF: AMM 12-20-02	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 2,4 REF: AMM 12-20-03	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A 20.010	PERFORM CORROSION INSPECTION (INTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019	09-SEP-2019
00-00/45B 20.011	PERFORM CORROSION INSPECTION (EXTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	6 300	+10%/-10% +10%/-10%	3 7:25		29-MAY-2018 7875:15 7050	01-DEC-2018 8182:40	19-DEC-2018 8212:40
20JFL01	PERFORM DENTS AND BUCKLES CHARTS REF:	MOS HRS/MSC AFL	150				03-AUG-2018 8020:35 7175	8170:35	
CHAPTER 21 AIR CONDITIONING									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN	PKG 2	MOS 12				03-AUG-2018 8020:35 7175		
	REF:		HRS/MSC AFL						
21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT	PKG 2	MOS 12				03-AUG-2018 8020:35 7175		
	REF:		HRS/MSC AFL						
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
21.040	REF: AMM 21-30-00	MOS 24	3000	+10%/-10%	7		01-DEC-2017 7582:40 6775	08-DEC-2019 10582:40	19-FEB-2020 10882:40
		HRS/MSC AFL		+10%/-10%					
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
21.030	REF: AMM 21-30-01	MOS 24	3000	+10%/-10%	7		01-DEC-2017 7582:40 6775	08-DEC-2019 10582:40	19-FEB-2020 10882:40
		HRS/MSC AFL		+10%/-10%					
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
21.010	REF: AMM 21-30-07	MOS 60		+10%/-10%	131		03-AUG-2018 8020:35 7175	12-DEC-2023	12-JUN-2024
		HRS/MSC AFL							
21-40/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
21.020	REF: AMM 21-30-08	MOS 60		+10%/-10%	131		03-AUG-2018 8020:35 7175	12-DEC-2023	12-JUN-2024
		HRS/MSC AFL							



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/50	CLEAN WATER SEPARATOR CONDENSER	MOS					03-AUG-2018		
21.080	REF: AMM 21-40-02	HRS/MSC AFL	450	+10%/-10%		12:05	8020:35 7175	8482:40	8527:40
21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%		131	03-AUG-2018	12-DEC-2023	12-JUN-2024
21.130	REF: AMM 21-40-06	HRS/MSC AFL					8020:35 7175		
21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%		131	03-AUG-2018	12-DEC-2023	12-JUN-2024
21.120	REF: AMM 21-60-05	HRS/MSC AFL					8020:35 7175		
21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)	MOS	12				03-AUG-2018		
	PKG 2	HRS/MSC AFL					8020:35 7175		
	REF: AMM 21-40-00								
21-40/55	RE-OIL AIR CONDITIONING COLD AIR UNIT	MOS					03-AUG-2018		
21.060	REF: AMM 21-40-01	HRS/MSC AFL	450	+10%/-10%		12:05	8020:35 7175	8482:40	8527:40
21-40/56	INSPECT/CHECK HEAT EXCHANGER MATRIX	MOS					03-AUG-2018		
21.070	REF: AMM 21-40-01	HRS/MSC AFL	450	+10%/-10%		12:05	8020:35 7175	8482:40	8527:40
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT	MOS	12				03-AUG-2018		
	PKG 2	HRS/MSC AFL					8020:35 7175		
	REF:								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) 959.90.22.140 508 REF:	MOS HRS/MSC AFL	300	+10%/-10%			03-AUG-2018 8020:35 7175	8320:35	8350:35
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140 508 REF:	MOS HRS/MSC AFL ACH	600	+10%/-10%			29-MAY-2018 7875:15 7050 885	1485	1545
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140 508 REF:	MOS HRS/MSC AFL ACH	600	+10%/-10%			29-MAY-2018 7875:15 7050 885	1485	1545
210005 21.340	OVERPRESSURE SWITCH 973.81.15.105 299 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
210010 21.255	REFRIGERATION PACK 959.90.20.111 1080 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
210015 21.370	WATER INJECTOR 959.90.20.141 1058 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210020	DUCT TEMP SENSOR								
21.320	959.90.20.121 1072 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	959.90.20.132 1047 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210030	HP SHUT OFF VALVE								
21.280	959.90.20.131 1046 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210035	WATER SEPARATOR ASSY								
21.220	521.41.12.060 2192 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210040	TEMPCONTROL VALVE								
21.310	959.90.20.136 1023 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	959.90.22.140 508 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:151 TSN:7875:15 TSN:7050			29-MAY-2018 7875:15 7050		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	1134104-9 0180 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAY-2018 7875:15 7050		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	959.90.22.116 786 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.118 722 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-JUL-2014 5680 4974		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	959.90.22.119 921 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-JUL-2014 5680 4974		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	959.90.91.121 63-A0451 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	959.90.91.111 63-7606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210075	CHECK VALVE								
21.400	959.90.91.151 63-A0561 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210080	JET PUMP								
21.410	959.90.91.161 63-1825 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210085	MANUAL CONTROLLER								
21.420	959.90.91.101 63-A0447 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	64547-130374-36 34-G0507 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-JUL-2012 4672:55 3982		
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	965.23.23.202 1023707 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210100	CAB RATE INDICATOR								
21.440	965.16.21.002 1081325 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:14 TSN:0 TSN:0			25-JUN-2016 6694:55 5975		
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	965.23.21.534 1042741 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C				03-AUG-2018 8020:35 7175		
210110	CABIN PX SWITCH								
21.360	965.23.21.533 1020421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-AUG-2018 8020:35 7175		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.507 505716 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210120	BAY TEMP SENSOR								
21.450	959.90.20.122 1052 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	975.15.16.101 A5836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210130	TEMP CONTROLLER								
21.235	959.90.20.123 1046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210140	SOLENOID VALVE								
21.300	963.14.11.001 208301 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	969.67.81.507 505721 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	963.30.11.106 0264B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	963.30.11.002 0290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210160	CABIN HEATER TEMPERATURE TRANSMITTER								
21.350	975.15.16.104 214 REF: AMM 21-40-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
210165	UNDERFLOOR HEATER TEMPERATURE TRANSMITTER								
21.260	975.15.16.105 650 REF: AMM 21-40-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-JUL-2012 4695:40 4002		
210170	OVERPRESSURE SWITCH								
21.340	973.81.15.106 303 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST								
	REF:	MOS HRS/MSC AFL	24				03-AUG-2018 8020:35 7175	03-AUG-2020	
CHAPTER 22	AUTO FLIGHT								
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK								
22.010	REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+10%/-10% +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 9020:35	09-SEP-2019 9120:35
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 4 ,2 REF: AMM 22-20-00	MOS HRS/MSC AFL	100				PKG 03-AUG-2018 8020:35 7175		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 2 REF: AMM 22-20-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
220005 22.160	AUTOPILOT MODE CONTROL 065-0086-17 1606 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C				26-MAR-2014 5493:05 4798		
220010 22.180	ALTITUDE PRESELECTOR 065-0089-16 1738 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C				24-MAR-2012 4491:58 3809		
220015 22.100	AILERON KSA372,065-00056-0056 ACTUATOR 985.92.03.161 5478 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220020 22.190	PITCH KSM375,065-00015-0000 MOUNT 985.92.03.173 9270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220025 22.110	ELEVATOR KSA372,065-00056-0059 ACTUATOR 065-00056-59 4082 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C				27-NOV-2015 6405:35 5696		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	985.92.03.171 9280 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	065-0056-80 4798 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C				16-SEP-2016 6822:20 6094		
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	985.92.03.171 9279 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220045	STICK PUSHER SERVO								
22.220	978.61.11.103 1475 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-NOV-2008 3244:58 2687		
220050	PITCH TRIM ADAPTER								
22.130	985.92.03.181 1555 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	978.61.11.124 1466 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
220060	STICK SHAKER								
22.230	978.61.11.143 0419 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220065	AUTOPILOT COMPUTER								
22.150	065-0064-15 2679 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				03-AUG-2015 6266:45 5575		
220070	STICK PUSHER COMPUTER								
22.170	975.44.23.104 121258 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			05-NOV-2008 3244:58 2687		
CHAPTER 23 COMMUNICATIONS									
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	984.81.10.203 10923 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	984.81.10.203 10925 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
230015	COMM/NAV 25 KHZ SYSTEM								
23.050	985.99.11.366 2190 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
230020	COMM/NAV 25 KHZ SYSTEM								
23.050	985.99.11.366 2198 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
230025	AUDIO SUMMING AMPLIFIER								
23.010	987.81.33.108 144 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230030	AUDIO SELECTOR								
23.040	010-00152-11 96294065 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-FEB-2014 5394:50 4695		
23JFL01	NO. 1 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78417717 REF:	MOS HRS/MSC AFL	O/C				03-APR-2014 5506:30 4812		
23JFL02	NO. 2 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78411824 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-JUL-2014 5680 4974		
CHAPTER 24 ELECTRICAL POWER									
24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM						PKG		
	PKG 2	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
	REF: AMM 24-20-00								
24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF: See Workcard								
24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED)						PKG		
	PKG 2	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF: See Workcard								
24-30/19	STARTER GENERATOR								
24.020	23085-029 MOD.A Y0256 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C				04-OCT-2017 7515:10 6713		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/20	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING 940.83.08.902 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	3000	+10%/-10%	TSN:0 TSN:0 TSN:0	-136:37	29-MAY-2015 6120:25 5448	8983:48	9283:48
24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
24-30/61	BRUSH CHECK STARTER GENERATOR BRUSHES (ALL P/N'S EXCEPT 978.91.23.407 AND 978.91.23.408) 23085-029 MOD.A Y0256 REF: AMM 24-30-01	MOS HRS/MSC AFL	150	+10%/-10%		12:05	03-AUG-2018 8020:35 7175	8182:40	8197:40
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%		7	01-DEC-2017 7582:40 6775	08-DEC-2019	19-FEB-2020
24-30/63	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES 524.32.12.158 MOD.F 100065 REF: AMM 24-30-02	MOS HRS/MSC AFL	300	+10%/-10%		7:25	29-MAY-2018 7875:15 7050	8182:40	8212:40
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A			58:49	02-OCT-2014 5828:35 5129		
24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING REF: AMM 24-30-04	MOS HRS/MSC AFL	1000	+10%/-10%		12:09	29-MAY-2018 7875:15 7050	8887:24	8987:24



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	31406-002 11501534 REF: AMM 24-30-07	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%		8:45	03-AUG-2018 8020:35 7175	03-AUG-2019 8329:20	09-SEP-2019 8359:20
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY								
24.050	501.1712.02 3945 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			03-AUG-2018 8020:35 7175	03-AUG-2019	03-SEP-2019
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	988.21.14.111 Y2279 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
240025	GENERATOR 2 2ND GENCON UNIT								
24.140	988.21.15.103 10640 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-FEB-2016 6480:20 5773		
240035	BUSBAR,CROSS TIE RCCB								
24.150	972.55.37.003 1061 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240040	BUSBAR,CROSS,TIE RCCB								
24.150	972.55.37.005 438 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240045	STARTER RELAY								
24.160	974.09.26.133 P436 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240050	BATTERY RELAY								
24.170	974.09.26.126 P748 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240055	EPU RELAY								
24.180	974.09.26.126 P911 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	972.81.32.301 377 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240065	OVERHEAD PANEL								
24.190	972.81.32.109 JWPIL002254 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			06-MAR-2017 7043:40 6309		
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	959.90.20.124 218 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	975.04.21.110 AGA00470 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	974.29.00.201 2597 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240095	S105 DC CURRENT SENSOR								
24.090	974.29.00.205 1817 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	974.29.00.205 1857 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	974.29.00.201 2610 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240110	S104 DC CURRENT SENSOR								
24.090	974.29.00.201 2635 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
240115	S106 DC CURRENT SENSOR								
24.100	974.29.00.201 2615 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243045	GENERATOR 2								
24.030	524.32.12.158 MOD.F 100065 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2014 5530:20 4841		
243080	EMERGENCY POWER SUPPLY								
24.050	501.1712.02 3945 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				23-DEC-2016 6936:40 6210		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11501534 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	TSR:5 TSR:291:15 TSR:259			03-AUG-2018 8020:35 7175		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 4,2	MOS HRS/MSC AFL	150						
25-10/294	CREW SEAT BELTS								
25.030 DISCARD	959.30.01.242/243 SN-UNKNOWN REF: AMM 25-10-02	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0		06-FEB-2014 5394:50 4695	06-FEB-2026	06-AUG-2026
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 2	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 2,4 REF:	MOS HRS/MSC AFL	12 150				PKG 03-AUG-2018 8020:35 7175		
25-20/295	NO. 1 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0		27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027
25-20/295	NO. 2 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0		27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 3 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m			27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027
DISCARD				TSN:0 TSN:0					
25-20/295	NO. 4 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m			27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027
DISCARD				TSN:0 TSN:0					
25-20/295	NO. 5 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m			27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027
DISCARD				TSN:0 TSN:0					
25-20/295	NO. 6 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: AMM 25-21-02 Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144	+6m/-6m			27-FEB-2015 5980:20 5297	15-DEC-2026	15-JUN-2027
DISCARD				TSN:0 TSN:0					
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS).						PKG		
	PKG 4 ,2	MOS					03-AUG-2018		
	REF:	HRS/MSC	100				8020:35		
		AFL					7175		
25-60/231 (s)	FUNCTIONAL TEST ELT (KANNAD 406 AF OR KANNAD INTEGRA 406 AF ER-N) IF INSTALLED						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF: See Workcard	HRS/MSC					8020:35		
		AFL					7175		
25-60/232 (s)	EXAMINE ELT INSTALLATION						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC					8020:35		
		AFL					7175		
25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY								
	S1820516-99	MOS		TSN:0			26-MAR-2015		24-SEP-2021 M
25.020	TM0000070798	HRS/MSC	DUE	TSN:0			6021:50		
DISCARD	REF: GENERIC NO REF	AFL		TSN:0			5345		
	Expiry Date: 24-SEP-2021								
250005	REMOTE CONTROL PANEL								
	985.13.80.817	MOS		TSN:0			28-OCT-2003		
25.070	M0291.0088	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER								
	985.13.80.853	MOS		TSN:0			28-OCT-2003		
25.050	M0131.0021	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-63-01	AFL		TSN:0			0		
250015	SCHROTH SEAT PILOT								
	959.30.01.133	MOS		TSN:140			11-JUN-2015		
25.040	856	HRS/MSC	O/C	TSN:0					
	REF: AMM 25-10-05	AFL							



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250020	SCHROTH SEAT CO-PILOT 959.30.01.134 862 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:140 TSN:0			11-JUN-2015		
250021	NO. 1 PASSENGER SEAT 959.30.01.617 23712 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250022	NO. 2 PASSENGER SEAT 959.30.01.618 23713 REF:	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		
250023	NO. 3 PASSENGER SEAT 959.30.01.633 29292 REF:	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		
250024	NO. 4 PASSENGER SEAT 959.30.01.634 29293 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250025	NO. 5 PASSENGER SEAT 959.30.01.641 23715 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250026	NO. 6 PASSENGER SEAT 959.30.01.642 23717 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
251010	PILOT SEAT BACKREST TUBES 959.30.01.133 856 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	10000	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		10000
25.060	LIFE LIMIT								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251015	COPILOT SEAT BACKREST TUBES 959.30.01.133	MOS		TSN:0			28-OCT-2003		
LIFE LIMIT	862 REF:	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0	10000	
25JFL02	PERFORMED FIRST AID KIT INSPECTION (DAC-AIR 348)	MOS	12	+1m/-1m			03-AUG-2018	03-AUG-2019	03-SEP-2019
	REF:	HRS/MSC AFL					8020:35 7175		
CHAPTER 26 FIRE PROTECTION									
26-20/2	COCKPIT FIRE EXTINGUISHER BA51015GR-3	MOS	120	TSN:0			03-MAY-2013	01-SEP-2021 M	
26.010 LIFE LIMIT	077088 REF: GENERIC NO REF	HRS/MSC AFL ACH		TSN:0 TSN:0			5100:15 4405		
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348) BA51015GR-3	MOS	12	+10%/-10%			03-AUG-2018	03-AUG-2019	09-SEP-2019
26.010	077088 REF: GENERIC NO REF	HRS/MSC AFL							
260005	FIRE/OVERHEAT DETECTOR 975.12.10.012	MOS		TSN:0			28-OCT-2003		
26.020	205156 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
CHAPTER 27 FLIGHT CONTROLS									
27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL PKG 4 ,2	MOS					PKG		
	REF:	HRS/MSC AFL	150				28-OCT-2003 0 0		
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES	MOS					28-OCT-2003		
	REF: GENERIC NO REF	HRS/MSC AFL	32500 42000				0 0	32500 42000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES								
27.010	REF: AMM 27-00-00	MOS HRS/MSC AFL	48 2000	+10%/-10% +10%/-10%		-83:47	11-AUG-2017 7368 6584	11-AUG-2021 9284:13	04-JAN-2022 9484:13
27-10/139 (s)	EXAMINE AILERON LH AND RH PKG 2,4	MOS HRS/MSC AFL	12 150				PKG 03-AUG-2018 8020:35 7175		
27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS PKG 2	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 2	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 2	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 PKG 2	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 PKG 2	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-10/394	EXAMINE - AILERON CONTROL SYSTEM	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-10-00								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/395	EDDY CURRENT INSPECTION	AILERON CABLE SEGMENT							
AIRWORTHINESS	REF: AMM 27-10-09	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS								
AIRWORTHINESS	REF: AMM 27-00-01	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
AIRWORTHINESS	REF: AMM 27-00-01	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS								
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/444	AILERON FLIGHT CONTROL CABLES								
LIFE LIMIT	REF:	PN		TSN:0			28-OCT-2003		
		SN-UNKNOWN		TSN:0			0		20000
		AFL	20000	TSN:0			0		27000
		AFL	27000	TSN:0			0		27000
+ 27-10/445	AILERON AUTOPILOT CONTROL CABLE								
LIFE LIMIT	REF:	PN		TSN:0			28-OCT-2003		
		SN-UNKNOWN		TSN:0			0		20000
		AFL	20000	TSN:0			0		27000
		AFL	27000	TSN:0			0		27000
27-10/470	LUBRICATE AILERON CONTROL SYSTEM BEARING								
REF: AMM 27-10-00		MOS	12	+10%/-10%			03-AUG-2018	03-AUG-2019	09-SEP-2019
		HRS/MSC	1200	+10%/-10%			8020:35	9220:35	9340:35
		AFL					7175		
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999						PKG		
	REF: See Workcard	PKG 2					03-AUG-2018		
		MOS	12				8020:35		
		HRS/MSC					7175		
		AFL							



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/140 (s)	EXAMINE RUDDER IN PARTICULAR THE COVER PLATE (PART NO. 555.40.12.215) ON THE BOTTOM OF THE RUDDER TO MAKE SURE IT IS NOT BENT AND THERE ARE NO SIGNS OF INTERFERENCE WITH THE RUDDER STOP. PKG 2,4 REF:	MOS HRS/MSC AFL	12 150				PKG 03-AUG-2018 8020:35 7175		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-20/242 (s)	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH PKG 2 REF: AMM 20-31-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 2 REF: AMM 27-25-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 2	MOS	12				PKG 03-AUG-2018 8020:35 7175		
	REF:	AFL					7175		
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					28-OCT-2003		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				0 0		
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	PN SN-UNKNOWN REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			0 0 0	20000 27000	
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	PN SN-UNKNOWN REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			0 0 0	20000 27000	
27-30/141 (s)	EXAMINE ELEVATORS PKG 2,4	MOS	12				PKG 03-AUG-2018 8020:35 7175		
	REF:	HRS/MSC AFL	100				7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 2 REF: AMM 27-30-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 2 REF: AMM 27-30-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-30/334	CHECK ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR) (REF. 12-A-27-30-00-00A-903A-A) REF: AMM 27-30-00	MOS HRS/MSC AFL	A/R				11-AUG-2017 7368 6584		
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM REF: AMM 27-30-00	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			0 0	20000 27000	
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			0 0	20000 27000	
+ 27-30/450	STICK PUSHER CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			0 0	20000 27000	
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%			03-AUG-2018	03-AUG-2019	09-SEP-2019
27.021		HRS/MSC AFL	3000				8020:35 7175	11020:35	
AIRWORTHINESS	REF: AMM 27-40-00								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES PKG 2,4 REF: AMM 27-40-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
27-40/25 27.020	PITCH TRIM ACTUATOR 978.73.14.203 833 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:10 TSR:7 TSN:1567:46 TSO:173:06 TSR:0434 TSO:96 TSR:0			16-SEP-2016 6822:20 6094		
27-40/252 (s)	EXAMINE HORIZONTAL STABILIZER TRIM ACTUATOR TOP AND BOTTOM ATTACHMENTS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-40/26 OVERHAUL	OVERHAUL PITCH TRIM ACTUATOR 978.73.14.203 833 REF: AMM 27-40-01	MOS HRS/MSC AFL	84 3400	TSI:0 TSI:96	350		16-SEP-2016 6822:20 6094	01-SEP-2024 10222:20	
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 4 ,2 REF: AMM 27-40-00	MOS HRS/MSC AFL	100				PKG 03-AUG-2018 8020:35 7175		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 2 REF: AMM 27-40-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-40/3 27.011 AIRWORTHINESS	PITCH TRIM ACTUATOR 978.73.14.203 833 REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000	TSO:10 TSR:7 TSN:1567:46 TSO:173:06 TSR:0434 TSO:96 TSR:0			16-SEP-2016 6822:20 6094	26649:14 32998	
27-40/307 27.036 LIFE LIMIT	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS PN SN-UNKNOWN REF: AMM 27-40-02	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0	10000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT 978.73.20.003 199 OVERHAUL	MOS HRS/MSC AFL	10000 13500	+10%/-10% +500/-500			28-OCT-2003 0 0	10000 13500	11000 14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0276 27.040 OVERHAUL	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			27-FEB-2013 4995:50 4276	9244:20 M 10701 M	9744:20 11201
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0207 27.040 OVERHAUL	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			27-FEB-2013 4995:50 4276	9127:10 M 10654 M	9627:10 11154



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS		TSI:3			13-APR-2017		
OVERHAUL	0322	HRS/MSC	5000	+10%/-10%	TSI:0		7080:50	12080:50	12580:50
	REF: AMM 27-50-03	AFL	7000	+500/-500	TSI:0		6348	13348	13848
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					27-FEB-2013		
OVERHAUL	0355	HRS/MSC	5000	+10%/-10%			4995:50	9021:25 M	9521:25
	REF: AMM 27-50-03	AFL	7000	+500/-500			4276	10826 M	11326
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.205	MOS		TSN:0			28-OCT-2003		
DISCARD	S5169	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.206	MOS		TSN:0			28-OCT-2003		
DISCARD	S5259	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.205	MOS		TSN:0			28-OCT-2003		
DISCARD	S5171	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.206	MOS		TSN:0			28-OCT-2003		
DISCARD	S5257	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/386	EXAMINE - FLAP MECHANISM								
AIRWORTHINESS		MOS					28-OCT-2003		
	REF: AMM 27-51-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
AIRWORTHINESS		MOS					28-OCT-2003		
	REF: AMM 27-51-00	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/388	EDDY CURRENT INSPECTION	FLAP DRIVE ARM (REMOVED)							
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS								
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
AIRWORTHINESS	REF: See Workcard	MOS					28-OCT-2003		
		HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/4	LEFT INBOARD FLAP ACTUATOR								
27.040	978.73.20.309	MOS					27-FEB-2013		
AIRWORTHINESS	REF: AMM 27-50-03	HRS/MSC	20000	TSN:751:30			4995:50		24244:20
		AFL	27000	TSN:575			4276		30701
27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
27.040	978.73.20.309	MOS					27-FEB-2013		
AIRWORTHINESS	REF: AMM 27-50-03	HRS/MSC	20000	TSN:869:40			4995:50		24126:10
		AFL	27000	TSN:622			4276		30654
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
27.050	978.73.20.309	MOS					13-APR-2017		
AIRWORTHINESS	REF: AMM 27-50-03	HRS/MSC	20000	TSO:3			7080:50		27080:50
		AFL	27000	TSN:5025:42 TSO:0			6348		33348
				TSN:3935 TSO:0					



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS					27-FEB-2013		
27.050	0355	HRS/MSC	20000	TSN:974:25			4995:50		24021:25
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	TSN:450			4276		30826
27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		TSN:0			28-OCT-2003		
57.060	430	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	TSN:0			0		30000
27-50/414	RIGHT HAND FLAP								
	557.50.12.004	MOS		TSN:0			28-OCT-2003		
57.060	426	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	TSN:0			0		30000
27-50/437	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS								
		MOS	12	+10%/-1m			03-AUG-2018	03-AUG-2019	09-SEP-2019
		HRS/MSC	150	+10%/-10%	4:40		8020:35	8175:15	8190:15
AIRWORTHINESS	REF: AMM 27-51-00	AFL					7175		
27-50/443	SERVICE FLAP UP AND DOWN LIMIT SWITCHES								
	PKG 5,6,8,10,12,14	MOS	12	+1m/-1m			03-AUG-2018	03-AUG-2019	03-SEP-2019
		HRS/MSC	200	+10%/-10%			8020:35	8220:35	8240:35
	REF: AMM 12-20-07	AFL					7175		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		TSN:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0		20000
LIFE LIMIT	REF:	AFL	27000	TSN:0			0		27000
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
	945.02.02.205	MOS					28-OCT-2003		
27.060	S5169	HRS/MSC	O/C				0		
	REF: AMM 27-50-00	AFL					0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
	945.02.02.206	MOS					28-OCT-2003		
27.060	S5259	HRS/MSC	O/C				0		
	REF: AMM 27-50-00	AFL					0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.205 S5171 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.206 S5257 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0276 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%		12:05	03-AUG-2018 8020:35 7175	03-AUG-2019 8182:40	03-SEP-2019 8197:40
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0207 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%		12:05	03-AUG-2018 8020:35 7175	03-AUG-2019 8182:40	03-SEP-2019 8197:40
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0322 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%		12:05	03-AUG-2018 8020:35 7175	03-AUG-2019 8182:40	03-SEP-2019 8197:40
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0355 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%		12:05	03-AUG-2018 8020:35 7175	03-AUG-2019 8182:40	03-SEP-2019 8197:40
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0276 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 9020:35 8475	03-SEP-2019 9120:35 8605
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0207 REF:	MOS HRS/MSC AFL	12	+1m/-1m +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 9020:35 8475	03-SEP-2019 9120:35 8605



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0322 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 9020:35 8475	03-SEP-2019
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0355 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 9020:35 8475	03-SEP-2019 9120:35 8605
270003	HORIZONTAL TAIL ASSY 555.10.12.037 429 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270015	ELEVATOR LH ASSY 555.20.12.039 S0108 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270023	ELEVATOR RH ASSY 555.20.12.040 S0111 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270025 27.090	RUDDER TRIM LINEAR ACTUATOR 978.73.18.132 545 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270033	RUDDER ASSY 555.40.12.038 434 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270035 27.130	FLAP CONTROL AND WARNING (FCWU) UNIT 978.73.20.016 112275 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C				16-SEP-2016 6822:20 6094		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270045	LH INBOARD TRANSMITTER								
27.100	978.73.20.021 01N086DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	978.73.20.602 0331 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 01N078DZ REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	978.73.20.021 01N076DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	978.73.20.602 0332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	978.73.18.132 612 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 01N089DK REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m			29-MAY-2018 7815:15 7050	29-MAY-2020	29-JUN-2020

CHAPTER 28 FUEL



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-10/306 28.029	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE REF: AMM 28-10-01	MOS HRS/MSC AFL	1000	+10%/-10%	61:25		29-MAY-2018 7875:15 7050	8936:40	9036:40
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 2,4 REF: AMM 28-20-07	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N) PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/32	ENGINE DRIVEN FUEL PUMP								
28.010 OVERHAUL	968.84.51.108 B4954 REF: AMM 28-20-03	MOS HRS/MSC AFL	3500 +10%/-10%	TSO:5 TSO:0 TSO:0			23-DEC-2016 6936:40 6210	10436:40	10786:40
28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM								
28.020	REF: See Workcard	MOS HRS/MSC AFL	48 1000 +10%/-10%		61:25		29-MAY-2018 7875:15 7050	29-MAY-2022 8936:40	23-OCT-2022 9036:40
280005	LOW PRESSURE FUEL PUMP								
28.120	968.84.51.108 B4511 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				25-NOV-2003 4:12		
280010	FUEL FLOW TRANSMITTER								
28.130	TFF2905-29 AAF1262 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-AUG-2013 5307:35 4605		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	963.87.22.301 1282 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	963.87.22.301 1279 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280025	FUEL FILTER ASSY								
28.025	968.35.21.001 00411 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	973.81.14.102 1021 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2941 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3286 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 854 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 854 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 863 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 691 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:5 TSR:0 TSR:0			25-MAR-2016 6551 5845		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B5648A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2946 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
280075	RIGHT WING EJECTOR,DELIVERY PUMP									
28.030	968.84.71.105 B3283 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0			
280080	FUEL QUANTITY,COLLECTOR SENSOR									
28.080	975.37.31.234 859 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0			
280085	FUEL QUANTITY,INNER SENSOR									
28.090	975.37.31.233 862 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0			
280090	FUEL QUANTITY,CENTRAL SENSOR									
28.070	975.37.31.232 861 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0			
280095	FUEL QUANTITY,OUTER SENSOR									
28.060	975.37.31.231 1175 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-SEP-2017 7456:55 6656			
280100	RIGHT WING FUEL,BOOSTER PUMP									
28.050	968.84.11.405 B5649A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0			
CHAPTER 29	HYDRAULIC POWER									
29-10/151 (s)	CHECK LOW PRESSURE FILTER BLOCKAGE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG			
	PKG 2,4	MOS	12				03-AUG-2018			
		HRS/MSC	100				8020:35			
	REF: AMM 29-10-04	AFL					7175			



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF: See Workcard	AFL					7175		
29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF: See Workcard	AFL					7175		
29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291)						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF: AMM 29-10-02	AFL					7175		
29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
29-10/418	NITROGEN ACCUMULATOR								
	960.30.01.291	MOS					28-OCT-2003		
29.020	0461	HRS/MSC	25000		TSN:0		0		25000
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000		TSN:0		0		30000
290005	LANDING GEAR STEER SELECTOR VALVE								
	960.30.01.271	MOS					23-DEC-2016		
29.040	0931ABC	HRS/MSC	O/C		TSO:8		6936:40		
	REF: GENERIC NO REF	AFL			TSO:0		6210		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290015	PRESSURE GAGE SWITCH 973.81.14.307 0595 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-FEB-2014 5394:50 4695		
290025	SERVICE SELECTOR VALVE 960.30.01.261 G0320095A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
290030	PRESSURE GAUGE 965.61.88.101 304089 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
290035	(K 601) RELAY 974.09.26.112 P796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
290040	HAND PUMP 529.21.12.021 431 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
290050	PRESSURE NITROGEN SWITCH 973.81.14.306 0495 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
291010	HYDRAULIC POWER PACK 960.30.01.154 G0330124 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS HYDRAULIC FLUID 960.30.02.101 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	+6m/-6m TSN:0 TSN:0 TSN:0			01-DEC-2017 7582:40 6775	01-DEC-2022	01-JUN-2023

CHAPTER 30 ICE AND RAIN PROTECTION



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS PKG 2,4 REF: AMM 30-10-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999 PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 2 REF: AMM 30-10-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
30-10/79 (s) 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING PKG 2,4 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 150				PKG 03-AUG-2018 8020:35 7175		
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM SINGLE P-S SYSTEM, DUAL SYSTEM AND P-S INDICATOR MSN 321 AND 401-999 PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 2,4 REF: AMM 30-60-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 2,4 REF: AMM 30-60-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
300005 30.140	PROP DE-ICE TIMER/ CONTROLLER 4E3163-2 U0662 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-AUG-2018 8020:35 7175		
300010 30.150	LPMI LINEAR ACTUATOR 978.73.15.301 29210 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300015 30.160	REGULATOR-RELIEVER ASSY 959.89.01.012 N0555 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300020 30.110	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2349 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300025 30.120	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2353 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300030 30.110	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	959.89.01.008 N2423 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	959.89.01.008 N2421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	973.81.14.312 2017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300050	WATER SEPARATOR								
30.060	959.89.01.010 B-1350 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	9598901014 U3050 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114034 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114036 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 2032 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 2028 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2048 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	P27S-7D5221-13 NCB2050 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-NOV-2014 5883:35 5185		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NDY2080 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2017 7582:40 6775		
300100	RH INBD-WING DE-ICER BOOT								
30.040	959.89.01.032 NAT9870 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:6 TSN:0 TSN:0			07-NOV-2012 4867:30 4141		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	P27-7D5221-12 NCS2330 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-AUG-2015 6266:45 5575		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.022 NCX4030 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2017 7080:50 6348		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NDW5740 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2017 7582:40 6775		
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"								
	REF:	MOS HRS/MSC AFL	150	+10%/-10%		12:05	03-AUG-2018 8020:35 7175	8182:40	8197:40
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-50/34	CAWS & CACU CLOCK BATTERY								
31.010 DISCARD	972.81.32.050 SN-UNKNOWN REF: AMM 31-50-03	MOS HRS/MSC AFL	24	+10%/-10%	TSN:2	1	13-APR-2017 7080:50 6348	14-FEB-2019	26-APR-2019
310020	FLAP POSITION INDICATOR								
31.090	975.44.16.203 00394 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
310035	CAWS COMPUTER								
31.050	972.81.32.030 171 REF: See Workcard	MOS HRS/MSC AFL	O/C				22-AUG-2013 5296:15 4594		
310040	CAWS DISPLAY								
31.060	972.81.32.031 131 REF: AMM 31-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
310050	DIGITAL CLOCK								
31.040	999.61.11.212 1019163 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
CHAPTER 32 LANDING GEAR									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 2,4 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 2 REF: AMM 32-10-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING REF:	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK REF:	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS					28-OCT-2003		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
32-10/436 (s)	REMOVE/CLEAN MLG SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS. EXAMINE FOR CORROSION. IF CORRODED, REPLACE BOLT WITH LATEST BOLT PART NUMBER. IF NOT CORRODED, APPLY GREASE P04-028 AND INSTALL THE BOLT.						PKG		
	PKG 2	MOS	12	+10%/-10%			03-AUG-2018		
	REF: AMM 32-10-00	HRS/MSC					8020:35		
		AFL					7175		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT								
		MOS	72				25-MAR-2016		25-MAR-2022
	REF: AMM 32-10-00	HRS/MSC					6551		
		AFL					5845		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT								
		MOS	72				25-MAR-2016		25-MAR-2022
	REF: AMM 32-10-00	HRS/MSC					6551		
		AFL					5845		
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS								
32.030		MOS	12	+10%/-10%			03-AUG-2018		03-AUG-2019 09-SEP-2019
	REF: AMM 12-20-06	HRS/MSC	T/C				8020:35		
		AFL					7175		
32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES								
32.010		MOS	12	+1m/-1m			03-AUG-2018		03-AUG-2019 03-SEP-2019
	REF: AMM 32-10-00	HRS/MSC	2000	+10%/-10%			8020:35		10020:35 10220:35
		AFL					7175		
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF: AMM 32-20-00	HRS/MSC					8020:35		
		AFL					7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 2,4 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
32-20/266 (s)	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 532.50.12.064 SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		06-FEB-2014 5394:50 4695		
32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				07-DEC-2012 4896:05 4185		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/403	NOSE LANDING GEAR								
	PN	MOS		TSN:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	25000	TSN:0			0		25000
OVERHAUL	REF: GENERIC NO REF	AFL	30000	TSN:0			0		30000
32-20/416	NOSE LANDING GEAR DRAG LINK								
	PN	MOS		TSN:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	TSN:0			0		30000
32-20/5 (s)	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
	532.20.12.296	MOS		TSN:0			07-DEC-2012		
32.020	N/A	HRS/MSC	O/C	TSN:0			4896:05		
	REF: AMM 32-20-05	AFL		TSN:0			4185		
32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF: AMM 32-30-00	AFL					7175		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
	960.30.01.103	MOS		TSN:0			28-OCT-2003		
32.040	0913E	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	TSN:0			0		30000
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
	960.30.01.105	MOS					16-JUL-2009		
32.040	0932EFGH	HRS/MSC	25000	TSN:0			3468:53		28468:53 M
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	TSN:0			2890		32890 M
		ACH							
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				25-MAR-2016		25-MAR-2022
		HRS/MSC					6551		
	REF: AMM 32-10-00	AFL					5845		
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				25-MAR-2016		25-MAR-2022
		HRS/MSC					6551		
	REF: AMM 32-10-00	AFL					5845		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 2 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE PKG 2,4 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 2 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 2,4 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 2,4 REF: AMM 12-10-02	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM REF: AMM 32-50-00	MOS HRS/MSC AFL	 32500 42000				28-OCT-2003 0 0	 32500 42000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 3576 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 3577 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320015	PARK BRAKE VALVE								
32.140	959.47.51.121 2147 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320020	NOSE WHEEL								
32.150	40-423 1370 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-NOV-2017 7574:45 6767		
320021	NOSE LANDING GEAR TIRE								
32.155	021-327-0 5267S00092 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-NOV-2017 7574:45 6767		
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.160	3-1543-1 0973 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-DEC-2017 7582:40 6775		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	021-350-0 5076S00324 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2017 7582:40 6775		
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.165	3-1543-1 1302 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-DEC-2017 7582:40 6775		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320025	SHIMMY DAMPER ASSY 532.20.12.215 SI-0039 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C				01-DEC-2017 7582:40 6775		
320026	RIGHT MAIN LANDING GEAR TIRE 021-350-0 6047S00259 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2017 7582:40 6775		
320030	COPILOT LH BRAKE MASTER CYLINDER 959.47.51.131 3580 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 959.47.51.131 3583 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY 532.20.12.249 VLG062 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320050	LEFT SHOCK ABSORBER ASSY 532.10.12.175 VLG153 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320055	RIGHT SHOCK ABSORBER ASSY 532.10.12.175 VLG154 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
320074	NOSE LANDING GEAR ACTUATOR 960.30.01.111 0977A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-FEB-2014 5394:50 4695		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320075	LH BRAKE ASSY								
32.050	2-1674-1 0155 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			22-MAR-2018 7729:20 6916		
320080	RH BRAKE ASSY								
32.050	2-1674-1 1014 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-AUG-2018 8020:35 7175		
CHAPTER 33 LIGHTS									
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF: See Workcard								
33-41/178 (s)	EXAMINE LANDING LIGHTS						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF: AMM 33-41-01								
33-42/179 (s)	EXAMINE TAXI LIGHTS						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF: AMM 33-42-01								
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF:								
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED)						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF:								
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED)						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
	REF:								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330005	DIM UNIT								
33.080	975.02.15.205 113487 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330010	DE-ICE LIGHT ASSY								
33.010	972.87.67.111 374547 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330015	LEFT WING POWER SUPPLY, HIDL UNIT								
33.020	972.87.69.413 367323 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330020	RIGHT WING POWER SUPPLY, HIDL UNIT								
33.020	972.87.69.413 371696 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	972.87.87.331 14274 REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	972.87.87.332 14289 REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330035	LH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 19961 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 29254056 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			16-SEP-2016 6822:20 6094		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330045	RH WING POWER SUPPLY UNIT 972.87.87.164 19962 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322 28290013 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2016 6586:05 5509		
330055	NAVIGATION (FC), BULB GREEN LIGHT MS25309-7512 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JUL-2014 5723:20 5012		
330060	NAVIGATION (FC), BULB RED LIGHT A7512-24 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-MAY-2013 5100:15 4405		
330065	NAVIGATION (FC), BULB WHITE LIGHT CM307 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C				15-FEB-2017 7009:45 6277		
330070	NOSE LANDING GEAR TAXI LIGHT, 1X0005287-10 4626 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-SEP-2014 5808:35 5108		
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10 9727855627 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-JUN-2014 5595 4898		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10 972.78.55.627 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-AUG-2013 5278:55 4582		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33JFL01 (s)	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00-00A-903A-A) PKG 2,4 REF:	MOS HRS/MSC AFL	12 150	+10%/-10% +10%/-10%			PKG 03-AUG-2018 8020:35 7175		
CHAPTER 34 NAVIGATION									
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 2 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
34-11/82 34.010	LEAK CHECK STATIC SYSTEM (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2019	28-FEB-2020
34-14/83 34.020	CALIBRATION CHECK ALTIMETER (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2019	28-FEB-2020



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348)								
34.030	REF: AMM 34-21-00	MOS HRS/MSC AFL	24	+10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2020	15-OCT-2020
34-25/85	CALIBRATION ATTITUDE HEADING REFERENCE SYSTEM (AHRS) CHECK SWING								
34.040	REF: AMM 34-25-00	MOS HRS/MSC AFL	24	+10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2020	15-OCT-2020
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348)								
34.050	REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%		60	03-AUG-2018 8020:35 7175	02-OCT-2020	14-DEC-2020
340005	PILOT ALTIMETER								
31.020	985.99.11.206 03050177BA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340006	COPILOT ALTIMETER								
	70256N01D01 03060187BA REF: AMM 34-14-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340007	NO. 1 TRANSPONDER								
34.140	985.99.11.361 31012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340007	NO. 2 ATC MODE A/C/S,KT70 SC+ TRANSPONDER								
	011-00455-10 84206654 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2016 6920:20 6194		
340009	NO. 1 DME/IFF ANTENNA								
34.080	984.81.10.240 61455 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340010	PILOT VERTICAL SPEED INDICATOR 965.16.15.101 284732 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-APR-2009 3378:23 2810		
340014	MARKER,KR21 RECEIVER 985.99.11.001 23262 REF: AMM 34-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340015	PILOT ATTITUDE INDICATOR 975.96.11.241 25454 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:2446:25			27-FEB-2013 4995:50 4276		
340020	MARKER ANTENNA 984.81.10.260 5627 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340025	EFIS 1 SG465 SYMBOL GENERATOR 975.96.32.402 4488 REF:	MOS HRS/MSC AFL	O/C	TSR:0			07-JUL-2009 3467:53 2890		
340026	STAND-BY ALTIMETER 965.23.22.101 431664 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340030	COPILOT VERTICAL SPEED INDICATOR 7040 7F476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-JUN-2017 7226:35 6476		
340034	EFIS 1 CONTROL,CP467 PANEL 071-01439-3100 3446 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C				06-FEB-2015 5965:10 5283		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY 066-03137-3100 4418 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				29-AUG-2018 8035:20 7227		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY 066-03137-3100 U3153 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				18-JUN-2014 5636:30 4935		
340044	TRIM TRIPLE INDICATOR 975.44.16.204 00434 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340055	PILOT AIRSPEED INDICATOR 965.12.13.334 1023713 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340059	WITH HARM FILTER,KN63 DME 985.99.11.101 27808 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340060	COPILOT AIRSPEED INDICATOR 965.12.13.335 1023718 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340065	WX-RADAR RT UNIT 071-01519-0101 10465 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			13-APR-2017 7080:50 6348		
340070	RADAR CONTROL PANEL 985.99.11.518 2430 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340075	WX,VERTICAL ANTENNA								
34.370	071-01549-0100 5752 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		
340080	NO. 2 TRANSPONDER								
34.080	984.81.10.240 61474 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340085	ADF,KA44B ANTENNA								
34.070	985.99.11.167 79243 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340090	GPS BRNAV,KLN90B UNIT								
34.340	985.99.11.199 40451 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	975.96.32.482 12363 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340100	FRONT KA92 GPS ANTENNA								
34.090	CI405-200 3083032 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C				14-NOV-2003 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	013-0235-00 85776 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-JUL-2013 5207:30 4513		
340105	LH NAV/GS ANTENNA								
34.380	984.81.10.280 4731 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	124282 5399 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-AUG-2015 6266:45 5575		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	124210-2022 1129 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				12-JUN-2018 7904:55 7076		
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	066-3034-02 56155 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C				12-DEC-2008 3284:13 2724		
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	985.99.11.771 10864 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340130	AIR DATA COMPUTER								
34.400	985.92.03.111 2357 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	985.99.11.865 11312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340135	MAGNETIC,STANDBY COMPASS								
34.130	999.98.80.103 AT-471 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340140	4206-100-V2 RADOME								
34.420	4206-100 107 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 3394 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27422 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27428 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 09398 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 28117 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-JUL-2014 5680 4974		
340165	DATA BASE,ATLANTIC,KLN90 UNIT								
34.440	985.99.11.224 43413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	985.99.11.570 3454 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:136 TSN:5962:20 TSN:5280			03-FEB-2015 5962:20 5280		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-14 74996 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-MAY-2015 6120:25 5448		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340195	MULTI FUNCTION DISPLAY								
34.190	066-04035-0101 6152 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C				06-FEB-2014 5394:50 4695		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	985.90.03.045 3179 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	985.90.03.044 2836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	985.90.03.046 2884 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340215	AHRS NO2 AHRS,LCR-92,WSYNCHR,124210-2022 UNIT								
34.320	985.99.11.878 1443 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				06-JUL-2010 3763:48 3160		
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 1335 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				13-NOV-2014 5883:35 5185		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	071-01549-0100 5752 REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		
340230	RH NAV/GS ANTENNA								
34.380	984.81.10.280 4730 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340235	AOA SENSOR RH UNIT 975.44.21.424 0713 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				04-JAN-2008 2663:12 2159		
340240	NO. 1 FLUX,KMT112 VALVE 071-1052-00 74762 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				12-JUN-2018 7904:55 7076		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT 985.99.11.505 11426 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE 975.11.20.111 01144 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340255	AOA SENSOR LH UNIT 975.44.21.423 0637 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				06-FEB-2014 5394:50 4695		
340260	NO. 2 FLUX,KMT112 VALVE 071-1052-00 KMT112-79695 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				31-JUL-2012 4695:40 4002		
340280	LEFT PITOT TUBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
340285	RIGHT PITOT TUBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341005	LH AOA PLATE TEMP CONTROLLER 975.44.21.417 U1022 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
341010	RH AOA PLATE TEMP CONTROLLER 975.44.21.417 U0285 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C				12-MAR-2004 106:12		
345015	HORIZON ARTIFICIAL 504-0111-930 50401119325166 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2016 6920:20 6194		
34C044	GYRO,DIRECTIONAL,KG102A 060-015-00 22023 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-AUG-2018 8020:35 7175		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m		-2	04-OCT-2017 7515:10 6713	02-OCT-2019	02-NOV-2019
CHAPTER 35	OXYGEN								
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 4 ,2 REF:	MOS HRS/MSC AFL	100				PKG 03-AUG-2018 8020:35 7175		
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 2 REF: AMM 35-00-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
35-10/6 35.010 AIRWORTHINESS	OXYGEN BOTTLE 95712122112 C18020456 REF: AMM 35-10-01	MOS HRS/MSC AFL	180	TSN:0 TSN:0 TSN:0			03-AUG-2018 8020:35 7175	03-AUG-2033	
35-10/7 35.010	HYDROSTATIC TEST OXYGEN BOTTLE 95712122112 C18020456 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				03-AUG-2018	03-AUG-2023	
35-20/87 35.010	INSPECTION/CHECK PASSENGER OXYGEN MASKS REF: AMM 35-20-00	MOS HRS/MSC AFL	36	+10%/-10%	60		03-AUG-2018 8020:35 7175	02-OCT-2021	20-JAN-2022
350020 35.040	PILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B005242 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-OCT-2014 5866:35 5163		
350025 35.040	COPILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B113156 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-SEP-2016 6822:20 6094		
350030 35.050	PRESSURE,GAGE,OXYGEN SWITCH 973.81.14.401 0430 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
350035 35.030	3-POSITION CONTROL VALVE 963.32.11.101 1804 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350040	ALTITUDE SENSING SWITCH								
35.020	973.81.52.102 569 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
CHAPTER 52 DOORS									
52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 150				03-AUG-2018 8020:35 7175		
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
AIRWORTHINESS	REF: AMM 52-10-00	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE								
	REF: AMM 52-00-01	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/406	EDDY CURRENT INSPECTION	PASSENGER/CREW DOOR SKIN							
		MOS					28-OCT-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 52-10-01	AFL	30000				0		30000
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
		MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
		HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
	52.010	AFL					6775		
	REF: See Workcard								
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
		MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
	AIRWORTHINESS	AFL	42000				0		42000
	REF: AMM 52-20-00								
52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF:	AFL					7175		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF: AMM 52-30-00	AFL					7175		
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF:	AFL					7175		
52-30/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/274 (s)	EXAMINE CARGO DOOR PKG 2	MOS	12				PKG 03-AUG-2018 8020:35 7175		
	REF:	HRS/MSC AFL					7175		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 52-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN	MOS					28-OCT-2003		
	REF: AMM 52-30-01	HRS/MSC AFL	25000 30000				0 0	25000 30000	
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS	MOS					28-OCT-2003		
52.020	PN SN-UNKNOWN	HRS/MSC	13000	TSN:0			0	13000	
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000	TSN:0			0	17000	
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED.	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
52.030	REF: See Workcard	HRS/MSC AFL	4000	+10%/-10%			7582:40 6775	11582:40	11982:40
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM	MOS	12				PKG 03-AUG-2018 8020:35 7175		
	REF: AMM 52-70-00	HRS/MSC AFL					7175		
520005	PASSENGER DOOR	MOS					28-OCT-2003		
52.050	552.05.12.007 424	HRS/MSC AFL	O/C	TSN:0			0 0		
	REF: AMM 52-10-01	AFL		TSN:0			0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	552.05.12.010 424 REF: AMM 52-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
520015	EMERGENGY 6 SERIE EXIT								
52.060	552.05.12.009 424 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
CHAPTER 53 FUSELAGE									
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC					8020:35		
		AFL					7175		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF: AMM 53-20-02	HRS/MSC					8020:35		
		AFL					7175		
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	28300 37000				0 0	28300 37000	
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	
53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					28-OCT-2003		
53.010 AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	20000 27000				0 0	20000 27000	
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%	16		01-DEC-2017	17-DEC-2021	11-MAY-2022
53.030 AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			7582:40 6775	11582:40	11982:40



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
CHAPTER 55	STABILIZERS								
270030	FIN ASSY								
	555.30.12.037	MOS					28-OCT-2003		
	424	HRS/MSC	O/C				0		
	REF: AMM 55-30-01	AFL					0		
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				28-OCT-2003 0 0	20000 27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	N/A				28-OCT-2003 0 0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 2,4	MOS	12				03-AUG-2018		
	REF:	HRS/MSC AFL	100				8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 2	MOS	12				PKG 03-AUG-2018 8020:35 7175		
	REF: AMM 55-00-00	HRS/MSC AFL							
55-10/415	HORIZONTAL STABILIZER PN	MOS		TSN:0			28-OCT-2003		
LIFE LIMIT	SN-UNKNOWN REF: AMM 55-10-01	HRS/MSC AFL	25000 30000	TSN:0 TSN:0			0 0	25000 30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		16	01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%					
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		16	01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%					
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE PKG 2,4	MOS	12				03-AUG-2018 8020:35 7175		
	REF:	HRS/MSC AFL	100						



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/199 (s)	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
	REF:	HRS/MSC	100				8020:35		
		AFL					7175		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC					8020:35		
		AFL					7175		
55-30/369	EXAMINE - VERTICAL STABILIZER								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
		MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/373	EXAMINE - RUDDER								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
CHAPTER 56	WINDOWS								
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
	REF: AMM 56-00-00	HRS/MSC AFL	100				8020:35 7175		
56-11/14	REPLACE LEFT HAND WINDSHIELD (INNER LAMINATION CRACKED)	MOS					02-JUN-2014		
	959.81.10.109	HRS/MSC AFL	A/R				5591:10 4894		
	REF:								
56-11/14	REPLACE RIGHT HAND WINDSHIELD (INNER LAMINATION CRACKED)	MOS					10-MAR-2011		
	959.81.10.110	HRS/MSC AFL	A/R				3990:33 3376		
	REF:								
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					02-JUN-2014		
	959.81.10.109	HRS/MSC AFL	A/R				5591:10 4894		
	REF:								
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					10-MAR-2011		
	959.81.10.110	HRS/MSC AFL	A/R				3990:33 3376		
	REF:								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS	MOS	120	+6m/-6m			06-FEB-2014	28-OCT-2023	28-APR-2024
	REF: AMM 56-11-02	HRS/MSC	11000	+500/-500			5394:50	16394:50	16894:50
		AFL					4695		
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS	MOS	12				PKG		
	PKG 2,4	HRS/MSC	100				03-AUG-2018		
	REF: AMM 56-00-00	AFL					8020:35		
							7175		
560015	SIDE,LH WINDOW	MOS			TSN:0		28-OCT-2003		
56.090	959.81.10.111	HRS/MSC	O/C		TSN:0		0		
	02196H1064	AFL			TSN:0		0		
	REF: AMM 56-11-02								
560020	SIDE,RH WINDOW	MOS			TSN:0		28-OCT-2003		
56.090	959.81.10.112	HRS/MSC	O/C		TSN:0		0		
	02198H1357	AFL			TSN:0		0		
	REF: AMM 56-11-02								
560025	RH NO 1 CABIN WINDOW	MOS			TSN:0		28-OCT-2003		
56.060	556.20.12.029	HRS/MSC	O/C		TSN:0		0		
	3448	AFL			TSN:0		0		
	REF: AMM 56-20-01								
560030	RH NO 2 CABIN WINDOW	MOS			TSN:0		28-OCT-2003		
56.060	556.20.12.029	HRS/MSC	O/C		TSN:0		0		
	3464	AFL			TSN:0		0		
	REF: AMM 56-20-01								
560035	RH NO 3 CABIN WINDOW	MOS			TSN:0		28-OCT-2003		
56.070	556.20.12.029	HRS/MSC	O/C		TSN:0		0		
	3465	AFL			TSN:0		0		
	REF: AMM 56-20-01								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	556.20.12.029 3466 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	556.20.12.029 3467 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	556.20.12.029 3473 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	556.20.12.029 3475 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	556.20.12.029 3478 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	556.20.12.029 3481 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
560070	DV-WINDOW ASSY								
56.030	556.14.12.100 15166H5808 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-NOV-2015 6405:35 5696		
561010	LEFT HAND WINDSHIELD								
56.010	959.81.10.109 13346H8940 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-JUN-2014 5591:10 4894		
AIRWORTHINESS									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561011	RIGHT HAND WINDSHIELD								
	959.81.10.110	MOS		TSN:0			10-MAR-2011		
56.010	10296H5486	HRS/MSC	O/C	TSN:0			3990:33		
AIRWORTHINESS	REF:	AFL		TSN:0			3376		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT	WING STRUCTURE							
		MOS					28-OCT-2003		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
57-00/11	STRUCTURAL LIMITATION RIGHT	WING STRUCTURE							
		MOS					28-OCT-2003		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
		HRS/MSC	100				8020:35		
	REF:	AFL					7175		
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK						PKG		
	06-00/218 OPENED/REMOVED								
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 2	MOS	12				03-AUG-2018		
		HRS/MSC					8020:35		
	REF:	AFL					7175		
57-00/326	STRUCTURAL LIMITATION LEFT	WING STRUCTURE (POST SB 04-009)							
		MOS					28-OCT-2003		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF:	AFL					0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/326	STRUCTURAL LIMITATION RIGHT	WING STRUCTURE (POST SB 04-009)							
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	N/A				28-OCT-2003 0 0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING								
AIRWORTHINESS	REF: AMM 57-00-00	MOS HRS/MSC AFL	30000 39000				28-OCT-2003 0 0	30000 39000	
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				28-OCT-2003 0 0	30000 39000	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT								
AIRWORTHINESS	REF: AMM 57-20-10	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
AIRWORTHINESS	REF: AMM 57-20-10	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
AIRWORTHINESS	REF: AMM 57-20-05	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
AIRWORTHINESS	REF: AMM 57-20-10	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
57-00/412	EXAMINE WING TIPS								
AIRWORTHINESS	REF: AMM 57-33-00	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					28-OCT-2003		
	REF:	HRS/MSC	16000				0		16000
		AFL	22500				0		22500
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
57.020	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
		AFL					6775		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
57.030	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
		AFL					6775		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m		-101	06-FEB-2014	28-OCT-2023	28-APR-2024
57.040	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			5394:50	16394:50	16894:50
		AFL					4695		
57-60/393	EXAMINE LEFT WING AILERON	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-60/411	EXAMINE AILERON TRIM TAB	MOS					28-OCT-2003		
	REF: AMM 57-60-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
570010	AILERON RH 10A SERIE ASSY	MOS					28-OCT-2003		
57.050	557.05.12.011	HRS/MSC	O/C				0		
	435	AFL					0		
	REF: AMM 57-60-01						0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570015	WING RE 10A SERIE STRUCTURE								
57.070	557.05.12.127 429 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
570025	AILERON LH 10A SERIE ASSY								
57.050	557.05.12.012 435 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
570035	WING LE 10A SERIE STRUCTURE								
57.070	557.05.12.128 429 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		

CHAPTER 61 PROPELLERS/PROPULSORS

61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC AFL					8020:35 7175		
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E4A-3D/E10477SK KX-738 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C	TSN:2427:05			09-DEC-2015 6419:30 5711		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

+ 612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	3049558-01	MOS		TSN:0			24-MAY-2018		
	21234393	HRS/MSC	3500	+500	TSN:0		0	(3500) 11520:35	4000
OVERHAUL	REF: GENERIC NO REF	ENC		TSN:0			0		
+ 612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
	3079148-01	MOS		TSN:0			24-MAY-2018		
	21238755	HRS/MSC	3500	+500	TSN:0		0	(3500) 11520:35	4000
OVERHAUL	REF: GENERIC NO REF	ENC		TSN:0			0		

PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX-738 Part # HC-E4A-3D/E10477SK



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	72 4000				14-MAY-2015 2021:25	14-MAY-2021 (6021:25) 10013:50	
OVERHAUL	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			03-AUG-2018 4028:10	03-AUG-2019 (4328:10) 8320:35	03-SEP-2019 4358:10
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%		8:45	03-AUG-2018 4028:10	03-AUG-2019 (4336:55) 8329:20	03-SEP-2019 4366:55
	REF:								
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE 9682913003 K82995 REF: GENERIC NO REF	MOS HRS/MSC	O/C		TSN:0 TSN:0		31-JUL-2009 0		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE 9682913003 K82990 REF: GENERIC NO REF	MOS HRS/MSC	O/C		TSN:0 TSN:0		31-JUL-2009 0		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE 9682913003 K82991 REF: GENERIC NO REF	MOS HRS/MSC	O/C		TSN:0 TSN:0		31-JUL-2009 0		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913003 K83000 REF: GENERIC NO REF	MOS HRS/MSC	O/C		TSN:0 TSN:0		31-JUL-2009 0		
CHAPTER 71 POWER PLANT									
71-00/101	OPERATIONAL TEST POWER PLANT TORQUE LIMITER	MOS HRS/MSC AFL	12 450	+10%/-10% +10%/-10%		12:05	03-AUG-2018 8020:35 7175	03-AUG-2019 8482:40	09-SEP-2019 8527:40
71.010	REF: See Workcard								



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/102	OPERATIONAL TEST POWER PLANT PERFORMANCE	MOS	12	+10%/-10%			03-AUG-2018	03-AUG-2019	09-SEP-2019
	REF: AMM 71-00-00	HRS/MSC	450	+10%/-10%			8020:35	8470:35	8515:35
		AFL					7175		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH	MOS					03-AUG-2018		
71.040	REF:	HRS/MSC	150	+10%/-10%	12:05		8020:35	8182:40	8197:40
		AFL					7175		
71-00/107	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS	MOS	12	+10%/-10%			03-AUG-2018	03-AUG-2019	09-SEP-2019
71.030	REF: AMM 71-00-03	HRS/MSC	150	+10%/-10%	12:05		8020:35	8182:40	8197:40
		AFL					7175		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME	MOS					28-OCT-2003		
71.050	571.20.12.036	HRS/MSC	20000				0	20000	
AIRWORTHINESS	429	AFL	27000				0	27000	
	REF: AMM 71-00-05								
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS	MOS					02-OCT-2009		
71.050	REF: AMM 71-00-04	HRS/MSC	11000				3571:05	14571:05	
AIRWORTHINESS		AFL					2975		
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
	REF: AMM 71-00-00	HRS/MSC	100				8020:35		
		AFL					7175		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 2	MOS	12				03-AUG-2018		
	REF:	HRS/MSC	100				8020:35		
		AFL					7175		
71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION						PKG		
	PKG 2,4	MOS	12				03-AUG-2018		
	REF:	HRS/MSC	100				8020:35		
		AFL					7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT PKG 2 REF: AMM 71-00-00	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9581 REF: AMM 71-00-01	MOS HRS/MSC AFL	4000/E/C	+1000	TSN:0 TSN:0 TSN:0		03-AUG-2018 8020:35 7175	12020:35	13020:35
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 10812 REF: AMM 71-00-01	MOS HRS/MSC AFL	4000/E/C	+1000	TSN:0 TSN:0 TSN:0		03-AUG-2018 8020:35 7175	12020:35	13020:35
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9678 REF: AMM 71-00-01	MOS HRS/MSC AFL	4000/E/C	+1000	TSN:0 TSN:0 TSN:0		03-AUG-2018 8020:35 7175	12020:35	13020:35
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9721 REF: AMM 71-00-01	MOS HRS/MSC AFL	4000/E/C	+1000	TSN:0 TSN:0 TSN:0		03-AUG-2018 8020:35 7175	12020:35	13020:35



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9720 REF: AMM 71-00-01	MOS HRS/MSC AFL	4000/E/C +1000	TSN:0 TSN:0 TSN:0			03-AUG-2018 8020:35 7175	12020:35	13020:35
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT REF: AMM 71-00-05	MOS HRS/MSC AFL	26600 35000				28-OCT-2003 0 0	26600 35000	
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		
710005 71.070	UPPER LH ENGINE VIBRATION ISOLATOR 571.20.12.106 1062 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
710015 71.080	UPPER CENTER ENGINE VIBRATION ISOLATOR 571.20.12.106 1066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
710025 71.090	UPPER RH ENGINE VIBRATION ISOLATOR 571.20.12.106 1070 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
710035 71.100	LOWER LH ENGINE VIBRATION ISOLATOR 571.20.12.106 1074 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	571.20.12.106 1079 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3042200 PCE-PR0796 REF: AMM 71-00-01	MOS HRS/MSC AFL ACH	E/C	TSN:0 TSN:0			30-JUL-2018 8020:35 7175		
71JFL02	PERFORM ENGINE RUN-UP								
	REF:	MOS HRS/MSC AFL	A/R				12-NOV-2010 3909:33 3308		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			24-MAY-2018 0 0	(3500) 11520:35	
+ 710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 2 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			24-MAY-2018 0 0		
+ 710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			24-MAY-2018 0 0	(1750) 9770:35	
+ 710031	NO. 1 ENGINE - BORESCOPE HOT SECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	200	+10%/-10%			24-MAY-2018 0 0	(200) 8220:35	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	4000	+100/-100			0 0	(4000) 12020:35	4100
+ 710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION	MOS					24-MAY-2018		
	REF: EMM 71-00-00	HRS/MSC ENC	150	+10%/-10%			0 0	(150) 8170:35	165
+ 710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS					24-MAY-2018		
	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION	MOS					24-MAY-2018		
	PKG 2	HRS/MSC ENC	300				0 0		
	REF: EMM 71-00-00								
710100 (s)	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS					24-MAY-2018		
	PKG 2,4	HRS/MSC ENC	A/R				0 0		
	REF: EMM 72-00-00								

CHAPTER 72 ENGINE

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

+ 720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS					24-MAY-2018		
	PN	HRS/MSC	3500	+500			0	(3500) 11520:35	
	SN-UNKNOWN	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		
720020	NO. 1 ENGINE - COMPRESSOR AIR INLET SCREEN	MOS					24-MAY-2018		
	PN	HRS/MSC	O/C				0		
	SN-UNKNOWN	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 2 REF: EMM 72-20-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 722011	NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 2 REF: EMM 72-20-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3039001 FRAEPWNL47 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		(24000) 31175
LIFE LIMIT									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA769675	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 31175	
+ 723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 2	MOS HRS/MSC ENC	300				24-MAY-2018 0 0		
	REF: EMM 72-30-04								
+ 723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040952 MCAKAXTL198	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 31175	
+ 723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 2	MOS HRS/MSC ENC	300				24-MAY-2018 0 0		
	REF: See Workcard								
+ 723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 FRAEPWMK16	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 31175	
+ 723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAE000L278	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 31175	
+ 723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 FRAEPWMN55	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 31175	
+ 725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 YUAB001K898	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
LIFE LIMIT	REF: GENERIC NO REF		8000					(8000) 15175	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000				24-MAY-2018 0 0	(5000) 13020:35	
LIFE LIMIT									
725022	NO. 1 ENGINE - 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	H/T	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 2 REF: EMM 72-50-05	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A00485BA REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0	(15000) 22175	
LIFE LIMIT									
+ 725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 YUAB001L056 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0	(15000) 22175	
LIFE LIMIT									
725050	NO. 1 ENGINE - COMPRESSOR TURBINE BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
726010	NO. 1 ENGINE - ACCESSORY GEARBOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500 TSN:0 TSN:0			24-MAY-2018 0 0	(3500) 11520:35	
OVERHAUL									



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726030	NO. 1 ENGINE - ELECTRICAL FILLER CAP AND INDICATOR, OIL-LEVEL								
	PN	MOS		TSN:0			24-MAY-2018		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

CHAPTER 73 ENGINE FUEL AND CONTROL

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

+ 731010	NO. 1 ENGINE - FUEL PUMP								
	3040760	MOS		TSN:0			24-MAY-2018		
	016070	HRS/MSC	3500	TSN:0			0	(3500) 11520:35	
OVERHAUL	REF: EMM 73-10-02	ENC		TSN:0			0		
+ 731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)								
		MOS					24-MAY-2018		
		HRS/MSC	400	+10%/-10%			0	(400) 8420:35	
	REF: See Workcard	ENC					0		
+ 731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)								
		MOS					24-MAY-2018		
		HRS/MSC	200	+10%/-10%			0	(200) 8220:35	
	REF: EMM 73-11-05	ENC					0		
+ 731030	NO. 1 ENGINE - OVERTORQUE LIMITER								
	3055748-01	MOS		TSN:0			24-MAY-2018		
	C51806	HRS/MSC	3500	+500	TSN:0		0	(3500) 11520:35	4000
OVERHAUL	REF: GENERIC NO REF	ENC		TSN:0			0		
+ 731031 (s)	NO. 1 ENGINE - CHECK FUEL PUMP FOR INSTALLATION AND LEAKS						PKG		
	PKG 2	MOS					24-MAY-2018		
		HRS/MSC	300				0		
	REF: EMM 73-10-02	ENC					0		
+ 731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION								
		MOS					24-MAY-2018		
		HRS/MSC	N/A				0		
	REF: EMM 73-10-02	ENC					0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 016070 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-MAY-2018 0 0	(600) 8620:35	
+ 731045 (s)	NO. 1 ENGINE - CHECK OIL-TO-FUEL HEATER INSTALLATION PKG 2 REF: EMM 73-10-01	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 016070 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 731055	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-MAY-2018 0 0	(600) 8620:35	
+ 731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300				PKG 24-MAY-2018 0 0		
+ 731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA57209 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500			24-MAY-2018 0 0	(3500) 11520:35	4000



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%			24-MAY-2018 0 0	(300) 8320:35	330
+ 731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0966 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500			24-MAY-2018 0 0	(3500) 11520:35	4000
731080	NO. 1 ENGINE - FUEL BOOST PUMP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				24-MAY-2018 0 0		
+ 731085 (s)	NO. 1 ENGINE - CHECK DRAIN VALVE(S) FOR INSTALLATION AND LEAKS PKG 2 REF: EMM 73-10-06	MOS HRS/MSC ENC	300				24-MAY-2018 0 0		
+ 731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-10 21259572 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500			24-MAY-2018 0 0	(3500) 11520:35	4000
	OVERHAUL								
+ 731091 (s)	NO. 1 ENGINE - CHECK FLOW DIVIDER FOR INSTALLATION AND LEAKS PKG 2 REF: EMM 73-10-04	MOS HRS/MSC ENC	300				24-MAY-2018 0 0		
+ 731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				24-MAY-2018 0 0		
+ 731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			24-MAY-2018 0 0	(300) 8320:35	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2	MOS	300				PKG 24-MAY-2018 0 0		
	REF: EMM 73-10-02	ENC							
+ 731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER PN	MOS		TSN:0			24-MAY-2018 0 0		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0					
	REF: EMM 73-10-02	ENC		TSN:0					
732010	NO. 1 ENGINE - FUEL FLOW TRANSMITTER PN	MOS		TSN:0			24-MAY-2018 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0					
	REF: GENERIC NO REF	ENC		TSN:0					
+ 732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2	MOS	300				PKG 24-MAY-2018 0 0		
	REF: EMM 73-20-00	ENC							
+ 733020	NO. 1 ENGINE - REPLACE P3 FILTER	MOS	900	+10%/-10%			24-MAY-2018 0 0	(900) 8920:35	
	REF: EMM 73-10-07	ENC							
733030	NO. 1 ENGINE - MAIN FUEL FILTER ASSEMBLY PN	MOS		TSN:0			24-MAY-2018 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0					
	REF: GENERIC NO REF	ENC		TSN:0					
733040	NO. 1 ENGINE - MAIN FUEL FILTER DRAIN VALVE PN	MOS		TSN:0			24-MAY-2018 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0					
	REF: EMM 73-10-06	ENC		TSN:0					
733050	NO. 1 ENGINE - AFT FUEL DRAIN VALVE PN	MOS		TSN:0			24-MAY-2018 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0					
	REF: GENERIC NO REF	ENC		TSN:0					



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733060	NO. 1 ENGINE - FORWARD FUEL DRAIN VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			24-MAY-2018 0 0	(300) 8320:35	
CHAPTER 74 IGNITION									
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 2,4 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA18140326 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	TSN:0 TSN:0 TSN:0		24-MAY-2018 0 0	(3500) 11520:35	4000
+ 740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%			24-MAY-2018 0 0	(400) 8420:35	
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINES AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			24-MAY-2018 0 0	(400) 8420:35	



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
+ 742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			24-MAY-2018 0 0	(400) 8420:35	
CHAPTER 75 AIR									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX1001362 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	TSN:0 TSN:0 TSN:0		24-MAY-2018 0 0	(3500) 11520:35	4000
CHAPTER 76 ENGINE CONTROLS									
76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 4 ,2 REF: AMM 76-10-00	MOS HRS/MSC AFL	100				PKG 03-AUG-2018 8020:35 7175		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+1m/-1m +10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2019 11020:35	03-SEP-2019 11320:35
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 941.94.11.417 20030032 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
760020 76.030	CONDITION CABLE ASSY. 941.94.11.418 20030039 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
760025 76.040	POWER CONTROL CABLE ASSY. 941.94.11.419 20107336 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		17-SEP-2015 6330:10 5628		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES REF: EMM 72-00-00	MOS HRS/MSC ENC	150	+10%/-10%			24-MAY-2018 0 0	(150) 8170:35	165
CHAPTER 77 ENGINE INDICATING									
77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206 6743-3-720 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2003 0 0		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	975.21.15.212 2342053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.034 502 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2016 6694:55 5975		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

770090	NO. 1 ENGINE - T1 THERMOCOUPLE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NRA103360 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
771020	NO. 1 ENGINE - T5 TERMINAL BLOCK								
	PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		

CHAPTER 78 EXHAUST

78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				03-AUG-2018 8020:35 7175		

CHAPTER 79 OIL



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY. PKG 2,4 REF: AMM 24-00-00	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 03-AUG-2018 8020:35 7175		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 2,4 REF: AMM 79-30-01	MOS HRS/MSC AFL	12 100				PKG 03-AUG-2018 8020:35 7175		
79-20/43 79.010	OIL COOLER 968.32.14.102 T0600 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+500	TSO:0 TSO:0 TSO:0	-658:15	22-MAR-2018 7729:20 6916	10571:05	11071:05
790005 79.020	TEMPERATURE BULB 975.11.20.101 119985 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
790020 79.030	PRESSURE,GAGE SWITCH 973.81.14.305 0445 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		
790025 79.040	THERMAL ACTUATOR 978.73.01.002 0574 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2003 0 0		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					24-MAY-2018		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
+ 790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			24-MAY-2018	24-MAY-2019	
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			0 0	(300) 8320:35	
+ 790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS	12	+1m/-1m			24-MAY-2018	24-MAY-2019	
	REF: See Workcard	HRS/MSC ENC	600	+10%/-10%			0 0	(600) 8620:35	
+ 790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS					24-MAY-2018		
	REF: EMM 79-20-02	HRS/MSC ENC	900	+10%/-10%			0 0	(900) 8920:35	990
+ 790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN	MOS					24-MAY-2018		
	REF: EMM 79-20-02	HRS/MSC ENC	150				0 0	(150) 8170:35	
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS	6	+10%/-10%			24-MAY-2018	24-NOV-2018	12-DEC-2018
	REF: EMM 72-60-00	HRS/MSC ENC	300	+10%/-10%			0 0	(300) 8320:35	330
+ 790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					24-MAY-2018		
	REF: EMM 79-20-02	HRS/MSC ENC	N/A				0 0		
+ 790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS						PKG		
	PKG 2	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	300				0 0		



Status Report

PC12 S/N 522 (LX-JFH): 8139 HRS, 7282 AFL as of 07-Oct-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 08-OCT-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2	MOS	300				PKG 24-MAY-2018 0 0		
	REF:	ENC					0		
792011	NO. 1 ENGINE - OIL FILTER BYPASS CHECK VALVE PN SN-UNKNOWN REF: EMM 79-20-02	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792020	NO. 1 ENGINE - THERMOSTATIC BYPASS CHECK VALVE PN SN-UNKNOWN REF: EMM 79-20-03	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792040	NO. 1 ENGINE - LOW OIL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792050	NO. 1 ENGINE - OIL DRAIN SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792060	NO. 1 ENGINE - OIL LEVEL SIGHT GAGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		
792070	NO. 1 ENGINE - OIL TANK PRESSURIZING VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS	O/C	TSN:0 TSN:0 TSN:0			24-MAY-2018 0 0		