

Status Report

EMB-505 - PHENOM 300
S/N 50500099 F-HJFG

OWNER: GDP VENDOME
ADDRESS: 1 RUE JEAN JAURES
ANNECY HTE SAVOIE 74000
PHONE:
FAX:

OPERATOR: GDP VENDOME
ADDRESS: 1 RUE JEAN JAURES
ANNECY HTE SAVOIE 74000
PHONE:
FAX:

OPERATOR: RCAM AVIATION
ADDRESS: CHEMIN DES PERVENCHES 10
GENEVA
PHONE:
FAX:

ANALYST: HANA FONTANIER +33 (0) 1.55.93.45.80 (OFFICE)
EMAIL: HANA.FONTANIER@CAMPSYSTEMS.EU +33 (0) 1.53.01.66.18 (EFAX-CARDS)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 50500099/F-HJFG **MODEL:** EMB-505 - PHENOM 300 **MANUFACTURER:** EMBRAER

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 01-JUN-2012	618:42 A/C HRS	as of 22-JAN-2019	A/C HRS	as of ___/___/___
	535 AFL	as of 22-JAN-2019	AFL	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-DG0202/3072913-01 **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 16-MAR-2012	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	618:42 ENG. HRS	as of 22-JAN-2019	ENG. HRS	as of ___/___/___
0 ENC	535 ENC	as of 22-JAN-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-DG0209/3072913-01 **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 12-MAY-2012	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	618:42 ENG. HRS	as of 22-JAN-2019	ENG. HRS	as of ___/___/___
0 ENC	535 ENC	as of 22-JAN-2019	ENC	as of ___/___/___



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05-30-01	600 FH MAINTENANCE PACKAGE							
	PKG 1	MOS				20-JUN-2014		
		HRS/MSC	600			389:58		989:58
	REF: SMR 05-30-01	AFL				203		
05-30-02	600 FH/12 MO MAINTENANCE PACKAGE							
	PKG 2	MOS	12			20-JUN-2018	01-JUN-2019	
		HRS/MSC	600		-19	573:42	1173:42	
	REF: SMR 05-30-02	AFL				502		
05-30-10	1200 FH MAINTENANCE PACKAGE							
	PKG 10	MOS				01-JUN-2012		
		HRS/MSC	1200			0		1200
	REF: SMR 05-30-10	AFL				0		
05-30-12	1200 FH/24 MO MAINTENANCE PACKAGE							
	PKG 12	MOS	24			20-JUN-2018	01-JUN-2020	
		HRS/MSC	1200		-19	573:42	1773:42	
	REF: SMR 05-30-12	AFL				502		
05-30-20	1800 FH MAINTENANCE PACKAGE							
	PKG 20	MOS				01-JUN-2012		
		HRS/MSC	1800			0		1800
	REF: SMR 05-30-20	AFL				0		
05-30-40	3000 FH MAINTENANCE PACKAGE							
	PKG 40	MOS				01-JUN-2012		
		HRS/MSC	3000			0		3000
	REF: SMR 05-30-40	AFL				0		
05-30-41	3000 FH/48 MO MAINTENANCE PACKAGE							
	PKG 41	MOS	48			01-JUL-2016	01-JUN-2020	
		HRS/MSC	3000		-30	474:50	3474:50	
	REF: SMR 05-30-41	AFL				341		
+ 05-30-42	3000 FH/60 MO MAINTENANCE PACKAGE							
	PKG 42	MOS	60	+1m/-1m		04-JUL-2017	01-JUN-2022	01-JUL-2022
		HRS/MSC	3000	+30/-30		511:06	3511:06	3541:06
	REF: SMR 05-30-42	AFL				428		
05-30-45	4800 FH MAINTENANCE PACKAGE							
	PKG 45	MOS				01-JUN-2012		
		HRS/MSC	4800			0		4800
	REF: SMR 05-30-45	AFL				0		
05-30-50	6000 FH MAINTENANCE PACKAGE							
	PKG 50	MOS				01-JUN-2012		
		HRS/MSC	6000			0		6000
	REF: SMR 05-30-50	AFL				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue
(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-53	6000 FH/96 MO MAINTENANCE PACKAGE PKG 53 REF: SMR 05-30-53	MOS HRS/MSC AFL	96 6000			01-JUN-2012 0 0	01-JUN-2020 6000	
05-30-60	7800 FH MAINTENANCE PACKAGE PKG 60 REF: SMR 05-30-60	MOS HRS/MSC AFL	7800			01-JUN-2012 0 0	7800	
05-30-65	12000 FH MAINTENANCE PACKAGE PKG 65 REF: SMR 05-30-65	MOS HRS/MSC AFL	12000			01-JUN-2012 0 0	12000	
05-30-80	12 MO MAINTENANCE PACKAGE PKG 80 REF: SMR 05-30-80	MOS HRS/MSC AFL	12	-19		20-JUN-2018 573:42 502	01-JUN-2019	
05-30-81	24 MO MAINTENANCE PACKAGE PKG 81 REF: SMR 05-30-81	MOS HRS/MSC AFL	24	-19		20-JUN-2018 573:42 502	01-JUN-2020	
05-30-82	36 MO MAINTENANCE PACKAGE PKG 82 REF: SMR 05-30-82	MOS HRS/MSC AFL	36		+1m/-1m	20-JUN-2018 573:42 502	20-JUN-2021	20-JUL-2021
05-30-83	48 MO MAINTENANCE PACKAGE PKG 83 REF: SMR 05-30-83	MOS HRS/MSC AFL	48	-30		01-JUL-2016 474:50 341	01-JUN-2020	
05-30-84	60 MO MAINTENANCE PACKAGE PKG 84 REF: SMR 05-30-84	MOS HRS/MSC AFL	60	-33		04-JUL-2017 511:06 428	01-JUN-2022	
05-30-87	120 MO MAINTENANCE PACKAGE PKG 87 REF: SMR 05-30-87	MOS HRS/MSC AFL	120			01-JUN-2012 0 0	01-JUN-2022	
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE PKG 90 REF: SMR 05-30-90	MOS HRS/MSC AFL	120		+30d/-30d	01-JUN-2012 0 0	01-JUN-2022	01-JUL-2022

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051254	NO. 1 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12	+30d	-19	20-JUN-2018	01-JUN-2019	01-JUL-2019
		HRS/MSC	600	+10%		573:42	(1173:42) 1173:42	1233:42
	REF: MM 05-20-00	ENC				502		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01								
051254	NO. 2 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12	+30d	-19	20-JUN-2018	01-JUN-2019	01-JUL-2019
		HRS/MSC	600	+10%		573:42	(1173:42) 1173:42	1233:42
	REF: MM 05-20-00	ENC				502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-CUS-01	AIRWORTHINESS CERTIFICATE RENEWAL	MOS	12				22-JAN-2019 618:42 535	09-FEB-2020 M	
	REF:	HRS/MSC AFL							
EM55-150504	ACCEPTANCE OF EMBRAER AMM 2757 REV 33 - 04 MAY 2015 - (CHAPTER 05).	MOS					27-JUL-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-150504A	ACCEPTANCE OF EMBRAER AMM 2757 REV 8 - 04 MAY 2015 - (CHAPTER 04).	MOS					27-JUL-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-150820	ACCEPTANCE OF EMBRAER REVISION: AMM 2757 REV 35 20-AUG-2015 (CHAPTER 05)	MOS					01-OCT-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-151112	ACCEPTANCE OF EMBRAER REVISION: AMM 2757 REV 36 12-NOV-2015 (CHAPTER 05)	MOS					21-APR-2017 506:06 405		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16	MOS					21-APR-2017 506:06 405		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160520	HRS/MSC - AFL							



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM	MOS HRS/MSC - AFL						27-JUL-2016	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705								
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM	MOS HRS/MSC - AFL						21-APR-2017 506:06 405	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705-1								
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS HRS/MSC - AFL						21-APR-2017 506:06 405	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160822								
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS HRS/MSC - AFL						21-APR-2017 506:06 405	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161022								
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016	MOS HRS/MSC - AFL						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122-1	HRS/MSC - AFL							
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161202	HRS/MSC - AFL							
EM55-161216	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/ MAINTENANCE CHECKS/CHAPTER-5 REVISION 45 DATED DEC 16/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161216	HRS/MSC - AFL							
EM55-170127	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS/CHAPTER-5 REVISION 46 DATED JAN 27/2017 REQUIREMENT SUMMARY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-170127	HRS/MSC - AFL							
EM55-170220	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS / CHAPTER-5 REVISION 47 DATED FEB 20/2017 REQUIREMENT SUMMARY CHANGE FORM	MOS					23-APR-2017		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-170220	HRS/MSC - AFL					506:06 405		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-170320	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS / CHAPTER-5 REVISION 48 DATED MAR 20/2017 REQUIREMENT SUMMARY CHANGE FORM	MOS						23-APR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-170320	HRS/MSC - AFL						506:06 405	
EM55-170522	REVIEW EMBRAER PHENOM 300 (EM55) TLMC / CHAPTER-5 REVISION 49 DATED MAY 22/2017 REQUIREMENT SUMMARY CHANGE FORM	MOS						02-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF EM55-170522	HRS/MSC - AFL							
EM55-170814	REVIEW EMBRAER PHENOM 300 (EM55) SMR / CHAPTER-5 REVISION 00 DATED AUGUST 14/2017 REQUIREMENT SUMMARY CHANGE FORM	MOS						18-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18	MOS						03-APR-2018	
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-180925	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV AR, DATED SEP 25/18	MOS						17-OCT-2018	
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01									



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-150720	NO. 1 ENGINE - REVIEW	PW535E	MM REV 9.0						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					27-JUL-2015		
E53E-150818	NO. 1 ENGINE - REVIEW	PW535E	EMM (P/N 3072702) REVISION NO. 9.1, DATED JUL 23/2015 - CAMP CHANGE FORM						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-151014	NO. 1 ENGINE - REVIEW	PW535E	MM REV 9.2						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-160129	NO. 1 ENGINE - REVIEW	PW535E	MM REV 10						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-160530	NO. 1 ENGINE - REVIEW	PW535E	MM REV 11.0						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-161031	NO. 1 ENGINE - REVIEW	PW535E	MM REV 12.0						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					(EBT)		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-161108	NO. 1 ENGINE - REVIEW	PW535E	MM REV 11.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-170224	NO. 1 ENGINE - REVIEW	PW535E	MM REV 12.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-170512	NO. 1 ENGINE - REVIEW	PW535E	MM REV 12.2				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-170529	NO. 1 ENGINE - REVIEW	PW535E	MM REV 13.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-170911	NO. 1 ENGINE - REVIEW	PW535E	MM REV 14.0				08-JAN-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-180426	NO. 1 ENGINE - REVIEW	PW535E	MM REV 14.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-180430	NO. 1 ENGINE - REVIEW	PW535E	MM REV 15.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-180806	NO. 1 ENGINE - REVIEW	PW535E	MM REV 16.0				15-OCT-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-181012	NO. 1 ENGINE - REVIEW	PW535E	MM REV 16.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
E53E-150720	NO. 2 ENGINE - REVIEW	PW535E	MM REV 9.0				27-JUL-2015		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-150818	NO. 2 ENGINE - REVIEW	PW535E	EMM (P/N 3072702) REVISION NO. 9.1, DATED JUL 23/2015 - CAMP CHANGE FORM				21-APR-2017 506:06 405		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-151014	NO. 2 ENGINE - REVIEW	PW535E	MM REV 9.2				21-APR-2017 506:06 405		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-160129	NO. 2 ENGINE - REVIEW	PW535E	MM REV 10						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-160530	NO. 2 ENGINE - REVIEW	PW535E	MM REV 11.0						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					21-APR-2017 506:06 405		
E53E-161031	NO. 2 ENGINE - REVIEW	PW535E	MM REV 12.0						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					(EBT)		
E53E-161108	NO. 2 ENGINE - REVIEW	PW535E	MM REV 11.1						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					(EBT)		
E53E-170224	NO. 2 ENGINE - REVIEW	PW535E	MM REV 12.1						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					(EBT)		
E53E-170512	NO. 2 ENGINE - REVIEW	PW535E	MM REV 12.2						
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC					(EBT)		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-170529	NO. 2 ENGINE - REVIEW	PW535E	MM REV 13.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-170911	NO. 2 ENGINE - REVIEW	PW535E	MM REV 14.0				08-JAN-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-180426	NO. 2 ENGINE - REVIEW	PW535E	MM REV 14.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-180430	NO. 2 ENGINE - REVIEW	PW535E	MM REV 15.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-180806	NO. 2 ENGINE - REVIEW	PW535E	MM REV 16.0				15-OCT-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
E53E-181012	NO. 2 ENGINE - REVIEW	PW535E	MM REV 16.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-150521	ACCEPTANCE OF EMBRAER REVISION: AMM 2757 REV 34 - 21 MAY 2015(CHAPTER 05).	MOS					27-JUL-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
H140-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE PKG 87	MOS	120	+30d/-30d			PKG		
	REF: AMM 05-42-00	HRS/MSC AFL							
H242-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE PKG 87	MOS	120	+30d/-30d			PKG		
	REF: AMM 05-42-00	HRS/MSC AFL					01-JUN-2012 0 0		
H430-001 (s)	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS PKG 84	MOS	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
	REF: AMM 05-46-00	HRS/MSC AFL							
H700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84	MOS	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
	REF: AMM 05-47-00	HRS/MSC AFL							
H700-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84	MOS	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
	REF: AMM 05-47-00	HRS/MSC AFL							

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H700-003 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
	REF: AMM 05-47-00								
CHAPTER 08 LEVELING AND WEIGHING									
8-0001-1	PERFORM WEIGHT AND BALANCE CHECK	MOS HRS/MSC AFL	48				01-JUL-2016 474:50 341	01-JUL-2020	
	NATIONAL REQUIREMENT REF:								
CHAPTER 21 AIR CONDITIONING									
21-01-01	RH INSC ILLUM PANEL 441-42629-002 1104	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: See Workcard								
21-20-01	AVIONICS BLOWER PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: See Workcard								
21-20-02	AVIONICS/DISPLAY COOLING FAN PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: See Workcard								
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 374	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: See Workcard								
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 375	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: See Workcard								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-05	GROUND COOLING FAN 1133660-3 240 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-21-02-001 (s)	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE PKG 50 REF: AMM 21-21-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
21-21-02-001 (s)	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE PKG 50 REF: AMM 21-21-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR 100000-77 26839 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-23-03	RAM AIR VALVE 505-18030-405 0000709830 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE POSITION PKG 50 REF: AMM 21-23-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 20-JUN-2014 389:58 203		
21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PKG 1 REF: AMM 21-23-03	MOS HRS/MSC AFL	600				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-23-04-001 (s)	OPERATIONAL CHECK OF RAM AIR CHECK VALVES PKG 50 REF: AMM 21-23-04	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
21-23-05-001 (s)	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN PKG 10 REF: AMM 21-23-05	MOS HRS/MSC AFL	1200				PKG 01-JUN-2012 0 0		
21-31-00-002 (s)	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-5 2119286-00719 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-01-001	RESTORATION (OVERHAUL) OF (ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-5 2119286-00719 REF: AMM 21-31-01	MOS HRS/MSC AFL	4800				01-JUN-2012 0 0	4800	
21-31-02	OUTFLOW VALVE 103922-1 103922-00113 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-31-02-001	RESTORATION (OVERHAUL) OF OUTFLOW VALVE 103922-1 103922-00113 REF: AMM 21-31-02	MOS HRS/MSC AFL	4800				01-JUN-2012 0 0	4800	
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE 130664-2 34163-0434 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-31-03-001 (s)	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 01-JUN-2012 0 0		
21-31-04	PRESSURE RELIEF (PRV) VALVE 103918-2 103918-00191 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-31-04-001 (s)	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-41-04	RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
21-52-01	CDM - COMPRESSOR 1133640-4 301 REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-2014 389:54 203		
21-52-01-001	DETAILED INSPECTION OF VCS COMPRESSOR DRIVE MODULE REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		
21-52-01-002 (s)	DISCARD OF COMPRESSOR DRIVE MODULE BELT PKG 20 REF: AMM 21-52-01	MOS HRS/MSC AFL	1800	+30/-30			PKG 20-JUN-2014 389:54 203		
21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION PKG 1 REF: AMM 21-52-01	MOS HRS/MSC AFL	600	+30/-30			PKG 20-JUN-2018 573:42 502		
21-52-01-004	RESTORATION (OVERHAUL) CDM - COMPRESSOR 1133640-4 301 REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			01-JUN-2012 0 0	2000	2030
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE 1133860-4 270 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES PKG 1	MOS					PKG 20-JUN-2014 389:58 203		
	REF: AMM 21-52-03	HRS/MSC AFL	600						
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER 1133850-104	MOS		TSN:0			01-JUN-2012 0 0		
	507	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 2	MOS	12				PKG 20-JUN-2018 573:42 502		
	REF: AMM 12-17-00	HRS/MSC AFL	600						
21-52-08	AIR CONDITION CONDENSER ASSEMBLY 1133760-2	MOS		TSN:0			01-JUN-2012 0 0		
	199	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
21-52-08-001 (s)	GENERAL VISUAL INSPECTION OF VCS CONDENSER PKG 10	MOS					PKG 01-JUN-2012 0 0		
	REF: AMM 21-52-08	HRS/MSC AFL	1200						
21-52-09	AIR CONDITION MIX FLOW CONDENSER FAN 1133720-4	MOS		TSN:0			01-JUN-2012 0 0		
	235	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER 1320260-2	MOS		TSN:0			01-JUN-2012 0 0		
	204	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1	MOS					PKG 20-JUN-2014 389:58 203		
	REF: AMM 21-61-00	HRS/MSC AFL	600						
21-61-01	ECS TEMPERATURE CONTROLLER 1300670-6	MOS					21-NOV-2012 107:58 52		
	236	HRS/MSC AFL	O/C						
	REF: See Workcard								
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					01-JUN-2012 0 0		
	1714	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
	REF: See Workcard								
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					01-JUN-2012 0 0		
	1735	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
	REF: See Workcard								
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					01-JUN-2012 0 0		
	1678	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
	REF: See Workcard								
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					01-JUN-2012 0 0		
	1570	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
	REF: See Workcard								
21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 50	MOS					PKG 01-JUN-2012 0 0		
	REF: AMM 21-61-06	HRS/MSC AFL	6000						



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210001-01	R/H TEMP. MODULATING VALVE 1300330-11 737	MOS HRS/MSC AFL	O/C				23-NOV-2012 107:58 52		
CUSTOMER CODE	REF:								
CHAPTER 22 AUTO FLIGHT									
22-11-00	GMC 715 GUIDANCE PANEL 011-01430-00 15900601 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
22-11-00-001	FUNCTIONAL CHECK AILERON	GSA 81 LOW TORQUE AUTOPILOT SERVO							
AIRWORTHINESS	REF: AMM 22-11-00	MOS HRS/MSC AFL	12				20-JUN-2018 573:42 502	20-JUN-2019	
22-11-00-001	FUNCTIONAL CHECK ELEVATOR	GSA 81 LOW TORQUE AUTOPILOT SERVO							
AIRWORTHINESS	REF: AMM 22-11-00	MOS HRS/MSC AFL	12				20-JUN-2018 573:42 502	20-JUN-2019	
22-11-00-001	FUNCTIONAL CHECK RUDDER	GSA 81 LOW TORQUE AUTOPILOT SERVO							
AIRWORTHINESS	REF: AMM 22-11-00	MOS HRS/MSC AFL	12				20-JUN-2018 573:42 502	20-JUN-2019	
22-11-00-001	FUNCTIONAL CHECK TAIL CONE	GSA 80 HIGH SPEED AUTOPILOT SERVO							
AIRWORTHINESS	REF: AMM 22-11-00	MOS HRS/MSC AFL	12				20-JUN-2018 573:42 502	20-JUN-2019	
22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS PKG 12 REF: AMM 22-11-00	MOS HRS/MSC AFL	24 1200				PKG 20-JUN-2018 573:42 502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-00-003 (s)	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE PKG 42 REF: AMM 22-11-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 04-JUL-2017 511:06 428		
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO 011-00877-21 1A0005653 REF: See Workcard	MOS HRS/MSC AFL	O/C				06-MAR-2013 166 85		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1007273 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1007316 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		
22-11-02	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1007323 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK006764 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK006724 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK006719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT 011-01904-00 1GK007149 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 23 COMMUNICATIONS									
23-10-01	VHF ANTENNA S65-8280-41 322-2870 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-11-01	PS440 HF CONTROL COMPUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-11-02	REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-11-03	KPA 1052 POWER AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-11-04	HF ANTENNA COUPLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-12-02	BOTTOM VHF 2 ANTENNA S65-8280-41 322-2890 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-21-01	SELCAL CSD DECODER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-50-01	LEFT GMA 1347D AUDIO PANEL 011-01257-20 17106659 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-50-02	COPILOT HEADSET 026-55-999-0131 00200924 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-50-02	PILOT HEADSET 026-55-999-0131 00200923 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-50-03	HAND MICROPHONE 85-03-12369-04 259892 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-50-04	COCKPIT SPEAKER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-50-05	CDVR MICROPHONE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3000				PKG 01-JUN-2012 0 0		
23-51-01	RIGHT GMA 1347D AUDIO PANEL 011-01257-20 17106744 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-51-05	LEFT CONTROL PANEL 441-40943-002 0810 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-51-05	RIGHT CONTROL PANEL 441-40943-002 0806 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
CHAPTER 23-50	COMMUNICATIONS								
23-50-06	CABIN HEADSET 308100-0280 048184C13540034AE REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-NOV-2014 391:14 205		
CHAPTER 24	ELECTRICAL POWER								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-01-01	LEFT CONSOLE CONTROL PANEL 441-40929-002 0436 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
24-31-01	NO. 1 ENGINE STARTER/GENERATOR 400SG180Q S00815XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			04-JUL-2017 511:06 428		
24-31-01	NO. 2 ENGINE STARTER/GENERATOR 400SG180Q S00832XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			04-JUL-2017 511:06 428		
24-31-01-001	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00815XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200				04-JUL-2017 511:06 428	1711:06	
24-31-01-001	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00832XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200				04-JUL-2017 511:06 428	1711:06	
24-31-01-002	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00815XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600				04-JUL-2017 511:06 428	1111:06	



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01-002	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00832XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600				04-JUL-2017 511:06 428	1111:06	
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S00815XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S00832XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
24-31-01-004	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S00815XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
24-31-01-004	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S00832XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT GCSG550-12B 60581 REF: See Workcard	MOS HRS/MSC AFL	O/C				04-JUL-2017 511:06 428		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT GCSG550-12B 60576 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			04-JUL-2017 511:06 428		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 20-JUN-2018 573:42 502		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 20-JUN-2018 573:42 502		
24-36-01	AFT MAIN BATTERY 7638-48P G02956203 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-DEC-2018 607:48 524		
24-36-01	FORWARD MAIN BATTERY 7639-34 G02991466 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			20-JUN-2018 573:42 502		
24-36-01-003	DISCARD AFT MAIN BATTERY 7638-48P G02956203 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			10-DEC-2018 607:48 524	10-DEC-2020 1124	09-JAN-2021 1154
24-36-01-003	DISCARD FORWARD MAIN BATTERY 7639-34 G02991466 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			20-JUN-2018 573:42 502	20-JUN-2020 1102	20-JUL-2020 1132

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7638-48P G02956203 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7639-34 G02991466 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015) 7638-48P G02956203 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			10-DEC-2018 607:48 524	10-DEC-2019	09-JAN-2020
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) 7639-34 G02991466 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			20-JUN-2018 573:42 502	20-JUN-2019	20-JUL-2019
24-36-02-001 (s)	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2) PKG 50 REF: AMM 24-36-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0421 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		
24-65-00	W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-01	LEFT POWER DISTRIBUTION BOX SX7EG20-1B 0097 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-MAY-2013 230:53 119		
24-65-02	RIGHT POWER DISTRIBUTION BOX SX7EG21-1B 0099 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-MAY-2013 230:53 119		
24-65-04	NOSE POWER DISTRIBUTION BOX SX7EG22-1B 0091 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2			22-MAR-2014 384 201		
24310420-0902	START CTR2 CONTACTOR SM400D117-1 9094 REF:	MOS HRS/MSC AFL	O/C				08-MAR-2013 166 85		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
25 EEI-1 (s)	INSPECT EMERGENCY EQUIPMENT (FAR 91.409 AND FAR 91.513) PKG 80 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				PKG 20-JUN-2018 573:42 502		
25-11-01	COPILOT SEAT 1419-02AH 191-1419 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-11-01	PILOT SEAT 1419-01AH 189-1419 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-01-001 (s)	DETAILED INSPECTION COPILOT SEAT PKG 40 REF: AMM 25-11-01	SEAT MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341		3474 M 3504
25-11-01-001 (s)	DETAILED INSPECTION PILOT SEAT PKG 40 REF: AMM 25-11-01	SEAT MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341		3474 M 3504
25-11-01-002 (s)	DETAILED INSPECTION OF COCKPIT SEAT BELTS PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341		3474 M 3504
25-21-01	PAX 1 - RH AFT FACE SEAT 403174-4F1GZ 52306 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
25-21-01	PAX 2 - LH AFT FACE SEAT 403174-1F1GZ 52301 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
25-21-01	PAX 3 - RH AFT FACE SEAT 403174-2F1GZ 52303 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
25-21-01	PAX 6 - LH FWD FACE SEAT 403174-3F1GZ 52304 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01	PAX 7 - RH FWD FACE SEAT 403174-4F1GZ 52305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER SEATS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341	3474 M	3504
25-21-01-002 (s)	DETAILED INSPECTION OF PASSENGER SEAT BELTS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341	3474 M	3504
25-21-02-001	DETAILED INSPECTION DIVAN REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		
25-21-02-002	DETAILED INSPECTION DIVAN SEAT BELTS REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		
25-21-03	PAX 4 - LH FWD FACE SEAT 403174-1F1GZ 52300 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-21-03	PAX 5 - RH FWD FACE SEAT 403174-2F1GZ 52302 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-04-001	RESTORATION DIVAN (OVERHAUL) OF SEAT BELT AIRBAG SYSTEM	MOS HRS/MSC AFL	N/A						
	REF: AMM 25-21-04								
25-43-01-001	DETAILED VISUAL INSPECTION BELTED TOILET UNIT	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		
NOT INSTALLED	REF: AMM 25-43-02								
25-43-01-002	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		
NOT INSTALLED	REF: AMM 25-43-02								
25-60-01	EMERGENCY LOCATOR TRANSMITTER	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	S1821502-02 LX1100018274 REF: See Workcard								
25-60-03	ELT ANTENNA	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	S65-8282-406 TM0000032826 REF: See Workcard								
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY	MOS HRS/MSC AFL	O/C	TSN:6 TSN:0 TSN:0			04-JUL-2017 511:06 428		
	S1820516-99 TM0000088249 REF: See Workcard								
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM	MOS HRS/MSC AFL	12		-19		20-JUN-2018 573:42 502	01-JUN-2019	
	S1821502-02 LX1100018274 REF: AMM 25-61-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-00-002	GENERAL VISUAL INSPECTION S1821502-02 LX1100018274 REF: AMM 25-61-00	EMERGENCY LOCATOR TRANSMITTER		OF EMERGENCY LOCATOR TRANSMITTER			20-JUN-2018 573:42 502	01-JUN-2019	
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY S1820516-99 TM0000088249 REF: AMM 25-61-04	MOS HRS/MSC AFL	12 DUE				04-JUL-2017 511:06 428	01-NOV-2023 M	
25-61-05	CS144-A ELT/NAV INTERFACE MODULE S1825502-02 TM0000016679 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
+ 25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE S1825502-02 TM0000016679 REF: AMM 25-61-07	MOS HRS/MSC AFL	120 16000				01-JUN-2012 0 0	01-JUN-2022 16000	
25-62-01	FIRST AID KIT S6-01-0005-312 MX309 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		TSN:104 TSN:153:42 TSN:238		20-JUN-2018 573:42 502		
25-62-01-001	VISUAL CHECK FIRST AID KIT S6-01-0005-312 MX309 REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				20-JUN-2018 573:42 502	12-JUN-2019 M	
25-62-02	COPILOT LIFE VEST 66601-505 L1817430 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	NO. 1 PASSENGER LIFE VEST 66601-105 L1811079 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 2 PASSENGER LIFE VEST 66601-105 L1811080 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 3 PASSENGER LIFE VEST 66601-105 L1811083 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 4 PASSENGER LIFE VEST 66601-105 L1811086 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 5 PASSENGER LIFE VEST 66601-105 L1811087 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 6 PASSENGER LIFE VEST 66601-105 L1811088 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02	NO. 7 PASSENGER LIFE VEST 66601-105 L1811089 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	PILOT LIFE VEST 66601-505 L1817429 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
25-62-02-003	DISCARD COPILOT LIFE VEST 66601-505 L1817430 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-MAR-2012 01-MAR-2022		
25-62-02-003	DISCARD NO. 1 PASSENGER LIFE VEST 66601-105 L1811079 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012 01-FEB-2022		
25-62-02-003	DISCARD NO. 2 PASSENGER LIFE VEST 66601-105 L1811080 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012 01-FEB-2022		
25-62-02-003	DISCARD NO. 3 PASSENGER LIFE VEST 66601-105 L1811083 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012 01-FEB-2022		
25-62-02-003	DISCARD NO. 4 PASSENGER LIFE VEST 66601-105 L1811086 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012 01-FEB-2022		
25-62-02-003	DISCARD NO. 5 PASSENGER LIFE VEST 66601-105 L1811087 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012 01-FEB-2022		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02-003	DISCARD NO. 6 PASSENGER LIFE VEST 66601-105 L1811088 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012	01-FEB-2022	
25-62-02-003	DISCARD NO. 7 PASSENGER LIFE VEST 66601-105 L1811089 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-FEB-2012	01-FEB-2022	
25-62-02-003	DISCARD PILOT LIFE VEST 66601-505 L1817429 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-MAR-2012	01-MAR-2022	
25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER PKG 81 REF: AMM 25-62-04	MOS HRS/MSC AFL	24				PKG 20-JUN-2018 573:42 502		
25-66-01 (s)	LIFE RAFT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A						
N/A EQUIPMENT NOT INSTALLED									
25-66-01-001 (s)	RESTORATION LIFE RAFT (OVERHAUL) PN SN-UNKNOWN REF: AMM 25-66-01	MOS HRS/MSC AFL	N/A						
N/A EQUIPMENT NOT INSTALLED									
CHAPTER 26 FIRE PROTECTION									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-11-01	LEFT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 46298 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
26-11-01	RIGHT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 46212 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200				PKG 01-JUN-2012 0 0		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200				PKG 01-JUN-2012 0 0		
26-11-01-002 (s)	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200				PKG 01-JUN-2012 0 0		
26-11-01-002 (s)	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200				PKG 01-JUN-2012 0 0		
26-15-01	MODEL 602 SMOKE DETECTOR 8930-223B60L014 21316 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 59362A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL REF: AMM 26-21-00	MOS HRS/MSC AFL	2400				01-JUN-2012 0 0	2400	
AIRWORTHINESS									
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL 441-42702-002 0450 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
26-21-03-001 (s)	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHER BOTTLE OF ENGINE EXTINGUISHING BOTTLE 33000073-1 PKG 87 59362A1 REF: AMM 26-21-03	MOS HRS/MSC AFL	120				PKG 01-MAY-2011		
AIRWORTHINESS									
26-21-05-001 (s)	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) PKG 20 REF: AMM 26-21-05	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
26-21-07	NO. 1 CARTRIDGE 30903962-1 2008ML REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
26-21-07	NO. 2 CARTRIDGE 30903963-1 2074MD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-07-001 (s)	DISCARD NO. 1 CARTRIDGE 30903962-1 PKG 87 2008ML REF: AMM 26-21-07	MOS HRS/MSC AFL	120				PKG 01-MAY-2011		
LIFE LIMIT									
26-21-07-001 (s)	DISCARD NO. 2 CARTRIDGE 30903963-1 PKG 87 2074MD REF: AMM 26-21-07	MOS HRS/MSC AFL	120				PKG 01-MAY-2011		
LIFE LIMIT									
26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 REF: AMM 26-21-09	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER BA51015-5 092589 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:10 TSN:0 TSN:0			13-JUL-2015 420 264		
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER BA51015-5 096846 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER BA51015-5 092589 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				11-JUN-2018	11-JUN-2019	
26-24-01-001	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER BA51015-5 096846 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				11-JUN-2018	11-JUN-2019	



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER P/N RTA1200 BA51015-5 092589 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
26-24-01-002	DISCARD COCKPIT PORTABLE FIRE EXTINGUISHER P/N RTA1200 BA51015-5 096846 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER P/N BA51015G-3 / -5 BA51015-5 092589 REF: AMM 26-24-01	MOS HRS/MSC AFL	120				03-SEP-2014	03-SEP-2024	
26-24-01-003	DISCARD COCKPIT PORTABLE FIRE EXTINGUISHER P/N BA51015G-3 / -5 BA51015-5 096846 REF: AMM 26-24-01	MOS HRS/MSC AFL	120				23-JUN-2015	23-JUN-2025	

CHAPTER 27 FLIGHT CONTROLS

27-001	LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0262 REF: See Workcard	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	1800
27-001	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0261 REF: See Workcard	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	1800
27-002	LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0434 REF: See Workcard	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	1800



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-002	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0436	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		1800
LIFE LIMIT	REF: See Workcard								
27-003	LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0527	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		1800
LIFE LIMIT	REF: See Workcard								
27-003	RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0520	MOS HRS/MSC AFL	1800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		1800
LIFE LIMIT	REF: See Workcard								
27-004	ROLL TRIM ACTUATOR 470500-1005 0124	MOS HRS/MSC AFL	8500	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		8500
LIFE LIMIT	REF: See Workcard								
27-005	YAW TRIM ACTUATOR 470600-1005 0122	MOS HRS/MSC AFL	8500	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		8500
LIFE LIMIT	REF: See Workcard								
27-006	PITCH TRIM ACTUATOR 467500-1003 0135	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-007	LEFT SPOILER ACTUATOR 456800-1003 0247	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		35000
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-007	RIGHT SPOILER ACTUATOR 456800-1003 0249	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR SYLC-53058 1671	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			04-JUL-2017 511:06 428		
27-009	RUDDER BOOSTER ACTUATOR 9125-3 0129T	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-01-01	LEFT CONTROL WHEEL 83912139 00608	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-01-01	RIGHT CONTROL WHEEL 83912141 00001	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81	MOS HRS/MSC AFL	24				PKG 20-JUN-2018 573:42 502		
27-010	LEFT TOGGLE LINK 456870-1001 0207	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		35000
LIFE LIMIT	REF: See Workcard								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-010	RIGHT TOGGLE LINK 456870-1001	MOS		TSN:0			01-JUN-2012		
	0208	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-011	STICK PUSHER ACTUATOR 9124-1	MOS		TSN:0			01-JUN-2012		
	0142T	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-012	POWER DRIVE UNIT 467700-1003	MOS		TSN:0			01-JUN-2012		
	0141	HRS/MSC	6000	TSN:0			0		6000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-013	LEFT FLAP POSITION SENSOR UNIT 457310-1001	MOS		TSN:0			01-JUN-2012		
	0295	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-013	RIGHT FLAP POSITION SENSOR UNIT 457310-1001	MOS		TSN:0			01-JUN-2012		
	0296	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-014	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005	MOS		TSN:0			01-JUN-2012		
	SSW0478	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-014	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005	MOS		TSN:0			01-JUN-2012		
	SSW0484	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-014	RIGHT INBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS		TSN:0			01-JUN-2012		
	SSW0481	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-014	RIGHT OUTBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS		TSN:0			01-JUN-2012		
	SSW0480	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-015	LEFT CENTER FLAP FLEXIBLE	2 SHAFT							
	457360-1007	MOS		TSN:0			01-JUN-2012		
	SSW0245	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-015	RIGHT CENTER FLAP FLEXIBLE	2 SHAFT							
	457360-1007	MOS		TSN:0			01-JUN-2012		
	SSW0249	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL								
	462900-1017	MOS					04-JUL-2017		
	0620	HRS/MSC	O/C				511:06		
	REF: See Workcard	AFL					428		
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL								
	462900-1017	MOS					04-JUL-2017		
	0793	HRS/MSC	O/C	TSN:1283			511:06		
	REF: See Workcard	AFL		TSN:1066			428		
27-03-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP						PKG		
	PKG 50	MOS					01-JUN-2012		
		HRS/MSC	6000				0		
	REF: AMM 27-03-01	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-03-01-003 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER PKG 50	MOS					PKG 01-JUN-2012		
	REF: AMM 27-03-01	HRS/MSC AFL	6000				0 0		
27-03-01-004 (s)	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR PKG 50	MOS					PKG 01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-03-01	HRS/MSC AFL	6000				0 0		
27-04-01	TRIM ACTUATOR CONTROLLER 475200-1005	MOS					01-JUN-2012		
	0165	HRS/MSC AFL	O/C	TSN:0			0 0		
	REF: See Workcard			TSN:0			0		
27-04-01-001 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER PKG 50	MOS					PKG 01-JUN-2012		
	REF: AMM 27-04-01	HRS/MSC AFL	6000				0 0		
27-04-01-002 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP PKG 50	MOS					PKG 01-JUN-2012		
	REF: AMM 27-04-01	HRS/MSC AFL	6000				0 0		
27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42	MOS	60	+1m/-1m			PKG 04-JUL-2017		
	REF: AMM 27-11-00	HRS/MSC AFL	3000	+30/-30			511:06 428		
27-11-01	LEFT AILERON PN	MOS					01-JUN-2012		
	SN-UNKNOWN	HRS/MSC AFL	O/C	TSN:0			0 0		
	REF: See Workcard			TSN:0			0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-11-01	RIGHT AILERON 505-14740-4001 0000707222 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			01-JUL-2016 474:50 341	01-JUL-2021 3474:50	01-AUG-2021 3504:50
27-11-02-002 (s)	DETAILED INSPECTION OF AILERON CONTROL CABLES PKG 42 REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 04-JUL-2017 511:06 428		
27-14-02-001 (s)	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY PKG 50 REF: AMM 27-14-03	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
AIRWORTHINESS									
27-14-02-002 (s)	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM PKG 50 REF: AMM 27-14-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
AIRWORTHINESS									
27-14-03	LEFT AILERON TAB 505-43063-4001 0000703861 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-21-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 04-JUL-2017 511:06 428		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-21-01	RUDDER ASSEMBLY 505-39084-405 0000722909 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION REF: AMM 27-21-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			01-JUL-2016 474:50 341	01-JUL-2021 3474:50	01-AUG-2021 3504:50
27-21-02-002 (s)	DETAILED INSPECTION OF RUDDER CONTROL CABLES PKG 42 REF: AMM 27-21-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 04-JUL-2017 511:06 428		
27-23-00-001 (s)	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM PKG 1 REF: AMM 27-23-00	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
27-24-02-001 (s)	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH PKG 50 REF: AMM 27-24-03	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
AIRWORTHINESS									
27-24-02-002 (s)	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM PKG 50 REF: AMM 27-24-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
AIRWORTHINESS									
27-24-03	RUDDER TRIM TAB 505-10450-403 0000717359 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-26-01	VENTRAL RUDDER 505-07540-417 0000713398 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-31-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 04-JUL-2017 511:06 428		
27-31-01	LEFT ELEVATOR 505-43071-4001 0000702997 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-31-01	RIGHT ELEVATOR 505-43071-4002 0000706856 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			01-JUL-2016 474:50 341	01-JUL-2021 3474:50	01-AUG-2021 3504:50
27-31-02-002 (s)	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES PKG 42 REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3000	+30/-30			PKG 04-JUL-2017 511:06 428		
27-31-03	LEFT ELEVATOR TAB 505-43073-4001 0000699997 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-03	RIGHT ELEVATOR TAB 505-43073-4002 0000699992 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-31-03-001 (s)	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
27-31-03-002 (s)	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
27-36-03-001 (s)	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH PKG 12 REF: AMM 27-36-03	MOS HRS/MSC AFL	24 1200				PKG 20-JUN-2018 573:42 502		
27-41-01-001 (s)	DETAILED INSPECTION OF PITCH TRIM ACTUATOR PKG 50 REF: AMM 27-41-01	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		AIRWORTHINESS
27-41-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH PKG 50 REF: AMM 27-40-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		AIRWORTHINESS
27-41-01-003 (s)	LUBRICATION OF PITCH TRIM ACTUATOR PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-41-01-004 (s)	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK						PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-41-01	HRS/MSC	6000				0		
		AFL					0		
27-41-01-005 (s)	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				01-JUL-2016		
	REF: AMM 12-18-00	HRS/MSC					474:50		
		AFL					341		
27-41-01-006 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP						PKG		
	PKG 50	MOS					01-JUN-2012		
	REF: AMM 27-41-01	HRS/MSC	6000				0		
		AFL					0		
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL								
	PN	MOS		TSN:0			01-JUN-2012		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL								
		MOS					01-JUN-2012		
	REF: NDT PART 5 27-51-00	HRS/MSC	17500				0		17500
AIRWORTHINESS		AFL	14000				0		14000
27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS						PKG		
	PKG 83	MOS	48				01-JUL-2016		
	REF: AMM 12-21-00	HRS/MSC					474:50		
		AFL					341		
27-51-01-002 (s)	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR						PKG		
	PKG 50	MOS					01-JUN-2012		
	REF: AMM 27-51-01	HRS/MSC	6000				0		
AIRWORTHINESS		AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-002 (s)	DETAILED VISUAL INSPECTION LEFT NO. 2	OUTBOARD FLAP ACTUATOR					PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-002 (s)	DETAILED VISUAL INSPECTION LEFT NO. 3	OUTBOARD FLAP ACTUATOR					PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-002 (s)	DETAILED VISUAL INSPECTION RIGHT NO. 1	INBOARD FLAP ACTUATOR					PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-002 (s)	DETAILED VISUAL INSPECTION RIGHT NO. 2	OUTBOARD FLAP ACTUATOR					PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-002 (s)	DETAILED VISUAL INSPECTION RIGHT NO. 3	OUTBOARD FLAP ACTUATOR					PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-004 (s)	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER						PKG		
	PKG 50	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC 6000					0		
		AFL					0		
27-51-01-005 (s)	SERVICING OF FLAP ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				01-JUL-2016		
		HRS/MSC					474:50		
	REF: AMM 12-18-00	AFL					341		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-05	LEFT INBOARD FLAP 505-14401-4001 0000694043 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-51-05	LEFT OUTBOARD FLAP 505-39079-4001 0000705849 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-51-05	RIGHT INBOARD FLAP 505-14401-4002 0000699733 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-51-05	RIGHT OUTBOARD FLAP 505-39079-4002 0000699987 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-51-06-001 (s)	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-001 (s)	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-001 (s)	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-001 (s)	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-001 (s)	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-001 (s)	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48				PKG 01-JUL-2016 474:50 341		
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER 780501-9 1331 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL REF: NDT PART 6 27-64-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL REF: NDT PART 5 27-64-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL REF: NDT PART 7 27-64-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-65-00-001 (s)	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM PKG 50 REF: AMM 27-60-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
27-65-01-001 (s)	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU) PKG 50 REF: AMM 27-65-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR 456896-1001 045073 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR 456896-1001 045074 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR 456897-1001 045929 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR 456897-1001 051173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 28 FUEL									
28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS PKG 2 REF: AMM 28-11-00	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-11-05	LEFT WING WATER DRAIN VALVE L83A13-628 F36171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-11-05	RIGHT WING WATER DRAIN VALVE L83A13-628 F36182 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-11-07	LEFT WING DUMP VALVE V98A32-001 F31179 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-11-07	RIGHT WING DUMP VALVE V98A32-001 F31166 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 2 REF: AMM 28-12-01	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE L87-19-001P2 F12309 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE L87-19-001P2 F12313 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-12-03-001 (s)	OPERATIONAL CHECK LEFT PKG 50 REF: AMM 28-12-03	FLOAT VENT VALVE MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK RIGHT PKG 50 REF: AMM 28-12-03	FLOAT VENT VALVE MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
28-21-01	LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-01	RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 F31910 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 F31911 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 F22213 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 F22216 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-05	LEFT WING JET PUMP FEED LINE T99A19-602 F35117 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-05	RIGHT WING JET PUMP FEED LINE T99A19-602 F35122 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-07	LEFT 0.75 SHUTOFF VALVE B97-15-601 F27115 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-07	RIGHT 0.75 SHUTOFF VALVE B97-15-601 F27124 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-07-001 (s)	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM PKG 1 REF: AMM 28-21-07	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
AIRWORTHINESS									
28-21-07-001 (s)	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM PKG 1 REF: AMM 28-21-07	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR D97C00-644P2 C701290 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-08	LEFT WING 28 VDC SOV ACTUATOR D97C00-644P2 C701287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR D97C00-644P2 C701286 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-09	LEFT WING SCAVENGER JET PUMP T99A19-603 F40442 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-09	RIGHT WING SCAVENGER JET PUMP T99A19-603 F40444 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE B97H19-608P2 F32456 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-10-001 (s)	OPERATIONAL CHECK OF FUEL XFEED VALVE PKG 65 REF: AMM 28-21-10	MOS HRS/MSC AFL	12000				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 F35563 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 F35562 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-21-13	INSC ILLUM PANEL 441-42621-002 1093 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-23-01	REFUEL CONTROL PANEL 742388-1-2 742388IN00207 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P2 F34648 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P2 F42365 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-23-04-001 (s)	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER PKG 40 REF: AMM 28-23-05	MOS HRS/MSC AFL	3000	+30/-30			01-JUL-2016 474:50 341	3474 M 3504	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-23-07	LEFT HIGH LEVEL SENSOR 722860-2-0 0812 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2015 407:05 228		
28-23-07	RIGHT HIGH LEVEL SENSOR 722860-2-0 0342 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:30 TSN:393:48 TSN:207			13-NOV-2014 393:48 207		
28-23-09	FUEL PORT AND CAP K97-63-613 F32298 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 1 LEFT PROBE 765896-1-0 765896IN00323 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 1 RIGHT PROBE 765896-1-0 765896IN00319 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 2 LEFT PROBE 765873-1-0 765873IN00317 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 2 RIGHT PROBE 765873-1-0 765873IN00333 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 3 LEFT PROBE 765874-1-0 765874IN00362 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 3 RIGHT PROBE 765874-1-0 765874IN00315 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 4 LEFT PROBE 765875-1-0 765875IN00373 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-01	NO. 4 RIGHT PROBE 765875-1-0 765875IN00336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT 738742-1-4 738790IN00531 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-43-01	TEMPERATURE SENSOR 798840-1-0 02894 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-43-01-001 (s)	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR PKG 50 REF: AMM 28-43-01	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-45-01	LEFT PRESSURE SWITCH D98C07-611 0745 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
28-45-01	RIGHT PRESSURE SWITCH D98C07-611 0759 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 29 HYDRAULIC POWER									
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR 3032763-002 MX757787A REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX756199 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX753732 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
29-12-02-001 (s)	VISUAL CHECK OF MANIFOLD/ RESERVOIR PKG 2 REF: AMM 29-12-02	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
29-12-02-002 (s)	OPERATIONAL CHECK LEFT EDP CHECK VALVE PKG 53 REF: AMM 29-10-00	MOS HRS/MSC AFL	96 6000				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-02-002 (s)	OPERATIONAL CHECK RIGHT PKG 53 REF: AMM 29-10-00	EDP CHECK VALVE MOS HRS/MSC AFL		96 6000			PKG 01-JUN-2012 0 0		
29-15-03	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 11172-2 11172-0072 REF: See Workcard	25 CU.IN ACCUMULATOR MOS HRS/MSC AFL		O/C		TSN:1 TSN:0 TSN:0	13-JUL-2015 420 264		
29-15-03-001 (s)	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 11172-2 PKG 2 11172-0072 REF: AMM 12-13-00	25 CU.IN ACCUMULATOR MOS HRS/MSC AFL	12	+30d/-30d +30/-30			PKG 20-JUN-2018 573:42 502		
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE 3032428-001 AA324432 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-JUN-2012 0 0		
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE 3032428-001 AA324434 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	01-JUN-2012 0 0		
29-15-04-001 (s)	OPERATIONAL CHECK LEFT PKG 41 REF: AMM 29-15-04	ENGINE HYDRAULIC SHUT-OFF VALVE MOS HRS/MSC AFL	48 3000				PKG 01-JUL-2016 474:50 341		
29-15-04-001 (s)	OPERATIONAL CHECK RIGHT PKG 41 REF: AMM 29-15-04	ENGINE HYDRAULIC SHUT-OFF VALVE MOS HRS/MSC AFL	48 3000				PKG 01-JUL-2016 474:50 341		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-15-05	PRIORITY VALVE 2217-0001-401 00117 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
29-31-02-001 (s)	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE PKG 53 REF: AMM 29-31-02	MOS HRS/MSC AFL	96 6000				01-JUN-2012 0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
30-01-01	MD INSC ILLUM PANEL 441-43234-002 1110 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-00-001 (s)	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM PKG 50 REF: AMM 30-10-00	MOS HRS/MSC AFL	6000				01-JUN-2012 0 0		
30-12-01-001 (s)	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS PKG 50 REF: AMM 30-12-01	MOS HRS/MSC AFL	6000				01-JUN-2012 0 0		
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-3 0124 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-4 0013 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7881-1-483 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7881-1-366 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7881-1-489 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7881-1-401 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-05-002 (s)	FUNCTIONAL CHECK RIGHT PKG 50 REF: AMM 30-12-05	HORIZONTAL MOS HRS/MSC AFL	STABILIZER 6000	ANTI-ICING PRESSURE TRANSDUCER			PKG 01-JUN-2012 0 0		
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000209 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000217 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7917-7-82 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7858-4-149 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE PKG 50 REF: AMM 30-21-03	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
30-21-04-001 (s)	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS PKG 20 REF: AMM 30-21-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING PKG 81 REF: AMM 30-30-00	MOS HRS/MSC AFL	24				20-JUN-2018 573:42 502	20-JUN-2020	
30-41-01-001 (s)	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING PKG 2 REF: AMM 30-41-01	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-3 01359 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-3 01360 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
30-81-02	LEFT NOSE ICE DETECTOR 0871LM3-1 0475 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
31-30-02	CVDR ACCELEROMETER 3001-01-111 0212-DTK1311 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-30-03	REAR CVDR IMPACT SWITCH 5930-4-000 5477 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-31-00-002	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) PKG 80 REF: AMM 31-31-00	MOS HRS/MSC AFL	12				20-JUN-2018 573:42 502	20-JUN-2019	
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER 2100-3083-50 000802105 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON DK120/90 AT56728 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			04-JUL-2017 511:06 428		
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DK120/90 AT56728 REF: AMM 31-31-03	MOS HRS/MSC AFL	DUE				04-JUL-2017 511:06 428	01-DEC-2023 M	
31-31-09	CVDR CONTROL PANEL 441-42635-003 0394 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-33-01	FDR - FLIGHT DATA RECORDER 2100-2044-00 000836260 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2015 435:10 286		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-33-03	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON DK120-90 AT114774 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-2018 573:42 502		
31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED) DK120-90 AT114774 REF: AMM 31-33-03	MOS HRS/MSC AFL	DUE				20-JUN-2018 573:42 502	01-JUN-2025 M	
31-33-04	FORWARD CVDR IMPACT SWITCH 5930-4-000 5439 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-40-01	LH DCU UNIT 011-01457-00 16905555 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-40-01	RH DCU UNIT 011-01457-00 16905976 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			15-SEP-2018 599:36 515		
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-20 1HQ005015 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-20 1HQ005034 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL 441-42627-001 1098 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 50 REF: AMM 31-42-00	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46714413 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46714301 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46714636 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-00	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY 011-01440-10 18T006043 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000				PKG 01-JUN-2012 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000				PKG 01-JUN-2012 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-01	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 18T005986 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-01	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-1 18T006044 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-05	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 32 LANDING GEAR									
32-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	600				PKG 01-JUL-2016 474:50 341		
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING 2317-1201-503 1383333/001 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING 2317-1201-504 1408685/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-003	LEFT PINTLE PIN 2317-1101-003 1407341/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-003	RIGHT PINTLE PIN 2317-1101-003 1407341/010	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-004	LEFT PINTLE PIN 2317-1102-001 1398392/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-004	RIGHT PINTLE PIN 2317-1102-001 1398392/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1403839/009	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1403839/004	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1407912/003	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		15300
LIFE LIMIT	REF: See Workcard								
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1407912/002	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		15300
LIFE LIMIT	REF: See Workcard								
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1399754/006	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1399754/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1426611/006	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1426611/008	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-10-00	LEFT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
	REF: AMM 32-11-00								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00	RIGHT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-405 00102 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-406 00102 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-405 00104 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-406 00107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1399624/006 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		15300
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1403792/004 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		15300

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1399625/006	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1407917/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1401017/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1401017/004	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-104	LEFT MAIN LANDING GEAR TRAILING ARM PN SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM 2317-1513-502 1408683/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1513-501 1407544/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1407754/004	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard		16800						
32-11-00-001 (s)	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR PKG 2	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
REF: AMM 32-11-00									
32-11-00-002	RESTORATION (OVERHAUL) OF LEFT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	120 600	+30d/-30d			01-JUN-2012 0 0	01-JUN-2022	01-JUL-2022 12030
OVERHAUL	REF: AMM 32-11-00		12000	+30/-30				12000	
32-11-00-002	RESTORATION (OVERHAUL) OF RIGHT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	120 600	+30d/-30d			01-JUN-2012 0 0	01-JUN-2022	01-JUL-2022 12030
OVERHAUL	REF: AMM 32-11-00		12000	+30/-30				12000	
32-11-00-003 (s)	LUBRICATION OF MAIN LANDING GEAR PKG 2	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
REF: AMM 12-21-00									
32-11-03-004 (s)	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER PKG 2	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
REF: AMM 12-14-02									
32-20-01	NOSE LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: AMM 32-21-00									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00221 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00232 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1356932/004 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT									
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1402706/001 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT									
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1403813/002 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT									
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1407916/002 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT									
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1330689/003 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1405825/005	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1344412/009	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1409022/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-21-00-001 (s)	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR PKG 2	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
REF: AMM 32-21-00									
32-21-00-002	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			01-JUN-2012 0 0	01-JUN-2022	01-JUL-2022 12030
OVERHAUL	REF: AMM 32-21-00								
32-21-00-003 (s)	LUBRICATION OF NOSE LANDING GEAR PKG 2	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
REF: AMM 12-21-00									
32-21-02	NLG RETRACTION ACTUATOR 2117-1000-401 00114	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-03	NLG DOWNLOCK ACTUATOR 2117-2000-401 00119 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-21-05-004 (s)	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER PKG 2 REF: AMM 12-14-03	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
32-21-06-005 (s)	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER PKG 2 REF: AMM 32-21-06	MOS HRS/MSC AFL	12 600				PKG 20-JUN-2018 573:42 502		
32-23-03	NLG DOOR - TORQUE TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3000-409 00681 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-JUL-2015 420 264		
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3000-409 00691 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-JUL-2015 420 264		
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3034-501 1414787/003 REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			(EBT)		
LIFE LIMIT			12000						12006



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3034-501 1411931/002	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-302	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 1409030/007	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-302	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 1411828/005	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-303	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1399753/006	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-303	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1399753/008	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 68030/0003	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 68030/0010	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1386481/008	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1386481/006	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-306	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1400170/002	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-306	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1400170/005	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-307	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 1401016/009	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-307	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 1411563/010	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1409026/002	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1409026/010 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT									
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1411588/001 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT									
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1411588/003 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
LIFE LIMIT									
32-31-01	LANDING GEAR CONTROL LEVER 827101-7 1120 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE 7342-1 0137T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-31-05	LH MLG UPLOCK BOX ASSY 2617-1000-401 00209 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-31-05	NLG UPLOCK BOX ASSY 2617-1000-401 00213 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-31-05	RH MLG UPLOCK BOX ASSY 2617-1000-402 00083 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:429 TSN:297			20-JUN-2014 389:54 203		
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1399725/009 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1399725/003 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12006
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00138 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10506
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00125 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10506
+ 32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		28000
+ 32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		28000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-35-00-001 (s)	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM PKG 12	MOS	24				PKG 01-JUL-2016 474:50		
AIRWORTHINESS	REF: AMM 32-35-00	HRS/MSC AFL	1200				341		
32-35-00-002 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES PKG 12	MOS	24				PKG 20-JUN-2018 573:42		
AIRWORTHINESS	REF: AMM 32-35-00	HRS/MSC AFL	1200				502		
32-35-02	CENTER FUSELAGE FREE FALL VALVE 7343-2 0137T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-400	NOSE LANDING GEAR SHOCK STRUT 2317-5100-403 00082 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT 2310-1144-005 1379571/003 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
LIFE LIMIT									
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT 2310-1173-001 1387581/001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
LIFE LIMIT									
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 1388930/002 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 1388930/005	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING 2317-5301-503 1386495/001	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER 2117-4000-403 00181	MOS HRS/MSC AFL	11200	TSN:0			31-MAY-2013 230:53 119		11319
LIFE LIMIT	REF: See Workcard								
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE 2317-5101-001 1377661/002	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1387496/002	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1387496/005	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN 2317-6003-001 1368530/006	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE 2310-1165-001 1361189/004	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
LIFE LIMIT	REF: See Workcard		11200						
32-41-00	BRAKE CONTROL UNIT DAP00100-10 343350339	MOS HRS/MSC AFL	O/C				04-JUL-2017 511:06 428		
32-41-00-001 (s)	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM PKG 50	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
REF: AMM 32-41-00									
32-41-01	BRAKE CONTROL UNIT TRAY DAP00134-01 0122	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard									
32-41-02	LH BRAKE PEDAL TRANSDUCER Q3008 031230	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard									
32-41-02	RH BRAKE PEDAL TRANSDUCER Q3008 031961	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard									
32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 50	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
REF: AMM 32-41-02									



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 50 REF: AMM 32-41-02	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 20-JUN-2018 573:42 502		
32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 20-JUN-2018 573:42 502		
32-41-06	LH MLG WHEEL SPEED TRANSDUCER DAP00103-01 98KM REF: See Workcard	MOS HRS/MSC AFL	O/C				22-JUN-2012 13:30 8		
32-41-06	RH MLG WHEEL SPEED TRANSDUCER DAP00103-01 23KU REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
32-41-07	BRAKE CONTROL MODULE DAP00101-02 52JK REF: See Workcard	MOS HRS/MSC AFL	O/C				22-JUN-2012 13:30 8		
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN 57675-1 00382 REF: See Workcard	MOS HRS/MSC AFL	11200		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		11200

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT 2310-1183-001 1378186/006	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
LIFE LIMIT	REF: See Workcard	AFL	11200						11200
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK 2317-5191-001 1388988/004	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
LIFE LIMIT	REF: See Workcard	AFL	11200						11200
32-43-00-001 (s)	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM PKG 50	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
REF: See Workcard		AFL							
32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 20-JUN-2014 389:58 203		
REF: AMM 32-43-00		AFL							
32-43-02	PRESSURE SWITCH DAP00108-01 56KY	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard		AFL							
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR DAP00106-01 106	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard		AFL							
32-43-05	EMERGENCY/PARKING BRAKE VALVE DAP00107-01 6KV	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
REF: See Workcard		AFL							

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-06	PRESSURE TRANSDUCER DAP00109-01 7768-6-284 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-43-08	THERMAL RELIEF VALVE DAP00110-01 120 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE DAP00202-01 170 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE 2216-0001-401 00381 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-43-11-001 (s)	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE PKG 1 REF: AMM 32-43-11	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
AIRWORTHINESS									
32-45-00	LH MAIN WHEEL AND TIRE ASSY 505-19517-601 5107LD REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		
32-45-00	NOSE WHEEL AND TIRE ASSY 505-19601-401 5068KV REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-00	RH MAIN WHEEL AND TIRE ASSY 505-19517-611 5004NS REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			25-OCT-2017 525:26 445		
32-45-01	LEFT MAIN WHEEL DAP00098-02 5107LD REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		
32-45-01	RIGHT MAIN WHEEL 505-19517-611 5004NS REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			25-OCT-2017 525:26 445		
32-45-01-002	SPECIAL DETAIL INSPECTION LH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-601 5107LD REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				13-JUL-2015 420 264		
32-45-01-002	SPECIAL DETAIL INSPECTION RH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5004NS REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				25-OCT-2017 525:26 445		
+ 32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5107LD REF: AMM 32-45-00	MOS HRS/MSC AFL	1500	TSI:383			20-JUN-2018 573:42 502		1619
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5004NS REF: AMM 32-45-00	MOS HRS/MSC AFL	1500				25-OCT-2017 525:26 445		1945

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-02	LEFT MAIN WHEEL TIRE 258K63-2 72782709 REF: AMM 32-45-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-2018 573:42 502		
32-45-02	RIGHT MAIN WHEEL TIRE 256K63-2 71632825 REF: AMM 32-45-03	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			25-OCT-2017 525:26 445		
32-45-03	LH MLG HUB CAP DAP00131-02 111KY REF: AMM 32-45-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-45-03	RH MLG HUB CAP DAP00131-02 47KU REF: AMM 32-45-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-45-11	NOSE WHEEL DAP00099-01 5068KV REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2018 573:42 502		
32-45-11-002	SPECIAL DETAIL INSPECTION NOSE WHEEL AND TIRE ASSY (NDT) OF NOSE LANDING GEAR WHEEL ASSEMBLY 505-19601-401 5068KV REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				06-JUN-2013 230:53 119		
+ 32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY DAP00099-01 5068KV REF: AMM 32-45-00	MOS HRS/MSC AFL	1500	TSI:383			20-JUN-2018 573:42 502		1619



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-12	NOSE TIRE 156K23B1 52532747 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-2018 573:42 502		
32-45-21	LH MLG CARBON BRAKE ASSY DAP00097-03 5014KK REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			20-JUN-2014 389:54 203		
32-45-21	RH MLG CARBON BRAKE ASSY DAP00097-04 5015KE REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			01-JUL-2016 474:50 341		
32-500	NOSE LANDING GEAR SHOCK ABSORBER 2317-5170-403 00088 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK 2317-5227-501 1379565/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING 2317-5113-005 1371006/004 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER 2317-5231-503 1378111/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-600	NOSE LANDING GEAR DRAG BRACE 2317-6000-403 00107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-601	NOSE LANDING GEAR UPPER DRAG BRACE 2317-6101-501 1409059/001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
32-602	NOSE LANDING GEAR LOWER DRAG BRACE 2317-6200-403 1320521-001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:471 TSN:426			20-JUN-2014 389:54 203	10977	
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1399721/001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1399721/009 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
32-604	NOSE LANDING GEAR DRAG BRACE PIN 2317-6003-001 1400161/009 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0	11200	
32-61-01	LH WING PROXIMITY SWITCH 80-057-01 29378 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH 80-057-01 29385 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 29203 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH 80-057-01 29380 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 2 NLG PROXIMITY SWITCH 80-057-01 29365 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-61-01	RH WING PROXIMITY SWITCH 80-057-01 29554 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-700	NOSE LANDING GEAR LOCKING STAY 2317-6500-403 00108 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
32-701	NOSE LANDING GEAR UPPER LOCKING STAY 2317-6521-003 1399685/007 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
32-702	NOSE LANDING GEAR LOWER LOCKING STAY 2317-6531-001 1423416/001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1411589/001 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1411589/008 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		11200

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32CUS01	L/H MLG ELECTRICAL WOW/WS HARNESS 2317-1146-401 0010671207 REF:	MOS HRS/MSC - AFL		TSN:0 TSN:0 TSN:0			30-MAR-2016 453:58 310		
32CUS02	L/H MLG ELECTRICAL WOW HARNESS 2317-1145-401 C012088286 REF:	MOS HRS/MSC - AFL		TSN:0 TSN:0 TSN:0			30-MAR-2016 453:58 310		
CHAPTER 33	LIGHTS								
33-01-01	OVERHEAD LIGHTS CONTROL PANEL 441-43246-002 1120 REF: See Workcard	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-12-01	COCKPIT DIMMER 81-01760-002 0481 REF: See Workcard	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-12-02	INSC ILLUM - TEST PANEL 441-42631-003 1064 REF: See Workcard	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-31-02	NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-42-01	LH LWR FWD TAXI LIGHT ASSY 81017-3 000164 REF: See Workcard	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-42-01	RH LWR FWD TAXI LIGHT ASSY 81017-4 000166 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-47-01	LEFT LANDING LIGHT ASSY 81017-5 000167 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-47-01	RIGHT LANDING LIGHT ASSY 81017-6 000163 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-48-00	LEFT NO. 1 NAVIGATION LIGHT 84075-1 000230 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			30-DEC-2015 449:18 305		
33-48-00	LEFT NO. 2 NAVIGATION LIGHT 84015-1 000177 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000288 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT 84015-2 000182 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00-001 (s)	DISCARD LEFT NO. 1 NAVIGATION LIGHT 84075-1 PKG 65 000230 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000				PKG 30-DEC-2015 449:18 305		
33-48-00-001 (s)	DISCARD LEFT NO. 2 NAVIGATION LIGHT 84015-1 PKG 65 000177 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000				PKG 01-JUN-2012 0 0		
33-48-00-001 (s)	DISCARD RIGHT NO. 1 NAVIGATION LIGHT 84004-7 PKG 65 000288 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000				PKG 01-JUN-2012 0 0		
33-48-00-001 (s)	DISCARD RIGHT NO. 2 NAVIGATION LIGHT 84015-2 PKG 65 000182 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000				PKG 01-JUN-2012 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 2 PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
33-49-00	NO. 1 STROBE LIGHT 84036-3 000164 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-49-00	NO. 2 STROBE LIGHT 84036-4 000174 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-49-00-001 (s)	DISCARD NO. 1 STROBE LIGHT 84036-3 PKG 60 000164 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800				PKG 01-JUN-2012 0 0		
33-49-00-001 (s)	DISCARD NO. 2 STROBE LIGHT 84036-4 PKG 60 000174 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800				PKG 01-JUN-2012 0 0		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800				PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-01	LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 000844 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-JUL-2015 420 264		
33-52-01	RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 000833 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-JUL-2015 420 264		
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 000844 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d		11	20-JUN-2018 573:42 502	01-JUL-2019	31-JUL-2019
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 000833 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d		11	20-JUN-2018 573:42 502	01-JUL-2019	31-JUL-2019
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 000844 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 000833 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 000844 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 000833 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-05	SELF-ILLUMINATED UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
33-52-17-001	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED) REF: AMM 33-52-17	MOS HRS/MSC AFL	N/A				20-JUN-2014 389:58 203		
CHAPTER 34 NAVIGATION									
34-00-01	ACSS TRANSPONDER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-00-02	TRANSPONDER RF RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-00-03	NO.1 IASP SMART PROBE 2015L-4B 0611 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2015 420 264		
34-00-03	NO.2 IASP SMART PROBE 2015L-4B 0240 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2015 420 264		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00-04	SD CARD DATABASE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-10-01	RADIO ALTIMETER 066-01153-0101 KRA405B-11993 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA S67-2002-45 553-4537 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA S67-2002-45 553-4539 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT C16786DA01 C16786002776 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-11-00-001	FUNCTIONAL CHECK IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) C16786DA01 C16786002776 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				20-JUN-2018 573:42 502	20-JUN-2020	
34-11-02	PITOT/STATIC PROBE 0856UT4 272760 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)								
	0856UT4	MOS	24	+30d/-30d			20-JUN-2018	01-JUL-2020	31-JUL-2020
	272760	HRS/MSC			11		573:42		
	REF: AMM 34-11-02	AFL					502		
34-15-00-001 (s)	FUNCTIONAL CHECK OF AIR DATA SYSTEM						PKG		
	PKG 81	MOS	24				20-JUN-2018		
	REF: AMM 34-15-00	HRS/MSC					573:42		
		AFL					502		
34-15-00-002 (s)	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS						PKG		
	PKG 81	MOS	24				20-JUN-2018		
	REF: AMM 34-15-00	HRS/MSC					573:42		
		AFL					502		
34-15-00-003	DETAILED INSPECTION OF IASP								
	PKG 81	MOS	24				20-JUN-2018	20-JUN-2020	
	REF: AMM 34-15-07	HRS/MSC					573:42		
		AFL					502		
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM								
	011-00868-10	MOS		TSN:0			01-JUN-2012		
	42018416	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM								
	011-00868-10	MOS		TSN:0			01-JUN-2012		
	42018419	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
34-20-02	LEFT MAGNETOMETER								
	011-00870-00	MOS		TSN:0			01-JUN-2012		
	1CM006599	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-20-02	RIGHT MAGNETOMETER 011-00870-00 1CM007193 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-23-00	MAGNETIC COMPASS KCA0120W BC2121108 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-NOV-2012 107:58 52		
34-23-00-001	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS KCA0120W BC2121108 REF: AMM 34-23-00	MOS HRS/MSC AFL	24				20-JUN-2018 573:42 502	20-JUN-2020	
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA S65-247170 173-2994 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE S65-247170 173-2974 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER 011-00987-00 47765138 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 9503 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 9501 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA 011-00883-20 47203745 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:6 TSO:0 TSO:0			20-JUN-2014 390 203		
34-40-04	TCAS II UNIT 9003500-55905 TSE01247 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-40-05	TCAS II TOP ANTENNA 7514060-902 ANE38528 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-43-02	LOWER TCAS L BAND ANTENNA S65-5366-7L 261-106522 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA S65-5366-7L 261-106498 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-02	TOP XPDR L BAND ANTENNA S65-5366-7L 261-106513 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-03	KN 63 DISTANCE MEASURING UNIT 066-01070-0001 35320 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-05	PHASING COUPLER SSPD-113-10 7005 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-06	MARKER BEACON ANTENNA S35-1000-2 102-9455 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-07	MARKER BEACON ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-08	VOR/LOC/GS ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-09	VOR/LOC/GS ANTENNA RF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-10	GSR 56 IRIDIUM UNIT 011-02268-00 1NZ005178 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-11	IRIDIUM SATCOM ANTENNA S67-1575-109 11605 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT 011-01746-00 1EJ005129 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-13	WI-FI - DATALINK ANTENNA S65-5366-71S 258-2610 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-14	ADF ANTENNA 622-7383-001 3Y8CG REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-50-15	ADF UNIT 622-7382-101 3WL6T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-104227 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-52-00	NO. 1 TRANSPONDER 7510700-951 RCE01183 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-00	NO. 2 TRANSPONDER 7510700-951 RCE01117 REF: See Workcard	MOS HRS/MSC AFL	O/C				12-AUG-2014 391:14 205		
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM 7510700-951 RCE01183 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				13-JUN-2018	13-JUN-2020	
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM 7510700-951 RCE01117 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				13-JUN-2018	13-JUN-2020	
34-52-04	LOWER COAXIAL UNIT D2-729B005 573152 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-52-04	UPPER COAXIAL UNIT D2-729B005 573144 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-53-01	ADF MOUNTING TRAY 622-5212-001 45HTY REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL 011-01428-00 194005235 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34RVSMGMU	CHECK RVSM GMU	MOS	24				19-JUL-2017	19-JUL-2019	
CUSTOMER CODE	REF:	HRS/MSC AFL							
CHAPTER 35 OXYGEN									
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	MOS	36				20-JUN-2018	01-JUN-2021	
AIRWORTHINESS	REF: AMM 35-00-00	HRS/MSC AFL	1800		-19		573:42 502	2373:42	
35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION	MOS	60				PKG 04-JUL-2017		
	PKG 84	HRS/MSC AFL					511:06 428		
	REF: AMM 35-01-02								
35-01-02	OXYGEN CYLINDER TRANSDUCER	MOS		TSN:0			01-JUN-2012		
	4441125-000	HRS/MSC	O/C	TSN:0			0		
	7702-2-48	AFL		TSN:0			0		
	REF: See Workcard								
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH	MOS		TSN:0			01-JUN-2012		
	P24151	HRS/MSC	O/C	TSN:0			0		
	0134	AFL		TSN:0			0		
	REF: See Workcard								
35-01-06	OXYGEN SYSTEM CONTROL PANEL	MOS		TSN:0			01-JUN-2012		
	441-40945-002	HRS/MSC	O/C	TSN:0			0		
	0367	AFL		TSN:0			0		
	REF: See Workcard								
35-01-07	COCKPIT SENSOR	MOS		TSN:0			01-JUN-2012		
	P24099	HRS/MSC	O/C	TSN:0			0		
	0115	AFL		TSN:0			0		
	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-08	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
35-01-09	ALTITUDE COMPENSATING REGULATOR 4421135-001 00282 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
35-01-10	LOW PRESSURE OXYGEN VALVE 4421132-109 00389 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
35-02-01	OXYGEN CYLINDER 4441122-050 405770203 REF: See Workcard	MOS HRS/MSC AFL	C/C	TSN:87 TSO:1 TSO:0 TSO:0			04-JUL-2017 511:06 428		
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER ASSEMBLY 4441122-050 405770203 REF: AMM 35-02-01	MOS HRS/MSC AFL	60				26-MAY-2017	26-MAY-2022	
35-02-01-003	DISCARD OF OXYGEN CYLINDER 4441122-050 405770203 REF: AMM 35-02-01	MOS HRS/MSC AFL	180				01-APR-2010	01-APR-2025	
LIFE LIMIT									
35-02-05	OXYGEN PRESSURE REGULATOR 172421-14 0265 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JUL-2017 511:06 428		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX	MOS	12				20-JUN-2018	20-JUN-2019	
AIRWORTHINESS	REF: AMM 35-11-02	HRS/MSC	600				573:42	1173:42	
		AFL					502		
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX	MOS		TSN:0			01-JUN-2012		
	1186F6-23	HRS/MSC	O/C	TSN:0			0		
	00818	AFL		TSN:0			0		
	REF: See Workcard								
35-11-01	PILOT OXYGEN MASK STOWAGE BOX	MOS		TSN:0			01-JUN-2012		
	1186F6-23	HRS/MSC	O/C	TSN:0			0		
	00792	AFL		TSN:0			0		
	REF: See Workcard								
35-11-02	LEFT CREW OXYGEN MASK	MOS		TSO:38			10-DEC-2018		
	174232-93	HRS/MSC	O/C	TSO:159:25			607:48		
	28991	AFL		TSO:220			524		
	REF: See Workcard								
35-11-02	RIGHT CREW OXYGEN MASK	MOS		TSO:1			04-JUL-2017		
	174232-93	HRS/MSC	O/C	TSO:0			511:06		
	32130	AFL		TSO:0			428		
	REF: See Workcard								
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK	MOS	36				10-DEC-2018	10-DEC-2021	
	174232-93	HRS/MSC	1800				607:48	2407:48	
	28991	AFL					524		
	REF: AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK	MOS	36	TSI:1	12		04-JUL-2017	16-JUN-2020	
	174232-93	HRS/MSC	1800				511:06	2311:06	
	32130	AFL		TSI:0			428		
	REF: AMM 35-11-02								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK 174232-93 28991 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30	TSl:2	-15	21-DEC-2015 448:23 304	06-OCT-2021 4048:23	05-NOV-2021 4078:23
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK 174232-93 32130 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30	TSl:1 TSl:0	12	04-JUL-2017 511:06 428	16-JUN-2023 4111:06	16-JUL-2023 4141:06
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 28991 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A						
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 32130 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A						
35-11-04-001	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	N/A				PKG 13-JUL-2015 420 264		
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE AIRWORTHINESS REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800			-19	20-JUN-2018 573:42 502	01-JUN-2021 2373:42	
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE AIRWORTHINESS REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800			-19	20-JUN-2018 573:42 502	01-JUN-2021 2373:42	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER 4411071-112 4411071-012-00446 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			13-JUL-2015 420 264		
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-002 4411072-002-00217 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-012 4411072-002-00848 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0	6		13-JUL-2015 420 264		
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-012 4411072-012-00018 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-012 4411072-012-00905 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-JUL-2015 420 264		
35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS PKG 82 REF: AMM 35-21-01	MOS HRS/MSC AFL	36	+1m/-1m			PKG 20-JUN-2018 573:42 502		
35-21-01-002	DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY AND SUPPORT REF: AMM 35-21-01	MOS HRS/MSC AFL	N/A				01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-31-01	PBE - PROTECTIVE BREATHING EQUIPMENT MR-10022NEMB E1103682	MOS HRS/MSC AFL	126	+30d/-30d	TSN:0 TSN:0 TSN:0		01-JAN-2012	13-JUN-2022 M	13-JUL-2022
DISCARD	REF: See Workcard								
CHAPTER 36 PNEUMATIC									
36-01-01	PNEUMATIC INSC ILLUM PANEL 441-42633-002 1120	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
	REF: See Workcard								
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-3 0295	MOS HRS/MSC AFL	O/C		TSR:3 TSN:299 TSR:0 TSN:285 TSR:0		02-JUN-2016 469:43 336		
	REF: See Workcard								
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-4 0133	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
	REF: See Workcard								
36-11-01-001 (s)	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER PKG 50	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
	REF: AMM 36-11-01								
36-11-01-002 (s)	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION PKG 1	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
	REF: AMM 36-11-00								
36-11-02-001	DETAILED INSPECTION OF BLEED LINE WATER DRAINS	MOS HRS/MSC AFL	N/A				20-JUN-2014 389:58 203		
	REF: AMM 36-11-02								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-03	AMS CONTROLLER SYLZ-53632-203 0173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-04	NO. 1 ENGINE FAN AIR VALVE RYLB-53527-1 0253 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-04	NO. 2 ENGINE FAN AIR VALVE RYLB-53527-1 0254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-04-001 (s)	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER PKG 50 REF: AMM 36-11-04	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-11-05	LH INCONEL 625 BLEED PRE-COOLER 10965000-105 T0116 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-05	RH INCONEL 625 BLEED PRE-COOLER 10964000-105 T0090 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-06	CROSS BLEED VALVE RYLB-53506-1 0104 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-06-001 (s)	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-06	MOS HRS/MSC AFL	600				PKG 20-JUN-2014 389:58 203		
36-11-06-002 (s)	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER PKG 50 REF: AMM 36-11-06	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7960-7-107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7960-7-110 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 28237 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 28241 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 28243 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 28245 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
36-21-01-001 (s)	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS PKG 50 REF: AMM 36-21-01	MOS HRS/MSC AFL	6000				PKG 01-JUN-2012 0 0		
AIRWORTHINESS									
CHAPTER 38	WATER/WASTE								
38-33-00	TOILET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-33-07	WASTE DRAIN VALVE 0218-0032-1 160670 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 44	CABIN SYSTEMS								
44-12-07	3-CHANNEL AUDIO AMPLIFIER 0700-005 11090235 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-03	DC-DC CONVERTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-09	IFE INSC ILLUM PANEL 441-42725-001 0185 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-11	XM RECEIVER 0500-200 11110158 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-13	XM HEAD CONTROL 0500-300 1105P037 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-15	AUDIO VOLUME CONTROLLER 0700-008 1105M044 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-21-17	IR RECEIVER WITH CONNECTOR 0500-018 1104P040 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-19	IR REMOTE CONTOLLER 0500-015 1106P022 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-21	WIRELESS AUDIO TRANSMITTER 0700-009 11110024 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-23	NO. 1 WIRELESS HEADPHONE 0500-100 11120279 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-21-25	HEADPHONE DISTRIBUTION AMPLIFER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER 0604-001 1005W004 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-DEC-2013 362:44 192		
44-22-03	10.4 INCH FOLD DOWN MONITOR- 1043-301 11090183 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-32-01	ATG5000 TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-32-03	AIRCELL CONFIGURATION MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
442127-0101	LH NO. 1 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
442127-0102	RH NO. 2 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
442127-0103	LH NO. 3 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
442127-0104	RH NO. 4 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
442127-0105	LH NO. 5 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
442127-0106	RH NO. 6 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 52 DOORS									
52-00-00	KEY LOCK KIT 505-38956-901 551478 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2014 391:14 205		
52-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
52-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
52-10-20-001 (s)	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL						PKG		
	PKG 12	MOS	24				20-JUN-2018		
	REF: AMM 52-10-20	HRS/MSC AFL	1200				573:42 502		
52-11-00-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM						PKG		
	PKG 41	MOS	48				01-JUL-2016		
	REF: AMM 52-11-00	HRS/MSC AFL	3000				474:50 341		
52-11-00-003 (s)	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH						PKG		
	PKG 2	MOS	12	+30d/-30d			20-JUN-2018		
	REF: AMM 52-11-23	HRS/MSC AFL	600				573:42 502		
52-13-22	MAIN DOOR BALANCING MECHANISM								
	PN	MOS			TSN:0		01-JUN-2012		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE								
	PN	MOS					01-JUN-2012		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 52-13-22	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-00	EMERGENCY DOOR 500-09700-437 0000710541 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
52-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR STRUCTURE PKG 90 REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 01-JUL-2016 474:50 341		
52-20-01-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE PKG 90 REF: See Workcard	MOS HRS/MSC AFL	60	+30d/-30d			PKG 01-JUL-2016 474:50 341		
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
52-20-20-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM PKG 41 REF: AMM 52-20-20	MOS HRS/MSC AFL	48 3000				PKG 01-JUL-2016 474:50 341		
52-20-21-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR RUBBER SEAL PKG 12 REF: AMM 52-20-21	MOS HRS/MSC AFL	24 1200				PKG 20-JUN-2018 573:42 502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM PKG 41 REF: AMM 52-31-20	MOS HRS/MSC AFL	48 3000				PKG 01-JUL-2016 474:50 341		
52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM PKG 41 REF: AMM 52-32-20	MOS HRS/MSC AFL	48 3000				PKG 01-JUL-2016 474:50 341		
52-71-20	LOWER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
52-71-20	UPPER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
CHAPTER 53 FUSELAGE									
53-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS PKG 1 REF: AMM 53-00-20	MOS HRS/MSC AFL	600				PKG 01-JUL-2016 474:50 341		
53-05-00-001 (s)	DETAILED INSPECTION OF FUSELAGE DRAINS PKG 84 REF: AMM 53-05-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 01-JUL-2016 474:50 341		
53-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 87	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
53-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0		14000
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0		14000
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0		14000
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0		14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-10-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD PKG 90								
	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120 +30d/-30d				PKG 01-JUN-2012 0 0		
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 84	MOS	60	+30d/-30d			01-JUL-2016 474:50	01-JUN-2022 M	01-JUL-2022
	REF: NDT PART 5 53-10-00	HRS/MSC AFL					341		
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WHEEL STRUCTURE. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WHEEL STRUCTURE.	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
53-14-00	NOSE RADOME 5190-102-1 417	MOS					22-MAR-2014		
	REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			384 201		
53-20-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0		
	REF: NDT PART 5 53-20-00	AFL					0		
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0		14000
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0		14000
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0		14000
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0		14000
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0		14000



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE						PKG		
	PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-05-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE						PKG		
	PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
		HRS/MSC					0		
	REF: NDT PART 5 53-20-00	AFL					0		
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					01-JUN-2012		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					01-JUN-2012		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					01-JUN-2012		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL								
		MOS					01-JUN-2012		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					01-JUN-2012		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
	REF: NDT PART 5 53-20-00								
53-20-06-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341		
	REF: NDT PART 5 53-20-00								
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-20-00								
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	MOS HRS/MSC AFL	8750 7000				01-JUN-2012 0 0		8750 7000
AIRWORTHINESS	REF: NDT PART 5 53-20-00								
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-20-00								
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-20-00								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE PKG 90	MOS	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
	REF: GENERIC NO REF	HRS/MSC AFL							
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-10-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL							
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE						PKG		
	PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				01-JUN-2012 0 0		
REF: NDT PART 5 53-30-00									
53-30-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES						PKG		
	PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				01-JUN-2012 0 0		
REF: NDT PART 5 53-30-00									
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL						PKG		
	PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				01-JUN-2012 0 0		
REF: NDT PART 5 53-30-00									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	12500 10000				01-JUN-2012 0 0	12500 10000	
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
53-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES						PKG		
	PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	10000 8000				0 0		10000 8000
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	12500 10000				0 0		12500 10000
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-07-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL	MOS					01-JUN-2012 0	17500	
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL	MOS					01-JUN-2012 0	17500	
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 87	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-08-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
CHAPTER 54		NACELLES/PYLONS							



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-00-00-001 (s)	GENERAL VISUAL INSPECTION OF PKG 1 REF: AMM 54-51-20	OF PYLON POLYURETHANE FILMS MOS HRS/MSC AFL	600				PKG 01-JUL-2016 474:50 341		
54-50-00-001 (s)	INTERNAL DETAILED INSPECTION PKG 90 REF: NDT PART 5 54-50-00	OF PYLON BEAMS - INTERNAL TO FUSELAGE MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
54-50-00-002 (s)	INTERNAL DETAILED INSPECTION PKG 90 REF: See Workcard	OF PYLON MAIN BOX MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
54-50-01-01-901	GENERAL VISUAL INSPECTION REF: NDT PART 5 54-50-00	OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
54-50-02-01-901	GENERAL VISUAL INSPECTION REF: NDT PART 5 54-50-00	OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
54-50-03-001 (s)	EXTERNAL - DETAILED INSPECTION PKG 84 REF: NDT PART 5 54-52-00	OF PYLON MAIN BOX AND LEADING EDGE. MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
54-50-03-01-901	GENERAL VISUAL INSPECTION REF: NDT PART 5 54-52-00	OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 54-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 54-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES						PKG		
	PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 54-55-00	HRS/MSC AFL					0 0		
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	

CHAPTER 55 STABILIZERS

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-001 (s)	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS PKG 1 REF: AMM 55-00-20	MOS HRS/MSC AFL	600				PKG 01-JUL-2016 474:50 341		
55-10-00	HORIZONTAL STABILIZER (COMPLETION) 505-10700-413 0000705630 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
55-10-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 01-JUN-2012 0 0		
55-10-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		
55-10-03-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 84	MOS	60	+30d/-30d			01-JUL-2016		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					474:50 341		01-JUN-2022 M 01-JUL-2022
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-05-001 (s)	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 55-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-10-08-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022	
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-10-09-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TRIM-TAB FITTINGS PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
	REF: See Workcard	HRS/MSC AFL					0 0		
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 8 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-04-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF PKG 87 REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
55-20-04-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS PKG 90 REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
55-22-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB PKG 87 REF: NDT PART 5 55-22-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
55-30-00	VERTICAL STABILIZER 505-10100-413 0000703031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
55-30-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022	
55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			04-JUL-2017		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					511:06 428		
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
55-30-03-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS								
	PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
AIRWORTHINESS									
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
AIRWORTHINESS									
55-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022	
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
AIRWORTHINESS									
55-30-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING	MOS	120	+30d/-30d			01-JUN-2012		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX	MOS	120	+30d/-30d			01-JUN-2012		
	PKG 87	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-40-00								
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS PKG 87	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0 0		
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0		14000
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0		14000
55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY PKG 87	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0 0		
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL	MOS					01-JUN-2012 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0		14000
55-42-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB PKG 90	MOS	120	+30d/-30d			PKG 01-JUN-2012 0 0		
	REF: NDT PART 5 55-42-00	HRS/MSC AFL					0 0		
CHAPTER 56	WINDOWS								
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH)								
	NP-195301-3	MOS					01-JUN-2012		
	11325H8644	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
					TSN:0				
					TSN:0				
					TSN:0				

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-4 11320H8095 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF SIDE WINDOW PKG 84 REF: NDT PART 5 56-12-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS REF: AMM 56-10-00	MOS HRS/MSC AFL	1200	+30/-30			13-JUL-2015 420 264	1620	1650
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 56-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
56-12-00	LEFT ACRYLIC SIDE WINDOW NP-195302-3 11244H9775 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
56-12-00	RIGHT ACRYLIC SIDE WINDOW NP-195302-4 11307H6616 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
56-20-00	NO. 1 WINDOW TRANSPARENCY 14024 1670384 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
56-20-00	NO. 10 WINDOW TRANSPARENCY 14024 1670405 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
56-20-00	NO. 11 WINDOW TRANSPARENCY 14024 1670406 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		
56-20-00	NO. 2 WINDOW TRANSPARENCY 14024 1670385 REF: See Workcard	MOS HRS/MSC AFL		O/C	TSN:0 TSN:0 TSN:0		01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 3 WINDOW TRANSPARENCY 14024 1670390 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 4 WINDOW TRANSPARENCY 14024 1670391 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 5 WINDOW TRANSPARENCY 14024 1670392 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 6 WINDOW TRANSPARENCY 14024 1670393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 7 WINDOW TRANSPARENCY 14024 1670394 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 8 WINDOW TRANSPARENCY 14024 1670402 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
56-20-00	NO. 9 WINDOW TRANSPARENCY 14024 1670404 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PASSENGER WINDOW PANELS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
REF: NDT PART 5 56-20-00									
CHAPTER 57 WINGS									
57-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600				PKG 01-JUL-2016 474:50 341		
REF: AMM 57-35-21									
57-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
REF: NDT PART 5 57-10-00									
57-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
REF: NDT PART 5 57-10-00									
57-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
REF: See Workcard									
57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL	MOS HRS/MSC AFL	17500				01-JUN-2012 0	17500	
AIRWORTHINESS	REF: NDT PART 5 57-10-00	AFL	14000				0	14000	
57-10-02-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
REF: NDT PART 5 57-10-00									

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-10-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				PKG 01-JUN-2012 0 0		
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-10-04-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR PKG 84	MOS HRS/MSC AFL	60 +30d/-30d				01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022	
AIRWORTHINESS	REF: NDT PART 5 57-20-00								
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87	MOS HRS/MSC AFL	120 +30d/-30d				PKG 01-JUN-2012 0 0		
AIRWORTHINESS	REF: NDT PART 5 57-10-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84	MOS	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-11-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE PKG 84	MOS	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022	M 01-JUL-2022
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	12500 10000				01-JUN-2012 0 0	12500 10000	
57-50-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS								
	PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022	
AIRWORTHINESS	REF: NDT PART 5 57-50-00								
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	11250 9000				01-JUN-2012 0 0	11250 9000	
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK						PKG		
	PKG 84	MOS	60	+30d/-30d			04-JUL-2017		
	REF: NDT PART 5 57-20-00	HRS/MSC AFL					511:06 428		
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP						PKG		
	PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 57-52-00	HRS/MSC AFL					0 0		
57-52-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP						PKG		
	PKG 84	MOS	60	+30d/-30d			04-JUL-2017		
	REF: NDT PART 5 57-52-00	HRS/MSC AFL					511:06 428		
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-52-00	HRS/MSC AFL	11250 9000				0 0	11250 9000	
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-53-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP	MOS					PKG		
	PKG 90	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 57-53-00	HRS/MSC AFL					0 0		
57-53-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP	MOS					PKG		
	PKG 84	MOS	60	+30d/-30d			04-JUL-2017		
	REF: NDT PART 5 57-53-00	HRS/MSC AFL					511:06 428		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 6 57-53-00	MOS HRS/MSC AFL	11250 9000				01-JUN-2012 0 0	11250 9000	
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500 14000				01-JUN-2012 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 6 57-53-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-60-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON PKG 87	MOS	120	+30d/-30d			01-JUN-2012		
	REF: NDT PART 5 57-60-00	HRS/MSC AFL					0 0		
57-60-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON TAB PKG 84	MOS	60	+30d/-30d			01-JUL-2016	01-JUN-2022 M	01-JUL-2022
	REF: NDT PART 5 57-60-00	HRS/MSC AFL					474:50 341		
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-70-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS	MOS	60	+30d/-30d			01-JUL-2016	01-JUN-2022	M 01-JUL-2022
	PKG 84	HRS/MSC AFL					474:50 341		
	REF: NDT PART 5 57-70-00								

CHAPTER 70 STANDARD PRACTICES - ENGINES

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01

700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION	MOS					24-FEB-2012		
		HRS/MSC ENC	A/R				0 0		
	REF: MM 70-00-00								

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01

700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION	MOS					21-MAR-2012		
		HRS/MSC ENC	A/R				0 0		
	REF: MM 70-00-00								

CHAPTER 71 POWER PLANT

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL PKG 50 REF: AMM 71-11-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 01-JUN-2012 0 0		
71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0394 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0726 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0727 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0428 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0695 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0700 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 71-20-00	HRS/MSC AFL	6000 6000				0 0	6000 6000	
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL	MOS					01-JUN-2012		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	3600				0 0	3600	
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY	MOS					01-JUN-2012		
AIRWORTHINESS	REF: AMM 71-20-00	HRS/MSC AFL	6000 6000				0 0	6000 6000	
71-31-00-001 (s)	DETAILED INSPECTION OF PYLON FIREWALL SEAL						PKG		
	PKG 20	MOS					01-JUN-2012		
	REF: AMM 71-31-00	HRS/MSC AFL	1800				0 0		
71-60-01	LEFT ENGINE AIR INLET								
	505-43420-403	MOS		TSN:0			01-JUL-2016		
	CP1277	HRS/MSC	O/C	TSN:0			474:50		
	REF: See Workcard	AFL		TSN:0			341		
71-60-01	RIGHT ENGINE AIR INLET								
	505-43420-403	MOS		TSN:0			01-JUL-2016		
	CP1275	HRS/MSC	O/C	TSN:0			474:50		
	REF: See Workcard	AFL		TSN:0			341		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE 3072913-01 PCE-DG0202 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71.EN1									
71EN2	NO. 2 ENGINE 3072913-01 PCE-DG0209 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71.EN2									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01									
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS HRS/MSC ENC	A/R					24-FEB-2012 0 0	
	REF: MM 70-00-00								
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH	MOS HRS/MSC ENC	12					20-JUN-2018 573:42 502	20-JUN-2019
	REF: MM 71-00-00								
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS HRS/MSC ENC	A/R					24-FEB-2012 0 0	
	REF: MM 71-00-00								
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS HRS/MSC ENC	12 630					20-JUN-2018 573:42 502	20-JUN-2019 (1203:42) 1203:42
	REF: MM 71-00-00								
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS HRS/MSC ENC	12 630					20-JUN-2018 573:42 502	20-JUN-2019 (1203:42) 1203:42
	REF: MM 72-00-02								

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS					21-MAR-2012		
	REF: MM 70-00-00	HRS/MSC	A/R				0		
		ENC					0		
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH	MOS	12				20-JUN-2018	20-JUN-2019	
	REF: MM 71-00-00	HRS/MSC					573:42		
		ENC					502		
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS					21-MAR-2012		
	REF: MM 71-00-00	HRS/MSC	A/R				0		
		ENC					0		
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12				20-JUN-2018	20-JUN-2019	
	REF: MM 71-00-00	HRS/MSC	630				573:42	(1203:42) 1203:42	
		ENC					502		
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				20-JUN-2018	20-JUN-2019	
	REF: MM 72-00-02	HRS/MSC	630				573:42	(1203:42) 1203:42	
		ENC					502		

CHAPTER 72		ENGINE	
ENGINE NO. 1	Model : PW535E	Serial # PCE-DG0202	Part # 3072913-01
72-00-00-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA		PKG
	PKG 1	MOS	12 +30d
		HRS/MSC	600 +10%
	REF: MM 72-00-00	ENC	
			502
72-00-00-212-802 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB		PKG
	PKG 1	MOS	12 +30d
		HRS/MSC	600 +10%
	REF: MM 72-00-00	ENC	
			502

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-804 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-805 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-806 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-807 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-808 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-809 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	MOS					24-FEB-2012		
	REF: MM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-280-818 (s)	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS	120	+1m			01-JUN-2012		
	PKG 87	HRS/MSC					0		
	REF: MM 72-00-00	ENC					0		
72-00-00-280-820 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	MOS	12	+30d			20-JUN-2018		
	PKG 1	HRS/MSC	600	+10%			573:42		
	REF: MM 72-00-00	ENC					502		
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					20-JUN-2018		
	REF: MM 72-00-00	HRS/MSC BF/F					573:42		
		ENC					502		
720010	NO. 1 ENGINE - OVERHAUL	MOS					24-FEB-2012		
	REF: GENERIC NO REF	HRS/MSC	5000	+100			0	(5000) 5000	5100
		ENC					0		
720060	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					24-FEB-2012		
	REF: MM 72-00-00	HRS/MSC	2500	+50			0	(2500) 2500	2550
		ENC					0		
721010	NO. 1 ENGINE - GEARBOX	MOS					24-FEB-2012		
	PN	HRS/MSC			TSN:0		0		
	SN-UNKNOWN	O/C			TSN:0		0		
	REF: GENERIC NO REF	ENC			TSN:0		0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 1 ENGINE - OIL PUMP 3073477-02 EC01A003A525 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY 3073356-01 A0033WR3 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0	(30000) 30000	
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A0034A9D REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0	(15000) 15000	
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1C6005 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0	(15000) 15000	
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A0033MN9 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0	(13500) 13500	
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 A00342NF REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0	(13500) 13500	
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY 3074676-01 EDA01153U REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723060	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING 3052663-02 FCN316441 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY 3075850-01 A0034R8R REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY 3076150-01 RWA60D883 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A0034LMD REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA413111 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00C270 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 PKAAA321847 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 UAAB823 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA000011324 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000N753 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723160	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 3052670-02 FCN352220 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA417836 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052616-01 FCN331733 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
723190	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A0030FMB	MOS HRS/MSC		TSN:0 TSN:0			24-FEB-2012 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	13500	TSN:0			0	(13500) 13500	
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A0034L5N	MOS HRS/MSC		TSN:0 TSN:0			24-FEB-2012 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	13500	TSN:0			0	(13500) 13500	
724001	NO. 1 ENGINE - INNER COMBUSTION LINER 3075516-01 A00332DC	MOS HRS/MSC	O/C	TSN:0 TSN:0			24-FEB-2012 0		
	REF: See Workcard	ENC		TSN:0			0		
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER 3075522-01 A0033L4N	MOS HRS/MSC	O/C	TSN:0 TSN:0			24-FEB-2012 0		
	REF: See Workcard	ENC		TSN:0			0		
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221835540	MOS HRS/MSC	O/C	TSN:0 TSN:0			24-FEB-2012 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A0031RXF	MOS HRS/MSC		TSN:0 TSN:0			24-FEB-2012 0		
LIFE LIMIT	REF: See Workcard	ENC	10000	TSN:0			0	(10000) 10000	
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A0033Y5K	MOS HRS/MSC		TSN:0 TSN:0			24-FEB-2012 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	13500	TSN:0			0	(13500) 13500	



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9877 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9966 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9975 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9976 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9977 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9981 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9995 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9996 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9999 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0004 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0014 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9878 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0018 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0022 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0023 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0027 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0030 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0037 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0048 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0051 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0054 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0059 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9885 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0062 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0067 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0070 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0085 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0091 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0095 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0097 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0098 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0106 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY0118 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9887 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6441 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6445 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6451 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6454 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6472 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6478 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6479 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6484 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6488 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6489 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9900 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6491 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6499 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6500 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6503 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6504 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6505 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6507 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6509 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6516 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6519 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9913 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6521 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9921 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9941 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY9960 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6522 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6524 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6528 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6531 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6537 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6540 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6543 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6546 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6553 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFY6555 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN351550 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA62D613 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 AWE014294 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3053163CL01 PDAH4L1C01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAH2EYX01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHEYNME01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN349284 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128751 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128763 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128764 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128775 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726060	NO. 1 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3072949-01 PKAAA398647 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA56D913 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1118526 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1117903 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0126859 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA412418 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA009A098 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA009A260 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-802 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-804 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-805 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-806 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-807 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-808 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-212-809 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR REF: MM 72-00-00	MOS HRS/MSC ENC	A/R				21-MAR-2012 0 0		
72-00-00-280-818 (s)	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) PKG 87 REF: MM 72-00-00	MOS HRS/MSC ENC	120	+1m			PKG 01-JUN-2012 0 0		
72-00-00-280-820 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL REF: MM 72-00-00	MOS HRS/MSC ENC	BF/F				20-JUN-2018 573:42 502		
720010	NO. 2 ENGINE - OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			21-MAR-2012 0 0	(5000) 5000	5100



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720060	NO. 2 ENGINE - HOT SECTION INSPECTION REF: MM 72-00-00	MOS HRS/MSC ENC	2500	+50			21-MAR-2012 0 0	(2500) 2500	2550
721010	NO. 2 ENGINE - GEARBOX REF: GENERIC NO REF	PN MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0		
722001	NO. 2 ENGINE - OIL PUMP REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0		
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY REF: GENERIC NO REF	MOS HRS/MSC ENC	30000		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0	(30000) 30000	
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR REF: See Workcard	MOS HRS/MSC ENC	15000		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0	(15000) 15000	
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR REF: GENERIC NO REF	MOS HRS/MSC ENC	15000		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0	(15000) 15000	
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR REF: GENERIC NO REF	MOS HRS/MSC ENC	13500		TSN:0 TSN:0 TSN:0		21-MAR-2012 0 0	(13500) 13500	

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 A0034BK9 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0	(13500) 13500	
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY 3074676-01 EDA01168A REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723060	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING 3052663-02 FCN213453 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY 3075850-01 A00351AK REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY 3076150-01 RWA66D630 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A0034WDP REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA413110 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00H909 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 UAAA3918 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 UAAB4536 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA000011326 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000P216 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723160	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 3052670-02 FCN338519 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA423558 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723190	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A0034TYA REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0	(13500) 13500	
LIFE LIMIT									
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A0034NRK REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0	(13500) 13500	
LIFE LIMIT									
724001	NO. 2 ENGINE - INNER COMBUSTION LINER 3075516-01 A003387C REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER 3075522-01 A003481C REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221836452 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A0034N28	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		(10000) 10000
LIFE LIMIT	REF: See Workcard								
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A0033Y5M	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		(13500) 13500
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8722	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8768	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8770	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8849	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8855	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8857 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8860 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8862 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8863 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8875 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8885 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8723 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8895 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8901 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5322 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5327 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5331 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5332 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5338 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5343 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5344 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5346 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8724 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5350 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5351 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5354 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5356 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5361 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5368 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5377 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5378 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5379 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5380 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8727 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5385 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX5387 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9827 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9829 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9830 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9837 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9840 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9848 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9851 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9854 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8735 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9861 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9864 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9867 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9868 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9870 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9871 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9873 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9883 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9884 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9892 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8737 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9915 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8754 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8758 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFL8765 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9916 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9917 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9954 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9957 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9962 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9965 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9970 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3077471-01 HWFX9984 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3077471-01 HWF9986 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3077471-01 HWF9988 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN351547 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA67D122 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA002A178 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3053163CL01 PDAH436R01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAH4KMF01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHERNPM01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN351829 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128366 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128418 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128422 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0128435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726060	NO. 2 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3072949-01 PKAAA412092 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA61D231 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1118538 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1122037 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726120	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0126860 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA425261 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA009A235 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA009A461 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
73-21-01	LEFT FADEC 1012300-2-002 2012020019 REF: See Workcard	MOS HRS/MSC AFL	O/C				31-MAY-2013 230:53 119		
73-21-01	RIGHT FADEC 3073593-06 2010080050 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:11 TSN:230:53 TSN:119			31-MAY-2013 230:53 119		
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 26832 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 27418 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01

72-00-00-280-819 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY						PKG		
	PKG 1	MOS	12	+30d			20-JUN-2018		
		HRS/MSC	600	+10%			573:42		
	REF: MM 72-00-00	ENC					502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES	MOS					(EBT)		
	REF: MM 73-10-04	HRS/MSC ENC	9900					(9900) 9900	
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT	MOS	12	+30d	-10		20-JUN-2018 573:42 502	10-JUN-2019	10-JUL-2019
	REF: MM 73-10-05	HRS/MSC ENC							
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER	MOS	600	+10%			27-MAY-2013 230:53 119	(830:53) 830:53	890:53
	REF: See Workcard	HRS/MSC ENC							
73-10-07-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE	MOS	12	+30d			20-JUN-2018 573:42 502		
	PKG 1	HRS/MSC ENC	600	+10%					
	REF: MM 73-10-07								
73-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS	MOS	12	+30d			20-JUN-2018 573:42 502		
	PKG 1	HRS/MSC ENC	600	+10%					
	REF: MM 73-20-02								
73-30-02-212-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR	MOS	12	+30d			20-JUN-2018 573:42 502		
	PKG 1	HRS/MSC ENC	600	+10%					
	REF: MM 73-30-02								
731002	NO. 1 ENGINE - FLOW DIVIDER	MOS					24-FEB-2012 0 0		
	PN	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0				
	SN-UNKNOWN								
	REF: GENERIC NO REF								



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BRU1913 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0753 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0754 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BRU1914 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BRU1915 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0745 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0746 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0747 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0748 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0749 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTD0752 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
732000	NO. 1 ENGINE - TEMPERATURE SENSOR ATS-9-800 080211-17 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2012080034 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:4 TSN:352 TSR:0 TSN:272 TSR:0			04-JUL-2017 511:06 428		
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F73327 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732005	NO. 1 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
732006	NO. 1 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS 3073237-04 N/A REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:21 TSN:0 TSN:0			11-DEC-2013		
732020	NO. 1 ENGINE - FUEL MANIFOLD AND FUEL NOZZLES PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
733001	NO. 1 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
72-00-00-280-819 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			20-JUN-2018 573:42 502		
+ 73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT) (9900) 9900		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d		-10	20-JUN-2018 573:42 502	10-JUN-2019	10-JUL-2019
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER REF: See Workcard	MOS HRS/MSC ENC	600	+10%			13-JUL-2015 420 264	(1020) 1020	1080
73-10-07-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12	+30d			20-JUN-2018 573:42 502		
73-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12	+30d			20-JUN-2018 573:42 502		
73-30-02-212-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12	+30d			20-JUN-2018 573:42 502		
731002	NO. 2 ENGINE - FLOW DIVIDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1049 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1065 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1066 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1055 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1056 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1057 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1059 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1061 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1062 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1063 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BTH1064 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
732000	NO. 2 ENGINE - TEMPERATURE SENSOR ATS-9-800 082511-15 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2015030013 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:622:25 TSN:592			04-JUL-2017 511:06 428		
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F73545 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
732005	NO. 2 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732006	NO. 2 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
732020	NO. 2 ENGINE - FUEL MANIFOLD AND FUEL NOZZLES PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
733001	NO. 2 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01

74-00-01-750-801 (s)	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				PKG 573:42 502		
74-10-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER PKG 1 REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
74-20-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG		
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG		
74-20-02-960-801	NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				20-JUN-2014 389:58 203		
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				20-JUN-2014 389:58 203		
741001	NO. 1 ENGINE - EXCITER IGNITION 31J2807-07 NNA12040185 REF: See Workcard	MOS	O/C			TSN:0 TSN:0 TSN:0	24-FEB-2012 0 0		
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C			TSN:0 TSN:0 TSN:0	24-FEB-2012 0 0		
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C			TSN:0 TSN:0 TSN:0	24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-01 NNA16100072 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:3 TSN:0 TSN:0			01-JUL-2016 474:50 341		
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA16100127 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			01-JUL-2016 474:50 341		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
74-00-01-750-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				PKG		
74-10-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER PKG 1 REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
74-20-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-960-801	NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				20-JUN-2014 389:58 203		
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				20-JUN-2014 389:58 203		
741001	NO. 2 ENGINE - EXCITER IGNITION 31J2807-07 NNA12090053 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-01 NNA16110081 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:3 TSN:0 TSN:0			01-JUL-2016 474:50 341		
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA16080175 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			01-JUL-2016 474:50 341		

CHAPTER 75 AIR

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR5800 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER 3071811-01 1481 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
753002	NO. 1 ENGINE - SERVO DISPLAY UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX0500060 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
75-30-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR5851 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER 3071811-01 1500 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
753002	NO. 2 ENGINE - SERVO DISPLAY UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX0500063 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
CHAPTER 76 ENGINE CONTROLS									
76110101-0901	THROTTLE CONTROL QUADRANT ASSY 6990010-11 1061 REF:	MOS HRS/MSC AFL	O/C				08-MAR-2013 166 85		
CHAPTER 77 ENGINE INDICATING									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01									
77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM REF: MM 77-20-02	MOS HRS/MSC ENC	36 1800	+30d +100	-19		20-JUN-2018 573:42 502	01-JUN-2021 (2373:42) 2373:42	01-JUL-2021 2473:42
772001	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772003	NO. 1 ENGINE - T6 THERMOCOUPLES PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
774001	NO. 1 ENGINE - DATA COLLECTION UNIT 3075878-01 15032224 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-JUL-2015 420 264		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM REF: MM 77-20-02	MOS HRS/MSC ENC	36 1800	+30d +100	-19		20-JUN-2018 573:42 502	01-JUN-2021 (2373:42) 2373:42	01-JUL-2021 2473:42
772001	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
772003	NO. 2 ENGINE - T6 THERMOCOUPLES PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
774001	NO. 2 ENGINE - DATA COLLECTION UNIT 3075394-01 DP09-1320 REF: See Workcard	MOS HRS/MSC ENC	O/C				22-NOV-2012 107:58 52		
CHAPTER 79 OIL									
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00230 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00205 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2012 0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0202 Part # 3072913-01									
79-20-01-960-801	NO. 1 ENGINE - DISCARD THE OIL FILTER PKG 1 REF: See Workcard	MOS HRS/MSC ENC	600	+10%			20-JUN-2014 389:58 203	(989:58) 989:58	1049:58
79-30-01-770-801 (s)	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
79-30-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 20-JUN-2018 573:42 502		
790020	NO. 1 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				24-FEB-2012 0 0		
793001	NO. 1 ENGINE - OIL CHIP DETECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
793002	NO. 1 ENGINE - COLD START VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 25520022 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
793004	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2012 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0209 Part # 3072913-01									
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER PKG 1 REF: See Workcard	MOS HRS/MSC ENC	600	+10%			20-JUN-2014 389:58 203	(989:58) 989:58	1049:58
79-30-01-770-801 (s)	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12	+30d +10%			20-JUN-2018 573:42 502		
79-30-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12	+30d +10%			20-JUN-2018 573:42 502		
790020	NO. 2 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				21-MAR-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793001	NO. 2 ENGINE - OIL CHIP DETECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
793002	NO. 2 ENGINE - COLD START VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 06988632 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
793004	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-MAR-2012 0 0		

CHAPTER --	GENERAL							
Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0	
Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION PKG 84 REF: See Workcard	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M 01-JUL-2022



Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 84 REF: AMM 05-41-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 84 REF: AMM 05-43-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 84 REF: AMM 05-43-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84 REF: AMM 05-44-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 04-JUL-2017 511:06 428		
Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500099 (F-HJFG): 618:42 HRS, 535 AFL as of 22-Jan-2019

Owner/Operator: GDP VENDOME

Report Date: 24-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 01-JUN-2012 0 0		
Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 84 REF: AMM 05-46-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022
Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+30d/-30d			01-JUL-2016 474:50 341	01-JUN-2022 M	01-JUL-2022