

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 531/LX-LAB **MODEL:** PC12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 25-NOV-2003	8396:50 A/C HRS	as of 12-OCT-2019	A/C HRS	as of ___/___/___
	7621 AFL	as of 12-OCT-2019	AFL	as of ___/___/___
	0 ACH	as of 10-SEP-2019	ACH	as of ___/___/___
	6846 FLTS	as of 12-OCT-2019	FLTS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0400/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 12-APR-2019	LAST ACTUALS		CURRENT ACTUAL	
7600:20 ENG. HRS 0 A/C HRS	7962:20 ENG. HRS	as of 12-OCT-2019	ENG. HRS	as of ___/___/___
6205 ENC	6504 ENC	as of 12-OCT-2019	ENC	as of ___/___/___

PROPELLER NOSERIAL/PART: KX1077/HC-E4A-3D/E10477SK **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 02-MAR-2018	LAST ACTUALS		CURRENT ACTUAL	
2818:50 PROP HRS 7468:45 A/C HRS	3746:55 PROP HRS	as of 12-OCT-2019	PROP HRS	as of ___/___/___



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 17	MOS				25-NOV-2003		
		HRS/MSC	A/R			0		
	REF: AMM 05-20-00	AFL				0		
05401A	300 HOUR INSPECTION							
+								
	PKG 18	MOS				10-SEP-2019		
		HRS/MSC	300	+30/-30	-6:20	8341:10	8634:50	8664:50
	REF: AMM 05-40-01	AFL				7583		
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 3	MOS	12			10-SEP-2019	10-SEP-2020	
		HRS/MSC	300	+30/-30	-6:20	8341:10	8634:50	8664:50
	REF: AMM 05-40-01	AFL				7583		
05403A	600 HOUR INSPECTION							
+								
	PKG 19	MOS				12-APR-2019		
		HRS/MSC	600	+10%/-10%		8034:50	8634:50	8694:50
	REF: AMM 05-40-01	AFL				7322		
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 20	MOS	12			12-APR-2019	12-APR-2020	
		HRS/MSC	600	+30/-30		8034:50	8634:50	8664:50
	REF: AMM 05-40-01	AFL				7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A +	1200 HOUR OR 12 MONTHS INSPECTION							
	PKG 21	MOS	12			12-APR-2019	12-APR-2020	
		HRS/MSC	1200	+30/-30		8034:50	9234:50	9264:50
	REF: AMM 05-40-01	AFL				7322		

05406A +	2400 HOUR OR 24 MONTHS INSPECTION							
	PKG 22	MOS	24	+1m/-1m		12-APR-2019	12-APR-2021	12-MAY-2021
		HRS/MSC	2400	+30/-30		8034:50	10434:50	10464:50
	REF: AMM 05-40-01	AFL				7322		

ENGINE NO. 1	Model : PT6A-67B/-67P	Serial # PCE-PR0400	Part # 3042200					
057010 +	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 0 in PKG 1	MOS				10-SEP-2019		
		HRS/MSC	300	+10%/-10%	-6:20	7906:40	(8200:20) 8634:50	8230:20
	REF: See Workcard	ENC				6466		

CHAPTER 72	ENGINE							
ENGINE NO. 1	Model : PT6A-67B/-67P	Serial # PCE-PR0400	Part # 3042200					
72JFL01	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 1	MOS				10-SEP-2019		
		HRS/MSC	300	+10%/-10%	-6:20	7906:40	(8200:20) 8634:50	8230:20
	REF:	ENC				6466		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC	A/R				8034:50		
		AFL					7322		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC	A/R				8034:50		
		AFL					7322		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 17	MOS					25-NOV-2003		
	REF:	HRS/MSC	A/R				0		
		AFL					0		
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					10-SEP-2019		
		HRS/MSC	-				8341:10		
		AFL					7583		
00JFL65	PERFORM PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 5 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					10-SEP-2019		
		HRS/MSC	-				8341:10		
		AFL					7583		
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM								
	REF: RCF PC12	MOS					(EBT)		
		HRS/MSC	-						
		AFL							
REQUIREMENT CHANGE FORMS									



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL					(EBT)		
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL					04-MAY-2016		
PC12-160717	REVIEW PILATUS PC12 AMM REV 32								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL					23-NOV-2016		
PC12-161212	REVIEW PILATUS PC12 AMM REV 33								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL					31-JAN-2017		
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34								
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL					29-SEP-2017		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS						16-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS						16-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37	MOS						16-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-190517	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38	MOS						19-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						10-SEP-2015 5822:10	
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						10-SEP-2015	
E072-150404	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 22 DATED NOV 16/2012 RCF								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						(EBT)	
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						10-SEP-2015 5822:10	
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						16-SEP-2016	
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC						03-JUN-2016	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26							01-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1							31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2							07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24							07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0							16-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27							(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					04-SEP-2017		
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2								
REQUIREMENT CHANGE FORMS	REF: RCF E072-170818	MOS HRS/MSC - ENC					11-SEP-2017		
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					(EBT)		
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					(EBT)		
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					(EBT)		
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					16-MAY-2019		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS					16-MAY-2019		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS					16-MAY-2019		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1077 Part # HC-E4A-3D/E10477SK									
P019-150423	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF	MOS					10-SEP-2015		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -					1520:30		
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					30-NOV-2015		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS HRS/MSC -						31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS HRS/MSC -						16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS HRS/MSC -						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS HRS/MSC -						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS HRS/MSC -						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS HRS/MSC -						06-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P019								

CHAPTER 04 LIMITATIONS



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		TSN:0			25-NOV-2003		
	SN-UNKNOWN	HRS/MSC	50000	TSN:0			0		50000
LIFE LIMIT	REF:	AFL	60000	TSN:0			0		60000
<hr/>									
+ 040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		TSN:0			25-NOV-2003		
	SN-UNKNOWN	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF:	AFL	43000	TSN:0			0		43000
<hr/>									
+ 040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		TSN:0			25-NOV-2003		
	SN-UNKNOWN	HRS/MSC	35000	TSN:0			0		35000
LIFE LIMIT	REF:	AFL	43000	TSN:0			0		43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-01	UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS					25-NOV-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS								
		MOS					25-NOV-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN								
		MOS					25-NOV-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER SUDDEN PROPELLER STOPPAGE								
		MOS					25-NOV-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					25-NOV-2003		
	REF: AMM 05-10-30	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					25-NOV-2003		
	REF:	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
05JFL01	DENT & BUCKLE	MOS							
	REF:	HRS/MSC	-						
		AFL							
05JFL11	- AIRWORTHINESS REVIEW CERTIFICATE	MOS					04-NOV-2018		01-DEC-2019 M
	REF:	HRS/MSC	DUE				7934:50		
		AFL					7236		
05JFL12	- CERTIFICATE OF REGISTRATION	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL13	- NOISE CERTIFICATE	MOS							
	REF:	HRS/MSC	A/R						
		AFL							



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05JFL14	- AIRCRAFT STATION LICENCE	MOS					18-JAN-2018		31-DEC-2019 M
	REF:	HRS/MSC AFL	DUE						
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING	MOS					17-SEP-2019		
	REF:	HRS/MSC AFL	300		-23:45		8358:35 7594		8634:50

CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC AFL	A/R				8034:50 7322		
+ 06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 17	MOS					12-APR-2019		
	REF: AMM 06-20-00	HRS/MSC AFL	A/R				8034:50 7322		
06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 12GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR.						PKG		
	PKG 17	MOS					12-APR-2019		
	REF: AMM 06-20-00	HRS/MSC AFL	A/R				8034:50 7322		
06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL						PKG		
	PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC AFL	A/R				8034:50 7322		

CHAPTER 07 LIFTING AND SHORING



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				12-APR-2019 8034:50 7322		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				12-APR-2019 8034:50 7322		
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST REF:	MOS HRS/MSC AFL	60	+1m/-1m			08-JUL-2016 6498:10 5994	08-JUL-2021	08-AUG-2021
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6) REF:	MOS HRS/MSC AFL					22-APR-2016 6369:45 5795		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			10-SEP-2019 8341:10 7583		
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%			12-APR-2019 8034:50 7322		
CHAPTER 12 SERVICING									



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS PKG 17 REF: AMM 12-20-01	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 17 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 17 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A 20.010	PERFORM CORROSION INSPECTION (INTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+10%/-10%		-20	12-APR-2019 8034:50 7322	23-MAR-2020	29-APR-2020
00-00/45B 20.011	PERFORM CORROSION INSPECTION (EXTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	6 300	+10%/-10% +10%/-10%		-6:20	10-SEP-2019 8341:10 7583	10-MAR-2020 8634:50	28-MAR-2020 8664:50
20JFL00	DENT & BUCKLE PERIODIC INSPECTION WITH REPORT ON FORM FT-PC12 REF:	MOS HRS/MSC AFL	-						
20JFL01	PERFORM DENTS AND BUCKLES CHARTS REF:	MOS HRS/MSC AFL	300	+10%/-10%		-6:20	10-SEP-2019 8341:10 7583	8634:50	8664:50

CHAPTER 21 AIR CONDITIONING

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue
(ENG/APU) = Engine/APU Units



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF:	AFL					7322		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
21.040		MOS	24	+10%/-10%	-9		01-MAR-2018	20-FEB-2020	02-MAY-2020
		HRS/MSC	3000	+10%/-10%			7468:45	10468:45	10768:45
	REF: AMM 21-30-00	AFL					6839		
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
21.030		MOS	24	+10%/-10%	-83		01-MAR-2018	08-DEC-2019	19-FEB-2020
		HRS/MSC	3000	+10%/-10%			7468:45	10468:45	10768:45
	REF: AMM 21-30-01	AFL					6839		
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
21.010		MOS	60	+10%/-10%	-111		12-APR-2019	22-DEC-2023	22-JUN-2024
		HRS/MSC					8034:50		
	REF: AMM 21-30-07	AFL					7322		
21-30/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
21.020		MOS	60	+10%/-10%	-111		12-APR-2019	22-DEC-2023	22-JUN-2024
		HRS/MSC					8034:50		
	REF: AMM 21-30-08	AFL					7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH	MOS					25-NOV-2003		
	REF: AMM 21-40-11	HRS/MSC AFL	N/A				0 0		
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER	MOS	12	+10%/-10%			28-SEP-2018		
21.080	PKG 21	HRS/MSC AFL	1200	+10%/-10%			7891:10 7197		
	REF: AMM 21-40-02								
+ 21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%	-111		12-APR-2019	22-DEC-2023	22-JUN-2024
21.130	REF: AMM 21-40-06	HRS/MSC AFL	4800	+10%/-10%			8034:50 7322	12834:50	13314:50
+ 21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%	-111		12-APR-2019	22-DEC-2023	22-JUN-2024
21.120	REF: AMM 21-60-05	HRS/MSC AFL	4800	+10%/-10%			8034:50 7322	12834:50	13314:50
+ 21-40/53	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 101-320 WITHOUT A MODIFIED AUXILIARY HEATING SYSTEM)	MOS					25-NOV-2003		
	REF: AMM 21-40-09	HRS/MSC AFL	N/A				0 0		
+ 21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)	MOS	12	+10%/-10%			12-APR-2019		
	PKG 21	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
	REF: AMM 21-40-00								
21-40/55	RE-OIL AIR CONDITIONING COLD AIR UNIT	MOS					10-SEP-2019		
21.060	PKG 19	HRS/MSC AFL	600	+10%/-10%			8341:10 7583	8941:10	9001:10
	REF: AMM 21-40-01								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/56	INSPECT/CHECK HEAT EXCHANGER MATRIX PKG 19	MOS					10-SEP-2019		
21.070	REF: AMM 21-40-01	HRS/MSC AFL	600	+10%/-10%			8341:10 7583	8941:10	9001:10
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT PKG 21	MOS	12	+10%/-10%			12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) 959.90.22.140	MOS					10-SEP-2019		
	2285	HRS/MSC	300	+10%/-10%			8341:10	8641:10	8671:10
	REF:	AFL					7583		
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140	MOS					10-SEP-2019		
	2285	HRS/MSC					8341:10		
	REF:	AFL					7583		
		ACH	600	+10%/-10%			0	600	660
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140	MOS					10-SEP-2019		
	2285	HRS/MSC					8341:10		
	REF:	AFL					7583		
		ACH	600	+10%/-10%			0	600	660
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) 959.90.22.140	MOS					10-SEP-2019		
21.110	REF: AMM 21-50-03	HRS/MSC AFL	N/A				8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.100	959.90.22.140 2285 REF: See Workcard	MOS HRS/MSC AFL	N/A				10-SEP-2019 8341:10 7583		
210005	OVERPRESSURE SWITCH								
21.340	973.81.15.105 0314 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210010	REFRIGERATION PACK								
21.255	959.90.20.111 1090 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210015	WATER INJECTOR								
21.370	959.90.20.141 1067 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210020	DUCT TEMP SENSOR								
21.320	959.90.20.121 1089 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	959.90.20.132 1057 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210030	HP SHUT OFF VALVE								
21.280	959.90.20.131 1057 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210035	WATER SEPARATOR ASSY 521.41.12.060	MOS		TSN:0			25-NOV-2003		
21.220	2200 REF: AMM 21-40-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
210040	TEMPCONTROL VALVE 959.90.20.136	MOS		TSN:0			25-NOV-2003		
21.310	1038 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE 959.90.22.140	MOS		TSN:0			10-SEP-2019		
21.380	2285 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			8341:10 7583		
210046	VAPOR CYCLE COMPRESSOR MOTOR 959.90.22.141	MOS		TSN:0			10-SEP-2019		
	0379 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			8341:10 7583		
210050	CENTER EVAPORATOR MODULE ASSY 959.90.22.116	MOS		TSN:0			25-NOV-2003		
21.200	799 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY 959.90.22.118	MOS		TSN:0			27-JUL-2010		
21.200	642 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			3517:21 2915		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY 959.90.22.119	MOS		TSN:0			27-JUL-2010		
21.210	569 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			3517:21 2915		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	959.90.91.121 83-A0462 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	959.90.91.131 83-B0472 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	959.90.91.111 83-7619 REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210075	CHECK VALVE								
21.400	959.90.91.151 83-A0577 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210080	JET PUMP								
21.410	959.90.91.161 83-1841 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210085	MANUAL CONTROLLER								
21.420	959.90.91.101 83-A0458 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	959.90.91.141 70-G0305 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				11-JUL-2008 2800:54 2250		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	965.23.23.202 1024232 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210100	CAB RATE INDICATOR								
21.440	965.16.21.002 1023823 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	965.23.21.532 102831 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210110	CABIN PX SWITCH								
21.360	9652321533 1019784 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-APR-2019 8034:50 7322		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.507 506828 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210120	BAY TEMP SENSOR								
21.450	959.90.20.122 1011 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	975.15.16.101 A5899 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210130	TEMP CONTROLLER								
21.235	959.90.20.123 1051 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210140	SOLENOID VALVE								
21.300	963.14.11.001 3060924 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	969.67.81.507 578561 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C				22-OCT-2018 7911:05 7213		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	963.30.11.106 0276B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	963.30.11.002 302 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210160	CABIN HEATER TEMPERATURE TRANSMITTER								
21.350	975.15.16.104 227 REF: AMM 21-40-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
210165	UNDERFLOOR HEATER TEMPERATURE TRANSMITTER								
21.260	974.03.38.111 2453 REF: AMM 21-40-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-AUG-2011 3972:56 3370		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210170	OVERPRESSURE SWITCH								
21.340	973.81.15.106 0312 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST								
	REF:	MOS HRS/MSC AFL	24				12-APR-2019 8034:50 7322	12-APR-2021	
CHAPTER 22 AUTO FLIGHT									
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 22	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK								
22.010	REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+10%/-10% +10%/-10%	-51		12-APR-2019 8034:50 7322	20-FEB-2020 9034:50	26-MAR-2020 9134:50
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583		
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM						PKG		
	PKG 18	MOS HRS/MSC AFL	300	+10%/-10%			10-SEP-2019 8341:10 7583		
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220005	AUTOPILOT MODE CONTROL								
22.160	065-0086-17 2769 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2011 3982:41 3377		
220010	ALTITUDE PRESELECTOR								
22.180	065-00089-0016 2271 REF: AMM 22-10-06	MOS HRS/MSC AFL ACH	O/C	TSR:2 TSR:0 TSR:0 TSR:0			30-DEC-2012 4618:41 3995		
220015	AILERON KSA372,065-00056-0056 ACTUATOR								
22.100	985.92.03.161 3974 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:56 TSN:0 TSN:0			23-JUL-2008		
220020	PITCH KSM375,065-00015-0000 MOUNT								
22.190	985.92.03.173 9285 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR								
22.110	065-00056-59 5508 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C				30-NOV-2015 6211:15 5669		
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	985.92.03.171 9312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	065-0056-80 5550 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C				15-AUG-2016 6596:10 6079		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	985.92.03.171 9308 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220045	STICK PUSHER SERVO								
22.220	978.61.11.103 1500 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220050	PITCH TRIM ADAPTER								
22.130	985.92.03.181 1558 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	978.61.11.124 1473 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
220060	STICK SHAKER								
22.230	2401-1-2100-01 0977 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			29-OCT-2009 3300:11 2690		
220065	AUTOPILOT COMPUTER								
22.150	522.10.12.053 X2191 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				21-AUG-2008 2867 2314		
220070	STICK PUSHER COMPUTER								
22.170	9754423104 125262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:76:10			12-MAR-2011 3737:46 3146		

CHAPTER 23 COMMUNICATIONS



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA 984.81.10.203 310-25641 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-FEB-2014 5193:35 4621		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA 984.81.10.203 11181 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
230015	COMM/NAV 25 KHZ SYSTEM 985.99.11.366 2151 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
230020	COMM/NAV 25 KHZ SYSTEM 985.99.11.366 1937 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
230025	AUDIO SUMMING AMPLIFIER 987.81.33.108 160 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
230030	GARMIN GMA-340 AUDIO SELECTOR 010-00152-11 96296071 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAY-2015 5917:50 5444		
23JFL01	NO. 1 NAV/COM/GPS TRANSCEIVER 011-00550-10 78417802 REF:	MOS HRS/MSC AFL	O/C				29-DEC-2016 6802:10 6323		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23JFL02	NO. 2 NAV/COM/GPS TRANSCEIVER 011-00550-10 78409366 REF:	MOS HRS/MSC AFL	O/C				02-MAR-2017 6893:40 6402		
CHAPTER 24 ELECTRICAL POWER									
+ 24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM PKG 21 REF: AMM 24-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT PKG 3 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED) PKG 3 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
24-30/19 24.020	STARTER GENERATOR 23085-029A Y10097 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A		TSO:0	6	25-JUL-2018 7777:25 7092		
+ 24-30/21 DISCARD	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING 9408308902 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	3000	+10%/-10%	TSN:0 TSN:0 TSN:0		27-MAY-2015 5917:50 5444	8917:50	9217:50
+ 24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/482 (s)	BRUSH CHECK STARTER GENERATOR BRUSHES (P/N 978.91.23.407, 978.91.23.408 AND 978.91.23.409) 23085-029A PKG 19 Y10097 REF:	MOS HRS/MSC AFL	600	+10%/-10%			PKG 25-NOV-2003 0 0		
24-30/491	OVERHAUL STARTER GENERATOR 23085-029A Y10097 REF:	MOS HRS/MSC AFL	1200				22-DEC-2016 6783:25 6309	7983:25	
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%	-9		01-MAR-2018 7468:45 6839	20-FEB-2020	02-MAY-2020
24.210									
+ 24-30/63	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES 524.32.12.158 MOD G 100580 REF: AMM 24-30-02	MOS HRS/MSC AFL	N/A				12-APR-2019 8034:50 7322		
24.030									
+ 24-30/64	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES 524.32.12.158 MOD G 100580 REF: AMM 24-30-02	MOS HRS/MSC AFL	600	+10%/-10%			12-APR-2019 8034:50 7322	8634:50	8694:50
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A		22:22		27-MAY-2015 5917:50 5444		
24.030									
+ 24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING REF: AMM 24-30-04	MOS HRS/MSC AFL	1800	+10%/-10%			28-SEP-2018 7891:10 7197	9691:10	9871:10
24.030									



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	31406-002 113001680 REF: AMM 24-30-07	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7563	10-SEP-2020 8641:10	16-OCT-2020 8671:10
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE						PKG		
	PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY								
24.050	501-1712-02 82918 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			12-APR-2019 8034:50 7322	12-APR-2020	12-MAY-2020
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS						PKG		
	PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	988.21.14.111 Y0127 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C				18-OCT-2013 5048:55 4430		
240025	GENERATOR 2 2ND GENCON UNIT								
24.140	988.21.15.103 10155 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-NOV-2003 0 0		
240035	BUSBAR,CROSS TIE RCCB								
24.150	972.55.37.003 1073 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240040	BUSBAR,CROSS,TIE RCCB								
24.150	972.55.37.005 480 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240045	STARTER RELAY								
24.160	974.09.26.133 P464 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240050	BATTERY RELAY								
24.170	974.09.26.126 P898 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240055	EPU RELAY								
24.180	974.09.26.126 P810 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	972.81.32.301 389 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240065	OVERHEAD PANEL								
24.190	972.81.32.102 JWPIL229 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSN:8898:30 TSR:0 TSR:0			22-JUL-2019 8234:05 7491		
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	959.90.20.124 230 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	975.04.21.110 AGA00480 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	974.29.00.201 2726 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240095	S105 DC CURRENT SENSOR								
24.090	974.29.00.205 1832 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	974.29.00.205 1862 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	974.29.00.201 2758 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
240110	S104 DC CURRENT SENSOR								
24.090	76607-1 2623 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C				20-OCT-2014 5650:40 5046		
240115	S106 DC CURRENT SENSOR								
24.100	76607-1 2728 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C				20-OCT-2014 5650:40 5046		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243045	GENERATOR 2								
24.030	524.32.12.158 MOD G 100580 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:6411:02 TSN:4023			14-MAR-2019 8006:20 7294		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 82918 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				22-DEC-2018 7968:25 7262		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 113001680 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				10-SEP-2019 8341:10 7563		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583		
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 18	MOS HRS/MSC AFL	300	+10%/-10%			10-SEP-2019 8341:10 7583		
25-10/293	COPILOT SEAT CUSHION								
	PN SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
25-10/293	PILOT SEAT CUSHION								
25.080	PN SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/294	COPILOT CREW SEAT BELT 5PC41400-506 N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0		13-JUN-2019 8119 7395	30-APR-2030	M 31-OCT-2030
25-10/294 (s) 25.030 DISCARD	CREW SEAT BELTS 1-10-870301 REVA N/A REF: AMM 25-10-02	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-5	30-NOV-2015 6211:15 5669		
25-10/294	PILOT CREW SEAT BELT 5PC41400-505 SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0	-487	30-NOV-2015 6211:15 5569	31-JUL-2026	31-JAN-2027
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
+ 25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 25-10/487 DISCARD	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				25-NOV-2003 0 0	10000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
25-20/295	NO. 1 PASSENGER SEAT BELT 5-02-2T4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-28	30-NOV-2015 3211:15 5669	02-NOV-2027	02-MAY-2028
25-20/295	NO. 2 PASSENGER SEAT BELT 5-02-2T4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-28	30-NOV-2015 3211:15 5669	02-NOV-2027	02-MAY-2028
25-20/295	NO. 3 PASSENGER SEAT BELT 5-02-2T4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-118	30-NOV-2015 3211:15 5669	04-AUG-2027	04-FEB-2028
25-20/295	NO. 4 PASSENGER SEAT BELT 5-02-T-4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-118	30-NOV-2015 3211:15 5669	04-AUG-2027	04-FEB-2028
25-20/295	NO. 5 PASSENGER SEAT BELT 5-02-2T4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-118	30-NOV-2015 3211:15 5669	04-AUG-2027	04-FEB-2028



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 6 PASSENGER SEAT BELT 5-02-2T4718MNI N/A REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0	-118	30-NOV-2015 3211:15 5669	04-AUG-2027	04-FEB-2028
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). PKG 18 REF:	MOS HRS/MSC AFL	300	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 25-60/231 (s)	OPERATIONAL TEST ELT PKG 3 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 25-60/483	PERFORM PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 985.13.80.853 M0131.0064 REF: AMM 25-63-10	MOS HRS/MSC AFL	A/R				25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY S1820516-99 AMDT D	MOS		TSN:0			13-FEB-2015	30-NOV-2021 M	
25.020	TM0000071128	HRS/MSC	DUE	TSN:0			5770:40		
DISCARD	REF: GENERIC NO REF	AFL		TSN:0			5215		
Expiry Date: 30-NOV-2021									
250005	REMOTE CONTROL PANEL 985.13.80.817	MOS		TSN:0			25-NOV-2003		
25.070	M0415.0014	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER 985.13.80.853	MOS		TSN:0			25-NOV-2003		
25.050	M0131.0064	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-63-01	AFL		TSN:0			0		
250015	SCHROTH SEAT PILOT 959.30.01.133	MOS					11-JUN-2015		
25.040	880	HRS/MSC	O/C						
	REF: AMM 25-10-05	AFL							
250020	SCHROTH SEAT CO-PILOT 959.30.01.134	MOS					11-JUN-2015		
25.040	887	HRS/MSC	O/C						
	REF: AMM 25-10-05	AFL							
250021	NO. 1 PASSENGER SEAT 959.30.01.617	MOS					11-JUN-2015		
	23910	HRS/MSC	O/C						
	REF:	AFL							
250022	NO. 2 PASSENGER SEAT 959.30.01.618	MOS					11-JUN-2015		
	23911	HRS/MSC	O/C						
	REF:	AFL							
250023	NO. 3 PASSENGER SEAT 959.30.01.633	MOS					11-JUN-2015		
	23912	HRS/MSC	O/C						
	REF:	AFL							



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250024	NO. 4 PASSENGER SEAT 959.30.01.634 23914 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250025	NO. 5 PASSENGER SEAT 959.30.01.641 23913 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250026	NO. 6 PASSENGER SEAT 959.30.01.642 23915 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
251010	PILOT SEAT BACKREST TUBES 959.30.01.134 887 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000			TSN:0 TSN:0 TSN:0	25-NOV-2003 0 0		10000
251015	COPILOT SEAT BACKREST TUBES 959.30.01.133 880 REF:	MOS HRS/MSC AFL	10000			TSN:0 TSN:0 TSN:0	25-NOV-2003 0 0		10000
25JFL00	FIRST AID KIT 70002-00 LOT : W108161 REF:	MOS HRS/MSC AFL	DUE					31-OCT-2021 M	
25JFL02	PERFORMED FIRST AID KIT INSPECTION REF:	MOS HRS/MSC AFL	12	+1m/-1m			10-SEP-2019 8341:10 7583	10-SEP-2020	10-OCT-2020

CHAPTER 26 FIRE PROTECTION



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
26-20/2	COCKPIT FIRE EXTINGUISHER									
26.010	BA51015R-5	MOS	120	TSN:2	-9		13-JUN-2017	04-APR-2027		
LIFE LIMIT	104741	HRS/MSC		TSN:0			7068			
	REF: GENERIC NO REF	AFL		TSN:0			6530			
		ACH								
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348)									
26.010	BA51015R-5	MOS	12	+1m/-1m			12-APR-2019	12-APR-2020	12-MAY-2020	
	104741	HRS/MSC					8034:50			
	REF: GENERIC NO REF	AFL					7322			
260005	FIRE/OVERHEAT DETECTOR									
26.020	975.12.10.012	MOS		TSN:0			25-NOV-2003			
	205163	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
CHAPTER 27 FLIGHT CONTROLS										
+ 27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL						PKG			
	PKG 18	MOS					10-SEP-2019			
	REF:	HRS/MSC	300	+10%/-10%			8341:10			
		AFL					7583			
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES									
		MOS					25-NOV-2003			
	REF: GENERIC NO REF	HRS/MSC	32500				0	32500		
		AFL	42000				0	42000		
+ 27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES									
27.010		MOS	60	+10%/-10%	45		12-APR-2019	27-MAY-2024	27-NOV-2024	
	REF: AMM 27-00-00	HRS/MSC	4800	+10%/-10%	-75:50		8034:50	12759	13239	
		AFL					7322			
+ 27-10/139 (s)	EXAMINE AILERON LH AND RH									
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019			
	REF:	HRS/MSC	300	+10%/-10%			8341:10			
		AFL					7583			



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 PKG 22	MOS	24	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
27-10/394	EXAMINE - AILERON CONTROL SYSTEM	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-10-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-10-09	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-10/444	AILERON FLIGHT CONTROL CABLES	MOS		TSN:0			25-NOV-2003		
LIFE LIMIT	REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0			0 0	20000 27000	
+ 27-10/445	AUTOPILOT CONTROL CABLE	MOS		TSN:0			25-NOV-2003		
LIFE LIMIT	REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0			0 0	20000 27000	
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARING	MOS	12	+10%/-10%			PKG 12-APR-2019		
	PKG 21	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
	REF: AMM 27-10-00								
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999	MOS	24	+10%/-10%			PKG 12-APR-2019		
	PKG 22	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
	REF: See Workcard								
+ 27-20/140 (s)	EXAMINE RUDDER IN PARTICULAR THE COVER PLATE (PART NO. 555.40.12.215) ON THE BOTTOM OF THE RUDDER TO MAKE SURE IT IS NOT BENT AND THERE ARE NO SIGNS OF INTERFERENCE WITH THE RUDDER STOP.	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	PKG 3	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
	REF: AMM 55-40-00								
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS	MOS	24	+10%/-10%			PKG 12-APR-2019		
	PKG 22	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
	REF:								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 27-20/242 (s)	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM. MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF: AMM 20-31-00	AFL					7322		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF: See Workcard	AFL					7322		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF: See Workcard	AFL					7322		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF: AMM 27-25-00	AFL					7322		
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-20-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0 0		32500 42000
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0		32500 42000
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					25-NOV-2003		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				0 0		
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES	MOS					25-NOV-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	TSN:0 TSN:0 TSN:0			0 0 0		20000 27000
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES	MOS					25-NOV-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	TSN:0 TSN:0 TSN:0			0 0 0		20000 27000
+ 27-30/141 (s)	EXAMINE ELEVATORS	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS	MOS	24	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF: AMM 27-30-00	AFL					7322		
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF: AMM 27-30-00	AFL					7322		
27-30/334	CHECK ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR) (REF. 12-A-27-30-00-00A-903A-A)								
		MOS					12-APR-2019		
		HRS/MSC	A/R				8034:50		
	REF: AMM 27-30-00	AFL					7322		
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-30-00	AFL	42000				0		42000
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					25-NOV-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	TSN:0 TSN:0 TSN:0			0 0 0	20000 27000	
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					25-NOV-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	TSN:0 TSN:0 TSN:0			0 0 0	20000 27000	
+ 27-30/450	STICK PUSHER CABLES	MOS					25-NOV-2003		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	TSN:0 TSN:0 TSN:0			0 0 0	20000 27000	
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%			12-APR-2019	20-FEB-2020	26-MAR-2020
27.021 AIRWORTHINESS	REF: AMM 27-40-00	HRS/MSC AFL	3000		-51		8034:50 7322	11034:50	
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES	MOS	12	+10%/-10%			10-SEP-2019		
	REF: AMM 27-40-00	PKG 3 HRS/MSC AFL	300	+10%/-10%			8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/25	PITCH TRIM ACTUATOR								
27.020	978.73.14.203 833 REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:2987:50 TSO:1593:10	7		08-JAN-2019 7972:25 7266		
+ 27-40/252 (s)	INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
OVERHAUL	978.73.14.203 833 REF: AMM 27-40-01	MOS HRS/MSC AFL	84 3400	TSI:1593:10 TSI:1363	-1630		08-JAN-2019 7972:25 7266	23-JUL-2021 9779:15	
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 18 REF: AMM 27-40-00	MOS HRS/MSC AFL	300	+10%/-10%			10-SEP-2019 8341:10 7583		
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 21 REF: AMM 27-40-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
27-40/3	PITCH TRIM ACTUATOR								
27.011 AIRWORTHINESS	978.73.14.203 833 REF: AMM 27-40-01	MOS HRS/MSC AFL	20000 27000	TSN:2987:50 TSO:1593:10			08-JAN-2019 7972:25 7266	26379:15 32903	
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS								
27.036 LIFE LIMIT	PN SN-UNKNOWN REF: AMM 27-40-02	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0	10000	
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION						PKG		
	PKG 17 REF:	MOS HRS/MSC AFL	A/R				12-APR-2019 8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT 978.73.20.003	MOS					25-NOV-2003		
	0215	HRS/MSC	10000	+10%/-10%			0	10000	11000
OVERHAUL	REF:	AFL	13500	+500/-500			0	13500	14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					20-AUG-2013		
27.040	1252	HRS/MSC	5000	+10%/-10%			4975:40	9975:40 M	10475:40
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4343	11343 M	11843
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					20-AUG-2013		
27.040	1250	HRS/MSC	5000	+10%/-10%			4975:40	9975:40 M	10475:40
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4343	11343 M	11843
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					20-AUG-2013		
27.050	1610	HRS/MSC	5000	+10%/-10%			4975:40	9975:40 M	10475:40
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4343	11343 M	11843



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					20-AUG-2013		
OVERHAUL	0269	HRS/MSC	5000	+10%/-10%			4975:40	9975:40 M	10475:40
	REF: AMM 27-50-03	AFL	7000	+500/-500			4343	11343 M	11843
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.205	MOS					25-NOV-2003		
DISCARD	S5295	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.206	MOS					25-NOV-2003		
DISCARD	S5292	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.205	MOS					25-NOV-2003		
DISCARD	S5298	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.206	MOS					25-NOV-2003		
DISCARD	S5277	HRS/MSC	10000	+500/-500	TSN:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	TSN:0		0	13500	14000
27-50/386	EXAMINE - FLAP MECHANISM								
AIRWORTHINESS		MOS					25-NOV-2003		
	REF: AMM 27-51-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
AIRWORTHINESS		MOS					25-NOV-2003		
	REF: AMM 27-51-00	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
AIRWORTHINESS		MOS					25-NOV-2003		
	REF: See Workcard	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS					20-AUG-2013		
27.040	978.73.20.309	HRS/MSC	20000	TSO:3			4975:40	24975:40	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	TSN:4995:30 TSO:0			4343	31343	
27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS					20-AUG-2013		
27.040	978.73.20.309	HRS/MSC	20000	TSO:3			4975:40	24975:40	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	TSN:4995:30 TSO:0			4343	31343	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		TSO:2			20-AUG-2013		
27.050	1610	HRS/MSC	20000	TSN:4588:50 TSO:0			4975:40		24975:40
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	TSN:3990 TSO:0			4343		31343
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		TSO:5			20-AUG-2013		
27.050	0269	HRS/MSC	20000	TSN:3659 TSO:0			4975:40		24975:40
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	TSN:3650 TSO:0			4343		31343
27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		TSN:0			25-NOV-2003		
57.060	435	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	TSN:0			0		30000
27-50/414	RIGHT HAND FLAP								
	557.50.12.004	MOS		TSN:0			25-NOV-2003		
57.060	432	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	TSN:0			0		30000
+ 27-50/437	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS								
		MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%	6:20		8034:50		12-APR-2020
AIRWORTHINESS	REF: AMM 27-51-00	AFL					7322		8641:10
									18-MAY-2020
									8701:10
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 12-20-07	AFL					7583		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		TSN:0			25-NOV-2003		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0		20000
LIFE LIMIT	REF:	AFL	27000	TSN:0			0		27000
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 17	MOS					25-NOV-2003		
		HRS/MSC	A/R				0		
	REF:	AFL					0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	945.02.02.205 S5295 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	945.02.02.206 S5292 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.205 S5298 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.206 S5277 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		
+ 27-50/73 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR (WHITE COLORED)						PKG		
27.040	978.73.20.309 PKG 3 1252 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8241:10 7583		
+ 27-50/73 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED)						PKG		
27.040	978.73.20.309 PKG 3 1250 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8241:10 7583		
+ 27-50/73 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED)						PKG		
27.050	978.73.20.309 PKG 3 1610 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8241:10 7583		
+ 27-50/73 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED)						PKG		
27.050	978.73.20.309 PKG 3 0269 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8241:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 1252 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583	10-SEP-2020 8634:50	16-OCT-2020 8664:50
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 1250 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583	10-SEP-2020 8634:50	16-OCT-2020 8664:50
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 1610 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583	10-SEP-2020 8634:50	16-OCT-2020 8664:50
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 0269 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-SEP-2019 8341:10 7583	10-SEP-2020 8634:50	16-OCT-2020 8664:50
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 1252 REF:	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			12-APR-2019 8034:50 7322	20-FEB-2021 10434:50 10522	02-MAY-2021 10674:50 10842
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 1250 REF:	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			12-APR-2019 8034:50 7322	20-FEB-2021 10434:50 10522	02-MAY-2021 10674:50 10842
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 1610 REF:	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			12-APR-2019 8034:50 7322	12-APR-2021 10434:50 10522	24-JUN-2021 10674:50 10842
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0269 REF:	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			12-APR-2019 8034:50 7322	20-FEB-2021 10434:50 10522	02-MAY-2021 10674:50 10842



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/77	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013)								
27.080	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-NOV-2003 0 0		
270003	HORIZONTAL TAIL ASSY 555.10.12.037 438 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270015	ELEVATOR LH ASSY 555.20.12.039 442 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270023	ELEVATOR RH ASSY 555.20.12.040 442 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR 978.73.18.132 590 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270033	RUDDER ASSY 555.40.12.038 443 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270035	FLAP CONTROL AND WARNING (FCWU) UNIT 978.73.20.016 113648 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C				08-DEC-2017 7393:20 6781		
270045	LH INBOARD TRANSMITTER 978.73.20.021 035009DZ REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270050	LH ROTATION TRANSMITTER								
27.120	978.73.20.602 0351 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 035006DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	978.73.20.021 035012DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	978.73.20.602 0342 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	978.73.18.132 638 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 035018DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m		-19	12-APR-2019 8034:50 7322	24-MAR-2021	24-APR-2021
CHAPTER 28	FUEL								
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS HRS/MSC AFL	12	+10%/-10%			10-SEP-2019 8341:10 7583		
	REF:		300	+10%/-10%					



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
	REF:	AFL	300	+10%/-10%			7583		
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE	MOS					08-JUN-2018		
28.029	REF: AMM 28-10-01	HRS/MSC	2400	+10%/-10%	29:02		7631:10 6963	10060:12	10300:12
		AFL							
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR	MOS	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
	REF: AMM 28-20-07	HRS/MSC	300	+10%/-10%			7583		
		AFL							
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT	MOS	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
	REF: See Workcard	HRS/MSC	300	+10%/-10%			7583		
		AFL							
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N)	MOS	12	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF:	HRS/MSC	600	+10%/-10%			7322		
		AFL							
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP	MOS	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
	REF:	HRS/MSC	300	+10%/-10%			7583		
		AFL							
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED	MOS	24	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF:	HRS/MSC	2400	+10%/-10%			7322		
		AFL							
28-20/32	ACCESSORY GEARBOX FUEL PUMP	MOS					04-APR-2017		
28.010	968.84.51.108	HRS/MSC	3500	+10%/-10%	TSO:0	78:56	6923	10501:56	10851:56
OVERHAUL	B5734	AFL			TSO:3420:30		6422		
	REF: AMM 28-20-03				TSO:0				



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM								
28.020		MOS	48	+10%/-10%			25-JUL-2018	25-JUL-2022	19-DEC-2022
	REF: See Workcard	HRS/MSC	1200	+10%/-10%	-6.45		7777:25	8970:40	9090:40
		AFL					7092		
280005	LOW PRESSURE FUEL PUMP								
28.120	968.84.51.108	MOS		TSN:0			25-NOV-2003		
	B4494	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
280010	FUEL FLOW TRANSMITTER								
28.130	975.35.12.602	MOS		TSN:0			25-NOV-2003		
	2453	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	963.87.22.301	MOS		TSN:0			25-NOV-2003		
	1300	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-08	AFL		TSN:0			0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	963.87.22.301	MOS		TSN:0			25-NOV-2003		
	1304	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-08	AFL		TSN:0			0		
280025	FUEL FILTER ASSY								
28.025	968.35.21.001	MOS		TSN:0			25-NOV-2003		
	439	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-01	AFL		TSN:0			0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	973.81.14.102	MOS		TSN:0			25-NOV-2003		
	1027	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-02	AFL		TSN:0			0		
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104	MOS		TSN:0			25-NOV-2003		
	B2972	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-05	AFL		TSN:0			0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3323 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 877 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 887 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 879 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 875 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B5691 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2971 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3297 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280080	FUEL QUANTITY, COLLECTOR SENSOR								
28.080	975.37.31.234 886 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280085	FUEL QUANTITY, INNER SENSOR								
28.090	975.37.31.233 887 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280090	FUEL QUANTITY, CENTRAL SENSOR								
28.070	975.37.31.232 884 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280095	FUEL QUANTITY, OUTER SENSOR								
28.060	975.37.31.231 875 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
280100	RIGHT WING FUEL, BOOSTER PUMP								
28.050	968.84.11.405 B5692 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		

CHAPTER 29 HYDRAULIC POWER

+ 29-10/151 (s)	RETURN LINE FILTER DIERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF: AMM 29-10-04	AFL					7322		
+ 29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: See Workcard	AFL					7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY. PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%					
+ 29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
+ 29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF: AMM 29-10-02	HRS/MSC AFL	1200	+10%/-10%					
+ 29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
29-10/418	NITROGEN ACCUMULATOR 960.30.01.291	MOS			TSN:0		25-NOV-2003		
29.020	0451	HRS/MSC	25000		TSN:0		0	25000	
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000		TSN:0		0	30000	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS					25-NOV-2003		
	REF:	HRS/MSC AFL	N/A				0 0		
290005	LANDING GEAR STEER SELECTOR VALVE 996.43.70.847	MOS					18-OCT-2013		
29.040	0826AB	HRS/MSC	O/C				5048:55		
	REF: GENERIC NO REF	AFL					4430		
290015	PRESSURE GAGE SWITCH 973.81.14.307	MOS					18-OCT-2013		
29.050	0586	HRS/MSC	O/C				5048:55		
	REF: GENERIC NO REF	AFL					4430		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290025	SERVICE SELECTOR VALVE								
29.070	960.30.01.261 G0320225A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
290030	PRESSURE GAUGE								
29.080	965.61.88.101 8-0923143 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-DEC-2008 2998:51 2404	08-FEB-2036 M	
290035	(K 601) RELAY								
29.090	974.09.26.112 R188 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-JUN-2016 6476:30 5976		
290040	HAND PUMP								
29.030	529.21.12.021 446 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	973.81.14.306 0538 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
291010	HYDRAULIC POWER PACK								
29.010	960.30.01.154 G0330709 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS -								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	+6m/-6m	TSN:0		01-MAR-2018 7468:45 6839	01-MAR-2023	01-SEP-2023

CHAPTER	30	ICE AND RAIN PROTECTION
+	30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS
	PKG 3	MOS 12 +10%/-10%
		HRS/MSC 300 +10%/-10%
	REF: AMM 30-10-00	AFL
		PKG
		10-SEP-2019
		8341:10
		7583



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999 PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: AMM 30-10-00	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
30-10/79 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING REF: GENERIC NO REF	MOS	6	+10%/-10%	18		10-SEP-2019 8341:10 7563	28-MAR-2020	15-APR-2020
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 22	MOS	24	+10%/-10%			PKG 12-APR-2019		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: AMM 30-60-00	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: AMM 30-60-00	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
300005	PROP DE-ICE TIMER/ CONTROLLER 4E3163-2	MOS					05-NOV-2018		
30.140	U0610 REF: AMM 30-60-01	HRS/MSC AFL	O/C				7934:50 7236		
300010	LPMI LINEAR ACTUATOR 978.73.15.302	MOS					20-SEP-2016		
30.150	D62800 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			6653:40 6122		
300015	REGULATOR-RELIEVER ASSY 959.89.01.012	MOS					25-NOV-2003		
30.160	N0550 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
300020	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS					25-NOV-2003		
30.110	N2279 REF: AMM 30-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
300025	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS					25-NOV-2003		
30.120	N2280 REF: AMM 30-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
300030	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS					25-NOV-2003		
30.110	N2414 REF: AMM 30-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS					25-NOV-2003		
30.120	N2407 REF: AMM 30-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	959.89.01.008 N2401 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	973.81.14.312 7934 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:13 TSN:0 TSN:0			07-MAR-2017 6902:35 6409		
300050	WATER SEPARATOR								
30.060	959.89.01.010 B1361 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.014 U3701 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C				07-FEB-2019 7992:20 7282		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114048 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114050 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 6195 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-FEB-2012 4134:41 3546		
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 2097 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2120 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2128 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.026 NCW3110 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2016 6351:35 5782		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	27S-7D5221-14 NAS3890 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-2013 4631:05 4007		
300100	RH INBD-WING DE-ICER BOOT								
30.040	959.89.01.023 NCJ9160 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2015 5770:40 5215		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.025 NCY1800 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2016 6351:35 5782		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.022 NCB2490 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2015 5770:40 5215		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.033 MCGN290 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JUL-2010 3517:06 2915		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"	MOS					10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%		-6:20	8341:10 7563	8634:50	8664:50
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-50/34	CAWS & CACU CLOCK BATTERY								
	9728132050	MOS	24	+10%/-10%	TSN:0	22	01-MAR-2018	23-MAR-2020	04-JUN-2020
31.010	SN-UNKNOWN	HRS/MSC			TSN:0		7468:45		
DISCARD	REF: AMM 31-50-03	AFL			TSN:0		6839		
310020	FLAP POSITION INDICATOR								
	975.44.16.203	MOS			TSN:0		25-NOV-2003		
31.090	00406	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
310035	CAWS COMPUTER								
	4802	MOS					01-MAR-2018		
31.050	139	HRS/MSC	O/C				7468:45		
	REF: See Workcard	AFL					6839		
310040	CAWS DISPLAY								
	972.81.31.031	MOS					16-DEC-2009		
31.060	143	HRS/MSC	O/C				3316:31		
	REF: AMM 31-50-02	AFL					2706		
310050	DIGITAL CLOCK								
	999.61.11.212	MOS			TSN:0		25-NOV-2003		
31.040	1014409	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
CHAPTER 32 LANDING GEAR									
+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF: AMM 12-20-04	AFL					7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 32-10/264	REMOVE MAIN LANDING GEAR LEFT AND RIGHT AXLE BOLT (PRE SB 32-006) AND EXAMINE. REPLACE IF DAMAGED. INSTALL A SERVICEABLE BOLT.	MOS					25-NOV-2003		
	REF:	HRS/MSC AFL	N/A				0 0		
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING	MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING	MOS					25-NOV-2003		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK	MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS					25-NOV-2003		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
32-10/436	REMOVE/CLEAN MLG SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS. EXAMINE FOR CORROSION. IF CORRODED, REPLACE BOLT WITH LATEST BOLT PART NUMBER. IF NOT CORRODED, APPLY GREASE P04-028 AND INSTALL THE BOLT.	MOS	12	+10%/-10%			12-APR-2019	12-APR-2020	18-MAY-2020
	REF: AMM 32-10-00	HRS/MSC					8034:50		
		AFL					7322		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				23-MAR-2016	23-MAR-2022	
	REF: AMM 32-10-00	HRS/MSC					6351:35		
		AFL					5782		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				23-MAR-2016	23-MAR-2022	
	REF: AMM 32-10-00	HRS/MSC					6351:35		
		AFL					5782		
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%			12-APR-2019	20-FEB-2020	26-MAR-2020
32.030	REF: AMM 12-20-06	HRS/MSC	T/C		-51		8034:50		
		AFL					7322		
+ 32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES	MOS	12	+1m/-1m			12-APR-2019	20-FEB-2020	20-MAR-2020
32.010	REF: AMM 32-10-00	HRS/MSC	2400	+10%/-10%	-51		8034:50	10434:50	10674:50
		AFL					7322		
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
	REF: AMM 32-20-00	HRS/MSC	600	+10%/-10%			8034:50		
		AFL					7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 20 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 32-20/266	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE REF: See Workcard	MOS HRS/MSC AFL	N/A				04-APR-2017 6351:35 5782		
+ 32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 532.50.12.064 SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-OCT-2013 5048:55 4430		
32-20/403	NOSE LANDING GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000		TSN:0 TSN:0 TSN:0		25-NOV-2003 0 0	25000 30000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/416	NOSE LANDING GEAR DRAG LINK								
	PN	MOS		TSN:0			25-NOV-2003		
	SN-UNKNOWN	HRS/MSC	25000	TSN:0			0		25000
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	TSN:0			0		30000
32-20/5	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
	532.20.12.296	MOS		TSN:0			25-NOV-2003		
32.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-20-05	AFL		TSN:0			0		
+ 32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF: AMM 32-30-00	AFL					7322		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
	9603001105	MOS					12-APR-2019		
32.040	1695H	HRS/MSC	25000	TSN:5017:55			8034:50		28016:55
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	TSN:3712			7322		33610
		ACH							
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
	9603001105	MOS					12-APR-2019		
32.040	1625H	HRS/MSC	25000	TSN:4876			8034:50		28158:50
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	TSN:4239			7322		33083
		ACH							
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				23-MAR-2016		23-MAR-2022
		HRS/MSC					6351:35		
	REF: AMM 32-10-00	AFL					5782		
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				23-MAR-2016		23-MAR-2022
		HRS/MSC					6351:35		
	REF: AMM 32-10-00	AFL					5782		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 12-10-04	AFL					7583		
+ 32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 12-10-04	AFL					7583		
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF:	AFL					7583		
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 12-10-02	AFL					7583		
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
	REF: AMM 32-50-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 3618 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 3619 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320015	PARK BRAKE VALVE								
32.140	959.47.51.121 2161 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320020	NOSE WHEEL								
32.150	3-1501 1111 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				25-JUL-2018 7777:25 7092		
320021	NOSE LANDING GEAR TIRE								
32.155	021-327-0 7283S00176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2018 7777:25 7092		
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.160	3-1543-1 1084 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				12-APR-2019 8034:50 7322		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	0-25-350-0 4350S00226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-2018 7631:10 6963		
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.165	3-1543-1 1604 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				29-MAY-2019 8094:35 7371		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320025	SHIMMY DAMPER ASSY 532.20.12.215 AM-032 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:1139:54			10-AUG-2010 3537:06 2931		
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 8087S00307 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAY-2019 8094:35 7371		
320030	COPILOT LH BRAKE MASTER CYLINDER 959.47.51.131 3621 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 959.47.51.131 3620 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY 532.20.12.249 VLG068 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320045	NOSE LANDING GEAR STRUT ASSY 532.20.12.038 VLG068 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320050	LEFT SHOCK ABSORBER ASSY 532.10.12.175 VLG139 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320055	RIGHT SHOCK ABSORBER ASSY 532.10.12.175 VLG140 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320065	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.049 VLG068 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320070	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.050 VLG068 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
320074	NOSE LANDING GEAR ACTUATOR								
29.060	9603001111 1561A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C				12-APR-2019 8034:50 7322		
320075	LH BRAKE ASSY								
32.050	2-1674-1 0087 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-APR-2017 6923 6422		
320080	RH BRAKE ASSY								
32.050	2-1674-1 0035 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-SEP-2019 8341:10 7583		

CHAPTER 33		LIGHTS							
+ 33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING							PKG	
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: See Workcard	AFL					7583		
+ 33-41/178 (s)	EXAMINE LANDING LIGHTS							PKG	
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 33-41-01	AFL					7583		
+ 33-42/179 (s)	EXAMINE TAXI LIGHTS							PKG	
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF: AMM 33-42-01	AFL					7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
330005	DIM UNIT 975.02.15.205	MOS					25-NOV-2003		
33.080	113499 REF: AMM 33-10-04	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
330010	DE-ICE LIGHT ASSY 972.87.67.111	MOS					25-NOV-2003		
33.010	379777 REF: AMM 33-40-11	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
330015	LEFT WING POWER SUPPLY, HIDL UNIT 972.78.55.627	MOS					15-JUN-2010		
33.020	SN-UNKNOWN REF: AMM 33-40-11	HRS/MSC AFL	O/C				3479:26 2878		
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 972.87.69.413	MOS					25-NOV-2003		
33.020	371691 REF: AMM 33-40-11	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 34-0226010-91	MOS					19-JUN-2012		
33.040	N/A REF: AMM 33-46-01	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		4325:31 3750		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	972.87.87.332 14501 REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
330035	LH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 21176 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 27003 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			18-OCT-2011 4041:21 3438		
330045	RH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 19386 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C				26-JUN-2008 2760 2218		
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 26227006 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-MAY-2013 4842:10 4211		
330055	NAVIGATION (FC), BULB GREEN LIGHT								
33.050	972.87.87.128 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-DEC-2013 5155 45965		
330060	NAVIGATION (FC), BULB RED LIGHT								
33.050	A7512-24 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2014 5369:40 4784		
330065	NAVIGATION (FC), BULB WHITE LIGHT								
33.060	2LA001625-00 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAR-2014 5240:50 4662		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330070	NOSE LANDING GEAR TAXI LIGHT, 1X0005287-10 03-4400-1000 30111001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSO:4 TSO:0 TSO:0			13-JUN-2017 7068 6530		
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10 9728769420 29190003 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2015 6211:15 5669		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10 03-4303-1000 29153007 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			01-MAR-2018 7468:45 6839		
33JFL01	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00-00A-903A-A) REF:	MOS HRS/MSC AFL	300	+10%/-10%			10-SEP-2019 8341:10 7563	8641:10	8671:10
CHAPTER 34	NAVIGATION								
+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 22 REF:	MOS HRS/MSC AFL	24	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%					
34-11/82	LEAK CHECK STATIC SYSTEM (DAC-AIR 348)	MOS	24	+10%/-10%		-83	01-MAR-2018 7468:45 6839	08-DEC-2019	19-FEB-2020
34.010	REF: See Workcard	HRS/MSC AFL							
34-14/83	CALIBRATION CHECK ALTIMETER (DAC-AIR 348)	MOS	24	+10%/-10%		-83	01-MAR-2018 7468:45 6839	08-DEC-2019	19-FEB-2020
34.020	REF: See Workcard	HRS/MSC AFL							
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348)	MOS	24	+10%/-10%		45	12-APR-2019 8034:50 7322	27-MAY-2021	08-AUG-2021
34.030	REF: AMM 34-21-00	HRS/MSC AFL							
34-25/85	CALIBRATION ATTITUDE HEADING REFERENCE SYSTEM (AHRS) CHECK SWING	MOS	24	+10%/-10%		61	12-APR-2019 8034:50 7322	12-JUN-2021	24-AUG-2021
34.040	REF: AMM 34-25-00	HRS/MSC AFL							
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348)	MOS	24	+10%/-10%		-83	01-MAR-2018 7468:45 6839	08-DEC-2019	19-FEB-2020
34.050	REF: See Workcard	HRS/MSC AFL							
340005	PILOT ALTIMETER	MOS					10-JAN-2012		
31.020	70256N01D01 04040267DB REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSR:7 TSR:0 TSR:0		4120:26 3533		
340006	COPILOT ALTIMETER	MOS					25-NOV-2003		
	70256N02D01 03050173BA REF: AMM 34-14-12	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340007	NO. 1 TRANSPONDER								
34.140	011-00455-10 84206661 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-OCT-2018 7907:45 7210		
340007	NO. 2 ATC MODE A/C/S,KT70 SC+ TRANSPONDER								
	011-00455-10 84206714 REF:	MOS HRS/MSC AFL	O/C				12-OCT-2018 7907:45 7210		
340009	NO. 1 DME/IFF ANTENNA								
34.080	984.81.10.240 61464 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340010	PILOT VERTICAL SPEED INDICATOR								
31.070	7040C.110 304982 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-FEB-2015 5770:40 5215		
340015	PILOT ATTITUDE INDICATOR								
31.080	975.96.11.241 5184 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			22-APR-2009 3103:21 2503		
340020	MARKER ANTENNA								
34.100	984.81.10.260 5622 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340025	EFIS 1 SG465 SYMBOL GENERATOR								
34.300	975.96.32.402 5255 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340026	STAND-BY ALTIMETER								
31.020	5934PAD-3 430210 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				04-MAR-2008 2555:36 2006		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340030	COPILOT VERTICAL SPEED INDICATOR 9651615101 276879 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-OCT-2013 5051:40 4441		
340034	EFIS 1 CONTROL,CP467 PANEL 071-01439-3100 U1653 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C				24-OCT-2016 6728:10 6174		
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY 066-03137-3100 5421 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-AUG-2016 6596:10 6079		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY 066-03137-3100 4030 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				09-MAY-2012 4254:16 3691		
340044	TRIM TRIPLE INDICATOR 975.44.16.204 00537 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:2394 TSN:1952			23-JUL-2008		
340055	PILOT AIRSPEED INDICATOR 965.12.13.334 1024030 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340059	WITH HARM FILTER,KN63 DME 985.99.11.101 27866 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340060	COPILOT AIRSPEED INDICATOR 965.12.13.335 1023762 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 ART2000-13489 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-DEC-2017 7393:20 6781		
340070	RADAR CONTROL PANEL								
34.240	985.99.11.518 2436 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	985.99.11.504 3399 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340080	NO. 2 TRANSPONDER								
34.080	984.81.10.240 61467 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340085	ADF,KA44B ANTENNA								
34.070	985.99.11.167 79586 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340090	GPS BRNAV,KLN90B UNIT								
34.340	985.99.11.199 40453 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	975.96.32.482 12386 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340100	FRONT KA92 GPS ANTENNA								
34.090	985.99.11.193 48619 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340101	REAR KA92 GPS ANTENNA								
34.090	071-01553-0200 334074 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUN-2011 3872:01 3259		
340105	LH NAV/GS ANTENNA								
34.380	984.81.10.280 4767/4766 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	985.99.11.823 3818 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	124210-2022 1683 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				04-APR-2017 6923 6422		
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	066-3034-02 57837 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C				13-FEB-2015 5770:40 5215		
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	985.99.11.771 10928 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340130	AIR DATA COMPUTER								
34.400	985.92.03.111 2356 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	985.99.11.865 11311 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340135	MAGNETIC,STANDBY COMPASS								
34.130	999.98.80.103 AT-480 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340140	4206-100-V2 RADOME								
34.420	985.79.00.003 1055 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			28-OCT-2009 3300:11		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 3413 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27897 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27882 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 09616 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 09610 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340165	DATA BASE,ATLANTIC,KLN90 UNIT								
34.440	985.99.11.224 42772 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	985.99.11.570 3775 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-14 70951 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C				18-AUG-2017 7213:35 6645		
340195	MULTI FUNCTION DISPLAY								
34.190	066-04035-0101 5288 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C				28-SEP-2018 7891:10 7197		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	985.90.03.045 3261 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	071-00158-0211 3095 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-SEP-2018 7891:10 7197		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	985.90.03.046 2885 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 1448 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				25-MAY-2012 4273:46 3710		
340230	RH NAV/GS ANTENNA								
34.380	984.81.10.280 4767/4766 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340235	AOA SENSOR RH UNIT 0012AC12 0839 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				08-DEC-2017 7393:20 6781		
340240	NO. 1 FLUX,KMT112 VALVE 985.99.11.064 67456 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT 985.99.11.505 11458 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE 975.11.20.111 1118 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340255	AOA SENSOR LH UNIT 012AC11 1933 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			10-SEP-2019 8341:10 7583		
340260	NO. 2 FLUX,KMT112 VALVE 985.99.11.064 67449 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340280	LEFT PITOT TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
340285	RIGHT PITOT TUBE PST305 AS02179215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2019 7994:35 7285		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341005	LH AOA PLATE TEMP CONTROLLER 975.44.21.417 U1030 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
341010	RH AOA PLATE TEMP CONTROLLER 975.44.21.417 U1028 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
345015	HORIZON ARTIFICIAL 504-0111-930 504011193025114 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-JUN-2014 5335:25 4753		
34C044	GYRO,DIRECTIONAL,KG102A 060-0015-00 33466 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-FEB-2015 5793:50 5231		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m	22		01-MAR-2018 7468:45 6839	23-MAR-2020	23-APR-2020
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM) REF:	MOS HRS/MSC AFL	12				10-APR-2019	10-APR-2020	
CHAPTER 35	OXYGEN								
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			10-SEP-2019 8341:10 7583		
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 18 REF:	MOS HRS/MSC AFL	300	+10%/-10%			10-SEP-2019 8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF:								
+ 35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
	REF: AMM 35-00-00								
35-10/6	OXYGEN BOTTLE 957.12.12.212 C13080253	MOS HRS/MSC AFL	180			-66	22-DEC-2018 7968:25 7262	22-JUN-2028	
35.010	AIRWORTHINESS			TSO:0 TSO:0 TSO:0					
	REF: AMM 35-10-01								
35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE 957.12.12.212 C13080253	MOS HRS/MSC AFL	60				10-AUG-2018	10-AUG-2023	
35.010	REF: GENERIC NO REF								
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS HRS/MSC AFL	36	+10%/-10%		-20	12-APR-2019 8034:50 7322	23-MAR-2022	11-JUL-2022
35.010	REF: AMM 35-20-00								
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B001404	MOS HRS/MSC AFL	O/C				09-NOV-2016 6750:20 6225		
35.040	REF: GENERIC NO REF			TSR:14 TSR:0 TSR:0					
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B094696	MOS HRS/MSC AFL	O/C				30-JUL-2019 8257:55 7515		
35.040	REF: GENERIC NO REF								
350030	PRESSURE,GAGE,OXYGEN SWITCH 973.81.14.401 0436	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		
35.050	REF: GENERIC NO REF			TSN:0 TSN:0 TSN:0					



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350035	3-POSITION CONTROL VALVE									
35.030	963.32.11.101 1799 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0			
350040	ALTITUDE SENSING SWITCH									
35.020	973.81.52.102 0585 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0			
CHAPTER 52 DOORS										
+ 52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG			
	PKG 20	MOS	12	+10%/-10%			12-APR-2019			
		HRS/MSC	600	+10%/-10%			8034:50			
	REF:	AFL					7322			
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG			
	PKG 20	MOS	12	+10%/-10%			12-APR-2019			
		HRS/MSC	600	+10%/-10%			8034:50			
	REF:	AFL					7322			
+ 52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG			
	PKG 20	MOS	12	+10%/-10%			12-APR-2019			
		HRS/MSC	600	+10%/-10%			8034:50			
	REF:	AFL					7322			
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG			
	PKG 20	MOS	12	+10%/-10%			12-APR-2019			
		HRS/MSC	600	+10%/-10%			8034:50			
	REF:	AFL					7322			
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG			
	PKG 21	MOS	12	+10%/-10%			12-APR-2019			
		HRS/MSC	1200	+10%/-10%			8034:50			
	REF:	AFL					7322			
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR									
		MOS					25-NOV-2003			
		HRS/MSC	32500				0		32500	
AIRWORTHINESS	REF: AMM 52-10-00	AFL	42000				0		42000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE	MOS					25-NOV-2003		
	REF: AMM 52-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN	MOS					25-NOV-2003		
	REF: AMM 52-10-01	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 52-10/472	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE	MOS					25-NOV-2003		
	REF:	HRS/MSC	N/A				0		
		AFL					0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%	-83		01-MAR-2018	08-DEC-2021	02-MAY-2022
52.010	REF: See Workcard	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)	MOS	12	+10%/-10%			PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			12-APR-2019		
	REF:	AFL					8034:50		
							7322		
+ 52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK	MOS	12	+10%/-10%			PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			12-APR-2019		
	REF:	AFL					8034:50		
							7322		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 52-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK	MOS	12	+10%/-10%			PKG		
	PKG 20	HRS/MSC	600	+10%/-10%			12-APR-2019		
	REF:	AFL					8034:50		
							7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF: AMM 52-30-00	AFL					7322		
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	600	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000				0		42000
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
	REF: See Workcard	AFL	42000				0		42000
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN								
		MOS					25-NOV-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 52-30-01	AFL	30000				0		30000
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS		TSN:0			25-NOV-2003		
52.020	SN-UNKNOWN	HRS/MSC	13000	TSN:0			0		13000
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000	TSN:0			0		17000
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED.								
		MOS	48	+10%/-10%	-83		01-MAR-2018	08-DEC-2021	02-MAY-2022
52.030		HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
	REF: See Workcard	AFL					6839		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF: AMM 52-70-00	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
520005	PASSENGER DOOR 525.05.12.007	MOS		TSN:0			25-NOV-2003		
52.050	433 REF: AMM 52-10-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
520010	FREIGHT OF 10SERIE DOOR ASSY 552.05.12.010	MOS		TSN:0			25-NOV-2003		
52.040	433 REF: AMM 52-30-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
520015	EMERGENGY 6 SERIE EXIT 552.05.12.009	MOS		TSN:0			25-NOV-2003		
52.060	433 REF: AMM 52-20-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
CHAPTER 53 FUSELAGE									
+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS. PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD PKG 22	MOS	24	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED PKG 21	MOS	12	+10%/-10%			PKG 12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					25-NOV-2003		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF:	AFL					0		
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF: AMM 53-20-02	AFL					7322		
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: See Workcard	AFL	42000				0		42000
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000				0		42000
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36								
		MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-20-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	28300 37000				0 0	28300 37000	
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	
53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE								
53.010		MOS					25-NOV-2003		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030		MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040		MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF:	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
CHAPTER 55	STABILIZERS								
270030	FIN ASSY								
	555.30.12.037	MOS					25-NOV-2003		
	433	HRS/MSC	O/C				0		
	REF: AMM 55-30-01	AFL					0		
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (
		MOS					25-NOV-2003		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)	MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC AFL	N/A				0 0		
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	PKG 3	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
	REF:								
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT	MOS	12	+10%/-10%			PKG 12-APR-2019		
	PKG 21	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
	REF: AMM 55-00-00								
55-10/415	HORIZONTAL STABILIZER	MOS					25-NOV-2003		
	PN	HRS/MSC	25000		TSN:0		0		25000
LIFE LIMIT	REF: AMM 55-10-01	AFL	30000		TSN:0		0		30000
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
		HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
	REF: GENERIC NO REF	AFL					6839		
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
		HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
	REF: AMM 53-10-16	AFL					6839		
55-20/362	EXAMINE LEFT ELEVATOR	MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-00	AFL	42000				0		42000
+ 55-20/362	EXAMINE RIGHT ELEVATOR	MOS					25-NOV-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/368	EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 55-30/199 (s)	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/373	EXAMINE - RUDDER	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
CHAPTER 56	WINDOWS								
+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
+ 56-11/12	REPLACE COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS								
	PN	MOS			TSN:0		25-NOV-2003		
56.020	SN-UNKNOWN	HRS/MSC	A/R		TSN:0		0		
AIRWORTHINESS	REF: AMM 56-20-01	AFL			TSN:0		0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-11/13	REPLACE COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110109 16060H3303 REF:	MOS HRS/MSC AFL	A/R				15-AUG-2016 6596:10 6079		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 959.81.10.110 15105H9325 REF:	MOS HRS/MSC AFL	A/R				23-MAR-2016 6351:35 5782		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 16060H3303 REF:	MOS HRS/MSC AFL	A/R				15-AUG-2016 6596:10 6079		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 959.81.10.110 15105H9325 REF:	MOS HRS/MSC AFL	A/R				23-MAR-2016 6351:35 5782		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500			20-FEB-2014 5193:35 4621	20-FEB-2024 16193:35	20-AUG-2024 16693:35
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS REF: See Workcard	MOS HRS/MSC AFL	32500 42000				25-NOV-2003 0 0	32500 42000	
AIRWORTHINESS									



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 3 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
560015 56.090	SIDE,LH WINDOW 959.81.10.111 03043H6225 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560020 56.090	SIDE,RH WINDOW 959.81.10.112 03044H6317 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560025 56.060	RH NO 1 CABIN WINDOW 556.20.12.029 3538 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560030 56.060	RH NO 2 CABIN WINDOW 556.20.12.029 3539 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560035 56.070	RH NO 3 CABIN WINDOW 556.20.12.029 3540 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560040 56.070	RH NO 4 CABIN WINDOW 556.20.12.029 3542 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560045 56.080	RH NO 5 CABIN WINDOW 556.20.12.029 3543 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560050	LH NO 1 CABIN WINDOW								
56.040	556.20.12.029 3544 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	556.20.12.029 3567 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	556.20.12.029 3592 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	556.20.12.029 3611 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
560070	DV-WINDOW ASSY								
56.030	556.14.12.091 03113H2510 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	9598110109 16060H3303 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-AUG-2016 6596:10 6079		
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	959.81.10.110 15105H9325 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2016 6351:35 5782		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				25-NOV-2003 0 0	20000 27000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					25-NOV-2003		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
		HRS/MSC	300	+10%/-10%			8341:10		
	REF:	AFL					7583		
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
		HRS/MSC	2400	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
		HRS/MSC	1200	+10%/-10%			8034:50		
	REF:	AFL					7322		
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)								
		MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)								
		MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING								
		MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0		30000
		AFL	39000				0		39000



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC AFL	30000 39000				0 0	30000 39000	
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC AFL	25000 30000				0 0	25000 30000	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/412	EXAMINE WING TIPS	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-33-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					25-NOV-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	16000 22500				0 0	16000 22500	
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-NOV-2003		
AIRWORTHINESS	REF:	HRS/MSC AFL	16000 22500				0 0	16000 22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		-83	01-MAR-2018	08-DEC-2021	02-MAY-2022
57.020	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			7468:45 6839	11468:45	11868:45



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%			01-MAR-2018	08-DEC-2021	02-MAY-2022
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			7468:45	11468:45	11868:45
		AFL					6839		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040		MOS	120	+6m/-6m			20-FEB-2014	25-NOV-2023	25-MAY-2024
	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			5193:35	16193:35	16693:35
		AFL					4621		
57-60/393	EXAMINE LEFT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS					25-NOV-2003		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 57-60/393	EXAMINE RIGHT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS					25-NOV-2003		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/411	EXAMINE AILERON TRIM TAB								
	REF: AMM 57-60-04	MOS					25-NOV-2003		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
570010	AILERON RH 10A SERIE ASSY								
57.050	557.05.12.011	MOS					25-NOV-2003		
	444	HRS/MSC	O/C				0		
	REF: AMM 57-60-01	AFL					0		
							TSN:0		
							TSN:0		
							TSN:0		
570015	WING RE 10A SERIE STRUCTURE								
57.070	557.05.12.127	MOS					25-NOV-2003		
	438	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
							TSN:0		
							TSN:0		
							TSN:0		
570025	AILERON LH 10A SERIE ASSY								
57.050	557.05.12.012	MOS					25-NOV-2003		
	444	HRS/MSC	O/C				0		
	REF: AMM 57-60-01	AFL					0		
							TSN:0		
							TSN:0		
							TSN:0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570035	WING LE 10A SERIE STRUCTURE								
57.070	557.05.12.128 438 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
CHAPTER 61 PROPELLERS/PROPULSORS									
+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E4A-3D/E10477SK KX1077 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C	TSN:2818:50			02-MAR-2018 7468:45 6839		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
OVERHAUL	8210-137 13573112 REF: See Workcard	MOS HRS/MSC ENC	3500	+500	TSO:0 TSO:0 TSO:0	-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
OVERHAUL	210949 13557052 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	TSO:0 TSO:0 TSO:0	-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1077 Part # HC-E4A-3D/E10477SK									
+ 610010	NO. 1 PROPELLER - OVERHAUL								
OVERHAUL	TRACKED ITEM	MOS HRS/MSC	72 4000				01-MAR-2018 2818:50	01-MAR-2024 (6818:50) 11468:45	
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION								
	REF:	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			10-SEP-2019 3691:15	10-SEP-2020 (3991:15) 8641:10	10-OCT-2020 4021:15



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER REF:	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%		-6:20	10-SEP-2019 3691:15	10-SEP-2020 (3984:55) 8634:50	10-OCT-2020 4014:55
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE 9682913023 L20946 REF: GENERIC NO REF	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-AUG-2012 0		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE 9682913023 L20938 REF: GENERIC NO REF	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-AUG-2012 0		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE 9682913023 L20939 REF: GENERIC NO REF	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-AUG-2012 0		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913023 L20944 REF: GENERIC NO REF	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-AUG-2012 0		
CHAPTER 71 POWER PLANT									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			12-APR-2019 8034:50 7322		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH								
71.040	REF:	MOS HRS/MSC AFL	300				10-SEP-2019 8341:10 7583	8641:10	



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/106	CLEAN OIL PRESSURE TRANSDUCER ELECTRICAL CONNECTOR								
71.020	REF: AMM 71-00-03	MOS HRS/MSC AFL	A/R				29-OCT-2009 3300:11 2690		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS								
71.030	PKG 20 REF: AMM 71-00-03	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	571.20.12.036 438 REF: AMM 71-00-05	MOS HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0	20000 27000	
AIRWORTHINESS									
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS								
71.050	REF: AMM 71-00-04	MOS HRS/MSC AFL	11000				25-NOV-2003 0 0	11000	
AIRWORTHINESS									
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION								
	PKG 17 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 12-APR-2019 8034:50 7322		
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP								
	PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)								
	PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT						PKG		
	PKG 17	MOS					12-APR-2019		
	REF: AMM 71-00-00	HRS/MSC AFL	A/R				8034:50 7322		
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME						PKG		
	PKG 22	MOS	24	+10%/-10%			12-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			8034:50 7322		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					12-APR-2019		
	11446	HRS/MSC	3500	+10%/-10%	TSN:0		8034:50	11534:50	11884:50
OVERHAUL	REF: AMM 71-00-01	AFL			TSN:0		7322		
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					12-APR-2019		
	11468	HRS/MSC	3500	+10%/-10%	TSN:0		8034:50	11534:50	11884:50
OVERHAUL	REF: AMM 71-00-01	AFL			TSN:0		7322		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					12-APR-2019		
	11463	HRS/MSC	3500	+10%/-10%	TSN:0		8034:50	11534:50	11884:50
OVERHAUL	REF: AMM 71-00-01	AFL			TSN:0		7322		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					12-APR-2019		
71.060	11491	HRS/MSC	3500	+10%/-10%	TSN:0		8034:50	11534:50	11884:50
OVERHAUL	REF: AMM 71-00-01	AFL			TSN:0		7322		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					12-APR-2019		
	11460	HRS/MSC	3500	+10%/-10%	TSN:0		8034:50	11534:50	11884:50
OVERHAUL	REF: AMM 71-00-01	AFL			TSN:0		7322		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT	MOS					25-NOV-2003		
AIRWORTHINESS	REF: AMM 71-00-05	HRS/MSC AFL	26600 35000				0 0	26600 35000	
71-00/476 (s)	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS PKG 17	MOS					25-NOV-2003		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R				0 0		
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC AFL	A/R				8034:50 7322		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION PKG 17	MOS					12-APR-2019		
	REF:	HRS/MSC AFL	A/R				8034:50 7322		
710005	UPPER LH ENGINE VIBRATION ISOLATOR	MOS					25-NOV-2003		
71.070	571.20.12.106 1153	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
	REF: GENERIC NO REF								
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR	MOS					25-NOV-2003		
71.080	571.20.12.106 1154	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
	REF: GENERIC NO REF								
710025	UPPER RH ENGINE VIBRATION ISOLATOR	MOS					25-NOV-2003		
71.090	571.20.12.106 1155	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
	REF: GENERIC NO REF								
710035	LOWER LH ENGINE VIBRATION ISOLATOR	MOS					25-NOV-2003		
71.100	571.20.12.106 1156	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	571.20.12.106 1157 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3042200 PCE-PR0400 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	TSN:7600:20 TSO:0			12-APR-2019 8034:50 7322		
71JFL05	PERFORM ENGINE RUN-UP								
	REF:	MOS HRS/MSC AFL	A/R				30-SEP-2011 4011:20 3410		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
710011	NO. 1 ENGINE - OVERHAUL								
	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500			12-DEC-2018 7600:20 6205	(11100:20) 11534:50	11600:20
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 0 , 1 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466		
710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			12-DEC-2018 7600:20 6205	(9350:20) 9784:50	9600:20
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%	-6:20		10-SEP-2019 7906:40 6466	(8200:20) 8634:50	8230:20



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION	MOS HRS/MSC ENC	A/R				07-MAY-2019 7640:45 6239		
	REF: See Workcard								
710053	NO. 1 ENGINE - AIR INLET HOUSING CORROSION INSPECTION	MOS HRS/MSC ENC					20-FEB-2014 4902:45 4024		
	REF:								
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS HRS/MSC ENC	300				22-JUL-2019 7799:35 6374	(8099:35) 8534:05	
	REF: See Workcard								
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
	PKG 0,1								
	REF: EMM 71-00-00								
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS HRS/MSC ENC	3500	+500		TSO:0 TSO:0 TSO:0	12-APR-2019 7600:20 6205	(11100:20) 11534:50	11600:20
	3042200								
	GG-PR0400								
	REF: See Workcard								
	OVERHAUL								
+ 720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL	MOS HRS/MSC ENC	A/R				(EBT)		
	REF: EMM 72-00-00								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				(EBT)		
+ 720025	NO. 1 ENGINE - OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0,1 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
+ 720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0,1 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
+ 720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0,1 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
+ 720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 ,1	MOS					PKG 10-SEP-2019 7906:40 6466		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%					
+ 721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI	MOS					10-NOV-2003 0 0		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R						
+ 721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL	MOS					10-NOV-2003 0 0		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R						
+ 721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT	MOS					10-NOV-2003 0 0		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R						
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS					(EBT)		
	REF: EMM 72-11-00	HRS/MSC ENC	A/R						
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0 ,1	MOS					PKG 10-SEP-2019 7906:40 6466		
	REF: See Workcard	HRS/MSC ENC	300	+10%/-10%					
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BOREScope, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0 ,1	MOS					PKG 10-SEP-2019 7906:40 6466		
	REF: EMM 72-20-00	HRS/MSC ENC	300	+10%/-10%					
+ 722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION	MOS					10-NOV-2003 0 0		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R						



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 722030	NO. 1 ENGINE - IMMERSION IN WATER	MOS					10-NOV-2003		
	REF: EMM 72-00-00	HRS/MSC A/R ENC					0 0		
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR	MOS		TSN:0			12-DEC-2018		
	3039001	HRS/MSC		TSN:0			7600:20		
	MCAKAXTR026	ENC	24000	TSN:0			6205		(30205) 31322
LIFE LIMIT	REF: GENERIC NO REF								
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT	MOS		TSN:0			12-DEC-2018		
	3043063	HRS/MSC		TSN:0			7600:20		
	PKAAA796813	ENC	24000	TSN:0			6205		(30205) 31322
LIFE LIMIT	REF: GENERIC NO REF								
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION	MOS					PKG		
	PKG 0 ,1	HRS/MSC	300	+10%/-10%			10-SEP-2019		
	REF: EMM 72-30-04	ENC					7906:40 6466		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR	MOS		TSN:0			10-NOV-2003		
	3040952	HRS/MSC		TSN:0			0		
	83B390	ENC	24000	TSN:0			0		(24000) 25117
LIFE LIMIT	REF: GENERIC NO REF								
+ 723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE	MOS					10-NOV-2003		
	REF: EMM 72-00-00	HRS/MSC A/R ENC					0 0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS	MOS					PKG		
	PKG 0 ,1	HRS/MSC	300	+10%/-10%			10-SEP-2019		
	REF: See Workcard	ENC					7906:40 6466		
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR	MOS		TSN:0			10-NOV-2003		
	3040933	HRS/MSC		TSN:0			0		
	83B737	ENC	24000	TSN:0			0		(24000) 25117
LIFE LIMIT	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 TX1A3233	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			10-NOV-2003 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 25117	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 3D484	MOS HRS/MSC ENC		TSN:2555			27-JUL-2011 3767:16 3066		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24511) 25628	
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
+ 724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								
+ 724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								
+ 724020	NO. 1 ENGINE - HIGH OIL PRESSURE	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								
+ 724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								
+ 724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
	REF: EMM 72-00-00								



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 724050	NO. 1 ENGINE - MATERIAL INGESTION	MOS					10-NOV-2003		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN	MOS					10-NOV-2003		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 725003	NO. 1 ENGINE - OVERSPEED	MOS					10-NOV-2003		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS					10-NOV-2003		
	3053740-01	HRS/MSC		TSN:0			0		
	A001DC71	ENC	8000	TSN:0			0		(8000) 9117
LIFE LIMIT	REF: GENERIC NO REF			TSN:0			0		
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					27-JUL-2011		
	REF: GENERIC NO REF	HRS/MSC ENC	5000				3767:16 3066		(8767:16) 9201:46
LIFE LIMIT									
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS					PKG		
	PKG 0 , 1	HRS/MSC	300	+10%/-10%			10-SEP-2019		
	REF: EMM 72-50-05	ENC					7906:40 6466		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS					10-NOV-2003		
	3037312	HRS/MSC		TSN:0			0		
	A001DK6W	ENC	15000	TSN:0			0		(15000) 16117
LIFE LIMIT	REF: GENERIC NO REF			TSN:0			0		
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS					10-NOV-2003		
	3037313	HRS/MSC		TSN:0			0		
	A001DK1K	ENC	15000	TSN:0			0		(15000) 16117
LIFE LIMIT	REF: GENERIC NO REF			TSN:0			0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - COMPRESSOR TURBINE BLADES 3118591-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:7600:20			12-DEC-2018 7600:20 6205		
726020	NO. 1 ENGINE - POWER SECTION MODULE 3042200 PS-PR0400 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500 TSO:89 TSO:111 TSO:95			12-APR-2019 7600:20 6205	(10989:20) 11423:50	11489:20
+ 726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
+ 726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
+ 726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
+ 726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-NOV-2003 0 0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
731010	NO. 1 ENGINE - FUEL PUMP (ARGOTEC) 825601-5 006452 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	+500 TSO:0 TSO:0 TSO:0		-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731024	NO. 1 ENGINE - FUEL NOZZLE 3119855-01 NSN REF:	MOS HRS/MSC ENC	O/C				10-SEP-2019 7906:40 6466		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3244882-2 C50449 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500		-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 006452 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			12-DEC-2018 7600:20 6205	(8200:20) 8634:50	8260:20
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 ,1 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
+ 731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 N/A REPLACE REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 ,1 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA57892 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500		-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 1792 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500			12-DEC-2018 7600:20 6205	(11100:20) 11534:50	11600:20
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-651 23052998 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500		-333:04	12-DEC-2018 7600:20 6205	(10767:16) 11201:46	11267:16
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
+ 731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS TRACKED ITEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				12-APR-2019 7600:20 6323		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0,1 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
731155	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER - DISCARD 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T			TSN:0 TSN:0 TSN:0	10-SEP-2019 7906:40 6466		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0,1 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			10-SEP-2019 7906:40 6466	(8806:40) 9241:10	8896:40
733030	NO. 1 ENGINE - MAIN FUEL FILTER ASSEMBLY 968.20.11.430 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				29-OCT-2009 3300:11 2642		
733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 1 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
CHAPTER 74 IGNITION									
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
740010	NO. 1 ENGINE - IGNITION EXCITER 10-381550-4 NNA11130023 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500			12-DEC-2018 7600:20 6205	(11100:20) 11534:50	11600:20
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	300	+10%/-10%			10-SEP-2019 7906:40 6466	(8206:40) 8641:10	8236:40
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG CH34055 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				18-AUG-2017 6922:45 5653		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%		-6:20	10-SEP-2019 7906:40 6466	(8200:20) 8634:50	8230:20
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG CH34055 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				18-AUG-2017 6922:45 5653		
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%		-6:20	10-SEP-2019 7906:40 6466	(8200:20) 8634:50	8230:20

CHAPTER 75

AIR

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3123532-01 17A133 REF: See Workcard	MOS HRS/MSC ENC	3500	+500			12-DEC-2018 7600:20 6205	(11100:20) 11534:50	11600:20

CHAPTER 76

ENGINE CONTROLS



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 18 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 10-SEP-2019 8341:10 7583		
+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 12-APR-2019 8034:50 7322		
+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-SEP-2019 8341:10 7583		
76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+1m/-1m +10%/-10%	-51		12-APR-2019 8034:50 7322	20-FEB-2020 11034:50	20-MAR-2020 11334:50
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 941.94.11.417 20030035 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				25-NOV-2003 0 0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760020	CONDITION CABLE ASSY.								
76.030	941.94.11.418 20030045 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
760025	POWER CONTROL CABLE ASSY.								
76.040	941.94.11.419 20030034 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
+ 761011 (s)	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES						PKG		
	PKG 0,1	MOS					10-SEP-2019		
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			7906:40 6466		
CHAPTER 77 ENGINE INDICATING									
+ 77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206 6688-1-197 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	975.21.15.212 1792865 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 0 0		
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.34 502 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-SEP-2019 8341:10 7583		
CHAPTER 78 EXHAUST									



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 78-00/214 (s)	EXAMINE EXHAUST STUBS PKG 3	MOS	12	+10%/-10%			PKG 10-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
CHAPTER 79 OIL									
+ 79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY.						PKG		
	PKG 20	MOS	12	+10%/-10%			12-APR-2019		
	REF: AMM 24-00-00	HRS/MSC AFL	600	+10%/-10%			8034:50 7322		
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 21	MOS	12	+10%/-10%			12-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			8034:50 7322		
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						PKG		
	PKG 3	MOS	12	+10%/-10%			10-SEP-2019		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%			8341:10 7583		
79-20/43	OIL COOLER								
	968.32.14.102	MOS					01-MAR-2018		
79.010	T0654	HRS/MSC	4000	+500/-10%	TSO:0		7468:45	11468:45	11968:45
OVERHAUL	REF: AMM 79-20-02	AFL			TSO:0		6839		
790005	TEMPERATURE BULB								
	975.11.20.101	MOS					25-NOV-2003		
79.020	119997	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 79-30-03	AFL			TSN:0		0		
790020	PRESSURE,GAGE SWITCH								
	973.81.14.305	MOS					25-NOV-2003		
79.030	0458	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 79-30-02	AFL			TSN:0		0		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790025	THERMAL ACTUATOR								
	978.73.01.002	MOS		TSN:0			25-NOV-2003		
79.040	0595	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0400 Part # 3042200									
701020	NO. 1 ENGINE - CONTAMINATION OF OILWITH NON-METALLIC FOREIGN MATERIAL								
		MOS					10-NOV-2003		
		HRS/MSC	A/R				0		
	REF: GENERIC NO REF	ENC					0		
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM								
		MOS					10-NOV-2003		
		HRS/MSC	A/R				0		
DISCARD	REF: GENERIC NO REF	ENC					0		
+ 790031 (s)	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR						PKG		
	PKG 1	MOS					10-SEP-2019		
		HRS/MSC	300	+10%/-10%			7906:40		
	REF: EMM 79-20-02	ENC					6466		
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR								
		MOS	12				10-SEP-2019	10-SEP-2020	
		HRS/MSC	300	+10%/-10%	-6:20		7906:40	(8200:20) 8634:50	8230:20
	REF: EMM 79-20-02	ENC					6466		
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT								
		MOS					12-DEC-2018		
		HRS/MSC	900	+10%/-10%			7600:20	(8500:20) 8934:50	8590:20
	REF: EMM 79-20-02	ENC					6205		
+ 790060 (s)	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN						PKG		
	PKG 1	MOS					10-SEP-2019		
		HRS/MSC	300				7906:40		
	REF: See Workcard	ENC					6466		
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN								
		MOS					10-SEP-2019		
		HRS/MSC	300	+10%/-10%	-6:20		7906:40	(8200:20) 8634:50	8230:20
	REF: EMM 72-60-00	ENC					6466		



Status Report

PC12/45 S/N 531 (LX-LAB): 8396:50 HRS, 7621 AFL as of 12-Oct-2019

Owner/Operator: JETFLY AVIATION SA

Report Date: 15-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
	REF: GENERIC NO REF								
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-SEP-2019 7906:40 6466		
	REF: GENERIC NO REF								
792011	NO. 1 ENGINE - OIL FILTER BYPASS CHECK VALVE 3036946 558	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			27-JUL-2011 3767:16 3066		
	REF: EMM 79-20-02								
792020	NO. 1 ENGINE - THERMOSTATIC BYPASS CHECK VALVE 3038242 WV102318	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			12-DEC-2018 7600:20 6205		
	REF: EMM 79-20-03								