

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 522/LX-JFH **MODEL:** PC12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 28-OCT-2003	8824:05 A/C HRS as of 17-JUN-2020	A/C HRS as of ___/___/___
	7863 AFL as of 17-JUN-2020	AFL as of ___/___/___
	1060:48 ACH as of 03-OCT-2019	ACH as of ___/___/___
	7459 FLTS as of 17-JUN-2020	FLTS as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0796/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 30-JUL-2018	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 8020:35 A/C HRS	803:30 ENG. HRS as of 17-JUN-2020	ENG. HRS as of ___/___/___
0 ENC	688 ENC as of 17-JUN-2020	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: KX1346/HC-E4A-3D/E10477SK **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 01-MAY-2019	LAST ACTUALS	CURRENT ACTUAL
2157:55 PROP HRS 8357:30 A/C HRS	2624:30 PROP HRS as of 17-JUN-2020	PROP HRS as of ___/___/___



Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 17 in PKG 3	MOS				03-OCT-2019	PKG	
	REF: AMM 05-20-00	HRS/MSC AFL	A/R			8593:25 7659		
05401A	300 HOUR INSPECTION							
+	PKG 18	MOS				03-OCT-2019		
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30	27:10	8593:25 7659	8920:35	8950:35
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 3	MOS	12	+1m/-1m		03-OCT-2019	03-OCT-2020	03-NOV-2020
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30	27:10	8593:25 7659	8920:35	8950:35
05403A	600 HOUR INSPECTION							
+	PKG 19	MOS				03-OCT-2019		
	REF: AMM 05-40-01	HRS/MSC AFL	600	+10%/-10%	27:10	8593:25 7659	9220:35	9280:35
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 20	MOS	12	+1m/-1m	-61	03-OCT-2019	03-AUG-2020	03-SEP-2020
	REF: AMM 05-40-01	HRS/MSC AFL	600	+30/-30	27:10	8593:25 7659	9220:35	9250:35



Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 21	MOS	12	+1m/-1m	-61	03-OCT-2019	03-AUG-2020	03-SEP-2020
		HRS/MSC	1200	+30/-30		8593:25	9793:25	9823:25
	REF: AMM 05-40-01	AFL				7659		
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+								
	PKG 22	MOS	24	+1m/-1m		03-AUG-2018	03-AUG-2020	03-SEP-2020
		HRS/MSC	2400	+30/-30		8020:35	10420:35	10450:35
	REF: AMM 05-40-01	AFL				7175		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0796 Part # 3042200								
057010	NO. 1 ENGINE - MINOR INSPECTION							
+								
	PKG 2 in PKG 3	MOS				03-OCT-2019		
		HRS/MSC	300	+10%/-10%		572:50	(872:50) 8893:25	902:50
	REF: See Workcard	ENC				484		
72JFL01	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 3	MOS				03-OCT-2019		
		HRS/MSC	300	+10%/-10%		572:50	(872:50) 8893:25	902:50
	REF:	ENC				484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED PKG 17 ,3	MOS HRS/MSC A/R					PKG 03-OCT-2019 8593:25 7659		
	REF:	AFL							
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH PKG 17 ,3	MOS HRS/MSC A/R					PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	AFL							
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION PKG 17 ,3	MOS HRS/MSC A/R					PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	AFL							
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC -					16-APR-2020 8778:15 7824		
	REF:	AFL							
00JFL64	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 4 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC -					05-APR-2019 8330:50 7440		
	REF:	AFL							
00JFL65	PERFORM PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 5 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC -					16-APR-2020 8778:15 7824		
	REF:	AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL7.0	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 7 AMDT 0 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - AFL							
	REF:								
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF	MOS					04-MAY-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-160717	REVIEW PILATUS PC12 AMM REV 32	MOS					23-NOV-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS						07-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS						29-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS						28-OCT-2003	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL					0 0		
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS						28-OCT-2003	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL					0 0		
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS						09-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS						08-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37	MOS						07-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-190517	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38	MOS						19-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-200515	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 39	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
	NEW REQUIREMENT ADDED ON 01-JUN-2020 (EFFECTIVE: 15-MAY-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						07-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS						07-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						06-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS					13-JAN-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS					23-APR-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 20-MAY-2020 (EFFECTIVE: 04-MAY-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 28-MAY-2020 (EFFECTIVE: 21-MAY-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1346 Part # HC-E4A-3D/E10477SK									
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					11-SEP-2015		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS					31-JAN-2017		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS					16-SEP-2016		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS					22-FEB-2018		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS					06-JUN-2019		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS					10-JAN-2020		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-200501	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
	NEW REQUIREMENT ADDED ON 12-JUN-2020 (EFFECTIVE: 01-MAY-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
P019-200501-1	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 147 REV 16	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
	NEW REQUIREMENT ADDED ON 03-JUN-2020 (EFFECTIVE: 01-MAY-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER 04 LIMITATIONS

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
<hr/>									
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000
<hr/>									
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000
<hr/>									
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-50-01	UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS					28-OCT-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS								
		MOS					28-OCT-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN								
		MOS					28-OCT-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
<hr/>									
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER SUDDEN PROPELLER STOPPAGE								
		MOS					28-OCT-2003		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					28-OCT-2003		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					28-OCT-2003		
	REF: AMM 05-10-30	HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					28-OCT-2003		
	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
05JFL11	AIRWORTHINESS REVIEW CERTIFICATE	MOS					31-OCT-2019	14-NOV-2020 M	
	REF:	HRS/MSC	DUE				8635:30		
		AFL					7692		
05JFL12	- CERTIFICATE OF REGISTRATION	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL13	- NOISE CERTIFICATE	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL14	- AIRCRAFT STATION LICENCE	MOS					16-NOV-2018	31-DEC-2021 M	
	REF:	HRS/MSC	DUE						
		AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING								
		MOS					03-OCT-2019		
		HRS/MSC	300				8593:25	8893:25	
	REF:	AFL					7659		
CHAPTER 06 DIMENSIONS AND AREAS									
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 17 ,3	MOS					03-OCT-2019		
		HRS/MSC	A/R				8593:25		
	REF: AMM 06-20-00	AFL					7659		
06-00/123	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 17 ,3	MOS					03-OCT-2019		
		HRS/MSC	A/R				8593:25		
	REF: AMM 06-20-00	AFL					7659		
06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR.						PKG		
	PKG 17 ,3	MOS					03-OCT-2019		
		HRS/MSC	A/R				8593:25		
	REF: AMM 06-20-00	AFL					7659		
06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL						PKG		
	PKG 17 ,3	MOS					03-OCT-2019		
		HRS/MSC	A/R				8593:25		
	REF: AMM 06-20-00	AFL					7659		
CHAPTER 07 LIFTING AND SHORING									

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 17 ,3 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				03-OCT-2019 8593:25 7659		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 17 ,3 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				03-OCT-2019 8593:25 7659		
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST REF:	MOS HRS/MSC AFL	60	+1m/-1m			03-OCT-2019 8593:25 7659	25-MAR-2021	M 25-APR-2021
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6) REF:	MOS HRS/MSC AFL	A/R				16-APR-2019 8341:25 7449		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
CHAPTER 11 PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
CHAPTER 12 SERVICING									

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS PKG 17 ,3 REF: AMM 12-20-01	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 17 ,3 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 17 ,3 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)	MOS	12	+1m/-1m		-61	03-OCT-2019 8593:25 7659	03-AUG-2020	03-SEP-2020
20.010	REF: AMM 20-40-00	HRS/MSC AFL							
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)	MOS	6	+10%/-10%		2	16-APR-2020 8778:15 7824	18-OCT-2020 9078:15	05-NOV-2020 9108:15
20.011	REF: AMM 20-40-00	HRS/MSC AFL	300	+10%/-10%					
20JFL01	PERFORM DENTS AND BUCKLES CHARTS REF:	MOS HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659	8893:25	8923:25
CHAPTER 21 AIR CONDITIONING									

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%				03-AUG-2018	
		HRS/MSC	2400	+10%/-10%				8020:35	
	REF: GENERIC NO REF	AFL						7175	
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
		MOS	24	+10%/-10%		66		03-OCT-2019	08-DEC-2021
21.040		HRS/MSC	3000	+10%/-10%				8593:25	11593:25
	REF: AMM 21-30-00	AFL						7659	11893:25
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
		MOS	24	+10%/-10%		66		03-OCT-2019	08-DEC-2021
21.030		HRS/MSC	3000	+10%/-10%				8593:25	11593:25
	REF: AMM 21-30-01	AFL						7659	11893:25
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
		MOS	60	+10%/-10%		131		03-AUG-2018	12-DEC-2023
21.010		HRS/MSC						8020:35	12-JUN-2024
	REF: AMM 21-30-07	AFL						7175	
21-30/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
		MOS	60	+10%/-10%		131		03-AUG-2018	12-DEC-2023
21.020		HRS/MSC						8020:35	12-JUN-2024
	REF: AMM 21-30-08	AFL						7175	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER						PKG		
21.080	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
	HRS/MSC		1200	+10%/-10%			8593:25		
	REF: AMM 21-40-02	AFL					7659		
+ 21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH								
21.130		MOS	60	+10%/-10%	131		03-AUG-2018	12-DEC-2023	12-JUN-2024
	HRS/MSC		4800	+10%/-10%			8020:35	12820:35	13300:35
	REF: AMM 21-40-06	AFL					7175		
+ 21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH								
21.120		MOS	60	+10%/-10%	131		03-AUG-2018	12-DEC-2023	12-JUN-2024
	HRS/MSC		4800	+10%/-10%			8020:35	12820:35	13300:35
	REF: AMM 21-60-05	AFL					7175		
21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
	HRS/MSC		1200	+10%/-10%			8593:25		
	REF: AMM 21-40-00	AFL					7659		
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 19	MOS					03-OCT-2019		
	HRS/MSC		600	+10%/-10%			8593:25		
	REF: AMM 21-40-01	AFL					7659		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 19	MOS					03-OCT-2019		
	HRS/MSC		600	+10%/-10%			8593:25		
	REF: AMM 21-40-01	AFL					7659		
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
	HRS/MSC		1200	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) 959.90.22.140 508 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%		27:10	03-OCT-2019 8593:25 7659	8920:35	8950:35
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140 508 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	600	+10%/-10%			29-MAY-2018 7875:15 7050 885	1485	1545
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) 959.90.22.140 508 REF: See Workcard	MOS HRS/MSC AFL ACH	600	+10%/-10%			29-MAY-2018 7875:15 7050 885	1485	1545
21-50/58 21.110	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) 959.90.22.140 508 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	N/A				06-FEB-2014 5394:50 4695 619:25		
21-50/59 21.100	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) 959.90.22.140 508 REF: See Workcard	MOS HRS/MSC AFL ACH	N/A				06-FEB-2014 5394:50 4695 619:25		
210005 21.340	OVERPRESSURE SWITCH 973.81.15.105 299 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210010	REFRIGERATION PACK								
21.255	959.90.20.111 1080 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210015	WATER INJECTOR								
21.370	959.90.20.141 1058 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210020	DUCT TEMP SENSOR								
21.320	959.90.20.121 1072 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	959.90.20.132 1047 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210030	HP SHUT OFF VALVE								
21.280	959.90.20.131 1046 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210035	WATER SEPARATOR ASSY								
21.220	521.41.12.060 2192 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210040	TEMPCONTROL VALVE								
21.310	959.90.20.136 1023 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	959.90.22.140 508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:151 N:7875:15 N:7050			29-MAY-2018 7875:15 7050		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	1134104-9 0180 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2018 7875:15 7050		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	959.90.22.116 786 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.118 722 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-JUL-2014 5680 4974		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	959.90.22.119 921 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-JUL-2014 5680 4974		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	959.90.91.121 63-A0451 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	959.90.91.111 63-7606 REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210075	CHECK VALVE								
21.400	959.90.91.151 63-A0561 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210080	JET PUMP								
21.410	959.90.91.161 63-1825 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210085	MANUAL CONTROLLER								
21.420	959.90.91.101 63-A0447 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	64547-130374-36 34-G0507 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				14-JUL-2012 4672:55 3982		
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	965.23.23.202 1023707 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210100	CAB RATE INDICATOR								
21.440	965.16.21.002 1081325 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:14 N:0 N:0			25-JUN-2016 6694:55 5975		
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	965.23.21.534 1042741 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C				03-AUG-2018 8020:35 7175		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210110	CABIN PX SWITCH								
21.360	965.23.21.533 1020421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-AUG-2018 8020:35 7175		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.507 505716 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210120	BAY TEMP SENSOR								
21.450	959.90.20.122 1052 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	975.15.16.101 A5836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210130	TEMP CONTROLLER								
21.235	959.90.20.123 1046 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210140	SOLENOID VALVE								
21.300	963.14.11.001 208301 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	969.67.81.507 505721 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	963.30.11.106 0264B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	963.30.11.002 0290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210160	CABIN HEATER TEMPERATURE TRANSMITTER								
21.350	975.15.16.104 214 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
210165	UNDERFLOOR HEATER TEMPERATURE TRANSMITTER								
21.260	975.15.16.105 650 REF: AMM 21-40-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2012 4695:40 4002		
210170	OVERPRESSURE SWITCH								
21.340	973.81.15.106 303 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST								
		MOS HRS/MSC AFL	24				03-AUG-2018 8020:35 7175	03-AUG-2020	

CHAPTER 22	AUTO FLIGHT
-------------------	--------------------

22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES	PKG
	PKG 22	03-AUG-2018
	MOS 24 +10%/-10%	8020:35
	HRS/MSC 2400 +10%/-10%	7175
	REF: GENERIC NO REF	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK								
22.010	REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+10%/-10% +10%/-10%		-61	03-OCT-2019 8593:25 7659	03-AUG-2020 9593:25	09-SEP-2020 9693:25
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 22-20-02								
22-20/130 (s)	CHECK STICK PUSHER SYSTEM						PKG		
	PKG 18	MOS HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 22-20-00								
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 22-20-00								
220005	AUTOPILOT MODE CONTROL								
22.160	065-0086-17 1606 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C				26-MAR-2014 5493:05 4798		
220010	ALTITUDE PRESELECTOR								
22.180	065-0089-16 1738 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C				24-MAR-2012 4491:58 3809		
220015	AILERON KSA372,065-00056-0056 ACTUATOR								
22.100	985.92.03.161 5478 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220020	PITCH KSM375,065-00015-0000 MOUNT								
22.190	985.92.03.173 9270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR								
22.110	065-00056-59 4082 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C				27-NOV-2015 6405:35 5696		
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	985.92.03.171 9280 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	065-0056-80 4798 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C				16-SEP-2016 6822:20 6094		
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	985.92.03.171 9279 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
220045	STICK PUSHER SERVO								
22.220	978.61.11.103 1475 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C				04-NOV-2008 3244:58 2687		
220050	PITCH TRIM ADAPTER								
22.130	985.92.03.181 1555 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:198 N:8778:15 N:7824			16-APR-2020 8778:15 7824		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220055	STICK PUSHER CAPSTAN								
22.140	978.61.11.124 1466 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
220060	STICK SHAKER								
22.230	978.61.11.143 0419 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
220065	AUTOPILOT COMPUTER								
22.150	065-0064-15 2679 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				16-APR-2020 8778:15 7824		
220070	STICK PUSHER COMPUTER								
22.170	975.44.23.104 115505 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2019 8593:25 7659		
CHAPTER 23 COMMUNICATIONS									
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	984.81.10.203 10923 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	984.81.10.203 10925 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
230015	COMM/NAV 25 KHZ SYSTEM								
23.050	985.99.11.366 2190 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230020	COMM/NAV 25 KHZ SYSTEM								
23.050	985.99.11.366 2198 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
230025	AUDIO SUMMING AMPLIFIER								
23.010	987.81.33.108 144 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
230030	AUDIO SELECTOR								
23.040	010-00152-11 96294065 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-FEB-2014 5394:50 4695		
23JFL01	NO. 1 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78417717 REF:	MOS HRS/MSC AFL	O/C				18-APR-2019 8347:35 7453		
23JFL02	NO. 2 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78411824 REF:	MOS HRS/MSC AFL	O/C				18-APR-2019 8347:35 7453		
CHAPTER 24	ELECTRICAL POWER								
24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM						PKG		
	PKG 21	MOS HRS/MSC	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 24-20-00	AFL							
24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT						PKG		
	PKG 3	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: See Workcard	AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659		
24-30/19	STARTER GENERATOR 23085-029 MOD A	MOS					03-OCT-2019		
24.020	Y0256 REF: AMM 24-30-01	HRS/MSC AFL	N/A				8593:25 7659		
24-30/21	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING 940.83.08.902	MOS					29-MAY-2015		
	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%			6120:25	8983:48	9283:48
DISCARD	REF: AMM 24-30-04	AFL				-136:3 7	5448		
24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER PKG 22	MOS	24	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			03-AUG-2018 8020:35 7175		
+ 24-30/482	BRUSH CHECK STARTER GENERATOR BRUSHES (P/N 978.91.23.407, 978.91.23.408 AND 978.91.23.409) 23085-029 MOD A PKG 19	MOS					03-OCT-2019		
	Y0256 REF: AMM 24-30-01	HRS/MSC AFL	600	+10%/-10%			8593:25 7659	9193:25	9253:25
24-30/491	STARTER GENERATOR 23085-029 MOD A	MOS					03-OCT-2019		
OVERHAUL	Y0256 REF:	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659	9793:25	9913:25

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS								
24.210	REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%		66	03-OCT-2019 8593:25 7659	08-DEC-2021	19-FEB-2022
24-30/64	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES 524.32.12.158 MOD.F PKG 19 100065	MOS HRS/MSC AFL	600	+10%/-10%			03-OCT-2019 8593:25 7659	9193:25	9253:25
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
24.030	REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A			58:49	02-OCT-2014 5828:35 5129		
+ 24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
	REF: AMM 24-30-04	MOS HRS/MSC AFL	1800	+10%/-10%			29-MAY-2018 7875:15 7050	9675:15	9855:15
24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY 31406-002 11501534	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020 8893:25	09-NOV-2020 8923:25
24-30/67	REMOVE AND SERVICE NO. 2 NICAD BATTERY PN NOT INSTALLED	MOS HRS/MSC AFL	N/A				05-JUL-2007 2305 1868		
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 22						PKG 03-AUG-2018 8020:35 7175		
	REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%					

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY								
24.050	501.1712.02 3945 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m		-61	03-OCT-2019 8593:25 7659	03-AUG-2020	03-SEP-2020
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS						PKG		
	PKG 22	MOS	24	+10%/-10%			03-AUG-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			8020:35 7175		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	988.21.14.111 Y2279 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		
240025	GENERATOR 2 2ND GENCON UNIT								
24.140	988.21.15.103 10640 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-FEB-2016 6480:20 5773		
240035	BUSBAR,CROSS TIE RCCB								
24.150	972.55.37.003 1061 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		
240040	BUSBAR,CROSS,TIE RCCB								
24.150	972.55.37.005 438 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		
240045	STARTER RELAY								
24.160	974.09.26.133 P436 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240050	BATTERY RELAY								
24.170	974.09.26.126 P748 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240055	EPU RELAY								
24.180	974.09.26.126 P911 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	972.81.32.301 377 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240065	OVERHEAD PANEL								
24.190	972.81.32.109 JWPIL2002159 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 N:3885:50 R:0 R:0			23-NOV-2018 8200:20 7328		
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	959.90.20.124 218 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	975.04.21.110 AGA00470 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	974.29.00.201 2597 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240095	S105 DC CURRENT SENSOR								
24.090	974.29.00.205 1817 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	974.29.00.205 1857 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	974.29.00.201 2610 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240110	S104 DC CURRENT SENSOR								
24.090	974.29.00.201 2635 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
240115	S106 DC CURRENT SENSOR								
24.100	974.29.00.201 2615 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
243045	GENERATOR 2								
24.030	524.32.12.158 MOD.F 100065 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2014 5530:20 4841		
243080	EMERGENCY POWER SUPPLY								
24.050	501.1712.02 3945 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				23-DEC-2016 6936:40 6210		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11501534 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				03-OCT-2019 8593:25 7659		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF								
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 18	MOS HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF								
25-10/293	COPILOT SEAT CUSHION								
	PN	MOS					28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 25-21-02	AFL					0		
25-10/293	PILOT SEAT CUSHION								
25.080	PN	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 25-21-02	AFL							
25-10/294	COPILOT CREW SEAT BELT								
	959.30.01.242	MOS	144				16-APR-2020	20-JUL-2027	
	N/A	HRS/MSC				-1732	8778:15		
DISCARD	REF:	AFL					7824		
25-10/294	PILOT CREW SEAT BELT								
	959.30.01.243	MOS	144				16-APR-2020	02-APR-2031	
	N/A	HRS/MSC					8778:15		
DISCARD	REF:	AFL				-380	7824		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 17 ,3 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 17 ,3 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
+ 25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				28-OCT-2003 0 0	10000	
DISCARD									
25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				28-OCT-2003 0 0	10000	
DISCARD									
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	1200	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
<hr/>									
25-20/295	NO. 1 PASSENGER SEAT BELT								
	5-02-2T4718MNI	MOS	144				27-FEB-2015	15-DEC-2026	
	NSN	HRS/MSC		N:0			5980:20		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5297		
	Manufacture Date: 15-DEC-2014								
<hr/>									
25-20/295	NO. 2 PASSENGER SEAT BELT								
	5-02-2T4718MNI	MOS	144				27-FEB-2015	15-DEC-2026	
	NSN	HRS/MSC		N:0			5980:20		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5297		
	Manufacture Date: 15-DEC-2014								
<hr/>									
25-20/295	NO. 3 PASSENGER SEAT BELT								
	5-02-2T4718MNI	MOS	144				27-FEB-2015	15-DEC-2026	
	NSN	HRS/MSC		N:0			5980:20		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5297		
	Manufacture Date: 15-DEC-2014								
<hr/>									
25-20/295	NO. 4 PASSENGER SEAT BELT								
	5-02-2T4718MNI	MOS	144				27-FEB-2015	15-DEC-2026	
	NSN	HRS/MSC		N:0			5980:20		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5297		
	Manufacture Date: 15-DEC-2014								
<hr/>									
25-20/295	NO. 5 PASSENGER SEAT BELT								
	5-02-2T4718MNI	MOS	144				27-FEB-2015	15-DEC-2026	
	NSN	HRS/MSC		N:0			5980:20		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5297		
	Manufacture Date: 15-DEC-2014								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 6 PASSENGER SEAT BELT 5-02-2T4718MNI NSN REF: GENERIC NO REF Manufacture Date: 15-DEC-2014	MOS HRS/MSC AFL	144				27-FEB-2015 5980:20 5297	15-DEC-2026	
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 17 ,3 REF: See Workcard	MOS HRS/MSC AFL	A/R				03-OCT-2019 8593:25 7659		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 17 ,3 REF: See Workcard	MOS HRS/MSC AFL	A/R				03-OCT-2019 8593:25 7659		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659		
25-60/231 (s)	OPERATIONAL TEST ELT PKG 3 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
25-60/483	PERFORM PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 985.13.80.853 M0131.0021 REF: AMM 25-63-10	MOS HRS/MSC AFL	A/R				28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY S1820516-99	MOS		N:0			26-MAR-2015	24-SEP-2021 M	
25.020	TM0000070798	HRS/MSC	DUE	N:0			6021:50		
DISCARD	REF: GENERIC NO REF	AFL		N:0			5345		
Expiry Date: 24-SEP-2021									
250005	REMOTE CONTROL PANEL 985.13.80.817	MOS		N:0			28-OCT-2003		
25.070	M0291.0088	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER 985.13.80.853	MOS		N:0			28-OCT-2003		
25.050	M0131.0021	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-63-01	AFL		N:0			0		
250015	SCHROTH SEAT PILOT 959.30.01.133	MOS		N:140			11-JUN-2015		
25.040	856	HRS/MSC	O/C	N:0					
	REF: AMM 25-10-05	AFL							
250020	SCHROTH SEAT CO-PILOT 959.30.01.134	MOS		N:140			11-JUN-2015		
25.040	862	HRS/MSC	O/C	N:0					
	REF: AMM 25-10-05	AFL							
250021	NO. 1 PASSENGER SEAT 959.30.01.617	MOS					11-JUN-2015		
	23712	HRS/MSC	O/C						
	REF:	AFL							
250022	NO. 2 PASSENGER SEAT 959.30.01.618	MOS					22-MAR-2018		
	23713	HRS/MSC	O/C				7729:20		
	REF:	AFL					6916		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250023	NO. 3 PASSENGER SEAT 959.30.01.633 29292 REF:	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		
250024	NO. 4 PASSENGER SEAT 959.30.01.634 29293 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250025	NO. 5 PASSENGER SEAT 959.30.01.641 23715 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250026	NO. 6 PASSENGER SEAT 959.30.01.642 23717 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
251010	PILOT SEAT BACKREST TUBES 959.30.01.133 856 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	10000	N:0 N:0 N:0			28-OCT-2003 0 0	10000	
251015	COPILOT SEAT BACKREST TUBES 959.30.01.134 862 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	10000	N:0 N:0 N:0			28-OCT-2003 0 0	10000	
25JFL02	PERFORMED FIRST AID KIT INSPECTION REF:	MOS HRS/MSC AFL	12	+1m/-1m		-61	03-OCT-2019 8593:25 7659	03-AUG-2020	03-SEP-2020

CHAPTER 26 FIRE PROTECTION

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/2	COCKPIT FIRE EXTINGUISHER								
26.010	BA51015GR-3 077088	MOS HRS/MSC	120	N:0			03-MAY-2013 5100:15	01-SEP-2021 M	
LIFE LIMIT	REF: GENERIC NO REF	AFL ACH		N:0			4405		
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348)								
26.010	BA51015GR-3 077088	MOS HRS/MSC	12	+10%/-10%		-53	25-SEP-2019	03-AUG-2020	09-SEP-2020
	REF: GENERIC NO REF	AFL							
260005	FIRE/OVERHEAT DETECTOR								
26.020	975.12.10.012 205156	MOS HRS/MSC	O/C	N:0			28-OCT-2003 0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 27 FLIGHT CONTROLS									
27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL						PKG		
	PKG 18	MOS					03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES								
		MOS					28-OCT-2003		
	REF: GENERIC NO REF	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES								
27.010		MOS	60	+10%/-10%			11-AUG-2017	11-AUG-2022	11-FEB-2023
	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%		-83:47	7368 6584	12084:13	12564:13
27-10/139 (s)	EXAMINE AILERON LH AND RH AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC TEMPORARY (MAT. NO. P10-001)						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%					
27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 PKG 22	MOS	24	+10%/-10%			PKG 03-AUG-2018 8020:35 7175		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%					
27-10/394	EXAMINE - AILERON CONTROL SYSTEM	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-10-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-10-09	HRS/MSC AFL	32500 42000				0 0	32500 42000	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/444	AILERON FLIGHT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-10-01	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-10-02	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARING	MOS	12	+10%/-10%			03-OCT-2019		
	REF: AMM 27-10-00	HRS/MSC	1200	+10%/-10%			8593:25		
		AFL					7659		
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999	MOS	24	+10%/-10%			03-AUG-2018		
	REF: See Workcard	HRS/MSC	2400	+10%/-10%			8020:35		
		AFL					7175		
27-20/140 (s)	EXAMINE RUDDER IN PARTICULAR THE COVER PLATE (PART NO. 555.40.12.215) ON THE BOTTOM OF THE RUDDER TO MAKE SURE IT IS NOT BENT AND THERE ARE NO SIGNS OF INTERFERENCE WITH THE RUDDER STOP.	MOS	12	+10%/-10%			03-OCT-2019		
	REF: AMM 55-40-00	HRS/MSC	300	+10%/-10%			8593:25		
		AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-AUG-2018 8020:35 7175		
27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
27-20/242 (s)	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH PKG 21 REF: AMM 20-31-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-AUG-2018 8020:35 7175		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 22 REF: AMM 27-25-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-AUG-2018 8020:35 7175		
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					28-OCT-2003		
	REF: AMM 27-20-00	HRS/MSC	A/R				0		
		AFL					0		
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-20-01	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-20-02	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
27-30/141 (s)	EXAMINE ELEVATORS	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC	300	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	AFL					8593:25		
							7659		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS	MOS	12	+10%/-10%			PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	AFL					8593:25		
							7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 22	MOS	24	+10%/-10%			PKG 03-AUG-2018 8020:35 7175		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%					
27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%					
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 22	MOS	24	+10%/-10%			PKG 03-AUG-2018 8020:35 7175		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%					
27-30/334	CHECK ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR) (REF. 12-A-27-30-00-00A-903A-A)	MOS					11-AUG-2017 7368 6584		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R						
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM	MOS					28-OCT-2003 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000						
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					28-OCT-2003 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000						

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-30-01	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: AMM 27-30-02	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-30/450	STICK PUSHER CABLES	MOS					28-OCT-2003		
LIFE LIMIT	REF: GENERIC NO REF	PN SN-UNKNOWN AFL	HRS/MSC 20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%			03-OCT-2019	03-AUG-2020	09-SEP-2020
27.021		HRS/MSC	3000				8593:25	11593:25	
AIRWORTHINESS	REF: AMM 27-40-00	AFL			-61		7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES PKG 3	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%					
27-40/252 (s)	INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 27-40-01	HRS/MSC AFL	1200	+10%/-10%					
27-40/26	OVERHAUL PITCH TRIM ACTUATOR 978.73.14.203 082	MOS	84				22-JAN-2019 8242:25 7361	22-JAN-2026 11642:25	
OVERHAUL	REF: AMM 27-40-01	HRS/MSC AFL	3400						
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 18	MOS					PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%					
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%					
27-40/3	PITCH TRIM ACTUATOR 978.73.14.203 082	MOS			O:4		22-JAN-2019 8242:25 7361	28242:25 34361	
27.011 AIRWORTHINESS	REF: AMM 27-40-01	HRS/MSC AFL	20000 27000		N:9058:51 O:0 N:6559 O:0				
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS PN	MOS			N:0		28-OCT-2003 0 0	10000	
27.036 LIFE LIMIT	REF: AMM 27-40-02	HRS/MSC AFL	10000		N:0 N:0				
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION PKG 17 ,3	MOS					PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R						

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 3	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT 978.73.20.003	MOS					28-OCT-2003		
OVERHAUL	199	HRS/MSC	10000	+10%/-10%			0	10000	11000
	REF:	AFL	13500	+500/-500			0	13500	14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					27-FEB-2013		
27.040	0276	HRS/MSC	5000	+10%/-10%			4995:50	9244:20	M 9744:20
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4276	10701	M 11201
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					27-FEB-2013		
27.040	0207	HRS/MSC	5000	+10%/-10%			4995:50	9127:10	M 9627:10
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4276	10654	M 11154
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					13-APR-2017		
27.050	0322	HRS/MSC	5000	+10%/-10%	I:3	11	7080:50	12080:50	12580:50
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			6348	13348	13848

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					27-FEB-2013		
OVERHAUL	0355 REF: AMM 27-50-03	HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			4995:50 4276	9021:25 M 10826 M	9521:25 11326
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.205	MOS					28-OCT-2003		
DISCARD	S5169 REF: See Workcard	HRS/MSC AFL	10000 13500	+500/-500 +500/-500	N:0 N:0		0 0	10000 13500	10500 14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.206	MOS					28-OCT-2003		
DISCARD	S5259 REF: See Workcard	HRS/MSC AFL	10000 13500	+500/-500 +500/-500	N:0 N:0		0 0	10000 13500	10500 14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.205	MOS					28-OCT-2003		
DISCARD	S5171 REF: See Workcard	HRS/MSC AFL	10000 13500	+500/-500 +500/-500	N:0 N:0		0 0	10000 13500	10500 14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.206	MOS					28-OCT-2003		
DISCARD	S5257 REF: See Workcard	HRS/MSC AFL	10000 13500	+500/-500 +500/-500	N:0 N:0		0 0	10000 13500	10500 14000
27-50/386	EXAMINE - FLAP MECHANISM								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC AFL	25000 30000				0 0	25000 30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS					27-FEB-2013		
27.040	978.73.20.309	HRS/MSC	20000	N:751:30			4995:50		24244:20
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:575			4276		30701
27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS					27-FEB-2013		
27.040	978.73.20.309	HRS/MSC	20000	N:869:40			4995:50		24126:10
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:622			4276		30654

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		O:3			13-APR-2017		
27.050	0322	HRS/MSC	20000	N:5025:42 O:0			7080:50		27080:50
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:3935 O:0			6348		33348
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS					27-FEB-2013		
27.050	0355	HRS/MSC	20000	N:974:25			4995:50		24021:25
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:450			4276		30826
27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		N:0			28-OCT-2003		
57.060	430	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0		30000
27-50/414	RIGHT HAND FLAP								
	557.50.12.004	MOS		N:0			28-OCT-2003		
57.060	426	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0		30000
+ 27-50/437 (s)	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
AIRWORTHINESS	REF: AMM 27-51-00	AFL					7659		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 12-20-07	AFL					7659		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 17 ,3	MOS					03-OCT-2019		
		HRS/MSC	A/R				8593:25		
	REF: GENERIC NO REF	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	945.02.02.205 S5169 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	945.02.02.206 S5259 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.205 S5171 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	945.02.02.206 S5257 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				28-OCT-2003 0 0		
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0276 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020 8893:25	09-NOV-2020 8923:25
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0207 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020 8893:25	09-NOV-2020 8923:25
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0322 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020 8893:25	09-NOV-2020 8923:25
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0355 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020 8893:25	09-NOV-2020 8923:25

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309	MOS	24	+10%/-10%			03-AUG-2018	03-AUG-2020	15-OCT-2020
	0276	HRS/MSC	2400	+10%/-10%			8020:35	10420:35	10660:35
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			7175	10375	10695
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309	MOS	24	+10%/-10%			03-AUG-2018	03-AUG-2020	15-OCT-2020
	0207	HRS/MSC	2400	+10%/-10%			8020:35	10420:35	10660:35
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			7175	10375	10695
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309	MOS	24	+10%/-10%			03-AUG-2018	03-AUG-2020	15-OCT-2020
	0322	HRS/MSC	2400	+10%/-10%			8020:35	10420:35	10660:35
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			7175	10375	10695
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309	MOS	24	+10%/-10%			03-AUG-2018	03-AUG-2020	15-OCT-2020
	0355	HRS/MSC	2400	+10%/-10%			8020:35	10420:35	10660:35
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			7175	10375	10695
27-50/77	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013)								
27.080		MOS					28-OCT-2003		
		HRS/MSC	N/A				0		
	REF: AMM 27-50-00	AFL					0		
270003	HORIZONTAL TAIL ASSY								
	555.10.12.037	MOS					28-OCT-2003		
	429	HRS/MSC	O/C		N:0		0		
	REF: AMM 55-10-01	AFL			N:0		0		
270015	ELEVATOR LH ASSY								
	555.20.12.039	MOS					28-OCT-2003		
	S0108	HRS/MSC	O/C		N:0		0		
	REF: AMM 55-20-01	AFL			N:0		0		
270023	ELEVATOR RH ASSY								
	555.20.12.040	MOS					28-OCT-2003		
	S0111	HRS/MSC	O/C		N:0		0		
	REF: AMM 55-20-01	AFL			N:0		0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	978.73.18.132 545 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270033	RUDDER ASSY								
	555.40.12.038 434 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270035	FLAP CONTROL AND WARNING (FCWU) UNIT								
27.130	978.73.20.016 112275 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C				16-SEP-2016 6822:20 6094		
270045	LH INBOARD TRANSMITTER								
27.100	978.73.20.021 01N086DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	978.73.20.602 0331 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 01N078DZ REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	978.73.20.021 01N076DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	978.73.20.602 0332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	978.73.18.132 612 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 01N089DK REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m			03-OCT-2019 8593:25 7659	18-OCT-2020	M 18-NOV-2020
CHAPTER 28 FUEL									
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	AFL							
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	AFL							
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS HRS/MSC AFL	2400	+10%/-10%	61:25		29-MAY-2018 7875:15 7050	10336:40	10576:40
	REF: AMM 28-10-01	AFL							
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 28-20-07	AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 3	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%					
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N) PKG 20	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 3	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 22	MOS	24	+10%/-10%			PKG 03-AUG-2018 8020:35 7175		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%					
28-20/32	ACCESSORY GEARBOX FUEL PUMP 968.84.51.108	MOS					23-DEC-2016		
28.010	B4954	HRS/MSC	3500				6936:40	10436:40	
OVERHAUL	REF: AMM 28-20-03	AFL					6210		
+ 28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM	MOS	48	+10%/-10%			29-MAY-2018	29-MAY-2022	23-OCT-2022
28.020	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%	61:25		7875:15 7050	9136:40	9256:40
280005	LOW PRESSURE FUEL PUMP 968.84.51.108	MOS					25-NOV-2003		
28.120	B4511	HRS/MSC	O/C				4:12		
	REF: GENERIC NO REF	AFL							

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280010	FUEL FLOW TRANSMITTER								
28.130	TFF2905-29 AAF1262 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-AUG-2013 5307:35 4605		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	963.87.22.301 1282 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	963.87.22.301 1279 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280025	FUEL FILTER ASSY								
28.025	968.35.21.001 00411 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	973.81.14.102 1021 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2941 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3286 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 854 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 854 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 863 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 691 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			25-MAR-2016 6551 5845		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B5648A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2946 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3283 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280080	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 859 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280085	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 862 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280090	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 861 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
280095	FUEL QUANTITY,OUTER SENSOR								
28.060	975.37.31.231 1175 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-SEP-2017 7456:55 6656		
280100	RIGHT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B5649A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
CHAPTER 29 HYDRAULIC POWER									
29-10/151 (s)	RETURN LINE FILTER DIIERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 29-10-04								
29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: See Workcard								
29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: See Workcard								
29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: AMM 29-10-02	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
29-10/418	NITROGEN ACCUMULATOR 960.30.01.291	MOS		N:0			28-OCT-2003		
29.020	0461	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000	N:0			0	30000	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS					28-OCT-2003		
	REF: AMM 29-10-02	HRS/MSC AFL	N/A				0 0		
290005	LANDING GEAR STEER SELECTOR VALVE 960.30.01.271	MOS		O:8			23-DEC-2016		
29.040	0931ABC	HRS/MSC	O/C	O:0			6936:40		
	REF: GENERIC NO REF	AFL		O:0			6210		
290015	PRESSURE GAGE SWITCH 973.81.14.307	MOS		N:0			06-FEB-2014		
29.050	0595	HRS/MSC	O/C	N:0			5394:50		
	REF: GENERIC NO REF	AFL		N:0			4695		
290025	SERVICE SELECTOR VALVE 960.30.01.261	MOS		N:0			28-OCT-2003		
29.070	G0320095A	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-10-05	AFL		N:0			0		
290030	PRESSURE GAUGE 965.61.88.101	MOS		N:0			28-OCT-2003		
29.080	304089	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290035	(K 601) RELAY								
29.090	974.09.26.112 P796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
290040	HAND PUMP								
29.030	529.21.12.021 431 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	973.81.14.306 0495 REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
291010	HYDRAULIC POWER PACK								
29.010	960.30.01.154 G0330124 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS - 960.30.02.101 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	+6m/-6m N:0 N:0 N:0			01-DEC-2017 7582:40 6775	01-DEC-2022	01-JUN-2023

CHAPTER 30 ICE AND RAIN PROTECTION

30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 30-10-00								
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999						PKG		
	PKG 20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: See Workcard								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 21	MOS	12	+10%/-10%			PKG		
	REF: AMM 30-10-00	HRS/MSC	1200	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		
30-10/79 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING REF: GENERIC NO REF	MOS	6	+10%/-10%	2		PKG	16-APR-2020	18-OCT-2020 05-NOV-2020
		HRS/MSC					8778:15		
		AFL					7824		
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 21	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		
30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC	600	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 22	MOS	24	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC	2400	+10%/-10%			03-AUG-2018		
		AFL					8020:35		
							7175		
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 30-60-00	HRS/MSC	600	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC	600	+10%/-10%			03-OCT-2019		
		AFL					8593:25		
							7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300005	PROP DE-ICE TIMER/ CONTROLLER 4E3163-2	MOS					13-JUN-2019		
30.140	U4203 REF: AMM 30-60-01	HRS/MSC AFL	O/C				8402:50 7503		
300010	LPMI LINEAR ACTUATOR 978.73.15.301	MOS		N:0			28-OCT-2003		
30.150	29210 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
300015	REGULATOR-RELIEVER ASSY 959.89.01.012	MOS		N:0			28-OCT-2003		
30.160	N0555 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
300020	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS					21-OCT-2019		
30.110	N085793 REF: AMM 30-10-02	HRS/MSC AFL	O/C				8623:30 7679		
300025	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS		N:0			28-OCT-2003		
30.120	N2353 REF: AMM 30-10-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		
300030	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS		N:0			28-OCT-2003		
30.110	N2408 REF: AMM 30-10-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE 3D2353-72	MOS		N:0			05-JUL-2019		
30.120	N172669 REF: AMM 30-10-02	HRS/MSC AFL	O/C	N:0 N:0			8457:05 7550		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008	MOS		N:0			28-OCT-2003		
30.130	N2421 REF: AMM 30-10-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	973.81.14.312 2017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300050	WATER SEPARATOR								
30.060	959.89.01.010 B-1350 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.014 U2601 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C				18-OCT-2019 8623:30 7679		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114034 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 114036 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 2032 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 2028 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2048 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 2046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.041 NEU0480 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-APR-2019 8341:25 7449		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NDY2080 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-DEC-2017 7582:40 6775		
300100	RH INBD-WING DE-ICER BOOT								
30.040	959.89.01.038 NEB5800 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C				05-APR-2019 8330:50 7440		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	P27-7D5221-24 NET0500 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-APR-2019 8341:25 7449		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.022 NCX4030 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			13-APR-2017 7080:50 6348		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NDW5740 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-DEC-2017 7582:40 6775		
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"								
	REF:	MOS HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659	8893:25	8923:25

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-50/34	CAWS & CACU CLOCK BATTERY								
	972.81.32.050	MOS	24	+10%/-10%	N:0	-50	05-APR-2019	14-FEB-2021	26-APR-2021
31.010	SN-UNKNOWN	HRS/MSC			N:0		8330:50		
DISCARD	REF: AMM 31-50-03	AFL			N:0		7440		
<hr/>									
310020	FLAP POSITION INDICATOR								
	975.44.16.203	MOS			N:0		28-OCT-2003		
31.090	00394	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
<hr/>									
310035	CAWS COMPUTER								
	972.81.32.030	MOS					05-APR-2019		
31.050	171	HRS/MSC	O/C				8330:50		
	REF: See Workcard	AFL					7440		
<hr/>									
310040	CAWS DISPLAY								
	972.81.32.031	MOS			N:0		28-OCT-2003		
31.060	131	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-50-02	AFL			N:0		0		
<hr/>									
310050	DIGITAL CLOCK								
	999.61.11.212	MOS			N:0		28-OCT-2003		
31.040	1019163	HRS/MSC	O/C		N:0		0		
	REF: See Workcard	AFL			N:0		0		
<hr/>									
CHAPTER 32 LANDING GEAR									
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: AMM 12-20-04	AFL					7659		
<hr/>									
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 20	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%					
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING	MOS					28-OCT-2003 0	25000	
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0	30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING	MOS					28-OCT-2003 0	25000	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0	30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK	MOS					28-OCT-2003 0	25000	
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0	30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS					28-OCT-2003 0	25000	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0	30000	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/436	REMOVE/CLEAN MLG SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS. EXAMINE FOR CORROSION. IF CORRODED, REPLACE BOLT WITH LATEST BOLT PART NUMBER. IF NOT CORRODED, APPLY GREASE P04-028 AND INSTALL THE BOLT.	MOS HRS/MSC AFL	12	+10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2020	09-NOV-2020
	REF: AMM 32-10-00								
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS HRS/MSC AFL	72				25-MAR-2016 6551 5845	25-MAR-2022	
	REF: AMM 32-10-00								
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS HRS/MSC AFL	72				25-MAR-2016 6551 5845	25-MAR-2022	
	REF: AMM 32-10-00								
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS HRS/MSC AFL	12	+10%/-10%		-61	03-OCT-2019 8593:25 7659	03-AUG-2020	09-SEP-2020
32.030			T/C						
	REF: AMM 12-20-06								
+ 32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES	MOS HRS/MSC AFL	12	+1m/-1m		-61	03-OCT-2019 8593:25 7659	03-AUG-2020 10993:25	03-SEP-2020 11233:25
32.010			2400	+10%/-10%					
	REF: AMM 32-10-00								
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE	MOS HRS/MSC AFL	12	+10%/-10%			03-OCT-2019 8593:25 7659		
	PKG 20		600	+10%/-10%					
	REF: AMM 32-20-00								
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR	MOS HRS/MSC AFL	12	+10%/-10%			03-OCT-2019 8593:25 7659		
	PKG 20		600	+10%/-10%					
	REF: AMM 12-20-04								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
32-20/266 (s)	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 532.50.12.064 SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-FEB-2014 5394:50 4695		
32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				07-DEC-2012 4896:05 4185		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/403	NOSE LANDING GEAR								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0		25000
OVERHAUL	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
32-20/416	NOSE LANDING GEAR DRAG LINK								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	N:0			0		30000
32-20/5 (s)	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
	532.20.12.296	MOS		N:0			07-DEC-2012		
32.020	N/A	HRS/MSC	O/C	N:0			4896:05		
	REF: AMM 32-20-05	AFL		N:0			4185		
32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	1200	+10%/-10%			8593:25		
	REF: AMM 32-30-00	AFL					7659		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
	960.30.01.103	MOS		N:0			28-OCT-2003		
32.040	0913E	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:0			0		30000
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
	960.30.01.105	MOS					16-JUL-2009		
32.040	0932EFGH	HRS/MSC	25000	N:0			3468:53		28468:53 M
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:0			2890		32890 M
		ACH							
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				25-MAR-2016		25-MAR-2022
		HRS/MSC					6551		
	REF: AMM 32-10-00	AFL					5845		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				25-MAR-2016	25-MAR-2022	
	REF: AMM 32-10-00	HRS/MSC AFL					6551 5845		
32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 20	HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 3	HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 12-10-04	AFL					7659		
32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 20	HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 3	HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 12-10-04	AFL					7659		
32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 3	HRS/MSC	300	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY	MOS	12	+10%/-10%			03-OCT-2019		
	PKG 3	HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 12-10-02	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
	REF: AMM 32-50-00	AFL	42000				0		42000
320005	PILOT LH BRAKE MASTER CYLINDER	MOS					28-OCT-2003		
32.130	959.47.51.131	HRS/MSC	O/C	N:0			0		
	3576	AFL		N:0			0		
	REF: AMM 32-40-04			N:0			0		
320010	PILOT RH BRAKE MASTER CYLINDER	MOS					28-OCT-2003		
32.130	959.47.51.131	HRS/MSC	O/C	N:0			0		
	3577	AFL		N:0			0		
	REF: AMM 32-40-04			N:0			0		
320015	PARK BRAKE VALVE	MOS					28-OCT-2003		
32.140	959.47.51.121	HRS/MSC	O/C	N:0			0		
	2147	AFL		N:0			0		
	REF: AMM 32-40-05			N:0			0		
320020	NOSE WHEEL	MOS					05-DEC-2019		
32.150	3-1501	HRS/MSC	O/C	O:0			8677:55		
	1220	AFL		O:0			7737		
	REF: AMM 32-40-02			O:0					
320021	NOSE LANDING GEAR TIRE	MOS					05-DEC-2019		
32.155	021-327-0	HRS/MSC	O/C				8677:55		
	7289S00181	AFL					7737		
	REF: GENERIC NO REF								
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY	MOS					01-DEC-2017		
32.160	3-1543-1	HRS/MSC	O/C				7582:40		
	0973	AFL					6775		
	REF: AMM 32-40-01								
320023	LEFT MAIN LANDING GEAR TIRE	MOS					18-OCT-2018		
32.160	025-350-0	HRS/MSC	O/C	N:0			8158:45		
	8080S00323	AFL		N:0			7295		
	REF: GENERIC NO REF			N:0					

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY 3-1543-1 2187 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				05-DEC-2019 8677:55 7737		
320025	SHIMMY DAMPER ASSY 532.20.12.215 SI-0039 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C				01-DEC-2017 7582:40 6775		
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 8086S00301 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-DEC-2019 8677:55 7737		
320030	COPILOT LH BRAKE MASTER CYLINDER 959.47.51.131 3580 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 959.47.51.131 3583 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY 532.20.12.249 VLG062 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
320050	LEFT SHOCK ABSORBER ASSY 532.10.12.175 VLG153 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
320055	RIGHT SHOCK ABSORBER ASSY 532.10.12.175 VLG154 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320074	NOSE LANDING GEAR ACTUATOR								
29.060	960.30.01.111 0977A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-FEB-2014 5394:50 4695		
320075	LH BRAKE ASSY								
32.050	2-1674-1 0155 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			22-MAR-2018 7729:20 6916		
320080	RH BRAKE ASSY								
32.050	2-1674-1 1014 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-AUG-2018 8020:35 7175		
CHAPTER 33 LIGHTS									
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: See Workcard								
33-41/178 (s)	EXAMINE LANDING LIGHTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 33-41-01								
33-42/179 (s)	EXAMINE TAXI LIGHTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: AMM 33-42-01								
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		
330005	DIM UNIT 975.02.15.205	MOS						28-OCT-2003	
33.080	113487 REF: AMM 33-10-04	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
330010	DE-ICE LIGHT ASSY 972.87.67.111	MOS						28-OCT-2003	
33.010	374547 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
330015	LEFT WING POWER SUPPLY, HIDL UNIT 972.87.69.413	MOS						28-OCT-2003	
33.020	367323 REF: AMM 33-40-11	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 972.87.69.413	MOS						28-OCT-2003	
33.020	371696 REF: AMM 33-40-11	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 972.87.87.331	MOS						28-OCT-2003	
33.040	14274 REF: AMM 33-46-01	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 972.87.87.332	MOS						28-OCT-2003	
33.040	14289 REF: AMM 33-46-01	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330035	LH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 19961 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 215561-3-2 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-2019 8593:25 7659		
330045	RH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 19962 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 28290013 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			13-APR-2016 6586:05 5509		
330055	NAVIGATION (FC), BULB GREEN LIGHT								
33.050	MS25309-7512 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-JUL-2014 5723:20 5012		
330060	NAVIGATION (FC), BULB RED LIGHT								
33.050	A7512-24 SN-UNKNOWN REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-MAY-2013 5100:15 4405		
330065	NAVIGATION (FC), BULB WHITE LIGHT								
33.060	972.72.51.030 N/A REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2019 8593:25 7659		
330070	NOSE LANDING GEAR TAXI LIGHT,1X0005287-10								
	4626 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-SEP-2014 5808:35 5108		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10 9727855627 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-JUN-2014 5595 4898		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10 972.78.55.627 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-AUG-2013 5278:55 4582		
33JFL01	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00A-903A-A) REF:	MOS HRS/MSC AFL	300				03-OCT-2019 8593:25 7659	8893:25	

CHAPTER 34

NAVIGATION

34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10% +10%/-10%			PKG 18-OCT-2018 8158:45 7295		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%					
34-11/82	LEAK CHECK STATIC SYSTEM (DAC-AIR 348)	MOS	24	+10%/-10%			03-OCT-2019 8593:25 7659	03-OCT-2021	15-DEC-2021
34.010	REF: See Workcard	HRS/MSC AFL							
34-14/83	CALIBRATION CHECK ALTIMETER (DAC-AIR 348)	MOS	24				03-OCT-2019 8593:25 7659	03-OCT-2021	
34.020	REF: See Workcard	HRS/MSC AFL							
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348)	MOS	24	+10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2020	15-OCT-2020
34.030	REF: AMM 34-21-00	HRS/MSC AFL							
34-25/85	CALIBRATION ATTITUDE HEADING REFERENCE SYSTEM (AHRS) CHECK SWING	MOS	24	+10%/-10%			03-AUG-2018 8020:35 7175	03-AUG-2020	15-OCT-2020
34.040	REF: AMM 34-25-00	HRS/MSC AFL							
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348)	MOS	24	+10%/-10%	60		03-AUG-2018 8020:35 7175	02-OCT-2020	14-DEC-2020
34.050	REF: See Workcard	HRS/MSC AFL							
340005	PILOT ALTIMETER	MOS					28-OCT-2003		
31.020	985.99.11.206 03050177BA REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
340006	COPILOT ALTIMETER	MOS					28-OCT-2003		
	70256N01D01 03060187BA REF: AMM 34-14-12	HRS/MSC AFL	O/C				0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340007	NO. 1 TRANSPONDER								
34.140	985.99.11.361 31012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340007	NO. 2 ATC MODE A/C/S,KT70 SC+ TRANSPONDER								
	011-00455-10 84206654 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2016 6920:20 6194		
340009	NO. 1 DME/IFF ANTENNA								
34.080	984.81.10.240 61455 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340010	PILOT VERTICAL SPEED INDICATOR								
31.070	965.16.15.101 284732 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-APR-2009 3378:23 2810		
340014	MARKER,KR21 RECEIVER								
34.290	985.99.11.001 23262 REF: AMM 34-32-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340015	PILOT ATTITUDE INDICATOR								
31.080	975.96.11.241 25454 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2446:25			27-FEB-2013 4995:50 4276		
340020	MARKER ANTENNA								
34.100	984.81.10.260 5627 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340025	EFIS 1 SG465 SYMBOL GENERATOR								
34.300	975.96.32.402 4488 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	R:0			07-JUL-2009 3467:53 2890		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340026	STAND-BY ALTIMETER								
31.020	965.23.22.101 431664 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340030	COPILOT VERTICAL SPEED INDICATOR								
31.070	7040 7F476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-JUN-2017 7226:35 6476		
340034	EFIS 1 CONTROL,CP467 PANEL								
34.230	071-01439-3100 3446 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C				06-FEB-2015 5965:10 5283		
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY								
34.170	066-03137-3100 4418 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C				29-AUG-2018 8035:20 7190		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY								
34.170	066-03137-3100 U3153 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C				18-JUN-2014 5636:30 4935		
340044	TRIM TRIPLE INDICATOR								
31.100	975.44.16.204 00434 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340055	PILOT AIRSPEED INDICATOR								
31.110	965.12.13.334 1023713 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340059	WITH HARM FILTER,KN63 DME								
34.200	985.99.11.101 27808 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340060	COPILOT AIRSPEED INDICATOR								
31.110	965.12.13.335 1023718 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 10465 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:3 O:0 O:0			13-APR-2017 7080:50 6348		
340070	RADAR CONTROL PANEL								
34.240	985.99.11.518 2430 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	071-01549-0100 5752 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		
340080	NO. 2 TRANSPONDER								
34.080	984.81.10.240 61474 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340085	ADF,KA44B ANTENNA								
34.070	985.99.11.167 79243 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340090	GPS BRNAV,KLN90B UNIT								
34.340	985.99.11.199 40451 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	975.96.32.482 12363 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340100	FRONT KA92 GPS ANTENNA								
34.090	CI405-200 3083032 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C				14-NOV-2003 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	013-0235-00 85776 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-JUL-2013 5207:30 4513		
340105	LH NAV/GS ANTENNA								
34.380	984.81.10.280 4731 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	124282 5399 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				03-AUG-2015 6266:45 5575		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	124210-2022 1683 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				31-DEC-2019 8694 7752		
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	066-3034-02 56155 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C				12-DEC-2008 3284:13 2724		
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	985.99.11.771 10864 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340130	AIR DATA COMPUTER								
34.400	985.92.03.111 2357 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340131	KCM 805 CONFIGURATION MODULE								
34.410	985.99.11.865 11312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340135	MAGNETIC,STANDBY COMPASS								
34.130	999.98.80.103 AT-471 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340140	4206-100-V2 RADOME								
34.420	4206-100 107 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 3394 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27422 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 27428 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 09398 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 28117 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			10-JUL-2014 5680 4974		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340165	DATA BASE,ATLANTIC,KLN90 UNIT								
34.440	985.99.11.224 43413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	985.99.11.570 3454 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:136 N:5962:20 N:5280			03-FEB-2015 5962:20 5280		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-14 74996 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-MAY-2015 6120:25 5448		
340195	MULTI FUNCTION DISPLAY								
34.190	066-04035-0101 6152 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C				06-FEB-2014 5394:50 4695		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	985.90.03.045 3179 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	985.90.03.044 2836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	985.90.03.046 2884 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340215	AHRS NO2 AHRU,LCR-92,WSYNCHR,124210-2022 UNIT								
34.320	985.99.11.878 1443 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				06-JUL-2010 3763:48 3160		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 1335 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				13-NOV-2014 5883:35 5185		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	071-01549-0100 5752 REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C				06-JUL-2012 4653:20 3963		
340230	RH NAV/GS ANTENNA								
34.380	984.81.10.280 4730 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340235	AOA SENSOR RH UNIT								
34.330	012AC12 0171 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2019 8593:25 7659		
340240	NO. 1 FLUX,KMT112 VALVE								
34.350	071-1052-00 74762 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				12-JUN-2018 7904:55 7076		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	985.99.11.505 11426 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE								
34.250	975.11.20.111 01144 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340255	AOA SENSOR LH UNIT								
34.330	975.44.21.423 0637 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				06-FEB-2014 5394:50 4695		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340260	NO. 2 FLUX,KMT112 VALVE								
34.350	071-1052-00 KMT112-79695 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				31-JUL-2012 4695:40 4002		
340280	LEFT PITOT TUBE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
340285	RIGHT PITOT TUBE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
341005	LH AOA PLATE TEMP CONTROLLER								
30.170	975.44.21.417 U1022 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
341010	RH AOA PLATE TEMP CONTROLLER								
30.170	975.44.21.417 U0285 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C				12-MAR-2004 106:12		
345015	HORIZON ARTIFICIAL								
	504-0111-930 50401119325166 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2016 6920:20 6194		
34C044	GYRO,DIRECTIONAL,KG102A								
	060-015-00 22023 REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-AUG-2018 8020:35 7175		
34C047	INDICATOR RMI,KI229								
	066-3038-00 7458 REF:	MOS HRS/MSC AFL	A/R	O:0 O:0 O:0			04-FEB-2020 8735:25 7789		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348)	MOS	24	+1m/-1m			03-OCT-2019 8593:25 7659	03-OCT-2021	03-NOV-2021
	REF:	HRS/MSC AFL							
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM)	MOS	12				03-OCT-2019 8593:25 7659	03-OCT-2020	
	REF:	HRS/MSC AFL							
CHAPTER 35 OXYGEN									
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED						PKG 03-OCT-2019 8593:25 7659		
	PKG 3	MOS	12	+10%/-10%					
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG 03-OCT-2019 8593:25 7659		
	PKG 18	MOS							
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT						PKG 03-OCT-2019 8593:25 7659		
	PKG 21	MOS	12	+10%/-10%					
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM						PKG 03-OCT-2019 8593:25 7659		
	PKG 21	MOS	12	+10%/-10%					
	REF: AMM 35-00-00	HRS/MSC AFL	1200	+10%/-10%					
35-10/6	REAR FUSELAGE OXYGEN CYLINDER						22-JAN-2019 8242:25 7361	31-MAY-2022 M	
	895-06077	MOS	180						
	C07050727	HRS/MSC							
35.010	REF: AMM 35-10-01	AFL							
AIRWORTHINESS									

Status Report
PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE								
35.010	895-06077 C07050727 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				29-FEB-2016	28-FEB-2021	
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS								
35.010	REF: AMM 35-20-00	MOS HRS/MSC AFL	36	+10%/-10%		60	03-AUG-2018 8020:35 7175	02-OCT-2021	20-JAN-2022
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	MC10-06-125 SE66890 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			12-DEC-2018 8229:40 7351		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	MC10-06-125 B005549 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			12-DEC-2018 8229:40 7351		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	973.81.14.401 0430 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
350035	3-POSITION CONTROL VALVE								
35.030	963.32.11.101 1804 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
350040	ALTITUDE SENSING SWITCH								
35.020	973.81.52.102 569 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

CHAPTER 52 DOORS

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	600	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	1200	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
		MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 52-10-00	AFL	42000				0		42000
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE								
		MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
	REF: AMM 52-00-01	AFL	42000				0		42000
52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN								
		MOS					28-OCT-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 52-10-01	AFL	30000				0		30000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/472	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE	MOS					28-OCT-2003		
	REF: AMM 52-10-06	HRS/MSC	N/A				0		
		AFL					0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
52.010	REF: See Workcard	HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
		AFL					6775		
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			8593:25		
		AFL					7659		
+ 52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			8593:25		
		AFL					7659		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR						28-OCT-2003		
AIRWORTHINESS	REF: AMM 52-20-00	MOS					0	32500	
		HRS/MSC	32500				0	42000	
		AFL	42000						
52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			8593:25		
		AFL					7659		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-OCT-2019		
	REF: AMM 52-30-00	HRS/MSC	600	+10%/-10%			8593:25		
		AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	600	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS						28-OCT-2003	
		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000					0	42000
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE								
		MOS						28-OCT-2003	
		HRS/MSC	32500					0	32500
	REF: AMM 52-30-00	AFL	42000					0	42000
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN								
		MOS						28-OCT-2003	
		HRS/MSC	25000					0	25000
	REF: AMM 52-30-01	AFL	30000					0	30000
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS						28-OCT-2003	
52.020	SN-UNKNOWN	HRS/MSC	13000		N:0			0	13000
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000		N:0			0	17000
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
		MOS	48	+10%/-10%		16		01-DEC-2017	17-DEC-2021
52.030		HRS/MSC	4000	+10%/-10%				7582:40	11982:40
	REF: See Workcard	AFL						6775	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM PKG 21	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: AMM 52-70-00	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		
520005	PASSENGER DOOR 552.05.12.007	MOS						28-OCT-2003	
52.050	424 REF: AMM 52-10-01	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0		
520010	FREIGHT OF 10SERIE DOOR ASSY 552.05.12.010	MOS						28-OCT-2003	
52.040	424 REF: AMM 52-30-01	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0		
520015	EMERGENCY 6 SERIE EXIT 552.05.12.009	MOS						28-OCT-2003	
52.060	424 REF: AMM 52-20-00	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0		
CHAPTER 53	FUSELAGE								
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS. PKG 3	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			8593:25 7659		
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD PKG 22	MOS	24	+10%/-10%			PKG	03-AUG-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			8020:35 7175		
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED PKG 21	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 22	MOS	24	+10%/-10%				03-AUG-2018	
		HRS/MSC	2400	+10%/-10%				8020:35	
	REF: GENERIC NO REF	AFL						7175	
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%				03-AUG-2018	
		HRS/MSC	2400	+10%/-10%				8020:35	
	REF: GENERIC NO REF	AFL						7175	
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						28-OCT-2003	
		HRS/MSC	N/A					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: AMM 53-20-02	AFL						7659	
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS						28-OCT-2003	
		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 53-10-06	AFL	42000					0	42000
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS						28-OCT-2003	
		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000					0	42000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
	REF: See Workcard	AFL	42000				0		42000
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					28-OCT-2003		
53.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%			01-DEC-2017	17-DEC-2021	11-MAY-2022
53.030		HRS/MSC	4000	+10%/-10%	16		7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT, WITH INSULATION REMOVED)	MOS	48	+10%/-10%			01-DEC-2017	17-DEC-2021	11-MAY-2022
53.040		HRS/MSC	4000	+10%/-10%	16		7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED	MOS	48	+10%/-10%			01-DEC-2017	17-DEC-2021	11-MAY-2022
53.070		HRS/MSC	4000	+10%/-10%	16		7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS	MOS	48	+10%/-10%			01-DEC-2017	17-DEC-2021	11-MAY-2022
53.050		HRS/MSC	4000	+10%/-10%	16		7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES	MOS	48	+10%/-10%			01-DEC-2017	17-DEC-2021	11-MAY-2022
53.060		HRS/MSC	4000	+10%/-10%	16		7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		

CHAPTER 55 STABILIZERS

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270030	FIN ASSY 555.30.12.037 424 REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				28-OCT-2003 0 0	20000 27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009) REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				28-OCT-2003 0 0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 21 REF: AMM 55-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
55-10/415	HORIZONTAL STABILIZER PN SN-UNKNOWN REF: AMM 55-10-01	MOS HRS/MSC AFL	25000 30000				28-OCT-2003 0 0	25000 30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED) REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED) REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%	16		01-DEC-2017 7582:40 6775	17-DEC-2021 11582:40	11-MAY-2022 11982:40

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/362	EXAMINE LEFT ELEVATOR								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 55-20/362	EXAMINE RIGHT ELEVATOR								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-20/368	EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES								
		MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF:	AFL					7659		
55-30/199 (s)	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG	03-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			8593:25		
		AFL					7659		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					28-OCT-2003		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					28-OCT-2003		
	REF: AMM 55-30-03	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/373	EXAMINE - RUDDER	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
	REF: AMM 55-40-04	AFL	42000				0		42000
CHAPTER 56 WINDOWS									
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 56-00-00	AFL					7659		
56-11/12	REPLACE COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS								
	PN	MOS		N:0			28-OCT-2003		
56.020	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
AIRWORTHINESS	REF: AMM 56-20-01	AFL		N:0			0		
56-11/13	REPLACE COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS								
	PN	MOS		N:0			28-OCT-2003		
	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
	REF: See Workcard	AFL		N:0			0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)								
	959.81.10.109	MOS					02-JUN-2014		
	13346H8940	HRS/MSC	A/R				5591:10		
	REF: GENERIC NO REF	AFL					4894		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)								
	959.81.10.110	MOS					10-MAR-2011		
	10296H5486	HRS/MSC	A/R				3990:33		
	REF: GENERIC NO REF	AFL					3376		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)								
	959.81.10.109	MOS					02-JUN-2014		
	13346H8940	HRS/MSC	A/R				5591:10		
	REF: GENERIC NO REF	AFL					4894		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 959.81.10.110 10296H5486 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				10-MAR-2011 3990:33 3376		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500		-101	06-FEB-2014 5394:50 4695	28-OCT-2023 16394:50	28-APR-2024 16894:50
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS REF: See Workcard	MOS HRS/MSC AFL	32500 42000				28-OCT-2003 0 0	32500 42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 3 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
560015	SIDE,LH WINDOW 959.81.10.111 02196H1064 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		
560020	SIDE,RH WINDOW 959.81.10.112 02198H1357 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		
560025	RH NO 1 CABIN WINDOW 556.20.12.029 3448 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560030	RH NO 2 CABIN WINDOW								
56.060	556.20.12.029 3464 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	556.20.12.029 3465 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	556.20.12.029 3466 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	556.20.12.029 3467 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	556.20.12.029 3473 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	556.20.12.029 3475 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	556.20.12.029 3478 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	556.20.12.029 3481 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560070	DV-WINDOW ASSY								
56.030	556.14.12.100 15166H5808 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2015 6405:35 5696		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010	959.81.10.109 13346H8940 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-JUN-2014 5591:10 4894		
AIRWORTHINESS									
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
56.010	959.81.10.110 10296H5486 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-MAR-2011 3990:33 3376		
AIRWORTHINESS									
CHAPTER 57	WINGS								
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010		MOS HRS/MSC AFL	20000 27000				28-OCT-2003 0 0	20000 27000	
AIRWORTHINESS	REF: GENERIC NO REF								
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
57.010		MOS HRS/MSC AFL	20000 27000				28-OCT-2003 0 0	20000 27000	
AIRWORTHINESS	REF: GENERIC NO REF								
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
	REF: GENERIC NO REF								
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 22	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			03-AUG-2018 8020:35 7175		
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 21	MOS	12	+10%/-10%				03-OCT-2019	
		HRS/MSC	1200	+10%/-10%				8593:25	
	REF: GENERIC NO REF	AFL						7659	
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A					0	
		AFL						0	
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A					0	
		AFL						0	
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000					0	30000
		AFL	39000					0	39000
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000					0	30000
		AFL	39000					0	39000
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000					0	30000
		AFL	39000					0	39000
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT								
		MOS						28-OCT-2003	
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000					0	25000
		AFL	30000					0	30000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/412	EXAMINE WING TIPS	MOS					28-OCT-2003		
	REF: AMM 57-33-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					28-OCT-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 57-20-01	AFL	30000				0		30000
<hr/>									
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					28-OCT-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 57-20-01	AFL	30000				0		30000
<hr/>									
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					28-OCT-2003		
		HRS/MSC	16000				0		16000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0		22500
<hr/>									
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					28-OCT-2003		
		HRS/MSC	16000				0		16000
	REF:	AFL	22500				0		22500
<hr/>									
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
57.020		HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
<hr/>									
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%		16	01-DEC-2017	17-DEC-2021	11-MAY-2022
57.030		HRS/MSC	4000	+10%/-10%			7582:40	11582:40	11982:40
	REF: GENERIC NO REF	AFL					6775		
<hr/>									
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m		-101	06-FEB-2014	28-OCT-2023	28-APR-2024
57-00/99		HRS/MSC	11000	+500/-500			5394:50	16394:50	16894:50
	REF: AMM 57-00-00	AFL					4695		
<hr/>									
57-60/393	EXAMINE LEFT WINGAILERON	MOS					28-OCT-2003		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 57-60-00	AFL	42000				0		42000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60/393	EXAMINE RIGHT WING AILERON	MOS					28-OCT-2003		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-60/411	EXAMINE AILERON TRIM TAB	MOS					28-OCT-2003		
	REF: AMM 57-60-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
570010	AILERON RH 10A SERIE ASSY	MOS					28-OCT-2003		
57.050	557.05.12.011 435	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-01	AFL		N:0			0		
570015	WING RE 10A SERIE STRUCTURE	MOS					28-OCT-2003		
57.070	557.05.12.127 429	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
570025	AILERON LH 10A SERIE ASSY	MOS					28-OCT-2003		
57.050	557.05.12.012 435	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-01	AFL		N:0			0		
570035	WING LE 10A SERIE STRUCTURE	MOS					28-OCT-2003		
57.070	557.05.12.128 429	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 61	PROPELLERS/PROPULSORS								
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 21	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	1200	+10%/-10%			8593:25		
	REF: GENERIC NO REF	AFL					7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E4A-3D/E10477SK KX1346 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C	N:2157:55			01-MAY-2019 8357:30 7460		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	3049558-01 21234393 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
OVERHAUL									
+ 612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
	3079148-01 21238755 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
OVERHAUL									
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1346 Part # HC-E4A-3D/E10477SK									
+ 610010	NO. 1 PROPELLER - OVERHAUL								
		MOS HRS/MSC	72 4000				26-MAR-2015 0	26-MAR-2021 (4000) 10199:35	
OVERHAUL	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION								
		MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			03-OCT-2019 2357:15	03-OCT-2020 (2657:15) 8856:50	03-NOV-2020 2687:15
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER								
		MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			03-OCT-2019 2357:15	03-OCT-2020 (2657:15) 8856:50	03-NOV-2020 2687:15
	REF:								
610040	NO. 1 PROPELLER - INSPECT MECHANICAL TACHOMETER								
		MOS HRS/MSC	N/A				26-MAR-2015 0		
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610070	NO. 1 PROPELLER - PRE-FLIGHT CHECKS	MOS HRS/MSC	A/R				26-MAR-2015 0		
	REF:								
+ 610080	NO. 1 PROPELLER - OPERATIONAL CHECKS	MOS HRS/MSC	A/R				26-MAR-2015 0		
	REF:								
+ 610510	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE	MOS HRS/MSC	A/R				26-MAR-2015 0		
	UNSCHEDULED MAINTENANCE CHECK								
	REF:								
+ 610520	NO. 1 PROPELLER - LIGHTNING STRIKE	MOS HRS/MSC	A/R				26-MAR-2015 0		
	UNSCHEDULED MAINTENANCE CHECK								
	REF:								
+ 610530	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE	MOS HRS/MSC	A/R				26-MAR-2015 0		
	UNSCHEDULED MAINTENANCE CHECK								
	REF:								
+ 610540	NO. 1 PROPELLER - FIRE/HEAT DAMAGE	MOS HRS/MSC	A/R				26-MAR-2015 0		
	UNSCHEDULED MAINTENANCE CHECK								
	REF:								
+ 610550	NO. 1 PROPELLER - SUDDEN STOPPAGE	MOS HRS/MSC	A/R				26-MAR-2015 0		
	UNSCHEDULED MAINTENANCE CHECK								
	REF:								

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
+ 610560	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION	MOS						26-MAR-2015		
		HRS/MSC	A/R					0		
UNSCHEDULED MAINTENANCE CHECK	REF:									
+ 610570	NO. 1 PROPELLER - LONG TERM STORAGE	MOS						26-MAR-2015		
		HRS/MSC	A/R					0		
	REF:									
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE	MOS						26-MAR-2015		
	9682913023	HRS/MSC	O/C	N:0				0		
	L57203			N:0						
	REF: GENERIC NO REF									
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE	MOS						26-MAR-2015		
	9682913023	HRS/MSC	O/C	N:0				0		
	L57207			N:0						
	REF: GENERIC NO REF									
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE	MOS						26-MAR-2015		
	9682913023	HRS/MSC	O/C	N:0				0		
	L57201			N:0						
	REF: GENERIC NO REF									
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE	MOS						26-MAR-2015		
	9682913023	HRS/MSC	O/C	N:0				0		
	L57205			N:0						
	REF: GENERIC NO REF									
CHAPTER 71	POWER PLANT									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG			
	PKG 20	MOS	12	+10%/-10%				03-OCT-2019		
71.010		HRS/MSC	600	+10%/-10%				8593:25		
	REF: AMM 71-00-00	AFL						7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE PKG 20	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 71-00-00	HRS/MSC AFL	600	+10%/-10%					
71-00/103	PERFORM COMPRESSOR & TURBINE WASH	MOS					03-OCT-2019 8593:25 7659		
71.040	REF:	HRS/MSC AFL	300	+10%/-10%				8893:25	8923:25
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS PKG 20	MOS	12	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
71.030	REF: AMM 71-00-03	HRS/MSC AFL	600	+10%/-10%					
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME 571.20.12.036	MOS					28-OCT-2003 0		
71.050	429	HRS/MSC	20000	N:0				20000	
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000	N:0			0	27000	
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS	MOS					02-OCT-2009 3571:05 2975		
71.050	REF: AMM 71-00-04	HRS/MSC AFL	11000					14571:05	
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION PKG 17 ,3	MOS					PKG 03-OCT-2019 8593:25 7659		
	REF: AMM 71-00-00	HRS/MSC AFL	A/R						
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP PKG 22	MOS	24	+10%/-10%			PKG 03-AUG-2018 8020:35 7175		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%					

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT PKG 17 ,3 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-AUG-2018 8020:35 7175		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9581 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500/E/C	+1000	N:0 N:0 N:0		03-AUG-2018 8020:35 7175	11520:35	12520:35
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 10812 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500/E/C	+1000	N:0 N:0 N:0		03-AUG-2018 8020:35 7175	11520:35	12520:35
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9678 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500/E/C	+1000	N:0 N:0 N:0		03-AUG-2018 8020:35 7175	11520:35	12520:35
71-00/38 71.060	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9721 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500/E/C	+1000	N:0 N:0 N:0		03-AUG-2018 8020:35 7175	11520:35	12520:35

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 9720 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500/E/C +1000	N:0 N:0 N:0			03-AUG-2018 8020:35 7175	11520:35	12520:35
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT AIRWORTHINESS REF: AMM 71-00-05	MOS HRS/MSC AFL	26600 35000				28-OCT-2003 0 0	26600 35000	
71-00/476 (s)	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS PKG 17 ,3 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 17 ,3 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION PKG 17 ,3 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 03-OCT-2019 8593:25 7659		
710005	UPPER LH ENGINE VIBRATION ISOLATOR 571.20.12.106 1062 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR 571.20.12.106 1066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR 571.20.12.106 1070 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710035	LOWER LH ENGINE VIBRATION ISOLATOR								
71.100	571.20.12.106 1074 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	571.20.12.106 1079 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3042200 PCE-PR0796 REF: AMM 71-00-01	MOS HRS/MSC AFL ACH	E/C	N:0 N:0			30-JUL-2018 8020:35 7175		
71JFL05	PERFORM ENGINE RUN-UP								
	REF:	MOS HRS/MSC AFL	A/R				12-NOV-2010 3909:33 3308		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 710011	NO. 1 ENGINE - OVERHAUL								
	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500			24-MAY-2018 0 0	(3500) 11520:35	4000
+ 710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 2 ,3 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			03-OCT-2019 572:50 484		
+ 710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			24-MAY-2018 0 0	(1750) 9770:35	2000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710031	NO. 1 ENGINE - BORESCOPE	HOT SECTION							
		MOS					03-OCT-2019		
	REF: EMM 72-00-00	HRS/MSC	300	+10%/-10%			572:50	(872:50) 8893:25	902:50
		ENC					484		
+ 710041	NO. 1 ENGINE - INSPECT POWER	TURBINE BLADES							
		MOS					18-OCT-2018		
		HRS/MSC	4000	+100/-100			138:10	(4138:10)	4238:10
	REF: EMM 72-00-00	ENC					120	12158:45	
+ 710051	NO. 1 ENGINE - COMPRESSOR WASH	PERFORMANCE RECOVERY AND DESALINATION							
		MOS					24-MAY-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		
+ 710061	NO. 1 ENGINE - PERFORM	ENGINE CONDITION TREND MONITORING (ECTM)							
		MOS					03-OCT-2019		
	REF: EMM 72-00-00	HRS/MSC	300				572:50	(872:50) 8893:25	
		ENC					484		
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						PKG		
	PKG 2 ,3	MOS					03-OCT-2019		
	REF: EMM 71-00-00	HRS/MSC	300	+10%/-10%			572:50		
		ENC					484		
710100 (s)	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE								
		MOS					18-OCT-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				138:10		
		ENC					120		

CHAPTER 72	ENGINE
ENGINE NO. 1	Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200
+ 720010	NO. 1 ENGINE - GAS GENERATOR MODULE
	PN
	SN-UNKNOWN
	REF: See Workcard
OVERHAUL	
	MOS
	HRS/MSC
	ENC
	3500
	+500
	N:0
	N:0
	N:0
	24-MAY-2018
	0
	(3500) 11520:35
	0
	4000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
720020	NO. 1 ENGINE - COMPRESSOR AIR INLET SCREEN REF: EMM 72-20-00	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				18-OCT-2018 138:10 120		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				18-OCT-2018 138:10 120		
+ 720025	NO. 1 ENGINE - OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS REF: EMM 72-11-00	MOS HRS/MSC ENC	A/R				18-OCT-2018 138:10 120		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 2 ,3 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 722011	NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 2 ,3 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 722030	NO. 1 ENGINE - IMMERSION IN WATER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3039001 FRAEPWNL47 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:0 N:0			24-MAY-2018 0 0 (24000) 31175		
+ 723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA769675 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:0 N:0			24-MAY-2018 0 0 (24000) 31175		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 2 ,3 REF: EMM 72-30-04	MOS HRS/MSC ENC	300	+10%/-10%			03-OCT-2019 572:50 484		
+ 723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040952 MCAKAXTL198 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				24-MAY-2018 0 0	(24000) 31175	
+ 723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE REF: EMM 72-00-00	MOS HRS/MSC A/R ENC					24-MAY-2018 0 0		
+ 723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 2 ,3 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			03-OCT-2019 572:50 484		
+ 723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 FRAEPWMK16 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				24-MAY-2018 0 0	(24000) 31175	
+ 723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAE000L278 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				24-MAY-2018 0 0	(24000) 31175	
+ 723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 FRAEPWMN55 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				24-MAY-2018 0 0	(24000) 31175	

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS					24-MAY-2018		
	UNSCCHEDULED MAINTENANCE CHECK	HRS/MSC	A/R				0		
	REF: See Workcard	ENC					0		
+ 724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724020	NO. 1 ENGINE - HIGH OIL PRESSURE	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724050	NO. 1 ENGINE - MATERIAL INGESTION	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN	MOS					24-MAY-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725003	NO. 1 ENGINE - OVERSPEED	MOS						24-MAY-2018	
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
+ 725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS						24-MAY-2018	
	3053740-01	HRS/MSC		N:0			0		
	YUAB001K898	ENC	8000	N:0			0		(8000) 15175
LIFE LIMIT	REF: GENERIC NO REF			N:0			0		
+ 725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS						24-MAY-2018	
	REF: GENERIC NO REF	HRS/MSC	5000				0		(5000) 13020:35
LIFE LIMIT		ENC					0		
725022	NO. 1 ENGINE - 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS						24-MAY-2018	
	PN	HRS/MSC		N:0			0		
	SN-UNKNOWN	ENC	H/T	N:0			0		
	REF: GENERIC NO REF			N:0			0		
+ 725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS						PKG	
	PKG 2 ,3	HRS/MSC	300	+10%/-10%			03-OCT-2019		
	REF: EMM 72-50-05	ENC					572:50		
							484		
+ 725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS						24-MAY-2018	
	3037312	HRS/MSC		N:0			0		
	A00485BA	ENC	15000	N:0			0		(15000) 22175
LIFE LIMIT	REF: GENERIC NO REF			N:0			0		
+ 725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS						24-MAY-2018	
	3037313	HRS/MSC		N:0			0		
	YUAB001L056	ENC	15000	N:0			0		(15000) 22175
LIFE LIMIT	REF: GENERIC NO REF			N:0			0		
725050	NO. 1 ENGINE - COMPRESSOR TURBINE BLADES	MOS						24-MAY-2018	
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	ENC		N:0			0		
	REF: GENERIC NO REF			N:0			0		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 1 ENGINE - ACCESSORY GEARBOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500 N:0 N:0 N:0			24-MAY-2018 0 0	(3500) 11520:35	4000
726030	NO. 1 ENGINE - ELECTRICAL FILLER CAP AND INDICATOR, OIL-LEVEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
+ 726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		

CHAPTER 73 ENGINE FUEL AND CONTROL

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731010	NO. 1 ENGINE - FUEL PUMP 3040760 016070 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	N:0 N:0 N:0			24-MAY-2018 0 0	(3500) 11520:35	
	OVERHAUL								
+ 731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	300	+10%/-10%			03-OCT-2019 572:50 484	(872:50) 8893:25	902:50
+ 731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51806 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
+ 731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 ,3 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 016070 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			03-OCT-2019 572:50 484	(1172:50) 9193:25	1232:50
+ 731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 2 ,3 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 016070 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 NSN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			05-APR-2019 310:15 265	(910:15) 8930:50	970:15
+ 731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA57209 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
+ 731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			03-OCT-2019 572:50 484	(872:50) 8893:25	902:50
+ 731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0966 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731080	NO. 1 ENGINE - FUEL BOOST PUMP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 2 ,3 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-10 21259572 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
+ 731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 ,3 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%	27:10		03-OCT-2019 572:50 484	(900) 8920:35	930
+ 731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2 ,3 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 3059779-01 NSN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T	N:0 N:0 N:0			05-APR-2019 310:15 265		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010	NO. 1 ENGINE - FUEL FLOW TRANSMITTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2 ,3 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			24-MAY-2018 0 0	(900) 8920:35	990
733030	NO. 1 ENGINE - MAIN FUEL FILTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
733040	NO. 1 ENGINE - MAIN FUEL FILTER DRAIN VALVE PN SN-UNKNOWN REF: EMM 73-10-06	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
733050	NO. 1 ENGINE - AFT FUEL DRAIN VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
733060	NO. 1 ENGINE - FORWARD FUEL DRAIN VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
+ 733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 3 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 74 IGNITION									
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF: AMM 74-00-00	AFL					7659		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
+ 740010	NO. 1 ENGINE - IGNITION EXCITER								
	3035889	MOS					24-MAY-2018		
	NNA18140326	HRS/MSC	3500	+500			0	(3500) 11520:35	4000
	REF: EMM 74-10-00	ENC					0		
+ 740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION								
		MOS					03-OCT-2019		
		HRS/MSC	300				572:50	(872:50) 8893:25	
	REF: EMM 74-10-00	ENC					484		
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG								
	PN	MOS					24-MAY-2018		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
+ 740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION								
		MOS					03-OCT-2019		
		HRS/MSC	300	+10%/-10%			572:50	(872:50) 8893:25	902:50
	REF: EMM 74-20-00	ENC					484		
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG								
	PN	MOS					24-MAY-2018		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
+ 742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION								
		MOS					03-OCT-2019		
		HRS/MSC	300	+10%/-10%			572:50	(872:50) 8893:25	902:50
	REF: EMM 74-20-00	ENC					484		
CHAPTER 75 AIR									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX1001362 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		24-MAY-2018 0 0	(3500) 11520:35	4000
CHAPTER 76	ENGINE CONTROLS								
76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 18 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 03-OCT-2019 8593:25 7659		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-OCT-2019 8593:25 7659		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES 76.010 REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+1m/-1m +10%/-10%		-61	03-OCT-2019 8593:25 7659	03-AUG-2020 11593:25	03-SEP-2020 11893:25

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760015	MANUAL OVERRIDE CABLE ASSY.								
76.020	941.94.11.417 20030032 REF: AMM 76-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
760020	CONDITION CABLE ASSY.								
76.030	941.94.11.418 20030039 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		
760025	POWER CONTROL CABLE ASSY.								
76.040	941.94.11.419 20107336 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-SEP-2015 6330:10 5628		

ENGINE NO. 1	Model : PT6A-67B	Serial # PCE-PR0796	Part # 3042200						
+ 761011 (s)	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES						PKG		
	PKG 2 ,3	MOS					03-OCT-2019		
		HRS/MSC	300	+10%/-10%			572:50		
	REF: EMM 72-00-00	ENC					484		

CHAPTER 77	ENGINE INDICATING								
77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM						PKG		
	PKG 3	MOS	12	+10%/-10%			03-OCT-2019		
		HRS/MSC	300	+10%/-10%			8593:25		
	REF: See Workcard	AFL					7659		

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206 6743-3-720 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-OCT-2003 0 0		

770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	975.21.15.212 2342053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-MAR-2018 7729:20 6916		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.017 537 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2019 8593:25 7659		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200

770090	NO. 1 ENGINE - T1 THERMOCOUPLE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NRA103360 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
771020	NO. 1 ENGINE - T5 TERMINAL BLOCK								
	PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		

CHAPTER 78 EXHAUST

78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		

CHAPTER 79 OIL

79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY.						PKG		
	PKG 20 REF: AMM 24-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-OCT-2019 8593:25 7659		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 3	MOS	12	+10%/-10%			PKG		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%			03-OCT-2019 8593:25 7659		
79-20/43	OIL COOLER 968.32.14.102	MOS					22-MAR-2018		
79.010	T0600 REF: AMM 79-20-02	HRS/MSC AFL	4000	+500	O:0 O:0 O:0		7729:20 6916	11729:20	12229:20
790005	TEMPERATURE BULB 975.11.20.101	MOS					28-OCT-2003		
79.020	119985 REF: AMM 79-30-03	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0		
790020	PRESSURE,GAGE SWITCH 973.81.14.305	MOS					28-OCT-2003		
79.030	0445 REF: AMM 79-30-04	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0		
790025	THERMAL ACTUATOR 978.73.01.002	MOS					28-OCT-2003		
79.040	0574 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0796 Part # 3042200									
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					24-MAY-2018		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
+ 790031 (s)	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR PKG 3	MOS					PKG		
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			03-OCT-2019 572:50 484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+10%/-10%			03-OCT-2019 572:50 484	03-OCT-2020 (872:50) 8893:25	902:50
+ 790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT REF: EMM 79-20-02	MOS HRS/MSC ENC	900	+10%/-10%			24-MAY-2018 0 0	(900) 8920:35	990
+ 790060 (s)	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN PKG 3 REF: EMM 79-20-02	MOS HRS/MSC ENC	300				PKG 03-OCT-2019 572:50 484		
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN REF: EMM 72-60-00	MOS HRS/MSC ENC	300	+10%/-10%	27:10		03-OCT-2019 572:50 484	(900) 8920:35	930
+ 790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE REF: EMM 79-20-02	MOS HRS/MSC ENC	A/R				24-MAY-2018 0 0		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				24-MAY-2018 0 0		
+ 790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		
+ 790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2 ,3 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-OCT-2019 572:50 484		

Status Report

PC12/45 S/N 522 (LX-JFH): 8824:05 HRS, 7863 AFL as of 17-Jun-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 18-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792011	NO. 1 ENGINE - OIL FILTER BYPASS CHECK VALVE PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792020	NO. 1 ENGINE - THERMOSTATIC BYPASS CHECK VALVE PN SN-UNKNOWN REF: EMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792040	NO. 1 ENGINE - LOW OIL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792050	NO. 1 ENGINE - OIL DRAIN SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792060	NO. 1 ENGINE - OIL LEVEL SIGHT GAGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		
792070	NO. 1 ENGINE - OIL TANK PRESSURIZING VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-MAY-2018 0 0		