

OWNER: GREEN SERVICES CVBA
ADDRESS: 3 RODERVELDLAAN
 ANTWERPEN ANTWERP 2600

OPERATOR: DAHER TARBES
ADDRESS: AEROPORT DE
 TARBES-LOURDES-PYRENEES
 TARBES CEDEX 9 65921

PHONE: +33-(0)5-62-41-73-00
FAX: +33-(0)5-62-41-73-05

ANALYST: MAXIME MOREAU +33-1.55.93.47.74 (DIRECT)
EMAIL: MAXIME.MOREAU@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; Requirement Items Only: CHECKED;

AIRCRAFT SERIAL/REGNO: 419/OO-EXE **MODEL:** TBM 700N **MANUFACTURER:** DAHER

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 04-OCT-2007	2727:57 A/C HRS	as of 19-AUG-2021	A/C HRS	as of ___/___/___
	1962 AFL	as of 19-AUG-2021	AFL	as of ___/___/___
	1962 FLTS	as of 19-AUG-2021	FLTS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-RV0075/3071016-01 **MODEL:** PT6A-66D **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 10-DEC-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	1 A/C HRS	2727:57 ENG. HRS	as of 19-AUG-2021	ENG. HRS	as of ___/___/___
ENC		1962 ENC	as of 19-AUG-2021	ENC	as of ___/___/___

PROPELLER NO SERIAL/PART: HH2965/HC-E4N-3/E9083SK **MODEL:** HC-E4N-3 **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 04-FEB-2021		LAST ACTUALS		CURRENT ACTUAL	
2520:10 PROP HRS	2593:54 A/C HRS	2656:53 PROP HRS	as of 19-AUG-2021	PROP HRS	as of ___/___/___



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-20-01	STANDARD PROGRAM - FIRST INSPECTION								
05.040	PKG 1 REF: TLMC 05-20-01	MOS HRS/MSC AFL	-						
05-20-02	STANDARD PROGRAM - A INSPECTION								
+	PKG 2 in PKG 3 ,4 REF: TLMC 05-20-02	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877	26-NOV-2021 2722:50	26-DEC-2021 2732:50
05-20-03	STANDARD PROGRAM - B INSPECTION								
+	PKG 3 in PKG 4 REF: TLMC 05-20-03	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877	26-NOV-2022 2922:50	26-DEC-2022 2932:50
05-20-04	STANDARD PROGRAM - C INSPECTION								
+	PKG 4 REF: TLMC 05-20-04	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877	26-NOV-2024 3322:50	26-DEC-2024 3332:50
05-20-05	ANNUAL INSPECTION								
+	PKG 9 REF:	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877	26-NOV-2021	26-DEC-2021

ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-70-CA-890-801	NO. 1 ENGINE - MINOR INSPECTION							
+								
	PKG 1	MOS	12			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	200	+1m		2520:10	(2720:10) 2720:10	2730:10
	REF: EMM 72-00-00	ENC				1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
+ 05-10-01-100-801 (s)	IF REQUIRED, CLEAN THE AIRCRAFT EXTERIOR SURFACE. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 12-22-01-301	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 05-10-01-200-801 (s)	SHUTDOWN ENGINE - CHECK FOR FUEL OR OIL LEAKS AT POWER PLANT. CHECK COMPONENTS REMOVED OR REPLACED DURING INSPECTION FOR CONDITION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 71-00-00-201	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 05-10-01-200-802 (s)	CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 12-12-01-301	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 05-10-01-200-803 (s)	CHECK THAT ENGINE COWLINGS, ACCESS DOORS, FLOOR PANELS, KARMANS AND FAIRINGS ARE CORRECTLY INSTALLED. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 71-10-00-601	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 05-10-01-200-804 (s)	SHUTDOWN ENGINE - CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 12-12-01-301	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 05-10-01-200-805 (s)	DO A GENERAL VISUAL INSPECTION OF UNCOVERED AREA UNDER FLOOR, INCLUDING VISIBLE HOSES PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 53-60-00-601	HRS/MSC	800	+10/-10				2522:50	
		AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-10-01-210-801 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 100, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-802 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 200, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-803 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 210, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-804 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 300, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-805 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 500, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-806 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 600, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-210-807 (s)	DO A GENERAL VISUAL INSPECTION OF AREA 700, INCLUDING VISIBLE HOSES PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-10-01-860-801 (s)	DISCONNECT THE GROUND POWER UNIT. PKG 2 ,3 ,4 REF: AMM 24-40-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-10-01-860-802 (s)	CONNECT A GROUND POWER UNIT AND ENERGIZE. PKG 2 ,3 ,4 REF: AMM 24-40-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-12-01-710-801 (s)	START ENGINE WITH GROUND POWER UNIT THEN MAKE GROUND POWER UNIT DISCONNECT. DO A MAINTENANCE RUN-UP. FILL ALL FILES OF MAINTENANCE RUN-UP. PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-12-01-710-802 (s)	DO A MAINTENANCE RUN-UP - FILL ALL FILES OF MAINTENANCE RUN-UP. PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 05-12-02-710-801 (s)	PERFORM A POST INSPECTION FLIGHT. FILL ALL FILES OF POST INSPECTION FLIGHT. PKG 4,9 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 26-NOV-2020 2522:50 1877		
+ 07-10-00-580-801 (s)	JACK-UP THE AIRCRAFT PKG 2 ,3 ,4 REF: AMM 07-10-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 07-10-00-580-802 (s)	LOWER THE AIRCRAFT TO GROUND AND REMOVE THE JACKS. PKG 2 ,3 ,4 REF: AMM 07-10-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
+ 08-10-00-970-801	PERFORM A WEIGHT AND BALANCE.								
08.010		MOS	60	+10%/-10%		81	26-NOV-2020	15-FEB-2026	15-AUG-2026
	REF: AMM 08-10-00-301	HRS/MSC					2522:50		
		AFL					1877		
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-21-00-210-801 (s)	PLACARDS AND MARKINGS, AREA 100. ENSURE PRESENCE AND READABILITY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 11-21-00-01	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 11-22-00-210-801 (s)	EXTERIOR PLACARDS AND MARKINGS, AREA 200. ENSURE PRESENCE AND READABILITY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 11-22-00-01	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 11-22-01-210-801 (s)	PLACARDS AND MARKINGS, AREA 210. ENSURE PRESENCE AND READABILITY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 11-22-00-01	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 11-23-00-210-801 (s)	PLACARDS AND MARKINGS, AREA 300. ENSURE PRESENCE AND READABILITY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 11-23-00-01	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 11-24-00-210-801 (s)	PLACARDS AND MARKINGS, AREA 500. ENSURE PRESENCE AND READABILITY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 11-24-00-01	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 11-24-00-210-802 (s)	PLACARDS AND MARKINGS, AREA 600 - ENSURE PRESENCE AND READABILITY. PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 11-24-00-01								
+ 11-25-00-210-801 (s)	PLACARDS AND MARKINGS, AREA 700 - ENSURE PRESENCE AND READABILITY. PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 11-25-00-01								
+ 11-30-00-210-801 (s)	INTERIOR PLACARDS AND MARKINGS, AREA 200 - ENSURE PRESENCE AND READABILITY. PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 11-30-00-01								
CHAPTER 12 SERVICING									
+ 12-21-00-640-801 (s)	LUBRICATION OF EXTERNAL ACCESS AND INSPECTION DOORS - LUBRICATE EXTERNAL DOOR HINGES. PKG 3 ,4	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
12.010	REF: See Workcard								
+ 12-21-00-640-802	PROTECTION OF EXTERNAL FITTINGS	MOS HRS/MSC AFL	1200	+10%/-10%			07-OCT-2019 2302:36	3502:36	3622:36
12.020	REF: See Workcard								
+ 12-21-01-640-801 (s)	LUBRICATE AREA 100 PKG 3 ,4	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 12-21-01-301								
+ 12-21-02-640-801 (s)	LUBRICATE AREA 200 PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 12-21-02-301								



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 12-21-03-640-801 (s)	LUBRICATE AREA 300 PKG 2 ,3 ,4 REF: AMM 12-21-03-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 12-21-04-640-801 (s) 12.030	PROTECTION OF EXTERNAL MOVABLE PARTS - LUBRICATE THE FLAP ROLLERS PKG 9 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 12-21-04-640-802 (s)	LUBRICATE AREA 500 PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 12-21-04-640-803 (s)	LUBRICATE AREA 600 PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 12-21-05-640-801 (s)	LUBRICATE AREA 700 PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 21 AIR CONDITIONING									
+ 21-00-01-210-801 (s)	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR ATTACHMENT AND CORRECT MECHANICAL OPERATION PKG 4 REF: AMM 21-00-01-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-00-01-710-801 (s)	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR CORRECT MECHANICAL OPERATION PKG 4 REF: AMM 21-00-01-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 21-20-00-200-801 (s)	FUSELAGE DUCTS - CHECK VENTILATION HOSES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4 REF: AMM 21-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 21-20-00-200-803 (s)	WINDSHIELD AND SIDE WINDOWS DEFOGGING OUTLETS - CHECK FOR CLOGGING PKG 4 REF: AMM 21-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 21-20-02-710-801 (s)	EMERGENCY AIR CONTROL - CHECK CONTROL MECHANICAL OPERATION PKG 4 REF: AMM 21-20-02-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 21-20-04-710-801 (s)	B17 CABIN FAN - CHECK OPERATION PKG 3,4 REF: AMM 21-20-04-501	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 21-30-00-900-801	PRESSURIZATION SAFETY HOSE T700A2130025000 NSN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	168	+20%	N:0		04-OCT-2007	04-OCT-2021	22-JUL-2024
	LIFE LIMIT								
21-30-00-900-802	PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 1 T700A2130025002 NSN REF:	MOS HRS/MSC AFL	168	+20%	N:0		04-OCT-2007	04-OCT-2021	22-JUL-2024
	LIFE LIMIT								



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30-00-900-803	PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 2 T700A213002501000 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0 N:0 N:0					
21-30-00-900-804	PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 1 T700A213002900200 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0 N:0 N:0					
21-30-00-900-805	PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 2 T700A2130025007 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0 N:0 N:0					
21-30-00-900-806	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025009 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0					
21-30-00-900-807	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025006 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0					
21-30-00-900-808	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025001 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0					
21-30-00-900-809	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025004 NSN REF:	MOS HRS/MSC AFL	168	+20%			04-OCT-2007	04-OCT-2021	22-JUL-2024
LIFE LIMIT				N:0					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30-00-900-810	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025005 NSN REF:	MOS HRS/MSC AFL	168	+20%	N:0		04-OCT-2007	04-OCT-2021	22-JUL-2024
21-30-00-900-811	REPLACE PRESSURIZATION HOSES. NEOPRENE-COTTON TAPE 4281621007 T700A2130025005 NSN REF:	MOS HRS/MSC AFL	168	+20%	N:0		04-OCT-2007	04-OCT-2021	22-JUL-2024
+ 21-30-01-100-801	OUTFLOW VALVE CONTROLLER - CLEAN THE FILTER 130618.1 57-565 REF: AMM 21-30-01-701	MOS HRS/MSC AFL	1200	+10%/-10%			07-OCT-2019 2302:36	3502:36	3622:36
+ 21-30-02-100-802 (s)	OUTFLOW VALVE - CLEAN VALVE SEAT PKG 9 REF: AMM 21-30-02-701	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 21-30-03-100-801	SAFETY VALVE - CLEAN THE FILTER REF: AMM 21-30-03-701	MOS HRS/MSC AFL	1200	+10%/-10%			07-OCT-2019 2302:36	3502:36	3622:36
+ 21-30-03-100-803 (s)	SAFETY VALVE - CLEAN VALVE SEAT PKG 9 REF: AMM 21-30-03-701	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 21-50-00-200-801 (s)	POWER PLANT COMPARTMENT DUCTS - CHECK CLAMPS FOR CONDITION AND ATTACHMENT ON HOSES AND RIGID PIPES. CHECK FOR DAMAGE PKG 4 REF: AMM 21-50-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50-00-200-802 (s)	PRESSURE REGULATING VALVE - CHECK V-BAND CLAMPS FOR CONDITION AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-803 (s)	TEMPERATURE CONTROL VALVE - CHECK V-BAND CLAMP FOR CONDITION AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-806 (s)	HEAT EXCHANGER/COOLING TURBINE PACK - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE. CHECK FOR CRACKS AT FASTENERS. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-807 (s)	OVERPRESSURE SWITCH - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-808 (s)	OVERTEMPERATURE SWITCH - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-809 (s)	DUCT OVERTEMPERATURE SWITCH - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 21-50-00-200-810 (s)	DUCT TEMPERATURE SENSOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50-00-200-811 (s)	CONTROLLER - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 21-50-00-200-812 (s)	CABIN TEMPERATURE SENSOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 21-50-00-200-814 (s)	CABIN TEMPERATURE SENSOR - CHECK CLEANLINESS AND CLEAN IF NECESSARY. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-00-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 21-50-00-200-815 (s)	HEAT EXCHANGER/COOLING TURBINE PACK - CHECK CLEANLINESS OF THE HEAT EXCHANGER CORE AND CLEAN IF NECESSARY PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 21-50-15-701	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 21-50-00-730-801	HEAT EXCHANGER/COOLING TURBINE PACK PN	MOS			N:0			04-OCT-2007	
21.070	SN-UNKNOWN	HRS/MSC	6000		N:0			0	6000
OVERHAUL	REF: AMM 21-50-15-401	AFL			N:0			0	
+ 21-50-04-200-802 (s)	WATER SEPARATOR - CHECK CLEANLINESS OF INLET. CHECK CLEANLINESS OF CONDENSER, CLEAN IF NECESSARY. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
21.090	REF: See Workcard	HRS/MSC AFL	200	+10/-10			2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50-15-200-801 (s)	BALL JOINTS OF BLEED AIR DUCTS - CHECK SEALS FOR CONDITION. PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF:	AFL	400	+10/-10					
+ 21-50-15-640-801 (s)	HEAT EXCHANGER/COOLING TURBINE PACK - LUBRICATE COOLING TURBINE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 21-50-15-301	AFL	800	+10/-10					
+ 21-50-15-680-801 (s)	HEAT EXCHANGER/COOLING TURBINE PACK - DRAIN COOLING TURBINE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 21-50-15-301	AFL	800	+10/-10					
+ 21-55-00-200-801 (s)	EVAPORATOR - CHECK CONDITION, CLEANLINESS AND CLEAN IF NECESSARY PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: GENERIC NO REF	AFL	800	+10/-10					
+ 21-55-00-610-803 (s)	VAPOR CYCLE COOLING SYSTEM - CHECK COMPLETE REFRIGERANT CHARGE PKG 9	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 12-15-03-301	AFL	HRS/MSC						
CHAPTER 22 AUTO FLIGHT									
+ 22-11-00-200-801 (s)	AUTOPILOT - CHECK A/P A82 COMPUTER, A83 AIR DATA COMPUTER, A91 CONVERTER, A84 YAW RATE GYRO AND A85 AURAL WARNING UNIT FOR ATTACHMENT AND DAMAGE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 22-11-00-601	AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-11-00-200-803 (s)	B35, 36, AND 37 SERVO ACTUATORS - CHECK CABLES FOR CONDITION. VERIFY THE PULLEYS TO MAKE SURE OF THE ABSENCE OF SET AND OF DETERIORATION (EXCEPT MARKINGS IN BOTTOM OF THROAT)						PKG		
	PKG 9	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC						2522:50	
	REF: See Workcard	AFL						1877	
+ 22-11-00-720-801 (s)	B35, B36, B37 AND B38 SERVO ACTUATORS - CHECK CLUTCH FRICTION TORQUES.						PKG		
22.010	PKG 9	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC						2522:50	
	REF: AMM 22-11-00-501	AFL						1877	
+ 22-11-00-820-801 (s)	B35, B36 AND B37 SERVO ACTUATORS - CHECK CABLES FOR TENSION						PKG		
	PKG 9	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC						2522:50	
	REF: See Workcard	AFL						1877	
+ 22-11-00-870-801 (s)	ADC DYNAMIC AND STATIC SYSTEMS - BLEED (2 BLEEDS UNDER FLOOR PANEL 232C)						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 34-11-00-301	AFL						1877	
+ 22-11-07-710-801 (s)	ALTITUDE AND VERTICLE SPEED SELECTOR - DO AN OPERATIONAL CHECK						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC	200	+10/-10				2522:50	
	REF: AMM 22-11-07-501	AFL						1877	
CHAPTER 23 COMMUNICATIONS									
+ 23-00-01-200-801 (s)	PL30 RADIO RACK AND AVIONICS - CHECK AVIONICS FOR CONDITION, CRACKS AND ATTACHMENT.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC	200	+10/-10				2522:50	
	REF: AMM 23-00-01-601	AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 23-00-10-710-801 (s)	PL30 RADIO RACK AVIONICS - DO AN OPERATIONAL TEST PKG 2 ,3 ,4 REF: AMM 23-10-00-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 23-60-00-210-801 (s)	STATIC DISCHARGERS - CHECK FOR CONDITION. PKG 2 ,3 ,4 REF: AMM 23-60-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 23-60-00-760-801 (s)	STATIC DISCHARGERS - CHECK FOR RESISTANCE AND CONTINUITY PKG 2 ,3 ,4 REF: AMM 23-60-00-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 24 ELECTRICAL POWER									
+ 24-00-00-200-801 (s)	ELECTRICAL HARNESSSES, AREA 100 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4 REF: AMM 24-00-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 24-00-00-200-802 (s)	ELECTRICAL HARNESSSES, AREA 200 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT PKG 4 REF: AMM 24-00-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 24-00-00-200-803 (s)	ELECTRICAL HARNESSSES, AREA 210 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4 REF: AMM 24-00-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 24-00-00-200-804 (s)	ELECTRICAL HARNESSSES, AREA 300 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4 REF: AMM 24-00-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-00-00-200-805 (s)	ELECTRICAL HARNESSSES, AREA 500 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-00-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 24-00-00-200-806 (s)	ELECTRICAL HARNESSSES, AREA 600 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-00-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 24-00-00-200-807 (s)	ELECTRICAL HARNESSSES, AREA 700 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-00-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 24-00-00-200-808 (s)	POWER PLANT / FIREWALL GROUND CABLE - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-00-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 24-30-02-200-801 (s)	ELECTRICAL POWER CENTER - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE OR LOOSE CONNECTIONS. PKG 3 ,4	MOS	24	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-30-02-601	HRS/MSC AFL	400	+10/-10			2522:50	1877	
+ 24-30-03-200-801 (s)	STARTER GENERATOR - CHECK FOR ATTACHMENT, CLEANLINES OF CONNECTION TERMINAL BLOCK AND ELECTRICAL CONNECTIONS, AND EVIDENCE OF OVERHEAT, ARCING AND DAMAGE. CHECK COVER FOR CONDITION. ENSURE GOOD CONDITION OF CLAMP AND SECTORS. CHECK FOR CRACKS. PKG 3 ,4	MOS	24	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 24-30-03-601	HRS/MSC AFL	400	+10/-10			2522:50	1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30-03-200-802 (s)	STARTER GENERATOR DRIVE PAD - CHECK DRAIN LINE FOR CONDITION. CHECK FOR LEAKS AT MOUNTING INTERFACE. PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
	REF: AMM 24-30-03-601	HRS/MSC AFL	400	+10/-10			2522:50 1877		
+ 24-30-03-730-801	STARTER-GENERATOR - CHECK BRUSHES 8012.F	MOS					17-FEB-2020		
24.030	463 REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			2381:48	2981:48	3041:48
+ 24-30-03-730-802	STARTER-GENERATOR - REPLACE BEARINGS. CLEAN AND BALANCE 8012.F	MOS					17-FEB-2020		
24.030	463 REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			2381:48	3581:48	3701:48
+ 24-30-03-730-803	STARTER-GENERATOR 8012.F	MOS					17-FEB-2020		
24.030	463 REF: AMM 24-30-03-401	HRS/MSC AFL	2400	O:0 N:2381:48 O:0 O:0			2381:48	4781:48	
	OVERHAUL								
+ 24-30-04-200-801 (s)	BATTERY CABLES - CHECK CABLES AND CONNECTORS FOR CORROSION AND EVIDENCE OF DAMAGE. CHECK FOR CLEANLINESS, EVIDENCE OF CORROSION AND CRACKS ON FIREWALL ATTACHMENTS. CHECK CONNECTIONS AND F100 FUSE FOR CONDITION. PKG 4	MOS	48	+10d/-10d			26-NOV-2020		
	REF: AMM 24-30-04-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 24-30-04-760-802	LEAD-ACID BATTERY, IF INSTALLED - REMOVE BATTERY. CHECK CAPACITY RG-380E/44	MOS	12	+10%/-10%			19-NOV-2020	19-NOV-2021	25-DEC-2021
24.010	70011896 REF: See Workcard	HRS/MSC AFL	200	+10%/-10%			2520:10 1876	2720:10	2740:10



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30-05-200-801 (s)	STAND-BY GENERATOR - CHECK CABLES FOR CONDITION AND CONNECTIONS. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 24-30-05-601	HRS/MSC AFL	800	+10/-10					
+ 24-30-05-200-802 (s)	STAND-BY GENERATOR BELT - CHECK FOR CONDITION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 24-30-05-501	HRS/MSC AFL	200	+10/-10					
+ 24-30-05-730-801	STAND-BY GENERATOR - CHECK BRUSHES FOR WEAR ALU-8521LS 4054007	MOS	600	+10%/-10%			17-FEB-2020 2381:48	2981:48	3041:48
24.065	REF: AMM 24-30-05-601	HRS/MSC AFL							
+ 24-30-05-730-802	STAND-BY GENERATOR - OVERHAUL. CLEAN AND PACK WITH GREASE THE ADAPTER ASSEMBLY. ALU-8521LS 4054007	MOS	3000		N:2381:36		17-FEB-2020 2381:48	3000:12	
24.020 OVERHAUL	REF: See Workcard	HRS/MSC AFL							
+ 24-30-05-820-801 (s)	STAND-BY GENERATOR BELT - CHECK FOR TENSION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 24-30-05-501	HRS/MSC AFL	200	+10/-10					
+ 24-30-05-900-801	STAND-BY GENERATOR BELT - REPLACE BELT. 24.020 SCRAP	MOS	1200				17-FEB-2020 2381:48	3581:48	
	REF: AMM 24-30-05-301	HRS/MSC AFL							



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30-06-200-801 (s)	STAND-BY GENERATOR DRIVE - CHECK DRAIN LINE FOR ATTACHMENTS AND CONDITION. CHECK FOR LEAKS AT MOUNTING INTERFACE. MANUALLY CHECK THAT THE SHEAR SHAFT OR THE PULLEY ARE NOT DAMAGED BY MANUALLY ROTATING THE STAND-BY GENERATOR DRIVE PULLEY						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 24-30-06-601	AFL						1877	
+ 24-40-00-200-801 (s)	EXTERNAL POWER SUPPLY - CHECK GPU RECEPTACLE FOR ATTACHMENT AND EVIDENCE OF DAMAGE. CHECK FOR CRACKS ON SHUNT BRIDGE. CHECK CABLES. ON FIREWALL, ENSURE THAT THERE IS NO CORROSION AND NO CRACKS AT SHUNT BRIDGE FASTENERS.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 24-40-00-601	AFL						1877	
+ 24-60-01-210-801 (s)	PL1 CIRCUIT BREAKER PANEL - CHECK PANEL FOR ATTACHMENT AND CLEANLINESS AND ELECTRICAL COMPONENTS FOR CONDITION.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 24-60-01-601	AFL						1877	
CHAPTER 25		EQUIPMENT/FURNISHINGS							
+ 25-11-00-210-803 (s)	SUN VISOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 25-11-00-601	AFL						1877	
+ 25-12-00-210-801 (s)	COCKPIT SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC	200	+10/-10				2522:50	
	REF: AMM 25-12-00-601	AFL						1877	
+ 25-12-00-210-802 (s)	COCKPIT BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC	200	+10/-10				2522:50	
	REF: AMM 25-12-00-601	AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-12-00-710-803 (s)	COCKPIT BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION. PKG 2 ,3 ,4 REF: AMM 25-12-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-21-00-210-801 (s)	STORAGE CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION PKG 4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-21-00-210-802 (s)	FOLDING TABLE, IF INSTALLED - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE. PKG 4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-21-00-210-803 (s)	AUDIO CABINET, IF INSTALLED - CHECK ELECTRICAL COMPONENTS FOR ATTACHMENT AND CONDITION. PKG 3 ,4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	24 400				PKG 24-APR-2018 1807:18		
+ 25-21-00-210-804 (s)	REFRESHMENT CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION. PKG 4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 24-APR-2018 1807:18		
+ 25-21-00-210-805 (s)	UPHOLSTERING PANELS - CHECK ATTACHMENT AND CONDITION. PKG 4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-21-00-210-806 (s)	CABIN WINDOW CURTAINS - CHECK CONDITION AND OPERATION. PKG 4 REF: AMM 25-21-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-05-710-801 (s)	TOILETS, REAR BAGGAGE COMPARTMENT, IF INSTALLED - DO AN OPERATIONAL TEST. PKG 3 ,4 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 06-MAY-2019 2189:24		
+ 25-22-00-210-801 (s)	PASSENGERS SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION. CHECK THAT PASSENGERS SEATS ARE INSTALLED IN CORRECT PAINT MARKS LOCATIONS. PKG 2 ,3 ,4 REF: AMM 25-22-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-22-00-210-802 (s)	PASSENGERS BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS. PKG 2 ,3 ,4 REF: AMM 25-22-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-22-00-710-803 (s)	PASSENGERS BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION. PKG 2 ,3 ,4 REF: AMM 25-22-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-50-00-610-801 (s)	FUSE AND BULB BOX - COMPLETE IF NECESSARY. PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-61-00-200-801 (s)	EMERGENCY LOCATOR TRANSMITTER - CHECK FOR ATTACHMENT AND POSITION OF FUNCTION SWITCH. MAKE SURE THERE ARE NO LEAKS AND NO CORROSION AT BATTERY. CHECK ANTENNA FOR ATTACHMENT AND CONNECTION. PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-61-00-200-804 (s)	EMERGENCY LOCATOR TRANSMITTER - CHECK BATTERY REPLACEMENT DATES PKG 2 ,3 ,4 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 25-61-00-710-806 (s)	EMERGENCY LOCATOR TRANSMITTER - DO AN OPERATIONAL TEST AND RECORD OPERATING TIME PKG 9 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 26-NOV-2020 2522:50 1877		
25-61-01-200-801 25.020	EMERGENCY LOCATOR TRANSMITTER - INSPECT/TEST 455-6607 4077 REF: AMM 25-61-00-601	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877	26-NOV-2021	26-DEC-2021
CHAPTER 26 FIRE PROTECTION									
26-10-00-200-801 (s)	FIRE DETECTION, IF INSTALLED - CHECK DETECTORS AND WIRINGS FOR CONDITION AND ATTACHMENT. PKG 1,2 ,3 ,4 REF:	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 17-FEB-2020 2381:48		
+ 26-20-01-200-802	FIRE EXTINGUISHER-AIR TOTAL (IF INSTALLED) - CHECK FIRE EXTINGUISHER FOR WEIGHT AND PRESSURE 74-00 A27169 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			07-OCT-2019	07-OCT-2021	19-DEC-2021
+ 26-20-01-730-801 OVERHAUL	FIRE EXTINGUISHER-AIR TOTAL (IF INSTALLED) - OVERHAUL 74-00 A27169 REF: MSC 26-24-05	MOS HRS/MSC AFL	120					31-MAY-2025 M	
+ 26-20-01-900-801 26.010	FIRE EXTINGUISHER 74-00 A27169 REF: AMM 26-20-01-401	MOS HRS/MSC AFL	240	N:0 N:0 N:0			01-MAY-2015	01-MAY-2035	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 27	FLIGHT CONTROLS								
+ 27-10-00-200-801 (s)	AILERON TRIM TAB ACTUATOR RODS - VISUALLY CHECK THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 27-10-00-601	AFL						1877	
+ 27-10-00-200-802 (s)	AILERON CONTROL INBOARD AND OUTBOARD L.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 57-60-00-601	AFL						1877	
+ 27-10-00-200-803 (s)	AILERON CONTROL INBOARD AND OUTBOARD R.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 57-60-00-601	AFL						1877	
+ 27-10-00-200-804 (s)	LH AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 27-10-00-601	AFL						1877	
+ 27-10-00-200-805 (s)	RH AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 27-10-00-601	AFL						1877	
+ 27-10-00-200-806 (s)	LH AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 27-10-00-601	AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10-00-200-807 (s)	RH AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10				2522:50 1877	
+ 27-10-00-200-808 (s)	SPOILER CABLE ASSEMBLY IN FUSELAGE - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC AFL	800	+10/-10				2522:50 1877	
+ 27-10-00-200-809 (s)	SPOILER AND AILERON CABLE ASSEMBLY ON L.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC AFL	800	+10/-10				2522:50 1877	
+ 27-10-00-200-810 (s)	SPOILER AND AILERON CABLE ASSEMBLY ON R.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC AFL	800	+10/-10				2522:50 1877	
+ 27-10-00-200-811 (s)	AILERON CONTROL INBOARD AND OUTBOARD LH BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10				2522:50 1877	
+ 27-10-00-200-812 (s)	AILERON CONTROL INBOARD AND OUTBOARD RH BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10				2522:50 1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10-00-200-813 (s)	LH WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 27-10-00-200-814 (s)	RH WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 27-10-00-720-801 (s)	AILERON TRIM TAB - CHECK TRAVEL. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
27.030	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 27-10-00-720-802 (s)	AILERONS AND SPOILERS - CHECK TRAVEL. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
27.010	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 27-10-00-720-803 (s)	CONTROL WHEEL ASSEMBLY - CHECK FOR SLACK AND FRICTION POINTS IN AILERON CONTROL. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 27-10-00-601	HRS/MSC AFL	800	+10/-10			2522:50	1877	
+ 27-10-00-820-801 (s)	SPOILER AND AILERON CABLE ASSEMBLY ON WING - CHECK CABLE TENSION AND SAFETYING OF TURNBUCKLES PKG 9	MOS	12	+1m/-1m			PKG	26-NOV-2020	
27.020	REF: AMM 27-10-00-501	HRS/MSC AFL					2522:50	1877	
+ 27-10-02-210-801 (s)	L.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK. PKG 3 ,4	MOS	24	+1m/-1m			PKG	26-NOV-2020	
	REF:	HRS/MSC AFL	400	+10/-10			2522:50	1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10-02-210-802 (s)	R.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK. PKG 3 ,4 REF:	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-10-02-210-803 (s)	L.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION. PKG 3 ,4 REF: AMM 57-70-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-10-02-210-804 (s)	R.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION. PKG 3 ,4 REF: AMM 57-70-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-20-00-200-801 (s)	RUDDER LEVER AND ROD ASSEMBLY - CHECK ATTACHMENT, CONDITION OF LEVER BALL JOINT AND SAFETYING OF ROD HINGES. CHECK THAT THE TWO STOP SCREWS CANNOT BE SCREWED OR UNSCREWED MANUALLY. PKG 4 REF: AMM 27-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-20-00-200-802 (s)	RUDDER CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-20-00-720-801 (s) 27.060	RUDDER TRIM TAB - CHECK TRAVEL. PKG 4 REF: AMM 27-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20-00-720-802 (s)	RUDDER - CHECK TRAVEL.						PKG		
27.040	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 27-20-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 27-20-00-820-801 (s)	RUDDER CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES						PKG		
27.050	PKG 9	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 27-20-00-501	HRS/MSC					2522:50		
		AFL					1877		
+ 27-20-01-710-801 (s)	RUDDER PEDALS - CHECK FREE MOVEMENT OF RUDDER PEDALS AND CORRECT OPERATION OF RUDDER PEDAL POSITION ADJUSTING CONTROLS FOR THE PILOT AND RIGHT STATIONS.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 27-20-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 27-20-04-200-801 (s)	RUDDER TRIM TAB ACTUATOR - VISUALLY CHECK FOR CONDITION AND ATTACHMENT. VISUALLY ENSURE THAT THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 27-20-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 27-30-00-200-801 (s)	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK FOR CONDITION, ATTACHMENT AND BALL JOINTS ON BELLCRANKS AND LEVERS. CHECK THAT STOP SCREWS ON HINGE BEARING CANNOT BE SCREWED OR UNSCREWED MANUALLY. CHECK SAFETYING OF ROD HINGES.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 27-30-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 27-30-00-200-802 (s)	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK CONDITION AND ATTACHMENT OF ROD, SLEEVE AND FOR CRACKS ON PRESSURE BULKHEAD C17.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
	REF: AMM 27-30-00-601	HRS/MSC	400	+10/-10			2522:50		
		AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30-00-200-803 (s)	ELEVATORS - CHECK SLACK INTO THE ELEVATOR CONTROL. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020		
	REF: AMM 27-30-00-601	HRS/MSC AFL	200	+10/-10			2522:50 1877		
+ 27-30-00-710-801 (s)	ELEVATOR TRIM TABS EMERGENCY MANUAL CONTROL - TURN TRIM WHEEL AND CHECK FREE MOVEMENT AND OPERATION OF INDICATOR. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020		
	REF: AMM 27-30-00-501	HRS/MSC AFL	200	+10/-10			2522:50 1877		
+ 27-30-00-720-801 (s)	ELEVATORS - CHECK TRAVEL. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020		
27.070	REF: AMM 27-30-00-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 27-30-00-720-802 (s)	ELEVATOR TRIM TABS - CHECK TRAVEL PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020		
27.080	REF: AMM 27-30-00-601	HRS/MSC AFL	800	+10/-10			2522:50 1877		
+ 27-30-00-720-803 (s)	CONTROL WHEEL ASSEMBLY - CHECK FOR SLACK, FRICTION POINTS IN ELEVATOR CONTROL. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020		
	REF: AMM 27-30-00-601	HRS/MSC AFL	200	+10/-10			2522:50 1877		
+ 27-30-00-820-801 (s)	ELEVATOR TRIM TAB CONTROL CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES PKG 9	MOS	12	+1m/-1m			PKG 26-NOV-2020		
27.080	REF: AMM 27-30-00-501	HRS/MSC AFL					2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30-03-200-801 (s)	ELEVATOR TRIM TAB CONTROL CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: See Workcard	AFL						1877	
+ 27-30-03-200-802 (s)	ELEVATOR TRIM TAB CONTROL CABLES - CHECK CONDITION OF SCREW JACK CHAINS. CHECK ATTACHMENT AND SAFETYING OF LINKS THAT CONNECT CABLES TO CHAINS. EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: See Workcard	AFL						1877	
+ 27-30-04-200-801 (s)	ELEVATOR TRIM TAB ACTUATORS - CHECK RODS FOR CONDITION AND NO SLACK. VISUALLY CHECK ATTACHMENTS ON REAR SPAR OF FIXED HORIZONTAL STABILIZER.						PKG		
	PKG 3,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 27-30-00-601	AFL						1877	
+ 27-50-00-200-801 (s)	FLAP CONTROL, LH BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS.						PKG		
	PKG 3,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 27-50-00-601	AFL						1877	
+ 27-50-00-200-802 (s)	FLAP CONTROL, RH BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS.						PKG		
	PKG 3,4	MOS	24	+1m/-1m				26-NOV-2020	
		HRS/MSC	400	+10/-10				2522:50	
	REF: AMM 27-50-00-601	AFL						1877	
+ 27-50-00-200-803 (s)	GEARED MOTOR - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE.						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 27-50-00-601	AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50-00-200-804 (s)	FLAP CONTROLS, INBOARD AND OUTBOARD LH ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE. PKG 3 ,4 REF: AMM 27-50-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-50-00-200-805 (s)	FLAP CONTROLS, INBOARD AND OUTBOARD RH ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE. PKG 3 ,4 REF: AMM 27-50-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 27-50-00-720-801 (s) 27.090	FLAPS - CHECK TRAVELS. PKG 4 REF: AMM 27-50-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 28 FUEL									
+ 28-10-00-200-801 (s)	FILLER CAP AND LINES, L.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION. PKG 4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-00-200-802 (s)	FILLER CAP AND LINES, R.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION. PKG 4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-00-200-803 28.030	FLAPPER VALVES - CHECK RUBBER CONDITION. REF: AMM 28-10-00-601	MOS HRS/MSC AFL	48 1500	+10%/-10% +10%/-10%			17-FEB-2020 2381:48	17-FEB-2024 3881:48	11-JUL-2024 4031:48



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARRES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-10-00-200-804 (s)	LH VENT VALVES - CHECK FOR CLEANLINESS. PKG 3 ,4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-00-200-805 (s)	RH VENT VALVES - CHECK FOR CLEANLINESS. PKG 3 ,4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-00-200-806 (s)	LH FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS. PKG 3 ,4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-00-200-807 (s)	RH FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS. PKG 3 ,4 REF: AMM 28-10-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-10-06-200-801 28.030	STRAINERS - CHECK FOR CLEANLINESS AND CONDITION. REF: See Workcard	MOS HRS/MSC AFL	48 1500	+10%/-10% +10%/-10%			17-FEB-2020 2381:48	17-FEB-2024 3881:48	11-JUL-2024 4031:48
+ 28-20-00-200-801 (s)	DISTRIBUTION SYSTEM - CHECK. PKG 4 REF: AMM 28-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-20-01-900-801 28.020	FUEL UNIT - REPLACE FILTER ELEMENT L88A15-651 C95504 REF: AMM 28-20-01-301	MOS HRS/MSC AFL	600				06-AUG-2020 2469:54 1854	3069:54	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-20-03-710-801 (s)	FUEL SEQUENCER - DO A GROUND OPERATIONAL TEST. PKG 2 ,3 ,4 REF: AMM 28-20-00-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 28-20-04-730-801 28.110 OVERHAUL	MECHANICAL PUMP - OVERHAUL 1127-02 470 REF: GENERIC NO REF	MOS HRS/MSC AFL	120 3500				25-OCT-2017 1596:06	25-OCT-2027 5096:06	
+ 28-20-05-730-801 28.010	ELECTRIC PUMP - CHECK BRUSHES FOR WEAR T700A2825068000 125415 REF: AMM 28-20-05-401	MOS HRS/MSC AFL	6000	+10%/-10%			04-OCT-2007 0 0	6000	6600
28-20-05-900-801 28.010 OVERHAUL	ELECTRIC PUMP T700A2825068000 125415 REF: AMM 28-20-05-401	MOS HRS/MSC AFL	6000		N:0 N:0 N:0		04-OCT-2007 0 0	6000	
+ 28-40-00-710-801 (s) 28.030	LOW LEVEL SENSORS - DO A LOW LEVEL TEST PKG 3 ,4 REF: AMM 28-40-00-501	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-10-00-210-801 (s)	PNEUMATIC DE-ICERS - CHECK FOR ATTACHMENT AND EVIDENCE OF ABRASION, CUTS OR NICKS. PKG 2 ,3 ,4 REF: AMM 30-10-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-10-00-870-801 (s)	DEICING SYSTEM - DEICING SYSTEM DRAINING. PKG 4 REF: AMM 30-10-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-10-03-200-801 (s)	A43 PNEUMATIC DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: AMM 30-10-03-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-10-04-200-801 (s)	WATER SEPARATOR FILTER - CHECK FOR CONDITION AND ATTACHMENT PN PKG 9 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 30-10-05-200-801 (s)	L21 DE-ICING VALVE - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: AMM 30-10-05-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-30-00-710-801 (s)	HEATING OF PITOT TUBES AND STALL WARNING INDICATOR - DO AN OPERATIONAL TEST. PKG 2 ,3 ,4 REF: AMM 30-30-00-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-40-00-200-801 (s)	A41 PILOT WINDSHIELD DE-ICING CONTROLLER - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-40-00-200-802 (s)	A42 R.H. WINDSHIELD DE-ICING CONTROLLER, IF INSTALLED - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 30-40-00-710-801 (s)	A42 RH WINDSHIELD DE-ICING CONTROLLER, IF INSTALLED - IF THE CONTROLLER IS FITTED WITH A TEST BUTTON, DO THE TEST. PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-40-00-710-803 (s)	A41 PILOT WINDSHIELD DE-ICING CONTROLLER - IF THE CONTROLLER IS FITTED WITH A TEST BUTTON, DO THE TEST. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	AFL	200	+10/-10				2522:50	
								1877	
+ 30-40-00-720-801 (s)	A41 PILOT WINDSHIELD DE-ICING CONTROLLER - DO A FUNCTIONAL TEST OF THE SYSTEM PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	AFL	800	+10/-10				2522:50	
								1877	
+ 30-40-00-720-802 (s)	A42 RH WINDSHIELD DE-ICE CONTROLLER, IF INSTALLED - DO A FUNCTIONAL TEST OF THE SYSTEM PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	AFL	800	+10/-10				2522:50	
								1877	
+ 30-60-00-200-801 (s)	PROPELLER DE-ICING SYSTEM - CHECK BRUSH BLOCK AND SLIP RING FOR EVIDENCE OF OIL LEAKS. CHECK DE-ICERS AND WIRINGS FOR CONDITION AND ATTACHMENT. CHECK FOR SLIP RING WEAR, OVERHEATING AND CLEANLINESS. CHECK BRUSHES FOR WEAR, EVIDENCE OF DAMAGE, ATTACHMENT AND CLEANLINESS. CHECK WIRES FOR CONDITION AND ATTACHMENT. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 30-60-00-601	AFL	200	+10/-10				2522:50	
								1877	
+ 30-60-00-710-801 (s)	PROPELLER DE-ICING SYSTEM - DO A GROUND OPERATIONAL TEST PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	AFL	200	+10/-10				2522:50	
								1877	
+ 30-60-02-200-801 (s)	A40 PROPELLER DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 30-60-02-601	AFL	800	+10/-10				2522:50	
								1877	

CHAPTER 31 INDICATING/RECORDING SYSTEMS



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-20-01-710-801 (s)	CHRONOMETER - CHECK OPERATION. PKG 2 ,3 ,4 REF: AMM 31-20-01-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 31-60-01-210-801 (s)	M6 "ADVISORY PANEL" - CHECK FOR CONDITION PKG 2 ,3 ,4 REF: AMM 31-60-01-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 31-60-01-710-801 (s)	M6 "ADVISORY PANEL" - CHECK FOR OPERATION PKG 2 ,3 ,4 REF: AMM 31-60-01-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 32 LANDING GEAR									
+ 32-00-00-100-801 (s)	LANDING GEARS - IF NECESSARY, CLEAN THE EXTERNAL SECTIONS OF LANDING GEARS. PKG 2 ,3 ,4 REF: AMM 12-22-01-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 32-00-00-210-801 (s)	LEFT MAIN LANDING - CHECK FOR CONDITION. CHECK FOR LEAKS. 6052307232 PKG 9 B235 REF: AMM 32-00-00-601	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		32.190
+ 32-00-00-210-801 (s)	NOSE - CHECK FOR CONDITION. CHECK FOR LEAKS. 6052307231 PKG 9 B236 REF: AMM 32-00-00-601	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		32.220
+ 32-00-00-210-801 (s)	RIGHT MAIN LANDING - CHECK FOR CONDITION. CHECK FOR LEAKS. 6052307233 PKG 9 B237 REF: AMM 32-00-00-601	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		32.195



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-00-00-640-801 (s)	L.H. R.H. AND NOSE LANDING GEAR - LUBRICATION OF LANDING GEAR AXLES PKG 9 REF: AMM 12-21-05-301	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 32-00-00-710-801 (s)	DO AN OPERATIONAL TEST IN NORMAL/EMERGENCY CONDITIONS AND CHECK FOR SEALING OF NORMAL/EMERGENCY HYDRAULIC VALVE. PKG 2 ,3 ,4 REF: AMM 32-00-00-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 32-10-00-730-801 32.010 OVERHAUL	LEFT MAIN LANDING GEAR 6052307232 B235 REF: AMM 32-10-01-401	MOS HRS/MSC AFL			N:0 N:0 N:0		04-OCT-2007 0 0		5000
+ 32-10-00-730-801 32.010 OVERHAUL	RIGHT MAIN LANDING GEAR 6052307233 B237 REF: AMM 32-10-01-401	MOS HRS/MSC AFL			N:0 N:0 N:0		04-OCT-2007 0 0		5000
+ 32-10-01-220-801 32.200	LEFT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS,CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS,DO A DIMENSIONAL CHECK FOR TORQUE LINKS,DO AN OIL CHANGE FOR THE SHOCK-ABSORBER. 6052307232 B235 REF: See Workcard	MOS HRS/MSC AFL	60	+10%/-10%			16-OCT-2018	16-OCT-2023	16-APR-2024
+ 32-10-01-220-801 32.205	RIGHT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS,CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS,DO A DIMENSIONAL CHECK FOR TORQUE LINKS,DO AN OIL CHANGE FOR THE SHOCK-ABSORBER. 6052307233 B237 REF: See Workcard	MOS HRS/MSC AFL	60	+10%/-10%			16-OCT-2018	16-OCT-2023	16-APR-2024



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10-01-220-802	LEFT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY								
32.210	6052307232 B235 REF: AMM 32-10-01-501	MOS HRS/MSC AFL	120	+10%/-10%			16-OCT-2018	16-OCT-2028	16-OCT-2029
+ 32-10-01-220-802	RIGHT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY								
32.215	6052307233 B237 REF: AMM 32-10-01-501	MOS HRS/MSC AFL	120	+10%/-10%			16-OCT-2018	16-OCT-2028	16-OCT-2029
+ 32-10-01-780-801 (s)	LEFT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE.								
32.120	PKG 9 REF: AMM 12-14-01-301	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 32-10-01-780-801 (s)	RIGHT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE.								
32.120	PKG 9 REF: AMM 12-14-01-301	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 32-20-00-200-801 (s)	NOSE LANDING GEAR MOUNT - VISUALLY CHECK FOR CRACKS. CHECK AXIAL PLAY OF HINGE BALL JOINTS. PENDULATE THE NOSE LANDING GEAR TO CHECK HINGE BALL JOINTS FOR CONDITION								
	PKG 4 REF: AMM 32-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 32-20-00-730-801	NOSE LANDING GEAR								
32.020	6052307231 B236 REF: AMM 32-20-01-401	MOS HRS/MSC AFL					04-OCT-2007 0		
OVERHAUL			5000				0	5000	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20-01-220-801	NOSE LANDING GEAR - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS,CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS,DO A DIMENSIONAL CHECK FOR TORQUE LINKS								
32.230	6052307231 B236 REF: See Workcard	MOS HRS/MSC AFL	60	+10%/-10%			16-OCT-2018	16-OCT-2023	16-APR-2024
+ 32-20-01-220-802	NOSE LANDING GEAR - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY								
32.240	6052307231 B236 REF: See Workcard	MOS HRS/MSC AFL	120	+10%/-10%			16-OCT-2018	16-OCT-2028	16-OCT-2029
+ 32-20-01-680-801	NOSE LANDING GEAR - DO AN OIL CHANGE FOR THE SHOCK ABSORBER								
	REF: AMM 12-13-04-301	MOS HRS/MSC AFL	60	+10%/-10%			16-OCT-2018	16-OCT-2023	16-APR-2024
+ 32-20-01-780-801 (s)	NOSE LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE.								
32.130	PKG 9 REF: AMM 12-14-02-301	MOS HRS/MSC AFL	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 32-20-01-900-801	NOSE LANDING GEAR - REPLACE NOSE GEAR ACTUATOR HINGE PIN SECURING BOLT.								
	REF: AMM 32-20-01-401	MOS HRS/MSC AFL	84				26-NOV-2020 2522:50 1877	26-NOV-2027 6877	
+ 32-20-03-200-801 (s)	SHIMMY DAMPER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS								
32.030	PKG 2 ,3 ,4 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20-03-680-801	SHIMMY DAMPER - REPLACE HYDRAULIC FLUID.								
32.030	REF: AMM 12-13-01-301	MOS HRS/MSC AFL	36	+10%/-10%			07-OCT-2019	07-OCT-2022	25-JAN-2023
+ 32-30-00-200-801 (s)	HYDRAULIC LINES (IN NOSE GEAR WELL) - CHECK FOR SEALING, CONDITION AND ATTACHMENT.						PKG		
	PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877		
	REF: AMM 32-30-00-601								
+ 32-30-00-200-802 (s)	HYDRAULIC AND BRAKE LINES (IN MAIN GEAR WELL) - CHECK FOR SEALING, CONDITION, ATTACHMENT AND ROUTING.						PKG		
	PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877		
	REF: AMM 32-30-00-601								
+ 32-30-00-210-801 (s)	MAIN LANDING GEAR ACTUATORS - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.						PKG		
	PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877		
	REF: AMM 32-30-00-601								
+ 32-30-00-210-802 (s)	NOSE LANDING GEAR ACTUATOR - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.						PKG		
	PKG 2 ,3 ,4	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877		
	REF: AMM 32-30-00-601								
+ 32-30-01-730-801	LEFT MAIN LANDING GEAR ACTUATOR - OVERHAUL								
32.040	VSTS083560	MOS	120	+10%/-10%	O:0		09-OCT-2017	09-OCT-2027	09-OCT-2028
	135	HRS/MSC			O:0				
OVERHAUL	REF: AMM 32-30-01-401	AFL	5000	+10%/-10%	O:0		1430	6430	6930



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30-01-730-801	RIGHT MAIN LANDING GEAR ACTUATOR - OVERHAUL								
32.040	VSTS083560	MOS	120	+10%/-10%	O:0		09-OCT-2017	09-OCT-2027	09-OCT-2028
OVERHAUL	668	HRS/MSC			O:0				
	REF: AMM 32-30-01-401	AFL	5000	+10%/-10%	O:0		1430	6430	6930
<hr/>									
+ 32-30-02-730-801	NOSE LANDING GEAR ACTUATOR - OVERHAUL								
32.050	VSTS083660	MOS	120	+10%/-10%	N:36		09-OCT-2017	09-OCT-2024	09-OCT-2025
OVERHAUL	65	HRS/MSC			O:327				
	REF: AMM 32-30-02-401	AFL	5000	+10%/-10%			1430	6103	6603
<hr/>									
+ 32-35-00-680-801	HYDRAULIC SYSTEM - REPLACE HYDRAULIC FLUID.								
32.070		MOS	36	+10%/-10%			07-OCT-2019	07-OCT-2022	25-JAN-2023
	REF: AMM 12-13-05-301	HRS/MSC							
		AFL							
<hr/>									
+ 32-35-01-200-801 (s)	ELECTRO-HYDRAULIC GENERATOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 32-35-01-601	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
<hr/>									
+ 32-35-01-200-802 (s)	ELECTRO-HYDRAULIC GENERATOR - CHECK FILTER CLEANLINESS.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 32-35-01-601	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
<hr/>									
+ 32-35-01-730-801	ELECTRO-HYDRAULIC GENERATOR								
32.060	T700A323500300400	MOS	120		O:24		09-OCT-2017	09-OCT-2025	
OVERHAUL	778	HRS/MSC			O:38				
	REF: AMM 32-35-01-401	AFL	10000				1430	11392	
<hr/>									
+ 32-40-01-100-801	LEFT MAIN LANDING GEAR WHEELS - CLEAN THE WHEEL BEARINGS OF THE LEFT MAIN LANDING GEAR .								
32.270		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
	REF: See Workcard	AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-01-100-801	RIGHT MAIN LANDING GEAR WHEEL - CLEAN THE WHEEL BEARINGS OF THE RIGHT MAIN LANDING GEAR.								
32.275		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
	REF: See Workcard	HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
		AFL					1877		
+ 32-40-01-200-803	LEFT MAIN LANDING GEAR WHEELS - CHECK BEARINGS FOR CONDITION AND CORROSION.								
32.280		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
	REF: GENERIC NO REF	HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
		AFL					1877		
+ 32-40-01-200-803	RIGHT MAIN LANDING GEAR WHEEL - CHECK BEARINGS FOR CONDITION AND CORROSION								
32.285		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
	REF: GENERIC NO REF	HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
		AFL					1877		
+ 32-40-01-210-801 (s)	MAIN LANDING GEAR TIRES - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 12-14-03-301	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 32-40-01-640-801	LEFT MAIN LANDING GEAR - LUBRICATE THE WHEEL BEARINGS OF THE MAIN LANDING GEAR								
		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
	REF: AMM 12-21-05-301	HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
		AFL					1877		
+ 32-40-01-640-801	RIGHT MAIN LANDING GEAR - LUBRICATE THE WHEEL BEARINGS OF THE MAIN LANDING GEAR								
		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
	REF: AMM 12-21-05-301	HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
		AFL					1877		
+ 32-40-01-730-801	LEFT MAIN LANDING GEAR WHEEL - OVERHAUL								
32.090	6068767226	MOS		O:0			17-FEB-2020		
	1389	HRS/MSC		O:0					
OVERHAUL	REF: AMM 32-40-01-401	AFL	1000	N:1812 O:0			1812	2812	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-01-730-801	RIGHT MAIN LANDING GEAR WHEEL - OVERHAUL								
32.100	6068767226	MOS		O:0			17-FEB-2020		
OVERHAUL	1387	HRS/MSC		O:0					
	REF: AMM 32-40-01-401	AFL	1000	N:1812 O:0			1812	2812	
+ 32-40-02-100-801	NOSE LANDING GEAR WHEEL - CLEAN THE WHEEL BEARINGS OF THE NOSE LANDING GEAR.								
32.290		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
	REF: See Workcard	AFL					1877		
+ 32-40-02-200-802	NOSE LANDING GEAR WHEEL - CHECK BEARINGS FOR CONDITION AND CORROSION.								
32.295		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
	REF: GENERIC NO REF	AFL					1877		
+ 32-40-02-210-801 (s)	NOSE LANDING GEAR TIRE - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 12-14-03-301	AFL					1877		
+ 32-40-02-640-801	NOSE LANDING GEAR WHEEL - LUBRICATE THE WHEEL BEARINGS OF THE NOSE LANDING GEAR								
		MOS	12	+1m/-1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	200	+10/-10			2522:50	2722:50	2732:50
	REF: AMM 12-21-05-301	AFL					1877		
+ 32-40-02-730-801	NOSE LANDING GEAR WHEEL								
32.110	6068757290	MOS		O:0			17-FEB-2020		
OVERHAUL	1547	HRS/MSC		O:0					
	REF: AMM 32-40-02-401	AFL	1000	N:1812 O:0			1812	2812	
+ 32-40-03-200-801 (s)	BRAKE ASSEMBLY - CHECK FOR WEAR, CRACKS ON LININGS AND DISK, AND REPLACE IF NECESSARY.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 32-40-03-601	AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-04-200-801 (s)	HYDRAULIC AND BRAKE LINES (IN FUSELAGE) - CHECK FOR SEALING, CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 32-40-04-601	HRS/MSC AFL	800	+10/-10					
+ 32-40-04-200-802 (s)	BRAKE MASTER CYLINDER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 32-40-04-601	HRS/MSC AFL	800	+10/-10					
+ 32-40-04-710-801 (s)	BRAKE MASTER CYLINDER - DO AN OPERATIONAL TEST. PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 32-40-00-501	HRS/MSC AFL	400	+10/-10					
+ 32-40-05-710-801 (s)	PARKING BRAKE VALVE AND CONTROL - CHECK CORRECT OPERATION OF INDICATION AND BRAKING. PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 32-40-00-501	HRS/MSC AFL	400	+10/-10					
+ 32-40-07-200-801 (s)	BRAKE RESERVOIR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS. CHECK HYDRAULIC FLUID LEVEL. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 12-13-01-301	HRS/MSC AFL	200	+10/-10					
+ 32-40-07-680-801 32.150	BRAKE RESERVOIR - REPLACE HYDRAULIC FLUID. REF: AMM 12-13-05-301	MOS HRS/MSC AFL	36	+10%/-10%			07-OCT-2019	07-OCT-2022	25-JAN-2023
+ 32-50-00-200-801 (s)	STEERING CONTROL - CHECK CONDITION OF RODS, BELLCRANK, CAM AND ROLLERS. MAKE SURE THAT THERE ARE NO FRICTION POINTS IN THE CONTROL. PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 32-50-00-601	HRS/MSC AFL	400	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 33	LIGHTS								
+ 33-00-01-710-801 (s)	INSTRUMENT PANEL AND PL1 LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-00-01-501	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-00-01-710-802 (s)	CABIN LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-00-01-501	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-20-00-710-802 (s)	REAR BAGGAGE COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-20-00-501	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-30-01-710-801 (s)	FRONT CARGO COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-30-00-601	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-30-02-710-801 (s)	FUEL UNIT CLOGGING INDICATOR LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-30-00-601	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-40-00-710-801 (s)	EXTERIOR LIGHTS - CHECK FOR CONDITION, ATTACHMENTS AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-40-00-501	HRS/MSC AFL	200	+10/-10				2522:50	1877
+ 33-50-00-710-801 (s)	INSTRUMENT PANEL EMERGENCY LIGHTING - CHECK FOR CONDITION AND OPERATION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 33-50-00-601	HRS/MSC AFL	200	+10/-10				2522:50	1877



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 34 NAVIGATION									
+ 34-00-00-200-801 (s)	INDICATORS, CONTROLS AND COMPONENTS - CHECK FOR CONDITION AND ATTACHMENT. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: See Workcard	HRS/MSC AFL	200	+10/-10					
+ 34-00-00-200-802 (s)	ANTENNAS - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF CORROSION. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: See Workcard	HRS/MSC AFL	200	+10/-10					
+ 34-00-00-710-801	VFR EQUIPMENT - DO AN OPERATIONAL TEST.	MOS	24	+10%/-10%			03-OCT-2019	03-OCT-2021	15-DEC-2021
34.040	REF: GENERIC NO REF	HRS/MSC AFL							
+ 34-00-00-710-802	IFR EQUIPMENT - DO AN OPERATIONAL TEST.	MOS	24	+10%/-10%			03-OCT-2019	03-OCT-2021	15-DEC-2021
34.050	REF: GENERIC NO REF	HRS/MSC AFL							
+ 34-11-00-200-801 (s)	STATIC PRESSURE PORTS - CHECK FOR CONDITION AND CLEANLINESS. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 34-11-00-601	HRS/MSC AFL	200	+10/-10					
+ 34-11-00-200-802 (s)	AIR DATA SYSTEM LINES - CHECK FOR CONDITION, ATTACHMENT AND WEAR DUE TO CHAFING AT HOSE CONNECTIONS. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 34-11-00-601	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11-00-210-801 (s)	PITOT TUBES - CHECK FOR CONDITION, ATTACHMENT, CLEANLINESS AND EVIDENCE OF OVERHEATING. PKG 3 ,4 REF: AMM 34-11-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-00-790-801 (s)	AIR DATA SYSTEM - DO A LEAKAGE TEST OF STATIC AND DYNAMIC SYSTEMS AND CHECK OF ASSOCIATED INSTRUMENTS AND EQUIPMENT PKG 3 ,4 REF: AMM 34-11-00-501	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-00-820-801	AIR DATA COMPUTER - CHECK CALIBRATION 6045327281 2310 MANDATORY REF: See Workcard	MOS HRS/MSC AFL	24				03-OCT-2019	03-OCT-2021	
+ 34-11-00-820-802	ENCODING ALTIMETER - CHECK CALIBRATION 5934PAD3 454402 34.010 MANDATORY REF: See Workcard	MOS HRS/MSC AFL	24				03-OCT-2019	03-OCT-2021	
+ 34-11-00-820-802	ENCODING ALTIMETER - CHECK CALIBRATION 5934PAD3 454402 REF: See Workcard	MOS HRS/MSC AFL	24				03-OCT-2019	03-OCT-2021	
+ 34-11-00-870-801 (s)	STATIC SYSTEMS - BLEED SYSTEM PKG 3 ,4 REF: AMM 34-11-00-301	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-00-870-802 (s)	STATIC SYSTEMS - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED PKG 2 ,3 ,4 REF: AMM 34-11-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11-00-870-803 (s)	DYNAMIC SYSTEM - BLEED SYSTEM PKG 3 ,4 REF: AMM 34-11-00-301	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-00-870-804 (s)	DYNAMIC SYSTEM - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED PKG 2 ,3 ,4 REF: AMM 34-11-00-301	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-06-710-801 (s)	VMO WARNING - DO A GROUND OPERATIONAL TEST. PKG 3 ,4 REF: AMM 34-11-06-501	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-11-07-710-801 (s)	STALL WARNING SYSTEM - DO A GROUND OPERATIONAL TEST. PKG 2 ,3 ,4 REF: AMM 34-11-07-501	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-13-00-210-801 (s)	OUTSIDE AIR TEMPERATURE PROBE - CHECK FOR ATTACHMENT AND CONDITION. PKG 4 REF: AMM 34-13-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-13-00-210-802 (s)	TEMPERATURE INDICATOR - CHECK FOR ATTACHMENT AND CONDITION. PKG 4 REF: AMM 34-13-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 34-20-00-210-801 (s)	STANDBY COMPASS - CHECK FOR ATTACHMENT, CONDITION AND FLUID LEVEL. PKG 4 REF: AMM 34-20-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-23-01-820-801	STANDBY COMPASS - DO A COMPENSATION								
34.030	PN SN-UNKNOWN REF: AMM 34-23-01-501	MOS HRS/MSC AFL	36	+10%/-10%			06-MAY-2019	06-MAY-2022	24-AUG-2022
+ 34-53-00-710-801	NO. 1 TRANSPONDER CONTROL - DO AN OPERATIONAL TEST OF TRANSPONDER CONTROL.								
34.060 MANDATORY	011-00455-10 84206809 REF: FAR FAR PART 91.413	MOS HRS/MSC AFL	24				03-OCT-2019	03-OCT-2021	
+ 34-53-00-710-801	NO. 2 TRANSPONDER CONTROL - DO AN OPERATIONAL TEST OF TRANSPONDER AND CONTROL								
34.060 MANDATORY	011-00490-00 83724860 REF: FAR FAR PART 91.413	MOS HRS/MSC AFL	24				03-OCT-2019	03-OCT-2021	
CHAPTER 35 OXYGEN									
+ 35-00-00-710-801 (s)	GASEOUS OXYGEN SYSTEM, IF INSTALLED - CHECK COMPONENTS AND LINES FOR LEAKS, CONDITION AND ATTACHMENT. DO AN OPERATIONAL TEST.						PKG		
35.010	PKG 9 REF: AMM 35-00-00-501	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		
+ 35-11-01-200-801 (s)	GASEOUS OXYGEN CYLINDER, IF INSTALLED - CHECK FOR TIGHTNESS. CHECK FOR CORROSION AND DISTORTION (BULGE, DENT). CHECK FOR ATTACHMENT. CHECK HYDROSTATIC TEST DATE.						PKG		
	PKG 2 ,3 ,4 REF:	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			26-NOV-2020 2522:50 1877		
+ 35-11-01-730-801	GASEOUS OXYGEN CYLINDER - DO A HYDROSTATIC TEST (DOT E8162-1850)								
35.040 HYDRO CHECK	2213-6519 923 REF: AMM 35-11-01-401	MOS HRS/MSC AFL	60				16-OCT-2020	16-OCT-2025	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-11-01-900-801	GASEOUS OXYGEN CYLINDER - REPLACE 2213-6519 35.040 LIFE LIMIT Manufacture Date: 01-JUN-2015	MOS HRS/MSC AFL	180				26-NOV-2020 2522:50 1877	01-JUN-2030	
+ 35-11-02-730-801	COPILOT OXYGEN MASK - OVERHAUL MRA005 2600 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	72				01-DEC-2016	01-DEC-2022	
+ 35-11-02-730-801	PILOT OXYGEN MASK - OVERHAUL MRA005 2477 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	72				01-DEC-2019	01-DEC-2025	
+ 35-21-01-110-801 (s)	NO. 1 PASSENGERS MASKS, GASEOUS OXYGEN, IF INSTALLED - INSPECT AND DESINFECT. PKG 9 35.050 REF: AMM 35-21-01-301	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		
+ 35-21-01-110-801 (s)	NO. 2 PASSENGERS MASKS, GASEOUS OXYGEN, IF INSTALLED - INSPECT AND DESINFECT. PKG 9 35.050 REF: AMM 35-21-01-301	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		
+ 35-21-01-110-801 (s)	NO. 3 PASSENGERS MASKS, GASEOUS OXYGEN, IF INSTALLED - INSPECT AND DESINFECT. PKG 9 35.060 REF: AMM 35-21-01-301	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		
+ 35-21-01-110-801 (s)	NO. 4 PASSENGERS MASKS, GASEOUS OXYGEN, IF INSTALLED - INSPECT AND DESINFECT. PKG 9 35.060 REF: AMM 35-21-01-301	MOS HRS/MSC AFL	12	+1m/-1m			26-NOV-2020 2522:50 1877		

CHAPTER 37 VACUUM



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 37-10-00-200-801 (s)	VENTURI - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 37-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 37-10-00-200-802 (s)	LINES - CHECK FOR CONDITION AND ATTACHMENTS. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 37-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 37-10-00-200-803 (s)	VACUUM REGULATOR - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 37-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 37-10-00-200-804 (s)	PRESSURE REGULATOR - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 37-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 37-10-00-200-805 (s)	PRESSURE SWITCH - CHECK FOR CONDITION AND ATTACHMENT. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 37-10-00-601	HRS/MSC AFL	800	+10/-10					

CHAPTER 51 STD PRACTICES AND STRUCT-GENRL

51-25-00-370-801 WITH MOD 70-135-11 - AIRCRAFT WITHOUT FINISH PAINT. AIRCRAFT MUST MANDATORILY BE PAINTED, AS PER DRAWING T700B-1110056, LAST ISSUE, WITHIN FIVE WEEKS AFTER AIRCRAFT INITIAL ACCEPTANCE (DELIVERY OF EXPORT CERTIFICATE OF AIRWORTHINESS BY FRENCH AUTHORITIES).

AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC - AFL
---------------	---------------------	-------------------------

CHAPTER 52 DOORS

+ 52-11-00-200-803 (s)	LATCH CATCH AND FITTING ASSEMBLIES (LARGE DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-11-00-601	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-11-00-200-804 (s)	LARGE DOOR SEAL - CHECK FOR CONDITION. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-11-00-601	HRS/MSC AFL	800	+10/-10					
+ 52-11-00-200-805 (s)	LARGE DOOR CLOSING MECHANISM - EXAMINE CABLE FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. CHECK GEARED MOTOR ASSEMBLY FOR SECURITY AND CONDITION. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-11-00-601	HRS/MSC AFL	800						
+ 52-11-00-220-801 (s)	LARGE DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-11-00-601	HRS/MSC AFL	800						
+ 52-11-00-710-801 (s)	LARGE DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK AND GAS STRUTS FOR OPERATION. CHECK CENTERING ROLLER FOR WEAR AND OPERATION. PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-11-00-601	HRS/MSC AFL	400						
52-12-00-200-802 (s)	PILOT DOOR - CHECK WINDOW FRAMING AND CARRY-THRU LONGERON ATTACHMENTS TO DOOR STRUCTURE FOR CRACKS AND LOOSE RIVETS. PKG 4	MOS	48	+1m/-1m			PKG 24-APR-2018 1807:18		
	REF: AMM 52-12-00-601	HRS/MSC AFL	800						
52-12-00-200-804 (s)	LATCH CATCH ASSEMBLIES AND PIN (PILOT DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR. PKG 4	MOS	48	+1m/-1m			PKG 24-APR-2018 1807:18		
	REF: AMM 52-12-00-601	HRS/MSC AFL	800	+10/-10					
52-12-00-200-805 (s)	PILOT DOOR SEAL - CHECK FOR CONDITION. PKG 4	MOS	48	+1m/-1m			PKG 24-APR-2018 1807:18		
	REF: AMM 52-12-00-601	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-12-00-220-801 (s)	PILOT DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES. PKG 4	MOS	48	+1m/-1m			PKG 24-APR-2018 1807:18		
	REF: AMM 52-12-00-601	HRS/MSC AFL	800	+10/-10					
52-12-00-710-801 (s)	PILOT DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK FOR OPERATION. PKG 3 ,4	MOS	24	+1m/-1m			PKG 06-MAY-2019 2189:24		
	REF: AMM 52-12-00-601	HRS/MSC AFL	400	+10/-10					
+ 52-20-00-710-801 (s)	EMERGENCY EXIT - CHECK FOR CONDITION, ATTACHMENT AND OPERATION (INSIDE AND OUTSIDE). PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-20-00-601	HRS/MSC AFL	400	+10/-10					
+ 52-30-01-010-801 (s)	OPEN ACCESS DOOR 211. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 06-30-01-01	HRS/MSC AFL	200	+10/-10					
+ 52-30-01-410-801 (s)	CLOSE ACCESS DOOR 211. PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 06-30-01-01	HRS/MSC AFL	200	+10/-10					
+ 52-30-01-710-801 (s)	ACCESS DOOR 211 - CHECK FOR CONDITION, ATTACHMENT AND LOCKING. CHECK OPERATION OF LOCK AND COMPENSATION ROD. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-30-01-601	HRS/MSC AFL	800	+10/-10					
+ 52-30-02-710-801 (s)	ACCESS DOOR 312 - CHECK FOR CONDITION, ATTACHMENT AND LOCKING. CHECK OPERATION OF LOCK AND COMPENSATION ROD. PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 52-30-02-601	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-40-01-210-801 (s)	LH WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-01-210-802 (s)	RH WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-010-801 (s)	REMOVE ACCESS PANEL 212, IF INSTALLED. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-010-802 (s)	REMOVE ACCESS PANELS 213 AND 214. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-010-803 (s)	OPEN ACCESS DOOR 311. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-210-801 (s)	ACCESS DOOR 311 - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: AMM 52-40-03-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-210-802 (s)	CLOGGING INDICATOR ACCESS DOOR - CHECK FOR CONDITION, ATTACHMENT AND LOCKING. PKG 4 REF: AMM 52-40-03-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-410-801 (s)	INSTALL ACCESS PANEL 212, IF REMOVED. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-40-03-410-802 (s)	INSTALL ACCESS PANELS 213 AND 214. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-40-03-410-803 (s)	CLOSE ACCESS DOOR 311. PKG 2 ,3 ,4 REF: AMM 06-30-01-01	MOS HRS/MSC AFL	12 200	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
+ 52-60-00-210-801 (s)	LARGE DOOR STAIRWAY AND HANDRAIL - CHECK FOR CONDITION, SECURITY AND OPERATION. EXAMINE HANDRAIL AND STAIRWAY CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. PKG 4 REF: AMM 52-60-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-71-00-710-801 (s)	LARGE DOOR INDICATION - CHECK FOR OPERATION. PKG 2 ,3 ,4 REF: AMM 52-71-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
52-71-00-710-802 (s)	PILOT DOOR INDICATION - CHECK FOR OPERATION. PKG 1,2 ,3 ,4 REF: AMM 52-71-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 17-FEB-2020 2381:48		
+ 52-80-01-200-801 (s)	MAIN LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF FITTINGS, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS. PKG 4 REF: AMM 52-80-01-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 52-80-02-200-801 (s)	NOSE LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF HINGES, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS. PKG 4 REF: AMM 52-80-02-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		

CHAPTER 53 FUSELAGE



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-00-200-801 (s)	LARGE DOOR FRAMING - CHECK DOOR FRAMING VISIBLE AREA AND STRUCTURE JUNCTION UNDER FLOOR FOR CRACKS AND LOOSE RIVETS.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
		HRS/MSC	800	+10/-10			2522:50		
	REF: AMM 53-00-00-601	AFL					1877		
53-00-00-200-802 (s)	PILOT DOOR FRAMING - CHECK FOR CRACKS AND LOOSE RIVETS.						PKG		
	PKG 4	MOS	48	+1m/-1m			24-APR-2018		
		HRS/MSC	800	+10/-10			1807:18		
	REF: AMM 53-00-00-601	AFL							
+ 53-00-00-210-802 (s)	EXTERNAL SURFACES - CHECK (REFER TO 53-00-00-601, PARAGRAPH 1)						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 53-00-00-601	AFL					1877		
+ 53-00-00-210-803 (s)	EXTERNAL SURFACES - CHECK, (REFER TO 53-00-00-601, PARAGRAPH 2)						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
		HRS/MSC	800	+10/-10			2522:50		
	REF: AMM 53-00-00-601	AFL					1877		
+ 53-00-00-280-801	UPPER FUSELAGE STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION								
53.020		MOS	168	+16m/-16m			01-OCT-2007	01-OCT-2021	M 01-FEB-2023
		HRS/MSC	6000	+600/-600				6000	M 6600
	REF: AMM 53-00-00-601	AFL							
+ 53-00-00-280-802	LARGE DOOR FRAMING - CHECK DOOR FRAMING AND STRUCTURE JUNCTIONS FOR CRACKS AND LOOSE RIVETS.								
53.040		MOS					04-OCT-2007		
		HRS/MSC	3000	+300/-300			0	3000	3300
	REF: AMM 53-00-00-601	AFL					0		
+ 53-00-00-280-803 (s)	PASSENGER DOORSTEP FRAME - CHECK FOR LOOSE RIVETS.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
		HRS/MSC	800	+10/-10			2522:50		
	REF: AMM 53-00-00-601	AFL					1877		
+ 53-00-00-900-801	FUSELAGE								
53.080	T700C5300000	MOS		N:0			04-OCT-2007		
	SN-UNKNOWN	HRS/MSC	16200	N:0			0	16200	
LIFE LIMIT	REF: GENERIC NO REF	AFL	12000	N:0			0	12000	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-00-200-801 (s)	DRAIN UNDER FLOOR - CHECK THAT DRAIN HOLES ARE NOT CLOGGED. CHECK GOOD CONDITION OF STRAINER SEAL OR SHUTTER. CHECK CLEANLINESS AND CORRECT ATTACHMENT OF STRAINER OR SEAT AND SHUTTER. CHECK THAT EMERGENCY EXIT DRAIN IS NOT CLOGGED.						PKG		
53.050	PKG 9	MOS	12				26-NOV-2020		
	REF: AMM 53-20-00-601	HRS/MSC					2522:50		
		AFL					1877		
+ 53-60-00-010-801 (s)	REMOVE FLOOR PANELS 222L, 222C, 222R, 232L, 232C, 232R, 241L, 241C, 241R, 251L,251C, 261L, 261C AND 261R.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
	REF: AMM 53-60-00-401	HRS/MSC	400	+10/-10			2522:50		
		AFL					1877		
+ 53-60-00-010-802 (s)	REMOVE FLOOR PANELS 231L AND 232L.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 53-60-00-401	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 53-60-00-200-801 (s)	FLOOR PANELS - CHECK FOR CONDITION AND DENTS.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 53-60-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 53-60-00-410-801 (s)	INSTALL FLOOR PANELS 222L, 222C, 222R, 232L, 232C, 232R, 241L, 241C, 241R, 251L, 251C, 261L, 261C AND 261R.						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
	REF: AMM 53-60-00-401	HRS/MSC	400	+10/-10			2522:50		
		AFL					1877		
+ 53-60-00-410-802 (s)	INSTALL FLOOR PANELS 231L AND 232L.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 53-60-00-401	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 53-70-00-200-801 (s)	PEDESTAL - CHECK FOR CRACKS AND EVIDENCE OF DAMAGE.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 53-70-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		

CHAPTER 55

STABILIZERS



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-00-00-280-803	HORIZONTAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION	MOS	168	+16m/-16m				01-OCT-2021 M	01-FEB-2023
	REF: AMM 55-10-00-601	HRS/MSC	6000	+600/-600				6000 M	6600
		AFL							
+ 55-00-00-280-804	VERTICAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION	MOS	60	+6m/-6m			25-OCT-2017	25-OCT-2022	25-APR-2023
	REF: AMM 55-30-00-601	HRS/MSC	3000	+300/-300			1596:06	4596:06	4896:06
		AFL							
+ 55-10-00-200-802 (s)	FIXED HORIZONTAL STABILIZER - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
	REF: AMM 55-10-00-601	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 55-10-00-280-801	FIXED HORIZONTAL STABILIZER - DO THE FOLLOWING INSPECTIONS : ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, TAPING INSPECTION FOR SKIN BONDINGS. (REFER TO 51-20-00)								
55.030	REF: See Workcard	MOS						17-FEB-2020	
		HRS/MSC	1200	+10%/-10%				2381:48	3581:48
		AFL							3701:48
+ 55-20-00-200-801 (s)	ELEVATORS - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK BONDING STRAPS FOR CONDITION. CHECK FITTINGS, BEARINGS AND HINGE PINS FOR CRACKS, EVIDENCE OF DAMAGE AND SLACK. CHECK ATTACHING BOLT SAFETYING. CHECK SLACK INTO THE ELEVATOR CONTROL.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
	REF: See Workcard	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
+ 55-20-00-200-803 (s)	ELEVATOR TRIM TABS - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF BEARINGS AND HINGE PINS AS WELL AS TRIM TABS FOR SLACK						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
	REF: AMM 55-20-00-601	HRS/MSC	200	-10%				2522:50	
		AFL						1877	
+ 55-20-00-280-801	ELEVATORS - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.								
55.060	REF: See Workcard	MOS						17-FEB-2020	
		HRS/MSC	1200	+10%/-10%				2381:48	3581:48
		AFL							3701:48



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-00-200-803 (s)	FIN - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION PKG 2 ,3 ,4 REF: AMM 55-30-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 55-30-00-280-801	FIN - DO THE FOLLOWING INSPECTIONS : - ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. (REFER TO 51-20-00) 55.040 REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 55-40-00-200-801 (s)	RUDDER - VISUALLY CHECK RUDDER AND HORN SKIN FOR CRACKS AND DENTS. CHECK CONDITION OF BONDING STRAP AND MAKE SURE THAT RUDDER DRAIN HOLES ARE NOT CLOGGED. CHECK FOR CONDITION, ATTACHMENT, CRACKS AND SLACK ON FITTINGS AND BEARINGS. VISUALLY CHECK THAT BOLTS ON UPPER AND CENTRAL BEARINGS AS WELL AS BEARING RIB NUT ARE SAFETIED PKG 2 ,3 ,4 REF: AMM 55-40-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 55-40-00-200-803 (s)	RUDDER TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF HINGE FITTINGS AND TRIM TAB FOR SLACK PKG 2 ,3 ,4 REF: AMM 55-40-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 55-40-00-280-801	RUDDER - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. 55.050 REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 55-40-00-640-801	RUDDER - SPRAY SICCATIVE OIL INSIDE THE TORQUE SHAFT REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48

CHAPTER 56 WINDOWS



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-10-00-210-801 (s)	WINDSHIELD AND SIDE WINDOWS - CHECK FOR CONDITION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 56-10-00-601	HRS/MSC AFL	200	+10/-10					
+ 56-20-00-210-801 (s)	CABIN WINDOWS - CHECK FOR CONDITION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 56-20-00-601	HRS/MSC AFL	200	+10/-10					
CHAPTER 57 WINGS									
+ 57-00-00-280-801	LEFT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION								
57.010		MOS	168	+16m/-16m				01-OCT-2021 M 01-FEB-2023 6000 M 6600	
	REF: AMM 57-00-00-601	HRS/MSC AFL	6000	+600/-600					
+ 57-00-00-280-802	RIGHT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPEC								
57.010		MOS	96	+9m/-9m				01-OCT-2021 M 01-JUL-2022 6000 M 6300	
	REF: AMM 57-00-00-601	HRS/MSC AFL	3000	+300/-300					
+ 57-10-00-210-801 (s)	L.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 57-10-00-210-802 (s)	R.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-10-00-601	HRS/MSC AFL	800	+10/-10					
+ 57-20-00-200-801 (s)	L.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-801	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-20-00-200-802 (s)	R.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-801	HRS/MSC AFL	800	+10/-10					
+ 57-20-00-200-803 (s)	L.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-601	HRS/MSC AFL	800	+10/-10					
+ 57-20-00-200-804 (s)	R.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-601	HRS/MSC AFL	800	+10/-10					
+ 57-20-00-200-805 (s)	L.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-601	HRS/MSC AFL	200	+10/-10					
+ 57-20-00-200-806 (s)	R.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 57-20-00-601	HRS/MSC AFL	200	+10/-10					
+ 57-20-00-900-801	LEFT WING T700A5720000 SN-UNKNOWN	MOS		N:0			04-OCT-2007 0		41600
57.010	REF: AMM 57-20-00-401	HRS/MSC AFL	41600	N:0			0		
LIFE LIMIT				N:0			0		
+ 57-20-00-900-801	RIGHT WING T700A5720000 SN-UNKNOWN	MOS		N:0			04-OCT-2007 0		41600
57.010	REF: AMM 57-20-00-401	HRS/MSC AFL	41600	N:0			0		
LIFE LIMIT				N:0			0		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-30-00-200-801 (s)	L.H. WING TIP - CHECK FOR CONDITION, ATTACHMENT AND DENTS PKG 3 ,4 REF: AMM 57-30-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-30-00-200-802 (s)	R.H. WING TIP - CHECK FOR CONDITION, ATTACHMENT AND DENTS PKG 3 ,4 REF: AMM 57-30-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-801 (s)	L.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-802 (s)	R.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT. PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-803 (s)	L.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-804 (s)	R.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-805 (s)	L.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-00-200-806 (s)	R.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-812 (s)	L.H. FLAP CARRIAGES - AIRCRAFT S/N 93 - 96, 99 - 9999, CHECK FOR CRACKS PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-200-814 (s)	R.H. FLAP CARRIAGES - AIRCRAFT S/N 93 - 96, 99 - 9999, CHECK FOR CRACKS PKG 2 ,3 ,4 REF: AMM 57-50-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-50-00-280-801	L.H. FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. 57.020 REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 57-50-00-280-802	R.H FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. 57.020 REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 57-60-00-200-803 (s)	AILERON TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK HINGES FOR CONDITION AND TRIM TAB FOR SLACK. CHECK BONDING STRAP FOR CONDITION. PKG 2 ,3 ,4 REF: AMM 57-60-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-60-00-210-801 (s)	L.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS PKG 2 ,3 ,4 REF: AMM 57-60-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60-00-210-802 (s)	R.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS PKG 2 ,3 ,4 REF: AMM 57-60-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-60-00-280-801	L.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 57-60-00-280-802	R.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS. REF: See Workcard	MOS HRS/MSC AFL	1200	+10%/-10%			17-FEB-2020 2381:48	3581:48	3701:48
+ 57-70-00-210-801 (s)	L.H. SPOILER - CHECK FOR CONDITION PKG 2 ,3 ,4 REF: AMM 57-70-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 57-70-00-210-802 (s)	R.H. SPOILER - CHECK FOR CONDITION PKG 2 ,3 ,4 REF: AMM 57-70-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
CHAPTER 61	PROPELLERS/PROPULSORS								
+ 61-10-00-220-801	BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +10%/-10%			26-NOV-2020 2522:50 1877	26-NOV-2021 3122:50	26-DEC-2021 3182:50
+ 61-10-01-640-801	PROPELLER - LUBRICATE. REF: AMM 61-10-01-301	MOS HRS/MSC AFL	12 400	+1m/-1m +10%/-10%			26-NOV-2020 2522:50 1877	26-NOV-2021 2922:50	26-DEC-2021 2962:50



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 61-20-00-200-801 (s)	PROPELLER GOVERNOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS PKG 2 ,3 ,4 REF: AMM 61-20-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 61-20-01-200-801 (s)	L2 PROPELLER OVERSPEED VALVE - CHECK FOR ATTACHMENT, LEAKS AND FOR ROUTING AND CONDITION OF WIRING PKG 2 ,3 ,4 REF: AMM 61-20-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 61-20-01-730-801 61.030	L2 PROPELLER OVERSPEED VALVE - OVERHAUL 6097867224 15244527 REF: AMM 61-20-01-401	MOS HRS/MSC AFL	3500	N:0 N:0 N:0			04-OCT-2007 0 0	3500	
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 61-20-00-730-801	NO. 1 ENGINE - PROPELLER GOVERNOR - OVERHAUL 8210-007-001 13603000G REF:	MOS HRS/MSC ENC	4000	N:0 N:0 N:0			04-OCT-2007 0 0	(4000) 4000	
PROPELLER NO. 1 Model : HC-E4N-3 Serial # HH2965 Part # HC-E4N-3/E9083SK									
61-10-00-200-801	NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION REF:	MOS HRS/MSC	12 400	+10% +10%			13-JAN-2021 2520:10	13-JAN-2022 (2920:10) 2991:14	18-FEB-2022 2960:10
610004	NO. 1 PROPELLER - INSPECTION OF THE DE-ICE SYSTEM REF: MM 30-61-80	MOS HRS/MSC	12 200				13-JAN-2021 2520:10	13-JAN-2022 (2720:10) 2791:14	
+ 610010 OVERHAUL	NO. 1 PROPELLER - OVERHAUL REF:	MOS HRS/MSC	72 3600				13-JAN-2021 2520:10	13-JAN-2022 (6120:10) 6191:14	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS	12	+10%			13-JAN-2021	13-JAN-2022	18-FEB-2022
		HRS/MSC	400	+10%			2520:10	(2920:10) 2991:14	2960:10
	REF:								
610040	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS	12	+10%			26-NOV-2020	26-NOV-2021	01-JAN-2022
		HRS/MSC	400	+10%			2520:10	(2920:10) 2991:14	2960:10
	REF:								
CHAPTER 71 POWER PLANT									
+ 71-00-00-100-801 (s)	IF NECESSARY, CLEAN ENGINE AND COWLINGS						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 71-00-00-701	AFL					1877		
+ 71-00-00-200-801 (s)	POWERPLANT - CHECK						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 71-00-00-601	AFL					1877		
+ 71-00-00-200-802 (s)	FIREWALL - CHECK FOR CONDITION AND EVIDENCE OF DAMAGE.						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
		HRS/MSC	800	+10/-10			2522:50		
	REF: AMM 53-00-00-601	AFL					1877		
+ 71-00-00-200-803 (s)	SOLENOID VALVE - CHECK FOR CONDITION, ATTACHMENTS AND LEAKS.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 61-20-01-401	AFL					1877		
+ 71-10-00-010-801 (s)	OPEN ENGINE COWLINGS 131 AND 132.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF:	AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-10-00-010-802 (s)	REMOVE ENGINE COWLINGS 121, 122, 133 AND 134 PKG 2 ,3 ,4 REF: AMM 71-10-00-401	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 71-10-00-210-801 (s)	POWER PLANT COWLING ASSEMBLY - CHECK FOR PAINT CONDITION, DENTS, CRACKS AND LOOSE RIVETS. CHECK FOR EROSION AT ENGINE COWLING 122 AIR INTAKE PKG 2 ,3 ,4 REF: AMM 71-10-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 71-10-00-410-801 (s)	CLOSE ENGINE COWLINGS 131 AND 132. PKG 2 ,3 ,4 REF:	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 71-10-00-410-802 (s)	INSTALL ENGINE COWLINGS 121, 122, 133 AND 134 PKG 2 ,3 ,4 REF: AMM 71-10-00-401	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 71-20-00-200-801 (s)	ENGINE MOUNT - CHECK FOR ATTACHMENT, CRACKS AND EVIDENCE OF DAMAGE CHECK ELASTOMER VIBRATION ISOLATORS FOR CONDITION AND ATTACHMENT PKG 2 ,3 ,4 REF: AMM 71-20-00-601	MOS HRS/MSC AFL	12 200	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 71-20-00-900-801	LEFT LOWER VIBRATION ISOLATOR - REPLACE ELASTOMER 71.010 SCRAP REF: AMM 71-20-00-401	MOS HRS/MSC AFL	3500				04-OCT-2007 0 0	3500	
+ 71-20-00-900-801	LEFT UPPER VIBRATION ISOLATOR - REPLACE ELASTOMER 71.010 SCRAP REF: AMM 71-20-00-401	MOS HRS/MSC AFL	3500				04-OCT-2007 0 0	3500	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-20-00-900-801	RIGHT LOWER VIBRATION ISOLATOR - REPLACE ELASTOMER								
71.020		MOS					04-OCT-2007		
SCRAP	REF: AMM 71-20-00-401	HRS/MSC	3500				0		3500
		AFL					0		
+ 71-20-00-900-801	RIGHT UPPER VIBRATION ISOLATOR - REPLACE ELASTOMER								
71.020		MOS					04-OCT-2007		
SCRAP	REF: AMM 71-20-00-401	HRS/MSC	3500				0		3500
		AFL					0		
+ 71-60-01-200-802 (s)	INERTIAL SEPARATOR - CHECK FOR CRACKS						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
	REF: AMM 71-60-01-601	HRS/MSC	400	+10/-10			2522:50		
		AFL					1877		
+ 71-60-01-200-805 (s)	INERTIAL SEPARATOR - CHECK THAT DRAIN HOLE IS NOT CLOGGED.						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 71-60-01-601	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 71-60-02-010-801 (s)	REMOVE ENGINE PLENUM CHAMBER ACCESS PANELS 138 AND 139						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 71-60-02-401	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 71-60-02-200-801 (s)	ENGINE PLENUM CHAMBER - CHECK						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 71-60-02-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		
+ 71-60-02-410-801 (s)	INSTALL ENGINE PLENUM CHAMBER ACCESS PANELS 138 AND 139						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
	REF: AMM 71-60-02-401	HRS/MSC	200	+10/-10			2522:50		
		AFL					1877		
+ 71-70-00-200-801 (s)	ECOLOGICAL TANK AND ENGINE DRAINS - CHECK HOSES AND RIGID PIPES FOR ATTACHMENT, ROUTING AND CONDITION						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
	REF: AMM 71-70-00-601	HRS/MSC	800	+10/-10			2522:50		
		AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 71-00-CA-820-801 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 71-00-00	ENC					1876		
CHAPTER 72 ENGINE									
72-00-00-200-801 (s)	ENGINE - CHECK FOR GENERAL CONDITION, ATTACHMENT, LINKAGE AND EVIDENCE OF DAMAGE						PKG		
	PKG 1,2,3,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF:	AFL					1877		
+ 72-10-00-200-801 (s)	PROPELLER DRIVE SHAFT SEAL - CHECK FOR LEAKS AND ATTACHMENT						PKG		
	PKG 2,3,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: EMM 72-10-00	AFL					1877		
72-30-00-200-801 (s)	GENERATOR TURBINE CASE - CHECK FOR CRACKS, DISTORTIONS AND CORROSION						PKG		
	PKG 3,4	MOS	24	+1m/-1m			26-NOV-2020		
		HRS/MSC	400	+10/-10			2522:50		
	REF:	AFL					1877		
72-60-00-200-801 (s)	ACCESSORY GEARBOX BREATHER LINE - CHECK FOR CONDITION AND ATTACHMENT						PKG		
	PKG 3,4	MOS	24	+1m/-1m			26-NOV-2020		
		HRS/MSC	400	+10/-10			2522:50		
	REF:	AFL					1877		
72-60-00-200-802 (s)	ENGINE ACCESSORIES - CHECK FOR GENERAL CONDITION, ATTACHMENTS AND LINKAGE						PKG		
	PKG 1,2,3,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF:	AFL					1877		
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 72-00-00-290-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION WITH BOROSCOPE								
		MOS					26-NOV-2020		
		HRS/MSC	400	+10%			2520:10	(2920:10) 2920:10	2960:10
	REF: See Workcard	ENC					1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-730-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION (HSI)	MOS					16-OCT-2018		
	REF: EMM 72-00-00	HRS/MSC	1750	+250			1978:54	(3728:54) 3728:54	3978:54
		ENC					1615		
+ 72-00-00-730-802	NO. 1 ENGINE - ENGINE - OVERHAUL	MOS					04-OCT-2007		
	OVERHAUL REF:	HRS/MSC	3500				0	(3500) 3500	
		ENC					0		
+ 72-00-CA-200-801 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
	REF: EMM 70-00-00	HRS/MSC	200	+10			2520:10		
		ENC					1876		
+ 72-00-CA-200-802 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
	REF: EMM 70-00-00	HRS/MSC	200	+10			2520:10		
		ENC					1876		
+ 72-00-CA-200-803 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
	REF: EMM 70-00-00	HRS/MSC	200	+10			2520:10		
		ENC					1876		
+ 72-00-CA-200-804 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
	REF: EMM 70-00-00	HRS/MSC	200	+10			2520:10		
		ENC					1876		
+ 72-00-CA-200-805 (s)	NO. 1 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
	REF: EMM 70-00-00	HRS/MSC	200	+10			2520:10		
		ENC					1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-CA-290-801 (s)	NO. 1 ENGINE - VISUAL INSPECT FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 72-00-00	ENC					1876		
72-00-CA-900-801	NO. 1 ENGINE - GAS GENERATOR MODULE								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	3500	+200	N:0		0	(3500) 3500	3700
OVERHAUL	REF: EMM 72-30-04	ENC							
+ 72-20-CA-200-801 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 72-20-00	ENC					1876		
+ 72-20-CA-200-802 (s)	NO. 1 ENGINE - INSPECT WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE THE COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: GENERIC NO REF	ENC					1876		
+ 72-30-CA-200-801 (s)	NO. 1 ENGINE - INSPECT/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 72-30-04	ENC					1876		
+ 72-30-CA-200-802 (s)	NO. 1 ENGINE - CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: GENERIC NO REF	ENC					1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-30-CA-900-802	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 EAAA000A662 REF: EMM 72-30-05	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
72-30-CA-900-804	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA048113 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
72-30-CA-900-805	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 TXA1B2271 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
+ 72-30-CA-900-806	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000A713 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
+ 72-30-CA-900-807	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAA000A544 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
+ 72-30-CA-900-808	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAA000C323 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	24000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
+ 72-50-CA-200-801 (s)	NO. 1 ENGINE - INSPECT/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 1 REF: EMM 72-50-05	MOS HRS/MSC ENC	12 200	+1m +10			PKG 26-NOV-2020 2520:10 1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-50-CA-900-803	NO. 1 ENGINE - COMPRESSOR TURBINE DISC 3053740-01 YUAB001L527 REF: EMM 72-50-02	MOS HRS/MSC ENC ACCCYC	8000	N:0			16-OCT-2018	(9615) 9615 M	
LIFE LIMIT									
+ 72-50-CA-900-805	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISC 3037312 A002729F REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	15000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
+ 72-50-CA-900-806	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISC 3037313 A0026K47 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	15000	N:0 N:0 N:0 N:0			04-OCT-2007 0 0		
LIFE LIMIT									
72-50-CA-900-810	NO. 1 ENGINE - NO. 1 FIRST STAGE RGB PLANET GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	N:0			0	(3000) 3000	
OVERHAUL									
72-50-CA-900-810	NO. 1 ENGINE - NO. 2 FIRST STAGE RGB PLANET GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	N:0			0	(3000) 3000	
OVERHAUL									
72-50-CA-900-810	NO. 1 ENGINE - NO. 3 FIRST STAGE RGB PLANET GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	N:0			0	(3000) 3000	
OVERHAUL									
72-60-CA-900-808	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200 N:0			0	(3500) 3500	3700
OVERHAUL									

CHAPTER 73 ENGINE FUEL AND CONTROL



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-06-200-801 (s)	GENERATOR CASE DRAIN - CHECK FOR ATTACHMENT AND LEAKS PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF:	AFL	800	+10/-10					
73-10-07-130-801 (s)	P3 FILTER - ULTRASONIC CLEANING. CHECK FOR CONDITON AND ATTACHMENT. PKG 1,2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: See Workcard	AFL	200	+10/-10					
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 73-10-02-200-801	NO. 1 ENGINE - FUEL PUMP INLET SCREEN - CHECK AND CLEAN 6048517292 470	MOS					17-FEB-2020 2381:48	(2981:48) 2981:48	3041:48
	REF:	ENC	600	+10%					
+ 73-10-02-200-802 (s)	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - CHECK FOR FOREIGN MATTER OR DISTORTION PKG 1	MOS	12	+1m			PKG 26-NOV-2020 2520:10 1876		
	REF:	ENC	200	+10					
+ 73-10-02-960-801	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - REPLACE 6048517292 470	MOS					17-FEB-2020 2381:48	(2981:48) 2981:48	3041:48
	REPLACE REF: EMM 73-10-02	ENC	600	+10%					
+ 73-10-05-790-801	NO. 1 ENGINE - FUEL MANIFOLD ADAPTERS - PERFORM LEAK TEST AND FUNCTION TEST	MOS					26-NOV-2020 2520:10 1876	(2720:10) 2720:10	2740:10
	REF: EMM 73-11-05	ENC	200	+10%					
+ 73-10-07-960-801	NO. 1 ENGINE - P3 FILTER - REPLACE ZOON6069607245 SN-UNKNOWN	MOS					16-OCT-2016 1978:54	(2978:54) 2978:54	3078:54
	REPLACE REF:	ENC	1000	+100					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-CA-200-801 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 72-00-00	ENC					1876		
+ 73-10-CA-200-802 (s)	NO. 1 ENGINE - CHECK FLOW DIVIDER FOR INSTALLATION AND LEAKS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-04	ENC					1876		
+ 73-10-CA-200-803 (s)	NO. 1 ENGINE - CHECK OIL-TO-FUEL HEATER INSTALLATION						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-01	ENC					1876		
+ 73-10-CA-200-804 (s)	NO. 1 ENGINE - CHECK P3 FILTER FOR INSTALLATION						PKG		
	ZOON6069607245 PKG 1	MOS	12	+1m			26-NOV-2020		
	SN-UNKNOWN	HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-07	ENC					1876		
+ 73-10-CA-200-805 (s)	NO. 1 ENGINE - CHECK DRAIN VALVE(S) FOR INSTALLATION AND LEAKS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-06	ENC					1876		
+ 73-10-CA-200-806 (s)	NO. 1 ENGINE - CHECK FUEL PUMP FOR INSTALLATION AND LEAKS						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-02	ENC					1876		
+ 73-10-CA-210-804 (s)	NO. 1 ENGINE - EXAMINE PNEUMATIC SYSTEM FILTER BOWL						PKG		
	PKG 1	MOS	12	+1m			26-NOV-2020		
		HRS/MSC	200	+10			2520:10		
	REF: EMM 73-10-07	ENC					1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-CA-900-801	NO. 1 ENGINE - REPLACE FUEL CONTROL UNIT BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	4000				0	(4000) 4000	
LIFE LIMIT									
+ 73-10-CA-900-802	NO. 1 ENGINE - ENGINE DRIVEN FUEL PUMP 6048517292 470 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	+500	O:0 O:0 O:0		09-OCT-2017 1596:06	(5096:06) 5096:06	5596:06
OVERHAUL									
+ 73-10-CA-900-803	NO. 1 ENGINE - FUEL HEATER PN SN-UNKNOWN REF: EMM 73-10-01	MOS HRS/MSC ENC	4000		N:0		0	(4000) 4000	
+ 73-10-CA-900-804	NO. 1 ENGINE - FLOW DIVIDER/START CONTROL VALVE 25638-3 1431 REF: EMM 73-10-04	MOS HRS/MSC ENC	4000		N:0		16-JUL-2015 1177:48	(5177:48) 5177:48	
73-10-CA-900-805	NO. 1 ENGINE - FUEL CONTROL UNIT PN SN-UNKNOWN REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL									
73-11-CA-900-801	NO. 1 ENGINE - OVERTORQUE LIMITER PN SN-UNKNOWN REF: EMM 73-10-09	MOS HRS/MSC ENC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL									
+ 73-20-CA-200-801 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 1 REF: EMM 73-20-00	MOS HRS/MSC ENC	12 200	+1m +10			PKG 26-NOV-2020 2520:10 1876		
+ 73-30-CA-100-801 (s)	NO. 1 ENGINE - CLEAN PNEUMATIC P3 FILTER ZOON6069607245 PKG 1 SN-UNKNOWN REF: EMM 73-10-07	MOS HRS/MSC ENC	12 200	+1m +10			PKG 26-NOV-2020 2520:10 1876		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-30-CA-100-802 (s)	NO. 1 ENGINE - CLEAN/INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 1	MOS	12	+1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC	200	+10				2520:10	
		ENC						1876	
CHAPTER 74 IGNITION									
74-10-00-200-801 (s)	IGNITION EXCITER - CHECK FOR CONDITION AND ATTACHMENT PKG 1,2,3,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
74-20-00-200-801 (s)	IGNITION CABLES - CHECK FOR ROUTING, ATTACHMENT AND WEAR DUE TO CHAFING PKG 4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: AMM 74-00-00-601	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
74-20-00-200-802 (s)	SPARK IGNITERS - CHECK FOR CLEANLINESS AND EROSION PKG 1,2,3,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: EMM 74-20-00	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
74-20-00-710-801 (s)	SPARK IGNITERS - DO AN OPERATIONAL TEST. PKG 1,2,3,4	MOS	12	+1m/-1m			PKG	26-NOV-2020	
	REF: See Workcard	HRS/MSC	200	+10/-10				2522:50	
		AFL						1877	
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 74-00-CA-200-801 (s)	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION PKG 1	MOS	12	+1m			PKG	26-NOV-2020	
	REF: EMM 74-10-00	HRS/MSC	200	+10				2520:10	
		ENC						1876	
+ 74-00-CA-200-802 (s)	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION (REF. 74-20-00, INSPECTION/CHECK). PKG 1	MOS	12				PKG	26-NOV-2020	
	REF:	HRS/MSC	200					2520:10	
		ENC						1876	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-00-CA-900-801	NO. 1 ENGINE - IGNITION EXCITER								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL	REF: EMM 74-10-00	ENC							
+ 74-20-CA-200-802 (s)	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION						PKG		
	PKG 1	MOS	12	+1m				26-NOV-2020	
		HRS/MSC	200	+10				2520:10	
	REF: EMM 74-20-00	ENC						1876	
CHAPTER 75 AIR									
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 75-30-CA-900-801	NO. 1 ENGINE - BLEED VALVE COMPRESSOR								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL	REF: EMM 75-30-00	ENC							
CHAPTER 76 ENGINE CONTROLS									
+ 76-10-00-200-801 (s)	ENGINE CONTROLS - CHECK FOR TRAVEL, ATTACHMENT, ROUTING AND EVIDENCE OF DAMAGE						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m				26-NOV-2020	
		HRS/MSC	200	+10/-10				2522:50	
	REF: AMM 76-10-00-601	AFL						1877	
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 76-10-CA-200-801 (s)	NO. 1 ENGINE - INSPECT CONTROL LINKAGES						PKG		
	PKG 1	MOS	12	+1m				26-NOV-2020	
		HRS/MSC	200	+10				2520:10	
	REF: EMM 72-00-00	ENC						1876	
CHAPTER 77 ENGINE INDICATING									
+ 77-11-00-200-801 (s)	MT12 NG TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 77-00-00-601	AFL						1877	
+ 77-11-00-210-801 (s)	M12 NG TACHOMETER - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE						PKG		
	PKG 4	MOS	48	+1m/-1m				26-NOV-2020	
		HRS/MSC	800	+10/-10				2522:50	
	REF: AMM 77-00-00-601	AFL						1877	



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 77-12-00-200-801 (s)	MT41 FUEL FLOW TRANSMITTER - CHECK FOR ATTACHMENT, LEAKS AND EVIDENCE OF DAMAGE PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	200	+10/-10					
+ 77-12-00-210-801 (s)	TOTALIZER / FLOW INDICATOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	800	+10/-10					
+ 77-13-00-200-801 (s)	MT11 NP TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	800	+10/-10					
+ 77-13-00-210-801 (s)	M11 PROPELLER TACHOMETER - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	800	+10/-10					
+ 77-14-00-200-801 (s)	MT10 TORQUE TRANSMITTER - CHECK FOR ATTACHMENT AND LEAKS PKG 2 ,3 ,4	MOS	12	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	200	+10/-10					
+ 77-14-00-210-801 (s)	M10 TORQUE INDICATOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 3 ,4	MOS	24	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	400	+10/-10					
+ 77-20-00-200-802 (s)	MT13 THERMOCOUPLE HARNESS - CHECK FOR CONDITION AND ATTACHMENT PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	800	+10/-10					
+ 77-20-00-210-801 (s)	M13 ITT TEMPERATURE INDICATOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4	MOS	48	+1m/-1m			PKG 26-NOV-2020 2522:50 1877		
	REF: AMM 77-00-00-601	HRS/MSC AFL	800	+10/-10					



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARDES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 78 EXHAUST									
+ 78-10-00-200-801 (s)	EXHAUST STUBS - CHECK FOR ATTACHMENT, CRACKS, DISTORTIONS AND EVIDENCE OF DAMAGE						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: AMM 78-10-00-601	AFL					1877		
CHAPTER 79 OIL									
+ 79-10-00-200-801 (s)	OIL FILLER CAP - CHECK FOR CONDITION AND ATTACHMENT						PKG		
	PKG 2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: EMM 72-60-00	AFL					1877		
79-20-00-200-801 (s)	OIL FILTER - INSPECT AND CLEAN IF NECESSARY						PKG		
	PKG 1,2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: EMM 79-20-02	AFL					1877		
+ 79-20-00-200-803 (s)	OIL COOLER - CHECK FOR CONDITION, ATTACHMENT, EVIDENCE OF DAMAGE AND LEAKS CHECK CORE CLEANLINESS						PKG		
	PKG 4	MOS	48	+1m/-1m			26-NOV-2020		
		HRS/MSC	800	+10/-10			2522:50		
	REF: AMM 79-20-00-601	AFL					1877		
+ 79-20-00-730-801	OIL COOLER								
79.020	PN-UNKNOWN	MOS			O:0		06-MAY-2019		
	SN-UNKNOWN	HRS/MSC	2100		O:0		2189:24		4289:24
OVERHAUL	REF: AMM 79-20-01-401	AFL			O:0				
79-20-02-760-801 (s)	CHIP DETECTOR - CHECK CONTINUITY WITH AN OHMMETER						PKG		
	PKG 1,2 ,3 ,4	MOS	12	+1m/-1m			26-NOV-2020		
		HRS/MSC	200	+10/-10			2522:50		
	REF: See Workcard	AFL					1877		
+ 79-30-00-200-801 (s)	S42 PRESSURE SWITCH AND MT15 OIL TEMPERATURE PROBE - CHECK FOR CONDITION, ATTACHMENT AND LEAKS						PKG		
	PKG 3 ,4	MOS	24	+1m/-1m			26-NOV-2020		
		HRS/MSC	400	+10/-10			2522:50		
	REF: AMM 79-30-00-601	AFL					1877		



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-30-00-200-802 (s)	MT14 OIL PRESSURE TRANSMITTER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS PKG 3 ,4 REF: AMM 79-30-00-601	MOS HRS/MSC AFL	24 400	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
+ 79-30-00-210-801 (s)	M14 DUAL INDICATOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE PKG 4 REF: AMM 79-30-00-601	MOS HRS/MSC AFL	48 800	+1m/-1m +10/-10			PKG 26-NOV-2020 2522:50 1877		
ENGINE NO. 1 Model : PT6A-66D Serial # PCE-RV0075 Part # 3071016-01									
+ 79-00-CA-200-801 (s)	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR(S) FOR CONTINUITY PKG 1 REF: EMM 79-20-02	MOS HRS/MSC ENC	12 200	+1m +10			PKG 26-NOV-2020 2520:10 1876		
+ 79-00-CA-200-802	NO. 1 ENGINE - EXAMINE THE OIL FILTER ELEMENT AND SECONDARY SCREEN REF: EMM 79-20-02	MOS HRS/MSC ENC	12 200	+1m +10			26-NOV-2020 2520:10 1876	26-NOV-2021 (2720:10) 2720:10	26-DEC-2021 2730:10
+ 79-00-CA-200-803 (s)	NO. 1 ENGINE - CHECK SCAVANGE OIL PUMP HOUSING FOR LEAKS PKG 1 REF: GENERIC NO REF	MOS HRS/MSC ENC	12 200	+1m +10			PKG 26-NOV-2020 2520:10 1876		
+ 79-20-00-200-802	NO. 1 ENGINE - ACCESSORY GEARBOX - CHECK INTERNAL SCAVENGE PUMP INLET SCREEN REF:	MOS HRS/MSC ENC	1000	+100			16-OCT-2018 1978:54	(2978:54) 2978:54	3078:54
+ 79-20-00-960-801	NO. 1 ENGINE - OIL FILTER - REPLACE PN-UNKNOWN SN-UNKNOWN REPLACE REF:	MOS HRS/MSC ENC	1000	+100			16-OCT-2018 1978:54	(2978:54) 2978:54	3078:54



Status Report

TBM 700N S/N 419 (OO-EXE): 2727:57 HRS, 1962 AFL as of 19-Aug-2021

Owner: GREEN SERVICES CVBA Operator: DAHER TARBES

Report Date: 13-SEP-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-20-02-710-801	NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST								
		MOS	12	+1m			26-NOV-2020	26-NOV-2021	26-DEC-2021
		HRS/MSC	600	+10%			2520:10	(3120:10) 3120:10	3180:10
	REF: EMM 79-20-02	ENC					1876		