



### Status Report

**PC-12/47E**  
**S/N 1160 OH-WWW**

**OWNER:** FLY 7 EXECUTIVE AVIATION SA  
**ADDRESS:** AEROPORT DE LAUSANNE  
LAUSANNE CH-1018  
**PHONE:** +41 21 648 21 42 (OPS)  
**FAX:** +41 21 648 21 43

**OPERATOR:** FLY 7 EXECUTIVE AVIATION SA  
**ADDRESS:** AEROPORT DE LAUSANNE  
LAUSANNE CH-1018  
**PHONE:** +41 21 648 21 42 (OPS)  
**FAX:** +41 21 648 21 43

**OPERATOR:** FLY 7 FINLAND OY  
**ADDRESS:** LIIKELENTOTIE 8  
VANTAA 01530  
**PHONE:** +358 40 594 3022  
**FAX:**

**ANALYST:** ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)  
**EMAIL:** ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)  
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS;

**AIRCRAFT SERIAL/REGNO:** 1160/OH-WWW **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 30-SEP-2009	3416:02 A/C HRS	as of 09-MAR-2022	_____ A/C HRS	as of ____/____/____
MANUFACTURER DATE: 23-SEP-2009	2504 AFL	as of 09-MAR-2022	_____ AFL	as of ____/____/____
	375:54 ACH	as of 02-SEP-2021	_____ ACH	as of ____/____/____

**ENGINE NO. 1 SERIAL/PART:** PCE-RY0189/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 30-SEP-2009	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	3416:02 ENG. HRS	as of 09-MAR-2022	_____ ENG. HRS
0 ENC		2457 ENC	as of 09-MAR-2022	_____ ENC

**PROPELLER NO SERIAL/PART:** KX804/HC-E4A-3D/E10477SK **MODEL:** HC-E4A-3 **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 04-SEP-2009	LAST ACTUALS		CURRENT ACTUAL	
0 PROP HRS	0 A/C HRS	3416:02 PROP HRS	as of 09-MAR-2022	_____ PROP HRS



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>								
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 15 in PKG 16,17,18,19,20,21	MOS				20-AUG-2021	PKG	
		HRS/MSC	A/R			3232:59		
	REF: AMM 05-20-00	AFL				2376		
<hr/>								
05401A	300 HOUR INSPECTION							
+								
	PKG 16	MOS				20-AUG-2021		
		HRS/MSC	300	+30/-30		3232:59	<b>3532:59</b>	3562:59
	REF: AMM 05-40-01	AFL				2376		
<hr/>								
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 17	MOS	12	+1m/-1m	-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
		HRS/MSC	300	+30/-30		3232:59	<b>3532:59</b>	3562:59
	REF: AMM 05-40-01	AFL				2376		
<hr/>								
05403A	600 HOUR INSPECTION							
+								
	PKG 18	MOS				20-AUG-2021		
		HRS/MSC	600	+60/-60		3232:59	<b>3832:59</b>	3892:59
	REF: AMM 05-40-01	AFL				2376		
<hr/>								
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 19	MOS	12	+1m/-1m	-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
		HRS/MSC	600	+60/-60		3232:59	<b>3832:59</b>	3892:59
	REF: AMM 05-40-01	AFL				2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	------------------	------	----------	-----	----------	------------	---------------------------	-----------

05405A +	1200 HOUR OR 12 MONTH INSPECTION							
	PKG 20	MOS	12	+1m/-1m	-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
		HRS/MSC	1200	+120/-120		3232:59	<b>4432:59</b>	4552:59
	REF: AMM 05-40-01	AFL				2376		

05406A +	2400 HOUR OR 24 MONTHS INSPECTION							
	PKG 21	MOS	24	+1m/-1m		17-AUG-2020	<b>17-AUG-2022</b>	17-SEP-2022
		HRS/MSC	2400	+60/-60		3051:53	<b>5451:53</b>	5511:53
	REF: AMM 05-40-01	AFL				2272		

ENGINE NO. 1	Model : PT6A-67B/-67P	Serial # PCE-RY0189	Part # 3072955-01
057010	NO. 1 ENGINE - MINOR INSPECTION		

	PKG 0	MOS				20-AUG-2021		
		HRS/MSC	300	+10%/-10%		3232:59	<b>(3532:59) 3532:59</b>	3562:59
	REF: See Workcard	ENC				2345		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
		HRS/MSC	A/R					3232:59	
	REF: GENERIC NO REF	AFL						2376	
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
		HRS/MSC	A/R					3232:59	
	REF: GENERIC NO REF	AFL						2376	
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
		HRS/MSC	A/R					3232:59	
	REF: GENERIC NO REF	AFL						2376	
050000	PLEASE COMPLY WITH FOLLOWING INSTRUCTIONS:								
	A. THIS WORK ORDER IS IN ACCORDANCE WITH AIRCRAFT MAINTENANCE PROGRAM (AMP):								
	- AMC / D-FNAH, ISSUE 2, REV 1, 16 OCT 2017								
	B. CRS SHOULD CONTAIN:								
	- AMP REFERENCE								
	- CAMO WO NUMBER								
	- MANUFACTURER DATAS USED (AS APPLICABLE) - MRO WO NUMBER								
	C. PROVIDE THE CAMO WITH FOLLOWING BEFORE AIRCRAFT DEPARTURE:								
	- LOGBOOK CRS								
	- CAMP WO TALLY SHEET								
		MOS						26-FEB-2018	
		HRS/MSC	-					2288	
	REF:	AFL						1754	
P019-160201	REVIEW HARTZELL PROPELLER INC, PROPELLER OWNER'S MANUAL REV 22, DATED FEB/2016								
		MOS						03-MAY-2016	
		HRS/MSC	-						
	REF:	AFL							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15	MOS						27-SEP-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b>	HRS/MSC -						1705:06	
		AFL						1377	
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16	MOS						23-JAN-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC -						1829:12	
		AFL						1481	
P47E-170719	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 17	MOS						29-AUG-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC -							
		AFL							
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04	MOS						30-SEP-2009	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC -						0	
		AFL						0	
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC -							
		AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19	MOS						08-NOV-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC -							
		AFL							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05	MOS						28-SEP-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS						07-JAN-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS						16-JUL-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS						30-SEP-2009	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL						0 0	
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS						11-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24	MOS						18-DEC-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-210716	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 25							05-AUG-2021	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
<hr/>									
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01</b>									
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25							17-JUL-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC						1632 1316	
<hr/>									
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0								
<b>REF:</b>		MOS HRS/MSC - ENC							
<hr/>									
E072-160421	NO. 1 ENGINE - REVIEW PWC, ENGINE MAINTENANCE MANUAL REV 44.0, MAR 07/2016							22-JUN-2016	
<b>REF: RCF E072</b>		MOS HRS/MSC - ENC						1601:48 1295	
<hr/>									
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26							06-NOV-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC						1752:48 1422	
<hr/>									
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1							24-JAN-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC						1830:48 1475	
<hr/>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						18-APR-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						18-APR-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0	MOS							
	<b>REF:</b>	HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PWC MAINTENANCE MANUAL (PN 3038338) REVISION 45.0 DATED 10 APR 2017	MOS						26-JUL-2017	
	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170621	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 25	MOS						15-AUG-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC					0 0		
E072-170707	NO. 1 ENGINE - REVIEW SB PT6A-72-14603 R27, DATED 07 JULY 2017	MOS						26-JUL-2017	
	<b>REF: RCF E072</b>	HRS/MSC - ENC							





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1	MOS						15-AUG-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC -						0	
		ENC						0	
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2	MOS						08-SEP-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072-170818</b>	HRS/MSC -						2097:42	
		ENC						1633	
E072-171030	NO. 1 ENGINE - REVIEW ENGINE MAINTENANCE MANUAL, REVISION 46.0, DATED 30 OCT 2017	MOS							
	<b>REF: RCF E072</b>	HRS/MSC -							
		ENC							
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS						22-MAY-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC -							
		ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS						14-JUN-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC -							
		ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS						15-NOV-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC -							
		ENC							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						25-SEP-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS						06-DEC-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						14-MAY-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS						22-AUG-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS						23-DEC-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS						16-APR-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0							11-MAY-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	MOS HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1							11-MAY-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	MOS HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2							04-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20							01-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29							01-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3							20-OCT-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-210412	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 53.0	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-210806	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 27	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-210913	NO. 1 ENGINE - REVIEW SB PT6A-72-14603 REV 30	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-211011	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 54.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EO72-171030	NO. 1 ENGINE - REVIEW ENGINE MAINTENANCE MANUAL, REVISION 46.0, DATED 30 OCT 2017	MOS						29-NOV-2017	
	REF:	HRS/MSC -							
		ENC							
<b>PROPELLER NO. 1 Model : HC-E4A-3 Serial # KX804 Part # HC-E4A-3D/E10477SK</b>									
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS						11-SEP-2016	
	REF: RCF P019	HRS/MSC -						1689:06	
	<b>REQUIREMENT CHANGE FORMS</b>								
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER OWNER'S MANUAL (NO.149) REVISION 23 DATED OCT/17	MOS						16-OCT-2017	
	REF:	HRS/MSC -							
P019-171002	NO. 1 PROPELLER - REVIEW HC-E4A-3 HC-SL-61-61 SL REV 11	MOS							
	REF: RCF P019	HRS/MSC -							
	<b>REQUIREMENT CHANGE FORMS</b>								
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS						03-MAY-2018	
	REF: RCF P019	HRS/MSC -							
	<b>REQUIREMENT CHANGE FORMS</b>								
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS						30-AUG-2018	
	REF: RCF P019	HRS/MSC -							
	<b>REQUIREMENT CHANGE FORMS</b>								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS						05-APR-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200301	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL (MANUAL 180) REVISION 32	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200501	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 26	MOS						23-JUL-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200501-1	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 147 REV 16	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 27	MOS						23-JUL-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 33	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC	-						
P019-200901	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 147 REV 17	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: See Workcard</b>	HRS/MSC	-						
P019-200901-1	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 34	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC	-						
P019-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC	-						
P019-210304	NO. 1 PROPELLER - REVIEW SERVICE LETTER HC-SL-61-61Y REVISION 13	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC	-						
P019-210401	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 TR-011	MOS							(EBT)
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC	-						



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-210601	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 28	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P019	HRS/MSC -							
P019-210601-1	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 36	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P019	HRS/MSC -							
P019-210707	NO. 1 PROPELLER - REVIEW HC-SL-61-61Y REV 14	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P019	HRS/MSC -							

## CHAPTER 04 LIMITATIONS

040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	60000	N:0			0		60000
		ACH							
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

## CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					30-SEP-2009		
	REF: AMM 05-10-30	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					30-SEP-2009		
	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
05ARC00	AIRWORTHINESS REVIEW CERTIFICATE (ARC)	MOS	12				08-SEP-2021		19-NOV-2022 M
	REF:	HRS/MSC							
		AFL							
<b>CHAPTER 06 DIMENSIONS AND AREAS</b>									
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
	REF: AMM 06-20-00	HRS/MSC	A/R				3232:59		
		AFL					2376		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
	REF: AMM 06-20-00	HRS/MSC	A/R				3232:59		
		AFL					2376		
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR.						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
	REF: AMM 06-20-00	HRS/MSC	A/R				3232:59		
		AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOINTHE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	A/R					3232:59	2376
<b>CHAPTER 07 LIFTING AND SHORING</b>									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
	REF: AMM 07-10-00	HRS/MSC AFL	A/R					3232:59	2376
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						20-AUG-2021	
	REF: AMM 07-10-00	HRS/MSC AFL	A/R					3232:59	2376
<b>CHAPTER 08 LEVELING AND WEIGHING</b>									
080000	WEIGHT CHECK AIRCRAFT								
08.005		MOS	48	+10%/-10%		31		20-AUG-2021	20-SEP-2025 13-FEB-2026
	REF: AMM 08-10-00	HRS/MSC AFL						3232:59	2376
<b>CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV</b>									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 17	MOS	12	+10%/-10%				20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				3232:59	2376
<b>CHAPTER 11 PLACARDS AND MARKINGS</b>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
<b>CHAPTER 12 SERVICING</b>									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG 20-AUG-2021		
	REF: AMM 12-20-01	HRS/MSC AFL	A/R				3232:59 2376		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 15 ,16,17,18,19,20,21	MOS					PKG 20-AUG-2021		
	REF: AMM 12-20-02	HRS/MSC AFL	A/R				3232:59 2376		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 15 ,16,17,18,19,20,21	MOS					PKG 20-AUG-2021		
	REF: AMM 12-20-03	HRS/MSC AFL	A/R				3232:59 2376		
<b>CHAPTER 20 STANDARD PRACTICES - AIRFRAME</b>									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)	MOS	12	+1m/-1m			20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
20.010	REF: AMM 20-40-00	HRS/MSC AFL				-13	3232:59 2376		
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)	MOS	6	+10%/-10%			20-AUG-2021	<b>21-JAN-2022</b>	08-FEB-2022
20.011	REF: AMM 20-40-00	HRS/MSC AFL				-30	3232:59 2376		
<b>CHAPTER 21 AIR CONDITIONING</b>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	REF: GENERIC NO REF	AFL					2272		
21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK								
		MOS	12	+10%/-10%		-13	20-AUG-2021	07-AUG-2022	13-SEP-2022
		HRS/MSC	3000				3232:59	6232:59	
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	AFL					2376		
21-30/314 (s)	PRESSURIZATION SAFETY VALVE - CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND						PKG		
	<b>CMT ITEM</b>								
	PN PKG 21	MOS	24	+10%/-10%		34	20-AUG-2021		
21.030	SN-UNKNOWN	HRS/MSC	2400	+10%/-10%			3232:59		
	REF: AMM 21-30-02	AFL					2376		
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
		MOS	12	+10%/-10%		-13	20-AUG-2021	07-AUG-2022	13-SEP-2022
21.045		HRS/MSC	3000				3232:59	6232:59	
<b>AIRWORTHINESS</b>	REF: AMM 21-30-00	AFL					2376		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
	<b>CMT ITEM</b>								
	PN	MOS	48	+10%/-10%			20-AUG-2021	20-AUG-2025	13-JAN-2026
21.040	SN-UNKNOWN	HRS/MSC	4800	+10%/-10%			3232:59	8032:59	8512:59
	REF: AMM 21-30-00	AFL					2376		
21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
		MOS					13-OCT-2017		
		HRS/MSC	N/A				2131		
	REF: AMM 21-43-00	AFL					1658		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH						PKG		
21.140	PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH						PKG		
21.150	9696781507 PKG 20 540888 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
21-40/50	CLEAN WATER SEPARATOR CONDENSER								
21.080	5214112047 PKG 20 2748 REF: AMM 21-40-03	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%	-13		20-AUG-2021 3232:59 2376	07-AUG-2022 4432:59	13-SEP-2022 4552:59
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
21.130	9738132216 193 REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	47		07-AUG-2019 2850:04 2131	23-SEP-2024 7650:04	23-MAR-2025 8130:04
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
21.120	9738132214 216 REF: AMM 21-60-05	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	47		07-AUG-2019 2850:04 2131	23-SEP-2024 7650:04	23-MAR-2025 8130:04
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 18 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			20-AUG-2021 3232:59 2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 18	MOS					20-AUG-2021		
	REF: AMM 21-40-02	HRS/MSC	600	+10%/-10%			3232:59		
		AFL					2376		
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			3232:59		
		AFL					2376		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)								
	9599022102	MOS	12	+1m/-1m		-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	1076	HRS/MSC	300	+10%/-10%			3232:59	<b>3532:59</b>	3562:59
	REF: AMM 21-40-03	AFL					2376		
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022102	MOS					30-SEP-2009		
	1076	HRS/MSC	N/A				0		
	REF: AMM 21-50-03	AFL					0		
		ACH					0		
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022102	MOS					30-SEP-2009		
	1076	HRS/MSC	N/A				0		
	REF: AMM 21-50-01	AFL					0		
		ACH					0		
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	9599022102	MOS					20-NOV-2015		
	1076	HRS/MSC					1456:48		
	REF: AMM 21-50-03	AFL					1203		
		ACH	500	+10%/-10%			154:42	<b>654:42</b>	704:42



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	9599022102 1076 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH					20-NOV-2015 1456:48 1203 154:42	654:42	704:42
21-CUS-01	PERFORM AIR-CONDITIONING HOURS STATEMENT								
	REF:	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%		-13	20-AUG-2021 3232:59 2376	07-AUG-2022 3532:59	07-SEP-2022 3562:59
210005	OVERPRESSURE SWITCH								
21.340	9738115105 822 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
210010	REFRIGERATION PACK								
21.255	9599020111 1610 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1592 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 2370 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1587 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210030	HP SHUT OFF VALVE								
21.280	2943A000 1270 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-AUG-2020 3051:53 2272		
210035	WATER SEPARATOR ASSY								
21.220	5214112047 2748 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1580 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022102 1076 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 509 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091122 103898-00194 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091132 21-F0303 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-OCT-2013 1011:06 907		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 540888 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	9599022118 491 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 539495 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 869 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	9599020160 661 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210180	CABIN PRESSURE CONTROL UNIT								
21.530	2119232-4 2119232-00445 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				21-OCT-2016 1731:12 1408		
210185	INTEG. ECS CONTROL UNIT								
21.540	959.90.20.129 0206 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210190	FLOOR DUCT TEMP. SENSOR								
21.550	9599020121 2336 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR								
21.560	9599020121 2332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	9633011005 225 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	9738132216 193 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	9738132214 216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	9633011105 0872B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 1156B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 1158B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	9633011106 1165B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR								
21.600	9599020121 2342 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
213050	RUN VAPOR CYCLE COOLING SYSTEM FOR 15 MINUTES								
21.050	REF: GENERIC NO REF	DAYS HRS/MSC AFL	A/R				0 0		
21C003	ECS CONTROLLER,6130C000-002								
	9599020129 206 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		

CHAPTER	AUTO FLIGHT					
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES					PKG
	PKG 21	MOS	24	+10%/-10%		17-AUG-2020
		HRS/MSC	2400	+10%/-10%		3051:53
	REF: GENERIC NO REF	AFL				2272



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10/60 (s)	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK PKG 20 REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1200	+1m/-1m +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
22-10/60 (s)	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK PKG 20 REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1200	+1m/-1m +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
22-10/60 (s)	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK PKG 20 REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1200	+1m/-1m +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 17 REF: AMM 22-20-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 16 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 20 REF: AMM 22-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220045	STICK PUSHER SERVO								
22.220	9786111103 80449 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	9786111124 80455 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
220060	STICK SHAKER								
22.230	9786111143 959 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
220070	STICK PUSHER								
22.170	9754423104 124868 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C				17-OCT-2017 2132:48 1661		
220075	KMC 9200 FLIGHT CONTROLLER								
22.270	9859912204 KMC9200-1017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:85 N:1731:12 N:1408			20-OCT-2016 1731:12 1408		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1542 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:85 N:1731:12 N:1408			20-OCT-2016 1731:12 1408		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1545 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:85 N:1731:12 N:1408			20-OCT-2016 1731:12 1408		
220100	RUDDER KSA 2700 SERVO								
22.260	9859912131 KSA2700-1562 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-MAY-2010 160:48 174		
220105	ELEVATOR KSA 2700 SERVO								
22.250	065-00190-0101 KSA2700-2323 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			13-OCT-2017 2131 1658		
220110	AILERON KSA 2700 SERVO								
22.240	9859912131 KSA2700-1558 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
220115	KMC 9200 VNAV FLIGHT CONTROLLER								
	985.99.12.204 1017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-NOV-2009		

## CHAPTER 23 COMMUNICATIONS



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH PKG 21	MOS	24	+10%/-10%			PKG	17-AUG-2020	
	REF: AMM 23-50-00	HRS/MSC AFL	2400	+10%/-10%				3051:53 2272	
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH PKG 21	MOS	24	+10%/-10%			PKG	17-AUG-2020	
	REF: AMM 23-12-00	HRS/MSC AFL	2400	+10%/-10%				3051:53 2272	
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203	MOS						30-SEP-2009	
	310-19544	HRS/MSC	O/C					0	
	REF: AMM 23-12-02	AFL						0	
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203	MOS						30-SEP-2009	
	310-19540	HRS/MSC	O/C					0	
	REF: AMM 23-12-03	AFL						0	
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
23.070	9848110210	MOS						30-SEP-2009	
	9299	HRS/MSC	O/C					0	
	REF: AMM 34-57-02	AFL						0	
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.090	069-01037-0102	MOS						21-FEB-2020	
	1083	HRS/MSC	O/C					3004:24	
	REF: AMM 23-12-01	AFL						2227	





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.080	069-01037-0102 3180 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C				21-JAN-2021 3151:21 2327		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	9859912108 E0268 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C				29-JUN-2017 2010:48 1592		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	9859912108 G0532 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 24 ELECTRICAL POWER</b>									
24-30/309 (s)	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437)								
24.210	<b>CMT ITEM</b> 978.91.23.407 P1541 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				17-AUG-2020 3051:53 2272		
24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-13	20-AUG-2021 3232:59 2376	<b>07-AUG-2022</b> <b>6232:59</b>	13-SEP-2022
<b>AIRWORTHINESS</b>									
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-13	20-AUG-2021 3232:59 2376	<b>07-AUG-2022</b> <b>6232:59</b>	13-SEP-2022
<b>AIRWORTHINESS</b>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST PKG 21	MOS	24	+10%/-10%			PKG 17-AUG-2020		
	REF: AMM 24-40-00	HRS/MSC AFL	2400	+10%/-10%			3051:53 2272		
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	REF: AMM 71-00-00	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
24-30/339	REMOVE AND SERVICE NO. 1 NICAD BATTERY <b>CMT ITEM</b>								
24.060	9761731302 12100144 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376	<b>20-AUG-2022</b> <b>3632:59</b>	26-SEP-2022 3672:59
24-30/339	REMOVE AND SERVICE NO. 2 NICAD BATTERY <b>CMT ITEM</b>								
24.061	9761731302 11800257 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376	<b>20-AUG-2022</b> <b>3632:59</b>	26-SEP-2022 3672:59
+ 24-30/473	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) <b>CMT ITEM</b>								
	978.91.23.407 PKG 18 P1541 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			20-AUG-2021 3232:59 2376	<b>3832:59</b>	3892:59
+ 24-30/474	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407) <b>CMT ITEM</b>								
	9789123407 PKG 18 P2163 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			20-AUG-2021 3232:59 2376	<b>3832:59</b>	3892:59



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR  978.91.23.407 P1541 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	+10%/-10%			17-AUG-2020 3051:53 2272	4251:53	4371:53
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR  9789123407 P2163 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+10%/-10%			07-AUG-2019 2850:04 2131	4050:04	4170:04
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR  9789123407 P2163 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A						
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE  PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 17-AUG-2020 3051:53 2272		
24-50/70  24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY <b>CMT ITEM</b> 501-1712-02 82123 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%			20-AUG-2021 3232:59 2376	20-AUG-2022	26-SEP-2022
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS  PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 17-AUG-2020 3051:53 2272		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	9882114111 P2165 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
240005-2	REGULATOR,VOLTAGE,51538-002A								
24.130	9882114111 P2145 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
240010	GENERATOR 1 300A CONTACTOR								
24.130	9740338113 P346 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
240015	GENERATOR 2 300A CONTACTOR								
24.130	9740338113 P339 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
240125	BATTERY/ EXIT POWER JUNCTION (BEPJB) BOX								
24.125	974.03.38.142 298 REF: AMM 24-40-01	MOS HRS/MSC AFL	O/C				09-NOV-2009		
243010	NO. 2 STARTER-GENERATOR								
24.215	9789123407 P2163 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 N:2364:21 O:0 N:2206 O:0			07-AUG-2019 2850:04 2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 82123 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			20-AUG-2021 3232:59 2376		
243100	NO. 1 NICAD BATTERY								
24.060	9761731302 12100144 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-AUG-2021 3232:59 2376		
243105	NO. 2 NICAD BATTERY								
24.061	9761731302 11800257 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	O:0 N:719:46 O:0 O:0			20-AUG-2021 3232:59 2376		
243160	NO. 1 STARTER GENERATOR								
24.205	978.91.23.407 P1541 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			17-AUG-2020 3051:53 2272		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	9750215107 5101 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	9755085111 N0833 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	9755085111 N0789 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
	REF: AMM 25-10-01	HRS/MSC AFL	300	+10%/-10%			3232:59 2376		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 16	MOS					20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3232:59 2376		
25-10/294	CREW SEAT BELTS								
25.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 20 <b>REF:</b> AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 17 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 20 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-20/295 25.010	PASSENGER SEAT BELTS PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 16 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-60/231 (s)	OPERATIONAL TEST ELT 9851380853 PKG 17 2621312-0020 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 20 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 9851380853 2621312-0020 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	ELT BATTERY 985.13.80.853 2621312-0020 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	DUE	R:0 R:0 R:0			17-AUG-2020 3051:53 2272	<b>01-JUN-2026 M</b>	
<b>DISCARD</b> Expiry Date: 01-JUN-2026									
25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) S1825502-02 2621139-0022 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			07-AUG-2019 2850:04 2131	<b>07-AUG-2029</b> <b>18850:04</b>	07-FEB-2030 19350:04
<b>DISCARD</b>									
25-63/477	CLEAN UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED <b>REF:</b> AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
25-63/478	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED <b>REF:</b> AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
25-63/479	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON BATTERY VOLTAGE (IF INSTALLED) PN NOT INSTALLED <b>REF:</b> AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
25-63/480	DISCARD UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED <b>REF:</b> AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
25-CUS-01	LIFE VEST INSPECTION  <b>REF:</b>	MOS HRS/MSC AFL	12	+1m/-1m		-13	20-AUG-2021 3232:59 2376	<b>07-AUG-2022</b>	07-SEP-2022



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-CUS-02	PERFORM LIFE RAFT OVERHAUL	MOS	36				13-NOV-2020	01-MAY-2023 M	
	REF:	HRS/MSC AFL							
25-CUS-021	LIFE RAFT (WINSLOW LIFE RAFT COMPANY) SURVIVAL KIT								
	69GASTL-09S-1-100	MOS		O:0			13-NOV-2020	01-MAY-2023 M	
	6STL-00247	HRS/MSC	-	O:0					
	REF:	AFL		O:0					
25-CUS-022	LIFE RAFT ELT WINSLOW SRB-406 (SINGLE ANTENNA) ELT								
	P3-03-0041-101	MOS		O:0			13-NOV-2020	01-MAY-2023 M	
	147556	HRS/MSC	-	O:0					
	REF:	AFL		O:0					
25-CUS-03	LIFE RAFT (WINSLOW LIFE RAFT COMPANY) SURVIVAL KIT								
	69GASTL-09S-1-100	MOS							
	6STL-00247	HRS/MSC	-						
	REF:	AFL							
250005	REMOTE CONTROL PANEL								
	9851380817	MOS		N:0			30-SEP-2009		
25.070	2621085-0081	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER								
	9851380853	MOS					10-JUL-2015		
25.050	2621312-0020	HRS/MSC	O/C				1456:48		
	REF: AMM 25-63-00	AFL					1203		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE								
	S1825502-02	MOS					07-AUG-2019		
25.060	2621139-0022	HRS/MSC	O/C				2850:04		
	REF: AMM 25-63-03	AFL					2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256015	CABLE ,S1825503-01 ASSEMBLY								
25.080	9851380859 2620844-0029 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
256020	LH BLACK PILOT SEAT								
25.090	9593001145 56690 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
256025	RH BLACK CO-PILOT SEAT								
25.100	9593001146 56672 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
256050	UNDERWATER LOCATOR BEACON								
<b>NOT INSTALLED</b>	PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			30-SEP-2009 0 0		
256114	PILOT LIFE VEST								
	63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256115	COPILOT LIFE VEST								
	63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256116	NO. 3 LIFE VEST								
	63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256117	NO. 4 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256118	NO. 5 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256119	NO. 6 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256120	NO. 7 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256121	NO. 8 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256122	NO. 1 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		
256123	NO. 2 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0			11-OCT-2018 2534:06 1923		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256130	RECERTIFY PILOT LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120	+1m/-1m			11-OCT-2018 2534:06 1923	08-MAY-2028 M	08-JUN-2028
+ 256131	RECERTIFY COPILOT LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
+ 256132	RECERTIFY NO. 3 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
+ 256133	RECERTIFY NO. 4 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
+ 256134	RECERTIFY NO. 5 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
+ 256135	RECERTIFY NO. 6 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
+ 256136	RECERTIFY NO. 7 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256137	RECERTIFY NO. 8 LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
256138	RECERTIFY NO. 1 LIFE VEST LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
256139	RECERTIFY NO. 2 LIFE VEST LIFE VEST 63600-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				11-OCT-2018 2534:06 1923	08-MAY-2028 M	
25C001	FIRST AID KIT INSPECTION  REF:	MOS HRS/MSC AFL	12	+1m/-1m			20-AUG-2021 3232:59 2376	20-AUG-2022	20-SEP-2022
25C008	PAX SEAT LEFT,STANDARD 5252212011 1322 REF:	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
25C009	PAX SEAT RIGHT,STANDARD 5252212012 1318 REF:	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
25C010	PAX SEAT LH AFSS,403150-7-CF 9593001821 44716 REF:	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C011	PAX SEAT RH AFSS,403150-8-CF 9593001822 44717 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
25C012	PAX SEAT LH FFSS,403150-9-BCF 9593001837 44719 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
25C013	PAX SEAT RH FFSS,403150-10-BCF 9593001838 44721 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
25C014	PC12/47E ENTERTAINMENT SYSTEM 5250512017 43 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
25C015	PAX SEAT LH FFSS,403150-9-CF 9593001835 44718 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
25C016	PAX SEAT RH FFSS,403150-10-CF 9593001836 44720 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 26</b>	<b>FIRE PROTECTION</b>								
26-20/2	COCKPIT FIRE EXTINGUISHER 9590806220 107252 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	N:0 N:0 N:0			11-OCT-2018 2534:06 1923	<b>11-OCT-2028</b>	
26.010									
<b>LIFE LIMIT</b>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/24 26.010	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK ( EXCEPT MODEL P3APP003010D - P/N 959.08.06.224 ) 9590806220 107252 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m		-13	20-AUG-2021 3232:59 2376	07-AUG-2022	07-SEP-2022
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224) 9590806220 107252 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
260005 26.020	FIRE/OVERHEAT DETECTOR 9751210012 216169 REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		10-DEC-2021 3349:19 2464		
<b>CHAPTER 27</b>	<b>FLIGHT CONTROLS</b>								
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
27-00/402 27.255	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES REF:	MOS HRS/MSC AFL	32500 42000	+10%/-10%			30-SEP-2009 0 0	32500 42000	35750
27-00/71 27.010	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK REF: AMM 27-00-00	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		47	07-AUG-2019 2850:04 2131	23-SEP-2024 7650:04	23-MAR-2025 8130:04





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001)						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
27-10/236 (s)	AILERON CONTROL SYSTEM - INSPECTION/ CHECK						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: AMM 27-10-00	AFL					2376		
27-10/237 (s)	CHECK AILERON CABLE TENSION						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: AMM 27-10-00	AFL					2376		
27-10/238 (s)	FUNCTIONAL TEST AILERONS						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	REF: AMM 27-10-00	AFL					2272		
27-10/394	AILERON CONTROL SYSTEM - EXAMINE								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0		32500
<b>AIRWORTHINESS</b>	REF: AMM 27-10-00	AFL	42000				0		42000



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-10-09	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
+ 27-10/444	FLIGHT CONTROL CABLES, AILERON	MOS					30-SEP-2009		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 27-10-01	PN SN-UNKNOWN AFL		N:0 N:0 27000			0 0 0	<b>20000</b> <b>27000</b>	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
<b>LIFE LIMIT</b>	<b>REF: AMM 27-10-02</b>	AFL	27000	N:0			0	27000	
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: AMM 27-10-00</b>	AFL					2376		
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	<b>REF: AMM 27-15-00</b>	AFL					2272		
27-20/140 (s)	INSPECTION/CHECK RUDDER						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: AMM 55-40-00</b>	AFL					2376		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	<b>REF: GENERIC NO REF</b>	AFL					2272		
27-20/241 (s)	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: AMM 27-20-00</b>	AFL					2376		
27-20/243 (s)	CHECK RUDDER CABLE TENSION						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: AMM 27-20-00</b>	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 21	MOS	24	+10%/-10%			PKG 17-AUG-2020		
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%			3051:53 2272		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 21	MOS	24	+10%/-10%			PKG 17-AUG-2020		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			3051:53 2272		
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					30-SEP-2009		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				0 0		
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					30-SEP-2009		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/446	FLIGHT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
<b>LIFE LIMIT</b>	<b>REF: AMM 27-20-01</b>	AFL	27000	N:0			0		27000
+ 27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
<b>LIFE LIMIT</b>	<b>REF: AMM 27-20-02</b>	AFL	27000	N:0			0		27000
27-20/575	REPLACE RUDDER BELLCRANK								
	PN	MOS					30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	20000				0		20000
<b>LIFE LIMIT</b>	<b>REF: AMM 27-20-04</b>	AFL	27000				0		27000
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	<b>REF: GENERIC NO REF</b>	AFL					2272		
27-30/249 (s)	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: AMM 27-30-00</b>	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 21	MOS	24	+10%/-10%			PKG 17-AUG-2020		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			3051:53 2272		
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					30-SEP-2009		
27.150	REF: AMM 27-30-00	HRS/MSC AFL	O/C				0 0		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)	MOS					30-SEP-2009		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R				0 0		
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE	MOS					30-SEP-2009		
AIRWORTHINESS	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					30-SEP-2009		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					30-SEP-2009		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-30-05</b>	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
+ 27-30/448	FLIGHT CONTROL CABLES, ELEVATOR	MOS		N:0			30-SEP-2009		
<b>LIFE LIMIT</b>	<b>REF: AMM 27-30-01</b>	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	<b>20000</b> <b>27000</b>	
+ 27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR	MOS		N:0			30-SEP-2009		
<b>LIFE LIMIT</b>	<b>REF: AMM 27-30-02</b>	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	<b>20000</b> <b>27000</b>	
+ 27-30/450	STICK PUSHER CABLES	MOS		N:0			30-SEP-2009		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	<b>20000</b> <b>27000</b>	
27-30/514 (s)	EXAMINE - ELEVATOR STOPS	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	PKG 20	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
	<b>REF: AMM 55-20-01</b>								
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)	MOS	12	+10%/-10%		-13	20-AUG-2021	<b>07-AUG-2022</b>	13-SEP-2022
27.021		HRS/MSC AFL	3000				3232:59 2376	<b>6232:59</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-40-00</b>								
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	PKG 17	HRS/MSC AFL	300	+10%/-10%			3232:59 2376		
	<b>REF: AMM 27-40-00</b>								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 27-40-01	HRS/MSC AFL	1200	+10%/-10%					
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR 9787314203 840	MOS	84				10-JUL-2015 1456:48 1203	<b>10-JUL-2022</b> <b>4856:48</b>	
<b>OVERHAUL</b>	REF: GENERIC NO REF	HRS/MSC AFL	3400		I:0				
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 16	MOS					PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%					
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%					
+ 27-40/3	REPLACE PITCH TRIM ACTUATOR 9787314203 840	MOS					10-JUL-2015 1456:48 1203	<b>18481:48</b> <b>25221</b>	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	HRS/MSC AFL	20000 27000		I:2975 I:2982				
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) PN	MOS			N:0		30-SEP-2009 0 0	<b>10000</b>	
27.036	SN-UNKNOWN	HRS/MSC	10000		N:0				
<b>LIFE LIMIT</b>	REF: AMM 27-40-02	AFL			N:0				
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R						





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			20-AUG-2021 3232:59 2376		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			20-AUG-2021 3232:59 2376		
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 20	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			20-AUG-2021 3232:59 2376		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST <b>CMT ITEM</b> PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			20-AUG-2021 3232:59 2376		
27-50/28	FLAP POWER DRIVE UNIT 9787320003	MOS							
27.030	834	HRS/MSC	10000	+500/-500	N:0		30-SEP-2009 0	10000	10500
<b>OVERHAUL</b>	REF: AMM 27-50-01	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 9787320309	MOS							
27.040	3599	HRS/MSC	5000	+10%/-10%			30-SEP-2009 0	5000	5500
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 9787320309	MOS							
27.041	3552	HRS/MSC	5000	+10%/-10%			30-SEP-2009 0	5000	5500
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR								
	9787320309	MOS					30-SEP-2009		
27.050	3600	HRS/MSC	5000	+10%/-10%			0	5000	5500
<b>OVERHAUL</b>	<b>REF: GENERIC NO REF</b>	AFL	7000	+500/-500			0	<b>7000</b>	<b>7500</b>
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS					30-SEP-2009		
27.051	3598	HRS/MSC	5000	+10%/-10%			0	5000	5500
<b>OVERHAUL</b>	<b>REF: GENERIC NO REF</b>	AFL	7000	+500/-500			0	<b>7000</b>	<b>7500</b>
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS					30-SEP-2009		
27.060	S6504	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS					30-SEP-2009		
27.060	S6417	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS					30-SEP-2009		
27.070	S6507	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS					30-SEP-2009		
27.070	S6427	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					30-SEP-2009		
		HRS/MSC	30000				0	30000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL	39000				0	<b>39000</b>	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
27-50/414	LEFT HAND FLAP								
	5575012003	MOS					30-SEP-2009		
57.060	953P	HRS/MSC	25000	N:0			0		<b>25000</b>
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL	30000	N:0			0		<b>30000</b>
		ACH					0		
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			30-SEP-2009		
57.060	953P	HRS/MSC	25000	N:0			0		<b>25000</b>
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL	30000	N:0			0		<b>30000</b>
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			20-AUG-2021	<b>07-AUG-2022</b>	13-SEP-2022
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-51-00	HRS/MSC	600	+10%/-10%	-13		3232:59	<b>3832:59</b>	3892:59
		AFL					2376		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF:</b> AMM 12-20-07	AFL					2376		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		<b>20000</b>
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL	27000	N:0			0		<b>27000</b>
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
		HRS/MSC	A/R				3232:59		
	<b>REF:</b> GENERIC NO REF	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/485	LEFT INBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			30-SEP-2009		
27.040	3599	HRS/MSC	20000	N:0			0		20000
<b>DISCARD</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0		27000
27-50/485	LEFT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			30-SEP-2009		
27.041	3552	HRS/MSC	20000	N:0			0		20000
<b>DISCARD</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0		27000
27-50/485	RIGHT INBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			30-SEP-2009		
27.050	3600	HRS/MSC	20000	N:0			0		20000
<b>DISCARD</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0		27000
27-50/485	RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			30-SEP-2009		
27.051	3598	HRS/MSC	20000	N:0			0		20000
<b>DISCARD</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0		27000
27-50/74 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR						PKG		
	9787320309 PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
27.040	3599	HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: AMM 27-50-00</b>	AFL					2376		
27-50/74 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR						PKG		
	9787320309 PKG 17	MOS	12	+1m/-1m			20-AUG-2021		
27.041	3552	HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: AMM 27-50-00</b>	AFL					2376		
27-50/74 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR						PKG		
	9787320309 PKG 17	MOS	12	+1m/-1m			20-AUG-2021		
27.050	3600	HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: AMM 27-50-00</b>	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR						PKG		
27.051	9787320309 PKG 17 3598 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			20-AUG-2021 3232:59 2376		
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 3599 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	55		17-AUG-2020 3051:53 2272	11-OCT-2022 5451:53 5472	23-DEC-2022 5691:53 5792
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 3552 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	55		17-AUG-2020 3051:53 2272	11-OCT-2022 5451:53 5472	23-DEC-2022 5691:53 5792
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 3600 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	55		17-AUG-2020 3051:53 2272	11-OCT-2022 5451:53 5472	23-DEC-2022 5691:53 5792
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 3598 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	55		17-AUG-2020 3051:53 2272	11-OCT-2022 5451:53 5472	23-DEC-2022 5691:53 5792
270003	HORIZONTAL TAIL ASSY								
	5551012037 972 REF: AMM 55-10-01	MOS HRS/MSC AFL					30-SEP-2009 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012039 1002 REF: AMM 55-20-01	MOS HRS/MSC AFL					30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270023	ELEVATOR RH ASSY								
27.023	5552012040 1004 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	ACL12A-1 1217 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-AUG-2020 3051:53 2272		
270030	FIN ASSY								
27.031	5553012039 953P REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270033	RUDDER ASSY								
27.033	5554012040 955P REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270035	FLAP CONTROL AND WARNING UNIT								
27.130	9787320017 124719 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 ++/091090DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 1332 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 ++/093059DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 ++/091112DZ REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1371 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270080	KTA2810,TRIM ADAPTER								
22.135	065-00195-0100 KTA2810-2364 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2018 2534:06 1923		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318138 116 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 ++/093069DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
274020	PITCH TRIM ACTUATOR								
	9787314203 840 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	O:0 N:2975 O:0 N:2982 O:0			10-JUL-2015 1456:48 1203		

## CHAPTER 28 FUEL





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 28-10-02	HRS/MSC AFL	300	+10%/-10%					
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE	MOS					29-JUN-2017 2010:48 1592	4400	4640
28.029	REF: AMM 28-10-01	HRS/MSC AFL	2400	+10%/-10%	-10:48				
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 28-20-07	HRS/MSC AFL	300	+10%/-10%					
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT <b>CMT ITEM</b> PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%					
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N) PKG 19	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP <b>CMT ITEM</b> PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 21	MOS	24	+10%/-10%			PKG	17-AUG-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			3051:53 2272		
28-20/32	OVERHAUL ENGINE DRIVEN PUMP	MOS							
28.010	9688451108 B5245	HRS/MSC AFL	3500	+14%/-14%	N:0 N:0 N:0		30-SEP-2009 0 0	3500	3990
	REF: AMM 28-20-03								
280005	LOW PRESSURE FUEL PUMP	MOS							
28.120	9688451108 B5245	HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
	REF: AMM 28-20-03								
280010	FUEL FLOW TRANSMITTER	MOS							
28.130	9753512106 AAF1072	HRS/MSC AFL	O/C		N:0 N:0 N:0		02-OCT-2013 1011:06 907		
	REF: AMM 73-30-01								
280012	FUEL CONTROL MONITORING UNIT	MOS							
	9753731334 269	HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
	REF: See Workcard								
280015	FIREWALL FUEL,SHUT-OFF VALVE	MOS							
28.110	9638722301 2442	HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
	REF: AMM 28-20-08								
280020	MAINTENANCE FUEL SHUT-OFF VALVE	MOS							
28.110	9638722301 2436	HRS/MSC AFL	O/C		N:0 N:0 N:0		30-SEP-2009 0 0		
	REF: AMM 28-20-12								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280025	FUEL FILTER ASSY								
28.025	9683521001 2009FFT832 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 1762 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B4307 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B4553 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731220 701 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731219 699 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731218 691 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731217 698 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 B7124 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B4303 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B4571 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731217 704 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731218 692 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	9753731219 665 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280095	FUEL QUANTITY, OUTER RH SENSOR								
28.060	9753731220 702 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280100	FUEL, BOOSTER RH PUMP								
28.050	9688411405 B7127 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280105	TOP CHECK VALVE								
28.150	9630423105 2353 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280110	BOTTOM CHECK VALVE								
28.150	9630423105 2357 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-OCT-2013 1011:06 907		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1192 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-OCT-2013 1011:06 907		

## CHAPTER 29 HYDRAULIC POWER

29-10/151 (s)	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: AMM 29-10-04	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/153 (s)	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 29-00-00	HRS/MSC AFL	300	+10%/-10%					
29-10/257 (s)	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED) 9603001291 PKG 20	MOS	12	+10%/-10%		-13	20-AUG-2021 3232:59 2376	<b>07-AUG-2022</b> <b>4432:59</b>	13-SEP-2022 4552:59
	1025L	HRS/MSC	1200	+10%/-10%					
	REF: AMM 29-10-02	AFL							
29-10/259 (s)	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
29-10/316 (s)	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED. PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 29-00-00	HRS/MSC AFL	300	+10%/-10%					
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED) 9603001291	MOS		N:0			30-SEP-2009		
29.020	1025L	HRS/MSC	25000	N:0			0	<b>25000</b>	
<b>LIFE LIMIT</b>	REF: AMM 29-10-02	AFL	30000	N:0			0	<b>30000</b>	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292) 9603001291	MOS					30-SEP-2009		
	1025L	HRS/MSC	N/A				0		
	REF: AMM 29-10-02	AFL					0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290015	PRESSURE GAGE SWITCH								
29.050	9738114307 1322 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-FEB-2018 2288 1754		
290025	SERVICE SELECTOR VALVE								
29.070	9603001261 G0920018A REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
290030	PRESSURE GAUGE								
29.080	9656188101 09-0409273 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
290040	HAND PUMP								
29.030	9688582111 1306 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2018 2534:06 1923		
290050	PRESSURE NITROGEN SWITCH								
29.100	9738114306 1193 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0920315 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 30</b>	<b>ICE AND RAIN PROTECTION</b>								
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	REF: AMM 30-10-00	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM PKG 19 REF: AMM 30-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
30-10/79 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1 REF: GENERIC NO REF	MOS HRS/MSC AFL	6	+10%/-10%		-30	20-AUG-2021 3232:59 2376	21-JAN-2022	08-FEB-2022
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED CMT ITEM PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 19 REF: AMM 30-30-20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 21 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 17-AUG-2020 3051:53 2272		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 19	MOS	12	+1m/-1m			PKG	20-AUG-2021	
	REF: See Workcard	HRS/MSC AFL	600	+30/-30				3232:59	2376
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 19	MOS	12	+1m/-1m			PKG	20-AUG-2021	
	REF: See Workcard	HRS/MSC AFL	600	+30/-30				3232:59	2376
300005	PROP DE-ICE CONTROLLER								
30.140	9682913227 U0679	MOS			R:0			07-MAR-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	O/C		R:0			3024:53	2239
300010	LPMI LINEAR ACTUATOR								
30.150	9787315302 C12671	MOS			N:0			30-SEP-2009	
	REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0			0	0
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N091042	MOS			N:0			30-SEP-2009	
	REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0			0	0
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N086050	MOS			N:0			30-SEP-2009	
	REF: AMM 30-10-02	HRS/MSC AFL	O/C		N:0			0	0
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N086059	MOS			N:0			30-SEP-2009	
	REF: AMM 30-10-02	HRS/MSC AFL	O/C		N:0			0	0



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N085786 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N085785 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 5068 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N092043 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	9598901014 U3639 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C				27-FEB-2019 2672:02 2018		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 124983 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 124984 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	9598901041 NEL9030 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2018		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NEK0890 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2018		
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NEU3540 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-FEB-2019 2672:02 2018	05-DEC-2023 M	
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	P27-7D5221-12 NDE2420 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:3 N:0 N:0			03-MAY-2016 1563:54 1275		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U2084 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	P27-7D5221-09 NDL8360 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:2 N:0 N:0			21-OCT-2016 1731:12 1408		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NEK9810 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-OCT-2018		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U2088 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 4989 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 5065 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 5025 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 5024 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	9598901008 N085784 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		

## CHAPTER 31 INDICATING/RECORDING SYSTEMS

31-30/421	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)								
	PN NOT INSTALLED REF: AMM 31-30-01	MOS HRS/MSC AFL	N/A				13-OCT-2017 2131 1658		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310050	DIGITAL CLOCK								
31.040	9996111213 1050605 REF: AMM 31-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310069	KMC 2210 DISPLAY CONTROLLER								
	071-01598-0501 KMC2220-1560 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			22-MAR-2016 1536:36 1257		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	9859912178 KMC2210-1390 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE								
31.240	7036410-1902 9032240 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				07-AUG-2019 2850:04 2131		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE								
31.270	7036410-1902 13039571 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				07-AUG-2019 2850:04 2131		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD								
31.160	7038231-1801 14069130 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-OCT-2014 1283:36 1107		
310085	OVERHEAD CONTROL BASIC PANEL								
31.260	9728121153 610 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:1830:18			07-AUG-2019 2850:04 2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310095	PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	071-01596-0201 KMC2210-1168 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-FEB-2020 3004:24 2227		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	985.99.12.190 0909B011 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				09-NOV-2009		
310100-4	MAU ACTUATOR I/O PROC MODULE								
	9859912144 7084917 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	985.99.12.190 0909B015 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				09-NOV-2009		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	9859912147 9054385 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	7038231-1801 14069129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-OCT-2014 1283:36 1107		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	9859912143 0905E064 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	9859912143 0905E068 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	7038622-1901 14080891 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		10/07/2015	07-OCT-2014 1283:42 1107		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	7036333-1906 14071334 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		10/07/2015	07-OCT-2014 1283:42 1107		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	9859912103 1890136909 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	9859912103 1890296526 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAY-2014 1122:42 992		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890163529 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890136912 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310155	REV CTL PNL,4-POT DISPLAY								
31.130	9728121141 174 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 0901B545 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 0902B777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT								
	PN NOT INSTALLED REF: AMM 31-30-01	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
<b>CHAPTER 32 LANDING GEAR</b>									
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: AMM 12-20-04	AFL					2376		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS						PKG		
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS						PKG		
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 19	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%					
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK	MOS	12	+1m/-1m					
32.010	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%	-13		20-AUG-2021 3232:59 2376	07-AUG-2022 5632:59	07-SEP-2022 5872:59
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY 5321012053	MOS		N:0			30-SEP-2009		
32.070	VLG405	HRS/MSC AFL	O/C	N:0 N:0			0 0		
	REF: GENERIC NO REF			N:0			0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY 5321012054	MOS		N:0			30-SEP-2009		
32.070	VLG405	HRS/MSC AFL	O/C	N:0 N:0			0 0		
	REF: GENERIC NO REF			N:0			0		
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	25000 30000	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	<b>25000</b> <b>30000</b>	
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	<b>25000</b> <b>30000</b>	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+1m/-1m			20-AUG-2021	<b>20-AUG-2022</b>	20-SEP-2022
	<b>REF:</b> See Workcard	HRS/MSC AFL					3232:59 2376		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				04-MAY-2016	<b>04-MAY-2022</b>	
	<b>REF:</b> See Workcard	HRS/MSC AFL					1563:54 1275		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				04-MAY-2016	<b>04-MAY-2022</b>	
	<b>REF:</b> See Workcard	HRS/MSC AFL					1563:54 1275		
32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS	MOS	12	+1m/-1m			20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	3-1543-1 1024 <b>REF:</b> AMM 12-20-06	HRS/MSC AFL	T/C		-13		3232:59 2376		
32-10/80	LUBRICATE NOSE WHEEL BEARINGS	MOS	12	+1m/-1m			20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	3-1501 1126 <b>REF:</b> AMM 12-20-06	HRS/MSC AFL	T/C		-13		3232:59 2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS 3-1543-1 1704 REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		-3	20-AUG-2021 3232:59 2376	17-AUG-2022	17-SEP-2022
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 19 REF: AMM 32-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 19 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 5325012064 SN-UNKNOWN LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC AFL	120 11000 15000	N:0 N:0 N:0			07-AUG-2019 2850:04 2131	07-AUG-2029 13850:04 17131	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
32.195	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/A				30-SEP-2009 0 0		
32-20/403	NOSE LANDING GEAR - OVERHAUL								
32.200 OVERHAUL	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000	+500/-500 +500/-500	N:0 N:0 N:0		30-SEP-2009 0 0	25500 30500	
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
LIFE LIMIT	PN SN-UNKNOWN REF: AMM 32-20-05	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		30-SEP-2009 0 0	25000 30000	
32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	<b>CMT ITEM</b> PKG 20 REF: AMM 32-30-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
32-30/417	LEFT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
32.040 LIFE LIMIT	9603001105 2717H REF: AMM 32-30-01	MOS HRS/MSC AFL ACH	25000 30000		N:2681:54 N:2443		13-OCT-2017 2131 1658	24449:06 29215	
32-30/417	RIGHT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
32.040 LIFE LIMIT	9603001105 2038H REF: AMM 32-30-01	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		30-SEP-2009 0 0	25000 30000	
32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
	<b>CMT ITEM</b> REF: AMM 32-30-10	MOS HRS/MSC AFL	N/A				20-NOV-2015 1456:48 1203		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/425	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS <b>CMT ITEM</b>	MOS HRS/MSC AFL	N/A				08-JUN-2018 2404:02 1834		
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS  <b>REF:</b> See Workcard	MOS HRS/MSC AFL	72				04-MAY-2016 1563:54 1275	<b>04-MAY-2022</b>	
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS  <b>REF:</b> See Workcard	MOS HRS/MSC AFL	72				04-MAY-2016 1563:54 1275	<b>04-MAY-2022</b>	
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE  <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	N/A				21-JAN-2021 3151:21 2327		
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE  <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	N/A				21-JAN-2021 3151:21 2327		
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS  PKG 19 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE  PKG 17 <b>REF:</b> AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	600	+10%/-10%				3232:59	
	REF: GENERIC NO REF	AFL						2376	
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 17	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	300	+10%/-10%				3232:59	
	REF: AMM 12-10-04	AFL						2376	
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 17	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	300	+10%/-10%				3232:59	
	REF: GENERIC NO REF	AFL						2376	
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 17	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	300	+10%/-10%				3232:59	
	REF: AMM 12-10-02	AFL						2376	
32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230		MOS						30-SEP-2009	
		HRS/MSC	32500	+10%/-10%				0	32500 35750
	REF:	AFL	42000					0	42000
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	9594751132	MOS			N:0			30-SEP-2009	
	504	HRS/MSC	O/C		N:0			0	
	REF: AMM 32-40-04	AFL			N:0			0	
320006	STEREER SELECTOR, LANDING GEAR VALVE								
29.040	9603001274	MOS			O:0			11-OCT-2018	
	807C	HRS/MSC	O/C		O:0			2534:06	
	REF: AMM 32-30-03	AFL			O:0			1923	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751132 502 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0		
320015	PARK BRAKE VALVE								
32.140	9594751133 212 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320020	NOSE WHEEL								
32.150	3-1501 1126 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				17-AUG-2020		
320021	NOSE LANDING GEAR TIRE								
32.155	PN SN-UNKNOWN REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				07-AUG-2019 2850:04 2131		
320022	LEFT MAIN LANDING GEAR WHEEL								
32.160	3-1543-1 1024 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	O:18 N:3126:40			17-AUG-2020		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 0045T00307 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-AUG-2021 3232:59 2376		
320024	RIGHT MAIN LANDING GEAR WHEEL								
32.165	3-1543-1 1704 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-AUG-2020 3051:53 2272		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320025	SHIMMY DAMPER ASSY								
32.100	532.20.12.215 VLG1255 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0			20-AUG-2021 3232:59 2376		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	959.56.01.308 SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				17-AUG-2020 3051:53 2272		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751132 505 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751132 529 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012249 VLG413 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012040 VLG413 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	532.10.12.211 SI-0658 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:41 R:28 N:41:40 R:0 N:24 R:0			26-FEB-2018 2288 1754		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320060	LH BRAKE ASSY								
32.050	9595601512 0851 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			11-OCT-2018 2534:06 1923		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	3-1543-1 2153 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
320074	NOSE LANDING GEAR HYDRAULIC ACTUATOR								
	9603001111 1334A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-NOV-2012 782:36 744		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG821 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320085	RH BRAKE ASSY								
32.050	959.56.01.512 1525 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			12-JAN-2021 3146:42 2324		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	3-1543-1 2154 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
32.170	973.30.33.113 1425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
32.175	9733033113 1452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH								
32.180	973.30.33.116 6835 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:3 N:0 N:0			26-FEB-2018 2288 1754		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
32.170	9733033113 1592 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH								
32.175	9733033113 1582 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320125	MAIN LANDING GEAR 72A74-01 LH "WOW" PROXIMITY SWITCH								
32.180	9733033113 1686 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
320130	L/H BOLT								
32.240	9448121314 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAY-2014		
<b>CHAPTER 33</b>	<b>LIGHTS</b>								
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	REF: AMM 33-40-00	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 17 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 17 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 17 REF: AMM 33-44-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
330005 33.080	DIM UNIT 9750215205 124906 REF: AMM 33-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
330010 33.010	DE-ICE LIGHT ASSY 9728767111 3224957 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-NOV-2015 1456:48 1203		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS		N:0			07-AUG-2019		
33.040	209053-7-38 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			2850:04 2131		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS		N:0			07-AUG-2019		
33.040	209053-7-33 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			2850:04 2131		
330035	LH WING POWER SUPPLY UNIT 9728787164	MOS					07-AUG-2019		
33.070	24019 REF: AMM 33-43-03	HRS/MSC AFL	O/C	O:2850:04			2850:04 2131		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY 9728787322	MOS		N:0			07-AUG-2019		
33.030	196963-3-4 REF: AMM 33-43-02	HRS/MSC AFL	O/C	N:0 N:0			2850:04 2131		
330045	RH WING POWER SUPPLY UNIT 9728787164	MOS		N:0			30-SEP-2009		
33.070	38154 REF: AMM 33-43-03	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY 9728787322	MOS		N:0			27-FEB-2019		
33.030	196963-3-18 REF: AMM 33-43-02	HRS/MSC AFL	O/C	N:0 N:0			2672:02 2018		
330055	NAVIGATION (FC), LED GREEN LIGHT 9728787158	MOS		N:0			30-SEP-2009		
33.050	38589 REF: AMM 33-43-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330060	NAVIGATION (FC), LED RED LIGHT								
33.050	9728787157 38398 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT								
33.060	9728787159 38065 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
330075	L/H 1X0005287-10 LANDING LIGHT								
33.090	9728769402 1499916 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
330076	R/H 1X0005287-10 LANDING LIGHT								
33.110	9728769402 1499921 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
330080	3060-S PULSELITE CONTROLLER								
33.100	9728769419 LSS01447 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		

## CHAPTER 34 NAVIGATION

34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	REF: GENERIC NO REF	AFL					2272		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11/185 (s)	EXAMINE PITOT TUBE PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 20 REF: AMM 34-11-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 20-AUG-2021 3232:59 2376		
34-11/343 34.565	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT REF: AMM 34-11-12	MOS HRS/MSC AFL	24	+10%/-10%			20-AUG-2021 3232:59 2376	<b>20-AUG-2023</b>	01-NOV-2023
34-11/82 34.010	LEAK CHECK STATIC SYSTEM REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+10%/-10%			20-AUG-2021 3232:59 2376	<b>20-AUG-2023</b>	01-NOV-2023
34-21/84 34.560	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED) REF: AMM 34-21-00	MOS HRS/MSC AFL	12	+10%/-10%	-13		20-AUG-2021 3232:59 2376	<b>07-AUG-2022</b>	13-SEP-2022
34-25/344 34.570	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM) REF: AMM 34-14-00	MOS HRS/MSC AFL	24	+10%/-10%	34		20-AUG-2021 3232:59 2376	<b>23-SEP-2023</b>	05-DEC-2023



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED)	MOS					30-SEP-2009		
	REF: AMM 34-26-40	HRS/MSC AFL	N/A				0 0		
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)	MOS	12	+10%/-10%		-13	20-AUG-2021	07-AUG-2022	13-SEP-2022
34.050	REF: See Workcard	HRS/MSC AFL					3232:59 2376		
34-CUS-01	ELECTRONIC EQUIPMENT TEST	MOS	12	+1m/-1m			20-AUG-2021	20-AUG-2022	20-SEP-2022
	REF:	HRS/MSC AFL					3232:59 2376		
340010	DME/IFF ANTENNA	MOS					30-SEP-2009		
34.080	9848110240 261-84547 REF: AMM 34-52-02	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
340020	MARKER ANTENNA	MOS					30-SEP-2009		
34.100	9848110260 101-6778 REF: AMM 34-32-01	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
340055	WITH HARM FILTER,KN63 DME	MOS					27-FEB-2019		
34.200	066-1070-01 38971 REF: AMM 34-52-01	HRS/MSC AFL	O/C	R:0 R:0 R:0			2672:02 2018		
340065	WX-RADAR RT UNIT	MOS					22-AUG-2016		
34.360	071-01519-0101 4078 REF: AMM 34-41-02	HRS/MSC AFL	O/C	R:0 R:0 R:0			1663:24 1343		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340075	WX,VERTICAL ANTENNA								
34.370	071-01549-0100 6527 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C				11-MAY-2016 1569:42 1280		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-84515 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 KA44B-A87458 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340100	FRONT KA92 ANTENNA								
34.090	9859911200 49305752 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	9859911200 49305712 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 8048 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 15501 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340135	STANDBY MAGNETIC COMPASS								
34.130	9999880103 AT1037 REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-JUL-2015 1456:48 1203		
340140	RADOME								
34.420	9857900003 1035 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 5522 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-47502 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-48360 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 21728 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 21724 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	9859918006 95035 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	9859918009 95603 REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 8049 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 0528 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-OCT-2017 2132:48 1661		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	9859911505 CM2000-21452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340255	AOA SENSOR LH UNIT								
34.330	9754421423 1802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			20-AUG-2021 3232:59 2376		
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	9848110240 261-84553 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340270	LEFT PITOT STATIC TUBE								
34.535	9651112302 1206708 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340275	RIGHT PITOT STATIC TUBE								
34.535	9651112302 A0840 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-FEB-2015 1362 1156		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-1693 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-1641 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	9859911887 KMH920-B1323 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340295	RH COAX SWITCH								
34.530	9859911371 13709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
340300	LH COAX SWITCH								
34.530	9859911371 13708 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340305	NO. 1 LH KGS200,GPS SENSOR UNIT 066-01201-0105	MOS					30-SEP-2009		
34.550	KGS200-1351 REF: AMM 34-57-01	HRS/MSC AFL	O/C	N:0			0 0		
340310	NO. 2 KXP 2290 MODE S TRANSPONDER 066-01198-0102	MOS					07-AUG-2019		
34.540	KXP2290A-M1724 REF: AMM 34-54-01	HRS/MSC AFL	O/C				2850:04 2131		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER 066-01198-0102	MOS					07-AUG-2019		
34.540	KXP2290A-M1399 REF: AMM 34-54-01	HRS/MSC AFL	O/C				2850:04 2131		
340320	LH OAT SENSOR 5341312025	MOS		N:0			30-SEP-2009		
34.525	3237 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340325	RH OAT SENSOR 5341312025	MOS		N:0			30-SEP-2009		
34.525	3245 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT 9859912205	MOS					19-JAN-2012		
34.505	KSG7200-B1325 REF: AMM 34-25-01	HRS/MSC AFL	O/C				563:06 550		
340335	NO. 2 RH KGS200,GPS SENSOR UNIT 066-01201-0105	MOS					30-SEP-2009		
34.550	KGS200-1344 REF: AMM 34-57-01	HRS/MSC AFL	O/C	N:0			0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340340	STANDBY INSTRUMENT PANEL								
34.510	9759611244 C16221017547 REF: AMM 34-26-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
34C034	RADAR ALTIMETER,KRA405B MOD 13 TRANSMITTER								
	9859911550 KRA405B-8817 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 35 OXYGEN</b>									
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE						PKG		
	PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	AFL							
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG		
	PKG 16	MOS HRS/MSC AFL	300	+10%/-10%			20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	AFL							
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT						PKG		
	PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	AFL							
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM						PKG		
	PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
	REF: AMM 35-00-00	AFL							
35-10/6	REAR FUSELAGE OXYGEN CYLINDER								
	<b>CMT ITEM</b>								
	9571212212 C17060308	MOS HRS/MSC AFL	180	N:0			13-OCT-2017 2131 1658	<b>30-APR-2032</b>	
<b>AIRWORTHINESS</b>	REF: AMM 35-10-01	AFL							
	Manufacture Date: 30-APR-2017								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER <b>CMT ITEM</b> 9571212212 C17060308 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60				03-OCT-2017	<b>30-APR-2022</b> M	
<b>AIRWORTHINESS</b>									
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)  <b>REF:</b> AMM 35-00-00	MOS HRS/MSC AFL	600	+10%/-10%			20-AUG-2021 3232:59 2376	<b>3832:59</b>	3892:59
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS  <b>REF:</b> AMM 35-20-00	MOS HRS/MSC AFL	36	+10%/-10%		52	20-AUG-2021 3232:59 2376	<b>11-OCT-2024</b>	29-JAN-2025
35.010									
35-CUS-01	OXYGEN BOTTLE REGULATOR 803213-03 C08100839 <b>REF:</b>	MOS HRS/MSC AFL	60				30-APR-2017 758 729	<b>30-APR-2022</b> M	
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY 9571201210 SE23816 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
35.040									
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B161980 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-AUG-2020 3051:53 2272		
35.040									
350030	PRESSURE,GAGE,OXYGEN SWITCH 9738114401 975 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-SEP-2009 0 0		
35.050									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350035	CONTR,3-POSITION,37071-03 VALVE									
35.030	9633211101 3213 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0			
350050	OXYGEN GAGE ASSY									
35.060	5351212085 60119 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0			
350055	OXYGEN PRESS TRANSDUCER									
35.070	9571201184 7427-5-197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0			
<b>CHAPTER 45 CENTRAL MAINT SYSTEM</b>										
45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG			
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021			
		HRS/MSC	1200	+10%/-10%			3232:59			
	REF: AMM 45-45-00	AFL					2376			
<b>CHAPTER 46 INFORMATION SYSTEMS</b>										
46-26/320	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES									
	PKG 17	MOS	12	+10%/-10%	-13		20-AUG-2021	<b>07-AUG-2022</b>	13-SEP-2022	
		HRS/MSC	300	+10%/-10%			3232:59	<b>3532:59</b>	3562:59	
	REF: See Workcard	AFL					2376			
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES						PKG			
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021			
		HRS/MSC	300	+10%/-10%			3232:59			
	REF: AMM 46-30-02	AFL					2376			
<b>CHAPTER 52 DOORS</b>										
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK						PKG			
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021			
		HRS/MSC	600	+10%/-10%			3232:59			
	REF: GENERIC NO REF	AFL					2376			



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 19	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%				3232:59	
		AFL						2376	
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS PKG 19	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%				3232:59	
		AFL						2376	
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 19	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%				3232:59	
		AFL						2376	
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 20	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%				3232:59	
		AFL						2376	
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS						30-SEP-2009	
<b>AIRWORTHINESS</b>	REF: AMM 52-10-00	HRS/MSC	32500					0	<b>32500</b>
		AFL	42000					0	<b>42000</b>
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE	MOS						30-SEP-2009	
52.100	REF:	HRS/MSC	32500					0	<b>32500</b>
		AFL	42000					0	<b>42000</b>
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN	MOS						30-SEP-2009	
52.110	REF:	HRS/MSC	25000					0	<b>25000</b>
		AFL	30000					0	<b>30000</b>





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)								
		MOS					30-SEP-2009		
		HRS/MSC	N/A				0		
	REF: AMM 52-10-06	AFL					0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
		MOS	48	+10%/-10%		47	07-AUG-2019	23-SEP-2023	16-FEB-2024
52.010		HRS/MSC	4000	+10%/-10%			2850:04	6850:04	7250:04
<b>MODERATE CORROSION ZONE</b>	REF: See Workcard	AFL					2131		
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)								
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK								
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0	32500	
<b>AIRWORTHINESS</b>	REF: AMM 52-20-00	AFL	42000				0	42000	
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK								
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.								
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: AMM 52-30-00	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF: GENERIC NO REF	AFL					2376		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0		32500
<b>AIRWORTHINESS</b>	REF: AMM 52-30-00	AFL	42000				0		42000
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
		MOS					30-SEP-2009		
52.120		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
		MOS					30-SEP-2009		
52.130		HRS/MSC	25000				0		25000
	REF:	AFL	30000				0		30000
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS			N:0		30-SEP-2009		
52.020	SN-UNKNOWN	HRS/MSC	13000		N:0		0		13000
<b>AIRWORTHINESS</b>	REF: AMM 52-30-07	AFL	17000		N:0		0		17000
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
		MOS	48	+10%/-10%		47	07-AUG-2019	23-SEP-2023	16-FEB-2024
52.030		HRS/MSC	4000	+10%/-10%			2850:04	6850:04	7250:04
<b>MODERATE CORROSION ZONE</b>	REF: See Workcard	AFL					2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM PKG 20	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: AMM 52-70-00	HRS/MSC	1200	+10%/-10%				3232:59	
		AFL						2376	
520005	PASSENGER DOOR 5520512007	MOS		N:0				30-SEP-2009	
52.050	953P	HRS/MSC	O/C	N:0				0	
	REF: See Workcard	AFL		N:0				0	
520010	FREIGHT OF 10SERIE DOOR ASSY 5520512010	MOS		N:0				30-SEP-2009	
52.040	953P	HRS/MSC	O/C	N:0				0	
	REF: AMM 52-30-01	AFL		N:0				0	
520015	EMERGENCY 6 SERIE EXIT 5520512009	MOS		N:0				30-SEP-2009	
52.060	953P	HRS/MSC	O/C	N:0				0	
	REF: AMM 52-20-01	AFL		N:0				0	
<b>CHAPTER 53 FUSELAGE</b>									
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 17	MOS	12	+10%/-10%				20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%				3232:59	
		AFL						2376	
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD PKG 20	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%				3232:59	
		AFL						2376	
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED PKG 20	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%				3232:59	
		AFL						2376	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 21	MOS	24	+10%/-10%				17-AUG-2020	
		HRS/MSC	2400	+10%/-10%				3051:53	
	REF: GENERIC NO REF	AFL						2272	
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%				17-AUG-2020	
		HRS/MSC	2400	+10%/-10%				3051:53	
	REF: GENERIC NO REF	AFL						2272	
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 20	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	1200	+10%/-10%				3232:59	
	REF: GENERIC NO REF	AFL						2376	
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						30-SEP-2009	
		HRS/MSC	N/A					0	
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	AFL						0	
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 20	MOS	12	+10%/-10%				20-AUG-2021	
		HRS/MSC	1200	+10%/-10%				3232:59	
	REF: AMM 53-20-02	AFL						2376	
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION								
		MOS						30-SEP-2009	
		HRS/MSC	32500					0	<b>32500</b>
<b>AIRWORTHINESS</b>	REF: AMM 53-10-06	AFL	42000					0	<b>42000</b>
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS								
		MOS						30-SEP-2009	
		HRS/MSC	32500					0	<b>32500</b>
<b>AIRWORTHINESS</b>	REF: AMM 53-10-00	AFL	42000					0	<b>42000</b>



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-20-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-30-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-00-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-00-00</b>	HRS/MSC	28300				0		<b>28300</b>
		AFL	37000				0		<b>37000</b>
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-00-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-03</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-20-02</b>	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/419	EDDY CURRENT INSPECTION - FRAME 40	MOS					30-SEP-2009		
53.210	<b>REF:</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					30-SEP-2009		
53.010	<b>REF:</b> GENERIC NO REF	HRS/MSC	20000				0		<b>20000</b>
<b>AIRWORTHINESS</b>		AFL	27000				0		<b>27000</b>
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%	47		07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
53.030	<b>REF:</b> GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>		AFL					2131		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)	MOS	48	+10%/-10%	47		07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
53.040	<b>REF:</b> GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>		AFL					2131		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED	MOS	48	+10%/-10%	47		07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
53.070	<b>REF:</b> GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>		AFL					2131		
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS	MOS	48	+10%/-10%	47		07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
53.050	<b>REF:</b> GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>		AFL					2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%		46	07-AUG-2019	22-SEP-2023	15-FEB-2024
<b>MODERATE CORROSION ZONE</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
		AFL					2131		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
34.575		MOS	12	+1m/-1m		-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	<b>REF: AMM 53-30-01</b>	HRS/MSC					3232:59		
		AFL					2376		
530070	FUSELAGE AB 1003 TEIL1								
53.090	5530512114	MOS			N:0		30-SEP-2009		
	953P	HRS/MSC	O/C		N:0		0		
	<b>REF: GENERIC NO REF</b>	AFL			N:0		0		
<b>CHAPTER 55 STABILIZERS</b>									
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC	20000				0	<b>20000</b>	
		AFL	27000				0	<b>27000</b>	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC	N/A				0		
		AFL					0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: AMM 55-00-00</b>	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/415	HORIZONTAL STABILIZER								
	PN	MOS		N:0			30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
<b>LIFE LIMIT</b>	<b>REF: AMM 55-10-01</b>	AFL	30000	N:0			0	<b>30000</b>	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%		47	07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
		HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>	<b>REF:</b>	AFL					2131		
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%		47	07-AUG-2019	<b>23-SEP-2023</b>	16-FEB-2024
		HRS/MSC	4000	+10%/-10%			2850:04	<b>6850:04</b>	7250:04
<b>MODERATE CORROSION ZONE</b>	<b>REF: GENERIC NO REF</b>	AFL					2131		
55-20/362	EXAMINE LEFT WING ELEVATOR								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0	<b>32500</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-00</b>	AFL	42000				0	<b>42000</b>	
+ 55-20/362	EXAMINE RIGHT WING ELEVATOR								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0	<b>32500</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-00</b>	AFL	42000				0	<b>42000</b>	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0	<b>32500</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	AFL	42000				0	<b>42000</b>	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
		MOS					30-SEP-2009		
		HRS/MSC	32500				0	<b>32500</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	AFL	42000				0	<b>42000</b>	





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
55-30/369	EXAMINE - VERTICAL STABILIZER								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-30-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-00-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-30-02</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
55.190		MOS					30-SEP-2009		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
55-40/373	EXAMINE - RUDDER								
		MOS					30-SEP-2009		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
		MOS					30-SEP-2009		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200		MOS					30-SEP-2009		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
55CUS01	SPECIAL INSPECTION FOR HORIZONTAL STABILIZER BOLTS P/N 555.10.12.139 REMOVAL AND INSPECTION FOR SIGNS OF CORROSION. CLEANING, CORROSION TREATMENT / REPLACEMENT OF BOLTS AS REQUIRED. INSTALLATION OF BOLTS AFTER INSPECTION								
		MOS					17-AUG-2020		
		HRS/MSC	-				3051:53		
	REF:	AFL					2272		
<b>CHAPTER 56</b>	<b>WINDOWS</b>								
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	REF:	AFL					2376		
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED								
56.020		MOS					30-SEP-2009		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	A/R				0		
		AFL					0		



## Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED	MOS					30-SEP-2009		
	REF: AMM 56-00-00	HRS/MSC	A/R				0		
		AFL					0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					30-SEP-2009		
	9598110109	HRS/MSC	A/R				0		
	08197H3328	AFL					0		
	REF: AMM 56-11-01								
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					30-SEP-2009		
	9598110110	HRS/MSC	A/R				0		
	08078H8311	AFL					0		
	REF: AMM 56-11-01								
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					30-SEP-2009		
	9598110109	HRS/MSC	A/R				0		
	08197H3328	AFL					0		
	REF: GENERIC NO REF								
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					30-SEP-2009		
	9598110110	HRS/MSC	A/R				0		
	08078H8311	AFL					0		
	REF: GENERIC NO REF								
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS	MOS	120	+6m/-6m		47	07-AUG-2019	<b>23-SEP-2029</b>	23-MAR-2030
56.100		HRS/MSC	11000	+500/-500			2850:04	<b>13850:04</b>	14350:04
	REF: AMM 56-11-02	AFL					2131		
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED	MOS					30-SEP-2009		
		HRS/MSC	32500				0	<b>32500</b>	
<b>AIRWORTHINESS</b>	REF: See Workcard	AFL	42000				0	<b>42000</b>	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-14/517 (s)	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND PKG 20	MOS	12				PKG 20-AUG-2021 3232:59 2376		
	REF: GENERIC NO REF	HRS/MSC AFL	1200						
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021 3232:59 2376		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%					
560015	SIDE,LH WINDOW 9598110111 08150H7223	MOS					30-SEP-2009 0 0		
56.090	REF: AMM 56-11-02	HRS/MSC AFL	O/C	N:0 N:0 N:0					
560020	SIDE,RH WINDOW 9598110112 08150H7165	MOS					30-SEP-2009 0 0		
56.090	REF: AMM 56-11-02	HRS/MSC AFL	O/C	N:0 N:0 N:0					
560025	RH NO 1 CABIN WINDOW 5562012029 9433	MOS					30-SEP-2009 0 0		
56.060	REF: AMM 56-20-01	HRS/MSC AFL	O/C	N:0 N:0 N:0					
560030	RH NO 2 CABIN WINDOW 5562012029 9503	MOS					30-SEP-2009 0 0		
56.060	REF: AMM 56-20-01	HRS/MSC AFL	O/C	N:0 N:0 N:0					
560035	RH NO 3 CABIN WINDOW 5562012029 9391	MOS					30-SEP-2009 0 0		
56.070	REF: AMM 56-20-01	HRS/MSC AFL	O/C	N:0 N:0 N:0					



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 9383 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 9392 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 9432 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 9442 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 9394 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 9438 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 08277H4478 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
	9598110109	MOS		N:0			30-SEP-2009		
56.010	08197H3328	HRS/MSC	O/C	N:0			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56-11-01</b>	AFL		N:0			0		
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
	9598110110	MOS		N:0			30-SEP-2009		
56.010	08078H8311	HRS/MSC	O/C	N:0			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56-11-01</b>	AFL		N:0			0		
<b>CHAPTER 57 WINGS</b>									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
		MOS					30-SEP-2009		
57.010		HRS/MSC	20000				0		<b>20000</b>
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-00</b>	AFL	27000				0		<b>27000</b>
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					30-SEP-2009		
57.010		HRS/MSC	20000				0		<b>20000</b>
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-00</b>	AFL	27000				0		<b>27000</b>
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	300	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			17-AUG-2020		
		HRS/MSC	2400	+10%/-10%			3051:53		
	<b>REF: GENERIC NO REF</b>	AFL					2272		
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	<b>REF: GENERIC NO REF</b>	AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 20	MOS	12	+10%/-10%			PKG	20-AUG-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: AMM 57-00-00	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: AMM 57-00-00	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	<b>25000</b> <b>30000</b>	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-05</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-05</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/412	EXAMINE - WING TIPS								
57.170		MOS					30-SEP-2009		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES								
		MOS					30-SEP-2009		
		HRS/MSC	25000	+500/-500			0		25000 25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0		30000 30500
57-00/413	EDDY CURRENT INSPECTION - WING SKIN AROUND DRAIN HOLES								
57.180		MOS					30-SEP-2009		
		HRS/MSC	25000				0		25000
	REF:	AFL	30000				0		30000
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-SEP-2009		
		HRS/MSC	16000				0		16000
<b>AIRWORTHINESS</b>	REF: AMM 57-20-10	AFL	22500				0		22500
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-SEP-2009		
		HRS/MSC	16000				0		16000
<b>AIRWORTHINESS</b>	REF: AMM 57-20-10	AFL	22500				0		22500
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)								
57.020		MOS	48	+10%/-10%	47		07-AUG-2019	23-SEP-2023	16-FEB-2024
<b>MODERATE CORROSION ZONE</b>	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	6850:04	7250:04
		AFL					2131		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%	47		07-AUG-2019	23-SEP-2023	16-FEB-2024
<b>MODERATE CORROSION ZONE</b>	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			2850:04	6850:04	7250:04
		AFL					2131		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040	REF: AMM 57-00-00	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500		47	07-AUG-2019 2850:04 2131	23-SEP-2029 13850:04	23-MAR-2030 14350:04
+ 57-60/393	EXAMINE - RIGHT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				30-SEP-2009 0 0	32500 42000	
57-60/393	EXAMINE -LEFT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				30-SEP-2009 0 0	32500 42000	
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190	REF:	MOS HRS/MSC AFL	32500 42000				30-SEP-2009 0 0	32500 42000	
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512017 2953P REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512018 2953P REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
570050	L/H WING								
57.080	5570512135 953P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570055	R/H WING								
57.090	5570512136 953P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 61 PROPELLERS/PROPULSORS</b>									
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	<b>CMT ITEM</b> PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3232:59 2376		
610015	NO. 1 PROPELLER BLADE								
61.020	9682913023 K87537 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
610015-5	NO. 2 PROPELLER BLADE								
	9682913023 K87541 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
610015-6	NO. 3 PROPELLER BLADE								
	9682913023 K87542 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
610015-7	NO. 4 PROPELLER BLADE								
	9682913023 K87544 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E4A-3D/E10477SK KX804 REF: See Workcard	MOS HRS/MSC AFL	PP/C						

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
612010	NO. 1 ENGINE - PROPELLER GOVERNOR 3049558-01 1653476 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500 +500	R:0 N:1456:48 R:0 R:0			02-JUL-2015 1456:48	(3500) 3500	4000
<b>OVERHAUL</b>									
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 3037685 16593410 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500 +500	N:0 N:0 N:0			30-SEP-2009 0 0	(3500) 3500	4000
<b>OVERHAUL</b>									
<b>PROPELLER NO. 1 Model : HC-E4A-3 Serial # KX804 Part # HC-E4A-3D/E10477SK</b>									
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	72 4000				20-AUG-2021 3232:59	<b>20-AUG-2027</b> (7232:59) 7232:59	
<b>OVERHAUL</b>	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS HRS/MSC	12 400	+1m/-1m +10%/-10%		-13	20-AUG-2021 3232:59	<b>07-AUG-2022</b> (3632:59) 3632:59	07-SEP-2022 3672:59
	REF: POM 61-00-49								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 400	+1m/-1m +10%/-10%		-13	20-AUG-2021 3232:59	<b>07-AUG-2022</b> (3632:59) 3632:59	07-SEP-2022 3672:59
	REF: POM 61-00-49								
+ 610070	NO. 1 PROPELLER - PRE-FLIGHT CHECKS	MOS HRS/MSC	A/R				31-JUL-2009 0		
	REF: POM 61-00-49								
+ 610080	NO. 1 PROPELLER - OPERATIONAL CHECKS	MOS HRS/MSC	A/R				31-JUL-2009 0		
	REF: POM 61-00-49								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610510	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610520	NO. 1 PROPELLER - LIGHTNING STRIKE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610530	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610540	NO. 1 PROPELLER - FIRE/HEAT DAMAGE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610550	NO. 1 PROPELLER - SUDDEN STOPPAGE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610560	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								
+ 610570	NO. 1 PROPELLER - LONG TERM STORAGE	MOS						31-JUL-2009	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF: POM 61-00-49								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE E10477SK K87544 REF: GENERIC NO REF	MOS HRS/MSC	O/C	O:0 O:0				16-NOV-2015 1456:48	
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE E10477SK K87537 REF: GENERIC NO REF	MOS HRS/MSC	O/C	O:0 O:0				16-NOV-2015 1456:48	
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE E10477SK K87541 REF: GENERIC NO REF	MOS HRS/MSC	O/C	O:0 O:0				16-NOV-2015 1456:48	
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE E10477SK K87542 REF: GENERIC NO REF	MOS HRS/MSC	O/C	O:0 O:0				16-NOV-2015 1456:48	
611505	NO. 1 PROPELLER - OVERHAUL DAMPER ASSEMBLIES  REF: GENERIC NO REF	MOS HRS/MSC	N/A					31-JUL-2009 0	
<b>CHAPTER 71 POWER PLANT</b>									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 19 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%				20-AUG-2021 3232:59 2376	
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 19 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%				20-AUG-2021 3232:59 2376	



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 19	MOS	12	+10%/-10%			20-AUG-2021		
	REF: AMM 71-00-03	HRS/MSC	600	+10%/-10%			3232:59		
		AFL					2376		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN	MOS		N:0			30-SEP-2009		
<b>AIRWORTHINESS</b>	SN-UNKNOWN	HRS/MSC	20000	N:0			0	<b>20000</b>	
	REF: AMM 71-00-05	AFL	27000	N:0			0	<b>27000</b>	
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050		MOS					30-SEP-2009		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC	11000				0	<b>11000</b>	
		AFL					0		
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
	REF: AMM 71-00-00	HRS/MSC	A/R				3232:59		
		AFL					2376		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			3232:59		
		AFL					2376		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			3232:59		
		AFL					2376		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS.						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					20-AUG-2021		
	REF: AMM 71-00-00	HRS/MSC	A/R				3232:59		
		AFL					2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY.						PKG		
	PKG 20	MOS	12	+10%/-10%			20-AUG-2021		
		HRS/MSC	1200	+10%/-10%			3232:59		
	REF:	AFL					2376		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					30-SEP-2009		
71.063	4612	HRS/MSC	5000/E/C	+10%/-10%	N:0		0	5000	5500
	REF: AMM 71-00-00	AFL			N:0		0		
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					30-SEP-2009		
71.064	4648	HRS/MSC	5000/E/C	+10%/-10%	N:0		0	5000	5500
	REF: AMM 71-00-00	AFL			N:0		0		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					30-SEP-2009		
71.061	4631	HRS/MSC	5000/E/C	+10%/-10%	N:0		0	5000	5500
	REF: AMM 71-00-00	AFL			N:0		0		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					30-SEP-2009		
71.060	4630	HRS/MSC	5000/E/C	+10%/-10%	N:0		0	5000	5500
	REF: AMM 71-00-00	AFL			N:0		0		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS					30-SEP-2009		
71.062	4633	HRS/MSC	5000/E/C	+10%/-10%	N:0		0	5000	5500
	REF: AMM 71-00-00	AFL			N:0		0		
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
		MOS					30-SEP-2009		
		HRS/MSC	26600				0	26600	
AIRWORTHINESS	REF: AMM 71-00-05	AFL	35000				0	35000	





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 20-AUG-2021 3232:59 2376		
710050	ENGINE MOUNT (WELDED) 5712012036 968 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
71EN1 71.EN1	NO. 1 ENGINE PT6A-67P PCE-RY0189 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01									
710011	NO. 1 ENGINE - OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			30-SEP-2009 0 0	(3500) 3500	3700
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE PKG 0 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710021	NO. 1 ENGINE - HOT SECTION INSPECTION <b>CMT ITEM</b>	MOS					22-MAR-2017		
		HRS/MSC	1750	+250		-138:2 4	1888:24	(3500) 3500	3750
	REF: EMM 72-00-00	ENC					1513		
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					20-AUG-2021		
		HRS/MSC	600	+10%/-10%			3232:59	(3832:59) 3832:59	3892:59
	REF: EMM 72-00-00	ENC					2345		
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					30-SEP-2009		
		HRS/MSC	N/A				0		
	REF: EMM 72-00-00	ENC					0		
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH	MOS	6	+10%/-10%		-30	20-AUG-2021	21-JAN-2022	08-FEB-2022
		HRS/MSC	300	+10%/-10%			3232:59	(3532:59) 3532:59	3562:59
	REF: EMM 71-00-00	ENC					2345		
+ 710051	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH	MOS	6	+10%/-10%		-30	20-AUG-2021	21-JAN-2022	08-FEB-2022
		HRS/MSC	300	+10%/-10%			3232:59	(3532:59) 3532:59	3562:59
	REF: EMM 71-00-00	ENC					2345		
+ 710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH	MOS				-10	17-AUG-2020		
		HRS/MSC	A/R				3051:53		
	REF: EMM 71-00-00	ENC					0		
+ 710053	NO. 1 ENGINE - EXTERNAL ENGINE WASH	MOS	6	+10%/-10%		-30	20-AUG-2021	21-JAN-2022	08-FEB-2022
		HRS/MSC	300	+10%/-10%			3232:59	(3532:59) 3532:59	3562:59
	REF: EMM 71-00-00	ENC					2345		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS	12	+1m/-1m		-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	REF: EMM 72-00-00	HRS/MSC	300	+10%/-10%			3232:59	<b>(3532:59) 3532:59</b>	3562:59
		ENC					2345		
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						PKG		
	PKG 0	MOS					20-AUG-2021		
	REF: EMM 71-00-00	HRS/MSC	300	+10%/-10%			3232:59		
		ENC					2345		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS	12	+1m/-1m		-13	20-AUG-2021	<b>07-AUG-2022</b>	07-SEP-2022
	REF: EMM 72-00-00	HRS/MSC	300	+10%/-10%			3232:59	<b>(3532:59) 3532:59</b>	3562:59
		ENC					2345		
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE								
	PN	MOS					30-SEP-2009		
	SN-UNKNOWN	HRS/MSC	3500	+200			0	<b>(3500) 3500</b>	3700
<b>OVERHAUL</b>	REF: See Workcard	ENC					0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL								
	REF: EMM 72-00-00	MOS					30-SEP-2009		
		HRS/MSC	A/R				0		
		ENC					0		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP								
	REF: EMM 72-60-00	MOS					30-SEP-2009		
		HRS/MSC	A/R				0		
		ENC					0		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT								
	PKG 0	MOS					20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			3232:59		
		ENC					2345		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
	REF: GENERIC NO REF								
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
	REF: GENERIC NO REF								
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
	REF: GENERIC NO REF								
+ 720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES	MOS HRS/MSC ENC	A/R				30-SEP-2009 0 0		
	REF: EMM 72-00-00								
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS HRS/MSC ENC	A/R				30-SEP-2009 0 0		
	REF: EMM 72-11-00								
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
	REF: See Workcard								
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
	REF: EMM 72-20-00								



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 TXA1C0190	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC 24000		N:0 N:0			0		
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA277321	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC 24000		N:0 N:0			0		
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 0	MOS HRS/MSC	300	+10%/-10%			20-AUG-2021 3232:59		
	<b>REF: EMM 72-30-04</b>	ENC					2345		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 EAAB000W376	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC 24000		N:0 N:0			0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 0	MOS HRS/MSC	300	+10%/-10%			20-AUG-2021 3232:59		
	<b>REF: See Workcard</b>	ENC					2345		
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000W997	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC 24000		N:0 N:0			0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 TXA1C0579	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC	24000	N:0 N:0			0		
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAB000W747	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC	24000	N:0 N:0			0		
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS HRS/MSC	A/R				30-SEP-2009 0		
<b>UNSCHEDULED MAINTENANCE CHECK</b>	<b>REF: See Workcard</b>	ENC					0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 A002M35B	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC	8000	N:0 N:0			0		
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS HRS/MSC	5000				30-SEP-2009 0	<b>(5000) 5000</b>	
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC					0		
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 0	MOS HRS/MSC	300	+10%/-10%			PKG 20-AUG-2021 3232:59 2345		
<b>REF: EMM 72-50-05</b>		ENC							
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A002M2YR	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC ACCCYC	15000	N:0 N:0			0		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 YUAA0033A899	MOS HRS/MSC		N:0 N:0			30-SEP-2009 0		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC ACCCYC	15000	N:0 N:0			0		
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN	MOS HRS/MSC	3500	+200 N:0			30-SEP-2009 0	(3500) 3500	3700
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	ENC		N:0			0		
726050 (s)	NO. 1 ENGINE - INSPECTION/CHECK FOR OIL LEAKS AT PROP SHAFT SEAL PKG 0	MOS HRS/MSC	100				PKG 20-AUG-2021 3232:59		
	<b>REF:</b>	ENC					2345		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP 3040760 009899	MOS HRS/MSC	3500	R:0 N:1456:48 R:0			02-JUL-2015 1456:48	(3500) 3500	
<b>OVERHAUL</b>	<b>REF:</b> EMM 73-10-02	ENC		R:0					
731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS HRS/MSC	N/A				11-OCT-2018 2534:06		
	<b>REF:</b> See Workcard	ENC					1916		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) <b>CMT ITEM</b>	MOS HRS/MSC	600	+10%/-10%			20-AUG-2021 3232:59	(3832:59) 3832:59	3892:59
	<b>REF:</b> EMM 73-11-05	ENC					2345		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51049 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	R:0 N:1456:48 R:0 R:0		02-JUL-2015 1456:48	(3500) 3500	4000
<b>OVERHAUL</b>									
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				30-SEP-2009 0 0		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN <b>CMT ITEM</b> 3040760 009899 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			20-AUG-2021 3232:59 2345	(3832:59) 3832:59	3892:59
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 009899 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				08-JUN-2018 2404:02 1827		
731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				08-JUN-2018 2404:02 1827		





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER <b>CMT ITEM</b> 3059779-01 NSN <b>REPLACE</b> REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			20-AUG-2021 3232:59 2345	(3832:59) 3832:59	3892:59
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA37332 <b>REF:</b> EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	R:0 N:1456:48 R:0 R:0		02-JUL-2015 1456:48	(3500) 3500	4000
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL  <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			20-AUG-2021 3232:59 2345	(3532:59) 3532:59	3562:59
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 9959525098 <b>REF:</b> EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		30-SEP-2009 0 0	(3500) 3500	4000
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 <b>REF:</b> EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-07 16604009 <b>OVERHAUL</b> REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	R:0 N:1456:48 R:0 R:0		07-FEB-2015 1456:48	(3500) 3500	4000



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	4000		N:0 N:0 N:0		30-SEP-2009 0 0	(4000) 4000	
731100	NO. 1 ENGINE - CLEAN P3 FILTER CMT ITEM REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345	(3532:59) 3532:59	3562:59
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 3059779-01 NSN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T		N:0 N:0 N:0		20-AUG-2021 3232:59 2345		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			20-AUG-2021 3232:59 2345		
733020	NO. 1 ENGINE - REPLACE P3 FILTER CMT ITEM REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%		49:56	07-AUG-2019 2850:04 2116	(3800) 3800	3890



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY	MOS					20-AUG-2021		
	REF: See Workcard	HRS/MSC	300	+10%/-10%			3232:59	(3532:59) 3532:59	3562:59
		ENC					2345		

CHAPTER 74	IGNITION								
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM						PKG		
	<b>CMT ITEM</b>								
	PKG 17	MOS	12	+10%/-10%			20-AUG-2021		
	REF: AMM 74-00-00	HRS/MSC	300	+10%/-10%			3232:59		
		AFL					2376		

ENGINE NO. 1	Model : PT6A-67P	Serial # PCE-RY0189	Part # 3072955-01
--------------	------------------	---------------------	-------------------

740010	NO. 1 ENGINE - IGNITION EXCITER								
	3035889	MOS			N:0		30-SEP-2009		
	NNA09250001	HRS/MSC	3500	+500	N:0		0	(3500) 3500	4000
	REF: EMM 74-10-00	ENC			N:0		0		

740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION								
		MOS					20-AUG-2021		
	REF: EMM 74-10-00	HRS/MSC	400	+10%/-10%			3232:59	(3632:59) 3632:59	3672:59
		ENC					2345		

740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG								
	3032096	MOS			N:3		03-MAY-2016		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		1563:54		
	REF: GENERIC NO REF	ENC			N:0		1268		

740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION								
	<b>CMT ITEM</b>								
		MOS					20-AUG-2021		
	REF: EMM 74-20-00	HRS/MSC	400	+10%/-10%			3232:59	(3632:59) 3632:59	3672:59
		ENC					2345		

740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG								
	3032096	MOS			N:3		03-MAY-2016		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		1563:54		
	REF: GENERIC NO REF	ENC			N:0		1268		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION								
	REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			20-AUG-2021 3232:59 2345	(3632:59) 3632:59	3672:59

## CHAPTER 75 AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE								
	3059835-01 AHX014644 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	R:0 N:1456:48 R:0 R:0		02-JUL-2015 1456:48	(3500) 3500	4000

## CHAPTER 76 ENGINE CONTROLS

76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT						PKG		
	PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		

76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM)						PKG		
	PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		

76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE.						PKG		
	CMT ITEM PKG 16 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			20-AUG-2021 3232:59 2376		

76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE						PKG		
	CMT ITEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 17	MOS	12	+10%/-10%			PKG 20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3232:59 2376		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES CMT ITEM								
76.010		MOS	12	+10%/-10%		-13	20-AUG-2021	07-AUG-2022	13-SEP-2022
	REF: AMM 76-10-02	HRS/MSC AFL	3000	+10%/-10%			3232:59 2376	6232:59	6532:59
760015	MANUAL OVERRIDE CABLE ASSY.								
76.020	9419411417	MOS		N:0			30-SEP-2009		
	20090049	HRS/MSC	O/C	N:0			0		
	REF: AMM 76-20-00	AFL		N:0			0		
760020	CONDITION CABLE ASSY.								
76.030	9419411418	MOS		N:0			30-SEP-2009		
	20090024	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419	MOS		N:0			30-SEP-2009		
	20090024	HRS/MSC	O/C	N:0			0		
	REF: AMM 76-10-04	AFL		N:0			0		
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01</b>									
761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES								
		MOS	12	+30d/-10%		-13	20-AUG-2021	07-AUG-2022	06-SEP-2022
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			3232:59 2345	(3532:59) 3532:59	3562:59
<b>CHAPTER 77 ENGINE INDICATING</b>									
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206	MOS		N:0			11-OCT-2018		
	8563-9-165	HRS/MSC	O/C	N:0			2534:06		
	REF: AMM 77-40-03	AFL		N:0			1923		



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	9752115212 3857650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-JUL-2013 964:54 878		
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01</b>									
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NR04686 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>CHAPTER 78 EXHAUST</b>									
78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 17	MOS HRS/MSC REF: GENERIC NO REF	12 300	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
<b>CHAPTER 79 OIL</b>									
79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK						PKG		
	<b>CMT ITEM</b> PKG 19	MOS HRS/MSC REF: AMM 79-30-06	12 600	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 20	MOS HRS/MSC REF: GENERIC NO REF	12 1200	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						PKG		
	<b>CMT ITEM</b> PKG 17	MOS HRS/MSC REF: AMM 79-30-01	12 300	+10%/-10% +10%/-10%			20-AUG-2021 3232:59 2376		
79-20/43	OIL COOLER								
79.010	9683214102 T1081 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		30-SEP-2009 0 0	3500	3850
<b>OVERHAUL</b>									



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790005	TEMPERATURE BULB								
79.020	9751120101 156898 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
790020	PRESSURE,GAGE SWITCH								
79.030	9738114305 1011 REF: AMM 79-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
790025	THERMAL ACTUATOR								
79.040	9787301002 1170 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0189 Part # 3072955-01</b>									
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM								
<b>DISCARD</b>	REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				06-JUL-2015 1456:48 1196		
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR								
	REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+30d/-10% +10%/-10%			20-AUG-2021 3232:59 2345	<b>20-AUG-2022</b> <b>(3532:59) 3532:59</b>	19-SEP-2022 3562:59
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR								
	<b>CMT ITEM</b>	MOS HRS/MSC ENC	12 600	+1m/-1m +10%/-10%	-13		20-AUG-2021 3232:59 2345	<b>07-AUG-2022</b> <b>(3832:59) 3832:59</b>	07-SEP-2022 3892:59
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT								
	<b>CMT ITEM</b>	MOS HRS/MSC ENC	900	+10%/-10%	49:56		07-AUG-2019 2850:04 2116	<b>(3800) 3800</b>	3890



# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN <b>CMT ITEM</b>	MOS					20-AUG-2021		
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			3232:59 2345	(3532:59) 3532:59	3562:59
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					20-AUG-2021		
	REF: EMM 72-60-00	HRS/MSC ENC	1000	+10%/-10%			3232:59 2345	(4232:59) 4232:59	4332:59
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					03-JUN-2015		
	REF: EMM 79-20-02	HRS/MSC ENC	N/A						
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING	MOS					30-SEP-2009		
	REF: EMM 72-00-00	HRS/MSC ENC	N/A				0 0		
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0	MOS					20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			3232:59 2345		
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0	MOS					20-AUG-2021		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			3232:59 2345		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 9752115214	MOS					30-SEP-2009		
	7518-8-65	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		

CHAPTER 91

-





# Status Report

PC-12/47E S/N 1160 (OH-WWW): 3416:02 HRS, 2504 AFL as of 09-Mar-2022

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 11-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240120	BATTERY EXT POWER JUNCTION BOX								
90.005	9740338141 287 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
910015	KBT 300 TTP BUS RES, A-157 TERMINAL								
90.015	9859912117 KBT300-1747 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL								
90.025	9859912117 KBT300-1717 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL								
90.020	9859912117 KBT300-1718 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX								
90.030	9740338144 141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-OCT-2017 2131 1658		
910035	CO-PILOT RIGHT HD POWER, FE1549R JUNCTION BOX								
90.030	9740338140 210 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
90.010	9859912117 KBT300-1713 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-SEP-2009 0 0		