

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 (0) 1.55.93.45.80 (OFFICE)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.53.01.66.18 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 855/LX-JFN **MODEL:** PC12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 31-OCT-2007	5763:15 A/C HRS	as of 30-DEC-2018	A/C HRS	as of ___/___/___
	4974 AFL	as of 30-DEC-2018	AFL	as of ___/___/___
	355 ACH	as of 18-SEP-2018	ACH	as of ___/___/___
	4543 FLTS	as of 30-DEC-2018	FLTS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0740/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 22-JUN-2016	LAST ACTUALS		CURRENT ACTUAL	
3939:35 ENG. HRS 4310:10 A/C HRS	5392:40 ENG. HRS	as of 30-DEC-2018	ENG. HRS	as of ___/___/___
3141 ENC	4315 ENC	as of 30-DEC-2018	ENC	as of ___/___/___

PROPELLER NOSERIAL/PART: KX456/HC-E4A-3D/D10477SK **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 04-AUG-2018	LAST ACTUALS		CURRENT ACTUAL	
5559:54 PROP HRS 0 A/C HRS	5788:29 PROP HRS	as of 30-DEC-2018	PROP HRS	as of ___/___/___



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05JFL02	ANNUAL INSPECTION							
	PKG 2	MOS	12			07-JUN-2018	07-JUN-2019	07-JUL-2019
		HRS/MSC				5454:35		
	REF:	AFL				4722		
05JFL03	150 HOURS INSPECTION							
	PKG 4 in PKG 2	MOS	12			18-SEP-2018	18-SEP-2019	
		HRS/MSC	150		-3:50	5608:25	5754:35	5769:35
	REF:	AFL				4855		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0740 Part # 3042200								
057010 (s)	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 0 in PKG 1	MOS				18-SEP-2018	PKG	
		HRS/MSC	150			5237:50		
	REF: See Workcard	ENC				4196		
CHAPTER 72 ENGINE								
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0740 Part # 3042200								
72JFL01	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 1	MOS				18-SEP-2018		
		HRS/MSC	150		4:40	5237:50	(5392:30) 5763:05	5407:30
	REF:	ENC				4196		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 2,4	MOS	12	+1m/-1m			18-SEP-2018		
	REF:	HRS/MSC	100	+10%/-10%			5608:25		
		AFL					4855		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					01-NOV-2018		
		HRS/MSC	-				5689:20		
		AFL					4921		
00JFL60	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 0 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					08-MAR-2017		
		HRS/MSC	-				4731:15		
		AFL					4121		
00JFL61	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 1 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					20-APR-2018		
		HRS/MSC	-				5306		
		AFL					4610		
00JFL62	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 2 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
	REF:	MOS					18-SEP-2018		
		HRS/MSC	-				5608:25		
		AFL					4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL63	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 6 AMDT 3 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - AFL							
	REF:								
00JFL64	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 4 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - AFL							
	REF:								
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF PC12								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM	MOS					20-AUG-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF	MOS					04-MAY-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-160717	REVIEW PILATUS PC12 AMM REV 32	MOS					23-NOV-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS					07-FEB-2017		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS					29-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	MOS HRS/MSC - AFL							
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12 NEW REQUIREMENT ADDED ON 18-DEC-2018 (EFFECTIVE: 29-NOV-2018). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.	MOS HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014							10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF							10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150404	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 22 DATED NOV 16/2012 RCF						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0							10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160317	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P SB	PT6A-72-14603 REV 25					16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-160421	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM	REV 44.0						
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-160919	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P SB	PT6A-72-14603 REV 26					01-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM	REV 44.1					31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM	REV 44.2					07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P SB	PT6A-72-14002 REV 24					07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170410	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 45.0					16-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW	PWC SB PT6A-72-14603	R27				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170728	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 45.1				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 45.2				11-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF E072-170818	MOS HRS/MSC - ENC							
E072-171030	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 46.0				22-FEB-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180409	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 47.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180409-1	NO. 1 ENGINE - REVIEW	CODE CHANGE NOT PART FOR REV 47					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM REV 47.1					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM REV 47.2					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P EMM REV 48.0					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 20-NOV-2018 (EFFECTIVE: 29-OCT-2018). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX456 Part # HC-E4A-3D/D10477SK									
P019-150423	NO. 1 PROPELLER - REVIEW	HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						10-SEP-2015	
P019-150901	NO. 1 PROPELLER - REVIEW	HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF							
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC -						10-SEP-2015	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-160201 (s)	NO. 1 PROPELLER - REVIEW	HARTZWELL	PROPELLER	HC-E4A-3	POM	REV 22		31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS	HRS/MSC	-					
P019-160801	NO. 1 PROPELLER - REVIEW	HC-E4A-3	SL	REV 10	REQUIREMENT SUMMARY	CHANGE FORM		16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS	HRS/MSC	-					
P019-171001	NO. 1 PROPELLER - REVIEW	HARTZELL	HC-E4A-3	POM	149	REV 23		(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS	HRS/MSC	-					
P019-180301	NO. 1 PROPELLER - REVIEW	HARTZELL	HC-34A-3	POM	147	REV 14		(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS	HRS/MSC	-					
P019-180701	NO. 1 PROPELLER - REVIEW	HC-E4A-3	POM	149	REV 24			(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS	HRS/MSC	-					
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05JFL11	- AIRWORTHINESS REVIEW CERTIFICATE								
		MOS	HRS/MSC	DUE			06-DEC-2018	12-DEC-2019 M	
REF:		AFL					5743:35		
							4959		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05JFL12	- CERTIFICATE OF REGISTRATION	MOS					08-NOV-2007		
	REF:	HRS/MSC AFL	A/R						
05JFL13	- NOISE CERTIFICATE	MOS					06-NOV-2007		
	REF:	HRS/MSC AFL	A/R						
05JFL14	- AIRCRAFT STATION LICENCE	MOS					16-NOV-2018	31-DEC-2021 M	
	REF:	HRS/MSC AFL	DUE						
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING	MOS					18-SEP-2018		
	REF:	HRS/MSC AFL ACH	150 150	+10%/-10% +10%/-10%	4:40		5608:25 4855 355	5763:05 5778:05 505	5778:05 520

CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 4 ,2	MOS					18-SEP-2018		
	REF:	HRS/MSC AFL	100				5608:25 4855		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 4 ,2	MOS					18-SEP-2018		
	REF: AMM 06-20-00	HRS/MSC AFL	100				5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR.						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: AMM 06-20-00	AFL					4722		
06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF:	AFL					4722		
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC	100				5454:35		
	REF: AMM 07-10-00	AFL					4722		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC	100				5454:35		
	REF: AMM 07-10-00	AFL					4722		
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST								
		MOS	60	+1m/-1m			22-SEP-2017	22-SEP-2022	22-OCT-2022
		HRS/MSC					5017:55		
	REF:	AFL					4360		
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6)								
		MOS					29-MAR-2018		
		HRS/MSC	-				5291:50		
	REF:	AFL					4599		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 10									
PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 2,4	MOS	12	+10%/-10%			18-SEP-2018		
		HRS/MSC	100	+10/-10			5608:25		
	REF:	AFL					4855		
CHAPTER 11									
PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: See Workcard	AFL					4722		
CHAPTER 12									
SERVICING									
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 12-20-01	AFL					4855		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 12-20-02	AFL					4855		
12-20/126 (s)	CLEAN COCKPIT AND CABIN						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 12-20-03	AFL					4855		
CHAPTER 20									
STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
		MOS	12	+10%/-10%			07-JUN-2018	07-JUN-2019	13-JUL-2019
20.010		HRS/MSC					5454:35		
	REF: AMM 20-40-00	AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
20.011	REF: AMM 20-40-00	MOS HRS/MSC AFL	6 300	+10%/-10% +10%/-10%		8:30	07-JUN-2018 5454:35 4722	07-DEC-2018 5763:05	25-DEC-2018 5793:05
20JFL01	PERFORM DENTS AND BUCKLES CHARTS								
	REF:	MOS HRS/MSC AFL	150				18-SEP-2018 5608:25 4855	5758:25	
CHAPTER 21 AIR CONDITIONING									
21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN						PKG		
	PKG 2	MOS HRS/MSC AFL	12				07-JUN-2018 5454:35 4722		
21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 2	MOS HRS/MSC AFL	12				07-JUN-2018 5454:35 4722		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
21.040	REF: AMM 21-30-00	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		9	21-SEP-2017 5017:55 4360	30-SEP-2019 8017:55	12-DEC-2019 8317:55
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
21.030	REF: AMM 21-30-01	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		9	21-SEP-2017 5017:55 4360	30-SEP-2019 8017:55	12-DEC-2019 8317:55



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH	MOS	60	+10%/-10%			21-SEP-2017	31-OCT-2022	30-APR-2023
21.010	REF: AMM 21-30-07	HRS/MSC AFL			40		5017:55 4360		
21-40/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH	MOS	60	+10%/-10%			21-SEP-2017	31-OCT-2022	30-APR-2023
21.020	REF: AMM 21-30-08	HRS/MSC AFL			40		5017:55 4360		
21-40/50	CLEAN WATER SEPARATOR CONDENSER	MOS					07-JUN-2018	5904:35	
21.080	REF: AMM 21-40-02	HRS/MSC AFL	450	+10%/-10%			5454:35 4722		
21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%			21-SEP-2017	31-OCT-2022	30-APR-2023
21.130	REF: AMM 21-40-06	HRS/MSC AFL			40		5017:55 4360		
21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%			21-SEP-2017	31-OCT-2022	30-APR-2023
21.120	REF: AMM 21-60-05	HRS/MSC AFL			40		5017:55 4360		
21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: AMM 21-40-00	HRS/MSC AFL					5454:35 4722		
21-40/55	RE-OIL AIR CONDITIONING COLD AIR UNIT	MOS					07-JUN-2018	5904:35	
21.060	REF: AMM 21-40-01	HRS/MSC AFL	450	+10%/-10%			5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/56	INSPECT/CHECK HEAT EXCHANGER MATRIX	MOS					07-JUN-2018		
21.070	REF: AMM 21-40-01	HRS/MSC AFL	450	+10%/-10%			5454:35 4722	5904:35	
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT	MOS	12				07-JUN-2018		
	PKG 2	HRS/MSC AFL					5454:35 4722		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)	MOS					07-JUN-2018		
	959.90.22.102	HRS/MSC	300	+10%/-10%	8:30		5454:35	5763:05	5793:05
	239	AFL					4722		
	REF:	AFL							
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)	MOS					31-OCT-2007		
	959.90.22.102	HRS/MSC	N/A				0		
	239	AFL					0		
	REF:	ACH							
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)	MOS					31-OCT-2007		
	959.90.22.102	HRS/MSC	N/A				0		
	239	AFL					0		
	REF:	ACH							
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)	MOS					31-OCT-2007		
21.110	REF: AMM 21-50-03	HRS/MSC AFL ACH	500	+10%/-10%			0 0 0	500	550



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.100	959.90.22.102 239 REF: See Workcard	MOS HRS/MSC AFL ACH	500	+10%/-10%			20-JUL-2012 2219:50 1874 0	500	550
210005	OVERPRESSURE SWITCH								
21.340	9738115105 645 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210010	REFRIGERATION PACK								
21.255	9599020111 1413 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 1573 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1389 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 1676 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C				18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210035	WATER SEPARATOR ASSY								
21.220	5214112060 2534 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1373 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	959.90.22.102 239 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-JUL-2012 2219:50 1874		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 270 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	9599022118 248 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 336 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-JAN-2008 106:06 90		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091123 67-C0177 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091133 67-G0179 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	9599091111 37-8247 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210075	CHECK VALVE								
21.400	9599091151 47-A1257 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210080	JET PUMP								
21.410	9599091161 47-2373 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210085	MANUAL CONTROLLER								
21.420	9599091101 67-A0776 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	9599091141 116-G0793 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	9652323202 1055639 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-NOV-2009 1023:06 789		
210100	CAB RATE INDICATOR								
21.440	9651621002 1044471 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.150 563537 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C				23-JAN-2018 5185:15 4510		
210120	BAY TEMP SENSOR								
21.450	9599020122 1393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	9751516101 D0054 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210130	TEMP CONTROLLER								
21.235	9599020123 1389 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210140	SOLENOID VALVE								
21.300	9631411001 07-05311084 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 527421 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	9633011106 0605B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	9633011002 594 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 667 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
21C007	DIFFERENTIAL PRESURE SWITCH								
	965.23.21.534 1035780 REF:	MOS HRS/MSC AFL	O/C				21-SEP-2017 5017:15 4360		
21C008	MAX CABIN ALTITUDE SWITCH								
	965.23.21.533 1026872 REF:	MOS HRS/MSC AFL	O/C				21-SEP-2017 5017:15 4360		
21C009	TEMP TRANSMIT,T21.10.110-HG1610A								
	9751516106 526 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21C010	TEMP TRANSMIT,T21.10.110-S1503 A 9751516105 579 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST REF:	MOS HRS/MSC AFL	24				07-JUN-2018 5454:35 4722	07-JUN-2020	
CHAPTER 22 AUTO FLIGHT									
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
22-10/60 22.010	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 6454:35	13-JUL-2019 6554:35
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 4 ,2 REF: AMM 22-20-00	MOS HRS/MSC AFL	100				PKG 18-SEP-2018 5608:25 4855		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 2 REF: AMM 22-20-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220005	AUTOPILOT MODE CONTROL								
22.160	065-0086-17 1583 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C				01-NOV-2018 5689:20 4921		
220010	ALTITUDE PRESELECTOR								
22.180	065-0089-16 2478 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C				08-DEC-2016 4601:25 4018		
220015	AILERON KSA372,065-00056-0056 ACTUATOR								
22.100	9859203161 6376 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220020	PITCH KSM375,065-00015-0000 MOUNT								
22.190	9859203173 10488 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR								
22.110	9859203164 M5420 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C				05-DEC-2014 3441:50 2995		
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	9859203171 10481 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	9859203163 6371 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	9859203171 10490 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220045	STICK PUSHER SERVO								
22.220	9786111103 80253 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220050	PITCH TRIM ADAPTER								
22.130	9859203181 1859 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	9786111124 80256 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220060	STICK SHAKER								
22.230	9786111143 763 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
220065	AUTOPILOT COMPUTER								
22.150	065-0064-15 3024 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			03-MAR-2011 1522:26 1191		
220070	STICK PUSHER COMPUTER								
22.170	975.44.23.104 121248 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-JUN-2018 5454:35 4722		

CHAPTER 23 COMMUNICATIONS



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203 310-16681 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-16682 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
230025	AUDIO SUMMING AMPLIFIER								
23.010	9878133108 495 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
23C011	RECEIVER/EXCITER,HF								
	9859911915 34742 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
23C013	UNIT,CONTROL,HF COMM,KCU951								
	9859911901 13015 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
23C014	AUDIO PANEL,GMA 340								
	9856115113 96280538 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
23JFL01	NO. 1 NAV/COM/GPS GARMIN GNS 530 TRANSCEIVER								
	011-00550-10 78415247 REF:	MOS HRS/MSC AFL	O/C				28-AUG-2015 3871:05 3335		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23JFL02	NO. 2 NAV/COM/GPS GARMIN GNS 530 TRANSCEIVER 011-00550-10 78417819 REF:	MOS HRS/MSC AFL	O/C				10-APR-2014 3009 2607		
CHAPTER 24 ELECTRICAL POWER									
24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM PKG 2 REF: AMM 24-20-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 18-SEP-2018 5608:25 4855		
24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED) PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
24-30/19	STARTER GENERATOR 23085-029A 97301 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C		TSO:3 TSO:0 TSO:0		08-MAR-2017 4731:15 4121		
24-30/20	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING 940.83.08.902 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	3000	+10%/-10%	TSN:0 TSN:0 TSN:0		11-NOV-2013 2854:25 2427	5854:25	6154:25
24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/61	BRUSH CHECK STARTER GENERATOR BRUSHES (ALL P/N'S EXCEPT 978.91.23.407 AND 978.91.23.408)								
24.020	23085-029A 97301 REF: AMM 24-30-01	MOS HRS/MSC AFL	150	+10%/-10%			18-SEP-2018 5608:25 4855	5758:25	5773:25
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS								
24.210	REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%	50		21-SEP-2017 5017:55 4360	10-NOV-2019	22-JAN-2020
24-30/64	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES								
	5243212158 100891 REF: AMM 24-30-02	MOS HRS/MSC AFL	300	+10%/-10%			07-JUN-2018 5454:35 4722	5754:35	5784:35
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
24.030	REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A		50:16		28-AUG-2015 3871:05 3335		
24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
	REF: AMM 24-30-04	MOS HRS/MSC AFL	1000	+10%/-10%	45:36		08-JUN-2017 4875:45 4239	5921:21	6021:21
24-30/68	PERFORM NO. 1 NICAD BATTERY NICAD BATTERY OR BATTERIES (PART NO. 976.17.31.302) REMOVE AND SERVICE (12-A-24-30-07-00A-920A-A AND CMM)								
	9761731302 11102400 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			18-SEP-2018 5608:25 4855	18-SEP-2019 5908:25	24-OCT-2019 5938:25



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	AFL					4722		
24-50/70 24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 9858314953 82392 REF: See Workcard	MOS	12	+1m/-1m			07-JUN-2018 5454:35 4722	07-JUN-2019	07-JUL-2019
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	AFL	100				4722		
240005 24.120	STARTER/GENERATOR 1 VOLTAGE REGULATOR 988.21.14.111 P4123 REF: AMM 24-30-05	MOS	O/C		TSN:0		19-JUL-2016 4366:55 3787		
		HRS/MSC			TSN:0				
		AFL			TSN:0				
240015 24.130	GENERATOR 2 300A CONTACTOR 9740338113 N680 REF: GENERIC NO REF	MOS	O/C		TSN:0		31-OCT-2007 0 0		
		HRS/MSC			TSN:0				
		AFL			TSN:0				
240020 24.130	GENERATOR 1 300A CONTACTOR 9740338113 N679 REF: GENERIC NO REF	MOS	O/C		TSN:0		31-OCT-2007 0 0		
		HRS/MSC			TSN:0				
		AFL			TSN:0				
240025 24.140	GENERATOR 2 2ND GENCON UNIT 988.21.15.103 10644 REF: GENERIC NO REF	MOS	O/C		TSN:0		28-AUG-2015 3871:05 3335		
		HRS/MSC			TSN:0				
		AFL			TSN:0				



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240035	BUSBAR,CROSS TIE RCCB								
24.150	9725537003 1449 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240040	BUSBAR,CROSS,TIE RCCB								
24.150	9725537005 813 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240045	STARTER RELAY								
24.160	9740926133 P918 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240050	BATTERY RELAY								
24.170	9740926126 R710 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240055	EPU RELAY								
24.180	9740926126 R719 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	9728132301 744 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240065	OVERHEAD PANEL								
24.190	972.81.32.109 JWPIL2002341 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-DEC-2017 5160:45 4490		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	959.90.20.124 387 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-JAN-2018 5185:15 4510		
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	9750421112 511 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240085	A242 26 VAC,SC3(A) INVERTER								
24.070	9750421112 466 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	9742900201 3857 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240095	S105 DC CURRENT SENSOR								
24.090	9742900205 2609 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	9742900205 2587 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	9742900201 3908 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240110	S104 DC CURRENT SENSOR								
24.090	9742900201 3845 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
240115	S106 DC CURRENT SENSOR								
24.100	9742900201 3859 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
243045	GENERATOR 2								
24.030	5243212158 100891 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	9858314953 82392 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-SEP-2014 3398:45 2863		
243100	NO. 1 NICAD BATTERY								
24.060	9761731302 11102400 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				18-SEP-2018 5608:25 4855		
24C019	DC-DC POWER CONVERTER								
	9750215106 1272 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC AFL	100				5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 2,4 REF:	MOS HRS/MSC AFL	12 150				PKG 18-SEP-2018 5608:25 4855		
25-10/294	COPILOT CREW SEAT BELT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0		31-OCT-2007	31-OCT-2019	30-APR-2020
25-10/294	PILOT CREW SEAT BELT 959.30.01.141 A21DEC-16-13 REF:	MOS HRS/MSC AFL	144	+6m/-6m	TSN:0 TSN:0 TSN:0		09-MAY-2017 4824:50 4194	09-MAY-2029	09-NOV-2029
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 18-SEP-2018 5608:25 4855		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 2,4	MOS	12				18-SEP-2018		
	REF:	AFL	HRS/MSC 150				5608:25		
							4855		
25-20/295	PASSENGER SEAT BELTS PN	MOS	144	+6m/-6m	TSN:0		31-OCT-2007	31-OCT-2019	30-APR-2020
25.010	SN-UNKNOWN	HRS/MSC			TSN:0		0		
DISCARD	REF: AMM 25-21-02	AFL			TSN:0		0		
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 2	MOS	12				07-JUN-2018		
	REF: See Workcard	AFL	HRS/MSC				5454:35		
							4722		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 2	MOS	12				07-JUN-2018		
	REF: See Workcard	AFL	HRS/MSC				5454:35		
							4722		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). PKG 4 ,2	MOS					18-SEP-2018		
	REF:	AFL	HRS/MSC 100				5608:25		
							4855		
25-60/231 (s)	OPERATIONAL TEST ELT PKG 2	MOS	12				07-JUN-2018		
	REF: See Workcard	AFL	HRS/MSC				5454:35		
							4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
25-63/23 25.020 DISCARD Expiry Date: 31-JAN-2020	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY S1820516-99 TM0000052795 REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE	TSN:0 TSN:0 TSN:0			11-NOV-2013 2854:25 2427	31-JAN-2020 M	
250005 25.070	REMOTE CONTROL PANEL 9851380817 2614874-0043 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
250010 25.050	EMERGENCY LOCATOR TRANSMITTER 9851380853 2616272-0015 REF: AMM 25-63-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
250015 25.040	IPECO PILOT SEAT 959.30.01.143 49817 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:92 TSN:0			11-JUN-2015		
250020 25.040	IPECO CO-PILOT SEAT 959.30.01.144 49921 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:92 TSN:0			11-JUN-2015		
250021	NO. 1 PASSENGER SEAT 959.30.01.617 34971 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250022	NO. 2 PASSENGER SEAT 959.30.01.618 34972 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250023	NO. 3 PASSENGER SEAT 959.30.01.618 34973 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250024	NO. 4 PASSENGER SEAT 959.30.01.634 34975 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250025	NO. 5 PASSENGER SEAT 959.30.01.641 34974 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
250026	NO. 6 PASSENGER SEAT 959.30.01.642 34976 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		
25C020	PAX SEAT LH AFSS,403150-1 9593001617 34971 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25C021	PAX SEAT RH AFSS,403150-2 9593001618 34972 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25C022	PAX SEAT LH FFSS,403150-3-B 9593001641 34974 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C023	PAX SEAT RH FFSS,403150-4-B 9593001642 34976 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25C025	PAX SEAT LH FFSS,403150-3 9593001633 34973 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25C026	PAX SEAT RH FFSS,403150-4 9593001634 34975 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25C027	ENTERTAINMENT SYSTEM INSTL 9501000440 2704004 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
25JFL02	PERFORMED FIRST AID KIT INSPECTION (DAC-AIR 348) REF:	MOS HRS/MSC AFL	12	+1m/-1m			07-JUN-2018 5454:35 4722	07-JUN-2019	07-JUL-2019
CHAPTER 26	FIRE PROTECTION								
26-20/2	COCKPIT FIRE EXTINGUISHER BA51015R-5 102431 REF: GENERIC NO REF	MOS HRS/MSC AFL	120				08-MAR-2017 4731:15 4121	08-AUG-2026	
26.010 LIFE LIMIT									
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348) BA51015R-5 102431 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			19-JUN-2018	19-JUN-2019	25-JUL-2019
26.010									
260005	FIRE/OVERHEAT DETECTOR 9751210012 207916 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
26.020									



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 27	FLIGHT CONTROLS								
27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL PKG 4 ,2	MOS HRS/MSC AFL	150				PKG 18-SEP-2018 5608:25 4855		
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES REF: GENERIC NO REF	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-00/71 27.010	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES REF: AMM 27-00-00	MOS HRS/MSC AFL	48 2000	+10%/-10% +10%/-10%			02-DEC-2015 4019:35 3491	02-DEC-2019 6019:35	26-APR-2020 6219:35
27-10/139 (s)	EXAMINE AILERON LH AND RH PKG 2,4	MOS HRS/MSC AFL	12 150				PKG 18-SEP-2018 5608:25 4855		
27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS PKG 2	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 2	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 2	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-10/394	EXAMINE - AILERON CONTROL SYSTEM REF: AMM 27-10-00	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT REF: AMM 27-10-09	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS REF: See Workcard	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
+ 27-10/444	AILERON FLIGHT CONTROL CABLES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0	20000 27000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/445	AILERON AUTOPILOT CONTROL CABLE								
	PN	MOS		TSN:0			31-OCT-2007		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0	20000	
LIFE LIMIT	REF:	AFL	27000	TSN:0			0	27000	
27-10/470	LUBRICATE AILERON CONTROL SYSTEM BEARING								
		MOS	12	+10%/-10%			07-JUN-2018	07-JUN-2019	13-JUL-2019
		HRS/MSC	1200	+10%/-10%			5454:35	6654:35	6774:35
	REF: AMM 27-10-00	AFL					4722		
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: See Workcard	AFL					4722		
27-20/140 (s)	EXAMINE RUDDER IN PARTICULAR THE COVER PLATE (PART NO. 555.40.12.215) ON THE BOTTOM OF THE RUDDER TO MAKE SURE IT IS NOT BENT AND THERE ARE NO SIGNS OF INTERFERENCE WITH THE RUDDER STOP						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	150				5608:25		
	REF: AMM 55-40-00	AFL					4855		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF:	AFL					4722		
27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF:	AFL					4722		
27-20/242	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH								
		MOS					31-OCT-2007		
		HRS/MSC	N/A				0		
	REF: AMM 20-31-00	AFL					0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 2 REF: AMM 27-25-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM REF: AMM 27-20-00	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS REF: AMM 27-20-04	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT REF: AMM 27-20-05	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER) REF: AMM 27-20-00	MOS HRS/MSC AFL	A/R				31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES								
	PN	MOS		TSN:0			31-OCT-2007		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0		20000
LIFE LIMIT	REF:	AFL	27000	TSN:0			0		27000
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES								
	PN	MOS		TSN:0			31-OCT-2007		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0		20000
LIFE LIMIT	REF:	AFL	27000	TSN:0			0		27000
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: AMM 27-30-00	HRS/MSC					5454:35		
		AFL					4722		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: AMM 27-30-00	HRS/MSC					5454:35		
		AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/334	CHECK ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR) (REF. 12-A-27-30-00-00A-903A-A)	MOS					21-SEP-2017 5017:55 4360		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R						
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM	MOS					31-OCT-2007 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000						
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					31-OCT-2007 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000						
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					31-OCT-2007 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000						
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					31-OCT-2007 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000						
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					31-OCT-2007 0 0	32500 42000	
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000						
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					31-OCT-2007 0 0	20000 27000	
LIFE LIMIT	PN SN-UNKNOWN REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0					
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					31-OCT-2007 0 0	20000 27000	
LIFE LIMIT	PN SN-UNKNOWN REF:	HRS/MSC AFL	20000 27000	TSN:0 TSN:0 TSN:0					



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/450	STICK PUSHER CABLES								
	PN	MOS		TSN:0			31-OCT-2007		
	SN-UNKNOWN	HRS/MSC	20000	TSN:0			0	20000	
LIFE LIMIT	REF:	AFL	27000	TSN:0			0	27000	
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM								
		MOS	12	+10%/-10%			07-JUN-2018	07-JUN-2019	13-JUL-2019
27.021		HRS/MSC	3000				5454:35	8454:35	
AIRWORTHINESS	REF: AMM 27-40-00	AFL					4722		
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 27-40-00	AFL					4855		
27-40/25	PITCH TRIM ACTUATOR								
	9787314203	MOS		TSO:0			11-NOV-2013		
27.020	120	HRS/MSC	O/C	TSO:0			2854:25		
	REF: GENERIC NO REF	AFL		TSO:0			2427		
27-40/252 (s)	EXAMINE HORIZONTAL STABILIZER TRIM ACTUATOR TOP AND BOTTOM ATTACHMENTS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF:	AFL					4722		
27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	129-1-1100-02	MOS	84				11-NOV-2013	10-OCT-2020 M	
	120	HRS/MSC	3400				2854:25	6254:25	
OVERHAUL	REF: AMM 27-40-01	AFL					2427		
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 4 ,2	MOS					18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 27-40-00	AFL					4855		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: AMM 27-40-00	AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/3	PITCH TRIM ACTUATOR								
27.011	129-1-1100-02	MOS					11-NOV-2013		
AIRWORTHINESS	120 REF: GENERIC NO REF	HRS/MSC AFL	20000 27000	TSN:3430:55 TSN:6329			2854:25 2427	19423:30 23098	
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS								
27.036	PN	MOS		TSN:0			31-OCT-2007		
LIFE LIMIT	SN-UNKNOWN REF: AMM 27-40-02	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0	10000	
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC AFL	100				5608:25 4855		
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC AFL	100				5608:25 4855		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC AFL					5454:35 4722		
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC AFL					5454:35 4722		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: See Workcard	HRS/MSC AFL					5454:35 4722		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT								
	9787320003	MOS					31-OCT-2007		
	644	HRS/MSC	10000	+10%/-10%			0	10000	11000
OVERHAUL	REF:	AFL	13500	+500/-500			0	13500	14000



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.040	978.73.20.309	MOS					21-SEP-2017		
OVERHAUL	1178	HRS/MSC	5000	+10%/-10%	-17:55		5017:55	10000	10500
	REF: AMM 27-50-03	AFL	7000	+500/-500			4360	11360	11860
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.040	978.73.20.309	MOS					21-SEP-2017		
OVERHAUL	0905	HRS/MSC	5000	+10%/-10%	-17:55		5017:55	10000	10500
	REF: AMM 27-50-03	AFL	7000	+500/-500			4360	11360	11860
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					21-SEP-2017		
OVERHAUL	0694	HRS/MSC	5000	+10%/-10%	-17:55		5017:55	10000	10500
	REF: AMM 27-50-03	AFL	7000	+500/-500			4360	11360	11860
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					21-SEP-2017		
OVERHAUL	0900	HRS/MSC	5000	+10%/-10%	-17:55		5017:55	10000	10500
	REF: AMM 27-50-03	AFL	7000	+500/-500			4360	11360	11860
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	9450202205	MOS					31-OCT-2007		
DISCARD	6044	HRS/MSC	10000	+500/-500			0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500			0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	9450202206	MOS					31-OCT-2007		
DISCARD	S6036	HRS/MSC	10000	+500/-500			0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500			0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	9450202205	MOS					31-OCT-2007		
DISCARD	6048	HRS/MSC	10000	+500/-500			0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500			0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	9450202206	MOS					31-OCT-2007		
DISCARD	S6037	HRS/MSC	10000	+500/-500			0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500			0	13500	14000



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/386	EXAMINE - FLAP MECHANISM								
AIRWORTHINESS	REF: AMM 27-51-00	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
AIRWORTHINESS	REF: AMM 27-51-00	MOS HRS/MSC AFL	25000 30000				31-OCT-2007 0 0	25000 30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	30000 39000				31-OCT-2007 0 0	30000 39000	
27-50/4	LEFT INBOARD FLAP ACTUATOR								
AIRWORTHINESS	REF: AMM 27-50-03	978.73.20.309 1178 MOS HRS/MSC AFL	20000 27000	TSO:0 TSN:4984:55 TSO:0 TSN:3040 TSO:0			21-SEP-2017 5017:55 4360	25017:55 31360	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
27.040	978.73.20.309	MOS		TSO:0			21-SEP-2017		
AIRWORTHINESS	0905 REF: AMM 27-50-03	HRS/MSC AFL	20000 27000	TSN:4984:55 TSO:0 TSN:3040 TSO:0			5017:55 4360	25017:55 31360	
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
27.050	978.73.20.309	MOS		TSO:0			21-SEP-2017		
AIRWORTHINESS	0694 REF: AMM 27-50-03	HRS/MSC AFL	20000 27000	TSN:5609 TSO:0 TSN:7248 TSO:0			5017:55 4360	25017:55 31360	
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
27.050	978.73.20.309	MOS		TSO:0			21-SEP-2017		
AIRWORTHINESS	0900 REF: AMM 27-50-03	HRS/MSC AFL	20000 27000	TSN:4984:55 TSO:0 TSN:3040 TSO:0			5017:55 4360	25017:55 31360	
27-50/414	LEFT HAND FLAP								
57.060	5575012003	MOS		TSN:0			31-OCT-2007		
LIFE LIMIT	762 REF: See Workcard	HRS/MSC AFL	25000 30000	TSN:0 TSN:0			0 0	25000 30000	
27-50/414	RIGHT HAND FLAP								
57.060	5575012004	MOS		TSN:0			31-OCT-2007		
LIFE LIMIT	759 REF: See Workcard	HRS/MSC AFL	25000 30000	TSN:0 TSN:0			0 0	25000 30000	
27-50/437	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS								
AIRWORTHINESS	REF: AMM 27-51-00	MOS HRS/MSC AFL	12 150	+10%/-1m +10%/-10%	-3:50		18-SEP-2018 5608:25 4855	18-SEP-2019 5754:35	24-OCT-2019 5769:35
27-50/443	SERVICE FLAP UP AND DOWN LIMIT SWITCHES								
	PKG 5,6,8,10,12,14	MOS	12	+1m/-1m			18-SEP-2018	18-SEP-2019	18-OCT-2019
	REF: AMM 12-20-07	HRS/MSC AFL	200	+10%/-10%			5608:25 4855	5808:25	5828:25
+ 27-50/451	FLAP TENSION RODS								
LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	20000 27000	TSN:0 TSN:0			31-OCT-2007 0 0	20000 27000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	9450202205 6044 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	9450202206 S6036 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	9450202205 6048 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	9450202206 S6037 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 1178 REF:	MOS HRS/MSC AFL	12 150	+1m/-1m +10%/-10%		9:30	18-SEP-2018 5608:25 4855	18-SEP-2019 5767:55	18-OCT-2019 5782:55
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0905 REF:	MOS HRS/MSC AFL	12 150	+1m/-1m +10%/-10%		9:30	18-SEP-2018 5608:25 4855	18-SEP-2019 5767:55	18-OCT-2019 5782:55
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0694 REF:	MOS HRS/MSC AFL	12 150	+1m/-1m +10%/-10%		9:30	18-SEP-2018 5608:25 4855	18-SEP-2019 5767:55	18-OCT-2019 5782:55
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0900 REF:	MOS HRS/MSC AFL	12 150	+1m/-1m +10%/-10%		9:30	18-SEP-2018 5608:25 4855	18-SEP-2019 5767:55	18-OCT-2019 5782:55



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 1178 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 6454:35 6022	07-JUL-2019 6554:35 6152
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0905 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 6454:35 6022	07-JUL-2019 6554:35 6152
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0694 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 6454:35 6022	07-JUL-2019
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0900 REF:	MOS HRS/MSC AFL	12 1000 1300	+1m/-1m +10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 6454:35 6022	07-JUL-2019 6554:35 6152
27-50/77 (s) 27.080	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013) REF: See Workcard	MOS HRS/MSC AFL	200	+10%/-10%			31-OCT-2007 0 0		
270003	HORIZONTAL TAIL ASSY 5551012037 774 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	31-OCT-2007 0 0	
270015	ELEVATOR LH ASSY 5552012039 787 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	31-OCT-2007 0 0	
270023	ELEVATOR RH ASSY 5552012040 789 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	31-OCT-2007 0 0	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318132 1603 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270033	RUDDER ASSY								
	5554012038 758 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270035	FLAP CONTROL AND WARNING (FCWU) UNIT								
27.130	20344-8 128800 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-MAR-2013 2494:05 2088		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 076044DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 1014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 076043DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 076040DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	9787318132 1575 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 076035DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m			18-SEP-2018 5608:25 4855	07-JUN-2019	M 07-JUL-2019
CHAPTER 28 FUEL									
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029	REF: AMM 28-10-01	MOS HRS/MSC AFL	1000	+10%/-10%	45:36		08-JUN-2017 4875:45 4239	5921:21	6021:21
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT						PKG		
	PKG 2,4	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
	REF: See Workcard	AFL							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N)						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
28-20/32	ELECTRIC DRIVEN FUEL PUMP								
28.010	968.84.51.108	MOS		TSO:0			05-DEC-2014		
OVERHAUL	B4307	HRS/MSC	3500	+10%/-10%	58:10		3441:50	7000	7350
	REF: AMM 28-20-03	AFL		TSO:0			2995		
28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM								
28.020		MOS	48	+10%/-10%			08-JUN-2017	08-JUN-2021	01-NOV-2021
	REF: See Workcard	HRS/MSC	1000	+10%/-10%	45:36		4875:45	5921:21	6021:21
		AFL					4239		
280005	LOW PRESSURE FUEL PUMP								
28.120	9688451108	MOS		TSN:0			31-OCT-2007		
	B4995	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
280010	FUEL FLOW TRANSMITTER								
28.130	9753512602	MOS		TSN:0			31-OCT-2007		
	2866	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301	MOS		TSN:0			31-OCT-2007		
	2033	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-08	AFL		TSN:0			0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301 2046 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280025	FUEL FILTER ASSY								
28.025	9683521001 2007FFT1419 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 1383 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3768 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4057 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	9753731231 1522 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	9753731232 1514 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	9753731233 1514 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	9753731234 1522 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	9688411405 B6637 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3751 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4102 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280080	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	9753731234 1539 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280085	FUEL QUANTITY,INNER SENSOR								
28.090	9753731233 1505 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280090	FUEL QUANTITY,CENTRAL SENSOR								
28.070	9753731232 1518 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
280095	FUEL QUANTITY,OUTER SENSOR								
28.060	9753731231 1528 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280100	RIGHT WING FUEL,BOOSTER PUMP								
28.050	9688411405 B6638 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
28C032	VALVE,CHECK								
	9630423105 1908 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
28C033	VALVE,CHECK								
	9630423105 1913 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		

CHAPTER 29 HYDRAULIC POWER

29-10/151 (s)	CHECK LOW PRESSURE FILTER BLOCKAGE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 2,4 REF: AMM 29-10-04	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG		
	PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.						PKG		
	PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12				07-JUN-2018 5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF: AMM 29-10-02	HRS/MSC AFL							
29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	HRS/MSC AFL							
29-10/418	NITROGEN ACCUMULATOR 960.30.01.291	MOS					21-SEP-2017 5017:55 4360	26304:55 31127	
29.020 LIFE LIMIT	0873H REF: AMM 29-10-02	HRS/MSC AFL	25000 30000	TSN:3713 TSN:3233					
290005	LANDING GEAR STEER SELECTOR VALVE 960.30.01.271	MOS		TSO:5			02-SEP-2016 4454:12 3851		
29.040	0830ABC REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSO:0					
290015	PRESSURE GAGE SWITCH 9738114307	MOS		TSN:0			19-JUL-2016 4366:55 3787		
29.050	0781 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0					
290025	SERVICE SELECTOR VALVE 9603001261	MOS		TSN:0			31-OCT-2007 0 0		
29.070	G0711025A REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0					
290030	PRESSURE GAUGE 9656188101	MOS		TSN:0			31-OCT-2007 0 0		
29.080	07-0418211 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0					
290035	(K 601) RELAY 974.09.26.112	MOS					19-JUL-2016 4366:55 3767		
29.090	R485 REF: GENERIC NO REF	HRS/MSC AFL	O/C						



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290040	HAND PUMP								
29.030	9688582111 774 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	9738114306 1806 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-2017 4875:45 4239		
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0720773 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS HYDRAULIC FLUID								
	960.30.02.101 262754 REF:	MOS HRS/MSC AFL	60	+6m/-6m TSN:0 TSN:0 TSN:0			02-SEP-2016 4454:20 3801	02-SEP-2021	02-MAR-2022
CHAPTER 30 ICE AND RAIN PROTECTION									
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 2,4 REF: AMM 30-10-00	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999						PKG		
	PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM						PKG		
	PKG 2 REF: AMM 30-10-00	MOS HRS/MSC AFL	12				07-JUN-2018 5454:35 4722		
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING								
30.010	REF: GENERIC NO REF	MOS HRS/MSC AFL	6 150				18-SEP-2018 5608:25 4855	18-MAR-2019 5758:25	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM SINGLE P-S SYSTEM, DUAL SYSTEM AND P-S INDICATOR MSN 321 AND 401-999 PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 2,4 REF: AMM 30-60-00	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 2,4 REF: AMM 30-60-00	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
300005 30.140	PROP DE-ICE TIMER/ CONTROLLER 4E3163-2 U0552 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-AUG-2018 5534:40 4793		
300010 30.150	LPMI LINEAR ACTUATOR 9787315302 B51216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N071380 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300020	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N064611 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300025	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N064607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300030	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N064590 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N064589 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N064586 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 3878 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N071233 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.014 U1733 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C				16-JAN-2014 2905:55 2519		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121038 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121040 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 3841 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 3838 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 3915 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 3912 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.041 NDY5820 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAR-2018 5291:50 4599		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.027 NBM2450 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			10-JUL-2013 2686:05 2282		
300100	RH INBD-WING DE-ICER BOOT								
30.040	959.89.01.023 NBD5420 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			10-JUL-2013 2686:05 2282		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.025 NDT7410 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAR-2018 5291:50 4599		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.022 NBM0160 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			10-JUL-2013 2686:05 2282		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.024 NBD5440 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			10-JUL-2013 2686:05 2282		
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"								
	REF:	MOS HRS/MSC AFL	150	+10%/-10%	4:40		18-SEP-2018 5608:25 4855	5763:05	5778:05
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
31-50/34	CAWS & CACU CLOCK BATTERY								
31.010	9728132050 0000266594 REF: AMM 31-50-03	MOS HRS/MSC AFL	24	+10%/-10%	TSN:9	55	20-APR-2018 5306 4610	14-SEP-2019	26-NOV-2019
DISCARD									
310020	FLAP POSITION INDICATOR								
31.090	9754416203 60167 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310025-1	AM-250 BARO ALTIMETER, ADC 9859911207 07050804D REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
310035 31.050	CAWS COMPUTER 9728132030 496 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			20-APR-2018 5306 4610		
310040 31.060	CAWS DISPLAY 9728132031 489 REF: AMM 31-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
310050 31.040	DIGITAL CLOCK 9996111212 1041424 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
31C035	COAX SWITCH 9859911371 10295 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
31C036	COAX SWITCH 9859911371 10288 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
CHAPTER 32 LANDING GEAR									
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 2,4 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 2 REF: AMM 32-10-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING REF:	MOS HRS/MSC AFL	25000 30000				31-OCT-2007 0 0	25000 30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				31-OCT-2007 0 0	25000 30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK REF:	MOS HRS/MSC AFL	25000 30000				31-OCT-2007 0 0	25000 30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				31-OCT-2007 0 0	25000 30000	
32-10/436 (s)	REMOVE/CLEAN MLG SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS. EXAMINE FOR CORROSION. IF CORRODED, REPLACE BOLT WITH LATEST BOLT PART NUMBER. IF NOT CORRODED, APPLY GREASE P04-028 AND INSTALL THE BOLT. PKG 2 REF: AMM 32-10-00	MOS HRS/MSC AFL	12	+10%/-10%			PKG 07-JUN-2018 5454:35 4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				05-APR-2016 4168:25 3627	05-APR-2022	
	REF: AMM 32-10-00	HRS/MSC AFL							
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				05-APR-2016 4168:25 3627	05-APR-2022	
	REF: AMM 32-10-00	HRS/MSC AFL							
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019	13-JUL-2019
32.030	REF: AMM 12-20-06	HRS/MSC AFL	T/C						
32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES	MOS	12	+1m/-1m			07-JUN-2018 5454:35 4722	07-JUN-2019 7454:35	07-JUL-2019 7654:35
32.010	REF: AMM 32-10-00	HRS/MSC AFL	2000	+10%/-10%					
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE	MOS	12				07-JUN-2018 5454:35 4722		
	PKG 2	HRS/MSC AFL							
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR	MOS	12				18-SEP-2018 5608:25 4855		
	PKG 2,4	HRS/MSC AFL	100						
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING.	MOS	12				18-SEP-2018 5608:25 4855		
	PKG 2,4	HRS/MSC AFL	100						
	REF:								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
32-20/266 (s)	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 5325012064 N/A LIFE LIMIT	MOS HRS/MSC AFL	120 11000 15000	TSN:0 TSN:0 TSN:0			21-SEP-2017 5017:55 4360	21-SEP-2027 16017:55 19360	
32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				16-APR-2013 2518:35 2146		
32-20/403	NOSE LANDING GEAR PN SN-UNKNOWN OVERHAUL	MOS HRS/MSC AFL	25000 30000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0	25000 30000	
32-20/416	NOSE LANDING GEAR DRAG LINK PN SN-UNKNOWN LIFE LIMIT	MOS HRS/MSC AFL	25000 30000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0	25000 30000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/5 (s)	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
32.020	532.20.12.296 SN-UNKNOWN REF: AMM 32-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-APR-2013 2518:35 2146		
32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 2 REF: AMM 32-30-00	MOS HRS/MSC AFL	12 100				07-JUN-2018 5454:35 4722		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
32.040 LIFE LIMIT	960.30.01.105 0843EFGH REF: AMM 32-30-01	MOS HRS/MSC AFL	25000 30000	TSN:4762:48 TSN:3791			21-SEP-2017 5017:55 4360	25255:07 30569	
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
32.040 LIFE LIMIT	960.30.01.105 0873EFGH REF: AMM 32-30-01	MOS HRS/MSC AFL	25000 30000	TSN:4762:48 TSN:3791			21-SEP-2017 5017:55 4360	25255:07 30569	
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: AMM 32-10-00	MOS HRS/MSC AFL	72				05-APR-2016 4168:25 3627	05-APR-2022	
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: AMM 32-10-00	MOS HRS/MSC AFL	72				05-APR-2016 4168:25 3627	05-APR-2022	
32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 2 REF:	MOS HRS/MSC AFL	12 100				07-JUN-2018 5454:35 4722		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 2,4 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 2	MOS	12				PKG		
	REF:	HRS/MSC AFL	100				07-JUN-2018 5454:35 4722		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 2,4	MOS	12				PKG		
	REF: AMM 12-10-04	HRS/MSC AFL	100				18-SEP-2018 5608:25 4855		
32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 2,4	MOS	12				PKG		
	REF:	HRS/MSC AFL	100				18-SEP-2018 5608:25 4855		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 2,4	MOS	12				PKG		
	REF: AMM 12-10-02	HRS/MSC AFL	100				18-SEP-2018 5608:25 4855		
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM REF: AMM 32-50-00	MOS HRS/MSC AFL	32500 42000					31-OCT-2007 0 0	32500 42000
320005	PILOT LH BRAKE MASTER CYLINDER 9594751131	MOS		TSN:0				31-OCT-2007	
32.130	5016 REF: AMM 32-40-04	HRS/MSC AFL	O/C	TSN:0 TSN:0				0 0	
320010	PILOT RH BRAKE MASTER CYLINDER 9594751131	MOS		TSN:0				31-OCT-2007	
32.130	5017 REF: AMM 32-40-04	HRS/MSC AFL	O/C	TSN:0 TSN:0				0 0	
320015	PARK BRAKE VALVE 9594751121	MOS		TSN:0				31-OCT-2007	
32.140	2522 REF: AMM 32-40-05	HRS/MSC AFL	O/C	TSN:0 TSN:0				0 0	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320020	NOSE WHEEL								
32.150	40-423 1167 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:37 TSN:1756:45 TSN:1534			20-OCT-2017 5079:50 4411		
320021	NOSE LANDING GEAR TIRE								
32.155	021-327-0 6009S00025 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-OCT-2017 5079:50 4411		
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.160	3-1543-1 2087/2207 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				09-FEB-2018 5203:45 4526		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 4155S00269 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-2018 5203:45 4526		
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.165	3-1543-1 1638 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-JUN-2018 5454:35 4722		
320025	SHIMMY DAMPER ASSY								
32.100	5322012215 346 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	025-350-0 7055S00391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-JUN-2018 5454:35 4722		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751131 5023 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751131 5030 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012249 VLG333 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012040 VLG333 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320050	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG687 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG686 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
320074	NOSE LANDING GEAR ACTUATOR								
29.060	960.30.01.111 1520A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			02-SEP-2016 4454:12 3851		
320075	LH BRAKE ASSY								
32.050	2-1674-1 0491 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-SEP-2016 4515:35 3901		
320080	RH BRAKE ASSY								
32.050	2-1674-1 0514 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			02-JUN-2016 4293:50 3729		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32C037	VALVE,PARK BRAKE,HP1457200-2 9594751121 2522 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
CHAPTER 33 LIGHTS									
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 2,4 REF: See Workcard	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 2,4 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 2,4 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
330005 33.080	DIM UNIT 9750215205 120444 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330010	DE-ICE LIGHT ASSY 9728767111 1291498 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330015	LEFT WING POWER SUPPLY, HIDL UNIT 9728769413 1265986 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 9728769413 1265987 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 34-0226010-91 SN-UNKNOWN REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			15-MAY-2012 2102:20 1778		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787332 17875 REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330035	LH WING POWER SUPPLY UNIT 9728787164 30377 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322 28290016 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAR-2016 4138:55 3599		
330045	RH WING POWER SUPPLY UNIT 04-1604-1429 30950 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C				11-FEB-2014 2932:10 2549		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 25980021 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-FEB-2014 2952:20 2564		
330055	NAVIGATION (FC), LED GREEN LIGHT								
33.050	9728787158 28717 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330060	NAVIGATION (FC), LED RED LIGHT								
33.050	9728787157 28932 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT								
33.060	03-9200-2001 25996002 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-APR-2013 2518:35 2146		
330070	NOSE LANDING GEAR TAXI LIGHT, 1X0005287-10								
	9728769421 179455-3-3 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-DEC-2016 4601:25 4018		
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10								
	03-4303-1000 30038001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-MAR-2017 4731:15 4121		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10								
	03-4303-0000 28307015 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-JUN-2015 3724:20 3219		
33JFL01 (s)	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00-00A-903A-A)								
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 150	+10%/-10% +10%/-10%			PKG 18-SEP-2018 5608:25 4855		

CHAPTER 34 NAVIGATION



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 2 REF:	MOS HRS/MSC AFL	12 100				PKG 07-JUN-2018 5454:35 4722		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
34-11/82 34.010	LEAK CHECK STATIC SYSTEM (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%			21-SEP-2017 5017:55 4360	21-SEP-2019	03-DEC-2019
34-14/83 34.020	CALIBRATION CHECK ALTIMETER (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%	72		21-SEP-2017 5017:55 4360	02-DEC-2019	13-FEB-2020
34-21/84 34.030	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348) REF: AMM 34-21-00	MOS HRS/MSC AFL	24	+10%/-10%	51		05-JAN-2018 5163:05 4492	25-FEB-2020	07-MAY-2020



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-25/85 34.040	CALIBRATION ATTITUDE HEADING REFERENCE SYSTEM (AHRS) CHECK SWING REF: AMM 34-25-00	MOS HRS/MSC AFL	24	+10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2020	19-AUG-2020
34-54/86 34.050	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+10%/-10%			21-SEP-2017 5017:55 4360	21-SEP-2019	03-DEC-2019
340005 31.020	PILOT ALTIMETER 9859911207 06010585D REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-JUL-2008		
340006	COPILOT ALTIMETER 70256N02D02 07050804D REF: AMM 34-14-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340009 34.080	NO. 1 DME/IFF ANTENNA 9848110240 261-75524 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340010 31.070	PILOT VERTICAL SPEED INDICATOR 9651615101 317978 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340015 31.080	PILOT ATTITUDE INDICATOR 504-0035-922 504003592225425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2017 4824:50 4194		
340020 34.100	MARKER ANTENNA 9848110260 101-6453 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340025	EFIS 1 SG465 SYMBOL GENERATOR								
34.300	9759632402 6145 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340026	STAND-BY ALTIMETER								
31.020	9652322101 462042 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340030	COPILOT VERTICAL SPEED INDICATOR								
31.070	9651615101 319113 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340034	EFIS 1 CONTROL_CP467 PANEL								
34.230	071-01439-3100 3698 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-SEP-2014 3298:45 2863		
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY								
34.170	066-03137-0101 5073 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				24-SEP-2018 5617:50 4861		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY								
34.170	066-03137-3100 4316 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-APR-2014 3009 2607		
340044	TRIM TRIPLE INDICATOR								
31.100	9754416204 00437 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				10-APR-2009 728:13		
340055	PILOT AIRSPEED INDICATOR								
31.110	9651213338 1044438 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340059	WITH HARM FILTER,KN63 DME								
34.200	9859911101 31073 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340060	COPILOT AIRSPEED INDICATOR								
31.110	9651213339 1045206 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 ATR2000-2586 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-AUG-2018 5534:40 4793		
340070	RADAR CONTROL PANEL								
34.240	9859911518 3068 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 5442 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:77 TSN:3008:45 TSN:2606			28-MAR-2014 3008:45 2606		
340080	NO. 2 TRANSPONDER								
34.080	9848110240 261-75722 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 84789 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	9759632482 13008 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340100	FRONT KA92 GPS ANTENNA								
34.090	9859911193 65367 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 7184 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	124210-2022-001 1104 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C				07-JUN-2018 5454:35 4722		
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	066-3034-02 15330 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-APR-2015 3575:30 3099		
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	9859911771 12078 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340130	AIR DATA COMPUTER								
34.400	9859203111 2833 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340135	MAGNETIC,STANDBY COMPASS								
34.130	9999880103 AT-816 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:76 TSN:2952:20 TSN:2564			25-FEB-2014 2952:20 2564		
340140	4206-100-V2 RADOME								
34.420	9857900003 812 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 4993 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-39016 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-39037 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 19306 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 17975 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340180	NO. 2 CAL PROM AHRS,LCR-92 UNIT								
34.390	9859911823 10080 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-14 72324 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-JUL-2018 5469:10 4735		
340195	MULTI FUNCTION DISPLAY								
34.190	066-04035-0101 9056 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C				24-SEP-2018 5617:50 4861		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	9859003045 6106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	9859003044 5375 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	9859003046 5644 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 1127 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				16-MAR-2009 705:26 522		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 7185 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 0888 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				07-JUN-2018 5454:35 4722		
340240	NO. 1 FLUX,KMT112 VALVE								
34.350	071-1052-00 83278 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-JUN-2018 5454:35 4722		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	9859911505 18205 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340250	OUTSIDE AIR TEMPERATURE PROBE								
34.250	9751120111 2333 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340255	AOA SENSOR LH UNIT								
34.330	975.44.21.423 0031 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				05-DEC-2014 3441:50 2995		
340260	NO. 2 FLUX,KMT112 VALVE								
34.350	9859911064 76157 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				13-MAR-2008 248:36 190		
340280	LEFT PITOT TUBE								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
340285	RIGHT PITOT TUBE								
	9651112302 AS07172220 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-AUG-2018 5534:40 4793		
341005	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U1682 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
341010	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U1679 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
345015	HORIZON,ARTIFICIAL								
	504-0111-930 504011193025186 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-JUN-2016 4330:20 3758		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C039	RADAR ALTIMETER,KRA405B MOD 13 9859911550 6426 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C040	GYRO,YAW RATE,KRG332 9859203151 11073 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C041	CONFIG.MODULE,071-00112-0200 9859911884 13527 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C043	INDICATOR,PICT NAV,KI525A 066-3046-07 KI525A-B99701 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-SEP-2014 3298:45 2863		
34C044	GYRO,DIRECTIONAL,KG102A 9859911063 53701 REF:	MOS HRS/MSC AFL	O/C	TSN:25 TSN:1034:16 TSN:797			09-NOV-2009 1023:06 789		
34C045	SLAVING,ACCESSORY,VERT,KA51B 985.99.11.070 KA51B-40313 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-FEB-2014 2952:20 2564		
34C046	INDICATOR VR/LC/GS,KI206 9859911303 71248 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C047	INDICATOR RMI,KI229 9859911331 13110 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C048	INDICATOR,DME,KDI574 9859911783 86062 REF:	MOS HRS/MSC AFL	O/C	TSN:74 TSN:2895:50 TSN:2509			20-DEC-2013 2895:50 2509		
34C049	ATC TRANSPONDER GTX330D-BLACK 011-00455-10 84206572 REF:	MOS HRS/MSC AFL	O/C				08-OCT-2009 992:41 756		
34C050	ATC TRANSPONDER GTX330D-BLACK 9859911369 84206622 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C051	ANTENNA,DME/IFF 9848110240 261-75747 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C052	GPS ANTENNA,CI 420-220 9859911209 143460 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
34C053	GPS ANTENNA,CI 420-220 CI420-220 382628 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2012 2316:30 1941		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m			21-SEP-2017 5017:55 4360	21-SEP-2019	21-OCT-2019
CHAPTER 35	OXYGEN								
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 4 ,2 REF:	MOS HRS/MSC AFL	100				PKG 18-SEP-2018 5608:25 4855		
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 2 REF:	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 2 REF: AMM 35-00-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
35-10/6 35.010 AIRWORTHINESS	OXYGEN BOTTLE 21507-03 ALT281-18655 REF: AMM 35-10-01	MOS HRS/MSC AFL	180	TSO:0 TSO:0 TSO:0	-108		19-FEB-2016 4104:15 3604	19-FEB-2022	
35-10/7 35.010 AIRWORTHINESS	HYDROSTATIC TEST OXYGEN BOTTLE 21507-03 ALT281-18655 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				15-FEB-2016	15-FEB-2021	
35-20/87 35.010	INSPECTION/CHECK PASSENGER OXYGEN MASKS REF: AMM 35-20-00	MOS HRS/MSC AFL	36	+10%/-10%	59		02-SEP-2016 4454:20 3851	31-OCT-2019	18-FEB-2020
350020 35.040	PILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B126280 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-SEP-2017 4647:20 3712		
350025 35.040	COPILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 SE23821 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:24 TSO:0 TSO:0			26-OCT-2017 5083:50 4413		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	9738114401 723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
350035	3-POSITION CONTROL VALVE								
35.030	9633211101 2573 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
350040	ALTITUDE SENSING SWITCH								
35.020	9738152102 R0928 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
35C054	TRANSDUCER,OXYGEN PRESS								
	9571201184 7291-3-71 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
35C055	OXYGEN GAGE ASSY.								
	5351212085 60046 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		

CHAPTER 52 DOORS

52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				18-SEP-2018 5608:25 4855		
52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG		
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 150				18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
		MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 52-10-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE								
		MOS					31-OCT-2007		
	REF: AMM 52-00-01	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN								
		MOS					31-OCT-2007		
	REF: AMM 52-10-01	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
52.010		MOS	48	+10%/-10%	90		02-SEP-2016	01-DEC-2020	25-APR-2021
	REF: See Workcard	HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
		AFL					3851		
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 52-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK	MOS	12				18-SEP-2018		
	PKG 2,4	HRS/MSC	100				5608:25		
	REF:	AFL					4855		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS	MOS	12				18-SEP-2018		
	PKG 2,4	HRS/MSC	100				5608:25		
	REF: AMM 52-30-00	AFL					4855		
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT	MOS	12				18-SEP-2018		
	PKG 2,4	HRS/MSC	100				5608:25		
	REF:	AFL					4855		
52-30/274 (s)	EXAMINE CARGO DOOR	MOS	12				07-JUN-2018		
	PKG 2	HRS/MSC					5454:35		
	REF:	AFL					4722		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 52-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE	MOS					31-OCT-2007		
		HRS/MSC	32500				0		32500
	REF: See Workcard	AFL	42000				0		42000
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN	MOS					31-OCT-2007		
		HRS/MSC	25000				0		25000
	REF: AMM 52-30-01	AFL	30000				0		30000



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS		TSN:0			31-OCT-2007		
52.020	SN-UNKNOWN	HRS/MSC	13000	TSN:0			0	13000	
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000	TSN:0			0	17000	
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED								
		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
52.030		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: See Workcard	AFL					3851		
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: AMM 52-70-00	AFL					4722		
520005	PASSENGER DOOR								
	5520512007	MOS		TSN:0			31-OCT-2007		
52.050	757	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-10-01	AFL		TSN:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
	5520512010	MOS		TSN:0			31-OCT-2007		
52.040	757	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-30-01	AFL		TSN:0			0		
520015	EMERGENGY 6 SERIE EXIT								
	5520512009	MOS		TSN:0			31-OCT-2007		
52.060	757	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 53	FUSELAGE								
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF:	AFL					4855		
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF:	AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					31-OCT-2007		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: AMM 53-20-02	HRS/MSC					5454:35		
		AFL					4722		
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS					31-OCT-2007		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	28300 37000				0 0	28300 37000	
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC AFL	30000 39000				0 0	30000 39000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/361	EDDY CURRENT INSPECTION	FRAMES 41 AND 43	STABILIZER ATTACHMENT						
AIRWORTHINESS	REF: See Workcard	MOS					31-OCT-2007		
		HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/419	EDDY CURRENT INSPECTION	FRAME 40							
		MOS					31-OCT-2007		
		HRS/MSC	32500				0		32500
	REF: See Workcard	AFL	42000				0		42000
53-00/9	STRUCTURAL LIMITATION	FUSELAGE AND ASSOCIATED	STRUCTURE						
53.010		MOS					31-OCT-2007		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: GENERIC NO REF	AFL					3851		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: GENERIC NO REF	AFL					3851		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: GENERIC NO REF	AFL					3851		
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: GENERIC NO REF	AFL					3851		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
		HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
	REF: GENERIC NO REF	AFL					3851		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
530005	FUS ASPC12 10 SERIE A T-1/2 ASSY								
53.080	5530512112 757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
CHAPTER 55 STABILIZERS									
270030	FIN ASSY								
	5553012038 757 REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				31-OCT-2007 0 0	20000 27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	N/A				31-OCT-2007 0 0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 2,4 REF:	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT								
	PKG 2 REF: AMM 55-00-00	MOS HRS/MSC AFL	12				PKG 07-JUN-2018 5454:35 4722		
55-10/415	HORIZONTAL STABILIZER								
LIFE LIMIT	PN SN-UNKNOWN REF: AMM 55-10-01	MOS HRS/MSC AFL	25000 30000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0	25000 30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		90	02-SEP-2016 4454:20 3851	01-DEC-2020 8454:20	25-APR-2021 8854:20



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
		AFL					3851		
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
55-30/199 (s)	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					31-OCT-2007		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					31-OCT-2007		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/373	EXAMINE - RUDDER	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					31-OCT-2007		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				0 0	32500 42000	
CHAPTER 56	WINDOWS								
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF: AMM 56-00-00	HRS/MSC AFL	100				5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/14	REPLACE LEFT HAND WINDSHIELD (INNER LAMINATION CRACKED) 9598110109 17363H5077 REF:	MOS HRS/MSC AFL	A/R						
56-11/14	REPLACE RIGHT HAND WINDSHIELD (INNER LAMINATION CRACKED) 9598110108 07083H9816 REF:	MOS HRS/MSC AFL	A/R				31-OCT-2007 0 0		
56-11/15	- LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 17363H5077 REF:	MOS HRS/MSC AFL	A/R						
56-11/15	- RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110108 07083H9816 REF:	MOS HRS/MSC AFL	A/R				31-OCT-2007 0 0		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500	40		21-SEP-2017 5017:55 4360	31-OCT-2027 16017:55	30-APR-2028 16517:55
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS REF: See Workcard	MOS HRS/MSC AFL	32500 42000				31-OCT-2007 0 0	32500 42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 2,4 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560015	SIDE,LH WINDOW								
56.090	9598110111 07031H4346 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560020	SIDE,RH WINDOW								
56.090	9598110112 07123H4690 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029 6952 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029 6953 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 6955 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 6956 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 6957 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 6936 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 6938 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 6944 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 6948 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412091 7190H2487 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
561010	LEFT HAND WINDSHIELD								
56.010 AIRWORTHINESS	9598110109 17363H5077 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-APR-2018 5306 4610		
561011	RIGHT HAND WINDSHIELD								
56.010 AIRWORTHINESS	9598110108 07083H9816 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				31-OCT-2007 0 0	20000 27000	
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				31-OCT-2007 0 0	20000 27000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES PKG 2,4	MOS	12				PKG 18-SEP-2018 5608:25 4855		
	REF:	HRS/MSC AFL	100						
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	HRS/MSC AFL							
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	HRS/MSC AFL							
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	HRS/MSC AFL							
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					31-OCT-2007		
AIRWORTHINESS	REF:	HRS/MSC AFL	N/A				0 0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					31-OCT-2007		
AIRWORTHINESS	REF:	HRS/MSC AFL	N/A				0 0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC AFL	30000 39000				0 0	30000 39000	
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT	MOS					31-OCT-2007		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					31-OCT-2007		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/412	EXAMINE WING TIPS	MOS					31-OCT-2007		
	REF: AMM 57-33-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					31-OCT-2007		
	REF: See Workcard	HRS/MSC AFL	25000 30000				0 0	25000 30000	
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-OCT-2007		
	REF:	HRS/MSC AFL	16000 22500				0 0	16000 22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		90	02-SEP-2016	01-DEC-2020	25-APR-2021
57.020	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			4454:20 3851	8454:20	8854:20



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%			02-SEP-2016	01-DEC-2020	25-APR-2021
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4454:20	8454:20	8854:20
		AFL					3851		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040		MOS	120	+6m/-6m			21-SEP-2017	31-OCT-2027	30-APR-2028
	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			5017:55	16017:55	16517:55
		AFL					4360		
57-60/393	EXAMINE LEFT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS					31-OCT-2007		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/411	EXAMINE AILERON TRIM TAB								
	REF: AMM 57-60-04	MOS					31-OCT-2007		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512016	MOS		TSN:0			31-OCT-2007		
	2757	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-60-01	AFL		TSN:0			0		
570015	WING RE 10A SERIE STRUCTURE								
57.070	5570512132	MOS		TSN:0			31-OCT-2007		
	759	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
570025	AILERON LH 10A SERIE ASSY								
57.050	5570512015	MOS		TSN:0			31-OCT-2007		
	2757	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-60-01	AFL		TSN:0			0		
570035	WING LE 10A SERIE STRUCTURE								
57.070	5570512131	MOS		TSN:0			31-OCT-2007		
	759	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

CHAPTER 61 PROPELLERS/PROPULSORS



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS PKG 2	MOS	12				PKG 07-JUN-2018 5454:35 4722		
	REF:	AFL							
61PR1	NO. 1 PROPELLER HC-E4A-3D/D10477SK	MOS					04-AUG-2018 5534:40 4793		
61.PR1	KX456 REF: AMM 61-10-01	HRS/MSC AFL	PP/C	TSN:5559:54					
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
612010	NO. 1 ENGINE - PROPELLER GOVERNOR 8210-137	MOS		TSO:43			28-JUL-2017	18-DEC-2025 M	
	12101732	HRS/MSC	3500	+500	TSN:6063:20		4609:40	(6066:20) 6436:55	6566:20
OVERHAUL	REF: GENERIC NO REF	ENC			TSO:2049:28 TSO:1764		3698		
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 210949C	MOS		TSO:0	-1310		08-JUN-2016	(5633:47) 6004:22	6133:47
	15280017	HRS/MSC	3500	+500	TSO:1805:48		3939:35		
OVERHAUL	REF: GENERIC NO REF	ENC					3141		
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX456 Part # HC-E4A-3D/D10477SK									
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS	72				05-JUN-2018	05-JUN-2024	
		HRS/MSC	4000				5484:15	(9484:15) 9459:01	
OVERHAUL	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS	12	+1m/-1m			18-SEP-2018	18-SEP-2019	18-OCT-2019
		HRS/MSC	300	+10%/-10%			5633:39	(5933:39) 5908:25	5963:39
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS	12	+1m/-1m			18-SEP-2018	18-SEP-2019	18-OCT-2019
		HRS/MSC	300	+10%/-10%			5633:39	(5933:39) 5908:25	5963:39
	REF:								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE E10477SK K47382 REF: GENERIC NO REF	MOS HRS/MSC	O/C				23-SEP-2013 3011:55		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE E10477SK K47384 REF: GENERIC NO REF	MOS HRS/MSC	O/C				23-SEP-2013 3011:55		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE E10477SK K47383 REF: GENERIC NO REF	MOS HRS/MSC	O/C				23-SEP-2013 3011:55		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE E10477SK K47380 REF: GENERIC NO REF	MOS HRS/MSC	O/C				23-SEP-2013 3011:55		

CHAPTER 71 POWER PLANT

71-00/101	OPERATIONAL TEST POWER PLANT TORQUE LIMITER	MOS HRS/MSC AFL	12 450	+10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 5904:35	13-JUL-2019
71.010	REF: See Workcard								
71-00/102	OPERATIONAL TEST POWER PLANT PERFORMANCE	MOS HRS/MSC AFL	12 450	+10%/-10% +10%/-10%			07-JUN-2018 5454:35 4722	07-JUN-2019 5904:35	13-JUL-2019
71-00/103	PERFORM COMPRESSOR & TURBINE WASH	MOS HRS/MSC AFL	150	+10%/-10%	4:40		18-SEP-2018 5608:25 4855	5763:05	5778:05
71-00/107	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS	MOS HRS/MSC AFL	12 150	+10%/-10% +10%/-10%			18-SEP-2018 5608:25 4855	18-SEP-2019 5758:25	24-OCT-2019 5773:25
71.030	REF: AMM 71-00-03								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
	571.20.12.036	MOS		TSN:0			31-OCT-2007		
71.050	772	HRS/MSC	20000	TSN:0			0		20000
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000	TSN:0			0		27000
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS								
		MOS					31-OCT-2007		
71.050		HRS/MSC	11000				0		11000
AIRWORTHINESS	REF: AMM 71-00-04	AFL					0		
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF: AMM 71-00-00	AFL					4855		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC	100				5454:35		
	REF:	AFL					4722		
71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF:	AFL					4855		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
		HRS/MSC	100				5608:25		
	REF:	AFL					4855		
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT						PKG		
	PKG 2	MOS	12				07-JUN-2018		
		HRS/MSC					5454:35		
	REF: AMM 71-00-00	AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		TSN:3			22-JUN-2016		
	9102	HRS/MSC	4000/E/C +1000	TSN:0			4310:10	8310:10	9310:10
	REF: AMM 71-00-01	AFL		TSN:0			3742		
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		TSN:2			22-JUN-2016		
	9194	HRS/MSC	4000/E/C +1000	TSN:0			4310:10	8310:10	9310:10
	REF: AMM 71-00-01	AFL		TSN:0			3742		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		TSN:3			22-JUN-2016		
	9105	HRS/MSC	4000/E/C +1000	TSN:0			4310:10	8310:10	9310:10
	REF: AMM 71-00-01	AFL		TSN:0			3742		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409	MOS		TSN:3			22-JUN-2016		
	9099	HRS/MSC	4000/E/C +1000	TSN:0			4310:10	8310:10	9310:10
	REF: AMM 71-00-01	AFL		TSN:0			3742		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		TSN:2			22-JUN-2016		
	9195	HRS/MSC	4000/E/C +1000	TSN:0			4310:10	8310:10	9310:10
	REF: AMM 71-00-01	AFL		TSN:0			3742		
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT								
		MOS					31-OCT-2007		
		HRS/MSC	26600				0	26600	
AIRWORTHINESS	REF: AMM 71-00-05	AFL	35000				0	35000	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
710005	UPPER LH ENGINE VIBRATION ISOLATOR								
71.070	5712012106	MOS		TSN:0			31-OCT-2007		
	3236	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR								
71.080	5712012106	MOS		TSN:0			31-OCT-2007		
	3235	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR								
71.090	5712012106	MOS		TSN:0			31-OCT-2007		
	3240	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
710035	LOWER LH ENGINE VIBRATION ISOLATOR								
71.100	5712012106	MOS		TSN:0			31-OCT-2007		
	3232	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	5712012106	MOS		TSN:0			31-OCT-2007		
	3237	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
710050	ENGINE MOUNT (WELDED)								
	5712012036	MOS		TSN:0			31-OCT-2007		
	772	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE PT6A-67B	MOS					22-JUN-2016		
71.EN1	PCE-PR0740 REF: AMM 71-00-01	HRS/MSC AFL	E/C	TSN:3939:35			4310:10 3742		
71JFL02	PERFORM ENGINE RUN-UP	MOS					23-NOV-2010		
	REF:	HRS/MSC AFL	A/R				1424:31 1115		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
710011	NO. 1 ENGINE - OVERHAUL	MOS					08-JUN-2016		
	REF: GENERIC NO REF	HRS/MSC ENC	3500	+500			3939:35 3141	(7439:35) 7810:10	7939:35
710021	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					08-JUN-2016		
	REF: EMM 72-00-00	HRS/MSC ENC	1750	+250			3939:35 3141	(5689:35) 6060:10	5939:35
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					07-JUN-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	400	+50			5084 4063	(5484) 5854:35	5534
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					18-SEP-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	150	+10%/-10%			5237:50 4196	(5387:50) 5758:25	5402:50
710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION	MOS					29-JUL-2011		
	REF: EMM 71-00-00	HRS/MSC ENC	A/R				1724:01 1326		
710053	NO. 1 ENGINE - AIR INLET HOUSING CORROSION INSPECTION	MOS					11-NOV-2013		
	REF:	HRS/MSC ENC					2625:35 2066		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710061	NO. 1 ENGINE - PERFORM	ENGINE	CONDITION TREND MONITORING (ECTM)						
		MOS					18-SEP-2018		
	REF: GENERIC NO REF	HRS/MSC	150	+10%/-10%		4:40	5237:50	(5392:30) 5763:05	5407:30
		ENC					4196		
710100 (s)	NO. 1 ENGINE - CORROSION INHIBITION PROCEDURE ON INLET CASE								
		MOS	12				05-APR-2016		
	REF: EMM 72-00-00	HRS/MSC	150				3939:35		
		ENC							
CHAPTER 72	ENGINE								
ENGINE NO. 1	Model : PT6A-67B	Serial #	PCE-PR0740	Part #	3042200				
720010	NO. 1 ENGINE - GAS GENERATOR MODULE								
	PN	MOS			TSO:0		08-JUN-2016		
	SN-UNKNOWN	HRS/MSC	3500	+500	TSO:0		3939:35	(7439:35) 7810:10	7939:35
OVERHAUL	REF: GENERIC NO REF	ENC			TSO:0		3141		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL								
		MOS					(EBT)		
	REF: EMM 72-00-00	HRS/MSC	A/R						
		ENC							
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP								
		MOS					(EBT)		
	REF: EMM 72-60-00	HRS/MSC	A/R						
		ENC							
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS								
		MOS					(EBT)		
	REF: EMM 72-11-00	HRS/MSC	A/R						
		ENC							
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR								
	3039001	MOS			TSN:0		31-OCT-2007		
	TXA1B2910	HRS/MSC			TSN:0		0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000		TSN:0		0	(24000) 24659	



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA113368	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		(24000) 24659
LIFE LIMIT	REF: GENERIC NO REF								
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040952 EAAB000A956	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		(24000) 24659
LIFE LIMIT	REF: GENERIC NO REF								
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000B103	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		(24000) 24659
LIFE LIMIT	REF: GENERIC NO REF								
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAA000A640	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		(24000) 24659
LIFE LIMIT	REF: GENERIC NO REF								
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAB000B490	MOS HRS/MSC ENC	24000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0		(24000) 24659
LIFE LIMIT	REF: GENERIC NO REF								
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 YUAA009A908	MOS HRS/MSC ENC	8000	TSN:1563			08-JUN-2016 3939:35 3141		(9578) 10237
LIFE LIMIT	REF: GENERIC NO REF								
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES 3036898 EAAB000B490	MOS HRS/MSC ENC	5000				22-JUN-2016 3939:35 3306		(8939:35) 9310:10
LIFE LIMIT	REF: GENERIC NO REF								
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A00365FP	MOS HRS/MSC ENC	15000	TSN:1477			08-JUN-2016 3939:35 3141		(16664) 17323
LIFE LIMIT	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 A0027CH3 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			31-OCT-2007 0 0	(15000) 15659	
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+1000 TSO:0 TSO:0 TSO:0			08-JUN-2016 3939:35 3141	(7439:35) 7810:10	8439:35
CHAPTER 73 ENGINE FUEL AND CONTROL									
73C058	FUEL,PUMP,3040760 968.20.11.430 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				12-AUG-2009 921:21 697		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
731010	NO. 1 ENGINE - FUEL PUMP (ARGOTEC) 825601-5 4475 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	+500 TSO:0 TSO:0 TSO:0			08-JUN-2016 3939:35 3141	(7439:35) 7810:10	7939:35
731024	NO. 1 ENGINE - FUEL NOZZLE 3119855-01 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C				07-JUN-2018 5084 4063		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	400	+50 -36:40			07-JUN-2018 5084 4063	(5447:20) 5817:55	5497:20
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3244882-2 C50806 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500 TSO:0 TSO:0 TSO:0			08-JUN-2016 3939:35 3141	(7439:35) 7810:10	7939:35



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 4475 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			07-JUN-2018 5084 4063	(5684) 6054:35	5744
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA30092 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500			08-JUN-2016 3939:35 3141	(7439:35) 7810:10	7939:35
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 9959524607 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500			08-JUN-2016 3939:35 3141	(7439:35) 7810:10	7939:35
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-041-01 12297407 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500		-1310	08-JUN-2016 3939:35 3141	(5633:47) 6004:22	6133:47
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS 8063-041-01 12297407 REF: GENERIC NO REF	MOS HRS/MSC ENC	4000				08-JUN-2016 3939:35	(6133:45) 6504:20	
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	150	+10%/-10%			18-SEP-2018 5237:50 4196	(5387:50) 5758:25	5402:50
731155	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER - DISCARD 3059779-01 SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%		57:40	18-SEP-2018 5237:50 4196	(5895:30) 6266:05	5955:30
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			08-JUN-2017 4505:10 3591	(5405:10) 5775:45	5495:10



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 1	MOS HRS/MSC ENC	150	+10%/-10%			PKG 18-SEP-2018 5237:50 4196		
	REF: See Workcard								
CHAPTER 74 IGNITION									
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 2,4	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
	REF: AMM 74-00-00								
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
740010	NO. 1 ENGINE - IGNITION EXCITER 10-381550-4 NNA13310137	MOS HRS/MSC ENC	3500	+500			22-JUN-2016 3939:35 3141	(7439:35) 7810:10	7939:35
	REF: EMM 74-10-00								
740015 (s)	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION PKG 1	MOS HRS/MSC ENC	150	+10%/-10%			PKG 18-SEP-2018 5237:50 4196		
	REF: EMM 74-10-00								
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG CH34055 SN-UNKNOWN	MOS HRS/MSC ENC	O/C				09-APR-2010 1128:01 862		
	REF: GENERIC NO REF								
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION	MOS HRS/MSC ENC	150	+10%/-10%		4:40	18-SEP-2018 5237:50 4196	(5392:30) 5763:05	5407:30
	REF: EMM 74-20-00								
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG CH34055 SN-UNKNOWN	MOS HRS/MSC ENC	O/C				09-APR-2010 1128:01 862		
	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION	MOS					18-SEP-2018		
	REF: EMM 74-20-00	HRS/MSC ENC	150	+10%/-10%		4:40	5237:50 4196	(5392:30) 5763:05	5407:30
CHAPTER 75 AIR									
75C059	VALVE ASSY.,3123532-01B								
	9682013191	MOS					31-OCT-2007		
	AHX008466	HRS/MSC	O/C				0		
	REF:	AFL					0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE								
	3059835-01	MOS					08-JUN-2016		
	AHX008466	HRS/MSC	3500	+500			3939:35	(7439:35) 7810:10	7939:35
	REF: GENERIC NO REF	ENC					3141		
CHAPTER 76 ENGINE CONTROLS									
76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM)						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE.						PKG		
	PKG 4 ,2	MOS					18-SEP-2018		
	REF: AMM 76-10-00	HRS/MSC	100				5608:25		
		AFL					4855		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF: See Workcard	HRS/MSC					5454:35		
		AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 2,4	MOS	12				PKG 18-SEP-2018 5608:25 4855		
	REF:	AFL	100				4855		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES	MOS	12	+1m/-1m			07-JUN-2018	07-JUN-2019	07-JUL-2019
76.010	REF: AMM 76-10-02	HRS/MSC	3000	+10%/-10%			5454:35 4722	8454:35	8754:35
	AFL								
760015	MANUAL OVERRIDE CABLE ASSY.	MOS					31-OCT-2007		
76.020	9419411417 20070042 REF: GENERIC NO REF	HRS/MSC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	AFL								
760020	CONDITION CABLE ASSY.	MOS					31-OCT-2007		
76.030	9419411418 20070049 REF: GENERIC NO REF	HRS/MSC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	AFL								
760025	POWER CONTROL CABLE ASSY.	MOS					31-OCT-2007		
76.040	9419411419 20070044 REF: GENERIC NO REF	HRS/MSC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	AFL								
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200									
761011 (s)	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES	MOS					PKG 18-SEP-2018 5237:50 4196		
	PKG 1	HRS/MSC	150	+10%/-10%			4196		
	REF: EMM 72-00-00	ENC							
CHAPTER 77 ENGINE INDICATING									
77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM	MOS	12				PKG 18-SEP-2018 5608:25 4855		
	PKG 2,4	HRS/MSC	100				4855		
	REF: See Workcard	AFL							



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	IPT-51DFP-1000-70D 7765-6-537 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2012 2316:30 1941		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	9752115219 10844216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-JUN-2018 5454:35 4722		
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.034 453 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-APR-2016 4168:25 3627		

ENGINE NO. 1	Model : PT6A-67B	Serial # PCE-PR0740	Part # 3042200
--------------	------------------	---------------------	----------------

771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NRA008060 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-JUN-2016 3939:35 3141		

CHAPTER 78	EXHAUST
-------------------	----------------

78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF:	HRS/MSC	100				5608:25		
		AFL					4855		

CHAPTER 79	OIL
-------------------	------------

79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY.						PKG		
	PKG 2,4	MOS	12				18-SEP-2018		
	REF: AMM 24-00-00	HRS/MSC	100				5608:25		
		AFL					4855		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 2	MOS	12				07-JUN-2018		
	REF:	HRS/MSC					5454:35		
		AFL					4722		



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 2,4 REF: AMM 79-30-01	MOS HRS/MSC AFL	12 100				PKG 18-SEP-2018 5608:25 4855		
79-20/43 79.010	OIL COOLER 968.32.14.102 T0760 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+500			28-AUG-2015 3871:05 3335	7371:05	7871:05
790005 79.020	TEMPERATURE BULB 9751120101 142031 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
790020 79.030	PRESSURE,GAGE SWITCH 9738114305 802 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
790025 79.040	THERMAL ACTUATOR 9787301002 935 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
790030 79.050	POWER ODM,B049913 MODULE 9752115240 43979 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		
79C060	SENSOR MODULE,ODM,B057185 REV.D 9752115242 43861 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2007 0 0		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0740 Part # 3042200

790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS HRS/MSC ENC	A/R				28-JUL-2010 1285:04 980		
DISCARD	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 855 (LX-JFN): 5763:15 HRS, 4974 AFL as of 30-Dec-2018

Owner/Operator: JETFLY AVIATION SA

Report Date: 03-JAN-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790031 (s)	NO. 1 ENGINE - CHECK PKG 1 REF: EMM 79-20-02	MAGNETIC CHIP DETECTOR MOS HRS/MSC ENC	150	+10%/-10%			PKG 18-SEP-2018 5237:50 4196		
790040	NO. 1 ENGINE - BRIDGE CHECK REF: EMM 79-20-02	MAGNETIC CHIP DETECTOR MOS HRS/MSC ENC	12 600	+1m/-1m +10%/-10%			05-JAN-2018 4792:30 3833	05-JAN-2019 (5392:30) 5763:05	05-FEB-2019 5452:30
790050	NO. 1 ENGINE - REPLACE REF: EMM 79-20-02	OIL FILTER ELEMENT MOS HRS/MSC ENC	900	+10%/-10%			05-JAN-2018 4792:30 3833	(5692:30) 6063:05	5782:30
790060 (s)	NO. 1 ENGINE - INSPECT PKG 1 REF: See Workcard	CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN MOS HRS/MSC ENC	150	+10%/-10%			PKG 18-SEP-2018 5237:50 4196		
790070	NO. 1 ENGINE - CHECK REF: EMM 72-60-00	SCAVENGE OIL PUMP INLET SCREEN MOS HRS/MSC ENC	900	+10%/-10%			08-JUN-2017 4505:10 3591	(5405:10) 5775:45	
790080 (s)	NO. 1 ENGINE - PERFORM REF: EMM 79-20-02	AN OIL SAMPLE MOS HRS/MSC ENC	150	+10%/-10%			18-MAY-2008 328:18 266		