

**OWNER:** HUMMINGBIRD AVIATION SERVICES  
**ADDRESS:** TEGELUDDSVAGEN 76  
 STOCKHOLM 115 28  
**PHONE:**  
**FAX:**

**OPERATOR:** HUMMINGBIRD AVIATION SERVICES  
**ADDRESS:** TEGELUDDSVAGEN 76  
 STOCKHOLM 115 28  
**PHONE:**  
**FAX:**

**ANALYST:** PASCAL GHANAME +33 (0) 1.55.93.45.80 (OFFICE)  
**EMAIL:** PASCAL.GHANAME@CAMPSYSTEMS.EU +33 (0) 1.53.01.66.18 (EFAX-CARDS)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 525-0519/SE-RMH **MODEL:** 525 - CJ1 **MANUFACTURER:** TEXTRON AVIATION INC.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 23-SEP-2003		1549:42 A/C HRS	as of 21-MAR-2019	_____ A/C HRS	as of ____/____/____
		1137 AFL	as of 21-MAR-2019	_____ AFL	as of ____/____/____
		480:06 ACH	as of 01-MAR-2019	_____ ACH	as of ____/____/____

**ENGINE NO. 1 SERIAL/PART:** 2057/45700-104 **MODEL:** FJ44-1A **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 23-SEP-2003		LAST ACTUALS		CURRENT ACTUAL	
7 ENG. HRS	7 A/C HRS	1549:42 ENG. HRS	as of 21-MAR-2019	_____ ENG. HRS	as of ____/____/____
ENC		1137 ENC	as of 21-MAR-2019	_____ ENC	as of ____/____/____

**ENGINE NO. 2 SERIAL/PART:** 2058/45700-104 **MODEL:** FJ44-1A **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 23-SEP-2003		LAST ACTUALS		CURRENT ACTUAL	
7 ENG. HRS	7 A/C HRS	1549:42 ENG. HRS	as of 21-MAR-2019	_____ ENG. HRS	as of ____/____/____
ENC		1137 ENC	as of 21-MAR-2019	_____ ENC	as of ____/____/____

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>								
5-12-01	INSPECTION DOCUMENT 01								
	PKG 1	MOS					23-NOV-2018		
		HRS/MSC	300	+30			1483	1783	1813
	REF: TLMC 5-12-01	AFL					1083		
5-12-02	INSPECTION DOCUMENT 02								
	PKG 2	MOS	12	+2m			23-NOV-2018	30-NOV-2019	23-JAN-2020
		HRS/MSC					1483		
	REF: TLMC 5-12-02	AFL					1083		
5-12-04 (s)	INSPECTION DOCUMENT 04 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 4	MOS	36	+2m			19-DEC-2014		
		HRS/MSC					1027		
	REF: TLMC 5-12-04	AFL					740		
5-12-05 (s)	INSPECTION DOCUMENT 05 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 5	MOS	60	+2m			23-SEP-2003		
		HRS/MSC					0		
	REF: TLMC 5-12-05	AFL					0		
5-12-06 (s)	INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 8	MOS	72	+2m			23-SEP-2003		
		HRS/MSC					0		
	REF: TLMC 5-12-06	AFL					0		
5-12-07 (s)	INSPECTION DOCUMENT 07 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 9	MOS	144	+2m			23-SEP-2003		
		HRS/MSC					0		
	REF: TLMC 5-12-07	AFL					0		
5-12-08	INSPECTION DOCUMENT 08								
	PKG 10	MOS	24	+2m			17-APR-2018	30-APR-2020	17-JUN-2020
		HRS/MSC	300	+30			1422:54	1722:54	1752:54
	REF: TLMC 5-12-08	AFL					1033		
5-12-09 (s)	INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 11	MOS	4	+2m			16-AUG-2018		
		HRS/MSC	200	+30			1450:30		
	REF: TLMC 5-12-09	AFL					1057		
5-12-10	INSPECTION DOCUMENT 10								
	PKG 12	MOS	36	+2m			01-MAR-2019	31-MAR-2022	01-MAY-2022
		HRS/MSC	1200	+30			1516:10	2716:10	2746:10
	REF: TLMC 5-12-10	AFL					1110		
5-12-11	INSPECTION DOCUMENT 11								
	PKG 13	MOS	36	+2m			26-OCT-2017	31-OCT-2020	26-DEC-2020
		HRS/MSC	1200	+30			1366:36	2566:36	2596:36
	REF: TLMC 5-12-11	AFL					993		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-12	INSPECTION DOCUMENT 12 - A/C NOT BEING OPERATED UNDER FAA PART 91, THEREFORE, AS PER SM CAP 02 A 1 MONTH TOLERANCE CAN BE USED.							
	PKG 14	MOS	12		-28	23-NOV-2018	<b>31-OCT-2019</b>	
		HRS/MSC				1483		
	REF: TLMC 5-12-12	AFL				1083		
5-12-13 (s)	INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)						<b>AIRWORTHINESS</b>	
	PKG 15	MOS	24			08-APR-2016		
		HRS/MSC				1123:34		
	REF: TLMC 5-12-13	AFL				809		
5-12-14 (s)	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)							
	PKG 16	MOS				23-SEP-2003		
		HRS/MSC	A/R			0		
	REF: TLMC 5-12-14	AFL				0		
5-12-18	INSPECTION DOCUMENT 18							
	PKG 33	MOS				23-NOV-2018		
		HRS/MSC	150	+30		1483	<b>1633</b>	1663
	REF: TLMC 5-12-18	AFL				1083		
5-12-21	INSPECTION DOCUMENT 21							
	PKG 34	MOS	24	+2m		17-APR-2018	<b>30-APR-2020</b>	17-JUN-2020
		HRS/MSC	600	+30		1422:54	<b>2022:54</b>	2052:54
	REF: TLMC 5-12-21	AFL				1033		
5-12-22 (s)	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)							
	PKG 36	MOS				08-APR-2016		
		HRS/MSC	300	+30		1123:34		
	REF: TLMC 5-12-22	AFL				809		
5-12-29	INSPECTION DOCUMENT 29							
	PKG 43	MOS				23-SEP-2003		
		HRS/MSC	7200	+30		0	<b>7200</b>	7230
	REF: TLMC 5-12-29	AFL				0		
5-12-33	INSPECTION DOCUMENT 33							
	PKG 47	MOS	12	+2m		23-NOV-2018	<b>30-NOV-2019</b>	23-JAN-2020
		HRS/MSC	300	+30		1483	<b>1783</b>	1813
	REF: TLMC 5-12-33	AFL				1083		
5-12-34	INSPECTION DOCUMENT 34 (NOT CURRENTLY USED)							
	PKG 48	MOS				23-SEP-2003		
		HRS/MSC	N/R			0		
	REF:	AFL				0		
		ACH				0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-35	INSPECTION DOCUMENT 35 (NOT CURRENTLY USED)								
	PKG 49	MOS					23-SEP-2003		
		HRS/MSC	N/R				0		
	REF:	AFL					0		
		ACH					0		
5-12-36	INSPECTION DOCUMENT 36							<b>AIRWORTHINES</b>	
	PKG 2201	MOS	6				23-NOV-2018	<b>S</b>	23-JUL-2019
		HRS/MSC		+2m			1483	<b>31-MAY-2019</b>	
	REF: TLMC 5-12-36	AFL					1083		
5-12-MA	INSPECTION DOCUMENT MA							<b>AIRWORTHINES</b>	
	PKG 50	MOS					23-NOV-2018	<b>S</b>	
		HRS/MSC	300				1483	<b>1783</b>	
	REF: TLMC 5-12-MA	AFL					1083		
5-12-MD	INSPECTION DOCUMENT MD							<b>AIRWORTHINES</b>	
	PKG 52	MOS					23-SEP-2003	<b>S</b>	
		HRS/MSC					0		
	REF: TLMC 5-12-MD	AFL	5000				0	<b>5000</b>	
5-12-MF	INSPECTION DOCUMENT MF							<b>AIRWORTHINES</b>	
	PKG 54	MOS					23-SEP-2003	<b>S</b>	
		HRS/MSC	6000				0	<b>6000</b>	
	REF: TLMC 5-12-MF	AFL					0		
5-12-MG	INSPECTION DOCUMENT MG							<b>AIRWORTHINES</b>	
	PKG 55	MOS					23-SEP-2003	<b>S</b>	
		HRS/MSC	6000				0	<b>6000</b>	
	REF: TLMC 5-12-MG	AFL					0		
5-12-MH	INSPECTION DOCUMENT MH							<b>AIRWORTHINES</b>	
	PKG 56	MOS					04-AUG-2008	<b>S</b>	
		HRS/MSC	3000				679	<b>3679</b>	
	REF: TLMC 5-12-MH	AFL							
5-12-MI	INSPECTION DOCUMENT MI							<b>AIRWORTHINES</b>	
	PKG 57	MOS					23-SEP-2003	<b>S</b>	
		HRS/MSC	7200				0	<b>7200</b>	
	REF: TLMC 5-12-MI	AFL					0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-MJ	INSPECTION DOCUMENT MJ							AIRWORTHINES S	
	PKG 58	MOS					23-SEP-2003		
		HRS/MSC	7200				0		7200
	REF: TLMC 5-12-MJ	AFL					0		
5-12-MK	INSPECTION DOCUMENT MK							AIRWORTHINES S	
	PKG 59	MOS					23-SEP-2003		
		HRS/MSC	7900				0		7900
	REF: TLMC 5-12-MK	AFL					0		
5-12-MM	INSPECTION DOCUMENT MM							AIRWORTHINES S	
	PKG 61	MOS					23-SEP-2003		
		HRS/MSC	12000				0		12000
	REF: TLMC 5-12-MM	AFL					0		
5-12-MN	INSPECTION DOCUMENT MN							AIRWORTHINES S	
	PKG 62	MOS					23-SEP-2003		
		HRS/MSC	12000				0		12000
	REF: TLMC 5-12-MN	AFL					0		
5-12-MO	INSPECTION DOCUMENT MO							AIRWORTHINES S	
	PKG 63	MOS					23-SEP-2003		
		HRS/MSC	15200				0		15200
	REF: TLMC 5-12-MO	AFL					0		
<b>ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104</b>									
052001	NO. 1 ENGINE - FJ44 CHECK 1								
	PKG 1 in PKG 2	MOS					23-NOV-2018		
		HRS/MSC	300	+30			1483	(1783)	1783
	REF: LM 05-20-00	ENC					1083		1813
052002	NO. 1 ENGINE - FJ44 CHECK 2								
	PKG 2	MOS					23-NOV-2018		
		HRS/MSC	600	+30			1483	(2083)	2083
	REF: LM 05-20-00	ENC					1083		2113
052003	NO. 1 ENGINE - FJ44 CHECK 3								
	PKG 3	MOS					23-SEP-2003		
		HRS/MSC	10500	+50	-8750		0	(1750)	1750
	REF: See Workcard	ENC					0		1800
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052004	NO. 1 ENGINE - FJ44 CHECK 4								
	PKG 4	MOS					23-SEP-2003		
		HRS/MSC	10500	+50	-7000		0	(3500)	3500
	REF: See Workcard	ENC					0		3550
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
052005	NO. 1 ENGINE - FJ44 CHECK 5 PKG 5	MOS HRS/MSC ENC	10500 +50	-5250		23-SEP-2003 0 0	(5250) 5250	5300
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052006	NO. 1 ENGINE - FJ44 CHECK 6 PKG 6	MOS HRS/MSC ENC	10500 +50	-3500		23-SEP-2003 0 0	(7000) 7000	7050
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052007	NO. 1 ENGINE - FJ44 CHECK 7 PKG 7	MOS HRS/MSC ENC	10500 +50	-1750		23-SEP-2003 0 0	(8750) 8750	8800
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052008	NO. 1 ENGINE - FJ44 CHECK 8 PKG 8	MOS HRS/MSC ENC	10500 +50			23-SEP-2003 0 0	(10500) 10500	10550
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
<b>ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104</b>								
052001	NO. 2 ENGINE - FJ44 CHECK 1 PKG 1 in PKG 2	MOS HRS/MSC ENC	300 +30			23-NOV-2018 1483 1083	(1783) 1783	1813
REF: LM 05-20-00								
052002	NO. 2 ENGINE - FJ44 CHECK 2 PKG 2	MOS HRS/MSC ENC	600 +30			23-NOV-2018 1483 1083	(2083) 2083	2113
REF: LM 05-20-00								
052003	NO. 2 ENGINE - FJ44 CHECK 3 PKG 3	MOS HRS/MSC ENC	10500 +50	-8750		23-SEP-2003 0 0	(1750) 1750	1800
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052004	NO. 2 ENGINE - FJ44 CHECK 4 PKG 4	MOS HRS/MSC ENC	10500 +50	-7000		23-SEP-2003 0 0	(3500) 3500	3550
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052005	NO. 2 ENGINE - FJ44 CHECK 5 PKG 5	MOS HRS/MSC ENC	10500 +50	-5250		23-SEP-2003 0 0	(5250) 5250	5300
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
052006	NO. 2 ENGINE - FJ44 CHECK 6							
	PKG 6	MOS				23-SEP-2003		
		HRS/MSC	10500	+50	-3500		(7000) 7000	7050
	REF: See Workcard	ENC				0		
THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052007	NO. 2 ENGINE - FJ44 CHECK 7							
	PKG 7	MOS				23-SEP-2003		
		HRS/MSC	10500	+50	-1750		(8750) 8750	8800
	REF: See Workcard	ENC				0		
THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								
052008	NO. 2 ENGINE - FJ44 CHECK 8							
	PKG 8	MOS				23-SEP-2003		
		HRS/MSC	10500	+50			(10500) 10500	10550
	REF: See Workcard	ENC				0		
THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 1750 HRS								



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
CJ01-160316	REVIEW MODEL 525 (SERIALS -0001 THRU -0684 AND -0686 THRU -0799) ALS CH 4 REV 12						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CJ01	MOS HRS/MSC - AFL							
CJ01-160421	REVIEW CITATION CJ1 (525), TLMC (CH 5) REV. 25						03-JUN-2016		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CJ01	MOS HRS/MSC - AFL							
CJ01-160601	REVIEW CITATION CJ1 (525), TLMC (CH 5) REV. 26						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CJ01	MOS HRS/MSC - AFL							
<b>ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104</b>									
E062-151014	NO. 1 ENGINE - REVIEW CAMP INFORMATION LETTER (WILLIAMS CODE CONVERSION)						(EBT)		
<b>INFORMATIONAL</b>	REF: RCF E062	MOS HRS/MSC - ENC							
E062-160920	NO. 1 ENGINE - REVIEW FJ44-1A LM REV 45								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC							
E062-161015	NO. 1 ENGINE - REVIEW CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-1A LINE MAINTENANCE MANUAL (P/N 50773), REVISION 41, DATED SEP 11/15						26-OCT-2015		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC							





# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E062-161216	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 46					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							
E062-170316	NO. 1 ENGINE - REVIEW	WILLIAMS INTERNATIONAL FJ44-1A LMM REV 47					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							
E062-170621	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 48					15-AUG-2017		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							
E062-170922-1	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 49					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							
E062-171212	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 50					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							
E062-180322	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 51					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E062</b>	MOS HRS/MSC - ENC							



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E062-180621	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 52					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-180921	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 53					18-OCT-2018		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-181213	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 54					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-190312	NO. 1 ENGINE - REVIEW	FJ44-1A LMM REV 55					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 29-MAR-2019 (EFFECTIVE: 12-MAR-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
<b>ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104</b>									
E062-151014	NO. 2 ENGINE - REVIEW	CAMP INFORMATION LETTER (WILLIAMS CODE CONVERSION)					(EBT)		
<b>INFORMATIONAL</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-160920	NO. 2 ENGINE - REVIEW	FJ44-1A LM REV 45							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E062-161015	NO. 2 ENGINE - REVIEW (P/N 50773), REVISION 41, DATED SEP 11/15	CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-1A LINE MAINTENANCE MANUAL							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					26-OCT-2015		
E062-161216	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 46							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					(EBT)		
E062-170316	NO. 2 ENGINE - REVIEW	WILLIAMS INTERNATIONAL FJ44-1A LMM REV 47							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					(EBT)		
E062-170621	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 48							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					15-AUG-2017		
E062-170922-1	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 49							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					(EBT)		
E062-171212	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 50							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF E062	MOS HRS/MSC - ENC					(EBT)		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E062-180322	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 51					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-180621	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 52					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-180921	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 53					18-OCT-2018		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-181213	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 54					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
E062-190312	NO. 2 ENGINE - REVIEW	FJ44-1A LMM REV 55					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF E062	MOS HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 29-MAR-2019 (EFFECTIVE: 12-MAR-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER	04	LIMITATIONS
04-01		PERFORM YEARLY RENEVAL OF ARC
<b>AIRWORTHINESS</b>	<b>REF:</b>	MOS 12 HRS/MSC O/C AFL
		10-JAN-2019 09-JAN-2020 M



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
04-02	PERFORM RENEWAL OF FULL ARC EVERY THREE YEARS	MOS	36				10-JAN-2019	09-JAN-2022 M	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL							
04-03	CERTIFICATE OF AIRWORTHINESS	MOS					10-JAN-2019		
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL	DUE						
04-04	CERTIFICATE NOISE	MOS					10-JAN-2019		
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL	DUE						
04-05	CERTIFICATE OF AVIATION INSURANCE	MOS	12				15-DEC-2018	19-APR-2019 M	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL							
04-10	RENEWAL OF THE SWEDISH POST AND TELECOM AUTHORITY	MOS	108				08-JAN-2019	31-DEC-2027 M	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL							
04-15	CERTIFICATE OF NATO AND REGISTRATION	MOS					04-JAN-2019		
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL	DUE						
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>								
05HB21	CHECK ACM HOURS	DAYS	30				01-MAR-2019	31-MAR-2019	
	<b>REF:</b>	HRS/MSC AFL					1516:10 1110		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05HB28	DRAIN FUEL SAMPLE FROM THE TANKS AND INSPECT FOR CONTAMINATION	DAYS	30				01-MAR-2019 1516:10 1110	31-MAR-2019	
	REF:	HRS/MSC AFL							
05HB30	CHECK BRAKE WEAR PINS, TIRES PRESSURE AND INSPECT TIRES CONDITION	DAYS	30	+10/-10			01-MAR-2019 1516:10 1110	31-MAR-2019	10-APR-2019
	REF:	HRS/MSC AFL	DUE						
05HB31	REFURBISH DEICE BOOTS WITH EDGE MASTER + ICE-X	MOS					01-MAR-2019 1516:10 1110		
	REF:	HRS/MSC AFL	A/R						
05HB32	REBURBISH DEICE BOOTS WITH ICE-X	MOS					01-MAR-2019 1516:10 1110		
	REF:	HRS/MSC AFL	A/R						
<b>CHAPTER 08-20 LEVELING AND WEIGHING</b>									
08-20-00	AIRCRAFT WEIGHING	MOS	48				08-DEC-2015 1076 773	31-DEC-2019	
	WEIGHT CHECK	HRS/MSC AFL							
	REF:		See Workcard						
<b>CHAPTER 21 AIR CONDITIONING</b>									
211003	HEAT PRESSURE EXCHANGER	MOS					23-SEP-2003		
	10840A	HRS/MSC	O/C		TSN:0		0		
21.010	824	AFL			TSN:0		0		
	REF:		AMM 21-40-00						
211004	RAM AIR MODULATING VALVE	MOS					23-SEP-2003		
	27241287-15	HRS/MSC	O/C		TSN:0		0		
21.020	2AWH1613	AFL			TSN:0		0		
	REF:		AMM 21-40-00						

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211005	EMERGENCY PRESS SHUTOFF VALVE								
21.020	2601-23 0370 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212001	UNDERFLOOR INLET AIR BLOWER								
21.030	0113-12 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212003	TEMP PRESS COMPRESSION SWITCH								
21.040	1173T42-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212011	AFT TEMP UNDERFLOOR SENSOR								
21.040	27221274 3AW129 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212202	OVERHEAD AIR VALVE SOLENOID								
21.050	D113204 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212302	BLOWER - WINDSHIELD AIR MOTOR								
21.060	7003-200 0967 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
212404	NOSE AVIONICS COOLING FAN								
21.080	032105 SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213001	PRESS MASTER OUTFLOW VALVE								
21.090	52771-301 SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
213002	PRESS SECONDARY OUTFLOW VALVE								
21.090	52772-101 SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
213003	PRESSURIZATION CONTROLLER								
21.100	52770-112 1444 REF:	MOS HRS/MSC AFL	O/C	TSO:187			15-SEP-2004 187		
213005	DIFFERENTIAL PRESS INDICATOR								
21.100	C668511-0105 22469 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
213008	PRESS MANUAL CONTROL SWITCH								
21.110	52773-001 1469 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
215001	FORWARD EVAPORATOR								
21.120	1134820-1 512 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215002	AFT EVAPORATOR								
21.120	1134820-2 586 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215003	AFT EVAPORATOR MOTOR								
21.130	1250210-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215003	FORWARD EVAPORATOR MOTOR								
21.130	1250210-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215004	AIR CONDITIONER COMPRESSOR								
21.140	1134160 5187 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0			04-AUG-2008  101		
215005	AIR CONDITIONER CONDENSER								
21.140	1134400-31 206 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215006	COMPRESSOR DRIVE MOTOR								
21.150	1134104-1 2975 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1		1	23-SEP-2003 0 0 0		
215007	RECEIVER DRYER ASSEMBLY								
21.160	1134140-3 NSN REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0			04-AUG-2008  101		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215008	BINARY SWITCH								
21.170	1250232-12 215 REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215009	A/C FLIGHT HOUR METER								
21.180	1250703-3 SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215011	AIR CONDITIONER DRIVE BELT								
21.310	232L100 NSN REF: AMM 21-50-00	MOS HRS/MSC AFL ACH	O/C	TSN:0			04-AUG-2008  101		
215012	COMPRESSOR DRIVE MOTOR BRUSHES								
21.150 LIFE LIMIT	1251171-6 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	500	TSI:0 TSN:0			23-SEP-2003 0 0 0	500	
215013	AFT EXPANSION VALVE								
21.190	1250218 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		
215013	FORWARD EXPANSION VALVE								
21.190	1250218 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:1			23-SEP-2003 0 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216002	TEMPERATURE CONTROLLER								
21.200	1E58-6 10AV88 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
216003	TEMP CNTL SYS SENSOR								
21.200	27221274 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A211001 (s)	INSPECT FLOW CONTROL VALVE DETAILED: INSPECTION DOCUMENT 10						PKG		
21.240	PKG 12 REF: AMM 21-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A215004 (s)	CHECK VAPOR CYCLE COOLING SYSTEM HOURMETER (COMPRESSOR MOTORS 1134104-1, -5): INSPECTION DOCUMENT MA						PKG		
	PKG 50 REF: AMM 21-50-00	MOS HRS/MSC AFL	300				23-NOV-2018 1483 1083		
A215005 (s)	CHECK VAPOR CYCLE COOLING SYSTEM HOURMETER (EXCEPT COMPRESSOR MOTORS 1134104-1, -5): INSPECTION DOCUMENT 01						PKG		
	PKG 1 REF: AMM 21-50-00	MOS HRS/MSC AFL	300	+30			23-NOV-2018 1483 1083		
B211001 (s)	OPERATIONAL CHECK EMERGENCY PRESSURIZATION VALVE: INSPECTION DOCUMENT 08						PKG		
21.020	PKG 10 REF: AMM 21-10-00	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
B213000 (s)	FUNCTION TEST OUTFLOW VALVE CABIN ALTITUDE LIMITER VALVE: INSPECTION DOCUMENT 10						PKG		
21.330	PKG 12 REF: AMM 21-30-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B213100 (s)	OPERATIONAL CHECK CABIN ALTITUDE SWITCH/ANNUNCIATION: INSPECTION DOCUMENT 10						PKG		
21.340	PKG 12 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 22 AUTO FLIGHT</b>									
221003	AILERON SERVO								
22.010	822-1168-002 13TTT REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
221004	RUDDER SERVO								
22.030	822-1168-001 13TYL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
221005	ELEVATOR SERVO								
22.020	822-1168-001 135MK REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
221006	AILERON SERVO MOUNT								
22.010	622-5735-021 13CYV REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
221006	ELEVATOR SERVO MOUNT								
22.020	622-5735-020 135TK REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
221006	RUDDER SERVO MOUNT								
22.030	622-5735-022 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221008	AUTOPILOT CONTROL								
22.040	622-6208-223 18CRX REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
<b>CHAPTER 23 COMMUNICATIONS</b>									
231003	MINIATURE CONTROL ADAPTER								
23.090	071-01268-0001 4812 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
232008	BOTTOM COMM 1 ANTENNA								
23.030	17-40-02W 0679 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
232008	TOP COMM 2 ANTENNA								
23.030	18-50-01 0853 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
235001	LEFT AUDIO AMPLIFIER								
23.040	5636-1 1084 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
235001	RIGHT AUDIO AMPLIFIER								
23.040	5636-1 1085 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
237003	CVR MICROPHONE								
23.130	S055-0065-00 000217777 REF: AMM 23-72-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237004	CVR IMPACT SWITCH								
23.150	6895D2X5-5 4486 REF: AMM 23-72-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
23FO-01 525/B	COCKPIT SPEAKER MUTE FACTORY OPTION								
	674B FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
23FO-06 525/X	HF COMM PROVISIONS KHF-950 FACTORY OPTION								
	631X FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
23FO-08 525/L	RECORDER-CKPT VOICE (PROVISIONS ONLY) FACTORY OPTION								
	634L FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
23FO-12	500W/115VAC INVERTER FACTORY OPTION								
	901 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
23FO-14	MILLIBARS/INCHES SWITCH FACTORY OPTION								
	806 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
23FO801	WX-1000E LIGHTNING DETECTION STORMSCOPE-GOODRICH FACTORY OPTION								
	801 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B236101 (s)	FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM: INSPECTION DOCUMENT 10						PKG		
23.050	PKG 12 REF: AMM 23-61-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 24 ELECTRICAL POWER</b>									
243002	LEFT GENERATOR CONTROL UNIT								
24.040	51525-001F Y3054 REF: AMM 24-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
243002	RIGHT GENERATOR CONTROL UNIT								
24.040	51525-001F 98352 REF: AMM 24-31-00	MOS HRS/MSC AFL	O/C				20-SEP-2011 880 604		
243003	MAIN BATTERY								
24.260	RG-380E/44LA5 40783050 REF: See Workcard	MOS HRS/MSC AFL	O/C				22-FEB-2018 1398 1016		
243004	BATTERY TEMPERATURE MONITOR-								
24.050	1529-1-1 3846 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
243005	OVERVOLTAGE MONITOR-								
24.050	1645-1-3 3273 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
243006	LEFT AMMETER								
24.060	C662501-0105 E23120 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243006	RIGHT AMMETER								
24.060	C662501-0105 D23738 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
243008	BATTERY DISCONNECT RELAY								
24.070	A931F 36895 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
243011	VOLTMETER								
24.080	C662502-0101 C23776 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245001	LEFT START PCB ASSY								
24.090	6318324-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245001	RIGHT START PCB ASSY								
24.090	6318324-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245002	LEFT ASSEMBLY-FUEL CONTROL PCB								
24.100	6318321-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245002	RIGHT ASSEMBLY-FUEL CONTROL PCB								
24.100	6318321-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
245003	LEFT ASSEMBLY-IGNITOR PCB								
24.110	6318322-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245003	RIGHT ASSEMBLY-IGNITOR PCB								
24.110	6318322-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245004	LEFT ANTI ICE PCB ASSY								
24.120	6318323-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245004	RIGHT ANTI ICE PCB ASSY								
24.120	6318323-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245005	ATTENUATOR PCB ASSY								
24.130	6318355-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245006	ENVIRONMENTAL PCB ASSY								
24.130	6318356-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245007	MISCELLANEOUS PCB ASSY								
24.140	6318357-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
245008	TRIM CONTROL PCB ASSY								
24.140	6518351-9 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245009	DIMMING PCB ASSY								
24.150	6518353-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
245010	GEAR LOGIC PCB ASSY								
24.150	6518354-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A243301	FUNCTIONAL CHECK MAIN BATTERY LEAD ACID BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 09								
24.170	RG-380E/44LA5 PKG 11 40783050 REF: See Workcard	MOS HRS/MSC AFL	4 200	+2m +30	-75		01-MAR-2019 1516:10 1110	<b>30-APR-2019</b> <b>1716:10</b>	16-JUN-2019 1746:10
<b>CHAPTER 25</b>	<b>EQUIPMENT/FURNISHINGS</b>								
256001	ELT TRANSMITTER								
25.030	453-5000-999 04020 REF: AMM 25-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
256002	REMOTE SWITCH								
25.110	452-0010 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
256004	ELT ANTENNA								
25.040	110-328-01 3597 REF: AMM 25-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256005	ELT BEACON BATTERY PACK 452-0133 375294-037 <b>REF:</b> AMM 25-61-02 Manufacture Date: 23-AUG-2017	MOS HRS/MSC AFL ACH	60	TSN:0 TSN:0			11-SEP-2017 1348:44 983	01-NOV-2022 M	
256006	NO. 1 LIFE VEST P01074-201WC 15030750003 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-NOV-2025 M	
256006	NO. 2 LIFE VEST P01074-201WC 15030750014 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	03-NOV-2025 M	
256006	NO. 3 LIFE VEST P01074-201W 12030310052 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-MAR-2022 M	
256006	NO. 4 LIFE VEST P01074-201W 12030310060 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-MAR-2022 M	
256006	NO. 5 LIFE VEST P01074-201W 12030310003 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-MAR-2022 M	
256006	NO. 6 LIFE VEST P01074-201W 12030310059 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-MAR-2022 M	

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256006	NO. 7 LIFE VEST P01074-103 16060500092 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:26 TSN:0 TSN:0			26-OCT-2017 1366:36 993	31-AUG-2020	
256006	NO. 8 LIFE VEST P01074-201WC 120030310056 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0			26-OCT-2017 1366:36 993	01-MAR-2022 M	
256007	GPS DIGITAL INTERFACE UNIT 453-6500 02329 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
256055	FIRST AID KIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-JAN-2019 1498:51 1094		
25FO-03 525	TAILCONE BAGGAGE EXTENSION FOR SKIS FACTORY OPTION 132 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
25FO-57 525/H	LH AFT BELTED W/FLUSH MOUNTED COAT ROD FACTORY OPTION 130H FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
25FO-61	ARTEX ELT C406-2 FACTORY OPTION 804 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
25FO-62	KIT FOR UNS-1L-UNIVERSAL (EXCH) FACTORY OPTION 805 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25FO697 K	PERMANENT DTU FACTORY OPTION 697K FO REF:	MOS HRS/MSC - AFL					23-SEP-2003 0 0		
25FO729 B	PEBBLE COLOR CKP/CB DOOR TRIMS FACTORY OPTION 729B FO REF:	MOS HRS/MSC - AFL					23-SEP-2003 0 0		
A251101 (s) 25.080	DETAILED INSPECTION CREW SEAT AND RESTRAINT SYSTEM: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 25-11-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A252101 (s) 25.080	DETAILED INSPECTION PASSENGER SEAT AND RESTRAINT SYSTEM: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 25-21-01	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A256001 (s) 25.090	DETAILED INSPECTION OF LIFE VEST: INSPECTION DOCUMENT 02 PKG 2 REF: AMM 25-60-01	MOS HRS/MSC AFL	12	+2m			PKG 23-NOV-2018 1483 1083		
A256002 (s) 25.130	DETAILED INSPECTION FIRST AID KIT: INSPECTION DOCUMENT 02 PKG 2 REF: AMM 25-60-02	MOS HRS/MSC AFL	12	+2m			PKG 23-NOV-2018 1483 1083		
A256103 (s) 25.140	DETAILED INSPECTION ARTEX EMERGENCY LOCATOR TRANSMITTER (ELT): INSPECTION DOCUMENT 12 PKG 14 REF: AMM 25-61-05	MOS HRS/MSC AFL	12				PKG 23-NOV-2018 1483 1083		
B256100 (s) 25.140	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER (ELT) (POINTER C-3000 ELT/DORNE MARGOLIN 8.1 EMERGENCY LOCATOR SYSTEM): INSPECTION DOCUMENT 12 PKG 14 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				PKG 23-NOV-2018 1483 1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B256103 (s)	OPERATIONAL CHECK	ARTEX	EMERGENCY LOCATOR TRANSMITTER (ELT):	INSPECTION DOCUMENT 12			PKG		
25.140	PKG 14	MOS	12				23-NOV-2018		
	REF: AMM 25-61-05	HRS/MSC					1483		
		AFL					1083		
<b>CHAPTER 26 FIRE PROTECTION</b>									
261002	LEFT FIRE DETECT SENSOR								
26.010	30012121004/4559	MOS					23-SEP-2003		
	204909	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-00	AFL		TSN:0			0		
261002	RIGHT FIRE DETECT SENSOR								
26.010	30012121004/4559	MOS					23-SEP-2003		
	204910	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-00	AFL		TSN:0			0		
262001	LEFT FIRE EXTINGUISHER BOTTLE								
26.020	30400031-1	MOS		TSN:258 TSO:10			26-OCT-2017		
	37341B1	HRS/MSC	O/C	TSO:0			1366:36		
	REF: AMM 26-20-00	AFL		TSO:0			993		
262001	RIGHT FIRE EXTINGUISHER BOTTLE								
26.030	30400031-1	MOS		TSN:181 TSO:9			26-OCT-2017		
	49356B1	HRS/MSC	O/C	TSO:0			1366:36		
	REF: AMM 26-20-00	AFL		TSO:0			993		
262002	LEFT NO. 1 FIRE EXTINGUISHER CARTRIDGE								
26.020	13083-5	MOS	72				26-OCT-2017		30-SEP-2022
	ESD16J655-001	HRS/MSC		TSN:0			1366:36		
	REF: AMM 26-20-00	AFL		TSN:0			993		
	Manufacture Date: 01-SEP-2016								
262002	LEFT NO. 2 FIRE EXTINGUISHER CARTRIDGE								
26.020	13083-5	MOS	72				26-OCT-2017		30-SEP-2022
	ESD16J655-001	HRS/MSC		TSN:0			1366:36		
	REF: AMM 26-20-00	AFL		TSN:0			993		
	Manufacture Date: 01-SEP-2016								



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262002	RIGHT NO. 1 FIRE EXTINGUISHER CARTRIDGE 13083-5	MOS	72				26-OCT-2017	31-MAY-2023	
26.030	ESD17E675-001	HRS/MSC		TSN:0			1366:36		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 26-20-00	AFL		TSN:0			993		
	Manufacture Date: 01-MAY-2017								
262002	RIGHT NO. 2 FIRE EXTINGUISHER CARTRIDGE 13083-5	MOS	72				26-OCT-2017	31-MAY-2023	
26.030	ESD17E675-001	HRS/MSC		TSN:0			1366:36		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 26-20-00	AFL		TSN:0			993		
	Manufacture Date: 01-MAY-2017								
262003	COCKPIT PORTABLE FIRE EXTINGUISHER C352TS	MOS		TSN:8			26-OCT-2017		
26.040	C-90387113	HRS/MSC	O/C	TSN:0			1366:36		
	<b>REF:</b> GENERIC NO REF	AFL		TSN:0			993		
A262002 (s)	GENERAL VISUAL INSPECTION ENGINE FIRE EXTINGUISHING SYSTEM: INSPECTION DOCUMENT 01 PKG 1	MOS					PKG		
26.050		HRS/MSC	300	+30			23-NOV-2018		
	<b>REF:</b> AMM 26-20-00	AFL					1483		
							1083		
A262201	DETAILED INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 06 C352TS PKG 8	MOS	72	+2m			15-FEB-2017	28-FEB-2023	15-APR-2023
26.060	C-90387113	HRS/MSC							
	<b>REF:</b> AMM 26-22-00	AFL							
B262001 (s)	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHING SYSTEM: INSPECTION DOCUMENT 10 PKG 12	MOS	36	+2m			PKG		
26.050		HRS/MSC	1200	+30			01-MAR-2019		
	<b>REF:</b> AMM 26-20-00	AFL					1516:10		
							1110		
B262002	RESTORATION (HYDROSTATIC TEST) LEFT FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 05 30400031-1 PKG 5	MOS	60				01-DEC-2016	31-DEC-2021	
26.020	37341B1	HRS/MSC							
	<b>REF:</b> AMM 26-20-00	AFL							



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B262002	RESTORATION (HYDROSTATIC TEST) RIGHT FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 05								
26.030	30400031-1 PKG 5 49356B1 REF: AMM 26-20-00	MOS HRS/MSC AFL	60				14-JUN-2017	30-JUN-2022	
B262201	FUNCTIONAL (WEIGHT) CHECK COCKPIT PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 02								
26.060	C352TS PKG 2 C-90387113 REF: AMM 26-22-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083	30-NOV-2019	23-JAN-2020
B262202	RESTORATION (HYDROSTATIC TEST) COCKPIT PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 07								
26.060	C352TS PKG 9 C-90387113 REF: AMM 26-22-00	MOS HRS/MSC AFL	144				15-FEB-2017	28-FEB-2029	
<b>CHAPTER 27 FLIGHT CONTROLS</b>									
273001	LEFT SHAKER CONTROL								
27.010	201 5881 REF: AMM 27-31-00	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
273002	ELEVATOR ELECTRIC TRIM SERVO								
27.020	44430-3548 T816 REF: AMM 27-30-02	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
273003	SERVO MOUNT ASSY								
27.020	44575-3415 T1375 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
273004	LEFT ELEVATOR TRIM ACTUATOR								
27.030	6361215-21 SN-UNKNOWN REF: AMM 27-30-02	MOS HRS/MSC AFL	O/C				26-OCT-2017 1366:36 993		
273004	RIGHT ELEVATOR TRIM ACTUATOR								
27.030	6396022-4 NSN REF: AMM 27-30-02	MOS HRS/MSC AFL	O/C				26-OCT-2017 1366:36 993		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273005	RUDDER TRIM TAB ACTUATOR								
27.040	6361215-21 SN-UNKNOWN REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
275002	LEFT FLAP HYD ACTUATOR								
27.060	1542000-7 1473 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
275002	RIGHT FLAP HYD ACTUATOR								
27.060	1542000-7 1471 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
276001	LEFT SPEEDBRAKE ACTUATOR								
27.070	1542100-5 1472 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
276001	RIGHT SPEEDBRAKE ACTUATOR								
27.070	1542100-5 1473 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A271001 (s)	INSPECT AILERON TRIM TAB ACTUATOR (WITH OR WITHOUT GREASE FITTINGS): INSPECTION DOCUMENT 10						PKG		
27.100	PKG 12 REF: AMM 27-00-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A272001 (s)	INSPECT RUDDER TRIM TAB ACTUATOR (WITH OR WITHOUT GREASE FITTINGS): INSPECTION DOCUMENT 10						PKG		
27.040	6361215-21 PKG 12 SN-UNKNOWN REF: AMM 27-00-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A273002 (s)	INSPECT ELEVATOR TRIM TAB ACTUATOR (WITH OR WITHOUT GREASE FITTINGS): INSPECTION DOCUMENT 10						PKG		
27.030	PKG 12 REF: AMM 27-00-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B270001 (s)	FUNCTIONAL CHECK AILERON AND AILERON TRIM CONTROL SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.160	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-10-00	AFL					1110		
B271002 (s)	CHECK AILERON TRIM TAB FREE PLAY: INSPECTION DOCUMENT 10						PKG		
27.170	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-10-00	AFL					1110		
B272001 (s)	FUNCTIONAL CHECK RUDDER TRIM CONTROL SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.240	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-20-00	AFL					1110		
B272002 (s)	FUNCTIONAL CHECK RUDDER CONTROL SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.250	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-20-00	AFL					1110		
B272003 (s)	CHECK RUDDER TRIM TAB FREE PLAY: INSPECTION DOCUMENT 10						PKG		
27.290	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-20-00	AFL					1110		
B273000 (s)	CHECK ELEVATOR TRIM TAB FREE PLAY: INSPECTION DOCUMENT 10						PKG		
27.300	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-30-00	AFL					1110		
B273001 (s)	FUNCTIONAL CHECK ELEVATOR TRIM CONTROL SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.260	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-30-00	AFL					1110		
B273003 (s)	FUNCTIONAL CHECK ELEVATOR CONTROL SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.270	PKG 12	MOS	36	+2m			01-MAR-2019		
	HRS/MSC		1200	+30			1516:10		
	REF: AMM 27-30-00	AFL					1110		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B275001 (s)	FUNCTIONAL CHECK FLAP SYSTEM: INSPECTION DOCUMENT 10						PKG		
27.280	PKG 12 REF: AMM 27-50-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
C271001 (s)	LUBRICATE AILERON TRIM TAB ACTUATOR: INSPECTION DOCUMENT 08						PKG		
27.360	PKG 10 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
C272001 (s)	LUBRICATE RUDDER TRIM TAB ACTUATOR INSPECTION: DOCUMENT 8						PKG		
27.040	6361215-21 PKG 10 SN-UNKNOWN REF: AMM 12-21-01	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
C273001 (s)	LUBRICATE ELEVATOR TRIM TAB ACTUATOR: INSPECTION DOCUMENT 08						PKG		
27.340	PKG 10 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
<b>CHAPTER 28 FUEL</b>									
281001	LEFT FUEL SURGE VALVE								
28.010	35C10D 2762 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
281001	RIGHT FUEL SURGE VALVE								
28.010	35C10D 2775 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
282001	LEFT ELECTRIC FUEL PUMP								
28.020	1C7-13 3AW44 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
282001	RIGHT ELECTRIC FUEL PUMP								
28.020	1C7-13 10AV172 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282002	LEFT FUEL TRANSFER PUMP								
28.030	RG45880 B1165 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282002	RIGHT FUEL TRANSFER PUMP								
28.030	RG45880 B1164 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282004	LEFT FUEL MOTOR ACTUATED VALVE								
28.040	EM9014-3 1472 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282004	RIGHT FUEL MOTOR ACTUATED VALVE								
28.040	EM9014-3 1468 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282005	LEFT FUEL TRANSFER EJECTOR								
28.050	RG45310 B8993 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282005	RIGHT FUEL TRANSFER EJECTOR								
28.050	RG45310 B8995 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
282006	TRANSFER VALVE								
28.060	ZSV57 3022596 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284001	LEFT #5 FUEL TRANSMITTER								
28.070	10307T01Y00 1213 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284001	RIGHT #5 FUEL TRANSMITTER								
28.070	10307T01Y00 1214 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284002	LEFT FUEL QUANTITY TRANSMITTER								
28.080	10309T03Y00 1391 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284002	RIGHT FUEL QUANTITY TRANSMITTER								
28.080	10309T03Y00 1235 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284003	FUEL QUANTITY SIGNAL CONDITIONER								
28.090	10310B01Y02 03010642 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284004	LEFT #3 FUEL TRANSMITTER								
28.100	10305T01Y00 1238 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284004	RIGHT #3 FUEL TRANSMITTER								
28.100	10305T01Y00 1237 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284005	LEFT #4 FUEL TRANSMITTER								
28.110	10306T01Y00 1211 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284005	RIGHT #4 FUEL TRANSMITTER								
28.110	10306T01Y00 1212 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284006	LEFT #2 FUEL TRANSMITTER 10304T01Y00 1254 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284006	RIGHT #2 FUEL TRANSMITTER 10304T01Y00 1235 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284007	LEFT #1 FUEL TRANSMITTER 10303T01Y00 1056 REF:	MOS HRS/MSC AFL	O/C	TSO:0			04-AUG-2008 679		
284007	RIGHT #1 FUEL TRANSMITTER 10303T01Y00 1214 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284008	LEFT FUEL LOW LEVEL SWITCH GIF5400-40 SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
284008	RIGHT FUEL LOW LEVEL SWITCH GIF5400-40 SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A281001 (s)	DETAILED INSPECTION FUEL STORAGE SYSTEM: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 28-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
B284001 (s)	FUNCTIONAL CHECK FUEL INDICATING SYSTEM: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 28-40-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B284002 (s)	FUNCTIONAL CHECK LOW FUEL WARNING AND LOW FUEL PRESSURE SYSTEM: INSPECTION DOCUMENT 10						PKG		
28.210	PKG 12 REF: AMM 28-40-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 29 HYDRAULIC POWER</b>									
291002	LEFT HYDRAULIC PUMP ASSY								
29.020	4120-021003 534 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291002	RIGHT HYDRAULIC PUMP ASSY								
29.020	4120-021003 535 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291003	HYDRAULIC CHECK VALVE								
29.030	CV02-193 SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291005	HYDRAULIC RESERVOIR ASSEMBLY								
29.040	6317001-57 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291007	PRESSURE SWITCH								
29.050	GPP1250-58 0315357 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291008	HYDRAULIC MANIFOLD ASSEMBLY								
29.060	8184-12 720 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291009	HYDRAULIC RELIEF VALVE								
29.070	1785-1 752 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291010	LEFT HYDRAULIC SHUTOFF VALVE ASSY								
29.080	AV24B1388-2 639274 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291010	RIGHT HYDRAULIC SHUTOFF VALVE ASSY								
29.080	AV24B1388-2 SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291011	LEFT FLOW SWITCH/CHECK HYD VALVE								
29.100	MC19251 SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291011	RIGHT FLOW SWITCH/CHECK HYD VALVE								
29.100	MC19251 SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291011	SYSTEM RELIEF VALVE								
29.090	2576-2 576A REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			12-JUL-2013 1006 722		
291012	SPEED BRAKE DUMP VALVE SOLENOID								
29.110	4082-6 336 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291013	LOADING VALVE SOLENOID								
29.110	4134-4 584 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291014	GEAR VALVE SOLENOID								
29.110	4051-3 334 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291015	GEAR PORTION CHECK VALVE								
29.120	9504-1 330 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291016	LEFT SPEED BRAKE PORTION VALVE								
29.130	9505-1 665 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291016	RIGHT SPEED BRAKE PORTION VALVE								
29.130	9505-1 666 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291017	SPEED BRAKE PORTION VALVE								
29.140	2577-1 333 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291018	PNUEMATIC DUMP VALVE								
29.140	9503-2 336 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291019	LEFT ATTENUATOR VALVE SOLENOID								
29.150	4107-3 337 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291019	RIGHT ATTENUATOR VALVE SOLENOID								
29.150	4107-4 338 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291020	NO. 1 SPEEDBRAKE VALVE SOLENOID								
29.160	4052-3 333 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291021	NO. 1 FLAP VALVE SOLENOID								
29.160	4052-4 336 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
291022	ELECTRO/HYDRAULIC SERVO VALVE								
29.170	37-509 527 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
D291001 (s)	DISCARD HYDRAULIC FLUID FILTER: INSPECTION DOCUMENT 10								
29.190	PKG 12 REF: AMM 29-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
<b>CHAPTER 30 ICE AND RAIN PROTECTION</b>									
301001	SHUTOFF ISOLATION VALVE								
30.010	2602-36 SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
301002	LEFT PNEUMATIC DEICE SWITCH								
30.020	1106P55-1 2474A REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
301002	RIGHT PNEUMATIC DEICE SWITCH								
30.020	1106P55-1 11249A REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-JAN-2018 1377:03 1002		
301003	LEFT SHUTOFF PRESS REGULATOR VALVE								
30.030	1H127-4 SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
301003	RIGHT SHUTOFF PRESS REGULATOR VALVE								
30.030	1H127-4 SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301004	LEFT TEMPERATURE DEICE SWITCH 1173T42-4	MOS					23-SEP-2003		
30.040	2285 REF: AMM 30-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301004	RIGHT TEMPERATURE DEICE SWITCH 1173T42-4	MOS					23-SEP-2003		
30.040	2296 REF: AMM 30-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301010	LEFT HORIZONTAL STABILIZER BOOT P29S4D5244-11	MOS					01-MAR-2019		
30.050	NEU7490 REF: AMM 55-10-00	HRS/MSC AFL	O/C				1516:10 1110		
301010	RIGHT HORIZONTAL STABILIZER BOOT P29S4D5244-12	MOS					05-JAN-2018		
30.050	NCW1670 REF: AMM 55-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			1377:03 1002		
301011	DEICE TAIL TIMER 937-1-1	MOS					23-SEP-2003		
30.060	0206094 REF: AMM 30-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302001	LEFT SOLENOID VALVE 1H127-5	MOS					23-SEP-2003		
30.070	S5AW15 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302001	RIGHT SOLENOID VALVE 1H127-5	MOS					23-SEP-2003		
30.070	S5AW16 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302003	LEFT INLET MONITOR SWITCH 21542-2-68-1	MOS					23-SEP-2003		
30.080	SN-UNKNOWN REF: AMM 30-20-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

## Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302003	RIGHT INLET MONITOR SWITCH								
30.080	21542-2-68-1 SN-UNKNOWN REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
303002	LEFT HEATED PITOT TUBE								
30.090	PH502 - REF: AMM 30-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
303002	RIGHT HEATED PITOT TUBE								
30.090	PH502 - REF: AMM 30-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304001	B/A TEMP MONITOR-								
30.100	1169-1 3327 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304002	HEAT EXCHANGER								
30.110	10653A 1464 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304003	WINDSHIELD S/O VALVE								
30.120	1H127-4 SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304004	LEFT PITOT STATIC CURRENT SENSOR								
30.130	76250-1 5104 REF: AMM 30-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304004	RIGHT PITOT STATIC CURRENT SENSOR								
30.130	76250-1 5108 REF: AMM 30-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304006	TEMP BLEED AIR CONTROLLER								
30.140	1E58-1 2AW30 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304007	TEMP CONTROL BLEED AIR VALVE								
30.140	27241287 1AW7 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304009	LEFT SOLENOID DEICE VALVE								
30.150	3D2353-06 N19484 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304009	RIGHT SOLENOID DEICE VALVE								
30.150	3D2353-06 N20323 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304010	ALCOHOL PUMP ASSEMBLY								
30.160	476411 SN-UNKNOWN REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304011	TEMPERATURE SENSOR								
30.170	27221274 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304012	LEFT WINDSHIELD BLEED AIR VALVE								
30.180	1403-25 3320 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304012	RIGHT WINDSHIELD BLEED AIR VALVE								
30.180	1403-25 2949 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304013	PRESSURE WINDSHIELD SWITCH								
30.190	1115P25 3917AB REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
304014	AFT TEMPERATURE EVAPORATOR SENSOR								
30.200	27221274 6AU285 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A301001 (s)	DETAILED INSPECTION HORIZONTAL STABILIZER DEICE BOOTS: INSPECTION DOCUMENT 08						PKG		
30.220	PKG 10 REF: AMM 30-10-00	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
B301002 (s)	OPERATIONAL CHECK WING BLEED AIR CROSSFLOW SHUTOFF VALVE: INSPECTION DOCUMENT 08						PKG		
30.240	PKG 10 REF: AMM 30-10-00	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
B301003 (s)	FUNCTIONAL CHECK HORIZONTAL STABILIZER DEICE SYSTEM: INSPECTION DOCUMENT 10						PKG		
30.230	PKG 12 REF: AMM 30-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
B304001 (s)	OPERATIONAL CHECK WINDSHIELD BLEED AIR ANTI-ICE SYSTEM: INSPECTION DOCUMENT 21						PKG		
30.210	PKG 34 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 600	+2m +30			17-APR-2018 1422:54 1033		
B304101 (s)	OPERATIONAL CHECK WINDSHIELD ALCOHOL ANTI-ICE SYSTEM: INSPECTION DOCUMENT 08						PKG		
30.250	PKG 10 REF: AMM 30-41-00	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
D304101 (s)	RESTORATION WINDSHIELD ALCOHOL PUMP FILTER: INSPECTION DOCUMENT 10						PKG		
30.280	PKG 12 REF: AMM 30-41-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		

## CHAPTER 31 INDICATING/RECORDING SYSTEMS

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312001	LEFT DIGITAL CLOCK								
31.010	M877A5V 13805 REF: AMM 31-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
313001	FLIGHT HOUR METER								
31.020	C664503-0104 SN-UNKNOWN REF: AMM 31-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
315001	CABIN ALTITUDE PRESSURE SWITCH								
31.040	GB300NA161 0602345 REF:	MOS HRS/MSC AFL	O/C	TSN:0			13-OCT-2006 462		
315002	MASTER WARN ANNUNCIATOR ASSY								
31.050	9912438-21 438000535 REF:	MOS HRS/MSC AFL	O/C	TSO:0			13-OCT-2006 462		
<b>CHAPTER 32 LANDING GEAR</b>									
321001	LEFT MAIN LANDING GEAR AND ATTACHING HARDWARE ASSEMBLY								
32.010	6341003-17L 3 REF: AMM 32-10-00	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
321001	NOSE LANDING GEAR STRUT AND ATTACHING HARDWARE ASSEMBLY								
32.280	6342000-31 22 REF: AMM 32-10-00	MOS HRS/MSC AFL		TSN:0 TSN:0			23-SEP-2003 0 0		22500
<b>LIFE LIMIT</b>									
321001	RIGHT MAIN LANDING GEAR AND ATTACHING HARDWARE ASSEMBLY								
32.010	6341003-18R 3 REF: AMM 32-10-00	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
321003	LEFT MAIN GEAR TRUNNION ASSEMBLY								
32.020	6341007-11 25057099 REF: AMM 32-10-00	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			26-OCT-2017 1366:36 993		11339
<b>LIFE LIMIT</b>									

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321004	RIGHT MAIN GEAR TRUNNION ASSEMBLY								
	6341007-12	MOS		TSN:0			26-OCT-2017		
32.020	24522248	HRS/MSC		TSN:0			1366:36		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-00</b>	AFL	10346	TSN:0			993		<b>11339</b>
321005	LEFT TRAILING LINK AND AXLE ASSEMBLY								
	6341002-27	MOS		TSN:0			26-OCT-2017		
32.480	26942247	HRS/MSC		TSN:0			1366:36		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-41-00</b>	AFL	23400	TSN:0			993		<b>24393</b>
321006	RIGHT TRAILING LINK AND AXLE ASSEMBLY								
	6341002-28	MOS		TSN:0			26-OCT-2017		
32.480	27006731	HRS/MSC		TSN:0			1366:36		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-41-00</b>	AFL	23400	TSN:0			993		<b>24393</b>
321007	SHIMMY DAMPER ASSEMBLY								
	6343001-7	MOS					23-SEP-2003		
32.040	212	HRS/MSC	O/C				0		
	<b>REF: AMM 32-20-01</b>	AFL		TSN:0			0		
321008	LEFT OLEO ASSEMBLY								
	6341130-6	MOS					23-SEP-2003		
32.050	6	HRS/MSC					0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-00</b>	AFL	23400	TSN:0			0		<b>23400</b>
321008	RIGHT OLEO ASSEMBLY								
	6341130-6	MOS					23-SEP-2003		
32.050	5	HRS/MSC					0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-00</b>	AFL	23400	TSN:0			0		<b>23400</b>
321009	FORK AND PISTON ASSEMBLY								
	6342000-32	MOS					23-SEP-2003		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	12500	TSN:0			0		<b>12500</b>
323000	NOSE LANDING GEAR ACTUATOR ASSEMBLY								
	9912370-5	MOS		TSN:0			27-JAN-2017		
32.060	1822	HRS/MSC		TSN:0			1255:42		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-20-00</b>	AFL	7500	TSN:0			910		<b>8410</b>





# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323001	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY 1541800-13	MOS					23-SEP-2003		
32.070	1133	HRS/MSC					0		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 32-10-00	AFL	9948	TSN:0			0		<b>9948</b>
323002	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY 1541800-13	MOS					23-SEP-2003		
32.070	1031	HRS/MSC					0		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 32-10-00	AFL	9948	TSN:0			0		<b>9948</b>
323003	NG UPLOCK ACTUATOR 6327504-7	MOS					23-SEP-2003		
32.060	343	HRS/MSC	O/C				0		
	<b>REF:</b> AMM 32-31-01	AFL		TSN:0			0		
323005	LEFT MLG UPLOCK ACTUATOR 6327504-6	MOS					23-SEP-2003		
32.080	634	HRS/MSC	O/C				0		
	<b>REF:</b> AMM 32-31-02	AFL		TSN:0			0		
323005	RIGHT MLG UPLOCK ACTUATOR 6327504-6	MOS					23-SEP-2003		
32.080	633	HRS/MSC	O/C				0		
	<b>REF:</b> AMM 32-31-02	AFL		TSN:0			0		
323006	HYD SHUTTLE VALVE 95784	MOS					23-SEP-2003		
32.090	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF:</b>	AFL		TSN:0			0		
324001	LEFT MAIN LANDING GEAR WHEEL 3-1527-2	MOS					26-OCT-2017		
32.100	1327	HRS/MSC	O/C				1366:36		
	<b>REF:</b> AMM 32-41-00	AFL		TSN:993			993		
324001	RIGHT MAIN LANDING GEAR WHEEL 3-1527-2	MOS					26-OCT-2017		
32.100	1367	HRS/MSC	O/C				1366:36		
	<b>REF:</b> AMM 32-41-00	AFL		TSN:993			993		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324002	NOSE LANDING GEAR WHEEL ASSY								
32.110	3-1418 6209 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSN:1110 TSO:0			01-MAR-2019 1516:10 1110		
324005	LEFT MLG TIRE								
32.100	277K08-1 61732209 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			26-OCT-2017 1366:36 993		
324005	RIGHT MLG TIRE								
32.100	277K08-1 61732211 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			26-OCT-2017 1366:36 993		
324007	NOSE LANDING GEAR TIRE								
32.110	184F08-1 71172529 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAR-2019 1516:10 1110		
324008	LEFT SHUTTLE VALVE								
32.120	195-191-1 SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324008	RIGHT SHUTTLE VALVE								
32.120	195-191-1 SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324016	LEFT MAIN LANDING GEAR BRAKE ASSY								
32.130	2-1559-3 (9912398-8) 1158 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			09-MAR-2016 1111:24 802		
324016	RIGHT MAIN LANDING GEAR BRAKE ASSY								
32.130	2-1559-3 1013 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C				24-MAY-2017 1311:36 945		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324101	POWER BRAKE AND ANTISKID VALVE								
32.140	38-747 653 REF: AMM 32-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324102	LEFT ANTISKID TRANSDUCER ASSEMBLY								
32.150	40-955 6512 REF: AMM 32-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324102	RIGHT ANTISKID TRANSDUCER ASSEMBLY								
32.150	40-955 6502 REF: AMM 32-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324103	BRAKE CONTROL BOX								
32.160	42-707-1 1388 REF: AMM 32-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324104	LEFT BRAKE CYLINDER ASSEMBLY								
32.170	95805 1263 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
324104	RIGHT BRAKE CYLINDER ASSEMBLY								
32.170	95805 1207 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
324104A	LEFT BRAKE CYLINDER ASSEMBLY								
32.180	95805-1 1264 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
324104A	RIGHT BRAKE CYLINDER ASSEMBLY								
32.180	95805-1 1229 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324105	PARKING BRAKE VALVE								
32.190	95853 0823A REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324106	HYDRAULIC PUMP MOTOR								
32.200	MP50B1 2593 REF: AMM 32-42-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324107	ANTISKID ACCUMULATOR								
32.210	57C57663 0051T REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324108	HYDRAULIC PRESSURE SWITCH								
32.220	GPP1250-29 0304754 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324109	BRAKE PRESSURE PUMP ASSY								
32.230	640929 (9912364-2) 3034A REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			09-MAR-2016 1111:24 802		
324110	EMERGENCY BRAKE VALVE ASSY								
32.240	878208-03 V332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
324111	LEFT MLG UP & LOCK SWITCH								
32.260	65-430087 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
324111	NLG UP & LOCK SWITCH								
32.250	65-430087 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324111	RIGHT MLG UP & LOCK SWITCH 65-430087 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
324112	PRESSURE ANTISKID SWITCH 38-747502 0703 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
325001	NOSE LANDING GEAR ASSEMBLY 6342000-30 22 REF: AMM 32-20-00	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
325002	NOSE STEERING BUNGEE ASSEMBLY 5565624-19 SN-UNKNOWN REF: AMM 32-50-00	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
326001	LEFT M/G DOWN&LOCK SWITCH 1EN118-6 SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
326001	RIGHT M/G DOWN&LOCK SWITCH 1EN118-6 SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
326002	N/G DOWN&LOCK SWITCH 1EN118-6 SN-UNKNOWN REF: AMM 32-31-01	MOS HRS/MSC AFL	O/C	TSN:0			23-SEP-2003 0 0		
326006	EMERGENCY GEAR BOTTLE 40005320-2 1634 REF: AMM 32-31-03 Manufacture Date: 01-MAR-1997	MOS HRS/MSC AFL	288				26-OCT-2017 1366:36 993	31-MAR-2021	

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326007	EMERGENCY GEAR GAUGE								
32.320	18225901 015967 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A320001 (s)	INSPECT MAIN AND NOSE GEAR ACTUATOR AXIAL MOVEMENT: INSPECTION DOCUMENT 08						PKG		
32.360	PKG 10 REF: AMM 32-00-00	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
A320002 (s)	ZONAL INSPECTION LANDING GEAR WHEEL WELL: INSPECTION DOCUMENT 10						PKG		
32.420	PKG 12 REF: AMM 32-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A320003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) LANDING GEAR: INSPECTION DOCUMENT 36						PKG		
	PKG 2201 REF: AMM 32-00-00	MOS HRS/MSC AFL	6	+2m			23-NOV-2018 1483 1083		
A320004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) LANDING GEAR: INSPECTION DOCUMENT 02						PKG		
	PKG 2 REF: AMM 32-00-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		
A323101	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE : INSPECTION DOCUMENT 04								
32.320	40005320-2 PKG 4 1634 REF: AMM 32-31-03	MOS HRS/MSC AFL	36				01-APR-2017	30-APR-2020	
A324103	SPECIAL DETAIL INSPECT LEFT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14						PKG		
32.100	3-1527-2 PKG 16 1327 REF: AMM 32-41-00	MOS HRS/MSC AFL	T/C				26-OCT-2017 1366:36 993		
A324103	SPECIAL DETAIL INSPECT NOSE LANDING GEAR WHEEL ASSY (NDI): INSPECTION DOCUMENT 14						PKG		
32.110	3-1418 PKG 16 6209 REF: AMM 32-41-00	MOS HRS/MSC AFL	T/C				01-MAR-2019 1516:10 1110		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A324103	SPECIAL DETAIL INSPECT RIGHT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14						PKG		
32.100	3-1527-2 PKG 16 1367 REF: AMM 32-41-00	MOS HRS/MSC AFL	T/C				26-OCT-2017 1366:36 993		
A325005 (s)	INSPECT FORK AND PISTON ASSEMBLY NOSE LANDING GEAR FORK: INSPECTION DOCUMENT MD						PKG		
32.030	6342000-32 PKG 52 SN-UNKNOWN REF: AMM 32-20-00	MOS HRS/MSC AFL	5000				23-SEP-2003 0 0		
B320001 (s)	FUNCTIONAL CHECK LANDING GEAR SYSTEM: INSPECTION DOCUMENT 10						PKG		
32.330	PKG 12 REF: AMM 32-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
B324202 (s)	FUNCTIONAL CHECK LANDING GEAR PNEUMATIC BRAKE SYSTEM: INSPECTION DOCUMENT 10						PKG		
32.350	PKG 12 REF: AMM 32-42-06	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
C320001 (s)	LUBRICATE LANDING GEAR: INSPECTION DOCUMENT 02						PKG		
32.390	PKG 2 REF: AMM 32-00-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		
D324201 (s)	DISCARD ANTISKID MOTOR/PUMP ASSEMBLY FILTER ELEMENT: INSPECTION DOCUMENT 10						PKG		
32.370	PKG 12 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
D324203 (s)	BRAKE RESERVOIR SUPPLY LINE FILTER CLEANING - COMPLETE TASK 32-42-04-160: INSPECTION DOCUMENT 10						PKG		
32.380	PKG 12 REF: AMM 32-42-04	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 33</b>	<b>LIGHTS</b>								
330001	CENTER PANEL LIGHTS DIMMER								
33.010	273-1 0303034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330001	LEFT PANEL LIGHTS DIMMER								
33.010	273-1 0303041 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
330001	RIGHT PANEL LIGHTS DIMMER								
33.010	273-1 0303033 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
330002	ELECTRICAL PANEL INVERTER								
33.020	EM2044-1 4001A REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
332001	L1 INDIRECT LIGHTING INVERTER								
33.030	6900113-3 4200 REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
332002	L2 INDIRECT LIGHTING INVERTER								
33.030	6900113-3 4145 REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
332003	L3 INDIRECT LIGHTING INVERTER								
33.040	6900113-3 4198 REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
332004	L4 INDIRECT LIGHTING INVERTER								
33.040	6900113-3 4197 REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
332005	R1 INDIRECT LIGHTING INVERTER								
33.050	6900113-3 4201 REF: AMM 33-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332006	R2 INDIRECT LIGHTING INVERTER 6900113-3	MOS					23-SEP-2003		
33.050	4204 REF: AMM 33-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
332007	R3 INDIRECT LIGHTING INVERTER 6900113-3	MOS					23-SEP-2003		
33.060	4205 REF: AMM 33-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
332008	R4 INDIRECT LIGHTING INVERTER 6900113-3	MOS					23-SEP-2003		
33.060	4250 REF: AMM 33-10-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
334001	GROUND RECOGNITION LIGHT 90033-13	MOS					23-SEP-2003		
33.070	013260 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
334003	LEFT ANTI COLLISION POWER SUPPLY 04-1502-1408	MOS					23-SEP-2003		
33.080	20313 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
334003	RIGHT ANTI COLLISION POWER SUPPLY 04-1502-1408	MOS					23-SEP-2003		
33.080	20288 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
334004	LEFT HOUSING ASSY-LANDING LIGHT LAMP 50033025-1	MOS					23-SEP-2003		
33.090	1444 REF: AMM 33-40-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
334004	RIGHT HOUSING ASSY-LANDING LIGHT LAMP 50033025-1	MOS					23-SEP-2003		
33.090	1446 REF: AMM 33-40-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334005	LEFT ANTI COLLISION LIGHT ASSY								
33.100	03-1302-1003 20967 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
334005	RIGHT ANTI COLLISION LIGHT ASSY								
33.100	03-1302-1004 21020 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
334006	LEFT EMERGENCY EXIT BATTERY PACK								
33.110	CBS28 0934 REF: AMM 33-50-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2009 760 462		
33FO-03 525/J	INDIRECT LIGHTING W/DELUXE REFRESHMENT CENTER FACTORY OPTION								
	50J FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
B335001 (s)	FUNCTIONAL CHECK EMERGENCY LIGHTING SYSTEM: INSPECTION DOCUMENT 10						PKG		
33.130	PKG 12 REF: AMM 33-50-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 34</b>	<b>NAVIGATION</b>								
340000	WINDSHEAR COMPUTER								
34.015	965-1206-011 1863 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341001	AOA COMPUTER								
34.010	C12406-3 101 REF: AMM 34-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341002	AOA CONTROLLER								
34.030	C12421-1 556 REF: AMM 34-13-02	MOS HRS/MSC AFL	O/C	TSN:0			13-OCT-2006 462		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341008	AOA INDICATOR C12405-1 9241 REF: AMM 34-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341009	AOA SENSOR C-12417-2 152996A-02 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-MAY-2016 1143 823		
341010	AFT RADIO ALTIMETER ANTENNA S67-2002 27187 REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341010	FORWARD RADIO ALTIMETER ANTENNA S67-2002 27196 REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341029	MARKER BEACON INDICATOR 066-01044-0001 1868 REF: AMM 34-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341031	TEMPERATURE PROBE SENSOR 0129G A47993 REF: AMM 34-11-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341033	AOA INDEXER C12463-3 521 REF: AMM 34-13-02	MOS HRS/MSC AFL	O/C	TSN:0			13-OCT-2006 462		
341055	CALIBRATION TEST LEFT AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 13 822-1109-002 PKG 15 1432C REF: See Workcard	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
34.460 FAR									



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341056	CALIBRATION TEST RIGHT AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 13								
34.465	822-1109-002 PKG 15 18MGM <b>REF:</b> See Workcard	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
341060	INSPECT RVSM SKIN WAVINESS CHECK: INSPECTION DOCUMENT 13								
34.595	PKG 15 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
341101	IAPS ICC 3001 CARD								
34.045	822-1459-001 13TDB <b>REF:</b> AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341102	NO. 1 IO PROCESSOR CARD								
34.055	822-1130-101 13PTP <b>REF:</b> AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341102	NO. 2 IO PROCESSOR CARD								
34.055	822-1130-101 13PTR <b>REF:</b> AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341103	NO. 1 CONFIGURATION STRAPPING UNIT								
34.065	822-1363-002 13NPN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
341103	NO. 2 CONFIGURATION STRAPPING UNIT								
34.065	822-1363-002 13NPJ <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342008	LEFT POWER IAPS SUPPLY								
34.085	822-1137-001 13RGM <b>REF:</b> AMM 34-14-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342008	RIGHT POWER IAPS SUPPLY								
34.085	822-1137-001 13RGJ REF: AMM 34-14-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342009	ENVIRONMENTAL CONTROL								
34.095	822-1167-001 135YN REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342010	COURSE PANEL								
34.125	822-1281-002 12W3V REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342010	LEFT OPERATION CONFIG MODULE								
34.105	822-1484-201 18P5C REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342010	RIGHT OPERATION CONFIG MODULE								
34.105	822-1484-201 18MYT REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342012	STANDBY AIRSPEED ALTIMETER								
34.115	WL102AMS6 AP694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-MAR-2016		
342012A	CALIBRATION TEST STANDBY AIRSPEED ALTIMETER (FAR 91.411) : INSPECTION DOCUMENT 13								
34.115	WL102AMS6 PKG 15 AP694 REF: GENERIC NO REF	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
342014	COURSE & HEADING PANEL								
34.125	822-1279-002 1904T REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSO:0			18-JUL-2007 559		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342015	LEFT AHRS COMPUTER								
34.135	822-1110-002 1420N REF: AMM 34-21-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342015	RIGHT AHRS COMPUTER								
34.135	822-1110-002 1420M REF: AMM 34-21-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342016	LEFT EXTERNAL COMPENSATION UNIT								
34.145	822-1200-998 28LJL REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSN:0			04-AUG-2008 679		
342016	RIGHT EXTERNAL COMPENSATION UNIT								
34.145	822-1200-003 13TYX REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342042	LEFT FLIGHT DIRECTOR MODE SELECTOR								
34.140	622-6209-019 18CHC REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342042	RIGHT FLIGHT DIRECTOR MODE SELECTOR								
34.140	622-6209-019 18G1G REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342043	CONTROL DISPLAY PANEL								
34.185	822-1134-102 18CTC REF: AMM 34-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342044	LEFT FLIGHT GUIDANCE COMPUTER								
34.195	822-1108-118 13LHP REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342044	RIGHT FLIGHT GUIDANCE COMPUTER								
34.195	822-1108-118 12LRL REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342050	LEFT FLUX DETECTOR								
34.210	822-1193-001 28673 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342050	RIGHT FLUX DETECTOR								
34.210	822-1193-001 28672 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342051	STANDBY HORIZONTAL SITUATION INDICATOR								
34.205	2855-01-1 MB2629 REF: AMM 34-21-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342054	CENTER FLIGHT ADAPTIVE DISPLAY MFD UNIT								
34.215	822-1753-220 12K4J REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:431			04-AUG-2008 679		
342054	LEFT FLIGHT ADAPTIVE DISPLAY UNIT								
34.215	822-1084-110 142VV REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342054	RIGHT FLIGHT ADAPTIVE DISPLAY UNIT								
34.215	822-1084-110 131ND REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342057	AFD CONTROL PANEL								
34.235	822-1746-102 24GXN REF: AMM 34-23-02	MOS HRS/MSC AFL	O/C	TSN:0			04-AUG-2008 679		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342063	STANDBY JET GYRO								
34.230	501-1568-56 6094 REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
342064	STANDBY GYRO POWER SUPPLY								
34.230	501-1682-01 80145 REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C				04-NOV-2016 1225 893		
342068	RIGHT CONTROL DISPLAY PANEL								
34.250	822-1134-102 18CTD REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
344001	ANTENNA GLIDESLOPE COUPLER								
34.260	82-70-01 1425 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
344005	RADAR TRANSCEIVER								
34.290	822-1050-004 1386K REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
344007	CENTER FMS CONFIGURATION MODULE								
34.300	11921 4869 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
344024	RADIO ALTIMETER INDICATOR								
34.320	622-2855-011 1464N REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
344025	RADIO ALTIMETER CONVERTER								
34.275	622-7209-003 18PXH REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345001	FORWARD DME #1 ANTENNA								
34.340	56-80-01 8310 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345002	NO. 1 DME RECEIVER/TRANSMITTER								
34.350	066-01070-0001 27767 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345003	LEFT DME INDICATOR								
34.360	066-01069-0014 84413 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345004	LEFT TOP DIVERSITY TRANSPONDER ANTENNA								
34.285	DMNI50-2-2 88324 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345004	NO. 1 TRANSPONDER ANTENNA								
34.370	DMNI50-2-2 87948 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345004	NO. 2 TRANSPONDER ANTENNA								
34.370	DMNI50-2-2 87830 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345004	RIGHT TOP DIVERSITY TRANSPONDER ANTENNA								
34.285	DMNI50-2-2 88308 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345005	MARKER BEACON ANTENNA								
34.380	31-10-01 4593 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345006	GLIDESLOPE ANTENNA								
34.380	RGS10-48 A8925 REF: AMM 34-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345008	LEFT DME 1 CONVERTER								
34.295	071-01227-0001 11187 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345011	NO. 1 ADF RECEIVER								
34.390	066-01072-0007 77010 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345012	NO. 1 ADF ANTENNA								
34.305	071-01234-0002 78934 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345022	LEFT NAVIGATION ANTENNA								
34.420	22-37-101 3685 REF: AMM 34-62-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			15-MAY-2015 1032 748		
345022	RIGHT NAVIGATION ANTENNA								
34.420	22-37-101 3684 REF: AMM 34-62-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			15-MAY-2015 1032 748		
345034	NO. 1 TRANSPONDER								
34.430	011-00455-30 84405504 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				17-APR-2018 1422:54 1033		
345034	NO. 2 TRANSPONDER								
34.430	011-00455-30 84405512 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				17-APR-2018 1422:54 1033		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345038A	UNIVERSAL CONTROL DISPLAY UNIT								
34.315	1117-1-104 3203 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-JAN-2016 1088 785		
345039	GPS 1 ANTENNA								
34.440	013-00235-00 77721 REF: AMM 34-57-05	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			18-NOV-2011		
345039	NO. 3 GPS 3 ANTENNA								
34.440	011-00147-00 SN-UNKNOWN REF: AMM 34-57-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345039	RIGHT GPS 2 ANTENNA								
34.440	013-00235-00 77735 REF: AMM 34-57-05	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			18-NOV-2011		
345046	FMS 1 COMPUTER								
34.345	3116-32-1116 198 REF: AMM 34-62-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			02-MAR-2012 903 628		
345053	NO. 1 COM/NAV/GPS GARMIN								
34.710	011-00835-10 46400166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345053	NO. 2 COM/NAV/GPS GARMIN								
34.710	011-00835-10 46400191 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
345066	FSU UNIT								
34.375	822-1543-101 28XWF REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			04-AUG-2008 679		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346006	STORMSCOPE PROCESSER								
34.740	78-8060-6086-5 80228 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
346007	STORMSCOPE ANTENNA								
34.745	78-8051-9200-8 80420 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
346009	LEFT AIR DATA COMPUTER								
34.460	822-1109-002 1432C REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C				16-MAR-2016		
346009	RIGHT AIR DATA COMPUTER								
34.465	822-1109-002 18MGM REF: AMM 34-22-00	MOS HRS/MSC AFL	O/C				16-MAR-2016		
346017	DATA TRANSFER UNIT								
34.415	1408-00-1 1550 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			18-NOV-2011		
346029	SKYWATCH HP DISPLAY								
34.425	805-11900-002 80029 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:462			13-OCT-2006 462		
346034	TCAS ANTENNA								
34.395	805-10003-001 SN-UNKNOWN REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
34FO-15 525/F	THIRD DISPLAY-COLLINS PROLINE 21 (EXCHANGE) FACTORY OPTION								
	607F FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B341011 34.530	FUNCTIONAL CHECK LEFT PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13 PKG 15 REF: AMM 34-11-02	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
B341011 34.530	FUNCTIONAL CHECK RIGHT PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13 PKG 15 REF: AMM 34-11-02	MOS HRS/MSC AFL	24		-20		05-APR-2018	31-MAR-2020	
B342100 (s) 34.555	FUNCTIONAL CHECK DIRECTIONAL GYRO COMPASS SYSTEM: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 34-21-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
B342101 (s) 34.510	CAPACITY CHECK AND PERIODIC CHECK PS-834 EMERGENCY POWER SUPPLY: INSPECTION DOCUMENT 02 PKG 2 REF: AMM 34-21-07	MOS HRS/MSC AFL	12	+2m			PKG 23-NOV-2018 1483 1083		
B342102 (s) 34.480	FUNCTIONAL CHECK COLLINS AHC-3000 (AHRs): INSPECTION DOCUMENT 10 PKG 12 REF: AMM 34-21-06	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
B345401 34.430 FAR	CALIBRATION CHECK NO. 1 TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13 011-00455-30 PKG 15 84405504 REF: See Workcard	MOS HRS/MSC AFL	24				05-APR-2018	30-APR-2020	
B345401 34.430 FAR	CALIBRATION CHECK NO. 2 TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13 011-00455-30 PKG 15 84405512 REF: See Workcard	MOS HRS/MSC AFL	24				05-APR-2018	30-APR-2020	
<b>CHAPTER 35</b>	<b>OXYGEN</b>								
350002 35.010	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE 176274-50 580867801 REF: AMM 35-00-00	MOS HRS/MSC AFL	60				01-SEP-2018	30-SEP-2023	



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350003	HYDROSTATIC TEST PORTABLE OXYGEN CYLINDER (DOT3AA)								
35.010	PN SN-UNKNOWN REF: AMM 35-00-00	MOS HRS/MSC AFL	N/R						
N/A EQUIPMENT NOT INSTALLED									
350004	HYDROSTATIC TEST OXYGEN BOTTLE (DOT SP-10945)								
35.010	176274-50 580867801 REF: AMM 35-00-00	MOS HRS/MSC AFL	N/R						
N/A EQUIPMENT NOT INSTALLED									
350006	OXYGEN BOTTLE								
35.010	176274-50 580867801 REF: AMM 35-31-00 Manufacture Date: 01-OCT-2013	MOS HRS/MSC AFL	180	TSR:5 TSR:0 TSR:0			01-MAR-2019 1516:10 1110		01-AUG-2028 M
LIFE LIMIT									
350007	OXYGEN PRESSURE GAGE								
35.020	C668512-0101 C23293 REF: AMM 35-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
351002	COPILOT OXYGEN MASK								
35.030	MC10-16-101 120655 REF: AMM 35-10-01	MOS HRS/MSC AFL	72	TSO:0 TSO:0 TSO:0	-18		17-APR-2018 1422:54 1033		31-MAR-2024
OVERHAUL									
351002	PILOT OXYGEN MASK								
35.030	MC10-16-101 96401 REF: AMM 35-10-01	MOS HRS/MSC AFL	72	TSO:0 TSO:0 TSO:0			31-MAY-2013 991 707		31-MAY-2019 M
OVERHAUL									
351004	LEFT ALTITUDE PRESSURE SWITCH								
35.040	P24031 2530 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351008	OXYGEN 3 POSITION VALVE								
35.050	P21007 1449 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
35FO-01 525/F	OXY-50 CU FT BOTTLE (EXCH) FACTORY OPTION								
	66F FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
A351001 (s)	DETAILED INSPECTION CREW OXYGEN MASKS: INSPECTION DOCUMENT 10						PKG		
35.070	PKG 12 REF: AMM 35-10-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A352001 (s)	DETAILED INSPECTION PASSENGER OXYGEN MASKS AND PASSENGER MASKS DROPOUT BOXES: INSPECTION DOCUMENT 02						PKG		
35.080	PKG 2 REF: AMM 35-20-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		
B350001 (s)	FUNCTIONAL CHECK OXYGEN SYSTEM: INSPECTION DOCUMENT 10						PKG		
35.060	PKG 12 REF: AMM 35-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 36</b>	<b>PNEUMATIC</b>								
361001	LEFT TEMPERATURE SENSOR								
36.010	27431501-05 3AW12 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361001	RIGHT TEMPERATURE SENSOR								
36.010	27431501-05 3AW13 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361002 (s)	LEFT B/A PRECOOLER ASSEMBLY								
36.020	9914402-6 S4883T0713 REF: AMM 36-10-00	MOS HRS/MSC AFL	84 2000	TSN:7 TSN:0 TSN:0			08-APR-2016 1123:34 809		
<b>LIFE LIMIT</b>									

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361002 (s)	RIGHT B/A PRECOOLER ASSEMBLY								
	9914402-6	MOS	84	TSN:7			08-APR-2016		
36.020	S4883T0715	HRS/MSC	2000	TSN:0			1123:34		
<b>LIFE LIMIT</b>	<b>REF: AMM 36-10-00</b>	AFL		TSN:0			809		
361004	LEFT PNEUMATIC SHUTOFF VALVE ASSY								
	2601-21	MOS					23-SEP-2003		
36.030	0740	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-10-00</b>	AFL		TSN:0			0		
361004	RIGHT PNEUMATIC SHUTOFF VALVE ASSY								
	2601-21	MOS					23-SEP-2003		
36.030	0751	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-10-00</b>	AFL		TSN:0			0		
361006	PRESSURE BLEED AIR REGULATOR								
	1H75-16	MOS					23-SEP-2003		
36.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-10-00</b>	AFL		TSN:0			0		
361007	DOOR SEAL CONTROL VALVE								
	MJV3	MOS					23-SEP-2003		
36.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-11-00</b>	AFL		TSN:0			0		
361007	LEFT OVER TEMP BLEED AIR SWITCH								
	1173T181-2	MOS					23-SEP-2003		
36.060	3978	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-11-00</b>	AFL		TSN:0			0		
361007	RIGHT OVER TEMP BLEED AIR SWITCH								
	1173T181-2	MOS					23-SEP-2003		
36.060	3987	HRS/MSC	O/C	TSN:0			0		
	<b>REF: AMM 36-11-00</b>	AFL		TSN:0			0		
361008	LEFT PRECOOLER DOOR VALVE								
	5060-00-01	MOS					23-SEP-2003		
36.070	4AV7	HRS/MSC	O/C	TSN:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		TSN:0			0		





# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361008	RIGHT PRECOOLER DOOR VALVE 5060-00-01 11AV33 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361009	LEFT CHECK VALVE 5253-00-1 0730 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361009	RIGHT CHECK VALVE 5253-00-1 0803 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361010	LEFT CHECK VALVE 1553-00-18 SN-UNKNOWN REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361010	RIGHT CHECK VALVE 1553-00-18 SN-UNKNOWN REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361011	LEFT PRECOOLER ACTUATOR 1H126-1 2417 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
361012	RIGHT PRECOOLER ACTUATOR 1H126-1 2418 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A361002	DETAILED INSPECTION LEFT B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22 9914402-6 PKG 36 S4883T0713 REF: AMM 36-10-01	MOS HRS/MSC AFL	300	+30			17-APR-2018 1422:54 1033	1722:54	1752:54

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A361002	DETAILED INSPECTION RIGHT B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22								
36.020	9914402-6 PKG 36 S4883T0715 REF: AMM 36-10-01	MOS HRS/MSC AFL	300	+30			17-APR-2018 1422:54 1033	1722:54	1752:54
<b>CHAPTER 52 DOORS</b>									
522001	DOOR INFLATABLE SEAL								
52.010	S15501-4 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0	23-SEP-2003 0 0		
522002	SECONDARY SEAL								
52.020	R441259 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0	23-SEP-2003 0 0		
522003	ESCAPE HATCH SEAL								
52.030	R441236 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0	23-SEP-2003 0 0		
522004	PRESSURE SWITCH								
52.040	P18M-30 3273 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0	23-SEP-2003 0 0		
A521001 (s)	DETAILED INSPECTION CABIN ENTRY DOOR: INSPECTION DOCUMENT MH						PKG		
52.060	PN PKG 56 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	6000			TSI:0 TSI:0 TSI:0	04-AUG-2008 679		
A521002 (s)	VISUAL INSPECTION CABIN ENTRY DOOR SEALS: INSPECTION DOCUMENT 33						PKG		
52.070	PKG 47 REF: AMM 52-10-00	MOS HRS/MSC AFL	12 300	+2m +30			23-NOV-2018 1483 1083		
A522001 (s)	DETAILED INSPECTION EMERGENCY ESCAPE HATCH: INSPECTION DOCUMENT MJ						PKG		
52.055	PKG 58 REF: AMM 52-20-00	MOS HRS/MSC AFL	7200			TSI:0 TSI:0 TSI:0	23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B521001 (s)	FUNCTIONAL CHECK DOOR INFLATABLE SEAL CABIN ENTRY DOOR SEAL: INSPECTION DOCUMENT 10						PKG		
52.010	S15501-4 PKG 12 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
C521001 (s)	LUBRICATE CABIN ENTRY DOOR: INSPECTION DOCUMENT 33						PKG		
52.050	PKG 47 REF: AMM 52-10-00	MOS HRS/MSC AFL	12 300	+2m +30			23-NOV-2018 1483 1083		
C522001 (s)	LUBRICATION EMERGENCY EXIT DOOR-SEAL: INSPECTION DOCUMENT 10						PKG		
	PKG 12 REF: AMM 52-20-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 53 FUSELAGE</b>									
531000	LEFT TRUNNION SUPPORT FITTING								
53.140	5513056-7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL					23-SEP-2003 0 0		22500
<b>LIFE LIMIT</b>			22500		TSN:0 TSN:0				
531000	RIGHT TRUNNION SUPPORT FITTING								
53.140	5513056-8 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL					23-SEP-2003 0 0		22500
<b>LIFE LIMIT</b>			22500		TSN:0 TSN:0				
531001	ACTUATOR SUPPORT FITTING								
53.150	6511105-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL					23-SEP-2003 0 0		22500
<b>LIFE LIMIT</b>			22500		TSN:0 TSN:0				
531201	RADOME ASSEMBLY								
53.010	6313101-47 SN-UNKNOWN REF: AMM 53-10-01	MOS HRS/MSC AFL	O/C				23-SEP-2003 0 0		
					TSN:0 TSN:0				
A530001 (s)	ZONAL INSPECTION NOSE SECTION: INSPECTION DOCUMENT 10						PKG		
53.040	PKG 12 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A530002 (s) 53.020	ZONAL INSPECTION COCKPIT AND CABIN ABOVE AND BELOW FLOORBOARD: INSPECTION DOCUMENT 29 PKG 43 REF: AMM 53-00-00	MOS HRS/MSC AFL	7200	+30			PKG 17-DEC-2009 760		
A530003 (s) 53.070	INSPECT INTERNAL EMPENNAGE ZONAL: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A530004 (s) 53.130	DETAILED INSPECTION CREW SEAT TRACKS/SEAT ATTACHMENT: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A530005 (s) 53.210	INSPECT COCKPIT AND CABIN BELOW FLOORBOARD ZONAL: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A530006 (s) 53.220	INSPECT EXTERNAL FUSELAGE ZONAL: INSPECTION DOCUMENT 10 PKG 12 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			PKG 01-MAR-2019 1516:10 1110		
A530007 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) NOSE LANDING GEAR WHEEL WELL: INSPECTION DOCUMENT 36 PKG 2201 REF: AMM 53-00-00	MOS HRS/MSC AFL	6	+2m			PKG 23-NOV-2018 1483 1083		
A530008 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) NOSE LANDING GEAR WHEEL WELL: INSPECTION DOCUMENT 02 PKG 2 REF: AMM 53-00-00	MOS HRS/MSC AFL	12	+2m			PKG 23-NOV-2018 1483 1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531001 (s)	INSPECTION FORWARD SIDE OF FORWARD PRESSURE BULKHEAD, STRINGERS AND BULKHEADS: INSPECTION DOCUMENT MI						PKG		
53.030	PKG 57 REF: AMM 53-10-05	MOS HRS/MSC AFL	7200				23-SEP-2003 0 0		
A531003 (s)	DETAILED INSPECTION WINDSHIELD,SIDE,AND CABIN WINDOW FRAMES: INSPECTION DOCUMENT MJ						PKG		
53.080	PKG 58 REF: AMM 53-10-07	MOS HRS/MSC AFL	7200				23-SEP-2003 0 0		
A531004 (s)	DETAILED INSPECTION CABIN DOOR FRAME: INSPECTION DOCUMENT MH						PKG		
53.090	PKG 56 REF: AMM 53-10-08	MOS HRS/MSC AFL	6000				04-AUG-2008 679		
A531005 (s)	INSPECT EMERGENCY ESCAPE HATCH DOORFRAME: INSPECTION DOCUMENT MJ						PKG		
53.100	PKG 58 REF: AMM 53-10-08	MOS HRS/MSC AFL	7200				23-SEP-2003 0 0		
A531010 (s)	INSPECTION FOR AIRPLANES -0001 THRU -0332. AFT PRESSURE BULKHEAD WEB(FORWARD SIDE) : INSPECTION DOCUMENT MI						PKG		
53.120	PKG 57 REF: AMM 53-10-05	MOS HRS/MSC AFL	7200	TSI:0 TSI:0 TSI:0			23-SEP-2003 0 0		
A531011 (s)	INSPECTION FOR AIRPLANES -0333 AND ON. AFT PRESSURE BULKHEAD WEB(FORWARD SIDE) : INSPECTION DOCUMENT MM						PKG		
53.120	PKG 61 REF: AMM 53-10-05	MOS HRS/MSC AFL	12000	TSI:0 TSI:0 TSI:0			23-SEP-2003 0 0		
A531012 (s)	INSPECTION FOR AIRPLANES -0001 THRU -0332. AFT PRESSURE BULKHEAD STRUCTURE (AFT SIDE) : INSPECTION DOCUMENT MI						PKG		
53.050	PKG 57 REF: AMM 53-10-05	MOS HRS/MSC AFL	7200	TSI:0 TSI:0 TSI:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531013 (s)	INSPECTION FOR AIRPLANES -0333 AND ON. AFT PRESSURE BULKHEAD STRUCTURE(AFT SIDE) : INSPECTION DOCUMENT MM						PKG		
53.050	PKG 61 REF: AMM 53-10-05	MOS HRS/MSC AFL	12000	TSI:0 TSI:0 TSI:0			23-SEP-2003 0 0		
A531016 (s)	DETAILED INSPECTION FOR AIRPLANES -0333 AND ON. AFT PRESSURE BULKHEAD RETAINING RING : INSPECTION DOCUMENT MN						PKG		
53.110	PKG 62 REF: AMM 53-10-05	MOS HRS/MSC AFL	12000	TSI:0 TSI:0 TSI:0			23-SEP-2003 0 0		
A533004 (s)	INSPECTION FUSELAGE SKIN JOINT EDDY CURRENT: INSPECTION DOCUMENT 11						PKG		
53.160	PKG 13 REF: AMM 53-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			26-OCT-2017 1366:36 993		
A533005 (s)	DETAILED INSPECTION FORWARD PRESSURE BULKHEAD RETAINING RING: INSPECTION DOCUMENT MI						PKG		
53.170	PKG 57 REF: AMM 53-10-05	MOS HRS/MSC AFL	7200				23-SEP-2003 0 0		
A533006 (s)	INSPECTION FUSELAGE EXTERIOR SKIN: INSPECTION DOCUMENT MG						PKG		
53.180	PKG 55 REF: AMM 53-30-00	MOS HRS/MSC AFL	6000				23-SEP-2003 0 0		
A533007 (s)	INSPECTION CABIN LOWER SKIN LONGITUDINAL SPLICE: INSPECTION DOCUMENT MF						PKG		
53.190	PKG 54 REF: AMM 53-30-00	MOS HRS/MSC AFL	6000				23-SEP-2003 0 0		
ASR-2011-064-ICA-11-00	INSPECTION OF GPS ANTENNA SEALANT AND AREA AROUND ANTENNA FOR CRACKS. - AS PER SM CAP 02 AN EXTENTION OF 1 MONTH CAN BE USED								
CUSTOMER CODE	REF: - CJ01	MOS HRS/MSC AFL	12				23-NOV-2018 1483 1083	30-NOV-2019	

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B531001 (s)	PERFORM NOSE RADOME ELECTRICAL BONDING CHECK: INSPECTION DOCUMENT 08						PKG		
53.200	PKG 10 REF: AMM 53-10-01	MOS HRS/MSC AFL	24 300	+2m +30			17-APR-2018 1422:54 1033		
<b>CHAPTER 54 NACELLES/PYLONS</b>									
A540001 (s)	ZONAL INSPECTION NACELLES AND PYLONS: INSPECTION DOCUMENT 10						PKG		
54.030	PKG 12 REF: AMM 54-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A545101 (s)	DETAILED INSPECTION PYLON FIREWALL (AIRPLANES -0001 THRU -0537 NOT INCORPORATING SB 525-54-04): INSPECTION DOCUMENT 18						PKG		
54.020	PKG 33 REF: AMM 54-51-00	MOS HRS/MSC AFL	150	+30			23-NOV-2018 1483 1083		
<b>CHAPTER 55 STABILIZERS</b>									
551010	EXAMINE HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS 4.78								
55.040	REF: AMM 55-10-00	MOS HRS/MSC AFL	14000				23-SEP-2003 0 0	14000	
<b>AIRWORTHINESS</b>									
A551001 (s)	DETAILED INSPECTION HORIZONTAL STABILIZER: INSPECTION DOCUMENT 10						PKG		
55.030	PKG 12 REF: AMM 55-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A551002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) HORIZONTAL STABILIZER AFT SPAR AREA: INSPECTION DOCUMENT 36						PKG		
	PKG 2201 REF: AMM 55-10-00	MOS HRS/MSC AFL	6	+2m			23-NOV-2018 1483 1083		
A551003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) HORIZONTAL STABILIZER AFT SPAR AREA: INSPECTION DOCUMENT 02						PKG		
	PKG 2 REF: AMM 55-10-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A553001 (s)	DETAILED INSPECTION VERTICAL STABILIZER: INSPECTION DOCUMENT 10						PKG		
55.010	PKG 12 REF: AMM 55-30-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A553002 (s)	INSPECTION VERTICAL STABILIZER FORWARD SPAR ATTACH BOLT HOLE: INSPECTION DOCUMENT MK						PKG		
55.020	PKG 59 REF: AMM 55-30-01	MOS HRS/MSC AFL	7900				23-SEP-2003 0 0		
A553003 (s)	INSPECTION VERTICAL STABILIZER AFT SPAR ATTACH BOLT HOLE: INSPECTION DOCUMENT MO						PKG		
55.020	PKG 63 REF: See Workcard	MOS HRS/MSC AFL	15200				23-SEP-2003 0 0		
A553004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) VERTICAL STABILIZER AFT SPAR AREA: INSPECTION DOCUMENT 36						PKG		
	PKG 2201 REF: AMM 55-30-01	MOS HRS/MSC AFL	6	+2m			23-NOV-2018 1483 1083		
A553005 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) VERTICAL STABILIZER AFT SPAR AREA: INSPECTION DOCUMENT 02						PKG		
	PKG 2 REF: AMM 55-30-01	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		

CHAPTER	56	WINDOWS
561001		LEFT WINDSHIELD ASSY, (LH)
56.010		P00042-1 477 REF: AMM 56-10-00
		MOS HRS/MSC AFL
		O/C
		TSN:0 TSN:0
		23-SEP-2003 0 0
561001		RIGHT WINDSHIELD ASSY, (LH)
56.010		P00042-2 566 REF: AMM 56-10-00
		MOS HRS/MSC AFL
		O/C
		TSN:0 TSN:0
		23-SEP-2003 0 0



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561002	L1 CABIN DOOR WINDOW								
56.020	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	L2 CABIN WINDOW								
56.020	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	L3 CABIN WINDOW								
56.030	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	L4 CABIN WINDOW								
56.030	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	R1 CABIN WINDOW								
56.040	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	R2 CABIN WINDOW								
56.040	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	R3 CABIN WINDOW								
56.050	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561002	R4 CABIN WINDOW								
56.050	161100-03 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561003	PILOT SIDE WINDOW								
56.060	6311263-1 0359 REF: AMM 56-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
561004	COPILOT SIDE WINDOW								
56.060	6311263-2 0246 REF: AMM 56-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A561001 (s)	INSPECTION WINDSHIELD OPTICAL PRISM: INSPECTION DOCUMENT 11						PKG		
56.070	PKG 13 REF: AMM 56-10-00	MOS HRS/MSC AFL	36 1200	+2m +30			26-OCT-2017 1366:36 993		
A561004 (s)	INSPECTION LEFT COCKPIT SIDE WINDOW OPTICAL PRISM: INSPECTION DOCUMENT MA						PKG		
56.080	PKG 50 REF: AMM 56-10-00	MOS HRS/MSC AFL	300				23-NOV-2018 1483 1083		
A561004 (s)	INSPECTION RIGHT COCKPIT SIDE WINDOW OPTICAL PRISM: INSPECTION DOCUMENT MA						PKG		
56.080	PKG 50 REF: AMM 56-10-00	MOS HRS/MSC AFL	300				23-NOV-2018 1483 1083		
<b>CHAPTER 57 WINGS</b>									
571000	LEFT AFT TRUNNION ATTACH FITTING								
57.060	6322070-21 SN-UNKNOWN REF: AMM 32-10-00	MOS HRS/MSC AFL		TSN:0 TSN:0			23-SEP-2003 0 0		23400
<b>LIFE LIMIT</b>			23400						
571000	RIGHT AFT TRUNNION ATTACH FITTING								
57.060	6322070-20 SN-UNKNOWN REF: AMM 32-10-00	MOS HRS/MSC AFL		TSN:0 TSN:0			23-SEP-2003 0 0		23400
<b>LIFE LIMIT</b>			23400						
571001	LEFT FORWARD TRUNNION ATTACH FITTING								
57.070	6322060-19 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL		TSN:0 TSN:0			23-SEP-2003 0 0		23400
<b>LIFE LIMIT</b>			23400						

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
571001	RIGHT FORWARD TRUNNION ATTACH FITTING 6322060-20 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	23400	TSN:0 TSN:0			23-SEP-2003 0 0		23400
57.070 LIFE LIMIT									
571002	LEFT SIDE BRACE FITTING 6322080-21 - REF: GENERIC NO REF	MOS HRS/MSC AFL	23400	TSN:0			23-SEP-2003 0 0		23400
57.080 LIFE LIMIT									
571002	RIGHT SIDE BRACE FITTING 6322080-24 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	23400	TSN:0 TSN:0			23-SEP-2003 0 0		23400
57.080 LIFE LIMIT									
571010	EXAMINE LOWER MAIN SPAR SPLICE AT WS 93.00 REF: GENERIC NO REF	MOS HRS/MSC AFL	13200				23-SEP-2003 0 0		13200
57.020 AIRWORTHINESS									
571015	EXAMINE LOWER REAR SPAR SPLICE AT WS 93.00 REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				23-SEP-2003 0 0		15000
57.030 AIRWORTHINESS									
571020	EXAMINE MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				23-SEP-2003 0 0		15000
57.040 AIRWORTHINESS									
571025	EXAMINE REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				23-SEP-2003 0 0		15000
57.050 AIRWORTHINESS									
571030	EXAMINE MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00) REF: GENERIC NO REF	MOS HRS/MSC AFL	15000				23-SEP-2003 0 0		15000
57.100 AIRWORTHINESS									

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A570001 (s)	INSPECT EXTERNAL WING ZONAL : INSPECTION DOCUMENT 10						PKG		
57.010	PKG 12 REF: AMM 57-00-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
A570002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) MAIN LANDING GEAR WHEEL WELL: INSPECTION DOCUMENT 36						PKG		
	PKG 2201 REF: AMM 57-00-00	MOS HRS/MSC AFL	6	+2m			23-NOV-2018 1483 1083		
A570003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) AFT WING SPAR AREA: INSPECTION DOCUMENT 36						PKG		
	PKG 2201 REF: AMM 57-00-00	MOS HRS/MSC AFL	6	+2m			23-NOV-2018 1483 1083		
A570004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) MAIN LANDING GEAR WHEEL WELL: INSPECTION DOCUMENT 02						PKG		
	PKG 2 REF: AMM 57-00-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		
A570005 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECT) AFT WING SPAR AREA: INSPECTION DOCUMENT 02						PKG		
	PKG 2 REF: AMM 57-00-00	MOS HRS/MSC AFL	12	+2m			23-NOV-2018 1483 1083		
<b>CHAPTER 71</b>	<b>POWER PLANT</b>								
712001	LEFT ENGINE AFT ISOLATOR MOUNT								
71.010	LM601SA4 LK1216 REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE		TSN:0 TSN:0		23-SEP-2003 0 0		
712001	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT								
71.020	LM601SA5 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE		TSN:0 TSN:0		23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712001	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT								
71.020	LM601SA5 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE	TSN:0 TSN:0			23-SEP-2003 0 0		
712001	RIGHT ENGINE AFT ISOLATOR MOUNT								
71.010	LM601SA4 LK1102 REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE	TSN:0 TSN:0			23-SEP-2003 0 0		
712001	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT								
71.030	LM601SA5 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE	TSN:0 TSN:0			23-SEP-2003 0 0		
712001	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT								
71.030	LM601SA5 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	DUE	TSN:0 TSN:0			23-SEP-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	45700-104 2057 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0			23-SEP-2003 0 0		
71EN2	NO. 2 ENGINE								
71.EN2	45700-104 2058 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0			23-SEP-2003 0 0		
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104									
720007	NO. 1 ENGINE - 1ST LP TURBINE NOZZLE								
	57375 AU01495 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723001	NO. 1 ENGINE - FAN ROTOR 65501 AU00073 REF: See Workcard	MOS HRS/MSC ENC	16500	TSN:0			23-SEP-2003 0 0		(16500) 16500
+ 723003 (s)	NO. 1 ENGINE - CLEAN FAN ROTOR AND PHYSICALLY INSPECT FOR DEFECTS (FEEL WITH FINGERS) 65501 PKG 2 AU00073 REF: LM 72-31-20	MOS HRS/MSC ENC	600	+30			23-NOV-2018 1483 1083		
723010	NO. 1 ENGINE - HP COMPRESSOR ROTOR 60442 HW15235 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:0			23-SEP-2003 0 0		(8000) 8000
723015	NO. 1 ENGINE - IP COMPRESSOR ROTOR 66032 HW15490 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0			23-SEP-2003 0 0		(10000) 10000
723021 (s)	NO. 1 ENGINE - VISUALLY INSPECT THE INSTALLED SPINNER PKG 2 REF: LM 72-30-10	MOS HRS/MSC ENC	600	+30			23-NOV-2018 1483 1083		
723022	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY 67894 AU01859 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
723061	NO. 1 ENGINE - HIGH PRESSURE SHAFT 64711 AU00923 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
723092	NO. 1 ENGINE - COMPLETE LP SHAFT ASSEMBLY 64574 RX1SN10653 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723149	NO. 1 ENGINE - HP COMPRESSOR COVER ASSY 65593 AU02100 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
724035	NO. 1 ENGINE - HP TURBINE ROTOR ASSEMBLY 65442 RRL1259 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
724040	NO. 1 ENGINE - REAR FUEL SLINGER SEAL ASSEMBLY 55608 AU03066 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
725010	NO. 1 ENGINE - HP TURBINE DISK 59494 RRL7S00629 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000 8000	TSN:0 TSN:0			23-SEP-2003 0 0	(8000) 8000 (8000) 8000	
725020	NO. 1 ENGINE - 1ST LP TURBINE DISK 50255 RRL7S02561 REF: GENERIC NO REF	MOS HRS/MSC ENC	14700	TSN:0			23-SEP-2003 0 0	(14700) 14700	
725030	NO. 1 ENGINE - 2ND LP TURBINE DISK 50792 RRL7S02655 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0			23-SEP-2003 0 0	(13500) 13500	
726011	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY 66882 WL02917 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
<b>ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104</b>									
720007	NO. 2 ENGINE - 1ST LP TURBINE NOZZLE 57375 AU01839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723001	NO. 2 ENGINE - FAN ROTOR 65501 AU00074 REF: See Workcard	MOS HRS/MSC ENC	16500	TSN:0			23-SEP-2003 0 0		(16500) 16500
+ 723003 (s)	NO. 2 ENGINE - CLEAN FAN ROTOR AND PHYSICALLY INSPECT FOR DEFECTS (FEEL WITH FINGERS) 65501 PKG 2 AU00074 REF: LM 72-31-20	MOS HRS/MSC ENC	600	+30			23-SEP-2003 23-NOV-2018 1483 1083		
723010	NO. 2 ENGINE - HP COMPRESSOR ROTOR 60442 HW15241 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:0			23-SEP-2003 0 0		(8000) 8000
723015	NO. 2 ENGINE - IP COMPRESSOR ROTOR 66032 HW15841 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0			23-SEP-2003 0 0		(10000) 10000
723021 (s)	NO. 2 ENGINE - VISUALLY INSPECT THE INSTALLED SPINNER PKG 2 REF: LM 72-30-10	MOS HRS/MSC ENC	600	+30			23-SEP-2003 23-NOV-2018 1483 1083		
723022	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY 67894 AU01856 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
723061	NO. 2 ENGINE - HIGH PRESSURE SHAFT 64711 AU00940 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
723092	NO. 2 ENGINE - COMPLETE LP SHAFT ASSEMBLY 64574 RX1SN10651 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723149	NO. 2 ENGINE - HP COMPRESSOR COVER ASSY 65593 AU02019 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
724035	NO. 2 ENGINE - HP TURBINE ROTOR ASSEMBLY 65442 RRL1283 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
724040	NO. 2 ENGINE - REAR FUEL SLINGER SEAL ASSEMBLY 55608 AU03067 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
725010	NO. 2 ENGINE - HP TURBINE DISK 59494 RRL7S00625 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000 8000	TSN:0 TSN:0			23-SEP-2003 0 0	<b>(8000) 8000</b> <b>(8000) 8000</b>	
725020	NO. 2 ENGINE - 1ST LP TURBINE DISK 50255 RRL7S02723 REF: GENERIC NO REF	MOS HRS/MSC ENC	14700	TSN:0			23-SEP-2003 0 0	<b>(14700) 14700</b>	
725030	NO. 2 ENGINE - 2ND LP TURBINE DISK 50792 RRL7S02518 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0			23-SEP-2003 0 0	<b>(13500) 13500</b>	
726011	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY 66882 WL02936 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
730001	LEFT ENGINE FUEL PRESSURE SWITCH 1103P0448 6027 REF: AMM 73-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730001	RIGHT ENGINE FUEL PRESSURE SWITCH 1103P0448	MOS					23-SEP-2003		
73.010	6003 REF: AMM 73-30-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732002	SYNCHRONIZER CONTROLLER 213693	MOS					23-SEP-2003		
73.020	13483294 REF: AMM 76-13-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732003	ENGINE SYNCHRONIZER ACTUATOR 5485-066	MOS					23-SEP-2003		
73.030	13442086 REF: AMM 76-13-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
733001	LEFT ENGINE FUEL FLOW TRANSMITTER 1573-4	MOS					08-APR-2016		
73.040	0715 REF: AMM 73-30-01	HRS/MSC AFL	O/C	TSO:6 TSO:0 TSO:0			1123:34 809		
733001	RIGHT ENGINE FUEL FLOW TRANSMITTER 1573-4	MOS					23-SEP-2003		
73.040	1515 REF: AMM 73-30-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
B732001 (s)	OPERATIONAL CHECK FUEL CONTROL TEMPERATURE SENSOR TUBE (TT2): INSPECTION DOCUMENT 10						PKG		
73.050	PKG 12 REF: AMM 73-20-01	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104</b>									
730002	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY 50817	MOS					23-NOV-2018		
	BCC-00003415 REF: See Workcard	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			1483 1083		
731001	NO. 1 ENGINE - FUEL PUMP 54904	MOS					23-SEP-2003		
OVERHAUL	YYK1378 REF: See Workcard	HRS/MSC ENC	5000	+100	TSN:0 TSN:0		0 0	(5000) 5000	5100



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005 (s)	NO. 1 ENGINE - (RENTAL ENGINES ONLY) REPLACE FUEL FLOW TO OIL COOLER FUEL TUBE ASSEMBLY AND HMU-TO-OIL COOLER FUEL TUBE ASSEMBLY PKG 2 REF: See Workcard	MOS HRS/MSC ENC	A/R				PKG 23-NOV-2018 1483 1083		
+ 731010 (s)	NO. 1 ENGINE - VISUALLY INSPECT AND CLEAN FUEL START NOZZLE AND START NOZZLE ADAPTER PKG 1,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 731015 (s)	NO. 1 ENGINE - CHECK FUEL START NOZZLE SPRAY PATTERN PKG 1,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
731025 (s)	NO. 1 ENGINE - CHANGE FUEL PUMP FILTER PKG 1,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
732090	NO. 1 ENGINE - START NOZZLE CONTROL VALVE 50803 RF13443979 OVERHAUL REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSN:0 TSN:0		23-SEP-2003 0 0	(5000) 5000	5100
732301	NO. 1 ENGINE - ELEC FUEL FILTER INDICATOR 57847 GE1456 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0		23-SEP-2003 0 0		
732401	NO. 1 ENGINE - FUEL CONTROL (HMU) UNIT 55629 RF13394325 OVERHAUL REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSN:0 TSN:0		23-SEP-2003 0 0	(5000) 5000	5100
ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104									
730002	NO. 2 ENGINE - FUEL NOZZLE ASSEMBLY 50817 BCC-00002005 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		23-NOV-2018 1483 1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731001	NO. 2 ENGINE - FUEL PUMP 54904 YYK1375 REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSN:0 TSN:0		23-SEP-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									
731005 (s)	NO. 2 ENGINE - (RENTAL ENGINES ONLY) REPLACE FUEL FLOW TO OIL COOLER FUEL TUBE ASSEMBLY AND HMU-TO-OIL COOLER FUEL TUBE ASSEMBLY PKG 2 REF: See Workcard	MOS HRS/MSC ENC	A/R				23-NOV-2018 1483 1083		
+ 731010 (s)	NO. 2 ENGINE - VISUALLY INSPECT AND CLEAN FUEL START NOZZLE AND START NOZZLE ADAPTER PKG 1,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			23-NOV-2018 1483 1083		
+ 731015 (s)	NO. 2 ENGINE - CHECK FUEL START NOZZLE SPRAY PATTERN PKG 1,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			23-NOV-2018 1483 1083		
731025 (s)	NO. 2 ENGINE - CHANGE FUEL PUMP FILTER PKG 1,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			23-NOV-2018 1483 1083		
732090	NO. 2 ENGINE - START NOZZLE CONTROL VALVE 50803 RF13443978 REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSN:0 TSN:0		23-SEP-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									
732301	NO. 2 ENGINE - ELEC FUEL FILTER INDICATOR 57847 GE1452 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0		23-SEP-2003 0 0		
732401	NO. 2 ENGINE - FUEL CONTROL (HMU) UNIT 55629 RF13443975 REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSN:0 TSN:0		23-SEP-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									

## CHAPTER 74 IGNITION

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue  
(ENG/APU) = Engine/APU Units



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104									
741010	NO. 1 ENGINE - INBOARD IGNITION EXCITER 68145 CK0300311 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
741020	NO. 1 ENGINE - OUTBOARD IGNITION EXCITER 68145 CK0300351 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
742001	NO. 1 ENGINE - SHORT IGNITOR LEAD 70163 NSN REF: See Workcard	MOS HRS/MSC ENC	O/C				09-JUN-2010 761 463		
742002	NO. 1 ENGINE - LONG IGNITOR LEAD 50853 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
+ 742037 (s)	NO. 1 ENGINE - VISUALLY INSPECT IGNITER PLUGS PKG 1,2 REF: LM 74-22-01	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 742040 (s)	NO. 1 ENGINE - OPERATIONAL TEST IGNITION SYSTEM PKG 1,2 REF: LM 74-00-10	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
742050 (s)	NO. 1 ENGINE - DIMENSIONALLY INSPECT IGNITER PLUGS PKG 1,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
742201	NO. 1 ENGINE - INBOARD IGNITOR CH31956 09044687 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0			09-JUN-2010 761 463		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742201	NO. 1 ENGINE - OUTBOARD IGNITOR CH31956 4004831 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0			19-AUG-2004 172		
ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104									
741010	NO. 2 ENGINE - INBOARD IGNITION EXCITER 68145 CK0200651 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0			16-JAN-2008 629		
741020	NO. 2 ENGINE - OUTBOARD IGNITION EXCITER 68145 CK0300310 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
742001	NO. 2 ENGINE - SHORT IGNITOR LEAD 50852 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
742002	NO. 2 ENGINE - LONG IGNITOR LEAD 50853 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
+ 742037 (s)	NO. 2 ENGINE - VISUALLY INSPECT IGNITER PLUGS PKG 1,2 REF: LM 74-22-01	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 742040 (s)	NO. 2 ENGINE - OPERATIONAL TEST IGNITION SYSTEM PKG 1,2 REF: LM 74-00-10	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
742050 (s)	NO. 2 ENGINE - DIMENSIONALLY INSPECT IGNITER PLUGS PKG 1,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742201	NO. 2 ENGINE - INBOARD IGNITOR CH31956 4004799 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0			19-AUG-2004 172		
742201	NO. 2 ENGINE - OUTBOARD IGNITOR CH31956 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0			20-OCT-2005 316		
<b>CHAPTER 75 AIR</b>									
ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104									
+ 753010 (s)	NO. 1 ENGINE - INSPECT ACCELERATION BLEED SYSTEM PKG 2 REF: LM 75-30-01	MOS HRS/MSC ENC	600	+30			PKG 23-NOV-2018 1483 1083		
ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104									
+ 753010 (s)	NO. 2 ENGINE - INSPECT ACCELERATION BLEED SYSTEM PKG 2 REF: LM 75-30-01	MOS HRS/MSC ENC	600	+30			PKG 23-NOV-2018 1483 1083		
<b>CHAPTER 77 ENGINE INDICATING</b>									
771003	STANDBY N1 INDICATOR 10645N01R01 B0130A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0			08-JUN-2004 152		
771004	COMPUTER-N1 C-13232-1 698 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
774002	LEFT FWD DCU CONCENTRATOR UNIT 822-1278-001 142WY REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774002	RIGHT FWD DCU CONCENTRATOR UNIT								
77.030	822-1278-001 146BF REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
774002A	LEFT AFT CONCENTRATOR UNIT								
77.020	822-1278-001 142XC REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
774002A	RIGHT AFT CONCENTRATOR UNIT								
77.020	822-1278-001 146BD REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
77FO-01 525	N1 COMPUTER C13232-1 SAFEFLIGHT FACTORY OPTION								
	680 FO REF:	MOS HRS/MSC AFL	-				23-SEP-2003 0 0		
ENGINE NO. 1 Model : FJ44-1A Serial # 2057 Part # 45700-104									
771005	NO. 1 ENGINE - N1 DUAL MAGNETIC SPEED SENSOR								
	50867 YYV1359 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
771015	NO. 1 ENGINE - N2 DUAL MAGNETIC SPEED SENSOR								
	50866 YYV1266 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 1 ENGINE - NO. 1 ITT PROBE								
	62142 YYF002531 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 1 ENGINE - NO. 2 ITT PROBE								
	62142 YYF002533 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		





# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772001	NO. 1 ENGINE - NO. 3 ITT PROBE 62141 YYF008571 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 1 ENGINE - NO. 4 ITT PROBE 62141 YYF008572 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 1 ENGINE - NO. 5 ITT PROBE 62141 YYF008273 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 1 ENGINE - NO. 6 ITT PROBE 62142 YYF002532 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104									
771005	NO. 2 ENGINE - N1 DUAL MAGNETIC SPEED SENSOR 50867 YYV1341 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
771015	NO. 2 ENGINE - N2 DUAL MAGNETIC SPEED SENSOR 50866 YYV1265 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 2 ENGINE - NO. 1 ITT PROBE 62141 YYF008581 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 2 ENGINE - NO. 2 ITT PROBE 62141 YYF008582 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772001	NO. 2 ENGINE - NO. 3 ITT PROBE 62141 YYF008583 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 2 ENGINE - NO. 4 ITT PROBE 62141 YYF008584 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 2 ENGINE - NO. 5 ITT PROBE 62141 YYF008585 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
772001	NO. 2 ENGINE - NO. 6 ITT PROBE 62141 YYF008586 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
<b>CHAPTER 78 EXHAUST</b>									
783001	LEFT T/A SWITCH 602EN602-6 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783001	RIGHT T/A SWITCH 602EN602-6 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783002	LEFT T/A PADDLE ASSY 6354051-79 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783002	RIGHT T/A PADDLE ASSY 6354051-79 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783003	LEFT ATTENUATOR ACTUATOR								
78.040	6317105-13 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783003	RIGHT ATTENUATOR ACTUATOR								
78.040	6317105-13 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783005	LEFT THRUST ATTENUATOR BELLCRANK								
78.050	6354051-103 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
783005	RIGHT THRUST ATTENUATOR BELLCRANK								
78.050	6354051-104 SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
A783000 (s)	DETAILED INSPECTION THRUST ATTENUATOR PADDLE: INSPECTION DOCUMENT 10						PKG		
78.100	PKG 12 REF: AMM 78-30-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
B783001 (s)	FUNCTION CHECK THRUST ATTENUATORS (AIRPLANES -0001 THRU -0599): INSPECTION DOCUMENT 10						PKG		
78.060	PKG 12 REF: AMM 78-30-00	MOS HRS/MSC AFL	36 1200	+2m +30			01-MAR-2019 1516:10 1110		
<b>CHAPTER 79 OIL</b>									
793002	LEFT ENGINE OIL TEMPERATURE TRANSMITTER								
79.020	MS28034-3 101271 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
793002	RIGHT ENGINE OIL TEMPERATURE TRANSMITTER								
79.020	MS28034-3 101240 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793004	LEFT ENGINE OIL PRESSURE TRANSMITTER								
79.030	APTE304-1000-200G 67859189 REF: AMM 79-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
793004	RIGHT ENGINE OIL PRESSURE TRANSMITTER								
79.030	APTE304-1000-200G 67859212 REF: AMM 79-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
793006	LEFT ENGINE OIL PRESSURE SWITCH								
79.040	S1103P89-3 1571 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0			02-AUG-2005 296		
793006	RIGHT ENGINE OIL PRESSURE SWITCH								
79.040	S1103P89-3 1870 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			03-AUG-2005 297		

ENGINE NO.	Model	Serial #	Part #						
ENGINE NO. 1	FJ44-1A	2057	45700-104						
+ 792010 (s)	NO. 1 ENGINE - REMOVE OIL FILTER AND SUBMIT FOR ANALYSIS					PKG			
	PKG 1,2	MOS					23-NOV-2018		
		HRS/MSC	300	+30			1483		
	REF: LM 72-00-05	ENC					1083		
+ 792015 (s)	NO. 1 ENGINE - INSTALL NEW OIL FILTER					PKG			
	PKG 1,2	MOS					23-NOV-2018		
		HRS/MSC	300	+30			1483		
	REF: See Workcard	ENC					1083		
+ 792020 (s)	NO. 1 ENGINE - REMOVE/INSPECT MAGNETIC CHIP COLLECTORS					PKG			
	PKG 1,2	MOS					23-NOV-2018		
		HRS/MSC	300	+30			1483		
	REF: See Workcard	ENC					1083		
+ 792025 (s)	NO. 1 ENGINE - CHANGE OIL					PKG			
	PKG 2	MOS					23-NOV-2018		
		HRS/MSC	600	+30			1483		
	REF: LM 72-00-03	ENC					1083		

# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792201	NO. 1 ENGINE - LUBE OIL COOLER 65664 PP0118 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
792401	NO. 1 ENGINE - LUBE AND SCAVENGE PUMP 60689 WL01764 REF: See Workcard	MOS HRS/MSC ENC	5000	+100 TSN:0 TSN:0			23-SEP-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									
<b>ENGINE NO. 2 Model : FJ44-1A Serial # 2058 Part # 45700-104</b>									
+ 792010 (s)	NO. 2 ENGINE - REMOVE OIL FILTER AND SUBMIT FOR ANALYSIS PKG 1 ,2 REF: LM 72-00-05	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 792015 (s)	NO. 2 ENGINE - INSTALL NEW OIL FILTER PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 792020 (s)	NO. 2 ENGINE - REMOVE/INSPECT MAGNETIC CHIP COLLECTORS PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 23-NOV-2018 1483 1083		
+ 792025 (s)	NO. 2 ENGINE - CHANGE OIL PKG 2 REF: LM 72-00-03	MOS HRS/MSC ENC	600	+30			PKG 23-NOV-2018 1483 1083		
792201	NO. 2 ENGINE - LUBE OIL COOLER 65664 PP0114 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-SEP-2003 0 0		
792401	NO. 2 ENGINE - LUBE AND SCAVENGE PUMP 60689 WL01766 REF: See Workcard	MOS HRS/MSC ENC	5000	+100 TSN:0 TSN:0			23-SEP-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									



# Status Report

525 - CJ1 S/N 525-0519 (SE-RMH): 1549:42 HRS, 1137 AFL as of 21-Mar-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 24-APR-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 80</b>	<b>STARTING</b>								
801101	LEFT ENGINE STARTER/GENERATOR								
	300SGL129Q	MOS		TSO:0			17-APR-2018		
80.010	6300XL2	HRS/MSC	1000	TSO:0			1422:54		<b>2422:54</b>
<b>OVERHAUL</b>	<b>REF: AMM 80-10-00</b>	<b>AFL</b>		<b>TSO:0</b>			<b>1033</b>		
801101	RIGHT ENGINE STARTER/GENERATOR								
	300SGL129Q	MOS		TSO:0			08-SEP-2011		
80.010	1437XL2	HRS/MSC	1000	TSO:0			875:05		<b>1875:05</b>
<b>OVERHAUL</b>	<b>REF: AMM 80-10-00</b>	<b>AFL</b>		<b>TSO:0</b>			<b>599</b>		