

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
 LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 876/LX-JFQ **MODEL:** PC12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 31-JAN-2008	6156:25 A/C HRS as of 20-JAN-2020	A/C HRS as of ___/___/___
	5601 AFL as of 20-JAN-2020	AFL as of ___/___/___
	16:42 ACH as of 26-APR-2019	ACH as of ___/___/___
	5002 FLTS as of 20-JAN-2020	FLTS as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0764/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-APR-2016	LAST ACTUALS	CURRENT ACTUAL
3884:45 ENG. HRS 4028:50 A/C HRS	6012:20 ENG. HRS as of 20-JAN-2020	ENG. HRS as of ___/___/___
3159 ENC	4940 ENC as of 20-JAN-2020	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: KX568/HC-E4A-3D/E10477K **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 25-MAY-2015	LAST ACTUALS	CURRENT ACTUAL
2537:10 PROP HRS 3448:25 A/C HRS	5245:10 PROP HRS as of 20-JAN-2020	PROP HRS as of ___/___/___



Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05200A	JOB SET UP / CLOSE UP PACKAGE								
	PKG 17	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: AMM 05-20-00	AFL					0		
05401A	300 HOUR INSPECTION								
+									
	PKG 18	MOS					20-SEP-2019		
		HRS/MSC	300				5983:25	6283:25	6313:25
	REF: AMM 05-40-01	AFL					5444		
05402A	300 HOUR OR 12 MONTHS INSPECTION								
+									
	PKG 3	MOS	12				20-SEP-2019	20-SEP-2020	
		HRS/MSC	300				5983:25	6283:25	6313:25
	REF: AMM 05-40-01	AFL					5444		
05403A	600 HOUR INSPECTION								
+									
	PKG 19	MOS					26-APR-2019		
		HRS/MSC	600				5788:15	6388:15	6448:15
	REF: AMM 05-40-01	AFL					5294		
05404A	600 HOUR OR 12 MONTHS INSPECTION								
+									
	PKG 20	MOS	12				26-APR-2019	26-APR-2020	
		HRS/MSC	600				5788:15	6388:15	6418:15
	REF: AMM 05-40-01	AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A +	1200 HOUR OR 12 MONTHS INSPECTION								
	PKG 21	MOS	12				26-APR-2019	26-APR-2020	
		HRS/MSC	1200	+30/-30			5788:15	6988:15	7018:15
	REF: AMM 05-40-01	AFL					5294		
05406A +	2400 HOUR OR 24 MONTHS INSPECTION								
	PKG 22	MOS	24	+1m/-1m			26-APR-2019	26-APR-2021	26-MAY-2021
		HRS/MSC	2400	+30/-30			5788:15	8188:15	8218:15
	REF: AMM 05-40-01	AFL					5294		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0764 Part # 3042200									
057010	NO. 1 ENGINE - MINOR INSPECTION								
	PKG 0 in PKG 1	MOS					20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5839:20	(6139:20) 6283:25	6169:20
	REF: See Workcard	ENC					4783		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0764 Part # 3042200									
72JFL01	NO. 1 ENGINE - MINOR INSPECTION								
	PKG 1	MOS					20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5839:20	(6139:20) 6283:25	6169:20
	REF:	ENC					4783		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 17	MOS					26-APR-2019		
	REF:	HRS/MSC	A/R				5788:15		
		AFL					5294		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 17	MOS					26-APR-2019		
	REF:	HRS/MSC	A/R				5788:15		
		AFL					5294		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 17	MOS					31-JAN-2008		
	REF:	HRS/MSC	A/R				0		
		AFL					0		
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
		MOS					28-NOV-2019		
	REF:	HRS/MSC	-				6082:30		
		AFL					5531		
00JFL64	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 4 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
		MOS					26-APR-2019		
	REF:	HRS/MSC	-				5788:15		
		AFL					5294		
00JFL65	PERFORM PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 5 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
		MOS					20-SEP-2019		
	REF:	HRS/MSC	-				5983:25		
		AFL					5444		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS						04-APR-2014	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF	MOS						04-MAY-2016	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-160717	REVIEW PILATUS PC12 AMM REV 32	MOS						23-NOV-2016	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS						07-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS						29-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-190517	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38	MOS						19-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-150404	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 22 DATED NOV 16/2012 RCF	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25	MOS						16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0	MOS						03-JUN-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26	MOS						01-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1	MOS						31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0	MOS						16-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1	MOS					04-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2	MOS					11-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF E072-170818	HRS/MSC - ENC							
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0	MOS					22-FEB-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
	NEW REQUIREMENT ADDED ON 26-DEC-2019 (EFFECTIVE: 05-DEC-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX568 Part # HC-E4A-3D/E10477K									
P019-150423	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS						31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS						16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS						22-FEB-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS HRS/MSC -					06-JUN-2019		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								

CHAPTER	04	LIMITATIONS						
+	040001	AIRCRAFT LIMIT OF VALIDITY						
		PN	MOS		N:0		31-JAN-2008	
		SN-UNKNOWN	HRS/MSC	25000	N:0		0	25000
	LIFE LIMIT	REF:	AFL	30000	N:0		0	30000
+	040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY						
		PN	MOS		N:0		31-JAN-2008	
		SN-UNKNOWN	HRS/MSC	35000	N:0		0	35000
	LIFE LIMIT	REF:	AFL	43000	N:0		0	43000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF:	AFL	43000	N:0			0		43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-01	UNSCCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-02	UNSCCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-03	UNSCCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-04	UNSCCHEDULED INSPECTION - CHECK AFTER SUDDEN PROPELLER STOPPAGE								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-05	UNSCCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-06	UNSCCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					31-JAN-2008		
	REF: AMM 05-10-30	HRS/MSC	20000				0		20000
		AFL	27000				0		27000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					31-JAN-2008		
	REF:	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
05JFL11	AIRWORTHINESS REVIEW CERTIFICATE	MOS					24-FEB-2019	09-MAR-2020 M	
	REF:	HRS/MSC	DUE				5690		
		AFL					5210		
05JFL12	- CERTIFICATE OF REGISTRATION	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL13	- NOISE CERTIFICATE	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL14	- AIRCRAFT STATION LICENCE	MOS					16-NOV-2018	31-DEC-2021 M	
	REF:	HRS/MSC	DUE						
		AFL							
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING	MOS					20-SEP-2019		
	REF:	HRS/MSC	300	+10%/-10%			5983:25	6283:25	6313:25
		AFL					5444		

CHAPTER 06 DIMENSIONS AND AREAS

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION PKG 17 REF:	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION PKG 17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR. PKG 17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL PKG 17 REF:	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST								
		MOS	60	+1m/-1m			11-MAY-2016	11-MAY-2021	11-JUN-2021
	REF:	HRS/MSC					4028:50		
		AFL					3721		
<hr/>									
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6)								
		MOS					26-APR-2019		
	REF:	HRS/MSC	A/R				5788:15		
		AFL					5294		
<hr/>									
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		
<hr/>									
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF: See Workcard	AFL					5294		
<hr/>									
CHAPTER 12 SERVICING									
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS						PKG		
	PKG 17	MOS					26-APR-2019		
	REF: AMM 12-20-01	HRS/MSC	A/R				5788:15		
		AFL					5294		
<hr/>									
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 17	MOS					26-APR-2019		
	REF: AMM 12-20-02	HRS/MSC	A/R				5788:15		
		AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 17	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
	REF: AMM 12-20-03								
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
20.010		MOS HRS/MSC AFL	12	+10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2020	20-APR-2020
	REF: AMM 20-40-00								
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL) TRACKED ITEM								
20.011		MOS HRS/MSC AFL	6 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-MAR-2020 6283:25	07-APR-2020 6313:25
	REF: AMM 20-40-00								
20JFL01	PERFORM DENTS AND BUCKLES CHARTS								
		MOS HRS/MSC AFL	300	+10%/-10%			20-SEP-2019 5983:25 5444	6283:25	6313:25
	REF:								
CHAPTER 21 AIR CONDITIONING									
+ 21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
	REF:								
+ 21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 22	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
	REF:								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
21.040	REF: AMM 21-30-00	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		-25	14-MAR-2018 5176:55 4778	17-FEB-2020 8176:55	29-APR-2020 8476:55
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
21.030	REF: AMM 21-30-01	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		-25	14-MAR-2018 5176:55 4778	17-FEB-2020 8176:55	29-APR-2020 8476:55
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
21.010	REF: AMM 21-30-07	MOS HRS/MSC AFL	60	+10%/-10%		-28	14-MAR-2018 5176:55 4778	14-FEB-2023	14-AUG-2023
21-30/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
21.020	REF: AMM 21-30-08	MOS HRS/MSC AFL	60	+10%/-10%		-28	14-MAR-2018 5176:55 4778	14-FEB-2023	14-AUG-2023
+ 21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
	REF: AMM 21-40-11	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER						PKG		
21.080	PKG 21 REF: AMM 21-40-02	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
+ 21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH								
21.130	REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		-28	14-MAR-2018 5176:55 4778	14-FEB-2023 9976:55	14-AUG-2023 10456:55

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH								
21.120		MOS	60	+10%/-10%		-28	14-MAR-2018	14-FEB-2023	14-AUG-2023
		HRS/MSC	4800	+10%/-10%			5176:55	9976:55	10456:55
	REF: AMM 21-60-05	AFL					4778		
21-40/53	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 101-320 WITHOUT A MODIFIED AUXILIARY HEATING SYSTEM)								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
	REF: AMM 21-40-09	AFL					0		
+ 21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF: AMM 21-40-00	AFL					5294		
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 19	MOS					26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF: AMM 21-40-01	AFL					5294		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 19	MOS					26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF: AMM 21-40-01	AFL					5294		
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)								
	1134400-53	MOS					20-SEP-2019		
	178	HRS/MSC	300	+10%/-10%			5983:25	6283:25	6313:25
	REF:	AFL					5444		
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	1134400-53	MOS							
	178	HRS/MSC	N/A						
	REF:	AFL							
		ACH							
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	1134400-53	MOS							
	178	HRS/MSC	N/A						
	REF:	AFL							
		ACH							
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	1134400-53	MOS					03-AUG-2018		
	178	HRS/MSC					5430:30		
	REF: AMM 21-50-03	AFL					4979		
		ACH	500	+10%/-10%			0	500	550
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.100	1134400-53	MOS					03-AUG-2018		
	178	HRS/MSC					5430:30		
	REF: See Workcard	AFL					4979		
		ACH	500	+10%/-10%			0	500	550
210005	OVERPRESSURE SWITCH								
21.340	9738115105	MOS					31-JAN-2008		
	659	HRS/MSC	O/C				0		
	REF: AMM 21-30-07	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210010	REFRIGERATION PACK								
21.255	9599020111 1439 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1399 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 1601 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1408 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 1208 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C				06-JUL-2017 4733:55 4347		
210035	WATER SEPARATOR ASSY								
21.220	5214112060 2572 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1399 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	1134400-53 178 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-AUG-2018 5430:30 4979		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	1134104-6 2589 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-AUG-2018 5430:30 4979		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 298 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.118 449 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-AUG-2009 657:20 502		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 304 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091123 47-C0162 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091133 97-G0196 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210070	AUXILIARY VOLUME TANK								
21.390	9599091111 37-8267 REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210075	CHECK VALVE								
21.400	9599091151 97-A1321 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210080	JET PUMP								
21.410	9599091161 97-2404 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210085	MANUAL CONTROLLER								
21.420	9599091101 87-A0792 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	959.90.91.141 89-G0229 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			22-JUN-2012 1838:25 1611		
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	3G10.32.35F.05.1.AL 1045442 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C				13-JUN-2008 158:06 106		
210100	CAB RATE INDICATOR								
21.440	9651621002 1045392 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	DDS.AE 1044267 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C					14-MAR-2018 5176:55 4778	
210110	CABIN PX SWITCH								
21.360	9652321533 1013653 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					14-FEB-2013 2186:05 1951	
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 528964 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
210120	BAY TEMP SENSOR								
21.450	9599020122 1424 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	9751516101 D0150 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
210130	TEMP CONTROLLER								
21.235	9599020123 1403 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
210140	SOLENOID VALVE								
21.300	9631411001 09-0823421 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 528967 REF: AMM 21-40-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	9633011106 0642B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	9633011002 630 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 681 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
21C007	TEMP TRANSMIT,T21.10.110-HG1610A								
	9751516106 599 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
21C008	TEMP TRANSMIT,T21.10.110-S1503 A								
	9751516105 586 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
21C009	MAX CABIN ALTITUDE SWITCH								
	9652321533 1045398 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21C010	DIFFERENTIAL PRESURE SWITCH 9652321534 1044267 REF:	MOS HRS/MSC AFL	A/R	R:0 R:0 R:0			09-APR-2018 5176:55 4778		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST REF:	MOS HRS/MSC AFL	24	+10%/-10%		1	26-APR-2019 5788:15 5294	27-APR-2021	09-JUL-2021
CHAPTER 22 AUTO FLIGHT									
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES PKG 22 REF:	MOS HRS/MSC AFL	24	+10%/-10%			26-APR-2019 5788:15 5294		
22-10/60 22.010	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+10%/-10%		-43	26-APR-2019 5788:15 5294	14-MAR-2020 6788:15	20-APR-2020 6888:15
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			20-SEP-2019 5983:25 5444		
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 18 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			20-SEP-2019 5983:25 5444		
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 21 REF: AMM 22-20-00	MOS HRS/MSC AFL	12	+10%/-10%			26-APR-2019 5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220005	AUTOPILOT MODE CONTROL								
22.160	9859203121 2863 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220010	ALTITUDE PRESELECTOR								
22.180	9859203131 2792 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220015	AILERON KSA372,065-00056-0056 ACTUATOR								
22.100	9859203161 6416 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220020	PITCH KSM375,065-00015-0000 MOUNT								
22.190	9859203173 A10558 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR								
22.110	9859203164 1379 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	9859203171 A10562 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	065-0056-80 MOD3 6283 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C				04-DEC-2014 3189:25 2890		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220040	AILERON KSM375,065-00015-0001	MOUNT							
22.210	9859203171 A10548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220045	STICK PUSHER SERVO								
22.220	9786111103 80276 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220050	PITCH TRIM ADAPTER								
22.130	9859203181 1932 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	9786111124 80277 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220060	STICK SHAKER								
22.230	9786111143 785 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220065	AUTOPILOT COMPUTER								
22.150	065-0064-15 2420 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				10-DEC-2012 2104:15 1870		
220070	STICK PUSHER COMPUTER								
22.170	9754423104 121558 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 23 COMMUNICATIONS

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203 310-16820 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-16830 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
230025	AUDIO SUMMING AMPLIFIER								
23.010	9878133108 517 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
23C011	AUDIO PANEL,GMA 340								
	9856115113 96281867 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
23JFL01	NO. 1 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78406071 REF:	MOS HRS/MSC AFL	O/C				11-JAN-2018 5078:35 4700		
23JFL02	NO. 2 NAV/COM/GPS TRANSCEIVER								
	011-00550-10 78409049 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			11-JAN-2018 5078:35 4700		

CHAPTER 24 ELECTRICAL POWER

+ 24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF: AMM 24-20-00	AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
24-30/19	STARTER GENERATOR 23085-029A	MOS					20-SEP-2019		
24.020	Y0276	HRS/MSC	N/A				5983:25		
	REF: AMM 24-30-01	AFL					5444		
+ 24-30/20 (s)	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING 940.83.08.902	MOS					26-APR-2019		
24.040	940.83.08.902	HRS/MSC	3000	+10%/-10%		211:4	5788:15		
	REF: AMM 24-30-04	AFL				5	5294		
+ 24-30/21	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING PN	MOS					26-APR-2019		
	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%			5788:15	8788:15	9088:15
	REF: AMM 24-30-04	AFL					5294		
+ 24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 24-30/482 (s)	STARTER GENERATOR FOR BRUSH WEAR 23085-029A PKG 19	MOS					PKG 20-SEP-2019		
	Y0276	HRS/MSC	600	+10%/-10%			5983:25		
	REF: AMM 24-30-01	AFL					5444		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/491	OVERHAUL STARTER GENERATOR 23085-029A Y0276	MOS HRS/MSC AFL	1200	+10%/-10%			20-SEP-2019 5983:25 5444	7183:25	7303:25
OVERHAUL	REF:								
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS								
24.210		MOS HRS/MSC AFL	24	+10%/-10%	-25		14-MAR-2018 5176:55 4778	17-FEB-2020	29-APR-2020
	REF: AMM 24-30-00								
+ 24-30/63	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES								
24.030	5243212158 MOD G 100907	MOS HRS/MSC AFL	N/A				26-APR-2019 5788:15 5294		
	REF: AMM 24-30-02								
24-30/64	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES								
	5243212158 MOD G 100907	MOS HRS/MSC AFL	600	+10%/-10%			26-APR-2019 5788:15 5294	6388:15	6448:15
	REF: AMM 24-30-02								
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
24.030		MOS HRS/MSC AFL	N/A		-18:20		17-FEB-2016 3884:45 3574		
	REF: AMM 24-30-04								
+ 24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
		MOS HRS/MSC AFL	1800	+10%/-10%	78:10		26-APR-2019 5788:15 5294	7666:25	7846:25
	REF: AMM 24-30-04								
24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	31406-002 11501227	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 6283:25	26-OCT-2020 6313:25
	REF: AMM 24-30-07								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	AFL	2400	+10%/-10%			5788:15		
							5294		
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 501-1712-02	MOS	12	+1m/-1m		-43	26-APR-2019	14-MAR-2020	14-APR-2020
24.050	81391	HRS/MSC					5788:15		
	REF: See Workcard	AFL					5294		
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	AFL	2400	+10%/-10%			5788:15		
							5294		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111	MOS			N:0		31-JAN-2008		
24.120	P1640	HRS/MSC	O/C		N:0		0		
	REF: AMM 24-30-05	AFL			N:0		0		
240015	GENERATOR 2 300A CONTACTOR 9740338113	MOS			N:0		31-JAN-2008		
24.130	N773	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
240020	GENERATOR 1 300A CONTACTOR 9740338113	MOS			N:0		31-JAN-2008		
24.130	N772	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
240025	GENERATOR 2 2ND GENCON UNIT 9882115103	MOS			N:0		31-JAN-2008		
24.140	10600	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240035	BUSBAR,CROSS TIE RCCB								
24.150	9725537003 1479 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240040	BUSBAR,CROSS,TIE RCCB								
24.150	9725537005 831 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240045	STARTER RELAY								
24.160	9740926133 P915 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240050	BATTERY RELAY								
24.170	9740926126 R329 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240055	EPU RELAY								
24.180	9740926126 R425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	9728132301 762 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240065	OVERHEAD PANEL								
24.190	9728132109 JWPIL2002370 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	9599020124 590 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	9750421112 552 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240085	A242 26 VAC,SC3(A) INVERTER								
24.070	9750421112 546 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	9742900201 3933 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240095	S105 DC CURRENT SENSOR								
24.090	9742900205 2562 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	9742900205 2552 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	9742900201 3938 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240110	S104 DC CURRENT SENSOR								
24.090	9742900201 3929 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240115	S106 DC CURRENT SENSOR								
24.100	9742900201 3815 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
243045	GENERATOR 2								
24.030	5243212158 MOD G 100907 REF: See Workcard	MOS HRS/MSC AFL	O/C				31-JAN-2008 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 81391 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	N:135 N:5788:15 N:5294			26-APR-2019 5788:15 5294		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11501227 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				20-SEP-2019 5983:25 5444		
24C015	EMERGENCY POWER SUPPLY,PS-855B								
	9858314953 81391 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
24C016	DC-DC POWER CONVERTER								
	9750215106 1280 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 25 EQUIPMENT/FURNISHINGS

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 18	MOS					PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
25-10/293	COPILOT SEAT CUSHION PN	MOS			N:0		31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 25-21-02	AFL			N:0		0		
25-10/293	PILOT SEAT CUSHION PN	MOS			N:0		31-JAN-2008		
25.080	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 25-21-02	AFL			N:0		0		
25-10/294	CREW SEAT BELTS PN	MOS	144	+6m/-6m	N:0		31-JAN-2008	31-JAN-2020	31-JUL-2020
25.030	SN-UNKNOWN	HRS/MSC			N:0		0		
DISCARD	REF: AMM 25-10-02	AFL			N:0		0		
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 17	MOS					PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC AFL	A/R				5788:15 5294		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 17	MOS					PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC AFL	A/R				5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 25-10/486	REPLACE BACKREST TUBES ON CREW SEATS WITH RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-SEP-2019 5983:25 5444		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	PASSENGER SEAT BELTS								
25.010	PN	MOS	144	+6m/-6m	N:0		31-JAN-2008	31-JAN-2020	31-JUL-2020
DISCARD	SN-UNKNOWN	HRS/MSC			N:0		0		
	REF: AMM 25-21-02	AFL			N:0		0		
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 17	MOS					26-APR-2019		
	REF: See Workcard	HRS/MSC	A/R				5788:15		
		AFL					5294		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION						PKG		
	PKG 17	MOS					26-APR-2019		
	REF: See Workcard	HRS/MSC	A/R				5788:15		
		AFL					5294		
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS).						PKG		
	PKG 18	MOS					20-SEP-2019		
	REF:	HRS/MSC	300	+10%/-10%			5983:25		
		AFL					5444		
+ 25-60/231 (s)	OPERATIONAL TEST ELT						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
	REF: See Workcard	HRS/MSC	300	+10%/-10%			5983:25		
		AFL					5444		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60/483	PERFORM PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 9851380853 2616806-0036 REF: AMM 25-63-10	MOS HRS/MSC AFL	A/R				31-JAN-2008 0 0		
25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY S1820516-99 TM0000079330 REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE	N:0 N:0 N:0			09-OCT-2015 3744:55 3392	28-FEB-2022 M	
25.020 DISCARD Expiry Date: 28-FEB-2022									
250005	REMOTE CONTROL PANEL 9851380817 2616809-0001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
250010	EMERGENCY LOCATOR TRANSMITTER 9851380853 2616806-0036 REF: AMM 25-63-01	MOS HRS/MSC AFL	O/C	N:69 N:2611:15 N:2343			18-OCT-2013 2611:15 2343		
250015	IPECO PILOT SEAT 959.30.01.143 50257 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:89 N:0			11-JUN-2015		
250020	IPECO CO-PILOT SEAT 959.30.01.144 50259 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:89 N:0			11-JUN-2015		
250021	NO. 1 PASSENGER SEAT 959.30.01.617 35375 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2015		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250022	NO. 2 PASSENGER SEAT 959.30.01.618 35376 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250023	NO. 3 PASSENGER SEAT 959.30.01.633 35377 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250024	NO. 4 PASSENGER SEAT 959.30.01.634 33379 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250025	NO. 5 PASSENGER SEAT 959.30.01.641 35378 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250026	NO. 6 PASSENGER SEAT 959.30.01.642 35380 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
251010	PILOT SEAT BACKREST TUBES PN 25.060 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0				31-JAN-2008 0 0	
251015	COPILOT SEAT BACKREST TUBES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0				31-JAN-2008 0 0	
25C017	PAX SEAT LH AFSS,403150-1 9593001617 35375 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C018	PAX SEAT RH AFSS,403150-2 9593001618 35376 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C019	PAX SEAT LH FFSS,403150-3-B 9593001641 35378 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C020	PAX SEAT RH FFSS,403150-4-B 9593001642 35380 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C021	PAX SEAT LH FFSS,403150-3-A 9593001635 1186 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C022	PAX SEAT RH FFSS,403150-4-BC 9593001644 1198 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C024	PAX SEAT LH FFSS,403150-3 9593001633 35377 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C025	PAX SEAT RH FFSS,403150-4 9593001634 35379 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C026	ENTERTAINMENT SYSTEM INSTL 9501000440 2704003 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25JFL02	PERFORMED FIRST AID KIT INSPECTION	MOS	12	+1m/-1m		-43	26-APR-2019 5788:15 5294	14-MAR-2020	14-APR-2020
	REF:	HRS/MSC AFL							
CHAPTER 26 FIRE PROTECTION									
26-20/2	COCKPIT FIRE EXTINGUISHER								
26.010	BA51015GR-3 083998	MOS HRS/MSC	120	N:4 N:0			14-FEB-2013 2186:05 1951	05-DEC-2022 M	
	LIFE LIMIT	REF: GENERIC NO REF		AFL ACH					
26-20/24	CONTENTS CHECK COCKPIT FIRE EXTINGUISHER								
26.010	BA51015GR-3 083998	MOS HRS/MSC	12	+10%/-10%		-12	14-MAR-2019	02-MAR-2020	08-APR-2020
		REF: GENERIC NO REF		AFL					
260005	FIRE/OVERHEAT DETECTOR								
26.020	9751210012 207694	MOS HRS/MSC	O/C	N:0 N:0			31-JAN-2008 0 0		
		REF: GENERIC NO REF		AFL					
CHAPTER 27 FLIGHT CONTROLS									
+ 27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL						PKG		
	PKG 18	MOS					20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES								
		MOS					31-JAN-2008		
	REF: GENERIC NO REF	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES								
27.010		MOS	60	+10%/-10%			26-APR-2019	26-APR-2024	26-OCT-2024
	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%			5788:15 5294	10588:15	11068:15

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/139 (s)	EXAMINE AILERON LH AND RH AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC TEMPORARY (MAT. NO. P10-001)						PKG		
	PKG 3	MOS	12	+10%/-10%				20-SEP-2019	
		HRS/MSC	300	+10%/-10%				5983:25	
	REF:	AFL						5444	
+ 27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS						PKG		
	PKG 21	MOS	12	+10%/-10%				26-APR-2019	
		HRS/MSC	1200	+10%/-10%				5788:15	
	REF:	AFL						5294	
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%				26-APR-2019	
		HRS/MSC	1200	+10%/-10%				5788:15	
	REF:	AFL						5294	
+ 27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 21	MOS	12	+10%/-10%				26-APR-2019	
		HRS/MSC	1200	+10%/-10%				5788:15	
	REF:	AFL						5294	
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999						PKG		
	PKG 21	MOS	12	+10%/-10%				26-APR-2019	
		HRS/MSC	1200	+10%/-10%				5788:15	
	REF: See Workcard	AFL						5294	
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999						PKG		
	PKG 22	MOS	24	+10%/-10%				26-APR-2019	
		HRS/MSC	2400	+10%/-10%				5788:15	
	REF: See Workcard	AFL						5294	
27-10/394	EXAMINE - AILERON CONTROL SYSTEM							31-JAN-2008	
		MOS						0	32500
		HRS/MSC	32500					0	42000
AIRWORTHINESS	REF: AMM 27-10-00	AFL	42000					0	42000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-10-09	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/444	AILERON FLIGHT CONTROL CABLES	MOS		N:0			31-JAN-2008		
LIFE LIMIT	REF:	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE	MOS		N:0			31-JAN-2008		
LIFE LIMIT	REF:	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARING	MOS	12	+10%/-10%		-43	PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			26-APR-2019		
	REF: AMM 27-10-00	AFL					5788:15		
							5294		
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999	MOS	24	+10%/-10%			PKG		
	PKG 22	HRS/MSC	2400	+10%/-10%			26-APR-2019		
	REF: See Workcard	AFL					5788:15		
							5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/140 (s)	INSPECT/CHECK RUDDER PKG 3 REF: AMM 55-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-SEP-2019 5983:25 5444		
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 27-20/242	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH REF: AMM 20-31-00	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 22 REF: AMM 27-25-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					31-JAN-2008		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				0 0		
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF:	PN SN-UNKNOWN AFL	20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-30/141 (s)	EXAMINE ELEVATORS PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
27-30/334	CHECK ELEVATOR CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR)	MOS					PKG 26-APR-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R				5788:15 5294		
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM	MOS					31-JAN-2008		
	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
AIRWORTHINESS									

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-30/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF:	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF:	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-30/450	STICK PUSHER CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF:	HRS/MSC	20000	N:0			0		20000
		AFL	27000	N:0			0		27000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%		-43	26-APR-2019	14-MAR-2020	20-APR-2020
27.021		HRS/MSC	3000				5788:15	8788:15	
AIRWORTHINESS	REF: AMM 27-40-00	AFL					5294		
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF: AMM 27-40-00	AFL					5444		
+ 27-40/252 (s)	INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	129-1-1100-02	MOS	84				10-SEP-2018	10-SEP-2025	
	238	HRS/MSC	3400				5485:40	8885:40	
OVERHAUL	REF: AMM 27-40-01	AFL					5022		
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 18	MOS					20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF: AMM 27-40-00	AFL					5444		
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF: AMM 27-40-00	AFL					5294		
27-40/3	PITCH TRIM ACTUATOR								
	129-1-1100-02	MOS					10-SEP-2018		
27.011	238	HRS/MSC	20000			O:0	5485:40	25485:40	
AIRWORTHINESS	REF: AMM 27-40-01	AFL	27000			N:6827 O:0	5022	32022	
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS								
	PN	MOS					31-JAN-2008		
27.036	SN-UNKNOWN	HRS/MSC	10000			N:0	0	10000	
LIFE LIMIT	REF: AMM 27-40-02	AFL				N:0	0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION PKG 17	MOS HRS/MSC AFL	A/R				PKG 26-APR-2019 5788:15 5294		
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 3	MOS HRS/MSC AFL		12 300	+10%/-10% +10%/-10%		PKG 20-SEP-2019 5983:25 5444		
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 21	MOS HRS/MSC AFL		12 1200	+10%/-10% +10%/-10%		PKG 26-APR-2019 5788:15 5294		
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 21	MOS HRS/MSC AFL		12 1200	+10%/-10% +10%/-10%		PKG 26-APR-2019 5788:15 5294		
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 PKG 21	MOS HRS/MSC AFL		12 1200	+10%/-10% +10%/-10%		PKG 26-APR-2019 5788:15 5294		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT 9787320003 670	MOS HRS/MSC AFL		10000 13500	+10%/-10% +500/-500		31-JAN-2008 0 0	10000 13500	11000 14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0981	MOS HRS/MSC AFL		5000 7000	+10%/-10% +500/-500		14-MAR-2018 5176:55 4778	10176:55 11778	10676:55 12278
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0994	MOS HRS/MSC AFL		5000 7000	+10%/-10% +500/-500		14-MAR-2018 5176:55 4778	10176:55 11778	10676:55 12278

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					14-MAR-2018		
OVERHAUL	0988	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
27.050	978.73.20.309	MOS					14-MAR-2018		
OVERHAUL	1177	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	9450202205	MOS					31-JAN-2008		
DISCARD	S6100	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	9450202206	MOS					31-JAN-2008		
DISCARD	S6130	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	9450202205	MOS					31-JAN-2008		
DISCARD	S6106	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	9450202206	MOS					31-JAN-2008		
DISCARD	S6124	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/386	EXAMINE - FLAP MECHANISM								
AIRWORTHINESS		MOS					31-JAN-2008		
	REF: AMM 27-51-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
AIRWORTHINESS		MOS					31-JAN-2008		
	REF: AMM 27-51-00	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS					14-MAR-2018		
27.040	978.73.20.309	HRS/MSC	20000	O:0			5176:55		25176:55
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:4972:35 O:0			4778		31778
				N:6422 O:0					

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		O:0			14-MAR-2018		
27.040	0994	HRS/MSC	20000	N:4971:35 O:0			5176:55	25176:55	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6422 O:0			4778	31778	
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		O:0			14-MAR-2018		
27.050	0988	HRS/MSC	20000	N:4971:35 O:0			5176:55	25176:55	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6422 O:0			4778	31778	
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		O:0			14-MAR-2018		
27.050	1177	HRS/MSC	20000	N:9666:50 O:0			5176:55	25176:55	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6720 O:0			4778	31778	
27-50/414	LEFT HAND FLAP								
	5575012003	MOS		N:0			31-JAN-2008		
57.060	782	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			31-JAN-2008		
57.060	779	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
+ 27-50/437	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS								
		MOS	12	+10%/-10%			26-APR-2019	26-APR-2020	01-JUN-2020
		HRS/MSC	600	+10%/-10%	1:45		5788:15	6390	6450
AIRWORTHINESS	REF: AMM 27-51-00	AFL					5294		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF: AMM 12-20-07	AFL					5444		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF:	AFL	27000	N:0			0	27000	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION PKG 17	MOS					PKG	31-JAN-2008	
	REF:	HRS/MSC AFL	A/R				0 0		
27-50/72 27.060	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 9450202205 S6100	MOS					31-JAN-2008		
	REF: AMM 27-50-00	HRS/MSC AFL	O/C				0 0		
27-50/72 27.060	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 9450202206 S6130	MOS					31-JAN-2008		
	REF: AMM 27-50-00	HRS/MSC AFL	O/C				0 0		
27-50/72 27.070	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 9450202205 S6106	MOS					31-JAN-2008		
	REF: AMM 27-50-00	HRS/MSC AFL	O/C				0 0		
27-50/72 27.070	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 9450202206 S6124	MOS					31-JAN-2008		
	REF: AMM 27-50-00	HRS/MSC AFL	O/C				0 0		
+ 27-50/73 27.040	LUBRICATE LEFT INBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.309 0981	MOS							
	REF: AMM 27-50-00	HRS/MSC AFL	N/A						
+ 27-50/73 27.040	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.309 0994	MOS							
	REF: AMM 27-50-00	HRS/MSC AFL	N/A						
+ 27-50/73 27.050	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.309 0988	MOS							
	REF: AMM 27-50-00	HRS/MSC AFL	N/A						

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/73	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED)								
27.050	978.73.20.309 1177 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0981 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 6283:25	26-OCT-2020 6313:25
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0994 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 6283:25	26-OCT-2020 6313:25
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0988 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 6283:25	26-OCT-2020 6313:25
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 1177 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 6283:25	26-OCT-2020 6313:25
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0981 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2021 8188:15 8494	26-MAY-2021 8428:15 8814
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0994 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2021 8188:15 8494	26-MAY-2021 8428:15 8814
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 0988 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			26-APR-2019 5788:15 5294	26-APR-2021 8188:15 8494	08-JUL-2021 8428:15 8814

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309	MOS	24	+10%/-10%		-43	26-APR-2019	14-MAR-2021	26-MAY-2021
	1177	HRS/MSC	2400	+10%/-10%			5788:15	8188:15	8428:15
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			5294	8494	8814
27-50/77	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013)								
27.080		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
270003	HORIZONTAL TAIL ASSY								
	5551012037	MOS					31-JAN-2008		
	796	HRS/MSC	O/C				0		
	REF: AMM 55-10-01	AFL					0		
270015	ELEVATOR LH ASSY								
	555.20.12.039	MOS					29-MAY-2015		
	586	HRS/MSC	O/C				3448:25		
	REF: AMM 55-20-01	AFL					3156		
270023	ELEVATOR RH ASSY								
	555.20.12.040	MOS					29-MAY-2015		
	586	HRS/MSC	O/C				3448:25		
	REF: AMM 55-20-01	AFL					3156		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	978.73.18.132	MOS					26-NOV-2014		
	0904	HRS/MSC	O/C				3172:35		
	REF: AMM 27-25-01	AFL					2878		
270033	RUDDER ASSY								
	5554012038	MOS					31-JAN-2008		
	778	HRS/MSC	O/C				0		
	REF: AMM 55-40-01	AFL					0		
270035	FLAP CONTROL AND WARNING (FCWU) UNIT								
27.130	9787320017	MOS					31-JAN-2008		
	121893	HRS/MSC	O/C				0		
	REF: AMM 27-50-05	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 079022DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 1063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 079007DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 079020DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1067 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	9787318132 1569 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 079021DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m			26-APR-2019 5788:15 5294	26-APR-2021	26-MAY-2021

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 28 FUEL									
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS					26-APR-2019		
		HRS/MSC	2400	+10%/-10%	78:10		5788:15	8266:25	8506:25
	REF: AMM 28-10-01	AFL					5294		
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF: AMM 28-20-07	AFL					5444		
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF: See Workcard	AFL					5444		
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N)						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	2400	+10%/-10%			5788:15		
		AFL					5294		
28-20/32	ACCESSORY GEARBOX FUEL PUMP								
28.010	968.84.51.108	MOS		O:0			07-AUG-2015		
OVERHAUL	B4919	HRS/MSC	3500	+10%/-10%	-94:55		3594:55	7000	7350
	REF: AMM 28-20-03	AFL		O:0			3282		
+ 28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM								
28.020		MOS	48	+10%/-10%			26-APR-2019	26-APR-2023	19-SEP-2023
	REF: See Workcard	HRS/MSC	1200	+10%/-10%	78:10		5788:15	7066:25	7186:25
		AFL					5294		
280005	LOW PRESSURE FUEL PUMP								
28.120	9688451108	MOS		N:0			31-JAN-2008		
	B5010	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
280010	FUEL FLOW TRANSMITTER								
28.130	9753512602	MOS		N:0			31-JAN-2008		
	2899	HRS/MSC	O/C	N:0			0		
	REF: AMM 73-30-01	AFL		N:0			0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			31-JAN-2008		
	2061	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-08	AFL		N:0			0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			31-JAN-2008		
	2062	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-08	AFL		N:0			0		
280025	FUEL FILTER ASSY								
28.025	9683521001	MOS		N:0			31-JAN-2008		
	2007FFT1777	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-01	AFL		N:0			0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 1566 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C				14-APR-2008 68:30 42		
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3823 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4136 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 403 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 960 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 1585 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 1583 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B7634 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-JUL-2012 1874:35 1635		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3821 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4135 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280080	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 862 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280085	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 1629 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280090	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 1573 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280095	FUEL QUANTITY,OUTER SENSOR								
28.060	975.37.31.231 299 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280100	RIGHT WING FUEL,BOOSTER PUMP								
28.050	9688411405 B6712 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
28C031	VALVE,CHECK								
	9630423105 1956 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
28C032	VALVE,CHECK 9630423105 1972 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0			
CHAPTER 29 HYDRAULIC POWER										
+ 29-10/151 (s)	RETURN LINE FILTER DIIERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG			
	PKG 20	MOS	12	+10%/-10%			26-APR-2019			
		HRS/MSC	600	+10%/-10%			5788:15			
	REF: AMM 29-10-04	AFL					5294			
+ 29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG			
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019			
		HRS/MSC	300	+10%/-10%			5983:25			
	REF: See Workcard	AFL					5444			
+ 29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.						PKG			
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019			
		HRS/MSC	300	+10%/-10%			5983:25			
	REF: See Workcard	AFL					5444			
+ 29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG			
	PKG 21	MOS	12	+10%/-10%			26-APR-2019			
		HRS/MSC	1200	+10%/-10%			5788:15			
	REF:	AFL					5294			
+ 29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291)						PKG			
	PKG 21	MOS	12	+10%/-10%			26-APR-2019			
		HRS/MSC	1200	+10%/-10%			5788:15			
	REF: AMM 29-10-02	AFL					5294			
+ 29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL						PKG			
	PKG 21	MOS	12	+10%/-10%			26-APR-2019			
		HRS/MSC	1200	+10%/-10%			5788:15			
	REF:	AFL					5294			

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/418	NITROGEN ACCUMULATOR								
	9603001291	MOS		N:0			31-JAN-2008		
29.020	822	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000	N:0			0	30000	
<hr/>									
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
	REF:	AFL					0		
<hr/>									
290005	LANDING GEAR STEER SELECTOR VALVE								
	960.30.01.271	MOS		O:0			25-FEB-2014		
29.040	0471AB	HRS/MSC	O/C	O:0			2717:45		
	REF: GENERIC NO REF	AFL		O:0			2508		
<hr/>									
290015	PRESSURE GAGE SWITCH								
	973.81.14.307	MOS					05-JUN-2014		
29.050	0726	HRS/MSC	O/C				2866:25		
	REF: GENERIC NO REF	AFL					2636		
<hr/>									
290025	SERVICE SELECTOR VALVE								
	9603001261	MOS		N:0			31-JAN-2008		
29.070	G0711047A	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
<hr/>									
290030	PRESSURE GAUGE								
	9656188101	MOS		N:0			31-JAN-2008		
29.080	07-0821145	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
<hr/>									
290035	(K 601) RELAY								
	9740926112	MOS		N:0			31-JAN-2008		
29.090	R555	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
<hr/>									
290040	HAND PUMP								
	9688582111	MOS		N:0			31-JAN-2008		
29.030	786	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-20-01	AFL		N:0			0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290050	PRESSURE NITROGEN SWITCH								
29.100	9738114306 1877 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-SEP-2018 5485:40 5022		
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0730769 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS -								
	960.30.02.101 201208 REF:	MOS HRS/MSC AFL	60	+6m/-6m O:0			27-APR-2017 4592:35 4216	27-APR-2022	27-OCT-2022
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444		
	REF: AMM 30-10-00								
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999						PKG		
	PKG 20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
	REF: See Workcard								
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
	REF: AMM 30-10-00								
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1								
30.010		MOS HRS/MSC AFL	6	+10%/-10%			20-SEP-2019 5983:25 5444	20-MAR-2020	07-APR-2020
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC	300	+10%/-10%			5983:25		
		AFL					5444		
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
+ 30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC	2400	+10%/-10%			5788:15		
		AFL					5294		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 30-60-00	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 30-60-00	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		
300005	PROP DE-ICE TIMER/ CONTROLLER 968.29.13.227	MOS					18-FEB-2016		
30.140	U0405	HRS/MSC	O/C				3885:20		
	REF: AMM 30-60-01	AFL					3575		
300010	LPMI LINEAR ACTUATOR 9787315302	MOS		N:0			31-JAN-2008		
30.150	B68297	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N073177 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300020	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N072569 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300025	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N072566 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300030	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N072541 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N072543 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N072542 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 8692 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			06-JUL-2017 4733:55 4347		
300050	WATER SEPARATOR								
30.060	9598901010 N074115 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.043 UA099 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121784 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121785 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 3973 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 7932 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:10 N:0 N:0			13-JUL-2016 4177:05 3846	15-AUG-2020 M	
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 4016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 4014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.026 NCO3910 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-AUG-2015 3594:55 3282		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.027 NCR8430 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-AUG-2015 3594:55 3282		
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NEW6140 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.034 NEL1990 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-SEP-2018 5485:40 5022		
300115	LH INBD-WING DE-ICER BOOT								
30.040	P27-7D5221-21 NEV2060 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NEB3380 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"								
	REF:	MOS HRS/MSC AFL	300	+10%/-10%			20-SEP-2019 5983:25 5444	6283:25	6313:25
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
31-50/34	CAWS & CACU CLOCK BATTERY								
31.010	9728132050 N/A REF: AMM 31-50-03	MOS HRS/MSC AFL	24	+10%/-10%	N:0 N:0 N:0	-25	14-MAR-2018 5176:55 4778	17-FEB-2020	29-APR-2020

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310020	FLAP POSITION INDICATOR								
31.090	9754416203 60200 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
310025-1	AM-250 BARO ALTIMETER, ADC								
	9859911207 07080829D REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
310035	CAWS COMPUTER								
31.050	9728132030 515 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:122 N:5176:55 N:4778			14-MAR-2018 5176:55 4778		
310040	CAWS DISPLAY								
31.060	9728132031 283 REF: AMM 31-50-02	MOS HRS/MSC AFL	O/C				19-APR-2008 80:18 50		
310050	DIGITAL CLOCK								
31.040	9996111213 1056675 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-APR-2011 1202:25 1002		
31C035	COAX SWITCH								
	9859911371 10396 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
31C036	COAX SWITCH								
	9859911371 10390 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 32 LANDING GEAR

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
32-10/264	REMOVE MAIN LANDING GEAR LEFT AND RIGHT AXLE BOLT (PRE SB 32-006) AND EXAMINE. REPLACE IF DAMAGED. INSTALL A SERVICEABLE BOLT.	MOS					31-JAN-2008		
	REF:	HRS/MSC AFL	N/A				0 0		
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	25000 30000	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK ABSORBER TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS.	MOS	12	+10%/-10%			26-APR-2019	26-APR-2020	01-JUN-2020
	REF: AMM 32-10-00	HRS/MSC					5788:15		
		AFL					5294		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2016	11-MAY-2022	
	REF: AMM 32-10-00	HRS/MSC					4028:50		
		AFL					3721		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2016	11-MAY-2022	
	REF: AMM 32-10-00	HRS/MSC					4028:50		
		AFL					3721		
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%			26-APR-2019	14-MAR-2020	20-APR-2020
32.030	REF: AMM 12-20-06	HRS/MSC	T/C		-43		5788:15		
		AFL					5294		
+ 32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES	MOS	12	+1m/-1m			26-APR-2019	14-MAR-2020	14-APR-2020
32.010	REF: AMM 32-10-00	HRS/MSC	2400	+10%/-10%	-43		5788:15	8188:15	8428:15
		AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF: AMM 32-20-00	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 20	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 20	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF:	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 20	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF:	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 32-20/266 (s)	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE PKG 21	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 21	MOS	12	+10%/-10%			PKG	26-APR-2019	
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK	MOS					15-APR-2013		
	REF: AMM 32-20-06	HRS/MSC AFL	N/A				2295:10 2059		
32-20/403	NOSE LANDING GEAR	MOS		N:0			31-JAN-2008		
	PN	HRS/MSC	25000	N:0			0		25000
OVERHAUL	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK	MOS		N:0			31-JAN-2008		
	PN	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	N:0			0		30000
32-20/5	NOSE LANDING GEAR UPPER RIGHT DRAG LINK	MOS		N:0			15-APR-2013		
	532.20.12.296	HRS/MSC	N/A	N:0			2295:10		
32.020	SN-UNKNOWN	AFL		N:0			2059		
	REF: AMM 32-20-05								
+ 32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM	MOS	12	+10%/-10%			26-APR-2019		
	PKG 21	HRS/MSC	1200	+10%/-10%			5788:15		
	REF: AMM 32-30-00	AFL					5294		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR	MOS		N:0			31-JAN-2008		
	9603001105	HRS/MSC	25000	N:0			0		25000
32.040	1654H	AFL	30000	N:0			0		30000
LIFE LIMIT	REF: AMM 32-30-01								
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR	MOS		N:0			31-JAN-2008		
	9603001105	HRS/MSC	25000	N:0			0		25000
32.040	1670H	AFL	30000	N:0			0		30000
LIFE LIMIT	REF: AMM 32-30-01								
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				17-FEB-2016	17-FEB-2022	
		HRS/MSC					3884:45		
	REF: AMM 32-10-00	AFL					3574		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				17-FEB-2016 3884:45 3574	17-FEB-2022	
	REF: AMM 32-10-00	HRS/MSC AFL							
+ 32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS	MOS	12	+10%/-10%			26-APR-2019 5788:15 5294		PKG
	PKG 20	HRS/MSC	600	+10%/-10%					
	REF:	AFL							
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE	MOS	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG
	PKG 3	HRS/MSC	300	+10%/-10%					
	REF: AMM 12-10-04	AFL							
+ 32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS	MOS	12	+10%/-10%			26-APR-2019 5788:15 5294		PKG
	PKG 20	HRS/MSC	600	+10%/-10%					
	REF:	AFL							
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE	MOS	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG
	PKG 3	HRS/MSC	300	+10%/-10%					
	REF: AMM 12-10-04	AFL							
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.	MOS	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG
	PKG 3	HRS/MSC	300	+10%/-10%					
	REF:	AFL							
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY	MOS	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG
	PKG 3	HRS/MSC	300	+10%/-10%					
	REF: AMM 12-10-02	AFL							

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM	MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
	REF: AMM 32-50-00	AFL	42000				0		42000
320005	PILOT LH BRAKE MASTER CYLINDER	MOS					31-JAN-2008		
32.130	9594751131	HRS/MSC	O/C	N:0			0		
	5135	AFL		N:0			0		
	REF: AMM 32-40-04			N:0			0		
320010	PILOT RH BRAKE MASTER CYLINDER	MOS					31-JAN-2008		
32.130	9594751131	HRS/MSC	O/C	N:0			0		
	5146	AFL		N:0			0		
	REF: AMM 32-40-04			N:0			0		
320015	PARK BRAKE VALVE	MOS					31-JAN-2008		
32.140	9594751121	HRS/MSC	O/C	N:0			0		
	2535	AFL		N:0			0		
	REF: AMM 32-40-05			N:0			0		
320020	NOSE WHEEL	MOS					03-MAY-2018		
32.150	3-1501	HRS/MSC	O/C				5230:20		
	0943	AFL					4832		
	REF: AMM 32-40-02								
320021	NOSE LANDING GEAR TIRE	MOS					03-MAY-2018		
32.155	021-327-0	HRS/MSC	O/C				5230:20		
	5268S00078	AFL		N:32			4832		
	REF: GENERIC NO REF								
320022	LEFT MAIN LANDING GEAR WHEEL	MOS					26-APR-2019		
32.160	3-1543-1	HRS/MSC	O/C	O:0			5788:15		
	1601	AFL		O:0			5294		
	REF: AMM 32-40-01			O:0					
320023	LEFT MAIN LANDING GEAR TIRE	MOS					26-APR-2019		
32.160	025-350-0	HRS/MSC	O/C	N:0			5788:15		
	8079S00312	AFL		N:0			5294		
	REF: GENERIC NO REF			N:0					

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320024	RIGHT MAIN LANDING GEAR WHEEL TRACKED ITEM								
32.165	3-1543-1 01081 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				10-SEP-2018 5485:40 5022		
320025	SHIMMY DAMPER ASSY								
32.100	532.20.12.215 VLG951 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:106:54 R:0 N:158 R:0			02-JUL-2019 5868:45 5355		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	021-250-0 7156S00388 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-SEP-2018 5485:40 5022		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751131 5122 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751131 5125 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012249 VLG-332 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012040 SI-0011 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320050	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 SI-0055 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012211 SI-0056 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320074	NOSE LANDING GEAR ACTUATOR								
29.060	9603001111 869A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320075	LH BRAKE ASSY								
32.050	2-1674-1 0794 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-2018 5078:35 4700		
320080	RH BRAKE ASSY								
32.050	2-1674-1 1313 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			26-SEP-2016 4324:45 3977		

CHAPTER	33	LIGHTS							
+	33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING							PKG
		PKG 3	MOS	12	+10%/-10%				20-SEP-2019
			HRS/MSC	300	+10%/-10%				5983:25
		REF: See Workcard	AFL						5444
+	33-41/178 (s)	EXAMINE LANDING LIGHTS							PKG
		PKG 3	MOS	12	+10%/-10%				20-SEP-2019
			HRS/MSC	300	+10%/-10%				5983:25
		REF: AMM 33-41-01	AFL						5444
+	33-42/179 (s)	EXAMINE TAXI LIGHTS							PKG
		PKG 3	MOS	12	+10%/-10%				20-SEP-2019
			HRS/MSC	300	+10%/-10%				5983:25
		REF: AMM 33-42-01	AFL						5444

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 3	MOS	12	+10%/-10%			PKG	20-SEP-2019	
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	20-SEP-2019	
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	20-SEP-2019	
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
330005	DIM UNIT 9750215205 121629 REF: AMM 33-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330010	DE-ICE LIGHT ASSY 9728767111 1309918 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330015	LEFT WING POWER SUPPLY, HIDL UNIT 9728769413 1295763 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 9728769413 1295766 REF: AMM 33-40-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787331 17852 REF: AMM 33-46-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787332	MOS		N:0			31-JAN-2008		
33.040	18051 REF: AMM 33-46-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330035	LH WING POWER SUPPLY UNIT 972.87.87.264	MOS					03-DEC-2014		
33.070	28584 REF: AMM 33-43-03	HRS/MSC AFL	O/C				3185:10 2887		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322	MOS					03-DEC-2014		
33.030	31091 REF: AMM 33-44-01	HRS/MSC AFL	O/C				3185:10 2887		
330045	RH WING POWER SUPPLY UNIT 972.87.87.164	MOS		N:0			25-FEB-2014		
33.070	41396 REF: AMM 33-43-03	HRS/MSC AFL	O/C	N:0 N:0			2717:45 2508		
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322	MOS		N:0			14-APR-2015		
33.030	28046017 REF: AMM 33-44-01	HRS/MSC AFL	O/C	N:0 N:0			3359 3086		
330055	NAVIGATION (FC), LED GREEN LIGHT 9728787158	MOS		N:0			31-JAN-2008		
33.050	28723 REF: AMM 33-43-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330060	NAVIGATION (FC), LED RED LIGHT 9728787157	MOS		N:0			31-JAN-2008		
33.050	28959 REF: AMM 33-43-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT 03-9200-2001	MOS					14-FEB-2013		
33.060	25311 REF: AMM 33-43-04	HRS/MSC AFL	O/C	N:325:40			2186:05 1951		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330070	NOSE LANDING GEAR TAXI LIGHT, 1X0005287-10 03-4400-1000 29798001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C				19-DEC-2016 4437 4074		
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10 972.87.69.420 29585001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	O:0			13-JUL-2016 4177:05 3846		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10 972.87.69.420 28983020 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 5690 5210		
33JFL01	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00-00A-903A-A) REF:	MOS HRS/MSC AFL	300	+10%/-10%			20-SEP-2019 5983:25 5444	6283:25	6313:25
CHAPTER 34 NAVIGATION									
+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 22 REF:	MOS HRS/MSC AFL	24	+10%/-10%			26-APR-2019 5788:15 5294		PKG
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG
+ 34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			20-SEP-2019 5983:25 5444		PKG

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC	300	+10%/-10%			5983:25		
		AFL					5444		
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
34-11/82 34.010	LEAK CHECK STATIC SYSTEM REF: See Workcard	MOS	24	+10%/-10%	-25		14-MAR-2018 5176:55	17-FEB-2020	29-APR-2020
		HRS/MSC					4778		
		AFL							
34-14/83 34.020	CALIBRATION CHECK ALTIMETER REF: See Workcard	MOS	24	+10%/-10%	-25		14-MAR-2018 5176:55	17-FEB-2020	29-APR-2020
		HRS/MSC					4778		
		AFL							
34-21/84 34.030	SWING CHECK STANDBY MAGNETIC COMPASS REF: AMM 34-21-00	MOS	24	+10%/-10%	-25		14-MAR-2018 5176:55	17-FEB-2020	29-APR-2020
		HRS/MSC					4778		
		AFL							
34-25/85 34.040	CHECK SWING ATTITUDE HEADING REFERENCE SYSTEM (AHRS) REF: AMM 34-25-00	MOS	24	+10%/-10%	-25		14-MAR-2018 5176:55	17-FEB-2020	29-APR-2020
		HRS/MSC					4778		
		AFL							
34-54/86 34.050	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) REF: See Workcard	MOS	24	+10%/-10%	-25		14-MAR-2018 5176:55	17-FEB-2020	29-APR-2020
		HRS/MSC					4778		
		AFL							
340005 31.020	PILOT ALTIMETER 9859911207 07080832D REF: GENERIC NO REF	MOS					31-JAN-2008		
		HRS/MSC	O/C				0		
		AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340006	COPILOT ALTIMETER 70256N02D02 07080829D REF: AMM 34-14-12	MOS HRS/MSC AFL	O/C				02-MAR-2010 796:25 620		
340009	NO. 1 DME/IFF ANTENNA 9848110240 261-75728 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340010	PILOT VERTICAL SPEED INDICATOR 9651615101 319809 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340015	PILOT ATTITUDE INDICATOR 504.00.35.922 25306 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAR-2013 2208 1977		
340020	MARKER ANTENNA 9848110260 101-6503 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340025	EFIS 1 SG465 SYMBOL GENERATOR 975.96.32.402 3132 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-FEB-2014 2717:45 2508		
340026	STAND-BY ALTIMETER 5984PAD-3 475696 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:16 N:694:45 N:751			25-FEB-2014 2717:45 2508		
340030	COPILOT VERTICAL SPEED INDICATOR 9651615101 319813 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340034	EFIS 1 CONTROL,CP467 PANEL 071-01439-3100 3265 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C					06-NOV-2012 2050:45 1779	
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY 066-03137-3100 3533 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C					06-AUG-2013 2484:35 2238	
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY 066-03137-3100 3349 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				25-FEB-2014 2717:45 2508	
340044	TRIM TRIPLE INDICATOR 975.44.16.204 00590 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C					07-AUG-2015 3594:55 3282	
340055	PILOT AIRSPEED INDICATOR 9651213338 1045354 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
340059	WITH HARM FILTER,KN63 DME 9859911101 31461 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
340060	COPILOT AIRSPEED INDICATOR 9651213339 1044443 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
340065	WX-RADAR RT UNIT 071-01519-0101 10357 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					09-MAR-2015 3299:20 2998	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340070	RADAR CONTROL PANEL								
34.240	9859911518 3104 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 5601 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340080	NO. 2 TRANSPONDER								
34.080	9848110240 261-75729 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 A85740 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	9759632482 13051 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340100	FRONT KA92 GPS ANTENNA								
34.090	071-01553-0200 06521 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C				17-MAR-2016 3949:55 3624		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 7324 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	9859911823 10266 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU 124210-2022-001	MOS		R:2			27-APR-2017		
34.060	1395 REF: AMM 34-25-01	HRS/MSC AFL	O/C	R:0 R:0			4592:35 4216		
340115	VR/LC/GS/CV,KI204 INDICATOR 9859911302	MOS		N:4			15-MAY-2008		
34.220	57283 REF: AMM 34-51-05	HRS/MSC AFL	O/C	N:0 N:0					
340120	PILOT SIDE RMI,KNI582-1 INDICATOR 9859911771	MOS		N:0			31-JAN-2008		
34.210	12127 REF: AMM 34-22-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340130	AIR DATA COMPUTER 9859203111	MOS		N:0			31-JAN-2008		
34.400	2922 REF: AMM 34-13-11	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340135	MAGNETIC,STANDBY COMPASS 9999880103	MOS		N:0			22-JUN-2012		
34.130	AT-1283 REF: AMM 34-21-01	HRS/MSC AFL	O/C	N:0 N:0			1838:25 1611		
340140	4206-100-V2 RADOME 9857900003	MOS		N:0			31-JAN-2008		
34.420	848 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340145	ANTENNA,VHF NAV COUPLER 9848110412	MOS		N:0			31-JAN-2008		
34.160	5053 REF: AMM 34-51-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA 9848129101	MOS		N:0			31-JAN-2008		
34.110	543-41040 REF: AMM 34-42-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41052 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 17719 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 17701 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340180	NO. 2 CAL PROM AHRS,LCR-92 UNIT								
34.390	9859911823 10266 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340190	ADF.W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-00 69511 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JUN-2018 5340 4911		
340195	MULTI FUNCTION DISPLAY								
34.190	9859911863 8923 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	9859003045 6182 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	9859003044 5413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	9859003046 5712 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 2578 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				04-SEP-2015 3675:40 3343		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 7325 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1066 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				24-OCT-2018 5580 5118		
340240	NO. 1 FLUX,KMT112 VALVE								
34.350	9859911064 75271 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE								
34.250	9751120111 2495 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340255	AOA SENSOR LH UNIT								
34.330	9754421423 875 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340260	NO. 2 FLUX,KMT112 VALVE								
34.350	9859911064 54939 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				09-JUL-2015 3552:05 3248		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340280	LEFT PITOT TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340285	RIGHT PITOT TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
341005	LH AOA PLATE TEMP CONTROLLER 9754421417 U1745 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
341010	RH AOA PLATE TEMP CONTROLLER 9754421417 U1747 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
345015	HORIZON,ARTIFICIAL 504.0111.930 504011193025177 REF:	MOS HRS/MSC AFL	A/R	O:0 O:0 O:0			17-NOV-2015 3796:25 3492		
34C039	RADAR ALTIMETER,KRA405B MOD 13 9859911550 6893 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C040	GYRO,YAW RATE,KRG332 9859203151 11105 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C041	CONFIG.MODULE,071-00112-0200 9859911884 13835 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C043	INDICATOR,PICT NAV,KI525A 9859911062 B97078 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C044	GYRO,DIRECTIONAL,KG102A 060-15-00 53392 REF:	MOS HRS/MSC AFL	A/R				09-AUG-2017 4820:20 4415		
34C045	SLAVING,ACCESSORY,VERT,KA51B 9859911070 39683 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C046	INDICATOR VR/LC/GS,KI206 9859911303 71194 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C047	INDICATOR RMI,KI229 9859911331 13197 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C048	INDICATOR,DME,KDI574 066-1069-04 84317 REF:	MOS HRS/MSC AFL	A/R	O:0 O:0 O:0			25-FEB-2014 2717:45 2508		
34C049	ATC TRANSPONDER GTX330D-BLACK 011-00455-10 84206640 REF:	MOS HRS/MSC AFL	A/R				02-MAR-2010 796:25 620		
34C050	ATC TRANSPONDER GTX330D-BLACK 011-00455-10 84206959 REF:	MOS HRS/MSC AFL	A/R				02-MAR-2010 796:25 620		

Status Report
PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C051	ANTENNA,DME/IFF 9848110240 261-77130 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C052	GPS ANTENNA,CI 420-220 9859911209 143467 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C053	GPS ANTENNA,CI 420-220 CI 420-220 561077 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			02-FEB-2018 5105:55 4721		
34C054	STANDBY HORIZON 5040035922 25528 REF:	MOS HRS/MSC AFL	O/C				08-APR-2009 479:10 360		
34C055	OPERATIONAL CHECK STANDBY HORIZON 5040035922 25528 REF:	MOS HRS/MSC AFL	N/R				08-APR-2009 479:10 360		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m		-31	25-FEB-2019 5690 5210	25-JAN-2021	25-FEB-2021
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM) REF:	MOS HRS/MSC AFL	12				02-JUL-2019 5868:45 5355	02-JUL-2020	

CHAPTER 35 OXYGEN

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 18	MOS					PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 35-00-00	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
35-10/6	OXYGEN BOTTLE 21507-03	MOS	180				07-AUG-2015	31-JAN-2022	
35.010	C07011053	HRS/MSC					3594:55		
AIRWORTHINESS	REF: AMM 35-10-01	AFL					3282		
35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE 21507-03	MOS	60				17-JUL-2015	17-JUL-2020	
35.010	C07011053	HRS/MSC							
	REF: GENERIC NO REF	AFL							
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS	36	+10%/-10%			27-APR-2017	31-JAN-2020	18-MAY-2020
35.010	REF: AMM 35-20-00	HRS/MSC AFL					4592:35 4216		
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY 9571201210	MOS					25-FEB-2014		
35.040	SE17435	HRS/MSC	O/C				2717:45		
	REF: GENERIC NO REF	AFL					2508		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210 B133905 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	9738114401 796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
350035	3-POSITION CONTROL VALVE								
35.030	9633211101 2695 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
350040	ALTITUDE SENSING SWITCH								
35.020	9738152102 948 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
35C054	TRANSDUCER,OXYGEN PRESS								
	9571201184 7291-3-66 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
35C055	OXYGEN GAGE ASSY.								
	535.12.12.085 60189 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			13-NOV-2012 2066:45 1794		
CHAPTER 52	DOORS								
+ 52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC AFL	600	+10%/-10%			5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	600	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 52-10-00	AFL	42000				0		42000
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
	REF: AMM 52-00-01	AFL	42000				0		42000
52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN								
		MOS					31-JAN-2008		
		HRS/MSC	25000				0		25000
	REF: AMM 52-10-01	AFL	30000				0		30000
+ 52-10/472	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
	REF:	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
52.010		MOS	48	+10%/-10%		-17	17-FEB-2016	31-JAN-2020	24-JUN-2020
	REF: See Workcard	HRS/MSC	4000	+10%/-10%			3884:45	7884:45	8284:45
		AFL					3574		
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
+ 52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
AIRWORTHINESS	REF: AMM 52-20-00	MOS					31-JAN-2008		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
	REF: AMM 52-30-00	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	600	+10%/-10%			5788:15		
		AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/274 (s)	EXAMINE CARGO DOOR PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 52-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE	MOS					31-JAN-2008		
	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN	MOS					31-JAN-2008		
	REF: AMM 52-30-01	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS	MOS					31-JAN-2008		
52.020	PN	HRS/MSC	13000		N:0		0		13000
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000		N:0		0		17000
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM	MOS	48	+10%/-10%			17-FEB-2016	31-JAN-2020	24-JUN-2020
52.030	REF: See Workcard	HRS/MSC	4000	+10%/-10%		-17	3884:45	7884:45	8284:45
		AFL					3574		
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 52-70-00	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
520005	PASSENGER DOOR	MOS					31-JAN-2008		
52.050	5520512007	HRS/MSC	O/C		N:0		0		
	REF: AMM 52-10-01	AFL			N:0		0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512010 778 REF: AMM 52-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
520015	EMERGENGY 6 SERIE EXIT								
52.060	5520512009 778 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 53 FUSELAGE

+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF:	AFL					0		
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF: AMM 53-20-02	AFL					5294		
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: See Workcard	AFL	42000				0		42000
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000				0		42000
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-20-00	AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-30-00	AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-00-00	AFL	42000				0		42000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					31-JAN-2008		
53.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%			17-FEB-2016	31-JAN-2020	24-JUN-2020
53.030		HRS/MSC	4000	+10%/-10%	-17		3884:45	7884:45	8284:45
	REF: GENERIC NO REF	AFL					3574		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-17	17-FEB-2016 3884:45 3574	31-JAN-2020 7884:45	24-JUN-2020 8284:45
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-17	17-FEB-2016 3884:45 3574	31-JAN-2020 7884:45	24-JUN-2020 8284:45
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050	REF:	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-17	17-FEB-2016 3884:45 3574	31-JAN-2020 7884:45	24-JUN-2020 8284:45
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-17	17-FEB-2016 3884:45 3574	31-JAN-2020 7884:45	24-JUN-2020 8284:45
530005	FUS ASPC12 10 SERIE A T-1/2 ASSY								
53.080	REF: GENERIC NO REF	5530512112 778 AFL			N:0 N:0 N:0		31-JAN-2008 0 0		
CHAPTER 55	STABILIZERS								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				31-JAN-2008 0 0	20000 27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	REF:	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 21	MOS	12	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 55-00-00	HRS/MSC AFL	1200	+10%/-10%			5788:15 5294		
55-10/415	HORIZONTAL STABILIZER PN	MOS			N:0		31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	25000		N:0		0	25000	
LIFE LIMIT	REF: AMM 55-10-01	AFL	30000		N:0		0	30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		-17	17-FEB-2016	31-JAN-2020	24-JUN-2020
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			3884:45 3574	7884:45	8284:45
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		-17	17-FEB-2016	31-JAN-2020	24-JUN-2020
	REF: AMM 53-10-16	HRS/MSC AFL	4000	+10%/-10%			3884:45 3574	7884:45	8284:45
55-20/362	EXAMINE LEFT ELEVATOR	MOS					29-MAY-2015		
	REF: AMM 55-20-00	HRS/MSC AFL	32500			-4773: 20	3448:25	31175:05	
AIRWORTHINESS			42000			-4444	3156	40712	
+ 55-20/362	EXAMINE RIGHT ELEVATOR	MOS					31-JAN-2008		
	REF: AMM 55-20-00	HRS/MSC AFL	32500				0	32500	
AIRWORTHINESS			42000				0	42000	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					29-MAY-2015		
		HRS/MSC	32500		-4773:		3448:25		31175:05
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000		20		3156		40712
					-4444				
55-20/368	EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES	MOS					29-MAY-2015		
		HRS/MSC	32500		-4773:		3448:25		31175:05
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000		20		3156		40712
					-4444				
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES	MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0		42000
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		
+ 55-30/199	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						26-APR-2019		
		MOS					5788:15		
		HRS/MSC	N/A				5294		
	REF:	AFL							
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-30-00	AFL	42000				0		42000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/373	EXAMINE - RUDDER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55C056	FIN ASSY	MOS					31-JAN-2008		
	5553012040	HRS/MSC	A/R	N:0			0		
	778	AFL		N:0			0		
	REF:			N:0			0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 56	WINDOWS								
+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH PKG 3	MOS	12	+10%/-10%			PKG 20-SEP-2019 5983:25 5444		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%					
+ 56-11/12	REPLACE COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS PN	MOS		N:0			31-JAN-2008		
56.020	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
AIRWORTHINESS	REF: AMM 56-20-01	AFL		N:0			0		
+ 56-11/13	REPLACE COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
	REF: See Workcard	AFL		N:0			0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110107	MOS					31-JAN-2008		
	06352H9967	HRS/MSC	A/R				0		
	REF:	AFL					0		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110108	MOS					31-JAN-2008		
	06346H9579	HRS/MSC	A/R				0		
	REF:	AFL					0		
56-11/15	- LEFT HAND WINDSHIELD ASSY, (LH) ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110107	MOS					31-JAN-2008		
	06352H9967	HRS/MSC	A/R				0		
	REF:	AFL					0		
56-11/15	- RIGHT HAND WINDSHIELD ASSY, (LH) ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110108	MOS					31-JAN-2008		
	06346H9579	HRS/MSC	A/R				0		
	REF:	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS	MOS	120	+6m/-6m		-42	14-MAR-2018	31-JAN-2028	31-JUL-2028
	REF: AMM 56-11-02	HRS/MSC	11000	+500/-500			5176:55	16176:55	16676:55
		AFL					4778		
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
	REF: AMM 56-00-00	HRS/MSC	300	+10%/-10%			5983:25		
		AFL					5444		
560015	SIDE,LH WINDOW								
56.090	9598110111	MOS					31-JAN-2008		
	07118H4166	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		
560020	SIDE,RH WINDOW								
56.090	9598110112	MOS					31-JAN-2008		
	07156H8166	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029	MOS					31-JAN-2008		
	7367	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029	MOS					31-JAN-2008		
	7254	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029	MOS					31-JAN-2008		
	7371	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 7372 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 7255 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 7311 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 7369 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 7316 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 7370 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412091 07270H1704 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010	9598110107 06352H9967 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
AIRWORTHINESS									

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
	9598110108	MOS		N:0			31-JAN-2008		
56.010	06346H9579	HRS/MSC	O/C	N:0			0		
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
		MOS					31-JAN-2008		
57.010		HRS/MSC	20000				0	20000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0	27000	
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					31-JAN-2008		
57.010		HRS/MSC	20000				0	20000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0	27000	
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 3	MOS	12	+10%/-10%			20-SEP-2019		
		HRS/MSC	300	+10%/-10%			5983:25		
	REF:	AFL					5444		
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
		HRS/MSC	2400	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
		HRS/MSC	1200	+10%/-10%			5788:15		
	REF:	AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/412	EXAMINE WING TIPS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-33-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	25000				0		25000
		AFL	30000				0		30000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0		16000
		AFL	22500				0		22500
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
	REF:	HRS/MSC	16000				0		16000
		AFL	22500				0		22500
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		-17	17-FEB-2016	31-JAN-2020	24-JUN-2020
57.020	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			3884:45	7884:45	8284:45
		AFL					3574		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%		-17	17-FEB-2016	31-JAN-2020	24-JUN-2020
57.030	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			3884:45	7884:45	8284:45
		AFL					3574		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m		-42	14-MAR-2018	31-JAN-2028	31-JUL-2028
57.040	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			5176:55	16176:55	16676:55
		AFL					4778		
57-60/393	EXAMINE LEFT WING AILERON	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 57-60/393	EXAMINE RIGHT WING AILERON	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-60/411	EXAMINE AILERON TRIM TAB	MOS					31-JAN-2008		
	REF: AMM 57-60-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512016 2778 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
570015	WING RE 10A SERIE STRUCTURE								
57.070	5570512132 778 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
570025	AILERON LH 10A SERIE ASSY								
57.050	5570512015 2778 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
570035	WING LE 10A SERIE STRUCTURE								
57.070	5570512131 778 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 61 PROPELLERS/PROPULSORS

+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 21	MOS	12	+10%/-10%			26-APR-2019		
	REF:	HRS/MSC	1200	+10%/-10%			5788:15		
		AFL					5294		
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E4A-3D/E10477K KX568 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C				25-MAY-2015 3448:25 3156		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200

612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	8210-137H	MOS					11-APR-2016		
	15424596	HRS/MSC	3500	+500	N:99 O:0		3884:45	(7384:45) 7528:50	7884:45
OVERHAUL	REF: EMM 61-20-00	ENC			N:3159 O:0		3159		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 210949C 15409228 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500 +500	N:99 O:0 N:3884:45 O:0 N:3159 O:0			11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX568 Part # HC-E4A-3D/E10477K									
+ 610010	NO. 1 PROPELLER - OVERHAUL REF:	MOS HRS/MSC	72 +10%/-10% 4000 +10%/-10%				02-JUL-2014 2114:50	02-JUL-2020 (6114:50) 7026:05	07-FEB-2021 6514:50
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION REF:	MOS HRS/MSC	12 +1m/-1m 300 +10%/-10%				20-SEP-2019 5072:10	20-SEP-2020 (5372:10) 6283:25	20-OCT-2020 5402:10
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER REF:	MOS HRS/MSC	12 +1m/-1m 300 +10%/-10%				20-SEP-2019 5072:10	20-SEP-2020 (5372:10) 6283:25	20-OCT-2020 5402:10
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE 9682913023 K64312 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			30-APR-2008 0		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE 9682913023 K64313 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			30-APR-2008 0		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE 9682913023 K64314 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			30-APR-2008 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913023 K64315 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			30-APR-2008 0		
CHAPTER 71 POWER PLANT									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER PKG 20	MOS	12	+10%/-10%			26-APR-2019		
71.010	HRS/MSC 600 +10%/-10% REF: See Workcard AFL						5788:15 5294		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE PKG 20	MOS	12	+10%/-10%			30-NOV-2018		
	HRS/MSC 600 +10%/-10% REF: AMM 71-00-00 AFL						5633:45 5164		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH	MOS					20-SEP-2019		
71.040	HRS/MSC 300 +10%/-10% REF: AFL						5983:25 5444	6283:25	6313:25
71-00/106	CLEAN OIL PRESSURE TRANSDUCER ELECTRICAL CONNECTOR	MOS					31-JAN-2008		
71.020	HRS/MSC A/R REF: AMM 71-00-03 AFL						0 0		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS PKG 20	MOS	12	+10%/-10%			26-APR-2019		
71.030	HRS/MSC 600 +10%/-10% REF: AMM 71-00-03 AFL						5788:15 5294		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME 571.20.12.036	MOS					31-JAN-2008		
71.050	793 REF: AMM 71-00-05 AFL	HRS/MSC	20000	N:0 N:0			0 0	20000 27000	
AIRWORTHINESS			27000	N:0			0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS	MOS					31-JAN-2008		
71.050 AIRWORTHINESS	REF: AMM 71-00-04	HRS/MSC AFL	11000				0 0	11000	
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION	MOS					PKG 26-APR-2019		
	PKG 17	HRS/MSC AFL	A/R				5788:15 5294		
	REF: AMM 71-00-00								
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP	MOS	24	+10%/-10%			PKG 26-APR-2019		
	PKG 22	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
	REF:								
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)	MOS	12	+10%/-10%			PKG 20-SEP-2019		
	PKG 3	HRS/MSC AFL	300	+10%/-10%			5983:25 5444		
	REF:								
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT	MOS					PKG 26-APR-2019		
	PKG 17	HRS/MSC AFL	A/R				5788:15 5294		
	REF: AMM 71-00-00								
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME	MOS	24	+10%/-10%			PKG 26-APR-2019		
	PKG 22	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
	REF:								
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY	MOS					11-MAY-2016		
	9448121409	HRS/MSC	3500	+10%/-10%	N:2		4028:50	7528:50	7878:50
	9094	AFL			N:0		3721		
OVERHAUL	REF: AMM 71-00-01				N:0				

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:2			11-MAY-2016		
	9089	HRS/MSC	3500	+10%/-10%	N:0		4028:50	7528:50	7878:50
OVERHAUL	REF: AMM 71-00-01	AFL		N:0			3721		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:2			11-MAY-2016		
	9031	HRS/MSC	3500	+10%/-10%	N:0		4028:50	7528:50	7878:50
OVERHAUL	REF: AMM 71-00-01	AFL		N:0			3721		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409	MOS		N:2			11-MAY-2016		
	9083	HRS/MSC	3500	+10%/-10%	N:0		4028:50	7528:50	7878:50
OVERHAUL	REF: AMM 71-00-01	AFL		N:0			3721		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:2			11-MAY-2016		
	9037	HRS/MSC	3500	+10%/-10%	N:0		4028:50	7528:50	7878:50
OVERHAUL	REF: AMM 71-00-01	AFL		N:0			3721		
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT								
		MOS					31-JAN-2008		
		HRS/MSC	26600				0	26600	
AIRWORTHINESS	REF: AMM 71-00-05	AFL	35000				0	35000	
71-00/476 (s)	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS						PKG		
	PKG 17	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: GENERIC NO REF	AFL					0		
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 17	MOS					26-APR-2019		
		HRS/MSC	A/R				5788:15		
	REF:	AFL					5294		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 17	MOS					26-APR-2019		
		HRS/MSC	A/R				5788:15		
	REF:	AFL					5294		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710005	UPPER LH ENGINE VIBRATION ISOLATOR								
71.070	5712012106 3368 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR								
71.080	5712012106 3391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR								
71.090	5712012106 3369 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710035	LOWER LH ENGINE VIBRATION ISOLATOR								
71.100	5712012106 3366 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	5712012106 3379 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710050	ENGINE MOUNT (WELDED)								
	5712012036 793 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67B PCE-PR0764 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	N:3884:45			23-APR-2016 4028:50 3721		
71JFL05	PERFORM ENGINE RUN-UP								
	REF:	MOS HRS/MSC AFL	A/R						

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
710011	NO. 1 ENGINE - OVERHAUL	MOS					11-APR-2016		
OVERHAUL	REF: GENERIC NO REF	HRS/MSC ENC	3500	+200			3884:45 3159	(7384:45) 7528:50	7584:45
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE	MOS					20-SEP-2019		
	PKG 0 ,1	HRS/MSC ENC	300	+10%/-10%			5839:20 4783		
	REF: EMM 72-30-05								
710021	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					20-SEP-2019		
	REF: EMM 72-00-00	HRS/MSC ENC	1750	+250			5839:20 4783	(7589:20) 7733:25	7839:20
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					20-SEP-2019		
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			5839:20 4783	(6139:20) 6283:25	6169:20
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					20-SEP-2019		
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			5839:20 4783	(6139:20) 6283:25	6169:20
710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION	MOS					24-SEP-2012		
	REF: See Workcard	HRS/MSC ENC	A/R				1998:15 1597		
710053	NO. 1 ENGINE - AIR INLET HOUSING CORROSION INSPECTION	MOS					25-FEB-2014		
	REF:	HRS/MSC ENC	-				2717:45 2217		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710061	NO. 1 ENGINE - PERFORM	ENGINE CONDITION TREND MONITORING (ECTM)							
	REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						PKG		
	PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		
	REF: EMM 71-00-00								
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE								
	3042200	MOS					11-APR-2016		
	PS-PR0764	HRS/MSC	3500	+500			3884:45	(7384:45) 7528:50	7884:45
OVERHAUL	REF: See Workcard	ENC							
+ 720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				10-SEP-2018 5341:35 4361		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP								
	REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				10-SEP-2018 5341:35 4361		
+ 720025	NO. 1 ENGINE - OVERTEMPERATURE								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF								
+ 720035	NO. 1 ENGINE - OVERTORQUE	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
	REF: EMM 72-00-00								
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF								
+ 720045	NO. 1 ENGINE - HEAVY/HARD LANDING	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
	REF: EMM 72-00-00								
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF								
+ 720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
	REF: EMM 72-00-00								
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF								
+ 721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
	REF: EMM 72-00-00								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS REF: EMM 72-11-00	MOS HRS/MSC ENC	A/R				(EBT)		
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0 ,1 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0 ,1 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
+ 722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 722030	NO. 1 ENGINE - IMMERSION IN WATER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3039001 EAAB000D576	MOS HRS/MSC		N:0 N:0			31-JAN-2008 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24661	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA026507	MOS HRS/MSC		N:9295			11-APR-2016 3884:45		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:15004			3159	(12155) 12816	
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 0 ,1	MOS HRS/MSC	300	+10%/-10%			20-SEP-2019 5839:20	PKG	
	REF: EMM 72-30-04	ENC					4783		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040952 TXA1B2817	MOS HRS/MSC		N:0 N:0			31-JAN-2008 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24661	
+ 723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 0 ,1	MOS HRS/MSC	300	+10%/-10%			20-SEP-2019 5839:20	PKG	
	REF: See Workcard	ENC					4783		
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000D014	MOS HRS/MSC		N:0 N:0			31-JAN-2008 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24661	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 TXA1B3778	MOS HRS/MSC		N:0 N:0			31-JAN-2008 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24661	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 TXA1B4010	MOS HRS/MSC		N:0 N:0			31-JAN-2008 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24661	
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS HRS/MSC A/R					31-JAN-2008 0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		
+ 724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS	MOS HRS/MSC A/R					31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE	MOS HRS/MSC A/R					31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 724020	NO. 1 ENGINE - HIGH OIL PRESSURE	MOS HRS/MSC A/R					31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS	MOS HRS/MSC A/R					31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT	MOS HRS/MSC A/R					31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 724050	NO. 1 ENGINE - MATERIAL INGESTION	MOS					31-JAN-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN	MOS					31-JAN-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 725003	NO. 1 ENGINE - OVERSPEED	MOS					31-JAN-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS					31-JAN-2008		
	3053740-01	HRS/MSC		N:0			0		
	A0029598	ENC	8000	N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	N:0			0		(8000) 8661
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					11-APR-2016		
	REF: GENERIC NO REF	HRS/MSC ENC	5000				3884:45 3159		(8884:45) 9028:50
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS					PKG		
	PKG 0 ,1	HRS/MSC	300	+10%/-10%			20-SEP-2019		
	REF: EMM 72-50-05	ENC					5839:20 4783		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS					31-JAN-2008		
	3037312	HRS/MSC		N:0			0		
	A0029CXX	ENC	15000	N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0		(15000) 15661
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS					31-JAN-2008		
	3037313	HRS/MSC		N:0			0		
	A0029A9M	ENC	15000	N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0		(15000) 15661

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726020	NO. 1 ENGINE - POWER SECTION MODULE 3042200 PCE-PR0764	MOS HRS/MSC	3500	+500			11-APR-2016 3884:45	(7384:45) 7528:50	7884:45
OVERHAUL	REF: GENERIC NO REF	ENC		O:0 O:0 O:0					
+ 726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
+ 726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF: EMM 72-00-00	ENC					0		
CHAPTER 73	ENGINE FUEL AND CONTROL								
73C059	FUEL,PUMP,3040760 9682013157 8627	MOS HRS/MSC	A/R				31-JAN-2008 0		
	REF:	AFL		N:0 N:0 N:0			0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
731010	NO. 1 ENGINE - FUEL PUMP 825601-5 008627	MOS HRS/MSC	3500				11-APR-2016 3884:45	(7384:45) 7528:50	
OVERHAUL	REF: EMM 73-10-02	ENC		N:99 O:0 N:3884:45 O:0 N:3159 O:0			3159		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731024	NO. 1 ENGINE - FUEL NOZZLE 3119855-01 N/A REF:	MOS HRS/MSC ENC	O/C				20-SEP-2019 5839:20 4783		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3244882-2 C50835 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 008627 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			26-APR-2019 5644:10 4633	(6244:10) 6388:15	6304:10
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 ,1 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
+ 731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 ,1 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA30908 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 9959524669 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-650 16571432 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	O:0 O:0 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 ,1 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	4000		N:0		23-APR-2016 3884:45	(7884:45) 8028:50	

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0 ,1 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T		N:0 N:0 N:0		20-SEP-2019 5839:20 4783		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0 ,1 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			30-NOV-2018 5489:40 4503	(6389:40) 6533:45	6479:40
733030	NO. 1 ENGINE - MAIN FUEL FILTER ASSEMBLY 3059779-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		29-MAY-2015 3448:25 2806		
733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 1 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		

CHAPTER 74 IGNITION

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 20-SEP-2019 5983:25 5444		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA16100164 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:1 N:0 N:0		11-MAY-2016 3884:45 3159	(7384:45) 7528:50	7884:45
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG CH34055 N/A REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		14-MAR-2018 5032:50 4117		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG CH34055 N/A REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		14-MAR-2018 5032:50 4117		
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783	(6139:20) 6283:25	6169:20
CHAPTER 75	AIR								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75C060	VALVE ASSY.,3123532-01B 9682013191 AHX009487 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX009487 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
--------	---	-----------------------	------	------	---	--	--------------------------------	-------------------	---------

CHAPTER 76 ENGINE CONTROLS

+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 20 REF:	MOS HRS/MSC AFL	12	+10%/-10%			26-APR-2019 5788:15 5294		
-----------------	---	-----------------------	----	-----------	--	--	--------------------------------	--	--

+ 76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			20-SEP-2019 5983:25 5444		
-----------------	---	-----------------------	----	-----------	--	--	--------------------------------	--	--

+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 18 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			20-SEP-2019 5983:25 5444		
-----------------	--	-----------------------	-----	-----------	--	--	--------------------------------	--	--

+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%			26-APR-2019 5788:15 5294		
-----------------	--	-----------------------	----	-----------	--	--	--------------------------------	--	--

+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3 REF:	MOS HRS/MSC AFL	12	+10%/-10%			20-SEP-2019 5983:25 5444		
-----------------	---	-----------------------	----	-----------	--	--	--------------------------------	--	--

Status Report
PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES								
76.010	REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+1m/-1m +10%/-10%			20-SEP-2019 5983:25 5444	20-SEP-2020 8983:25	20-OCT-2020 9283:25
760015	MANUAL OVERRIDE CABLE ASSY.								
76.020	9419411417 20070066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
760020	CONDITION CABLE ASSY.								
76.030	9419411418 20070072 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419 20070067 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
+ 761011 (s)	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES						PKG		
	PKG 0 ,1	MOS HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		
	REF: EMM 72-00-00								
CHAPTER 77 ENGINE INDICATING									
+ 77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			20-SEP-2019 5983:25 5444		
	REF: See Workcard								
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206 7765-6-455 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JAN-2012 1601:05 1393		

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	9752115219 10832297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-MAR-2018 5176:55 4778		
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.034 183 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2016 4139:30 3816		

ENGINE NO. 1	Model : PT6A-67B	Serial # PCE-PR0764	Part # 3042200
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS		
	3043825-01 NRA006949 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C
			O:0 O:0 O:0
			11-APR-2016 3884:45 3159

CHAPTER 78	EXHAUST
+ 78-00/214 (s)	EXAMINE EXHAUST STUBS
	PKG 3
	MOS 12 +10%/-10%
	HRS/MSC 300 +10%/-10%
	REF: AFL
	20-SEP-2019 5983:25 5444

CHAPTER 79	OIL
+ 79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY.
	PKG 20
	MOS 12 +10%/-10%
	HRS/MSC 600 +10%/-10%
	REF: AMM 24-00-00
	AFL
	26-APR-2019 5788:15 5294
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT
	PKG 21
	MOS 12 +10%/-10%
	HRS/MSC 1200 +10%/-10%
	REF: AFL
	26-APR-2019 5788:15 5294
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM
	PKG 3
	MOS 12 +10%/-10%
	HRS/MSC 300 +10%/-10%
	REF: AMM 79-30-01
	AFL
	20-SEP-2019 5983:25 5444

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20/43	OIL COOLER								
79.010	9683214102 T0327 REF: AMM 79-20-02	MOS HRS/MSC AFL	4000 +500	O:0 O:0 O:0			07-APR-2016 3994:05 3669	7994:05	8494:05
790005	TEMPERATURE BULB								
79.020	9751120101 142042 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
790020	PRESSURE,GAGE SWITCH								
79.030	9738114305 819 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
790025	THERMAL ACTUATOR								
79.040	9787301002 969 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
790030	POWER ODM,B049913 MODULE								
79.050	9752115240 44650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
79C061	SENSOR MODULE,ODM,B057185 REV.D								
	9752115242 44328 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
701020	NO. 1 ENGINE - CONTAMINATION OF OILWITH NON-METALLIC FOREIGN MATERIAL								
		MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
	REF: GENERIC NO REF								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					30-JUL-2019		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				5757:10 4720		
+ 790031 (s)	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS					PKG		
	PKG 1	HRS/MSC ENC	300	+10%/-10%			20-SEP-2019 5839:20 4783		
	REF: EMM 79-20-02								
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS	12				20-SEP-2019	20-SEP-2020	
		HRS/MSC ENC	300	+10%/-10%			5839:20 4783	(6139:20) 6283:25	6169:20
	REF: EMM 79-20-02								
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS					26-APR-2019		
		HRS/MSC ENC	900	+10%/-10%			5644:10 4633	(6544:10) 6688:15	6634:10
	REF: EMM 79-20-02								
+ 790060 (s)	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN	MOS					PKG		
	PKG 1	HRS/MSC ENC	300				20-SEP-2019 5839:20 4783		
	REF: See Workcard								
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					20-SEP-2019		
		HRS/MSC ENC	300	+10%/-10%			5839:20 4783	(6139:20) 6283:25	6169:20
	REF: EMM 72-60-00								
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					31-JAN-2008		
		HRS/MSC ENC	A/R				0 0		
	REF: EMM 79-20-02								
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING	MOS					31-JAN-2008		
		HRS/MSC ENC	N/A				0 0		
	REF: EMM 72-00-00								

Status Report

PC12/45 S/N 876 (LX-JFQ): 6156:25 HRS, 5601 AFL as of 20-Jan-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 21-JAN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0 ,1	MOS HRS/MSC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF	ENC							
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0 ,1	MOS HRS/MSC	300	+10%/-10%			PKG 20-SEP-2019 5839:20 4783		
	REF: GENERIC NO REF	ENC							