

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 876/LX-JFQ **MODEL:** PC12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 31-JAN-2008	6477:25 A/C HRS	as of 16-SEP-2020	A/C HRS	as of ___/___/___
	5847 AFL	as of 16-SEP-2020	AFL	as of ___/___/___
	116:24 ACH	as of 13-JUL-2020	ACH	as of ___/___/___
	5246 FLTS	as of 16-SEP-2020	FLTS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-PR0764/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-APR-2016	LAST ACTUALS		CURRENT ACTUAL	
3884:45 ENG. HRS 4028:50 A/C HRS	6333:20 ENG. HRS	as of 16-SEP-2020	ENG. HRS	as of ___/___/___
3159 ENC	5186 ENC	as of 16-SEP-2020	ENC	as of ___/___/___

PROPELLER NOSERIAL/PART: KX568/HC-E4A-3D/E10477K **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 25-MAY-2015	LAST ACTUALS		CURRENT ACTUAL	
2537:10 PROP HRS 3448:25 A/C HRS	5566:10 PROP HRS	as of 16-SEP-2020	PROP HRS	as of ___/___/___



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 17	MOS				31-JAN-2008		
		HRS/MSC	A/R			0		
	REF: AMM 05-20-00	AFL				0		
05401A	300 HOUR INSPECTION							
+								
	PKG 18	MOS				09-JUN-2020		
		HRS/MSC	300	+30/-30		6214:55	6514:55	6544:55
	REF: AMM 05-40-01	AFL				5654		
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 3	MOS	12	+1m/-1m		09-JUN-2020	09-JUN-2021	09-JUL-2021
		HRS/MSC	300	+30/-30		6214:55	6514:55	6544:55
	REF: AMM 05-40-01	AFL				5654		
05403A	600 HOUR INSPECTION							
+								
	PKG 19	MOS				09-JUN-2020		
		HRS/MSC	600/-	+30/-30		6214:55	6814:55	6844:55
	REF: AMM 05-40-01	AFL				5654		
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 20	MOS	12	+1m/-1m	-44	09-JUN-2020	26-APR-2021	26-MAY-2021
		HRS/MSC	600	+30/-30		6214:55	6814:55	6844:55
	REF: AMM 05-40-01	AFL				5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 21	MOS	12	+1m/-1m	-44	09-JUN-2020	26-APR-2021	26-MAY-2021
		HRS/MSC	1200	+30/-30		6214:55	7414:55	7444:55
	REF: AMM 05-40-01	AFL				5654		
<hr/>								
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+								
	PKG 22	MOS	24	+1m/-1m		26-APR-2019	26-APR-2021	26-MAY-2021
		HRS/MSC	2400	+30/-30		5788:15	8083:25 M	8113:25
	REF: AMM 05-40-01	AFL				5294		
<hr/>								
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-PR0764 Part # 3042200								
057010	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 0	MOS				09-JUN-2020		
		HRS/MSC	300/-	+30/-30		6070:50	(6370:50) 6514:55	6400:50
	REF: See Workcard	ENC				4993		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED PKG 3,17	MOS					PKG	09-JUN-2020	
	REF:	HRS/MSC	A/R					6214:55	
		AFL						5654	
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH PKG 3,17	MOS					PKG	09-JUN-2020	
	REF: GENERIC NO REF	HRS/MSC	A/R					6214:55	
		AFL						5654	
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION PKG 3,17	MOS					PKG	09-JUN-2020	
	REF: GENERIC NO REF	HRS/MSC	A/R					6214:55	
		AFL						5654	
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02049 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						14-JUL-2020	
	REF:	HRS/MSC	-					6278:45	
		AFL						5701	
00JFL64	PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 4 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						26-APR-2019	
	REF:	HRS/MSC	-					5788:15	
		AFL						5294	
00JFL65	PERFORM PERFORM INSPECTION FOLLOWING JFL PE PC12 LEG ED 6 AMDT 5 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						30-MAR-2020	
	REF:	HRS/MSC	-					6212:10	
		AFL						5650	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL7.0	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 7 AMDT 0 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - REF: AFL						09-JUN-2020 6214:55 5654	
00JFL7.1	PERFORM INSPECTION FOLLOWING JFL AMP PC12 LEG ED 7 AMDT 1 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS HRS/MSC - REF: AFL							
PC12-110608	REVIEW AMM REVISION 23, CHAPTER 4 & 5 - CAMP CHANGE FORM	MOS HRS/MSC - REF: RCF PC12 AFL					(EBT)		
PC12-120228	REVIEW PC-12 - AMM TR NO. 05-04 - CAMP CHANGE FORM	MOS HRS/MSC - REF: RCF PC12 AFL					(EBT)		
PC12-120316	REVIEW PC-12 AMM REVISION 25 - CAMP CHANGE FROM	MOS HRS/MSC - REF: RCF PC12 AFL					(EBT)		
PC12-130301	REVIEW PILATUS PC12 AMM CHAPTER 4 & 5 REVISION 26 - CAMP CHANGE FORM	MOS HRS/MSC - REF: RCF PC12 AFL					(EBT)		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-130906	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140330	REVIEW PC12 CHAPTER 4 & 5 REVISION NO. 27 - CAMP CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140401	REVIEW PC12 CHAPTER 4 TR 04-04 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-140721	REVIEW 12-A-AM-00-00-00-I, DOC #. 02049 AMM, REVISION 28, DATED 22 MAY 2014 CAMP REQUIREMENT CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF	MOS					04-MAY-2016		
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-160717	REVIEW PILATUS PC12 AMM REV 32	MOS						23-NOV-2016	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS						07-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS						29-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS						31-JAN-2008	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL						0 0	
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS						31-JAN-2008	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL						0 0	
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-190517	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38	MOS						19-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
PC12-200515	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 39	MOS						12-AUG-2020	
REQUIREMENT CHANGE FORMS	REF: RCF PC12	HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-150404	NO. 1 ENGINE - REVIEW	PWC, PT6A-72-14002	REVISION NO. 22	DATED NOV 16/2012	RCF				
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-150812	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 43.0					10-SEP-2015	
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-160317	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	SB PT6A-72-14603	REV 25				16-SEP-2016	
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-160421	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 44.0					03-JUN-2016	
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-160919	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	SB PT6A-72-14603	REV 26				01-FEB-2017	
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-170113	NO. 1 ENGINE - REVIEW	PT6A-67B/-67P	EMM REV 44.1					31-JAN-2017	
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0	MOS						16-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1	MOS						04-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2	MOS						11-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072-170818	HRS/MSC - ENC							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0	MOS						22-FEB-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						23-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS					13-JAN-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS					23-APR-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS						10-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX568 Part # HC-E4A-3D/E10477K									
P019-150423	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF	MOS						10-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS						31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS						16-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS						22-FEB-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS						06-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS						01-JAN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-200301	NO. 1 PROPELLER - REVIEW	PROPELLER	ICE PROTECTION SYSTEM	MANUAL (MANUAL 180)	REVISION 32			(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
P019-200501	NO. 1 PROPELLER - REVIEW	HC-E4A-3	POM 149	REV 26				05-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
P019-200501-1	NO. 1 PROPELLER - REVIEW	HC-E4A-3	POM 147	REV 16				(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
P019-200701	NO. 1 PROPELLER - REVIEW	HC-E4A-3	POM 149	REV 27				(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
P019-200801	NO. 1 PROPELLER - REVIEW	PROPELLER	ICE PROTECTION SYSTEM	MANUAL 180	REV 33			(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P019	MOS HRS/MSC	-						
	NEW REQUIREMENT ADDED ON 12-AUG-2020 (EFFECTIVE: 01-AUG-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER 04	LIMITATIONS
+ 040001	AIRCRAFT LIMIT OF VALIDITY
	PN MOS N:0 31-JAN-2008
	SN-UNKNOWN HRS/MSC 20000 N:0 0 20000
	REF: GENERIC NO REF AFL 27000 N:0 0 27000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
+ 040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-50-01	UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER SUDDEN PROPELLER STOPPAGE								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE								
		MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS						31-JAN-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					31-JAN-2008		
	REF: AMM 05-10-30	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
+ 050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					31-JAN-2008		
	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
05JFL11	AIRWORTHINESS REVIEW CERTIFICATE	MOS					09-MAR-2020	09-MAR-2021 M	
	REF:	HRS/MSC	DUE				6208:25		
		AFL					5647		
05JFL12	- CERTIFICATE OF REGISTRATION	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL13	- NOISE CERTIFICATE	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
05JFL14	- AIRCRAFT STATION LICENCE	MOS					16-NOV-2018	31-DEC-2021 M	
	REF:	HRS/MSC	DUE						
		AFL							
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING	MOS					09-JUN-2020		
	REF:	HRS/MSC	300	+10%/-10%			6214:55	6514:55	6544:55
		AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 06 DIMENSIONS AND AREAS									
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION PKG 3,17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION PKG 3,17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR. PKG 3,17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB. 61KB. 61MB. 61NB. 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL PKG 3,17 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 3,17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 3,17 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE MUST TO BE PERFORMED WITH EX-6S-2 CONFIGURATION AND LIFE VEST REF:	MOS HRS/MSC AFL	60	+1m/-1m			11-MAY-2016 4028:50 3721	11-MAY-2021	11-JUN-2021
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED (FILL FORM W&B IN, POH SECTION 6) REF:	MOS HRS/MSC AFL	A/R				26-APR-2019 5788:15 5294		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			09-JUN-2020 6214:55 5654		
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%			09-JUN-2020 6214:55 5654		
CHAPTER 12 SERVICING									
12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS PKG 3,17 REF: AMM 12-20-01	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 3,17 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 3,17 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)	MOS	12	+10%/-10%			09-JUN-2020	26-APR-2021	01-JUN-2021
20.010	REF: AMM 20-40-00	HRS/MSC AFL			-44		6214:55 5654		
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL) TRACKED ITEM	MOS	6	+10%/-10%			09-JUN-2020	09-DEC-2020	27-DEC-2020
20.011	REF: AMM 20-40-00	HRS/MSC AFL	300	+10%/-10%			6214:55 5654	6514:55	6544:55
20JFL01	PERFORM DENTS AND BUCKLES CHARTS REF:	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654	6514:55	6544:55
CHAPTER 21 AIR CONDITIONING									
+ 21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
		HRS/MSC	2400	+10%/-10%			5788:15		
	REF: GENERIC NO REF	AFL					5294		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
		MOS	24	+10%/-10%		-87	09-JUN-2020	14-MAR-2022	26-MAY-2022
21.040		HRS/MSC	3000	+10%/-10%			6214:55	9214:55	9514:55
	REF: AMM 21-30-00	AFL					5654		
21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
		MOS	24	+10%/-10%		-87	09-JUN-2020	14-MAR-2022	26-MAY-2022
21.030		HRS/MSC	3000	+10%/-10%			6214:55	9214:55	9514:55
	REF: AMM 21-30-01	AFL					5654		
21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
		MOS	60	+10%/-10%		-28	14-MAR-2018	14-FEB-2023	14-AUG-2023
21.010		HRS/MSC					5176:55		
	REF: AMM 21-30-07	AFL					4778		
21-30/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
		MOS	60	+10%/-10%		-28	14-MAR-2018	14-FEB-2023	14-AUG-2023
21.020		HRS/MSC					5176:55		
	REF: AMM 21-30-08	AFL					4778		
+ 21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
	REF: AMM 21-40-11	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER						PKG		
21.080	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 21-40-02	HRS/MSC	1200	+10%/-10%			6214:55		
		AFL					5654		
+ 21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH								
21.130		MOS	60	+10%/-10%	-28		14-MAR-2018	14-FEB-2023	14-AUG-2023
	REF: AMM 21-40-06	HRS/MSC	4800	+10%/-10%			5176:55	9976:55	10456:55
		AFL					4778		
+ 21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH								
21.120		MOS	60	+10%/-10%	-28		14-MAR-2018	14-FEB-2023	14-AUG-2023
	REF: AMM 21-60-05	HRS/MSC	4800	+10%/-10%			5176:55	9976:55	10456:55
		AFL					4778		
21-40/53	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 101-320 WITHOUT A MODIFIED AUXILIARY HEATING SYSTEM)								
		MOS					31-JAN-2008		
	REF: AMM 21-40-09	HRS/MSC	N/A				0		
		AFL					0		
+ 21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 21-40-00	HRS/MSC	1200	+10%/-10%			6214:55		
		AFL					5654		
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 19	MOS					09-JUN-2020		
	REF: AMM 21-40-01	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 19 REF: AMM 21-40-01	MOS HRS/MSC AFL	600	+10%/-10%			09-JUN-2020 6214:55 5654		
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT						PKG		
	PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)						PKG		
	1134400-53 178 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654	6514:55	6544:55
21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	1134400-53 178 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	N/A						
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	1134400-53 178 REF: See Workcard	MOS HRS/MSC AFL ACH	N/A						
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	1134400-53 178 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	500	+10%/-10%			03-AUG-2018 5430:30 4979 0	500	550



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.100	1134400-53 178 REF: See Workcard	MOS HRS/MSC AFL ACH					03-AUG-2018 5430:30 4979 0	500	550
21005	OVERPRESSURE SWITCH								
21.340	9738115105 659 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210010	REFRIGERATION PACK								
21.255	9599020111 1439 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1399 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 1601 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1408 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210030	HP SHUT OFF VALVE								
21.280	9599020131 1208 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C				06-JUL-2017 4733:55 4347		
210035	WATER SEPARATOR ASSY								
21.220	5214112060 2572 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1399 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	1134400-53 178 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-AUG-2018 5430:30 4979		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	1134104-6 0125 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			09-JUN-2020 6214:55 5654		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 298 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.118 449 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-AUG-2009 657:20 502		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 304 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091123 47-C0162 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091133 97-G0196 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	9599091111 37-8267 REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210075	CHECK VALVE								
21.400	9599091151 97-A1321 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210080	JET PUMP								
21.410	9599091161 97-2404 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210085	MANUAL CONTROLLER								
21.420	9599091101 87-A0792 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210090	OUTFLOW VALVE CONTROLLER								
21.430	959.90.91.141 89-G0229 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			22-JUN-2012 1838:25 1611		
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	3G10.32.35F.05.1.AL 1045442 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C				13-JUN-2008 158:06 106		
210100	CAB RATE INDICATOR								
21.440	9651621002 1045392 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	DDS.AE 1044267 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C				14-MAR-2018 5176:55 4778		
210110	CABIN PX SWITCH								
21.360	9652321533 1013653 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-FEB-2013 2186:05 1951		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 528964 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210120	BAY TEMP SENSOR								
21.450	9599020122 1424 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	9751516101 D0150 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210130	TEMP CONTROLLER								
21.235	9599020123 1403 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210140	SOLENOID VALVE								
21.300	9631411001 09-0823421 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 528967 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	9633011106 0642B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	9633011002 630 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 681 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21C007	TEMP TRANSMIT,T21.10.110-HG1610A 9751516106 599 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
21C008	TEMP TRANSMIT,T21.10.110-S1503 A 9751516105 586 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
21C009	MAX CABIN ALTITUDE SWITCH 9652321533 1045398 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
21C010	DIFFERENTIAL PRESURE SWITCH 9652321534 1044267 REF:	MOS HRS/MSC AFL	A/R	R:0 R:0 R:0			09-APR-2018 5176:55 4778		
21JFL02	PERFORM AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST REF:	MOS HRS/MSC AFL	24	+10%/-10%		1	26-APR-2019 5788:15 5294	27-APR-2021	09-JUL-2021
CHAPTER 22 AUTO FLIGHT									
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			26-APR-2019 5788:15 5294		
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK REF: AMM 22-10-00	MOS HRS/MSC AFL	12	+10%/-10%		-44	09-JUN-2020 6214:55 5654	26-APR-2021 7214:55	01-JUN-2021 7314:55



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 3 REF: AMM 22-20-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 18 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 21 REF: AMM 22-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
220005 22.160	AUTOPILOT MODE CONTROL 9859203121 2863 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220010 22.180	ALTITUDE PRESELECTOR 9859203131 2792 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220015 22.100	AILERON KSA372,065-00056-0056 ACTUATOR 9859203161 6416 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220020 22.190	PITCH KSM375,065-00015-0000 MOUNT 9859203173 A10558 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR								
22.110	9859203164 1379 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	9859203171 A10562 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	065-0056-80 MOD3 6283 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C				04-DEC-2014 3189:25 2890		
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	9859203171 A10548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220045	STICK PUSHER SERVO								
22.220	9786111103 80276 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220050	PITCH TRIM ADAPTER								
22.130	9859203181 1932 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	9786111124 80277 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220060	STICK SHAKER								
22.230	9786111143 785 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
220065	AUTOPILOT COMPUTER								
22.150	065-0064-15 2420 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				10-DEC-2012 2104:15 1870		
220070	STICK PUSHER COMPUTER								
22.170	9754423104 121558 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
CHAPTER 23 COMMUNICATIONS									
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203 310-16820 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-16830 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
230025	AUDIO SUMMING AMPLIFIER								
23.010	9878133108 517 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
23C011	AUDIO PANEL,GMA 340								
	9856115113 96281867 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
23JFL01	NO. 1 NAV/COM/GPS TRANSCEIVER 011-00550-10 78409049 REF:	MOS HRS/MSC AFL	O/C				30-JUN-2020 6273:25 5699			
23JFL02	NO. 2 NAV/COM/GPS TRANSCEIVER 011-00550-10 78406071 REF:	MOS HRS/MSC AFL	O/C				30-JUN-2020 6273:25 5699			
CHAPTER 24 ELECTRICAL POWER										
+ 24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM						PKG			
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020			
		HRS/MSC	1200	+10%/-10%			6214:55			
	REF: AMM 24-20-00	AFL					5654			
+ 24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT						PKG			
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020			
		HRS/MSC	300	+10%/-10%			6214:55			
	REF: See Workcard	AFL					5654			
+ 24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED)						PKG			
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020			
		HRS/MSC	300	+10%/-10%			6214:55			
	REF: See Workcard	AFL					5654			
24-30/19	STARTER GENERATOR									
	23085-029A	MOS					20-SEP-2019			
24.020	Y0276	HRS/MSC	N/A				5983:25			
	REF: AMM 24-30-01	AFL					5444			



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/20 (s)	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING								
	940.83.08.902	MOS		N:0			26-APR-2019		
24.040	940.83.08.902	HRS/MSC	3000	+10%/-10%	N:0	211:45	5788:15		
DISCARD	REF: AMM 24-30-04	AFL		N:0			5294		
+ 24-30/21	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING								
	PN	MOS		N:0			26-APR-2019		
	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%	N:0		5788:15	8788:15	9088:15
DISCARD	REF: AMM 24-30-04	AFL		N:0			5294		
+ 24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
		HRS/MSC	2400	+10%/-10%			5788:15		
	REF: See Workcard	AFL					5294		
+ 24-30/482 (s)	STARTER GENERATOR FOR BRUSH WEAR						PKG		
	23085-029A PKG 19	MOS					09-JUN-2020		
	Y0276	HRS/MSC	600	+10%/-10%			6214:55		
	REF: AMM 24-30-01	AFL					5654		
24-30/491	OVERHAUL STARTER GENERATOR								
	23085-029A	MOS					20-SEP-2019		
	Y0276	HRS/MSC	1200	+10%/-10%			5983:25	7183:25	7303:25
OVERHAUL	REF: GENERIC NO REF	AFL					5444		
+ 24-30/61	BRUSH CHECK STARTER GENERATOR BRUSHES (ALL P/N'S EXCEPT 978.91.23.407, 978.91.23.408 AND 978.91.23.409)								
	23085-029A	MOS					26-APR-2019		
24.020	Y0276	HRS/MSC	N/A				5788:09		
	REF: AMM 24-30-01	AFL					5294		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS								
24.210	REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%		-87	09-JUN-2020 6214:55 5654	14-MAR-2022	26-MAY-2022
+ 24-30/63	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES								
24.030	5243212158 MOD G 100907 REF: AMM 24-30-02	MOS HRS/MSC AFL	N/A				26-APR-2019 5788:15 5294		
24-30/64 (s)	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES						PKG		
	5243212158 MOD G PKG 19 100907 REF: AMM 24-30-02	MOS HRS/MSC AFL	600	+10%/-10%			09-JUN-2020 6214:55 5654		
24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
24.030	REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A			-18:20	17-FEB-2016 3884:45 3574		
+ 24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING								
	REF: AMM 24-30-04	MOS HRS/MSC AFL	1800	+10%/-10%		78:10	26-APR-2019 5788:15 5294	7666:25	7846:25
24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	31406-002 11501227 REF: AMM 24-30-07	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 6514:55	15-JUL-2021 6544:55
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE								
	PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY								
24.050	501-1712-02 81391 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m		-44	09-JUN-2020 6214:55 5654	26-APR-2021	26-MAY-2021
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	9882114111 P1640 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JAN-2008 0 0		
240015	GENERATOR 2 300A CONTACTOR								
24.130	9740338113 N773 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JAN-2008 0 0		
240020	GENERATOR 1 300A CONTACTOR								
24.130	9740338113 N772 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JAN-2008 0 0		
240025	GENERATOR 2 2ND GENCON UNIT								
24.140	9882115103 10600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JAN-2008 0 0		
240035	BUSBAR,CROSS TIE RCCB								
24.150	9725537003 1479 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240040	BUSBAR,CROSS,TIE RCCB								
24.150	9725537005 831 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240045	STARTER RELAY								
24.160	9740926133 P915 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240050	BATTERY RELAY								
24.170	9740926126 R329 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240055	EPU RELAY								
24.180	9740926126 R425 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	9728132301 762 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240065	OVERHEAD PANEL								
24.190	9728132109 JWPIL2002370 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240075	HEATING,ELECTRICAL CONTROLLER								
24.200	9599020124 590 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240080	A241 26 VAC,SC3(A) INVERTER								
24.070	9750421112 552 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240085	A242 26 VAC,SC3(A) INVERTER								
24.070	9750421112 546 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240090	S102 DC CURRENT SENSOR								
24.080	9742900201 3933 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240095	S105 DC CURRENT SENSOR								
24.090	9742900205 2562 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240100	S108 DC CURRENT SENSOR								
24.100	9742900205 2552 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240105	S103 DC CURRENT SENSOR								
24.080	9742900201 3938 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
240110	S104 DC CURRENT SENSOR								
24.090	9742900201 3929 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240115	S106 DC CURRENT SENSOR								
24.100	9742900201 3815 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
243045	GENERATOR 2								
24.030	5243212158 MOD G 100907 REF: See Workcard	MOS HRS/MSC AFL	O/C				31-JAN-2008 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 81391 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	N:149 N:6214:55 N:5654			09-JUN-2020 6214:55 5654		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11501227 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				09-JUN-2020 6214:55 5654		
24C015	EMERGENCY POWER SUPPLY,PS-855B								
	9858314953 81391 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
24C016	DC-DC POWER CONVERTER								
	9750215106 1280 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 25	EQUIPMENT/FURNISHINGS								
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 18	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654		
25-10/293	COPILOT SEAT CUSHION PN	MOS					31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 25-21-02	AFL					0		
25-10/293	PILOT SEAT CUSHION PN	MOS					31-JAN-2008		
25.080	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 25-21-02	AFL					0		
25-10/294	CREW SEAT BELTS 4095-1-021-2396	MOS	144				30-JUN-2018	30-JUN-2030	
25.030	A07JUL18-1	HRS/MSC					6157:45		
DISCARD	REF: AMM 25-10-02	AFL					5603		
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 3,17	MOS					PKG		
	REF: See Workcard	HRS/MSC AFL	A/R				09-JUN-2020 6214:55 5654		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 3,17	MOS					PKG		
	REF: See Workcard	HRS/MSC AFL	A/R				09-JUN-2020 6214:55 5654		
+ 25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 21	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/486	REPLACE BACKREST TUBES ON CREW SEATS WITH RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
25-20/295	PASSENGER SEAT BELTS 5-02-2T4718MNI SN-UNKNOWN DISCARD REF: GENERIC NO REF	MOS HRS/MSC AFL	144		N:0 N:0 N:0		30-NOV-2015 6157:45 5603	30-NOV-2027	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 3,17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 3,17 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 25-60/231 (s)	OPERATIONAL TEST ELT PKG 3 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
25-60/483	PERFORM PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 9851380853 2616806-0036 REF: AMM 25-63-10	MOS HRS/MSC AFL	A/R				31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY S1820516--99	MOS		N:0			09-OCT-2015	28-FEB-2022 M	
25.020	TM0000079330	HRS/MSC	DUE	N:0			3744:55		
DISCARD	REF: GENERIC NO REF	AFL		N:0			3392		
Expiry Date: 28-FEB-2022									
250005	REMOTE CONTROL PANEL 9851380817	MOS		N:0			31-JAN-2008		
25.070	2616809-0001	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER 9851380853	MOS		N:69			18-OCT-2013		
25.050	2616806-0036	HRS/MSC	O/C	N:2611:15			2611:15		
	REF: AMM 25-63-01	AFL		N:2343			2343		
250015	IPECO PILOT SEAT 959.30.01.143	MOS		N:89			11-JUN-2015		
25.040	50257	HRS/MSC	O/C	N:0					
	REF: AMM 25-10-05	AFL							
250020	IPECO CO-PILOT SEAT 959.30.01.144	MOS		N:89			11-JUN-2015		
25.040	50259	HRS/MSC	O/C	N:0					
	REF: AMM 25-10-05	AFL							
250021	NO. 1 PASSENGER SEAT 959.30.01.617	MOS					11-JUN-2015		
	35375	HRS/MSC	O/C						
	REF:	AFL							
250022	NO. 2 PASSENGER SEAT 959.30.01.618	MOS					11-JUN-2015		
	35376	HRS/MSC	O/C						
	REF:	AFL							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250023	NO. 3 PASSENGER SEAT 959.30.01.633 35377 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250024	NO. 4 PASSENGER SEAT 959.30.01.634 33379 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250025	NO. 5 PASSENGER SEAT 959.30.01.641 35378 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
250026	NO. 6 PASSENGER SEAT 959.30.01.642 35380 REF:	MOS HRS/MSC AFL	O/C					11-JUN-2015	
251010	PILOT SEAT BACKREST TUBES PN 25.060 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0				31-JAN-2008 0 0	
251015	COPILOT SEAT BACKREST TUBES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0				31-JAN-2008 0 0	
25C017	PAX SEAT LH AFSS,403150-1 9593001617 35375 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	
25C018	PAX SEAT RH AFSS,403150-2 9593001618 35376 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				31-JAN-2008 0 0	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C019	PAX SEAT LH FFSS,403150-3-B 9593001641 35378 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C020	PAX SEAT RH FFSS,403150-4-B 9593001642 35380 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C021	PAX SEAT LH FFSS,403150-3-A 9593001635 1186 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C022	PAX SEAT RH FFSS,403150-4-BC 9593001644 1198 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C024	PAX SEAT LH FFSS,403150-3 9593001633 35377 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C025	PAX SEAT RH FFSS,403150-4 9593001634 35379 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25C026	ENTERTAINMENT SYSTEM INSTL 9501000440 2704003 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
25JFL02	PERFORMED FIRST AID KIT INSPECTION REF:	MOS HRS/MSC AFL	12	+1m/-1m		-44	09-JUN-2020 6214:55 5654	26-APR-2021	26-MAY-2021



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 26	FIRE PROTECTION								
26-20/2	COCKPIT FIRE EXTINGUISHER								
	BA51015GR-3	MOS	120	N:4			14-FEB-2013	05-DEC-2022 M	
26.010	083998	HRS/MSC		N:0			2186:05		
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			1951		
		ACH							
+ 26-20/24	CONTENTS CHECK CABIN FIRE EXTINGUISHER								
	PN	MOS					31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
26-20/24	CONTENTS CHECK COCKPIT FIRE EXTINGUISHER								
	BA51015GR-3	MOS	12	+1m/-1m			30-MAR-2020	30-MAR-2021	30-APR-2021
26.010	083998	HRS/MSC							
	REF: GENERIC NO REF	AFL							
26-20/515	CONTENTS CHECK CABIN FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224)								
	PN	MOS					31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
26-20/515	CONTENTS CHECK COCKPIT FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224)								
	BA51015GR-3	MOS					31-JAN-2008		
	083998	HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
26-20/516	LIFE LIMIT CABIN FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224)								
	PN	MOS					31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
26-20/516	LIFE LIMIT COCKPIT FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224)								
	BA51015GR-3	MOS					31-JAN-2008		
	083998	HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
260005	FIRE/OVERHEAT DETECTOR								
26.020	9751210012 207694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
CHAPTER 27 FLIGHT CONTROLS									
+ 27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL						PKG		
	PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654		
27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	32500 42000				31-JAN-2008 0 0	32500 42000	
+ 27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES								
27.010	REF: AMM 27-00-00	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294	26-APR-2024 10588:15	26-OCT-2024 11068:15
+ 27-10/139 (s)	EXAMINE AILERON LH AND RH AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC TEMPORARY (MAT. NO. P10-001)						PKG		
	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
+ 27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS						PKG		
	PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG		
	PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/236 (s)	EXAMINE AILERON CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: See Workcard	AFL					5654		
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
		HRS/MSC	2400	+10%/-10%			5788:15		
	REF: See Workcard	AFL					5294		
27-10/394	EXAMINE - AILERON CONTROL SYSTEM								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-10-00	AFL	42000				0		42000
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-10-09	AFL	42000				0		42000
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/444	AILERON FLIGHT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-10-01	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-10-02	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARING	MOS	12	+10%/-10%			PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			09-JUN-2020		
	REF: AMM 27-10-00	AFL					6214:55		
							5654		
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999	MOS	24	+10%/-10%			PKG		
	PKG 22	HRS/MSC	2400	+10%/-10%			26-APR-2019		
	REF: See Workcard	AFL					5788:15		
							5294		
+ 27-20/140 (s)	INSPECT/CHECK RUDDER	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC	300	+10%/-10%			09-JUN-2020		
	REF: AMM 55-40-00	AFL					6214:55		
							5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 27-20/241 (s)	EXAMINE RUDDER CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-20/242	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH	MOS	N/A				31-JAN-2008		
	REF: AMM 20-31-00	HRS/MSC AFL					0 0		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/374	EXAMINE - RUDDER CONTROL SYSTEM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					31-JAN-2008		
	REF: AMM 27-20-00	HRS/MSC	A/R				0		
		AFL					0		
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-20-01	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-20-02	PN		N:0			0		20000
		SN-UNKNOWN	20000	N:0			0		20000
		AFL	27000	N:0			0		27000
+ 27-30/141 (s)	EXAMINE ELEVATORS	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC	300	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	AFL					6214:55		
							5654		
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS	MOS	12	+10%/-10%			PKG		
	PKG 21	HRS/MSC	1200	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	AFL					6214:55		
							5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 27-30/249 (s)	EXAMINE ELEVATOR CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
27-30/334	CHECK ELEVATOR CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR)	MOS					26-APR-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R				5788:15 5294		
27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: AMM 27-30-02	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
+ 27-30/450	STICK PUSHER CABLES	MOS					31-JAN-2008		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			0 0 0	20000 27000	
27-30/514 (s)	EXAMINE ELEVATOR STOPS	MOS	12				PKG 31-JAN-2008		
	PKG 21	HRS/MSC AFL	1200				0 0		
	REF: AMM 55-20-01								
27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%			09-JUN-2020	26-APR-2021	01-JUN-2021
27.021		HRS/MSC AFL	3000		-44		6214:55 5654	9214:55	
AIRWORTHINESS	REF: AMM 27-40-00								
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	PKG 3	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
	REF: AMM 27-40-00								



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40/252 (s)	INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 27-40-01	HRS/MSC AFL	1200	+10%/-10%					
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR 129-1-1100-02 238	MOS	84				10-SEP-2018 5485:40 5022	10-SEP-2025 8885:40	
OVERHAUL	REF: AMM 27-40-01	HRS/MSC AFL	3400						
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 18	MOS					PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%					
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%					
27-40/3	PITCH TRIM ACTUATOR 129-1-1100-02 238	MOS			O:0		10-SEP-2018 5485:40 5022	25485:40 32022	
27.011 AIRWORTHINESS	REF: AMM 27-40-01	HRS/MSC AFL	20000 27000		N:7781:59 O:0 N:6827 O:0				
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS PN	MOS			N:0		31-JAN-2008 0 0	10000	
27.036 LIFE LIMIT	REF: AMM 27-40-02	HRS/MSC AFL	10000		N:0				
27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION PKG 3,17	MOS					PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R						
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT 9787320003	MOS					31-JAN-2008		
	670	HRS/MSC	10000	+10%/-10%			0	10000	11000
OVERHAUL	REF:	AFL	13500	+500/-500			0	13500	14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					14-MAR-2018		
27.040	0981	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					14-MAR-2018		
27.040	0994	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					14-MAR-2018		
27.050	0988	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309	MOS					14-MAR-2018		
27.050	1177	HRS/MSC	5000	+10%/-10%			5176:55	10176:55	10676:55
OVERHAUL	REF: AMM 27-50-03	AFL	7000	+500/-500			4778	11778	12278



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			31-JAN-2008		
27.060	S6100	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			31-JAN-2008		
27.060	S6130	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			31-JAN-2008		
27.070	S6106	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			31-JAN-2008		
27.070	S6124	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: See Workcard	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/386	EXAMINE - FLAP MECHANISM								
		MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS		O:0			14-MAR-2018		
27.040	978.73.20.309	HRS/MSC	20000	N:4972:35 O:0			5176:55		25176:55
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6422 O:0			4778		31778
27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS		O:0			14-MAR-2018		
27.040	978.73.20.309	HRS/MSC	20000	N:4971:35 O:0			5176:55		25176:55
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6422 O:0			4778		31778
27-50/4	RIGHT INBOARD FLAP ACTUATOR	MOS		O:0			14-MAR-2018		
27.050	978.73.20.309	HRS/MSC	20000	N:4971:35 O:0			5176:55		25176:55
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6422 O:0			4778		31778



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		O:0			14-MAR-2018		
27.050	1177	HRS/MSC	20000	N:9666:50 O:0			5176:55	25176:55	
AIRWORTHINESS	REF: AMM 27-50-03	AFL	27000	N:6720 O:0			4778	31778	
27-50/414	LEFT HAND FLAP								
	5575012003	MOS		N:0			31-JAN-2008		
57.060	782	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			31-JAN-2008		
57.060	779	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
+ 27-50/437 (s)	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: AMM 12-20-07	AFL					5654		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0	27000	
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 3,17	MOS					09-JUN-2020		
		HRS/MSC	A/R				6214:55		
	REF: GENERIC NO REF	AFL					5654		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
	9450202205	MOS					31-JAN-2008		
27.060	S6100	HRS/MSC	O/C				0		
	REF: AMM 27-50-00	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.060	9450202206 S6130 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-JAN-2008 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	9450202205 S6106 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-JAN-2008 0 0		
27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE								
27.070	9450202206 S6124 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C				31-JAN-2008 0 0		
+ 27-50/73	LUBRICATE LEFT INBOARD FLAP ACTUATOR (WHITE COLORED)								
27.040	978.73.20.309 0981 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED)								
27.040	978.73.20.309 0994 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED)								
27.050	978.73.20.309 0988 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED)								
27.050	978.73.20.309 1177 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.309 PKG 3 0981 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 6514:55	15-JUL-2021 6544:55



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 0994 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 6514:55	15-JUL-2021 6544:55
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 0988 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 6514:55	15-JUL-2021 6544:55
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 PKG 3 1177 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 6514:55	15-JUL-2021 6544:55
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0981 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2021 8188:15 8494	26-MAY-2021 8428:15 8814
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0994 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2021 8188:15 8494	26-MAY-2021 8428:15 8814
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 0988 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			26-APR-2019 5788:15 5294	26-APR-2021 8188:15 8494	08-JUL-2021 8428:15 8814
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.309 1177 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-43		26-APR-2019 5788:15 5294	14-MAR-2021 8188:15 8494	26-MAY-2021 8428:15 8814
27-50/77	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013) 27.080 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270003	HORIZONTAL TAIL ASSY 5551012037 796 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270015	ELEVATOR LH ASSY 555.20.12.039 586 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C				29-MAY-2015 3448:25 3156		
270023	ELEVATOR RH ASSY 555.20.12.040 586 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C				29-MAY-2015 3448:25 3156		
270025 27.090	RUDDER TRIM LINEAR ACTUATOR 978.73.18.132 0904 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C				26-NOV-2014 3172:35 2878		
270033	RUDDER ASSY 5554012038 778 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270035 27.130	FLAP CONTROL AND WARNING (FCWU) UNIT 9787320017 121893 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270045 27.100	LH INBOARD TRANSMITTER 9787320021 079022DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270050 27.120	LH ROTATION TRANSMITTER 9787320602 1063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 079007DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 079020DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1067 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270090	AILERON TRIM LINEAR ACTUATOR								
27.140	9787318132 1569 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 079021DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
27JFL01	EXCHANGE RELAYS K021 & K022								
DISCARD	REF:	MOS HRS/MSC AFL	24	+1m/-1m			26-APR-2019 5788:15 5294	26-APR-2021	26-MAY-2021
CHAPTER 28	FUEL								
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE	MOS					26-APR-2019		
28.029		HRS/MSC	2400	+10%/-10%	78:10		5788:15 5294	8266:25	8506:25
	REF: AMM 28-10-01	AFL							
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 28-20-07	HRS/MSC AFL	300	+10%/-10%					
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%					
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N) PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019 5788:15 5294		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%					



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/32	ACCESSORY GEARBOX FUEL PUMP								
28.010	968.84.51.108	MOS		O:0			07-AUG-2015		
OVERHAUL	B4919	HRS/MSC	3500	O:0	-94:55		3594:55	7000	
	REF: AMM 28-20-03	AFL		O:0			3282		
+ 28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM								
28.020		MOS	48	+10%/-10%			26-APR-2019	26-APR-2023	19-SEP-2023
		HRS/MSC	1200	+10%/-10%	78:10		5788:15	7066:25	7186:25
	REF: See Workcard	AFL					5294		
280005	LOW PRESSURE FUEL PUMP								
28.120	9688451108	MOS		N:0			31-JAN-2008		
	B5010	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
280010	FUEL FLOW TRANSMITTER								
28.130	9753512602	MOS		N:0			31-JAN-2008		
	2899	HRS/MSC	O/C	N:0			0		
	REF: AMM 73-30-01	AFL		N:0			0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			31-JAN-2008		
	2061	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-08	AFL		N:0			0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			31-JAN-2008		
	2062	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-08	AFL		N:0			0		
280025	FUEL FILTER ASSY								
28.025	9683521001	MOS		N:0			31-JAN-2008		
	2007FFT1777	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-01	AFL		N:0			0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102	MOS					14-APR-2008		
	1566	HRS/MSC	O/C				68:30		
	REF: AMM 28-20-02	AFL					42		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3823 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4136 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 403 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 960 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 1585 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 1583 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.405 B7634 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-JUL-2012 1874:35 1635		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	9688471104 B3821 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	9688471105 B4135 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
280080	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 862 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280085	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 1629 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280090	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 1573 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280095	FUEL QUANTITY,OUTER SENSOR								
28.060	975.37.31.231 299 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUL-2016 4177:05 3846		
280100	RIGHT WING FUEL,BOOSTER PUMP								
28.050	9688411405 B6712 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
28C031	VALVE,CHECK								
	9630423105 1956 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
28C032	VALVE,CHECK								
	9630423105 1972 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 29	HYDRAULIC POWER								
+ 29-10/151 (s)	RETURN LINE FILTER DIIERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 20	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	600	+10%/-10%				6214:55	
	REF: AMM 29-10-04	AFL						5654	
+ 29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	300	+10%/-10%				6214:55	
	REF: See Workcard	AFL						5654	
+ 29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.						PKG		
	PKG 3	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	300	+10%/-10%				6214:55	
	REF: See Workcard	AFL						5654	
+ 29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 21	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	1200	+10%/-10%				6214:55	
	REF: GENERIC NO REF	AFL						5654	
+ 29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291)						PKG		
	PKG 21	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	1200	+10%/-10%				6214:55	
	REF: AMM 29-10-02	AFL						5654	
+ 29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL						PKG		
	PKG 21	MOS	12	+10%/-10%				09-JUN-2020	
		HRS/MSC	1200	+10%/-10%				6214:55	
	REF: GENERIC NO REF	AFL						5654	
29-10/418	NITROGEN ACCUMULATOR								
	9603001291	MOS						31-JAN-2008	
29.020	822	HRS/MSC	25000					0	25000
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000					0	30000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS						31-JAN-2008	
	REF: AMM 29-10-02	HRS/MSC AFL	N/A					0 0	
290005	LANDING GEAR STEER SELECTOR VALVE	MOS						25-FEB-2014	
29.040	960.30.01.271 0471AB REF: GENERIC NO REF	HRS/MSC AFL	O/C	O:0 O:0 O:0				2717:45 2508	
290015	PRESSURE GAGE SWITCH	MOS						05-JUN-2014	
29.050	973.81.14.307 0726 REF: GENERIC NO REF	HRS/MSC AFL	O/C					2866:25 2636	
290025	SERVICE SELECTOR VALVE	MOS						31-JAN-2008	
29.070	9603001261 G0711047A REF: AMM 29-10-05	HRS/MSC AFL	O/C	N:0 N:0 N:0				0 0 0	
290030	PRESSURE GAUGE	MOS						31-JAN-2008	
29.080	9656188101 07-0821145 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0 N:0				0 0 0	
290035	(K 601) RELAY	MOS						31-JAN-2008	
29.090	9740926112 R555 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0 N:0				0 0 0	
290040	HAND PUMP	MOS						31-JAN-2008	
29.030	9688582111 786 REF: AMM 29-20-01	HRS/MSC AFL	O/C	N:0 N:0 N:0				0 0 0	
290050	PRESSURE NITROGEN SWITCH	MOS						10-SEP-2018	
29.100	9738114306 1877 REF: AMM 29-10-02	HRS/MSC AFL	O/C	N:0 N:0 N:0				5485:40 5022	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0730769 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS - 960.30.02.101 201208 REF:	MOS HRS/MSC AFL	60	+6m/-6m O:0			27-APR-2017 4592:35 4216	27-APR-2022	27-OCT-2022
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS PKG 3 REF: AMM 30-10-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999 PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 21 REF: AMM 30-10-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1 30.010 REF: GENERIC NO REF	MOS HRS/MSC AFL	6	+10%/-10%	-10		30-MAR-2020 6212:10 5650	20-SEP-2020	08-OCT-2020
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: See Workcard	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 22	MOS	24	+10%/-10%			PKG 26-APR-2019		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: AMM 30-60-00	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: See Workcard	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
300005	PROP DE-ICE TIMER/ CONTROLLER 968.29.13.227	MOS					18-FEB-2016		
30.140	U0405	HRS/MSC	O/C				3885:20		
	REF: AMM 30-60-01	AFL					3575		
300010	LPMI LINEAR ACTUATOR 9787315302	MOS					31-JAN-2008		
30.150	B68297	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
300015	REGULATOR-RELIEVER ASSY 9598901012	MOS					31-JAN-2008		
30.160	N073177	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300020	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N072569 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300025	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N072566 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300030	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N072541 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N072543 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N072542 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 8692 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			06-JUL-2017 4733:55 4347		
300050	WATER SEPARATOR								
30.060	9598901010 N074115 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.043 UA099 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121784 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 121785 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 3973 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	9738114312 7932 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:10 N:0 N:0			13-JUL-2016 4177:05 3846		
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 4016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	9738114312 4014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.890.1041 NET4380 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-JUN-2020 6214:55 5654		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.027 NCR8430 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-AUG-2015 3594:55 3282		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NEW6140 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.034 NEL1990 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-SEP-2018 5485:40 5022		
300115	LH INBD-WING DE-ICER BOOT								
30.040	P27-7D5221-21 NEV2060 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NEB3380 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
30JFL02	PERFORM AIRFOIL DE-ICERS BOOTS BLEED SYSTEM AND LEAK TEST (REF. 12-A-30-10-00-00A-903A-A)"								
	REF:	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654	6514:55	6544:55
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
31-50/34	CAWS & CACU CLOCK BATTERY								
31.010	9728132050 N/A REF: AMM 31-50-03	MOS HRS/MSC AFL	24	+10%/-10%	N:0 N:0 N:0		09-JUN-2020 6214:55 5654	09-JUN-2022	21-AUG-2022
DISCARD									
310020	FLAP POSITION INDICATOR								
31.090	9754416203 60200 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310025-1	AM-250 BARO ALTIMETER, ADC 9859911207 07080829D REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
310035 31.050	CAWS COMPUTER 9728132030 N/A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:149 N:6214:55 N:5654			09-JUN-2020 6214:55 5654		
310040 31.060	CAWS DISPLAY 9728132031 283 REF: AMM 31-50-02	MOS HRS/MSC AFL	O/C				19-APR-2008 80:18 50		
310050 31.040	DIGITAL CLOCK 9996111213 1056675 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-APR-2011 1202:25 1002		
31C035	COAX SWITCH 9859911371 10396 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
31C036	COAX SWITCH 9859911371 10390 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
CHAPTER 32	LANDING GEAR								
+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 20 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
32-10/264	REMOVE MAIN LANDING GEAR LEFT AND RIGHT AXLE BOLT (PRE SB 32-006) AND EXAMINE. REPLACE IF DAMAGED. INSTALL A SERVICEABLE BOLT.	MOS					31-JAN-2008		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000				0 0	25000 30000	
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK	MOS					31-JAN-2008		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK ABSORBER TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS.	MOS	12	+10%/-10%			09-JUN-2020	09-JUN-2021	15-JUL-2021
	REF: AMM 32-10-00	HRS/MSC					6214:55		
		AFL					5654		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2016	11-MAY-2022	
	REF: AMM 32-10-00	HRS/MSC					4028:50		
		AFL					3721		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2016	11-MAY-2022	
	REF: AMM 32-10-00	HRS/MSC					4028:50		
		AFL					3721		
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%			09-JUN-2020	26-APR-2021	01-JUN-2021
32.030	REF: AMM 12-20-06	HRS/MSC	T/C				6214:55		
		AFL					5654		
+ 32-10/81	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES	MOS	12	+1m/-1m			09-JUN-2020	26-APR-2021	26-MAY-2021
32.010	REF: AMM 32-10-00	HRS/MSC	2400	+10%/-10%			6214:55	8614:55	8854:55
		AFL					5654		
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 32-20-00	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 20 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 32-20/266 (s)	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				15-APR-2013 2295:10 2059		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/403	NOSE LANDING GEAR								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
OVERHAUL	REF: GENERIC NO REF	AFL	30000	N:0			0	30000	
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
	PN	MOS		N:0			31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	N:0			0	30000	
32-20/5	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
	532.20.12.296	MOS		N:0			15-APR-2013		
32.020	SN-UNKNOWN	HRS/MSC	N/A	N:0			2295:10		
	REF: AMM 32-20-05	AFL		N:0			2059		
+ 32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 32-30-00	HRS/MSC	1200	+10%/-10%			6214:55		
		AFL					5654		
32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
	9603001105	MOS		N:0			31-JAN-2008		
32.040	1654H	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:0			0	30000	
32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
	9603001105	MOS		N:0			31-JAN-2008		
32.040	1670H	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:0			0	30000	
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				17-FEB-2016	17-FEB-2022	
	REF: AMM 32-10-00	HRS/MSC					3884:45		
		AFL					3574		
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				17-FEB-2016	17-FEB-2022	
	REF: AMM 32-10-00	HRS/MSC					3884:45		
		AFL					3574		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	600	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: AMM 12-10-04	AFL					5654		
+ 32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	600	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: AMM 12-10-04	AFL					5654		
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: AMM 12-10-02	AFL					5654		
32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
	REF: AMM 32-50-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	9594751131 5135 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751131 5146 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320015	PARK BRAKE VALVE								
32.140	9594751121 2535 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320020	NOSE WHEEL								
32.150	3-1501 0943 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				03-MAY-2018 5230:20 4832		
320021	NOSE LANDING GEAR TIRE								
32.155	021-327-0 5268S00078 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:32			03-MAY-2018 5230:20 4832		
320022	LEFT MAIN LANDING GEAR WHEEL								
32.160	3-1543-1 1601 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			26-APR-2019 5788:15 5294		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 8079S00312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
320024	RIGHT MAIN LANDING GEAR WHEEL								
32.165	TRACKED ITEM 3-1543-1 2067 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2020 6148:15 5593		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320025	SHIMMY DAMPER ASSY 532.20.12.215 VLG951 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:106:54 R:0 N:158 R:0				02-JUL-2019 5868:45 5355	
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 9060S00289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				15-JAN-2020 6148:15 5593	
320030	COPILOT LH BRAKE MASTER CYLINDER 9594751131 5122 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
320035	COPILOT RH BRAKE MASTER CYLINDER 9594751131 5125 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
320040	NOSE FOLDING STRUT SPRING PACK ASSY 5322012249 VLG-332 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
320045	NOSE LANDING GEAR STRUT ASSY 5322012040 SI-0011 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
320050	LEFT SHOCK ABSORBER ASSY 5321012211 SI-0055 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
320055	RIGHT SHOCK ABSORBER ASSY 5321012211 SI-0056 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320074	NOSE LANDING GEAR ACTUATOR								
29.060	9603001111 869A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
320075	LH BRAKE ASSY								
32.050	2-1674-1 0794 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-2018 5078:35 4700		
320080	RH BRAKE ASSY								
32.050	2-1674-1 0895 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2020 6148:15 5593		

CHAPTER 33		LIGHTS							
+ 33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING								PKG
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
	REF: See Workcard								
+ 33-41/178 (s)	EXAMINE LANDING LIGHTS								PKG
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
	REF: AMM 33-41-01								
+ 33-42/179 (s)	EXAMINE TAXI LIGHTS								PKG
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
	REF: AMM 33-42-01								
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS								PKG
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF								



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
330005	DIM UNIT 9750215205	MOS					31-JAN-2008		
33.080	121629	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-10-04	AFL		N:0			0		
330010	DE-ICE LIGHT ASSY 9728767111	MOS					31-JAN-2008		
33.010	1309918	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
330015	LEFT WING POWER SUPPLY, HIDL UNIT 9728769413	MOS					31-JAN-2008		
33.020	1295763	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-40-11	AFL		N:0			0		
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 9728769413	MOS					31-JAN-2008		
33.020	1295766	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-40-11	AFL		N:0			0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787331	MOS					31-JAN-2008		
33.040	17852	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-46-01	AFL		N:0			0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787332	MOS					31-JAN-2008		
33.040	18051	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-46-01	AFL		N:0			0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330035	LH WING POWER SUPPLY UNIT 972.87.87.264 28584 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C					03-DEC-2014 3185:10 2887	
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322 31091 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C					03-DEC-2014 3185:10 2887	
330045	RH WING POWER SUPPLY UNIT 972.87.87.164 41396 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				25-FEB-2014 2717:45 2508	
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY 972.87.87.322 28046017 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				14-APR-2015 3359 3086	
330055	NAVIGATION (FC), LED GREEN LIGHT 9728787158 28723 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330060	NAVIGATION (FC), LED RED LIGHT 9728787157 28959 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JAN-2008 0 0	
330065	NAVIGATION (FC), LED WHITE LIGHT 03-9200-2001 25311 REF: AMM 33-43-04	MOS HRS/MSC AFL	O/C	N:325:40				14-FEB-2013 2186:05 1951	
330070	NOSE LANDING GEAR TAXI LIGHT,1X0005287-10 03-4400-1000 29798001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C					19-DEC-2016 4437 4074	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330075	L/H LANDING LIGHT, LANDING, 1X0005287-10 972.87.69.420 29585001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	O:0			13-JUL-2016 4177:05 3846		
330076	R/H LANDING LIGHT, LANDING, 1X0005287-10 972.87.69.420 28983020 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 5690 5210		
33JFL01	OPERATIONAL TEST INTERIOR LIGHTING (12-A-33-00-00-00A-903A-A) REF:	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654	6514:55	6544:55
CHAPTER 34 NAVIGATION									
+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			PKG 26-APR-2019 5788:15 5294		
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 21	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			09-JUN-2020 6214:55 5654		
34-11/82	LEAK CHECK STATIC SYSTEM	MOS	24	+10%/-10%					
34.010	REF: See Workcard	HRS/MSC AFL			-87		09-JUN-2020 6214:55 5654	14-MAR-2022	26-MAY-2022
34-14/83	CALIBRATION CHECK ALTIMETER	MOS	24	+1m/-1m					
34.020	REF: See Workcard	HRS/MSC AFL	-		-61		09-JUN-2020 6214:55 5654	09-APR-2022	09-MAY-2022
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS	MOS	24	+1m/-1m					
34.030	REF: AMM 34-21-00	HRS/MSC AFL	-		-87		09-JUN-2020 6214:55 5654	14-MAR-2022	14-APR-2022
34-25/85	CHECK SWING ATTITUDE HEADING REFERENCE SYSTEM (AHRS)	MOS	24	+10%/-10%					
34.040	REF: AMM 34-25-00	HRS/MSC AFL			-87		09-JUN-2020 6214:55 5654	14-MAR-2022	26-MAY-2022
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)	MOS	24	+1m/-1m					
34.050	REF: See Workcard	HRS/MSC AFL			-87		09-JUN-2020 6214:55 5654	14-MAR-2022	14-APR-2022
340005	PILOT ALTIMETER	MOS							
31.020	9859911207 07080832D REF: GENERIC NO REF	HRS/MSC AFL	O/C				31-JAN-2008 0 0		
340006	COPILOT ALTIMETER	MOS							
	70256N02D02 07080829D REF: AMM 34-14-12	HRS/MSC AFL	O/C				02-MAR-2010 796:25 620		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340009	NO. 1 DME/IFF ANTENNA								
34.080	9848110240 261-75728 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340010	PILOT VERTICAL SPEED INDICATOR								
31.070	9651615101 319809 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340015	PILOT ATTITUDE INDICATOR								
31.080	504.00.35.922 25306 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAR-2013 2208 1977		
340020	MARKER ANTENNA								
34.100	9848110260 101-6503 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340025	EFIS 1 SG465 SYMBOL GENERATOR								
34.300	975.96.32.402 3132 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-FEB-2014 2717:45 2508		
340026	STAND-BY ALTIMETER								
31.020	5934PAD-3A.260 442569 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JAN-2020 6148:15 5593		
340030	COPILOT VERTICAL SPEED INDICATOR								
31.070	9651615101 319813 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340034	EFIS 1 CONTROL,CP467 PANEL								
34.230	071-01439-3100 3265 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C				06-NOV-2012 2050:45 1779		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY 066-03137-3100 3533 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C				06-AUG-2013 2484:35 2238		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY 066-03137-3100 3349 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-FEB-2014 2717:45 2508		
340044	TRIM TRIPLE INDICATOR 975.44.16.204 00590 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2015 3594:55 3282		
340055	PILOT AIRSPEED INDICATOR 9651213338 1045354 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340059	WITH HARM FILTER,KN63 DME 066-10701-01 28623 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-JAN-2020 6164:15 5609		
340060	COPILOT AIRSPEED INDICATOR 9651213339 1044443 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340065	WX-RADAR RT UNIT 071-01519-0101 10357 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-MAR-2015 3299:20 2998		
340070	RADAR CONTROL PANEL 9859911518 3104 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 5601 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340080	NO. 2 TRANSPONDER								
34.080	9848110240 261-75729 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 A85740 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	9759632482 13051 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340100	FRONT KA92 GPS ANTENNA								
34.090	071-01553-0200 06521 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C				17-MAR-2016 3949:55 3624		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 7324 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	9859911823 10266 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	124210-2022-001 1395 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			27-APR-2017 4592:35 4216		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	9859911302 57283 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			15-MAY-2008		
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	9859911771 12127 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340130	AIR DATA COMPUTER								
34.400	9859203111 2922 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340135	MAGNETIC,STANDBY COMPASS								
34.130	9999880103 AT-1283 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2012 1838:25 1611		
340140	4206-100-V2 RADOME								
34.420	9857900003 848 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 5053 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41040 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41052 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 17719 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 17701 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340180	NO. 2 CAL PROM AHRS,LCR-92 UNIT								
34.390	9859911823 10266 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-00 69511 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JUN-2018 5340 4911		
340195	MULTI FUNCTION DISPLAY								
34.190	9859911863 8923 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	9859003045 6182 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	9859003044 5413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	9859003046 5712 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	066-01175-2101 2578 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C				04-SEP-2015 3675:40 3343		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 7325 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1561 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C				11-MAR-2020 6208:25 5647		
340240	NO. 1 FLUX,KMT112 VALVE								
34.350	9859911064 75271 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE								
34.250	9751120111 2495 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340255	AOA SENSOR LH UNIT								
34.330	9754421423 875 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
340260	NO. 2 FLUX,KMT112 VALVE								
34.350	9859911064 54939 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C				09-JUL-2015 3552:05 3248		
340280	LEFT PITOT TUBE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340285	RIGHT PITOT TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
341005	LH AOA PLATE TEMP CONTROLLER 9754421417 U1745 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
341010	RH AOA PLATE TEMP CONTROLLER 9754421417 U1747 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
345015	HORIZON,ARTIFICIAL 504.0111.930 504011193025177 REF:	MOS HRS/MSC AFL	A/R	O:0 O:0 O:0			17-NOV-2015 3796:25 3492		
34C039	RADAR ALTIMETER,KRA405B MOD 13 9859911550 6893 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C040	GYRO,YAW RATE,KRG332 9859203151 11105 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C041	CONFIG.MODULE,071-00112-0200 9859911884 13835 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C043	INDICATOR,PICT NAV,KI525A 9859911062 B97078 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C044	GYRO,DIRECTIONAL,KG102A 060-15-00 53392 REF:	MOS HRS/MSC AFL	A/R				09-AUG-2017 4820:20 4415		
34C045	SLAVING,ACCESSORY,VERT,KA51B 9859911070 39683 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C046	INDICATOR VR/LC/GS,KI206 9859911303 71194 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C047	INDICATOR RMI,KI229 9859911331 13197 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
34C048	INDICATOR,DME,KDI574 066-1069-04 84317 REF:	MOS HRS/MSC AFL	A/R	O:0 O:0 O:0			25-FEB-2014 2717:45 2508		
34C049	ATC TRANSPONDER GTX330D-BLACK 011-00455-10 84206780 REF:	MOS HRS/MSC AFL	A/R	O:3 O:6:30 O:7			09-JUN-2020 6214:55 5654		
34C050	ATC TRANSPONDER GTX330D-BLACK 011-00455-10 84206959 REF:	MOS HRS/MSC AFL	A/R				09-JUN-2020 6214:55 5654		
34C051	ANTENNA,DME/IFF 9848110240 261-77130 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C052	GPS ANTENNA,CI 420-220 013-00235-00 190685 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			09-JUN-2020 6214:55 5654		
34C053	GPS ANTENNA,CI 420-220 013-00235-00 188239 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			14-JUL-2020 6278:45 5701		
34C054	STANDBY HORIZON 5040035922 25528 REF:	MOS HRS/MSC AFL	O/C				08-APR-2009 479:10 360		
34C055	OPERATIONAL CHECK STANDBY HORIZON 5040035922 25528 REF:	MOS HRS/MSC AFL	N/R				08-APR-2009 479:10 360		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m		-31	25-FEB-2019 5690 5210	25-JAN-2021	25-FEB-2021
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM) REF:	MOS HRS/MSC AFL	12				09-JUN-2020 6214:55 5654	09-JUN-2021	
34JFL04	TEST OF PROBE AND PITOT STATIC PORT (INCULDING ALTIMETER,AIRSPEED INDICATOR, VERTICAL SPEED INDICATOR AND STANDBY INSTRUMENTS TO VERIFY ACCURACY) REF:	MOS HRS/MSC AFL	24					14-MAR-2022 M	

CHAPTER 35 OXYGEN



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF								
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 18	MOS HRS/MSC AFL	300	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF								
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF								
+ 35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 35-00-00								
35-10/6	OXYGEN BOTTLE 895-06077 ALT281-47521	MOS HRS/MSC AFL	180		O:0 O:0 O:0		18-MAY-2020 6214:55 5654	18-MAY-2035	
	35.010 AIRWORTHINESS								
35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE 895-06077 ALT281-47521	MOS HRS/MSC AFL	60				30-APR-2020	30-APR-2025	
	35.010 REF: GENERIC NO REF								
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS HRS/MSC AFL	36	+10%/-10%		-43	09-JUN-2020 6214:55 5654	27-APR-2023	14-AUG-2023
	35.010 REF: AMM 35-20-00								
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY 9571201210 SE17435	MOS HRS/MSC AFL	O/C				25-FEB-2014 2717:45 2508		
	35.040 REF: GENERIC NO REF								



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210 B133905 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2019 5788:15 5294		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	9738114401 796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
350035	3-POSITION CONTROL VALVE								
35.030	9633211101 2695 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
350040	ALTITUDE SENSING SWITCH								
35.020	9738152102 948 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
35C054	TRANSDUCER,OXYGEN PRESS								
	9571201184 7291-3-66 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
35C055	OXYGEN GAGE ASSY.								
	535.12.12.085 60189 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			13-NOV-2012 2066:45 1794		
CHAPTER 52	DOORS								
+ 52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC 600		+10%/-10%					
		AFL							
+ 52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC 600		+10%/-10%					
		AFL							
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 20	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC 600		+10%/-10%					
		AFL							
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: GENERIC NO REF	HRS/MSC 1200		+10%/-10%					
		AFL							
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS					31-JAN-2008 0		
AIRWORTHINESS	REF: AMM 52-10-00	HRS/MSC 32500							32500
		AFL 42000					0		42000
52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE	MOS					31-JAN-2008 0		
	REF: AMM 52-00-01	HRS/MSC 32500							32500
		AFL 42000					0		42000
52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN	MOS					31-JAN-2008 0		
	REF: AMM 52-10-01	HRS/MSC 25000							25000
		AFL 30000					0		30000
+ 52-10/472	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE	MOS					31-JAN-2008 0		
	REF: AMM 52-10-06	HRS/MSC N/A							
		AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
52.010		MOS	48	+10%/-10%		-113	09-JUN-2020	17-FEB-2024	11-JUL-2024
	REF: See Workcard	HRS/MSC	4000	+10%/-10%			6214:55	10214:55	10614:55
		AFL					5654		
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			6214:55		
		AFL					5654		
+ 52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			6214:55		
		AFL					5654		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
AIRWORTHINESS	REF: AMM 52-20-00	MOS					31-JAN-2008		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 52-30-00	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			6214:55		
		AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/274 (s)	EXAMINE CARGO DOOR PKG 21	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			09-JUN-2020 6214:55 5654		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 52-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE	MOS					31-JAN-2008		
	REF: AMM 52-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN	MOS					31-JAN-2008		
	REF: AMM 52-30-01	HRS/MSC AFL	25000 30000				0 0	25000 30000	
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS	MOS					31-JAN-2008		
52.020	PN	MOS			N:0		31-JAN-2008		
AIRWORTHINESS	REF: AMM 52-30-07	HRS/MSC AFL	13000 17000		N:0 N:0		0 0	13000 17000	
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
52.030	REF: See Workcard	HRS/MSC AFL	4000	+10%/-10%	-113		6214:55 5654	10214:55	10614:55
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM PKG 21	MOS	12	+10%/-10%			PKG		
	REF: AMM 52-70-00	HRS/MSC AFL	1200	+10%/-10%			09-JUN-2020 6214:55 5654		
520005	PASSENGER DOOR	MOS					31-JAN-2008		
52.050	REF: AMM 52-10-01	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512010 778 REF: AMM 52-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
520015	EMERGENGY 6 SERIE EXIT								
52.060	5520512009 778 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		

CHAPTER 53 FUSELAGE

+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		
+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			5788:15 5294		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					31-JAN-2008		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: AMM 53-20-02	AFL					5654		
53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-06	AFL	42000				0		42000
53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000				0		42000
53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-20-00	AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-30-00	AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE								
		MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-00-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					31-JAN-2008		
53.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
53.030		HRS/MSC	4000	+10%/-10%	-113		6214:55	10214:55	10614:55
	REF: GENERIC NO REF	AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-113	09-JUN-2020 6214:55 5654	17-FEB-2024 10214:55	11-JUL-2024 10614:55
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-113	09-JUN-2020 6214:55 5654	17-FEB-2024 10214:55	11-JUL-2024 10614:55
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-113	09-JUN-2020 6214:55 5654	17-FEB-2024 10214:55	11-JUL-2024 10614:55
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		-113	09-JUN-2020 6214:55 5654	17-FEB-2024 10214:55	11-JUL-2024 10614:55
530005	FUS ASPC12 10 SERIE A T-1/2 ASSY								
53.080	REF: GENERIC NO REF	5530512112 778 AFL			N:0 N:0 N:0		31-JAN-2008 0 0		
CHAPTER 55	STABILIZERS								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				31-JAN-2008 0 0	20000 27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 21	MOS	12	+10%/-10%			PKG 09-JUN-2020		
	REF: AMM 55-00-00	HRS/MSC AFL	1200	+10%/-10%			6214:55 5654		
55-10/415	HORIZONTAL STABILIZER PN	MOS					31-JAN-2008		
	SN-UNKNOWN	HRS/MSC	25000				0	25000	
LIFE LIMIT	REF: AMM 55-10-01	AFL	30000				0	30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%		-113	6214:55 5654	10214:55	10614:55
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%		-113	6214:55 5654	10214:55	10614:55
55-20/362	EXAMINE LEFT ELEVATOR	MOS					29-MAY-2015		
	REF: AMM 55-20-00	HRS/MSC AFL	32500			-4773: 20	3448:25	31175:05	
AIRWORTHINESS			42000			-4444	3156	40712	
+ 55-20/362	EXAMINE RIGHT ELEVATOR	MOS					31-JAN-2008		
	REF: AMM 55-20-00	HRS/MSC AFL	32500				0	32500	
AIRWORTHINESS			42000				0	42000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					29-MAY-2015		
		HRS/MSC	32500		-4773:		3448:25		31175:05
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000		20		3156		40712
					-4444				
55-20/368	EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES	MOS					29-MAY-2015		
		HRS/MSC	32500		-4773:		3448:25		31175:05
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000		20		3156		40712
					-4444				
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES	MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0		42000
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF:	AFL					5654		
+ 55-30/199	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.	MOS					26-APR-2019		
		HRS/MSC	N/A				5788:15		
	REF: GENERIC NO REF	AFL					5294		
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					31-JAN-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-30-00	AFL	42000				0		42000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-30-03	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/373	EXAMINE - RUDDER	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/410	EXAMINE RUDDER TRIM TAB	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 55-40-04	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55C056	FIN ASSY	MOS					31-JAN-2008		
	5553012040	HRS/MSC	A/R	N:0			0		
	778	AFL		N:0			0		
	REF:			N:0			0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 56	WINDOWS								
+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH PKG 3	MOS	12	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%					
+ 56-11/12	REPLACE COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS PN	MOS		N:0			31-JAN-2008 0		
56.020	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
AIRWORTHINESS	REF: AMM 56-20-01	AFL		N:0			0		
+ 56-11/13	REPLACE COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS PN	MOS		N:0			31-JAN-2008 0		
	SN-UNKNOWN	HRS/MSC	A/R	N:0			0		
	REF: See Workcard	AFL		N:0			0		
56-11/14	REPLACE LEFT HAND WINDSHEILD ASSEMBLY (INNER LAMINATION CRACKED) 9598110107	MOS					31-JAN-2008 0		
	06352H9967	HRS/MSC	A/R				0		
	REF: GENERIC NO REF	AFL					0		
56-11/14	REPLACE RIGHT HAND WINDSHEILD ASSEMBLY (INNER LAMINATION CRACKED) 9598110108	MOS					31-JAN-2008 0		
	06346H9579	HRS/MSC	A/R				0		
	REF: GENERIC NO REF	AFL					0		
56-11/15	- LEFT HAND WINDSHIELD ASSY, (LH) ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110107	MOS					31-JAN-2008 0		
	06352H9967	HRS/MSC	A/R				0		
	REF:	AFL					0		
56-11/15	- RIGHT HAND WINDSHIELD ASSY, (LH) ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110108	MOS					31-JAN-2008 0		
	06346H9579	HRS/MSC	A/R				0		
	REF:	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS								
		MOS	120	+6m/-6m		-42	14-MAR-2018	31-JAN-2028	31-JUL-2028
	REF: AMM 56-11-02	HRS/MSC	11000	+500/-500			5176:55	16176:55	16676:55
		AFL					4778		
56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS								
		MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
	REF: AMM 56-00-00	HRS/MSC	300	+10%/-10%			6214:55		
		AFL					5654		
560015	SIDE,LH WINDOW								
	9598110111	MOS					31-JAN-2008		
56.090	07118H4166	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		
560020	SIDE,RH WINDOW								
	9598110112	MOS					31-JAN-2008		
56.090	07156H8166	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		
560025	RH NO 1 CABIN WINDOW								
	5562012029	MOS					31-JAN-2008		
56.060	7367	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		
560030	RH NO 2 CABIN WINDOW								
	5562012029	MOS					31-JAN-2008		
56.060	7254	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		
560035	RH NO 3 CABIN WINDOW								
	5562012029	MOS					31-JAN-2008		
56.070	7371	HRS/MSC	O/C				0		
	REF: AMM 56-20-01	AFL					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 7372 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 7255 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 7311 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 7369 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 7316 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 7370 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412091 07270H1704 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010	9598110107 06352H9967 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
AIRWORTHINESS									



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
	9598110108	MOS		N:0			31-JAN-2008		
56.010	06346H9579	HRS/MSC	O/C	N:0			0		
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
		MOS					31-JAN-2008		
57.010		HRS/MSC	20000				0	20000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0	27000	
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					31-JAN-2008		
57.010		HRS/MSC	20000				0	20000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0	27000	
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 3	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	300	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 22	MOS	24	+10%/-10%			26-APR-2019		
		HRS/MSC	2400	+10%/-10%			5788:15		
	REF: GENERIC NO REF	AFL					5294		
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020		
		HRS/MSC	1200	+10%/-10%			6214:55		
	REF: GENERIC NO REF	AFL					5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					31-JAN-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/412	EXAMINE WING TIPS	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-33-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-01	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-01	HRS/MSC	25000				0		25000
		AFL	30000				0		30000



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
57-00/427	EDDY CURRENT INSPECTION WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					31-JAN-2008		
	REF:	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
57.020	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%	-113		6214:55	10214:55	10614:55
		AFL					5654		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%			09-JUN-2020	17-FEB-2024	11-JUL-2024
57.030	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%	-113		6214:55	10214:55	10614:55
		AFL					5654		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m			14-MAR-2018	31-JAN-2028	31-JUL-2028
57.040	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500	-42		5176:55	16176:55	16676:55
		AFL					4778		
57-60/393	EXAMINE LEFT WING AILERON	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 57-60/393	EXAMINE RIGHT WING AILERON	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/411	EXAMINE AILERON TRIM TAB	MOS					31-JAN-2008		
	REF: AMM 57-60-04	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
570010	AILERON RH 10A SERIE ASSY									
57.050	5570512016 2778 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0			
570015	WING RE 10A SERIE STRUCTURE									
57.070	5570512132 778 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0			
570025	AILERON LH 10A SERIE ASSY									
57.050	5570512015 2778 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0			
570035	WING LE 10A SERIE STRUCTURE									
57.070	5570512131 778 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0			
CHAPTER 61 PROPELLERS/PROPULSORS										
+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG			
	PKG 21	MOS	12	+10%/-10%			09-JUN-2020			
		HRS/MSC	1200	+10%/-10%			6214:55			
	REF: GENERIC NO REF	AFL					5654			
610580	PROPELLER GROUND IDLE OPERATING RESTRICTIONS									
		MOS								
		HRS/MSC	A/R							
	REF:	AFL								
61PR1	NO. 1 PROPELLER									
61.PR1	HC-E4A-3D/E10477K KX568 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C				25-MAY-2015 3448:25 3156			
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200										



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
612010	NO. 1 ENGINE - PROPELLER GOVERNOR 8210-137H 15424596 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500				11-APR-2016 3884:45 (7384:45) 7528:50 3159	7884:45
OVERHAUL									
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 210949C 15409228 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500				11-APR-2016 3884:45 (7384:45) 7528:50 3159	7884:45
OVERHAUL									
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX568 Part # HC-E4A-3D/E10477K									
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	72 4000/-					09-JUN-2020 5303:40	09-JUN-2026 (9303:40) 10214:55
OVERHAUL	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%				09-JUN-2020 5303:40	09-JUN-2021 (5603:40) 6514:55 09-JUL-2021 5633:40
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%				09-JUN-2020 5303:40	09-JUN-2021 (5603:40) 6514:55 09-JUL-2021 5633:40
	REF:								
+ 610070	NO. 1 PROPELLER - PRE-FLIGHT CHECKS	MOS HRS/MSC	A/R					30-APR-2008 0	
	REF:								
+ 610080	NO. 1 PROPELLER - OPERATIONAL CHECKS	MOS HRS/MSC	A/R					30-APR-2008 0	
	REF:								



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610510	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610520	NO. 1 PROPELLER - LIGHTNING STRIKE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610530	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610540	NO. 1 PROPELLER - FIRE/HEAT DAMAGE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610550	NO. 1 PROPELLER - SUDDEN STOPPAGE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610560	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							
+ 610570	NO. 1 PROPELLER - LONG TERM STORAGE	MOS HRS/MSC	A/R				30-APR-2008 0		
	UNSCHEDULED MAINTENANCE CHECK	REF:							



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE E10477SK K64314 REF: GENERIC NO REF	MOS HRS/MSC	O/C				02-JUN-2020		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE E10477SK K64315 REF: GENERIC NO REF	MOS HRS/MSC	O/C				02-JUN-2020		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE E10477SK K64312 REF: GENERIC NO REF	MOS HRS/MSC	O/C				02-JUN-2020		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE E10477SK K64313 REF: GENERIC NO REF	MOS HRS/MSC	O/C				02-JUN-2020		
CHAPTER 71 POWER PLANT									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH								
71.040	REF:	MOS HRS/MSC AFL	300	+10%/-10%			09-JUN-2020 6214:55 5654	6514:55	6544:55



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/106	CLEAN OIL PRESSURE TRANSDUCER ELECTRICAL CONNECTOR								
71.020	REF: AMM 71-00-03	MOS HRS/MSC AFL	A/R				31-JAN-2008 0 0		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 20 REF: AMM 71-00-03	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	571.20.12.036 793 REF: AMM 71-00-05	MOS HRS/MSC AFL	20000 27000		N:0 N:0 N:0		31-JAN-2008 0 0	20000 27000	
AIRWORTHINESS									
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS								
71.050	REF: AMM 71-00-04	MOS HRS/MSC AFL	11000				31-JAN-2008 0 0	11000	
AIRWORTHINESS									
71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 3,17 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				09-JUN-2020 6214:55 5654		
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			26-APR-2019 5788:15 5294		
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT PKG 3,17 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 09-JUN-2020 6214:55 5654		
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 26-APR-2019 5788:15 5294		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 9094 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500	+10%/-10%	N:2 N:0 N:0		11-MAY-2016 4028:50 3721	7528:50	7878:50
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 9089 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500	+10%/-10%	N:2 N:0 N:0		11-MAY-2016 4028:50 3721	7528:50	7878:50
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY 9448121409 9031 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500	+10%/-10%	N:2 N:0 N:0		11-MAY-2016 4028:50 3721	7528:50	7878:50
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 9083 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500	+10%/-10%	N:2 N:0 N:0		11-MAY-2016 4028:50 3721	7528:50	7878:50
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 9037 REF: AMM 71-00-01	MOS HRS/MSC AFL	3500	+10%/-10%	N:2 N:0 N:0		11-MAY-2016 4028:50 3721	7528:50	7878:50



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT	MOS					31-JAN-2008		
AIRWORTHINESS	REF: AMM 71-00-05	HRS/MSC	26600				0	26600	
		AFL	35000				0	35000	
71-00/476 (s)	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS PKG 3,17	MOS					09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				6214:55		
		AFL					5654		
71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 3,17	MOS					09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				6214:55		
		AFL					5654		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION PKG 3,17	MOS					09-JUN-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				6214:55		
		AFL					5654		
710005	UPPER LH ENGINE VIBRATION ISOLATOR	MOS					31-JAN-2008		
71.070	5712012106	HRS/MSC	O/C	N:0			0		
	3368	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR	MOS					31-JAN-2008		
71.080	5712012106	HRS/MSC	O/C	N:0			0		
	3391	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR	MOS					31-JAN-2008		
71.090	5712012106	HRS/MSC	O/C	N:0			0		
	3369	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		
710035	LOWER LH ENGINE VIBRATION ISOLATOR	MOS					31-JAN-2008		
71.100	5712012106	HRS/MSC	O/C	N:0			0		
	3366	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	5712012106 3379 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
710050	ENGINE MOUNT (WELDED)								
	5712012036 793 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67B PCE-PR0764 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	N:3884:45			23-APR-2016 4028:50 3721		
71JFL05	PERFORM ENGINE RUN-UP								
	REF:	MOS HRS/MSC AFL	A/R						
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			11-APR-2016 3884:45 3159	(7384:45) 7528:50	7584:45
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 0 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			20-SEP-2019 5839:20 4783	(7589:20) 7733:25	7839:20



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION REF: See Workcard	MOS HRS/MSC ENC	A/R				24-SEP-2012 1998:15 1597		
710053	NO. 1 ENGINE - AIR INLET HOUSING CORROSION INSPECTION REF:	MOS HRS/MSC ENC	-				25-FEB-2014 2717:45 2217		
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM) REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION PKG 0 REF: EMM 71-00-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				26-APR-2019 5644:10 4633		

CHAPTER 72 ENGINE
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720010	NO. 1 ENGINE - GAS GENERATOR MODULE 3042200 PS-PR0764 REF: See Workcard	MOS HRS/MSC ENC	3500	+500			3884:45	11-APR-2016 (7384:45) 7528:50	7884:45
OVERHAUL									
+ 720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				26-APR-2019 5644:10 4633		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				26-APR-2019 5644:10 4633		
+ 720025	NO. 1 ENGINE - OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	PKG	
+ 720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	PKG	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 09-JUN-2020 6070:50 4993		
+ 720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 09-JUN-2020 6070:50 4993		
+ 720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS REF: EMM 72-11-00	MOS HRS/MSC A/R ENC					26-APR-2019 5644:10 4633		
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 09-JUN-2020 6070:50 4993		
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 09-JUN-2020 6070:50 4993		
+ 722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC A/R ENC					31-JAN-2008 0 0		
+ 722030	NO. 1 ENGINE - IMMERSION IN WATER REF: EMM 72-00-00	MOS HRS/MSC A/R ENC					31-JAN-2008 0 0		
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3039001 EAAB000D576 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				31-JAN-2008 0 0	(24000) 24661	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA026507 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000				11-APR-2016 3884:45 3159	(12155) 12816	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 0 REF: EMM 72-30-04	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040952 TXA1B2817 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		31-JAN-2008 0 0	(24000) 24661	
+ 723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000D014 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		31-JAN-2008 0 0	(24000) 24661	
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 TXA1B3778 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		31-JAN-2008 0 0	(24000) 24661	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 TXA1B4010 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		31-JAN-2008 0 0	(24000) 24661	



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS					31-JAN-2008		
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R				0		
	REF: See Workcard	ENC					0		
+ 724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724020	NO. 1 ENGINE - HIGH OIL PRESSURE	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724050	NO. 1 ENGINE - MATERIAL INGESTION	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		
+ 724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN	MOS					31-JAN-2008		
		HRS/MSC	A/R				0		
	REF: EMM 72-00-00	ENC					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725003	NO. 1 ENGINE - OVERSPEED	MOS					31-JAN-2008		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS					31-JAN-2008		
	3053740-01	HRS/MSC		N:0			0		
	A0029598	ENC	8000	N:0			0	(8000) 8661	
LIFE LIMIT	REF: GENERIC NO REF								
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					11-APR-2016		
		HRS/MSC	5000				3884:45	(8884:45) 9028:50	
LIFE LIMIT	REF: GENERIC NO REF	ENC					3159		
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS					PKG		
	PKG 0	HRS/MSC	300	+10%/-10%			09-JUN-2020		
	REF: EMM 72-50-05	ENC					6070:50		
							4993		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS					31-JAN-2008		
	3037312	HRS/MSC		N:0			0		
	A0029CXX	ENC	15000	N:0			0	(15000) 15661	
LIFE LIMIT	REF: GENERIC NO REF								
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS					31-JAN-2008		
	3037313	HRS/MSC		N:0			0		
	A0029A9M	ENC	15000	N:0			0	(15000) 15661	
LIFE LIMIT	REF: GENERIC NO REF								
726020	NO. 1 ENGINE - POWER SECTION MODULE	MOS					11-APR-2016		
	3042200	HRS/MSC	3500	+500	O:0		3884:45	(7384:45) 7528:50	7884:45
	PCE-PR0764	ENC			O:0				
OVERHAUL	REF: GENERIC NO REF				O:0				
+ 726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE	MOS					31-JAN-2008		
		HRS/MSC A/R					0		
	REF: EMM 72-00-00	ENC					0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
+ 726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
73C059	FUEL,PUMP,3040760 9682013157 8627 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
731010	NO. 1 ENGINE - FUEL PUMP 825601-5 008627 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	N:99 O:0 N:3884:45 O:0 N:3159 O:0			11-APR-2016 3884:45 3159	(7384:45) 7528:50	
731024	NO. 1 ENGINE - FUEL NOZZLE 3119855-01 N/A REF:	MOS HRS/MSC ENC	O/C				09-JUN-2020 6070:50 4993		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3244882-2 C50835 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
OVERHAUL									
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 008627 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			09-JUN-2020 6070:50 4993	(6670:50) 6814:55	6730:50
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
+ 731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			09-JUN-2020 6070:50 4993	(6670:50) 6814:55	6730:50
REPLACE									
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA30908 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 9959524669 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-650 16571432 OVERHAUL REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	O:0 O:0 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	4000		N:0		23-APR-2016 3884:45	(7884:45) 8028:50	
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T	N:9 N:231:30 N:210			09-JUN-2020 6070:50 4993		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			30-NOV-2018 5489:40 4503	(6389:40) 6533:45	6479:40
733030	NO. 1 ENGINE - MAIN FUEL FILTER ASSEMBLY 3059779-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-MAY-2015 3448:25 2806		
733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993		
CHAPTER 74	IGNITION								
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			09-JUN-2020 6214:55 5654		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA16100164 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:1 N:0 N:0		11-MAY-2016 3884:45 3159	(7384:45) 7528:50	7884:45



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG CH34055 N/A REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-MAR-2018 5032:50 4117		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG CH34055 N/A REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-MAR-2018 5032:50 4117		
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50

CHAPTER 75 AIR

75C060	VALVE ASSY.,3123532-01B 9682013191 AHX009487 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
--------	--	-----------------------	-----	-------------------	--	--	-----------------------	--	--

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX009487 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:99 O:0 N:3884:45 O:0 N:3159 O:0		11-APR-2016 3884:45 3159	(7384:45) 7528:50	7884:45
--------	---	-----------------------	------	------	---	--	--------------------------------	-------------------	---------

CHAPTER 76 ENGINE CONTROLS



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 18 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+1m/-1m +10%/-10%			09-JUN-2020 6214:55 5654	09-JUN-2021 9214:55	09-JUL-2021 9514:55
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 9419411417 20070066 REF: AMM 76-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760020	CONDITION CABLE ASSY.								
76.030	9419411418 20070072 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419 20070067 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
+ 761011 (s)	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES							PKG	
	PKG 0	MOS						09-JUN-2020	
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			6070:50 4993		
CHAPTER 77 ENGINE INDICATING									
+ 77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM							PKG	
	PKG 3	MOS	12	+10%/-10%				09-JUN-2020	
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			6214:55 5654		
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	975.21.15.206 7765-6-455 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JAN-2012 1601:05 1393		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	9752115219 10832297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-MAR-2018 5176:55 4778		
770020	ACQ/DISPLAY UNIT								
77.020	975.29.02.034 183 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2016 4139:30 3816		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS 3043825-01 NRA006949 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			11-APR-2016 3884:45 3159		
CHAPTER 78 EXHAUST									
+ 78-00/214 (s)	EXAMINE EXHAUST STUBS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
CHAPTER 79 OIL									
+ 79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY. PKG 20 REF: AMM 24-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 3 REF: AMM 79-30-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 09-JUN-2020 6214:55 5654		
79-20/43	OIL COOLER 9683214102 T0327 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+10%/-10%	O:0 O:0 O:0		07-APR-2016 3994:05 3669	7494:05	7844:05
790005	TEMPERATURE BULB 9751120101 142042 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790020	PRESSURE,GAGE SWITCH								
79.030	9738114305 819 REF: AMM 79-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
790025	THERMAL ACTUATOR								
79.040	9787301002 969 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
790030	POWER ODM,B049913 MODULE								
79.050	9752115240 44650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2008 0 0		
79C061	SENSOR MODULE,ODM,B057185 REV.D								
	9752115242 44328 REF:	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			31-JAN-2008 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0764 Part # 3042200									
701020	NO. 1 ENGINE - CONTAMINATION OF OILWITH NON-METALLIC FOREIGN MATERIAL								
	REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM								
DISCARD	REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				30-JUL-2019 5757:10 4720		
+ 790031 (s)	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR						PKG		
	PKG 0 REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+30d/-10% +10%/-10%			09-JUN-2020 6070:50 4993		



Status Report

PC12/45 S/N 876 (LX-JFQ): 6477:25 HRS, 5847 AFL as of 16-Sep-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 17-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+10%/-10%			09-JUN-2020 6070:50 4993	09-JUN-2021 (6370:50) 6514:55	6400:50
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT REF: EMM 79-20-02	MOS HRS/MSC ENC	900	+10%/-10%			26-APR-2019 5644:10 4633	(6544:10) 6688:15	6634:10
+ 790060 (s)	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300				09-JUN-2020 6070:50 4993	PKG	
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN REF: EMM 72-60-00	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	(6370:50) 6514:55	6400:50
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE REF: EMM 79-20-02	MOS HRS/MSC ENC	A/R				31-JAN-2008 0 0		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				31-JAN-2008 0 0		
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	PKG	
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			09-JUN-2020 6070:50 4993	PKG	