



Status Report

PC-12/47E S/N 1467 T7-DUD

OWNER: FLY 7 EXECUTIVE AVIATION SA
ADDRESS: AEROPORT DE LAUSANNE
 LAUSANNE CH-1018
PHONE: +41 21 648 21 42 (OPS)
FAX: +41 21 648 21 43

OPERATOR: FLY 7 EXECUTIVE AVIATION SA
ADDRESS: AEROPORT DE LAUSANNE
 LAUSANNE CH-1018
PHONE: +41 21 648 21 42 (OPS)
FAX: +41 21 648 21 43

OPERATOR: HENDELL AVIATION OY
ADDRESS: LIIKELENTOTIE 8
PHONE: +358 40 594 3022
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 1467/T7-DUD **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 03-APR-2014	607 A/C HRS as of 16-OCT-2020	A/C HRS as of ___/___/___
	606 AFL as of 16-OCT-2020	AFL as of ___/___/___
	100:36 ACH as of 30-JAN-2018	ACH as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-RY0431/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 14-MAR-2014	LAST ACTUALS	CURRENT ACTUAL
8 ENG. HRS 0 A/C HRS	615 ENG. HRS as of 16-OCT-2020	ENG. HRS as of ___/___/___
5 ENC	610 ENC as of 16-OCT-2020	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: SA542/HC-E5A-3A **MODEL:** HC-E5A-3A **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 03-APR-2020	LAST ACTUALS	CURRENT ACTUAL
0 PROP HRS 537:22 A/C HRS	67:45 PROP HRS as of 16-OCT-2020	PROP HRS as of ___/___/___



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 15 in PKG 16,17,18,19,20,21	MOS				03-APR-2020	PKG	
	REF: AMM 05-20-00	HRS/MSC AFL	A/R			537:22 528		
05401A	300 HOUR INSPECTION							
+	PKG 16	MOS				29-JAN-2018		
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30		395:12 393	695:12	725:12
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 17	MOS	12	+1m/-1m	-64	03-APR-2020	29-JAN-2021	28-FEB-2021
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30		537:22 528	837:22	867:22
05403A	600 HOUR INSPECTION							
+	PKG 18	MOS				29-JAN-2018		
	REF: AMM 05-40-01	HRS/MSC AFL	600	+60/-60		395:12 393	995:12	1055:12
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 19	MOS	12	+1m/-1m	-64	03-APR-2020	29-JAN-2021	28-FEB-2021
	REF: AMM 05-40-01	HRS/MSC AFL	600	+60/-60		537:22 528	1137:22	1197:22



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A +	1200 HOUR OR 12 MONTH INSPECTION							
	PKG 20	MOS	12	+1m/-1m	-64	03-APR-2020	29-JAN-2021	28-FEB-2021
		HRS/MSC	1200	+120/-120		537:22	1737:22	1857:22
	REF: AMM 05-40-01	AFL				528		
05406A +	2400 HOUR OR 24 MONTHS INSPECTION							
	PKG 21	MOS	24	+1m/-1m	-64	03-APR-2020	29-JAN-2022	28-FEB-2022
		HRS/MSC	2400	+60/-60		537:22	2937:22	2997:22
	REF: AMM 05-40-01	AFL				528		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0431 Part # 3072955-01								
057010	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 0	MOS				03-APR-2020		
		HRS/MSC	300	+10%/-10%		545:22	(845:22) 837:22	875:22
	REF: See Workcard	ENC				539		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
		HRS/MSC	A/R				537:22		
	REF: GENERIC NO REF	AFL					528		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
		HRS/MSC	A/R				537:22		
	REF: GENERIC NO REF	AFL					528		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
		HRS/MSC	A/R				537:22		
	REF: GENERIC NO REF	AFL					528		
E072-150706	REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 43.0 DATED JUL 06/2015 RCF								
		MOS					17-FEB-2016		
		HRS/MSC	-						
	REF:	AFL							
	REQUIREMENT CHANGE FORMS								
E072-170818	PERFORM PWC, PT6A-67B/-67P MAINTENANCE MANUAL (P/N 3038338) REVISION 45.2 DATED 18 AUG 2017								
		MOS					11-SEP-2017		
		HRS/MSC	-						
	REF:	AFL							
P019-160201	REVIEW HARTZELL PROPELLER INC, PROPELLER OWNER'S MANUAL REV 22, DATED FEB/2016								
		MOS					03-MAY-2016		
		HRS/MSC	-						
	REF:	AFL							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47-150818	REVIEW 12-B-AM-00-00-00-I, 02300, REVISION 13, DATED 18 AUG 2015 RCF	MOS						17-FEB-2016	
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - AFL							
P47E-140731	REVIEW 12-B-AM-00-00-00-I, REVISION 11, DATED MAY 22, 2014 CAMP REQUIREMENT CHANGE FORM	MOS						30-APR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-150226	REVIEW 12-B-AM-00-00-00-I, 02300, REVISION 12, DATED 13 JAN 2015 RCF	MOS						12-MAR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-151231	REVIEW REVISION SUMMARY CHANGE FORM FOR AMM REVISION 14, DOCUMENT NUMBER 02300, 12-B-AM-00-00-00-I, DATED 06-NOV-2015	MOS						12-JAN-2016	
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - AFL							
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15	MOS						23-SEP-2016	
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - AFL						298:48 298	
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16	MOS						21-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL						320:24 320	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-170719	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 17	MOS						28-AUG-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL						0 0	
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04	MOS						03-APR-2014	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL						0 0	
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19	MOS						11-JUL-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05	MOS						28-SEP-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS						07-JAN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS						19-JUN-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS						20-APR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS						11-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014	MOS						02-APR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC						184:06 193	
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF	MOS						03-APR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-150404	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 22 DATED NOV 16/2012 RCF	MOS						29-APR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-150820	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 23 DATED AUG 20/2015 RCF							17-FEB-2016	
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC							
E072-151019	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14603 REVISION NO. 23 DATED OCT 19/2015 RCF							17-FEB-2016	
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC							
E072-160105	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14603 REVISION NO. 24 DATED JAN 05/2016 RCF							17-FEB-2016	
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC							
E072-160304	NO. 1 ENGINE - NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P (P/N 3038336), ENGINE MAINTENANCE MANUAL, REV. 44.0, DATED MAR 07/2016-RCF							28-JUN-2016	
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC							
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25							07-JUL-2016 295:54 293	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26							01-NOV-2016 315:24 314	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1	MOS						21-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -						328:24	
		ENC						325	
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						18-APR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						18-APR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-170410	NO. 1 ENGINE - REVIEW PWC MAINTENANCE MANUAL (P/N 3038338) REVISION 45.0 DATED 10 APR 2017	MOS						26-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							
E072-170621	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 25	MOS						12-AUG-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -						0	
		ENC						0	
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27, DATED 07 JUL 2017	MOS						26-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
		ENC							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1							12-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC					0 0		
E072-171030	NO. 1 ENGINE - REVIEW ENGINE MAINTENANCE MANUAL, REVISION 46.0, DATED 30 OCT 2017							29-NOV-2017	
	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0							22-MAY-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47							14-JUN-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1							16-JUL-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2							25-SEP-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS						06-DEC-2018	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						14-MAY-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS						22-AUG-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS						23-DEC-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS						16-APR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS						11-MAY-2020	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS						11-MAY-2020	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC -							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS						04-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS						01-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS						01-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS						20-OCT-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA542 Part # HC-E5A-3A									
PE5A-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 33	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

PE5A-200901	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 34	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
	NEW REQUIREMENT ADDED ON 21-SEP-2020 (EFFECTIVE: 01-SEP-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

PE5A-200901-1	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
	NEW REQUIREMENT ADDED ON 22-SEP-2020 (EFFECTIVE: 01-SEP-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER 04 LIMITATIONS

040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
LIFE LIMIT	REF: GENERIC NO REF	AFL	60000	N:0			0		60000

040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050000	PLEASE COMPLY WITH FOLLOWING INSTRUCTIONS: A. THIS WORK ORDER IS IN ACCORDANCE WITH AIRCRAFT MAINTENANCE PROGRAM (AMP): - AMC / HB-FVY, ISSUE 3, REV 0, 16 JAN 2017 B. CRS SHOULD CONTAIN: - AMP REFERENCE - CAMO WO NUMBER - MANUFACTURER DATAS USED (AS APPLICABLE) - MRO WO NUMBER C. PROVIDE THE CAMO WITH FOLLOWING BEFORE AIRCRAFT DEPARTURE: - LOGBOOK CRS - CAMP WO TALLY SHEET								
	REF:	MOS						30-NOV-2017	
		HRS/MSC	-					388	
		AFL						386	
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)								
	REF: AMM 05-10-30	MOS						03-APR-2014	
		HRS/MSC	25000					0	25000
		AFL	30000					0	30000
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION								
	REF: GENERIC NO REF	MOS						03-APR-2014	
		HRS/MSC	25000					0	25000
		AFL	30000					0	30000
05ARC00	AIRWORTHINESS REVIEW CERTIFICATE (ARC)								
	REF:	MOS						20-MAR-2020	19-MAR-2021 M
		HRS/MSC	DUE						
		AFL							
05C505	PERFORM REGISTRATION MARKS INSPECTION								
	REF:	MOS	6	+10%/-10%				29-JUL-2020	29-JAN-2021 16-FEB-2021
		HRS/MSC	500	+10%/-10%				568:55	1068:55 1118:55
		AFL						567	

CHAPTER 06 DIMENSIONS AND AREAS



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT PKG 15 ,16,17,18,19,20,21 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR. PKG 15 ,16,17,18,19,20,21 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTION IN THE FOLLOWING PANELS: 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
071005	LIFT MECHANISM ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
071010	LIFT CONTROL BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 08 LEVELING AND WEIGHING									
080000	WEIGHT CHECK AIRCRAFT								
08.005	REF: AMM 08-10-00	MOS HRS/MSC AFL	60				03-APR-2020 537:22 528	03-APR-2025	
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 17	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
CHAPTER 11 PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 20	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
	REF: See Workcard								
CHAPTER 12 SERVICING									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS HRS/MSC AFL	A/R				03-APR-2020 537:22 528		
	REF: AMM 12-20-01								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A 20.010	PERFORM CORROSION INSPECTION (INTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+1m/-1m		-64	03-APR-2020 537:22 528	29-JAN-2021	28-FEB-2021
00-00/45B 20.011	PERFORM CORROSION INSPECTION (EXTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	6	+10%/-10%			29-JUL-2020 568:55 567	29-JAN-2021	16-FEB-2021
CHAPTER 21 AIR CONDITIONING									
21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			03-APR-2020 537:22 528		
21-20/317 AIRWORTHINESS	CHECK ECS EMERGENCY SHUT-OFF SYSTEM REF: GENERIC NO REF	MOS HRS/MSC AFL	12 3000	+10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021 3537:22	05-MAR-2021



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/314	CHECK PRESSURIZATION SAFETY VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND								
21.030	PN SN-UNKNOWN REF: AMM 21-30-02	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		-107	03-APR-2020 537:22 528	17-DEC-2021 3537:22	28-FEB-2022 3837:22
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
21.045 AIRWORTHINESS	REF: AMM 21-30-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021 3537:22	05-MAR-2021
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
21.040	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		-107	03-APR-2020 537:22 528	17-DEC-2021 3537:22	28-FEB-2022 3837:22
21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
	REF: AMM 21-43-00	MOS HRS/MSC AFL	N/A				29-JAN-2018 395:12 393		
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH								
21.140	PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH								
21.150	9696781507 PKG 20 565038 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/50	CLEAN WATER SEPARATOR CONDENSER								
21.080	PN PKG 20 SN-UNKNOWN REF: AMM 21-40-03	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021 1737:22	05-MAR-2021 1857:22
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
21.130	9738132216 0611 REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		42	20-FEB-2019 473:24 465	03-APR-2024 5273:24	03-OCT-2024 5753:24
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
21.120	9738132214 0563 REF: AMM 21-60-05	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		42	20-FEB-2019 473:24 465	03-APR-2024 5273:24	03-OCT-2024 5753:24
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 18 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			03-APR-2014 0 0		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 18 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			03-APR-2014 0 0		
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
21-50/433 (s)	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)						PKG		
	9599022106 PKG 17 1412 REF: AMM 21-40-03	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			20-FEB-2019 473:24 465		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022106	MOS					03-APR-2014		
	1412	HRS/MSC	N/A				0		
	REF: AMM 21-50-03	AFL					0		
		ACH					0		
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022106	MOS					03-APR-2014		
	1412	HRS/MSC	N/A				0		
	REF: AMM 21-50-01	AFL					0		
		ACH					0		
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	9599022106	MOS					03-APR-2014		
	1412	HRS/MSC					0		
	REF: AMM 21-50-03	AFL					0		
		ACH	500	+10%/-10%			0	500	550
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	9599022106	MOS					03-APR-2014		
	1412	HRS/MSC					0		
	REF: AMM 21-50-01	AFL					0		
		ACH	500	+10%/-10%			0	500	550
21-CUS-01	PERFORM STATEMENT HOURS AIR-CONDITIONING								
		MOS					20-FEB-2019		
		HRS/MSC	300	+10%/-10%			473:24	773:24	803:24
	REF:	AFL					465		
210005	OVERPRESSURE SWITCH								
21.340	9738115105	MOS		N:0			03-APR-2014		
	1175	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-40-07	AFL		N:0			0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210010	REFRIGERATION PACK								
21.255	9599020111 1928 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1896 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 3653 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	2959A000 1756 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-APR-2020 537:22 528		
210030	HP SHUT OFF VALVE								
21.280	2943A000 1337 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-APR-2020 537:22 528		
210035	WATER SEPARATOR ASSY								
21.220	PN SN-UNKNOWN REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1899 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022106 1412 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 772 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 893 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091122 103898-00478 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091132 113-F0477 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 565038 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	9599022118 861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 565045 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 1234 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	9599020160 1305 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210180	CABIN PRESSURE CONTROL UNIT								
21.530	9599091144 2119232-00495 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210185	INTEG. ECS CONTROL UNIT								
21.540	9599020129 0502 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210190	FLOOR DUCT TEMP. SENSOR								
21.550	9599020121 3650 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR								
21.560	9599020121 3661 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	9633011005 0588 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	9738132216 0611 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	9738132214 0563 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	9633011105 1245B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2031B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2045B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	9633011106 2046B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR								
21.600	9599020121 3664 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
210240	INSULATED, WATER SEPERATOR ASSY								
	5214112047 3039 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER 22 AUTO FLIGHT

22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 21	MOS	24	+10%/-10%			03-APR-2020		
		HRS/MSC	2400	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
22-10/60	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-64	03-APR-2020	29-JAN-2021	28-FEB-2021
		HRS/MSC	1000	+10%/-10%			537:22	1537:22	1637:22
	REF: AMM 22-10-00	AFL					528		
22-10/60	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-64	03-APR-2020	29-JAN-2021	28-FEB-2021
		HRS/MSC	1000	+10%/-10%			537:22	1537:22	1637:22
	REF: AMM 22-10-00	AFL					528		
22-10/60	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-64	03-APR-2020	29-JAN-2021	28-FEB-2021
		HRS/MSC	1000	+10%/-10%			537:22	1537:22	1637:22
	REF: AMM 22-10-00	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 17 REF: AMM 22-20-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 16 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 29-JAN-2018 395:12 393		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 20 REF: AMM 22-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
220045 22.220	STICK PUSHER SERVO 9786111103 80767 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220055 22.140	STICK PUSHER CAPSTAN 9786111124 80751 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220060 22.230	STICK SHAKER 9786111143 1281 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220070 22.170	STICK PUSHER 9754423104 132304 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B2470 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B2463 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B2461 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220100	RUDDER KSA 2700 SERVO								
22.260	065-00190-0101 KSA2700-1414 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-MAY-2015 184:36 198		
220105	ELEVATOR KSA 2700 SERVO								
22.250	9859912131 KSA2700-2520 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220110	AILERON KSA 2700 SERVO								
22.240	9859912131 KSA2700-2500 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
220115	KMC 9200 VNAV FLIGHT CONTROLLER								
	9859912204 KMC9200-1616 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER 23 COMMUNICATIONS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue
(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH PKG 21	MOS	24	+10%/-10%			PKG		
	REF: AMM 23-50-00	HRS/MSC AFL	2400	+10%/-10%			03-APR-2020 537:22 528		
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH PKG 21	MOS	24	+10%/-10%			PKG		
	REF: AMM 23-12-00	HRS/MSC AFL	2400	+10%/-10%			03-APR-2020 537:22 528		
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA 9848110203	MOS		N:0			03-APR-2014		
23.020	310-25368	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-02	AFL		N:0			0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA 9848110203	MOS		N:0			03-APR-2014		
23.030	310-25370	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-03	AFL		N:0			0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA 9848110210	MOS		N:0			03-APR-2014		
23.070	12668	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-57-02	AFL		N:0			0		
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO 9859912254	MOS		N:0			03-APR-2014		
23.090	3892	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-01	AFL		N:0			0		
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO 069-01037-0102	MOS					17-DEC-2014		
23.080	3458	HRS/MSC	O/C				141:18		
	REF: AMM 23-12-01	AFL					153		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	9859912108 J01275 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	9859912108 J01290 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
230075	ATG 5000 UNIT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
230080	AIRCELL CONIF MODULE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
230085	NO. 1 COMANT CI-5500 COMDAT ANTENNA								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
230090	NO. 2 COMANT CI-5500 COMDAT ANTENNA								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 24 ELECTRICAL POWER									
24-30/309	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437)								
24.210	9789123407 P1982 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/310	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.437)								
24.026	9789123407 P1978 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		
24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021 3537:22	05-MAR-2021
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021 3537:22	05-MAR-2021
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST						PKG		
	PKG 21 REF: AMM 24-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST						PKG		
	PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
24.010	RG-380E/44 40946537 REF: See Workcard	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%		13	29-JUL-2020 568:55 567	11-FEB-2021 1168:55	27-FEB-2021 1228:55
24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44 40950782 REF: AMM 24-30-07	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%		13	29-JUL-2020 568:55 567	11-FEB-2021 1168:55	27-FEB-2021 1228:55



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/473	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) 9789123407 PKG 18 P1982 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			20-FEB-2019 473:24 465	1073:24	1133:24
+ 24-30/474	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407) 9789123407 PKG 18 P1978 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			20-FEB-2019 473:24 465	1073:24	1133:24
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR 9789123407 P1982 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	+10%/-10%			03-APR-2014 0 0	1200	1320
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR 9789123407 P1978 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+10%/-10%			03-APR-2014 0 0	1200	1320
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR 9789123407 P1982 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR 9789123407 P1978 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 21	MOS	24	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			537:22 528		
24-50/70 24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 9858314953 83138 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%		-64	03-APR-2020 537:22 528	29-JAN-2021	05-MAR-2021
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 21	MOS	24	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			537:22 528		
240005 24.120	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111 P3413 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
240010 24.130	GENERATOR 1 300A CONTACTOR 9740338113 R467 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
240015 24.130	GENERATOR 2 300A CONTACTOR 9740338113 R393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
240125	BATTERY/ EXIT POWER JUNCTION (BEPJB) BOX 9740338142 681 REF: AMM 24-40-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240135	NO. 1 LEAD ACID BATTERY								
24.010	RG-380E/44 40946537 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			29-MAY-2018 411:06 414		
240140	NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44 40950782 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			29-MAY-2018 411:06 414		
243010	NO. 2 STARTER-GENERATOR								
24.215	9789123407 P1978 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	9858314953 83138 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	N:32 N:317 N:316			15-DEC-2016 317 316		
243160	NO. 1 STARTER GENERATOR								
24.205	9789123407 P1982 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	9750215107 6781 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	9755085111 N2652 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	9755085111 N2662 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
243190	VOLTAGE REGULATOR								
	9882114111 P3301 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 16	MOS HRS/MSC AFL	300	+10%/-10%			29-JAN-2018 395:12 393		
+ 25-10/294	CO-PILOT SEAT BELT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/294	CREW SEAT BELTS								
25.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-OCT-2013 0 0		
+ 25-10/294	PILOT SEAT BELT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				03-APR-2020 537:22 528		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				03-APR-2020 537:22 528		
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS.						PKG		
	PKG 20 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS						PKG		
	PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXCUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
+ 25-20/295	NO. 1 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 2 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 3 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 4 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 5 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 6 PASSENGER SEAT BELT								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	PASSENGER SEAT BELTS								
25.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-AUG-2014 0 0		
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 29-JAN-2018 395:12 393		
25-60/231 (s)	OPERATIONAL TEST ELT 9851380853 PKG 17 LX1100065614 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 9851380853 LX1100065614 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	ELT BATTERY S1820516-99 25.020 TM0000178541 DISCARD Expiry Date: 01-JUN-2026	MOS HRS/MSC AFL	DUE	N:0 N:0 N:0			25-SEP-2019 507:28 498	01-JUN-2026 M	
25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) 9851380858 KA2625254006 DISCARD REF: GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			03-APR-2014 0 0	03-APR-2024 16000	03-OCT-2024 16500
25-63/477	CLEAN UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
25-63/478	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
25-63/479	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON BATTERY VOLTAGE (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
25-63/480	DISCARD UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
25-CUS-01	INSPECT LIFE VEST REF:	MOS HRS/MSC AFL	12	+10%/-10%			03-APR-2020 537:22 528	03-APR-2021	09-MAY-2021



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250005	REMOTE CONTROL PANEL								
25.070	9851380817 TM0000046654 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
250010	EMERGENCY LOCATOR TRANSMITTER								
25.050	9851380853 LX1100065614 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
250021	L/H NO. 1 AFSS PASSENGER SEAT								
25.120	959.30.01.821 57247 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		
250022	R/H NO. 2 AFSS PASSENGER SEAT								
25.125	959.30.01.822 57248 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		
250023	L/H NO. 3 FFSS PASSENGER SEAT								
25.130	959.30.01.835 57249 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		
250024	R/H NO. 4 FFSS PASSENGER SEAT								
25.135	959.30.01.836 57251 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		
250025	L/H NO. 5 FFSS PASSENGER SEAT								
25.140	959.30.01.837 57250 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250026	R/H NO. 6 FFSS PASSENGER SEAT								
25.145	959.30.01.838 57252 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0			17-DEC-2014 141:18 153		
250027	L/H NO. 7 STANDARD PASSENGER SEAT								
25.150	959.30.01.521 1766 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0			17-DEC-2014 141:18 153		
250028	R/H NO. 8 STANDARD PASSENGER SEAT								
25.155	959.30.01.522 1822 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0			17-DEC-2014 141:18 153		
250029	R/H NO. 9 STANDARD PASSENGER RIGHT SEAT								
	5252212012 1397 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE								
25.060	9851380858 KA2625254006 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
256015	CABLE ,S1825503-01 ASSEMBLY								
25.080	9851380859 TM0000060905 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
256020	LH BLACK PILOT SEAT								
25.090	9593001165 72749 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256025	RH BLACK CO-PILOT SEAT								
25.100	9593001166 72673 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
256050	UNDERWATER LOCATOR BEACON								
	PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
256114	PILOT LIFE VEST								
	63600-105 L2486430 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256115	COPILLOT LIFE VEST								
	63600-105 L2486431 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256116	NO. 3 LIFE VEST								
	63600-105 L2486432 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256117	NO. 4 LIFE VEST								
	63600-105 L2486433 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256118	NO. 5 LIFE VEST								
	63600-105 L2486434 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256119	NO. 6 LIFE VEST 63600-105 L2486435 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256120	NO. 7 LIFE VEST 63600-105 L2486436 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256121	NO. 8 LIFE VEST 63600-105 L2486437 REF:	MOS HRS/MSC AFL ACH	O/C				03-APR-2014 0 0 0		
256122	NO. 1 LIFE VEST 63600-105 L2486438 REF:	MOS HRS/MSC AFL	O/C						
256123	NO. 2 LIFE VEST 63600-105 L2486439 REF:	MOS HRS/MSC AFL	O/C						
+ 256130	RECERTIFY PILOT LIFE VEST 63600-105 L2486430 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256131	RECERTIFY COPILOT LIFE VEST 63600-105 L2486431 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256132	RECERTIFY NO. 3 LIFE VEST 63600-105 L2486432 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256133	RECERTIFY NO. 4 LIFE VEST 63600-105 L2486433 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256134	RECERTIFY NO. 5 LIFE VEST 63600-105 L2486434 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256135	RECERTIFY NO. 6 LIFE VEST 63600-105 L2486435 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256136	RECERTIFY NO. 7 LIFE VEST 63600-105 L2486436 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
+ 256137	RECERTIFY NO. 8 LIFE VEST 63600-105 L2486437 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
256138	RECERTIFY NO. 1 LIFE VEST LIFE VEST 63600-105 L2486438 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	
256139	RECERTIFY NO. 2 LIFE VEST LIFE VEST 63600-105 L2486439 REF:	MOS HRS/MSC AFL	120				28-FEB-2014	29-FEB-2024	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C001	PERFORM INSPECTION FIRST AID KIT REF:	MOS HRS/MSC AFL	12				03-APR-2020 537:22 528	01-FEB-2021 M	
25C002	FIRST AID KIT - AFAK FIRST AID KIT 725050 / 725040 4764 REF:	MOS HRS/MSC AFL	-				03-APR-2020 537:22 528	01-FEB-2021 M	
CHAPTER 26 FIRE PROTECTION									
26-20/2	COCKPIT FIRE EXTINGUISHER 9590806216 B35946 REF: GENERIC NO REF Manufacture Date: 01-JAN-2014	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-JAN-2014	01-JAN-2024	
26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224) 9590806216 B35946 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m	-64		03-APR-2020 537:22 528	29-JAN-2021	28-FEB-2021
26-20/515	CABIN FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
26-20/515	COCKPIT FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224) 9590806216 B35946 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224) 9590806216 B35946 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-APR-2014 0 0		
260005	FIRE/OVERHEAT DETECTOR 9751210012 213286 REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 27 FLIGHT CONTROLS									
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 29-JAN-2018 395:12 393		
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES REF:	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
+ 27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES REF: GENERIC NO REF	MOS HRS/MSC AFL	32500 42000	+500/-500 +500/-500			03-APR-2014 0 0	32500 42000	33000 42500
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK REF: AMM 27-00-00	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	42		20-FEB-2019 473:24 465	03-APR-2024 5273:24	03-OCT-2024 5753:24
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
27-10/236 (s)	AILERON CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
27-10/237 (s)	CHECK AILERON CABLE TENSION						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: AMM 27-10-00	AFL						528	
27-10/238 (s)	FUNCTIONAL TEST AILERONS						PKG		
	PKG 21	MOS	24	+10%/-10%				03-APR-2020	
		HRS/MSC	2400	+10%/-10%				537:22	
	REF: AMM 27-10-00	AFL						528	
27-10/394	AILERON CONTROL SYSTEM - EXAMINE								
		MOS						03-APR-2014	
27.155		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 27-10-00	AFL	42000					0	42000
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT								
		MOS						03-APR-2014	
27.160		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 27-10-09	AFL	42000					0	42000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS								
27.165		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
27.170		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS								
27.175		MOS					03-APR-2014		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
27.215		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 27-10/444	FLIGHT CONTROL CABLES, AILERON								
	PN	MOS			N:0		03-APR-2014		
LIFE LIMIT	REF: AMM 27-10-01	HRS/MSC	20000		N:0		0		20000
		AFL	27000		N:0		0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS			N:0		03-APR-2014		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	20000		N:0		0		20000
		AFL	27000		N:0		0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: AMM 27-10-00	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM PKG 21 REF: AMM 27-15-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/140 (s)	INSPECTION/CHECK RUDDER PKG 17 REF: AMM 55-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/241 (s)	RUDDER CONTROL - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 20 REF: AMM 27-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 21 REF: AMM 27-20-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 21 REF: AMM 27-25-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					03-APR-2014		
27.180	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0	32500	
AIRWORTHINESS							0	42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					03-APR-2014		
27.185	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0	32500	
AIRWORTHINESS							0	42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					03-APR-2014		
27.190	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0	32500	
AIRWORTHINESS							0	42000	
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					19-SEP-2014		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				95:18 108		
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					19-SEP-2014		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				95:18 108		
+ 27-20/446	FLIGHT CONTROL CABLES, RUDDER	MOS					03-APR-2014		
	REF: AMM 27-20-01	HRS/MSC AFL	20000 27000		N:0 N:0 N:0		0	20000	
LIFE LIMIT							0	27000	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-20-02	AFL	27000	N:0			0		27000
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			03-APR-2020		
		HRS/MSC	2400	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
27-30/249 (s)	ELEVATOR CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: AMM 27-30-00	AFL					528		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR						PKG		
	PKG 21	MOS	24	+10%/-10%			03-APR-2020		
		HRS/MSC	2400	+10%/-10%			537:22		
	REF: AMM 27-30-00	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED								
27.150	REF: AMM 27-30-00	MOS HRS/MSC AFL	O/C				19-SEP-2014 95:18 108		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)								
	REF: AMM 27-30-00	PN SN-UNKNOWN AFL	A/R				19-SEP-2014 95:18 108		
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE								
27.195	REF: AMM 27-30-00	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
AIRWORTHINESS									
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS								
27.200	REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
AIRWORTHINESS									
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
27.205	REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
AIRWORTHINESS									
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
27.210	REF: AMM 27-30-05	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
AIRWORTHINESS									
+ 27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	REF: AMM 27-30-01	PN SN-UNKNOWN AFL	20000 27000		N:0 N:0 N:0		03-APR-2014 0 0	20000 27000	
LIFE LIMIT									



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-02	AFL	27000	N:0			0		27000
+ 27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2014		
		HRS/MSC	1200	+10%/-10%			0		
	REF: See Workcard	AFL					0		
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)								
		MOS	12	+10%/-10%	-64		03-APR-2020	29-JAN-2021	05-MAR-2021
27.021		HRS/MSC	3000				537:22	3537:22	
AIRWORTHINESS	REF: AMM 27-40-00	AFL					528		
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: AMM 27-40-00	AFL					528		
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: AMM 27-40-01	AFL					528		
27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	978.73.14.203	MOS	84	N:0			03-APR-2014	03-APR-2021	
27.020	1411	HRS/MSC	3400	N:0			0	3400	
OVERHAUL	REF:	AFL		N:0			0		
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	PN	MOS	84				03-APR-2014	03-APR-2021	
	SN-UNKNOWN	HRS/MSC	3400				0	3400	
OVERHAUL	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 16	MOS					PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%			29-JAN-2018 395:12 393		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%			03-APR-2020 537:22 528		
27-40/3	PITCH TRIM ACTUATOR 9787314203	MOS		N:0			03-APR-2014		
27.011	1411	HRS/MSC	20000	N:0			0	20000	
AIRWORTHINESS	REF:	AFL	27000	N:0			0	27000	
+ 27-40/3	REPLACE PITCH TRIM ACTUATOR PN	MOS					03-APR-2014		
	SN-UNKNOWN	HRS/MSC	20000				0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000				0	27000	
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) PN	MOS		N:0			03-APR-2014		
27.036	SN-UNKNOWN	HRS/MSC	10000	N:0			0	10000	
LIFE LIMIT	REF: AMM 27-40-02	AFL		N:0			0		
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R				03-APR-2020 537:22 528		
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
27-50/28	FLAP POWER DRIVE UNIT 9787320003	MOS					06-JUN-2014		
27.030	0268	HRS/MSC	10000	+500/-500	N:6681:24		48:42	3367:18	3867:18
OVERHAUL	REF: AMM 27-50-01	AFL	13500	+500/-500	N:6378		46	7168	7668
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 9787320309	MOS					03-APR-2014		
27.040	5053	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 9787320309	MOS					03-APR-2014		
27.041	5055	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR 9787320309	MOS					03-APR-2014		
27.050	5051	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR 9787320309	MOS					03-APR-2014		
27.051	5054	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202205	MOS					03-APR-2014		
27.060	S7210	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			03-APR-2014		
27.060	S7193	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			03-APR-2014		
27.070	S7209	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			03-APR-2014		
27.070	S7095	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					03-APR-2014		
27.220		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					03-APR-2014		
27.225		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	30000				0	30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					03-APR-2014		
27.230		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					03-APR-2014		
27.235		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS					03-APR-2014		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS								
		MOS					03-APR-2014		
27.240		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS								
		MOS					03-APR-2014		
		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
		MOS					03-APR-2014		
27.245		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
		MOS					03-APR-2014		
27.250		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
27-50/4	LEFT INBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		03-APR-2014		
27.040	5053	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000
27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		03-APR-2014		
27.041	5055	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		03-APR-2014		
27.050	5051	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		03-APR-2014		
27.051	5054	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/414	LEFT HAND FLAP								
	5575012003	MOS		N:0			03-APR-2014		
57.060	1222E	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			03-APR-2014		
57.060	1222E	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			03-APR-2020	29-JAN-2021	05-MAR-2021
		HRS/MSC	600	+10%/-10%		-64	537:22	1137:22	1197:22
AIRWORTHINESS	REF: AMM 27-51-00	AFL					528		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: AMM 12-20-07	AFL					528		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			03-APR-2014		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
		HRS/MSC	A/R				537:22		
	REF: GENERIC NO REF	AFL					528		
27-50/74 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR						PKG		
	9787320309 PKG 17	MOS	12	+10%/-10%			03-APR-2020		
27.040	5053	HRS/MSC	300	+10%/-10%			537:22		
	REF: AMM 27-50-00	AFL					528		
27-50/74 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR						PKG		
	9787320309 PKG 17	MOS	12	+1m/-1m			03-APR-2020		
27.041	5055	HRS/MSC	300	+10%/-10%			537:22		
	REF: AMM 27-50-00	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR						PKG		
27.050	9787320309 PKG 17 5051 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			03-APR-2020 537:22 528		
27-50/74 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR						PKG		
27.051	9787320309 PKG 17 5054 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			03-APR-2020 537:22 528		
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 5053 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-107		03-APR-2020 537:22 528	17-DEC-2021 2937:22 3728	28-FEB-2022 3177:22 4048
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 5055 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-107		03-APR-2020 537:22 528	17-DEC-2021 2937:22 3728	28-FEB-2022 3177:22 4048
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 5051 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-107		03-APR-2020 537:22 528	17-DEC-2021 2937:22 3728	28-FEB-2022 3177:22 4048
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 5054 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-107		03-APR-2020 537:22 528	17-DEC-2021 2937:22 3728	28-FEB-2022 3177:22 4048
270003	HORIZONTAL TAIL ASSY								
	5551012037 1274 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012039 1328 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270023	ELEVATOR RH ASSY								
27.023	5552012040 1326 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318138 0880 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270030	FIN ASSY								
27.031	5553012041 1220E REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270033	RUDDER ASSY								
27.033	5554012040 1223E REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270035	FLAP CONTROL AND WARNING UNIT								
27.130	9787320017 132557 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 1390059DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 2038 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 1390110DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 1390028DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 2039 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270080	KTA2810,TRIM ADAPTER								
22.135	9859912249 KTA2810-1862 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318138 0900 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 1390094DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
274020	PITCH TRIM ACTUATOR								
	PN SN-UNKNOWN REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 28	FUEL								
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE	MOS					03-APR-2014		
28.029	REF: AMM 28-10-01	HRS/MSC AFL	2400	+10%/-10%			0 0	2400	2640
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 17	MOS	12	+10%/-10%			PKG		
	REF: AMM 28-20-07	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 17	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N) PKG 19	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			03-APR-2020 537:22 528		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 21	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/32	OVERHAUL ENGINE DRIVEN PUMP								
28.010	9688451108	MOS		N:0			03-APR-2014		
OVERHAUL	B5851	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 28-20-03	AFL		N:0			0		
280005	LOW PRESSURE FUEL PUMP								
28.120	9688451108	MOS		N:0			03-APR-2014		
	B5851	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-03	AFL		N:0			0		
280010	FUEL FLOW TRANSMITTER								
28.130	9753512108	MOS					07-JUL-2016		
	0846-017	HRS/MSC	O/C				287:24		
	REF: AMM 73-30-01	AFL					287		
280012	FUEL CONTROL MONITORING UNIT								
28.155	9753731336	MOS		N:0			03-APR-2014		
	603	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			03-APR-2014		
	3137	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-08	AFL		N:0			0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301	MOS		N:0			03-APR-2014		
	3147	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-12	AFL		N:0			0		
280025	FUEL FILTER ASSY								
28.025	9683521001	MOS		N:0			03-APR-2014		
	2013FFT2192	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-01	AFL		N:0			0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102	MOS		N:0			03-APR-2014		
	2222	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-02	AFL		N:0			0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B5420 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B5386 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731253 1765 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731252 1722 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731251 1723 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731250 1731 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 B8106 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B5420 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B5412 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731250 1718 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731251 1710 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	9753731252 1725 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731253 1779 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 B8110 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280105	TOP CHECK VALVE								
28.150	9630423105 3150 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280110	BOTTOM CHECK VALVE								
28.150	9630423105 3149 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1252 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1255 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER 29 HYDRAULIC POWER

29-10/151	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		
29-10/153	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		
29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)	PN NOT INSTALLED REF: AMM 29-10-02	MOS HRS/MSC AFL	N/A			16-DEC-2016 317 316		
29-10/259	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL	MOS HRS/MSC AFL	N/A				16-DEC-2016 317 316		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.	MOS						16-DEC-2016	
	REF: AMM 29-00-00	HRS/MSC AFL	N/A					317 316	
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED)	MOS						03-APR-2014	
29.020	PN NOT INSTALLED REF: AMM 29-10-02	HRS/MSC AFL	N/A	N:0 N:0 N:0				0 0 0	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS						PKG 03-APR-2020	
	PN PKG 21 NOT INSTALLED REF: AMM 29-10-02	HRS/MSC AFL	N/A						
CHAPTER 30 ICE AND RAIN PROTECTION									
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS	MOS	12	+10%/-10%				PKG 03-APR-2020	
	PKG 17 REF: AMM 30-10-00	HRS/MSC AFL	300	+10%/-10%				537:22 528	
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM	MOS	12	+10%/-10%				PKG 03-APR-2020	
	PKG 19 REF: AMM 30-20-00	HRS/MSC AFL	600	+10%/-10%				537:22 528	
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM	MOS	12	+10%/-10%				PKG 03-APR-2020	
	PKG 20 REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%				537:22 528	
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1	MOS	6	+10%/-10%				29-JUL-2020	29-JAN-2021 16-FEB-2021
30.010	REF: GENERIC NO REF	HRS/MSC AFL						568:55 567	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 19 REF: AMM 30-30-20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 21 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 19 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 03-APR-2020 537:22 528		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 19 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 03-APR-2020 537:22 528		
300005 30.140	PROP DE-ICE CONTROLLER 9682913227 U2767 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300010 30.150	LPMI LINEAR ACTUATOR 9787315302 C99216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 132627 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N132428 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N132412 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N132676 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N132679 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 6995 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N132894 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	9598901014 U3852 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	R:0 N:556:48 R:0 N:359 R:0			23-JUN-2020 545:20 544		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300060	LEFT WINDSHIELD DE ICE CONTROLLER 9728132202 133537 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2014 141:18 153		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER 9728132202 132409 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300090	LH HORIZ STAB DE-ICER BOOT 9598901026 NBT-7570 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300095	RH HORIZ STAB DE-ICER BOOT 9598901027 NBT-9460 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300100	RH INBD-WING DE-ICER BOOT 9598901023 SN-UNKNOWN REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C				19-SEP-2014 95:18 108		
300105	RH OUTBD-WING DE-ICER BOOT 9598901025 NBP-4480 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300110	LH AOA PLATE TEMP CONTROLLER 9754421417 UD765 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300115	LH INBD-WING DE-ICER BOOT 9598901022 NBT-5540 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901024 NBR-7950 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 UD795 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 6940 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 6937 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 7022 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 7023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	9598901008 N132698 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER 31 INDICATING/RECORDING SYSTEMS



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-00/CFR	TEST/INSPECT COPILOT ALTIMETER (14 CFR 91.411)	MOS					03-APR-2014		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 31-00/CFR	TEST/INSPECT PILOT ALTIMETER (14 CFR 91.411)	MOS					03-APR-2020		
	REF: See Workcard	HRS/MSC	N/A				537:22		
		AFL					528		
31-30/421	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)	MOS	12	+10%/-10%			03-APR-2020	29-JAN-2021	05-MAR-2021
	9859920146 PKG 20	HRS/MSC	1200	+10%/-10%	-64		537:22	1737:22	1857:22
	1005930	AFL					528		
	REF: AMM 31-30-01								
310050	DIGITAL CLOCK	MOS					03-APR-2014		
31.040	9996111214	HRS/MSC	O/C	N:0			0		
	22231	AFL		N:0			0		
	REF: AMM 31-20-12			N:0			0		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER	MOS					03-APR-2014		
31.180	9859912178	HRS/MSC	O/C	N:0			0		
	KMC2210-2127	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE	MOS					03-APR-2014		
31.240	9859912222	HRS/MSC	O/C	N:0			0		
	1310A017	AFL		N:0			0		
	REF: AMM 31-42-00			N:0			0		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE	MOS					03-APR-2014		
31.270	9859912222	HRS/MSC	O/C	N:0			0		
	1310A022	AFL		N:0			0		
	REF: AMM 31-42-00			N:0			0		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD	MOS					03-APR-2014		
31.160	9859912231	HRS/MSC	O/C	N:0			0		
	13084940	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310085	OVERHEAD CONTROL BASIC PANEL								
31.260	9728121155 0488 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310090	KMC2220 MF CONTOLLER								
31.170	9859912189 KMC2220-1616 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310095	PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	9859912178 KMC2210-2047 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1312H413 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1401H521 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	9859912147 13086946 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	9859912231 13084695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	9859912250 13060840 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	9859912250 13070881 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	9859912252 13120628 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	9859912251 13101150 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	9859912103 1890324291 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	9859912103 1890324294 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890324290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890325079 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310155	REV CTL PNL,4-POT DISPLAY								
31.130	9728121141 0497 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40335984 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40319037 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310167	CC-500 CONTROL UNIT								
31.280	9859912202 421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310170	CCD INTERNAL ELECTRICAL ASSEMBLY								
31.290	9859912218 0270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310175	REAR CENTRE CONS PNL PC-12 47/E								
31.300	9728121154 0440 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310177	MIDDLE CENTRE CONS PANEL								
	9728121146 0470 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310180	COCKPIT AREA MICROPHONE								
	9859920137 000925304 REF: AMM 31-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT								
	9859920146 1005930 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-SEP-2014 141:18 153		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310187 (s)	OPERATIONAL CHECK COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT 9859920146 1005930 REF:	MOS HRS/MSC AFL	12				29-JAN-2018 395:12 393		
CHAPTER 32 LANDING GEAR									
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 19 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 19 REF: AMM 32-10-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK 32.010 REF: See Workcard	MOS HRS/MSC AFL	12 2400	+1m/-1m +10%/-10%	-64		03-APR-2020 537:22 528	29-JAN-2021 2937:22	28-FEB-2021 3177:22



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	5321012055 VLG1015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	5321012056 VLG1015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	25000 30000				03-APR-2014 0 0	25000 30000	
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
32.215 AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				03-APR-2014 0 0	25000 30000	
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION								
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				03-APR-2014 0 0	25000 30000	
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION								
32.220 AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000				03-APR-2014 0 0	25000 30000	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			03-APR-2020 537:22 528	03-APR-2021	03-MAY-2021
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT								
	REF: See Workcard	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
	REF: See Workcard								
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
	REF: AMM 32-10-00								
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
	REF: AMM 32-10-00								
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
	REF: AMM 32-10-00								
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
	REF: AMM 32-10-00								
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	120				03-APR-2014 0 0	03-APR-2024	
	REF: AMM 32-10-00								
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	120				03-APR-2014 0 0	03-APR-2024	
	REF: AMM 32-10-00								
32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS	MOS HRS/MSC AFL	12	+1m/-1m		-64	03-APR-2020 537:22 528	29-JAN-2021	28-FEB-2021
	532.45.12.066 2851 REF: AMM 12-20-06								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/80	LUBRICATE NOSE WHEEL BEARINGS 9595602302 1331 REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		-64	03-APR-2020 537:22 528	29-JAN-2021	28-FEB-2021
32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS 532.45.12.066 2825 REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		-64	03-APR-2020 537:22 528	29-JAN-2021	28-FEB-2021
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 19 REF: AMM 32-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 19 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
32-20/335	NOSE LANDING GEAR TORQUE TUBE PN 32.190 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC AFL	120 11000 15000	N:0 N:0 N:0			03-APR-2014 0 0	03-APR-2024 11000 15000	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
32.195	PN	MOS					03-APR-2014		
AIRWORTHINESS	SN-UNKNOWN	HRS/MSC	2000				0		2000
	REF: AMM 32-20-06	AFL	2500				0		2500
32-20/403	NOSE LANDING GEAR - OVERHAUL								
32.200	PN	MOS		N:0			03-APR-2014		
OVERHAUL	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0		0		25000 25500
	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0		0		30000 30500
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
32.225	PN	MOS		N:0			03-APR-2014		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC	25000	N:0			0		25000
	REF: AMM 32-20-05	AFL	30000	N:0			0		30000
32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM								
		MOS					29-JAN-2018		
		HRS/MSC	N/A				395:12		
	REF: AMM 32-30-00	AFL					393		
32-30/423	LEFT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601823	MOS		N:0			03-APR-2014		
LIFE LIMIT	54	HRS/MSC		N:0			0		
	REF: See Workcard	AFL	30000	N:0			0		30000
32-30/423	NOSE LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601824	MOS		N:0			03-APR-2014		
LIFE LIMIT	27	HRS/MSC		N:0			0		
	REF: See Workcard	AFL	30000	N:0			0		30000
32-30/423	RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601823	MOS		N:0			03-APR-2014		
LIFE LIMIT	53	HRS/MSC		N:0			0		
	REF: See Workcard	AFL	30000	N:0			0		30000
32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%		-64	03-APR-2020	29-JAN-2021	05-MAR-2021
AIRWORTHINESS		HRS/MSC	2000				537:22	2537:22	
	REF: AMM 32-30-10	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/425 (s)	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS						PKG		
	PKG 19	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	600	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%		-64	03-APR-2020	29-JAN-2021	05-MAR-2021
		HRS/MSC	2000				537:22	2537:22	
AIRWORTHINESS	REF: AMM 32-30-08	AFL					528		
32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%		-64	03-APR-2020	29-JAN-2021	05-MAR-2021
		HRS/MSC	2000				537:22	2537:22	
AIRWORTHINESS	REF: AMM 32-10-06	AFL					528		
32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS					03-APR-2014		
		HRS/MSC					0		
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS					03-APR-2014		
		HRS/MSC					0		
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS					03-APR-2014		
		HRS/MSC					0		
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				03-APR-2020	03-APR-2026	
		HRS/MSC					537:22		
	REF: See Workcard	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS REF: See Workcard	MOS HRS/MSC AFL	72				03-APR-2020 537:22 528	03-APR-2026	
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE PKG 17 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 17 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 17 REF: AMM 12-10-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230		MOS					03-APR-2014		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
+ 32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230		MOS					03-APR-2014		
		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 32-50-00	AFL	42000	+500/-500			0		42000 42500
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	9594751131	MOS		N:0			03-APR-2014		
	5818	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-04	AFL		N:0			0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751131	MOS		N:0			03-APR-2014		
	5850	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-04	AFL		N:0			0		
320015	PARK BRAKE VALVE								
32.140	9594751121	MOS		N:0			03-APR-2014		
	2721	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-05	AFL		N:0			0		
320020	NOSE WHEEL								
32.150	9595602302	MOS		N:8			17-DEC-2014		
	1331	HRS/MSC	O/C	N:141:18			141:18		
	REF: AMM 32-40-02	AFL		N:153			153		
320022	LEFT MAIN LANDING GEAR WHEEL								
32.160	532.45.12.066	MOS					29-JAN-2018		
	2851	HRS/MSC	O/C				395:12		
	REF: AMM 32-40-01	AFL					393		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	9595601308	MOS					29-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C				395:12		
	REF: AMM 32-40-01	AFL					393		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320024	RIGHT MAIN LANDING GEAR WHEEL 532.45.12.066 2825 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				29-JAN-2018 395:12 393		
320025	SHIMMY DAMPER ASSY 5322012215 VLG690 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 7158S00325 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-AUG-2019 499:42 492		
320030	COPILOT LH BRAKE MASTER CYLINDER 9594751131 5854 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 9594751131 5858 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY 5322012249 VLG591 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320045	NOSE LANDING GEAR STRUT ASSY 5322012044 VLG1013 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320055	RIGHT SHOCK ABSORBER ASSY 5321012211 VLG1212 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320060	LH BRAKE ASSY								
32.050	9595601517 2677 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	9595601503 2807 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320066	OUTER LEFT WHEEL & COVER ASSY								
32.205	9595601503 2825 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG1211 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320085	RH BRAKE ASSY								
32.050	9595601517 2683 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	9595601503 2833 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320091	OUTER RIGHT WHEEL & COVER ASSY								
32.210	9595601503 2851 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
32.170	9733033116 4480 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
32.175	9733033116 4470 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
32.170	9733033116 4478 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH								
32.175	9733033116 4476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320140	INTERMEDIATE CABLE ASSY								
	959.56.01.816 00039 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320140	MAIN GEAR CABLE ASSY								
	959.56.01.814 00077 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320140	NOSE GEAR CABLE ASSY								
	959.56.01.815 00033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320145	EXTENSION GEAR EMERGENCY HANDLE								
	959.56.01.827 00027 REF: AMM 32-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320150	FRONT HIGH CURRENT RELAY								
	974.09.26.112 N843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320150	REAR HIGH CURRENT RELAY 974.09.26.112 N828 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320155	LEFT HAND SPRING PACK ASSY 532.34.12.120 875 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-FEB-2019 473:24 465		
320155	RIGHT HAND SPRING PACK ASSY 532.34.12.101 874 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-FEB-2019 473:24 465		
320160	MLG L/H WOW NLG UP SWITCH ASSY 532.69.21.026 1225 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
320160	MLG R/H WOW NLG UP SWITCH ASSY 532.69.21.026 1226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 33	LIGHTS								
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 17 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 17 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 17 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 17 REF: AMM 33-44-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
330005 33.080	DIM UNIT 9750215205 131757 REF: AMM 33-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330010 33.010	DE-ICE LIGHT ASSY 9728767111 2446947 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330025 33.040	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787337 140148-6-10 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330030 33.040	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787337 140148-6-11 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	9728787342 140447-13-3 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330045	RH WING POWER SUPPLY UNIT								
33.070	9728787179 140145-5-2 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	9728787343 140148-9-6 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330070	NOSE LANDING GEAR TAXI LIGHT								
33.090	9728769421 29951001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-DEC-2016 317 316		
330075	L/H 1X0005287-10 LANDING LIGHT								
33.090	9728769420 29948001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-DEC-2016 317 316		
330076	R/H 1X0005287-10 LANDING LIGHT								
33.110	9728769406 28971009 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-NOV-2015 239 245		
330085	LEFT HAND RECOGNITION LED LIGHT								
	972.87.69.407 140447-7-11 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
330085	RIGHT HAND RECOGNITION LED LIGHT								
	972.87.69.407 140447-7-12 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 34	NAVIGATION								
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 21	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
34-11/185 (s)	EXAMINE PITOT TUBE PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
34-11/186 (s)	EXAMINE STATIC PORTS PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
	REF: AMM 34-11-00								
34-11/343 34.565	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT	MOS HRS/MSC AFL	24	+10%/-10%			03-APR-2020 537:22 528	03-APR-2022	15-JUN-2022
	REF: AMM 34-11-12								
34-11/82 34.010	LEAK CHECK STATIC SYSTEM	MOS HRS/MSC AFL	24	+10%/-10%			03-APR-2020 537:22 528	03-APR-2022	15-JUN-2022
	REF: AMM 34-11-00								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/CFR	PERFORM LEAK CHECK OF STATIC SYSTEM (14 CFR 91.411)	MOS					03-APR-2014		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED)	MOS	24	+10%/-10%		-64	03-APR-2020	29-JAN-2022	10-APR-2022
34.560	REF: AMM 34-21-00	HRS/MSC					537:22		
		AFL					528		
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)	MOS	24	+10%/-10%		-107	03-APR-2020	17-DEC-2021	28-FEB-2022
34.570	REF: AMM 34-14-00	HRS/MSC					537:22		
		AFL					528		
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED)	MOS	24	+10%/-10%			03-APR-2020	03-APR-2022	15-JUN-2022
	REF: AMM 34-26-40	HRS/MSC					537:22		
		AFL					528		
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)	MOS	24	+10%/-10%			03-APR-2020	03-APR-2022	15-JUN-2022
34.050	REF: See Workcard	HRS/MSC					537:22		
		AFL					528		
+ 34-54/CFR	TEST/INSPECT NO. 1 TRANSPONDER SYSTEM (14 CFR 91.413)	MOS					03-APR-2014		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
+ 34-54/CFR	TEST/INSPECT NO. 2 TRANSPONDER SYSTEM (14 CFR 91.413)	MOS					03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	N/A				537:22		
		AFL					528		
34-CUS-01	PERFORM EGPWS DATABASE CHECK FOR UPDATE	MOS	12				03-APR-2020	03-APR-2021	
	REF:	HRS/MSC					537:22		
		AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340010	DME/IFF ANTENNA								
34.080	9848110240 261-110410 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340020	MARKER ANTENNA								
34.100	9848110260 1017836 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340055	WITH HARM FILTER,KN63 DME								
34.200	9859911101 36533 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340065	WX-RADAR RT UNIT								
34.360	9859911507 14491 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 7719 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-110409 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 KA44B-A92423 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340100	FRONT KA92 ANTENNA								
34.090	9859911200 49310594 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			15-DEC-2016 317 316		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340101	REAR KA92 GPS ANTENNA								
34.090	9859911200 49308247 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 18221 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340135	STANDBY MAGNETIC COMPASS								
34.130	9999880103 AT-1411 REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340140	RADOME								
34.420	9857900005 245 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-68999 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-69000 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 25976 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 24812 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911508 KRA405B-14724 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	9859918006 99577 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1625 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340255	AOA SENSOR LH UNIT								
34.330	9754421423 1535 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	9848110240 291-110426 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340270	LEFT PITOT STATIC TUBE								
34.535	PST305 A0261 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-2949 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-3269 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	9859911887 KMH920-B1629 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340310	NO. 2 KXP 2290 MODE S TRANSPONDER								
34.540	066-01198-0102 KXP2290A-2068 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				17-DEC-2014 141:18 153		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER								
34.540	066-01198-0102 KXP2290A-1859 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				17-DEC-2014 141:18 153		
340320	LH OAT SENSOR								
34.525	5341312025 04889 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340325	RH OAT SENSOR								
34.525	5341312025 04887 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT								
34.505	9859912245 KSG7200-B2258 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340355	LH NAV/WHITE ANTENNA								
	9848110280 10598 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
340357	RH NAV/WHITE ANTENNA								
	9848110280 10599 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341035	NO. 1 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-2135 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
341037	NO. 2 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-2136 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
341039	MAG-3100 MAGNETOMETER 9859003058 80483 REF: AMM 34-26-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
341040	PHASING COUPLER 9848110412 7698 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
341045	ESI-1000 STANDBY SYSTEM 9759611247 2038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER	35	OXYGEN							
35-10/187 (s)		CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528	
35-10/188 (s)		CHECK OXYGEN SYSTEM CONTENTS PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 29-JAN-2018 395:12 393	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: AMM 35-00-00	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
35-10/6	REAR FUSELAGE OXYGEN CYLINDER 895-06077 C12041059	MOS	180		O:3		29-MAY-2018 411:06	01-MAR-2027	
AIRWORTHINESS	REF: AMM 35-10-01 Manufacture Date: 01-MAR-2012	HRS/MSC AFL			O:0 O:0		414		
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER 895-06077 C12041059	MOS	60					01-JAN-2023 M	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL							
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)	MOS					19-JUL-2017		
	REF: AMM 35-00-00	HRS/MSC AFL	400	+10%/-10%			366:12 361	766:12	806:12
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS 35.010	MOS	36	+10%/-10%			03-APR-2020 537:22	03-APR-2023	21-JUL-2023
	REF: AMM 35-20-00	HRS/MSC AFL					528		
35-CUS-01	OXYGEN BOTTLE (AVOX SIL NO.SIL-35-114) REGULATOR PN SN-UNKNOWN	MOS	60		O:3		29-JAN-2018 395:12	16-OCT-2022 M	
OVERHAUL	REF:	HRS/MSC AFL					393		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210 B004974 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210 B005222 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	9738114401 1310 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350035	CONTR,3-POSITION,37071-03 VALVE								
35.030	9633211102 0290 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350050	OXYGEN GAGE ASSY								
35.060	5351212085 60217 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350055	OXYGEN PRESS TRANSDUCER								
35.070	9571201184 7960-11-414 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
350067	OXYGEN SHUT-OFF VALVE								
	957.12.12.232 000137783 REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

CHAPTER 45 CENTRAL MAINT SYSTEM



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: AMM 45-45-00	AFL					528		
CHAPTER 46 INFORMATION SYSTEMS									
46-26/320	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES								
	PKG 17	MOS	12	+10%/-10%		-64	03-APR-2020	29-JAN-2021	05-MAR-2021
		HRS/MSC	300	+10%/-10%			537:22	837:22	867:22
	REF: See Workcard	AFL					528		
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: AMM 46-30-02	AFL					528		
460105	WIRELESS DATA LOADING DEVICE								
	975.96.32.439	MOS					03-APR-2014		
	2051	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
CHAPTER 52 DOORS									
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 19	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	600	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 19	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	600	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS						PKG		
	PKG 19	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	600	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	600	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
		MOS						03-APR-2014	
52.070		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 52-10-00	AFL	42000					0	42000
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE								
		MOS						03-APR-2014	
52.100		HRS/MSC	32500					0	32500
	REF:	AFL	42000					0	42000
+ 52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE								
		MOS						03-APR-2014	
52.100		HRS/MSC	32500	+500/-500				0	32500 33000
	REF: AMM 52-00-01	AFL	42000	+500/-500				0	42000 42500
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN								
		MOS						03-APR-2014	
52.110		HRS/MSC	25000					0	25000
	REF:	AFL	30000					0	30000
+ 52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN								
		MOS						03-APR-2014	
52.110		HRS/MSC	25000	+500/-500				0	25000 25500
	REF: AMM 52-10-01	AFL	30000	+500/-500				0	30000 30500



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)	MOS					03-APR-2014		
	REF: AMM 52-10-06	HRS/MSC AFL	N/A				0 0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
52.010	REF: See Workcard	HRS/MSC AFL	4000	+10%/-10%			395:12 393	4395:12	4795:12
	MODERATE CORROSION ZONE								
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)	MOS	12	+10%/-10%			PKG		
	PKG 20	HRS/MSC AFL	1200	+10%/-10%			03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK	MOS	12	+10%/-10%			PKG		
	PKG 20	HRS/MSC AFL	1200	+10%/-10%			03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS					03-APR-2014		
52.080	REF: AMM 52-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
	AIRWORTHINESS								
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK	MOS	12	+10%/-10%			PKG		
	PKG 19	HRS/MSC AFL	600	+10%/-10%			03-APR-2020 537:22 528		
	REF: GENERIC NO REF								
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.	MOS	12	+10%/-10%			PKG		
	PKG 19	HRS/MSC AFL	600	+10%/-10%			03-APR-2020 537:22 528		
	REF: AMM 52-30-00								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	600	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS						03-APR-2014	
52.090		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000					0	42000
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
		MOS						03-APR-2014	
52.120		HRS/MSC	32500					0	32500
	REF:	AFL	42000					0	42000
+ 52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
		MOS						03-APR-2014	
52.120		HRS/MSC	32500	+500/-500				0	32500 33000
	REF: AMM 52-30-00	AFL	42000	+500/-500				0	42000 42500
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
		MOS						03-APR-2014	
52.130		HRS/MSC	25000					0	25000
	REF:	AFL	30000					0	30000
+ 52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
		MOS						03-APR-2014	
52.130		HRS/MSC	25000	+500/-500				0	25000 25500
	REF: AMM 52-30-01	AFL	30000	+500/-500				0	30000 30500
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS			N:0			03-APR-2014	
52.020	SN-UNKNOWN	HRS/MSC	13000		N:0			0	13000
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000		N:0			0	17000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
52.030		MOS	48	+10%/-10%		64	29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: See Workcard	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
	REF: AMM 52-70-00	HRS/MSC	1200	+10%/-10%			537:22		
		AFL					528		
520005	PASSENGER DOOR								
52.050	5520512007	MOS		N:0			03-APR-2014		
	1216E	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512013	MOS		N:0			03-APR-2014		
	1220E	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-30-01	AFL		N:0			0		
520015	EMERGENCY 6 SERIE EXIT								
52.060	5520512009	MOS		N:0			03-APR-2014		
	1220E	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-20-01	AFL		N:0			0		
CHAPTER 53	FUSELAGE								
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			537:22		
		AFL					528		
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 21	MOS	24	+10%/-10%			03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	2400	+10%/-10%			537:22		
		AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 21	MOS	24	+10%/-10%				03-APR-2020	
		HRS/MSC	2400	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%				03-APR-2020	
		HRS/MSC	2400	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: GENERIC NO REF	AFL						528	
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						03-APR-2014	
		HRS/MSC	25000					0	25000
AIRWORTHINESS	REF: GENERIC NO REF	AFL	30000					0	30000
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 20	MOS	12	+10%/-10%				03-APR-2020	
		HRS/MSC	1200	+10%/-10%				537:22	
	REF: AMM 53-20-02	AFL						528	
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION								
		MOS						03-APR-2014	
53.100		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 53-10-06	AFL	42000					0	42000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS								
53.110		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS								
53.120		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
53.130		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE								
53.140		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN								
53.150		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN								
53.160		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION								
53.180		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION								
53.190		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION								
53.200		MOS					03-APR-2014		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210		MOS					03-APR-2014		
	REF:	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210		MOS					03-APR-2014		
	REF: See Workcard	HRS/MSC	32500	+500/-500			0		32500
		AFL	42000	+500/-500			0		42000
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE								
53.010		MOS					03-APR-2014		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030		MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT, WITH INSULATION REMOVED)								
53.040		MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%		64	29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%		64	29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
34.575		MOS	12	+1m/-1m		-64	03-APR-2020	29-JAN-2021	28-FEB-2021
	REF: AMM 53-30-01	HRS/MSC					537:22		
		AFL					528		
530070	FUSELAGE AB 1003 TEIL1								
53.090	5530512116	MOS			N:0		03-APR-2014		
	1220E	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
CHAPTER 55 STABILIZERS									
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
AIRWORTHINESS	REF: GENERIC NO REF	MOS					03-APR-2014		
		HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
AIRWORTHINESS	REF: GENERIC NO REF	MOS					03-APR-2014		
		HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			537:22		
		AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 55-00-00	HRS/MSC AFL	1200	+10%/-10%			03-APR-2020 537:22 528		
55-10/415	HORIZONTAL STABILIZER PN	MOS		N:0			03-APR-2014		
55.090	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 55-10-01	AFL	30000	N:0			0	30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		64	29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			395:12 393	4395:12	4795:12
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		64	29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			395:12 393	4395:12	4795:12
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					03-APR-2014		
55.100		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 55-20-00	AFL	42000				0	42000	
+ 55-20/362	EXAMINE RIGHT WING ELEVATOR	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					03-APR-2014		
55.110		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0	42000	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
55.120		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
55-30/369	EXAMINE - VERTICAL STABILIZER								
55.130		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
		MOS					03-APR-2014		
55.140		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: See Workcard	AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
		MOS					03-APR-2014		
55.150		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-00-00	AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
		MOS					03-APR-2014		
55.160		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-30-02	AFL	42000				0		42000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
55.190		MOS					03-APR-2014		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
+ 55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
55.190		MOS					03-APR-2014		
		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 55-30-03	AFL	42000	+500/-500			0		42000 42500
55-40/373	EXAMINE - RUDDER								
55.170		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
55.180		MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200		MOS					03-APR-2014		
	REF:	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200		MOS					03-APR-2014		
		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 55-40-04	AFL	42000	+500/-500			0		42000 42500
55CUS01	SPECIAL INSPECTION FOR HORIZONTAL STABILIZER BOLTS P/N 555.10.12.139 REMOVAL AND INSPECTION FOR SIGNS OF CORROSION. CLEANING, CORROSION TREATMENT / REPLACEMENT OF BOLTS AS REQUIRED. INSTALLATION OF BOLTS AFTER INSPECTION								
		MOS					03-APR-2020		
	REF:	HRS/MSC	-				537:22		
		AFL					528		

CHAPTER 56 WINDOWS



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH PKG 17	MOS	12	+10%/-10%			PKG		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED	MOS					03-APR-2014		
56.020 AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	A/R				0 0		
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED	MOS					03-APR-2014		
	REF: AMM 56-00-00	HRS/MSC AFL	A/R				0 0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					03-APR-2014		
	9598110109 12340H9071 REF: See Workcard	HRS/MSC AFL	A/R				0 0 0		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					03-APR-2014		
	9598110110 12304H5292 REF: See Workcard	HRS/MSC AFL	A/R				0 0 0		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					03-APR-2014		
	9598110109 12340H9071 REF: GENERIC NO REF	HRS/MSC AFL	A/R				0 0 0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)	MOS					03-APR-2014		
	9598110110 12304H5292 REF: GENERIC NO REF	HRS/MSC AFL	A/R				0 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS								
56.100	REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500			03-APR-2014 0 0	03-APR-2024 11000	03-OCT-2024 11500
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED								
56.110 AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS								
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%			537:22 528		
560015	SIDE,LH WINDOW								
56.090	9598110111 12349H0113 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
560020	SIDE,RH WINDOW								
56.090	9598110112 12219H5891 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029 0001425560-004 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029 0001339798-001 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 0001448692-008 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 0001425560-012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 0001339801-007 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 0001448692-010 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 0001448692-004 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 0001339798-002 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 0001407318-012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 13114H4317 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010	9598110109 12340H9071 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
AIRWORTHINESS									



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
	9598110110	MOS		N:0			03-APR-2014		
56.010	12304H5292	HRS/MSC	O/C	N:0			0		
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
		MOS					03-APR-2014		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	27000				0		27000
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					03-APR-2014		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	27000				0		27000
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 17	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	300	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			03-APR-2020		
		HRS/MSC	2400	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 20	MOS	12	+10%/-10%			03-APR-2020		
		HRS/MSC	1200	+10%/-10%			537:22		
	REF: GENERIC NO REF	AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					03-APR-2014		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					03-APR-2014		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					03-APR-2014		
57.100		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0		39000
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					03-APR-2014		
57.110		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					03-APR-2014		
57.120		HRS/MSC	25000				0		25000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0		30000
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					03-APR-2014		
57.130		HRS/MSC	25000				0		25000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0		30000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					03-APR-2014		
57.140		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-05	AFL	30000				0	30000	
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					03-APR-2014		
57.150		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					03-APR-2014		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/412	EXAMINE - WING TIPS	MOS					03-APR-2014		
57.170		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF:	AFL	42000				0	42000	
+ 57-00/412	EXAMINE - WING TIPS	MOS					03-APR-2014		
57.170		HRS/MSC	32500	+500/-500			0	32500	33000
AIRWORTHINESS	REF: AMM 57-33-00	AFL	42000	+500/-500			0	42000	42500



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES								
57.180		MOS					03-APR-2014		
		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0	30000	30500
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES								
		MOS					03-APR-2014		
		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0	30000	30500
57-00/413	EDDY CURRENT INSPECTION - WING SKIN AROUND DRAIN HOLES								
57.180		MOS					03-APR-2014		
		HRS/MSC	25000				0	25000	
	REF:	AFL	30000				0	30000	
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					03-APR-2014		
		HRS/MSC	16000				0	16000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0	22500	
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					03-APR-2014		
		HRS/MSC	16000				0	16000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0	22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)								
57.020		MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%	64		29-JAN-2018	03-APR-2022	27-AUG-2022
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			395:12	4395:12	4795:12
		AFL					393		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040	REF: AMM 57-00-00	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500			03-APR-2014 0 0	03-APR-2024 11000	03-OCT-2024 11500
+ 57-60/393	EXAMINE - RIGHT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
57-60/393	EXAMINE -LEFT WING AILERON								
57.160	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190	REF:	MOS HRS/MSC AFL	32500 42000				03-APR-2014 0 0	32500 42000	
+ 57-60/411	EXAMINE - AILERON TRIM TAB								
57.190	REF: AMM 57-60-04	MOS HRS/MSC AFL	32500 42000	+500/-500 +500/-500			03-APR-2014 0 0	32500 42000	33000 42500
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512017 3224E REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512018 3224E REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
570050	L/H WING								
57.080	5570512139 1220E REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570055	R/H WING								
57.090	5570512140 1220E REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
CHAPTER 61 PROPELLERS/PROPULSORS									
61-10/37	PROPELLER								
61.010 OVERHAUL	HC-E5A-3A SA542 REF: See Workcard	MOS HRS/MSC AFL	72 4000	N:2 N:0 N:0			03-APR-2020 537:22 528	03-FEB-2026 4537:22	
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			03-APR-2020 537:22 528		
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E5A-3A SA542 REF: See Workcard	MOS HRS/MSC AFL	PP/C	N:0			03-APR-2020 537:22 528		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
OVERHAUL	3049558-01 18603588 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		12-DEC-2013 0 0	(3500) 3492	4000
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
OVERHAUL	3037685 18622991 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		12-DEC-2013 0 0	(3500) 3492	4000
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA542 Part # HC-E5A-3A									
+ 610004 (s)	NO. 1 PROPELLER - INSPECTION OF THE DE-ICE SYSTEM						PKG		
	PKG 19	MOS HRS/MSC	12 600	+10%/-10% +10%/-10%			03-MAR-2020 0		
	REF: MM 30-61-80								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	36 3000				03-MAR-2020 0	03-MAR-2023 (3000) 3539:15	
	OVERHAUL								
	REF: GENERIC NO REF								
+ 610020	NO. 1 PROPELLER - ACCOMPLISH A DETAIL INSPECTION	MOS HRS/MSC	12 400	+10%/-10% +10%/-10%			03-MAR-2020 0	03-MAR-2021 (400) 939:15	09-APR-2021 440
	REF: POM 61-00-47								
+ 610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 400				03-MAR-2020 0	03-MAR-2021 (400) 939:15	
	REF: POM 61-00-47								
+ 610050	NO. 1 PROPELLER - INSPECT BLADE USING COIN-TAP	MOS HRS/MSC	1200	+10%/-10%			03-MAR-2020 0	(1200) 1739:15	1320
	REF: RMM 61-13-70								
+ 610060	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP	MOS HRS/MSC	600	+10%/-10%			03-MAR-2020 0	(600) 1139:15	660
	REF: RMM 61-13-70								
611501	NO. 1 PROPELLER - NO. 1 BLADE NC10245B C4358	MOS HRS/MSC	O/C				30-MAR-2020 0		
	REF: GENERIC NO REF								
611502	NO. 1 PROPELLER - NO. 2 BLADE NC10245B C4359	MOS HRS/MSC	O/C				30-MAR-2020 0		
	REF: GENERIC NO REF								
611503	NO. 1 PROPELLER - NO. 3 BLADE NC10245B C4362	MOS HRS/MSC	O/C				30-MAR-2020 0		
	REF: GENERIC NO REF								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
611504	NO. 1 PROPELLER - NO. 4 BLADE NC10245B C4363 REF: GENERIC NO REF	MOS HRS/MSC	O/C				30-MAR-2020 0			
611505	NO. 1 PROPELLER - NO. 5 BLADE NC10245B C4365 REF: GENERIC NO REF	MOS HRS/MSC	O/C				30-MAR-2020 0			
CHAPTER 71 POWER PLANT										
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG			
71.010	PKG 19 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-APR-2020 537:22 528			
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG			
	PKG 19 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-APR-2020 537:22 528			
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG			
71.030	PKG 19 REF: AMM 71-00-03	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			03-APR-2020 537:22 528			
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME									
71.050	PN SN-UNKNOWN REF: AMM 71-00-05	MOS HRS/MSC AFL	20000 27000		N:0 N:0 N:0		03-APR-2014 0 0	20000 27000		
AIRWORTHINESS										
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS									
71.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	11000				03-APR-2014 0 0	11000		
AIRWORTHINESS										



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS. PKG 15 ,16,17,18,19,20,21 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 03-APR-2020 537:22 528		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. PKG 21 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
71-00/327	ENGINE (POST SB 04-009) MOUNTING FRAME PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		03-APR-2014 0 0	25000 30000	
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 7528 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		03-APR-2014 0 0	3500	3850



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.064	9448121409	MOS		N:0			03-APR-2014		
OVERHAUL	7533	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
71.061	9448121409	MOS		N:0			03-APR-2014		
OVERHAUL	7532	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409	MOS		N:0			03-APR-2014		
OVERHAUL	7525	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	9448121409	MOS		N:0			03-APR-2014		
OVERHAUL	7521	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
71.130		MOS					03-APR-2014		
AIRWORTHINESS		HRS/MSC	26600				0	26600	
	REF: AMM 71-00-05	AFL	35000				0	35000	
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				537:22		
		AFL					528		
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				537:22		
		AFL					528		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				537:22		
		AFL					528		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710050	(WELDED) ENGINE MOUNT								
71.120	5712012036 1270 REF: AMM 71-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P PCE-RY0431 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
71-00/103A	NO. 1 ENGINE - PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH								
	REF:	MOS HRS/MSC ENC	12 300				03-APR-2020 545:22 539	03-APR-2021 (845:22) 837:22	
71-00/104A	NO. 1 ENGINE - PERFORM COMPRESSOR DESALINATION WASH								
	REF:	MOS HRS/MSC ENC	12 300				03-APR-2020 545:22 539	03-APR-2021 (845:22) 837:22	
71-00/105A	NO. 1 ENGINE - PERFORM TURBINE WASH								
	REF:	MOS HRS/MSC ENC	12 300				03-APR-2020 545:22 539	03-APR-2021 (845:22) 837:22	
710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			12-DEC-2013 0 0	(3500) 3492	3700
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 0 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710021	NO. 1 ENGINE - HOT SECTION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			12-DEC-2013 0 0	(1750) 1742	2000
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	400	+10%/-10%			16-DEC-2016 325 321	(725) 717	765
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				12-DEC-2013 0 0		
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM) REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				29-JAN-2018 403:12 398		
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION PKG 0 REF: EMM 71-00-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				29-JAN-2018 403:12 398		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE OVERHAUL	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	3500	+500	N:0 N:0 O:0 N:0	12-DEC-2013 0 0	(3500) 3492	4000



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				03-APR-2020 545:22 539		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				03-APR-2020 545:22 539		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
+ 720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				12-DEC-2013 0 0		
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS REF: EMM 72-11-00	MOS HRS/MSC ENC	A/R				20-FEB-2019 481:24 470		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
	REF: See Workcard								
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
	REF: EMM 72-20-00								
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 TXA1C8456	MOS HRS/MSC ENC			N:0 N:0 N:0		12-DEC-2013 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 23996	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA489396	MOS HRS/MSC ENC			N:0 N:0 N:0		12-DEC-2013 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 23996	
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
	REF: EMM 72-30-04								
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 TXA1C9033	MOS HRS/MSC ENC			N:0 N:0 N:0		12-DEC-2013 0 0		
LIFE LIMIT	REF: GENERIC NO REF		24000					(24000) 23996	
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 0	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
	REF: See Workcard								



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAC000Y839	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 23996	
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 TXA1C8907	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 23996	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 TXA1D0042	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 23996	
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION REF: See Workcard	MOS HRS/MSC ENC	A/R				12-DEC-2013 0 0		
	UNSCHEDULED MAINTENANCE CHECK								
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 YUAA012A589	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	N:0			0	(8000) 7996	
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000				12-DEC-2013 0 0	(5000) 4992	
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 0 REF: EMM 72-50-05	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A0038PM2	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14996	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 A00384X3	MOS HRS/MSC		N:0 N:0			12-DEC-2013 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14996	
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN	MOS HRS/MSC	3500	+500 N:0			12-DEC-2013 0	(3500) 3492	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		
726050 (s)	NO. 1 ENGINE - INSPECTION/CHECK FOR OIL LEAKS AT PROP SHAFT SEAL PKG 0	MOS HRS/MSC	100				PKG 03-APR-2020 545:22		
	REF:	ENC					539		
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP 3040760 012143	MOS HRS/MSC	3500				12-DEC-2013 0	(3500) 3492	
OVERHAUL	REF: EMM 73-10-02	ENC		N:0			0		
731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS HRS/MSC	N/A				16-DEC-2016 325		
	REF: See Workcard	ENC					321		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS HRS/MSC	400	+10%/-10%			16-DEC-2016 325	(725) 717	765
	REF: EMM 73-11-05	ENC					321		
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51314	MOS HRS/MSC	3500	+500			12-DEC-2013 0	(3500) 3492	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				12-DEC-2013 0 0		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 012143 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			20-FEB-2019 481:24 470	(1081:24) 1073:24	1141:24
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 012143 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				12-DEC-2013 0 0		
731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				12-DEC-2013 0 0		
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 9682011430 SN-UNKNOWN REPLACE REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-NOV-2015 247 250	(847) 839	907



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA46313 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		12-DEC-2013 0 0	(3500) 3492	4000
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			03-APR-2020 545:22 539	(845:22) 837:22	875:22
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0046 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		12-DEC-2013 0 0	(3500) 3492	4000
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
731090 OVERHAUL	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-07 18617496 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		12-DEC-2013 0 0	(3500) 3492	4000
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
731095 LIFE LIMIT	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	4000		N:0 N:0 N:0		12-DEC-2013 0 0	(4000) 3992	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539	(845:22) 837:22	875:22
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 9682011430 SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T	N:0			24-NOV-2015 247 250		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			03-APR-2020 545:22 539	(1445:22) 1437:22	1535:22
733050	NO. 1 ENGINE - AFT FUEL DRAIN VALVE 1155507209 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:8 N:0 N:0			18-MAY-2016 283 287		
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539	(845:22) 837:22	875:22

CHAPTER 74 IGNITION



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 17	MOS	12	+10%/-10%			PKG		
	REF: AMM 74-00-00	HRS/MSC AFL	300	+10%/-10%			03-APR-2020 537:22 528		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01

740010	NO. 1 ENGINE - IGNITION EXCITER 3035889	MOS		N:0			12-DEC-2013		
	NNA13040083	HRS/MSC	3500	+500	N:0		0	(3500) 3492	4000
	REF: EMM 74-10-00	ENC		N:0			0		

740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION	MOS					20-FEB-2019		
	REF: EMM 74-10-00	HRS/MSC	400	+10%/-10%			481:24	(881:24) 873:24	921:24
		ENC					470		

740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION	MOS					20-FEB-2019		
	REF: EMM 74-20-00	HRS/MSC	400	+10%/-10%			481:24	(881:24) 873:24	921:24
		ENC					470		

742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION	MOS					20-FEB-2019		
	REF: EMM 74-20-00	HRS/MSC	400	+10%/-10%			481:24	(881:24) 873:24	921:24
		ENC					470		

CHAPTER 75 AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01	MOS		N:0			12-DEC-2013		
	AHX1000318	HRS/MSC	3500	+500	N:0		0	(3500) 3492	4000
	REF: EMM 75-30-00	ENC		N:0			0		

CHAPTER 76 ENGINE CONTROLS

76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 19	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			03-APR-2020 537:22 528		
		AFL							



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 16 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 29-JAN-2018 395:12 393		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 03-APR-2020 537:22 528		
76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+10%/-10% +10%/-10%	-64		03-APR-2020 537:22 528	29-JAN-2021 3537:22	05-MAR-2021 3837:22
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 9419411417 20104877 REF: AMM 76-20-00	MOS HRS/MSC AFL	O/C				03-APR-2014 0 0		
760020 76.030	CONDITION CABLE ASSY. 9419411418 20104889 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-APR-2014 0 0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419 20104887 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

ENGINE NO. 1	Model : PT6A-67P	Serial # PCE-RY0431	Part # 3072955-01
761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES		
		MOS HRS/MSC ENC	300 +10%/-10%
	REF: EMM 72-00-00		
			20-FEB-2019 481:24 470
			(781:24) 773:24 811:24

CHAPTER 77 ENGINE INDICATING

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	9752115206 7987-1-248 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		
770025	DIFFERENTIAL PRESSURE TRANSDUCER								
	9752115219 3952677 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2014 0 0		

ENGINE NO. 1	Model : PT6A-67P	Serial # PCE-RY0431	Part # 3072955-01
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS		
	3043825-01 NRA002202 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C
			N:0 N:0 N:0
			12-DEC-2013 0 0

CHAPTER 78 EXHAUST

78-00/214 (s)	EXAMINE EXHAUST STUBS							PKG
	PKG 17	MOS	12	+10%/-10%			03-APR-2020	
		HRS/MSC	300	+10%/-10%			537:22	
	REF: GENERIC NO REF	AFL					528	

CHAPTER 79 OIL

79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK							PKG
	PKG 19	MOS	12	+10%/-10%			03-APR-2020	
		HRS/MSC	600	+10%/-10%			537:22	
	REF: AMM 79-30-06	AFL					528	



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT PKG 20	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			537:22 528		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 17	MOS	12	+10%/-10%			PKG 03-APR-2020		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%			537:22 528		
79-20/43	OIL COOLER 9683214102	MOS					03-APR-2014		
79.010	T1445	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
OVERHAUL	REF: AMM 79-20-02	AFL			N:0		0		
790005	TEMPERATURE BULB 9751120101	MOS			N:0		03-APR-2014		
79.020	192288	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
790020	PRESSURE,GAGE SWITCH 9738114305	MOS			N:0		03-APR-2014		
79.030	1358	HRS/MSC	O/C		N:0		0		
	REF: AMM 79-30-04	AFL			N:0		0		
790025	THERMAL ACTUATOR 9787301002	MOS			N:0		03-APR-2014		
79.040	1540	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0431 Part # 3072955-01									
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					12-DEC-2013		
		HRS/MSC	A/R				0		
DISCARD	REF: GENERIC NO REF	ENC					0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+30d/-10% +10%/-10%			03-APR-2020 545:22 539	03-APR-2021 (845:22) 837:22	03-MAY-2021 875:22
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 600	+1m/-1m +10%/-10%	-64		03-APR-2020 545:22 539	29-JAN-2021 (1145:22) 1137:22	28-FEB-2021 1205:22
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT REF: EMM 79-20-02	MOS HRS/MSC ENC	900	+10%/-10%			12-DEC-2013 0 0	(900) 892	990
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN REF: EMM 79-20-02	MOS HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539	(845:22) 837:22	875:22
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN REF: EMM 72-60-00	MOS HRS/MSC ENC	1000	+10%/-10%			12-DEC-2013 0 0	(1000) 992	1100
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE REF: EMM 79-20-02	MOS HRS/MSC ENC	N/A				17-DEC-2014 149:18 158		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				12-DEC-2013 0 0		
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 03-APR-2020 545:22 539		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			03-APR-2020 545:22 539		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 9752115214	MOS						12-DEC-2013	
	6688-6-234	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
CHAPTER 91 -									
910015	KBT 300 TTP BUS RES, A-157 TERMINAL 9859912117	MOS							
90.015	KBT300-2961	HRS/MSC	O/C				03-APR-2014 0		
	REF: GENERIC NO REF	AFL					0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL 9859912117	MOS							
90.025	KBT300-3005	HRS/MSC	O/C				03-APR-2014 0		
	REF: GENERIC NO REF	AFL					0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL 9859912117	MOS							
90.020	KBT300-3002	HRS/MSC	O/C				03-APR-2014 0		
	REF: GENERIC NO REF	AFL					0		
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX 9740338144	MOS							
90.030	741	HRS/MSC	O/C				03-APR-2014 0		
	REF: GENERIC NO REF	AFL					0		
910035	CO-PILOT RIGHT HD POWER, FE1549R JUNCTION BOX 9740338145	MOS							
90.030	620	HRS/MSC	O/C				03-APR-2014 0		
	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1467 (T7-DUD): 607 HRS, 606 AFL as of 16-Oct-2020

Owner/Operator: FLY 7 EXECUTIVE AVIATION SA

Report Date: 26-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
	9859912117	MOS		N:0			03-APR-2014		
90.010	KBT300-2983	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		