

**OWNER:** JETFLY AVIATION SA  
**ADDRESS:** 11 RUE JEAN FISCHBACH  
 LEUDELANGE L-3372  
**PHONE:** +352 26 19 36 36  
**FAX:**

**OPERATOR:** JETFLY AVIATION SA  
**ADDRESS:** 11 RUE JEAN FISCHBACH  
 LEUDELANGE L-3372  
**PHONE:** +352 26 19 36 36  
**FAX:**

**ANALYST:** ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)  
**EMAIL:** ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 1008/LX-TAI      **MODEL:** PC-12/47E      **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 30-APR-2008	5077:05 A/C HRS	as of 19-NOV-2020	A/C HRS	as of ___/___/___
	4428 AFL	as of 19-NOV-2020	AFL	as of ___/___/___
	1424:24 ACH	as of 24-APR-2020	ACH	as of ___/___/___
	4287 FLTS	as of 19-NOV-2020	FLTS	as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** PCE-RY0008/3072955-01      **MODEL:** PT6A-67P      **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 29-MAY-2018	LAST ACTUALS		CURRENT ACTUAL	
3830:20 ENG. HRS      3950:50 A/C HRS	4956:35 ENG. HRS	as of 19-NOV-2020	ENG. HRS	as of ___/___/___
3310 ENC	4298 ENC	as of 19-NOV-2020	ENC	as of ___/___/___

**PROPELLER NOSERIAL/PART:** KX1250/HC-E4A-3D/E10477SK      **MODEL:** HC-E4A-3D      **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 24-APR-2020	LAST ACTUALS		CURRENT ACTUAL	
3380:55 PROP HRS      4827:05 A/C HRS	3630:55 PROP HRS	as of 19-NOV-2020	PROP HRS	as of ___/___/___



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>								
05200A	JOB SET UP / CLOSE UP PACKAGE								
	PKG 1 in PKG 3,5,6,7,8,9	MOS					24-APR-2020	PKG	
	REF: AMM 05-20-00	HRS/MSC AFL	A/R				4827:05 4223		
05401A	300 HOUR INSPECTION								
	PKG 5	MOS					24-APR-2020		
	REF: AMM 05-40-01	HRS/MSC AFL	300				4827:05 4223	5127:05	5157:05
05402A	300 HOUR OR 12 MONTHS INSPECTION								
	PKG 3	MOS	12				24-APR-2020	24-APR-2021	24-MAY-2021
	REF: AMM 05-40-01	HRS/MSC AFL	300				4827:05 4223	5127:05	5157:05
05403A	600 HOUR INSPECTION								
	PKG 6	MOS					24-APR-2020		
	REF: AMM 05-40-01	HRS/MSC AFL	600/-				4827:05 4223	5427:05	5457:05
05404A	600 HOUR OR 12 MONTHS INSPECTION								
	PKG 7	MOS	12				24-APR-2020	24-APR-2021	24-MAY-2021
	REF: AMM 05-40-01	HRS/MSC AFL	600/-				4827:05 4223	5427:05	5457:05



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTH INSPECTION								
	PKG 8	MOS	12				24-APR-2020	<b>24-APR-2021</b>	24-MAY-2021
		HRS/MSC	1200/-				4827:05	<b>6027:05</b>	6057:05
	REF: AMM 05-40-01	AFL					4223		
05406A	2400 HOUR OR 24 MONTHS INSPECTION								
	PKG 9	MOS	24				25-FEB-2019	<b>25-FEB-2021</b>	25-MAR-2021
		HRS/MSC	2400				4381:45	<b>6781:45</b>	6841:45
	REF: AMM 05-40-01	AFL					3818		
<b>ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0008 Part # 3072955-01</b>									
057010	NO. 1 ENGINE - MINOR INSPECTION								
	PKG 0	MOS					24-APR-2020		
		HRS/MSC	300/-				4706:35	<b>(5006:35) 5127:05</b>	5036:35
	REF: See Workcard	ENC					4093		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED PKG 1 ,3,5,6,7,8,9 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH PKG 1 ,3,5,6,7,8,9 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION PKG 1 ,3,5,6,7,8,9 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02300 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL <b>REF:</b>	MOS HRS/MSC AFL	-				23-SEP-2020 5028:40 4398		
00JFL6.1	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 6 AMDT 10 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL <b>REF:</b>	MOS HRS/MSC AFL	-				09-AUG-2019 4692:25 4111		
00JFL6.11	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 6 AMDT 11 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL <b>REF:</b>	MOS HRS/MSC AFL	-				24-APR-2020 4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL67	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 6 AMDT 7 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						27-SEP-2018	
	REF:	HRS/MSC -						4242	
		AFL						3696	
00JFL68	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 6 AMDT 8 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						25-FEB-2019	
	REF:	HRS/MSC -						4381:45	
		AFL						3818	
00JFL7.0	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 7 AMDT 0 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL	MOS						27-JUL-2020	
	REF:	HRS/MSC -						4940:25	
		AFL						4324	
00JFL7.1	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 7 AMDT 1 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION	MOS						01-SEP-2020	
	REF:	HRS/MSC -						4992:40	
		AFL						4366	
P47E-111209	REVIEW AMM PC12/47E CHAPTER 4 & CHAPTER 5 REVISION 6 - CAMP CHANGE FORM	MOS						(EBT)	
05.150	REQUIREMENT CHANGE FORMS	HRS/MSC -							
	REF: RCF P47E	AFL							
P47E-120202	REVIEW PC-12/47E AMM REVISION 7 - CAMP CHANGE FORM	MOS						(EBT)	
	REQUIREMENT CHANGE FORMS	HRS/MSC -							
	REF: RCF P47E	AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-120322	REVIEW PC-12/47E AMM REVISION 8 - CAMP CHANGE FORM	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC - AFL							
P47E-130309	REVIEW PILATUS PC12/47E AMM CHAPTER 4 & 5 REVISION 9 - CAMP CHANGE FORM	MOS					06-MAY-2013		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC - AFL							
P47E-130805	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS					05-AUG-2013		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b>	HRS/MSC - AFL							
P47E-140305	REVIEW PC12/47E CHAPTER 4 & 5 REVISION NO. 10 - SUMMARY CHANGE FORM	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC - AFL							
P47E-140401	REVIEW PC12/47E CHAPTER 4 TR 04-02 - CAMP CHANGE FORM	MOS					04-APR-2014		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC - AFL							
P47E-140731	REVIEW 12-B-AM-00-00-00-I, REVISION 11, DATED MAY 22, 2014 CAMP REQUIREMENT CHANGE FORM	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b> RCF P47E	HRS/MSC - AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-150226	REVIEW 12-B-AM-00-00-00-I, 02300, REVISION 12, DATED 13 JAN 2015 RCF							09-SEP-2015	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
P47E-150923	REVIEW PILATUS PC-12/47E (MSN-1001-UP) AIRCRAFT MAINTENANCE MANUAL REVISION 13, DATED 18-AUGUST-2015-RCF								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
P47E-160106	REVIEW PC-12/47E, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 (DOCUMENT NUMBER 02300, 12-B-AM-00-00-00-I) REVISION 14, DATED 11/06/15 - CORRECTED VERSION-CAMP CHANGE FORM							04-MAY-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15							23-NOV-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF:</b>	MOS HRS/MSC - AFL							
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16							08-FEB-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
P47E-170719	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 17							11-SEP-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04	MOS						22-FEB-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18	MOS						08-JUN-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19	MOS						26-MAR-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05	MOS						26-MAR-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS						26-MAR-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS						24-JUL-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	HRS/MSC - AFL							





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22							20-APR-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23							12-AUG-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P47E</b>	MOS HRS/MSC - AFL							
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01</b>									
E072-140908	NO. 1 ENGINE - REVIEW PWC, PT6A-67B/-67P ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0 DATED JUL 07/2014							09-SEP-2015	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-150226	NO. 1 ENGINE - REVIEW PWC, PT6A-67B / -67P, (P/N 3038336) ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN 12/2015 RCF							(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-150404	NO. 1 ENGINE - REVIEW PWC, PT6A-72-14002 REVISION NO. 22 DATED NOV 16/2012 RCF							(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0							09-SEP-2015	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25	MOS						15-JUL-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0	MOS						03-JUN-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26	MOS						01-FEB-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1	MOS						31-JAN-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						07-MAR-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						07-MAR-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0	MOS						16-JUN-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1	MOS					04-SEP-2017		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072-170818</b>	HRS/MSC - ENC							
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0	MOS					30-APR-2008		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC					0 0		
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS					26-MAR-2019		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS					26-MAR-2019		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS					26-MAR-2019		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS						13-JAN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS						23-APR-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS						10-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
<b>PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1250 Part # HC-E4A-3D/E10477SK</b>									
P019-150423	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF	MOS					10-SEP-2015		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -					729		
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					30-NOV-2015		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS					31-JAN-2017		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS						16-SEP-2016	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS						22-FEB-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS						13-JAN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-200301	NO. 1 PROPELLER - REVIEW	PROPELLER ICE PROTECTION SYSTEM MANUAL (MANUAL 180) REVISION 32							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200501	NO. 1 PROPELLER - REVIEW	HC-E4A-3 POM 149 REV 26							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200501-1	NO. 1 PROPELLER - REVIEW	HC-E4A-3 POM 147 REV 16							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200701	NO. 1 PROPELLER - REVIEW	HC-E4A-3 POM 149 REV 27							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200801	NO. 1 PROPELLER - REVIEW	PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 33							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P019</b>	HRS/MSC -							
P019-200901	NO. 1 PROPELLER - REVIEW	HC-E4A-3 POM 147 REV 17							
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: See Workcard</b>	HRS/MSC -							





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

P019-200901-1 NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 34

MOS (EBT)  
HRS/MSC -

**REQUIREMENT CHANGE  
FORMS**

REF: RCF P019

NEW REQUIREMENT ADDED ON 22-SEP-2020 (EFFECTIVE: 01-SEP-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.

## CHAPTER 04 LIMITATIONS

040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	25000	N:0			0		25000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	30000	N:0			0		30000

040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

## CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-01	UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS					30-APR-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		

05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS								
		MOS					30-APR-2008		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER PROPELLER SUDDEN STOPPAGE OR IMPACT	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDANCE	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					30-APR-2008		
	REF: AMM 05-10-30	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					30-APR-2008		
	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
05JFL11	- AIRWORTHINESS REVIEW CERTIFICATE <b>TRACKED ITEM</b>	MOS					25-JUL-2020	<b>02-AUG-2021 M</b>	
	REF:	HRS/MSC	DUE				4940:30		
		AFL					4324		
05JFL12	- CERTIFICATE OF REGISTRATION	MOS							
	REF:	HRS/MSC	A/R						
		AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05JFL13	- NOISE CERTIFICATE	MOS HRS/MSC AFL	A/R						
	REF:	AFL							
05JFL14	- AIRCRAFT STATION LICENCE	MOS HRS/MSC AFL	DUE				16-NOV-2018	31-DEC-2021	M
	REF:	AFL							
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING	MOS HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223	5127:05	5157:05
	REF:	AFL							

## CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
	PKG 1 ,3,5,6,7,8,9	AFL							
	REF: AMM 06-20-00	AFL							
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
	PKG 1 ,3,5,6,7,8,9	AFL							
	REF: AMM 06-20-00	AFL							
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR.	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
	PKG 1 ,3,5,6,7,8,9	AFL							
	REF: AMM 06-20-00	AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOIN THE FOLLOWING PANELS: 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						24-APR-2020	
	REF: GENERIC NO REF	HRS/MSC	A/R					4827:05	
		AFL						4223	
<b>CHAPTER 07 LIFTING AND SHORING</b>									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						24-APR-2020	
	REF: AMM 07-10-00	HRS/MSC	A/R					4827:05	
		AFL						4223	
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						24-APR-2020	
	REF: AMM 07-10-00	HRS/MSC	A/R					4827:05	
		AFL						4223	
<b>CHAPTER 08 LEVELING AND WEIGHING</b>									
08JFL01	WEIGHT AND BALANCE								
		MOS	60	+1m/-1m		27		03-MAR-2016	30-MAR-2021 30-APR-2021
	REF:	HRS/MSC						2977:20	
		AFL						2611	
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED(FILL FORM W&B IN, POH SECTION 6)								
		MOS						24-APR-2020	
	REF:	HRS/MSC	A/R					4827:05	
		AFL						4223	
<b>CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV</b>									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 3	MOS	12	+10%/-10%				24-APR-2020	
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%				4827:05	
		AFL						4223	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 11</b>									
<b>PLACARDS AND MARKINGS</b>									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: See Workcard	AFL					4223		
<b>CHAPTER 12</b>									
<b>SERVICING</b>									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	REF: AMM 12-20-01	AFL					4223		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	REF: AMM 12-20-02	AFL					4223		
12-20/126 (s)	CLEAN COCKPIT AND CABIN						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	REF: AMM 12-20-03	AFL					4223		
<b>CHAPTER 20</b>									
<b>STANDARD PRACTICES - AIRFRAME</b>									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
		MOS	12	+10%/-10%			24-APR-2020	24-APR-2021	30-MAY-2021
20.010		HRS/MSC					4827:05		
	REF: AMM 20-40-00	AFL					4223		
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
		MOS	6	+10%/-10%			24-APR-2020	24-OCT-2020	11-NOV-2020
20.011		HRS/MSC	300	+10%/-10%			4827:05	5127:05	5157:05
	REF: AMM 20-40-00	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20JFL01	PERFORMED DENTS AND BUCKLES CHARTS	MOS					24-APR-2020		
	REF:	HRS/MSC	300	+10%/-10%			4827:05	5127:05	5157:05
		AFL					4223		
<b>CHAPTER 21 AIR CONDITIONING</b>									
21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
	REF: GENERIC NO REF	HRS/MSC	2400	+10%/-10%			4381:45		
		AFL					3818		
21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK								
		MOS	12	+10%/-10%			24-APR-2020	24-APR-2021	30-MAY-2021
	ALI	HRS/MSC	3000				4827:05	7827:05	
	REF: GENERIC NO REF	AFL					4223		
21-30/314	REMOVE/CLEAN PRESSURIZATION SAFETY VALVE								
	PN	MOS	24	+10%/-10%	19		24-APR-2020	13-MAY-2022	25-JUL-2022
21.030	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%			4827:05	7827:05	8127:05
	REF: AMM 21-30-02	AFL					4223		
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
		MOS	12	+10%/-10%			24-APR-2020	24-APR-2021	30-MAY-2021
21.045		HRS/MSC	3000				4827:05	7827:05	
ALI	REF: AMM 21-30-00	AFL					4223		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
	PN	MOS	24	+10%/-10%	19		24-APR-2020	13-MAY-2022	25-JUL-2022
21.040	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%			4827:05	7827:05	8127:05
	REF: AMM 21-30-00	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/463	OPERATIONAL TEST CABIN PRESSURIZATION DUMP CONTROL	MOS					30-APR-2008		
	REF: AMM 21-30-00	HRS/MSC	N/A				0		
		AFL					0		
21-30/464	OPERATIONAL TEST CABIN PRESSURIZATION MANUAL CONTROL	MOS					30-APR-2008		
	REF: AMM 21-30-00	HRS/MSC	N/A				0		
		AFL					0		
21-30/465	FUNCTIONAL TEST CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE	MOS					30-APR-2008		
	REF: AMM 21-30-00	HRS/MSC	N/A				0		
		AFL					0		
21-30/466	CHECK CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND	MOS					30-APR-2008		
	REF: AMM 21-30-02	HRS/MSC	N/A				0		
		AFL					0		
21-30/467	EXAMINE CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE	MOS					30-APR-2008		
	REF: AMM 21-30-05	HRS/MSC	N/A				0		
		AFL					0		
21-30/468	FUNCTIONAL TEST CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION	MOS					30-APR-2008		
	REF: AMM 21-30-00	HRS/MSC	N/A				0		
		AFL					0		
21-30/469	FUNCTIONAL TEST CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING	MOS					30-APR-2008		
	REF: AMM 21-30-00	HRS/MSC	N/A				0		
		AFL					0		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH						PKG		
21.140	PKG 8 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
21-40/331	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH								
21.150	9696781507 PKG 8 529418 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>6027:05</b>	30-MAY-2021 6147:05
21-40/50	CLEAN WATER SEPARATOR CONDENSER								
21.080	5214112060 PKG 8 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>6027:05</b>	30-MAY-2021 6147:05
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
21.130	973.81.32.216 0527 REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	-4		29-MAY-2018 3950:50 3440	<b>25-MAY-2023</b> <b>8750:50</b>	25-NOV-2023 9230:50
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
21.120	9738132214 55 REF: AMM 21-60-05	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	-4		29-MAY-2018 3950:50 3440	<b>25-MAY-2023</b> <b>8750:50</b>	25-NOV-2023 9230:50
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 6 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			24-APR-2020 4827:05 4223		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 6 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			24-APR-2020 4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) 9599022102 883 REF: See Workcard	MOS HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223	5127:05	5157:05
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) 9599022102 883 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	N/A				30-APR-2008 0 0		
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) 9599022102 883 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH	N/A				30-APR-2008 0 0		
21-50/58  21.110	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) 9599022102 883 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	500	+10%/-10%			04-AUG-2017 3689:40 3213 1069:30	1569:30	1619:30
21-50/59  21.100	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED 9599022102 883 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH	500	+10%/-10%	-35:30		04-AUG-2017 3689:40 3213 1069:30	1534	1584



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210005	OVERPRESSURE SWITCH								
21.340	9738115105 1922 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-AUG-2020 4979:25 4358		
210010	REFRIGERATION PACK								
21.255	9599020111 1453 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1433 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 1633 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1434 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 1426 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210035	WATER SEPARATOR ASSY								
21.220	5214112060 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:130 N:4381:45 N:3818			25-FEB-2019 4381:45 3818		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210040	TEMPCONTROL VALVE								
	9599020136	MOS		N:0			30-APR-2008		
21.310	1421	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-60-02	AFL		N:0			0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
	9599022102	MOS		N:0			30-APR-2008		
21.380	883	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-50-01	AFL		N:0			0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	959.90.22.126	MOS		N:0			04-AUG-2017		
	6262	HRS/MSC	O/C	N:0			3689:40		
	REF: AMM 21-50-01	AFL		N:0			3213		
210050	CENTER EVAPORATOR MODULE ASSY								
	9599022121	MOS		N:0			30-APR-2008		
21.200	282	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
	9599022119	MOS		N:0			30-APR-2008		
21.210	290	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
210060	CABIN PRESSURE OUTFLOW VALVE								
	103898-3	MOS					20-JUL-2018		
21.250	103-898-00312	HRS/MSC	O/C				4093:50		
	REF: AMM 21-30-03	AFL					3577		
210065	CABIN PRESSURE RELIEVE VALVE								
	9599091132	MOS		N:0			30-APR-2008		
21.270	117-F0012	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER 9696781507 21.240 529418 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY 9599022118 21.200 289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210145	CABIN (REAR) ELECTRIC HEATER 9696781507 21.230 529423 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210170	OVERPRESSURE SWITCH 973.81.15.106 21.340 1936 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2020 4992:40 4366		
210175	FLOW CONTROL VALVE ACTUATOR 959.90.20.160 21.175 1426 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C				03-MAR-2016 2977:20 2611		
210180	CABIN PRESSURE CONTROL UNIT 2119232-3 21.180 2119232-00504 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				09-FEB-2018 3900 3388		
210185	INTEG. ECS CONTROL 6130C000-002 959.90.20.129 21.185 0539 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C				03-MAR-2016 2977:20 2611		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210190	FLOOR DUCT TEMP. SENSOR 9599020121 1624 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR 959.90.20.121 3679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
210200	FIREWALL 1415-3 SHUT OFF VALVE 9633011005 62 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH 973.81.32.216 0527 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-APR-2013 1685:55 1507		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH 9738132214 55 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK 9633011105 0714B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK 9633011106 0662B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK 9633011106 0668B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK 9633011106 0682B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR 9599020121 1492 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210240	INSULATED, WATER SEPERATOR ASSY 521.41.12.060 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
21JFL02	AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST  REF:	MOS HRS/MSC AFL	24	+10%/-10%			25-FEB-2019 4381:45 3818	25-FEB-2021	07-MAY-2021
<b>CHAPTER 22</b>	<b>AUTO FLIGHT</b>								
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			25-FEB-2019 4381:45 3818		
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK  REF: AMM 22-10-00	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021 5827:05	30-MAY-2021 5927:05



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 3	MOS	12	+10%/-10%			PKG	24-APR-2020	
	REF: AMM 22-20-02	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 5	MOS					PKG	24-APR-2020	
	REF: AMM 22-20-00	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 8	MOS	12	+10%/-10%			PKG	24-APR-2020	
	REF: AMM 22-20-00	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
220045	STICK PUSHER SERVO 9786111103	MOS						30-APR-2008	
22.220	80299	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
220055	STICK PUSHER CAPSTAN 9786111124	MOS						30-APR-2008	
22.140	80304	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
220060	STICK SHAKER 9786111143	MOS						30-APR-2008	
22.230	807	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
220070	STICK PUSHER 9754423104	MOS						30-APR-2008	
22.170	122170	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220075	KMC 9200 FLIGHT CONTROLLER 071-01597-0401 KMC9200-1206 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT 9859912133 KSM375-1047 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT 9859912133 KSM375-B1040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT 9859912133 KSM375-B1046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220100	RUDDER KSA 2700 SERVO 065-00190-0101 KSA2700-1715 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:9 R:0 R:0			16-NOV-2013 1983:40 1742		
220105	ELEVATOR KSA 2700 SERVO 065-00190-0101 KSA2700-1655 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-MAR-2018 3937:25 3429		
220110	AILERON KSA 2700 SERVO 065-00190-0101 KSA2700-1034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-MAR-2018 3937:25 3429		

## CHAPTER 23 COMMUNICATIONS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue  
(ENG/APU) = Engine/APU Units



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH PKG 9 REF: AMM 23-50-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH PKG 9 REF: AMM 23-12-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
23-LUX-01	EXAMINE OF COCKPIT VOICE RECORDER RECORDED SIGNAL IN ACCORDANCE WITH ICAO ANNEX 6 PART II REQUIREMENTS REF:	MOS HRS/MSC AFL	N/A						
230005 23.020	VHF/NAV SYSTEM I VHF COMM ANTENNA 9848110203 310-17351 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230010 23.030	VHF/NAV SYSTEM II VHF COMM ANTENNA 9848110203 310-17330 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA 9848110210 7628 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO 9859912134 1355 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO 9859912134 1405 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
230055	PILOT KMA 29 AUDIO/MARKER PANEL 9859912108 D0136 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL 9859912020 Q02691 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C				29-APR-2020 4832:10 4229			
<b>CHAPTER 24 ELECTRICAL POWER</b>										
24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION									
24.015 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>7827:05</b>	30-MAY-2021	
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION									
24.025 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>7827:05</b>	30-MAY-2021	
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST						PKG			
	PKG 9 REF: AMM 24-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			25-FEB-2019 4381:45 3818			
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST						PKG			
	PKG 8 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223			



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/339	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
24-30/339	REMOVE AND SERVICE NO. 2 NICAD BATTERY								
24.061	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
24.010	<b>TRACKED ITEM</b> RG-380E/44 40885352 REF: See Workcard	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%	-4		01-SEP-2020 4992:40 4366	<b>25-FEB-2021</b> <b>5592:40</b>	13-MAR-2021 5652:40
24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44 40743113 REF: AMM 24-30-07	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%	-4		01-SEP-2020 4992:40 4366	<b>25-FEB-2021</b> <b>5592:40</b>	13-MAR-2021 5652:40
24-30/473	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407)								
	978.91.23.407 PKG 6 P1142 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			24-APR-2020 4827:05 4223	<b>5427:05</b>	5487:05
24-30/474	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407)								
	978.91.23.407 PKG 6 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			24-APR-2020 4827:05 4223	<b>5427:05</b>	5487:05



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR  978.91.23.407 P1142 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	(P/N 978.9123.407)			24-APR-2020 4827:05 4223	6027:05	
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR  978.91.23.407 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	(P/N 978.9123.407)			24-APR-2020 4827:05 4223	6027:05	
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR  978.91.23.407 P1142 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A	(P/N 978.9123.437)			24-APR-2020 4827:05 4223		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR  978.91.23.407 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A	(P/N 978.9123.437)			24-APR-2020 4827:05 4223		
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE  PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
24-50/70  24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY  501.1712.02 81999 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021	30-MAY-2021



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 9	MOS	24	+10%/-10%			PKG	25-FEB-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			4381:45 3818		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111	MOS		N:0			30-APR-2008		
24.120	P1680	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-05	AFL		N:0			0		
240010	GENERATOR 1 300A CONTACTOR 9740338113	MOS		N:0			30-APR-2008		
24.130	N864	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240015	GENERATOR 2 300A CONTACTOR 9740338113	MOS		N:0			30-APR-2008		
24.130	N815	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240135	NO. 1 LEAD ACID BATTERY RG-380E/44	MOS		N:37			01-SEP-2020		
24.010	40885352	HRS/MSC	O/C	N:1303			4992:40		
	REF: AMM 24-30-07	AFL		N:1153			4366		
240140	NO. 2 LEAD ACID BATTERY RG-380E/44	MOS					01-SEP-2020		
24.010	40743113	HRS/MSC	O/C				4992:40		
	REF: AMM 24-30-07	AFL					4366		
243010	NO. 2 STARTER-GENERATOR 978.91.23.407	MOS		O:0			24-APR-2020		
24.215	P1706	HRS/MSC	O/C	N:3044:19 O:0			4827:05		
	REF: AMM 24-30-01	AFL		N:3165 O:0			4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501.1712.02 81999 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
243160	NO. 1 STARTER GENERATOR								
24.205	978.91.23.407 P1142 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:33 N:3235:55 O:1137:25 N:2706 O:1010			24-APR-2020 4827:05 4223		
243170	110 VOLT STATIC ,SS50 INVERTER								
	9750215107 3663 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
	9755085111 N217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
	9755085111 N208 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243190	VOLTAGE REGULATOR 9882114111 P1680 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
25-10/134 (s)	EXAMINE CREW COPILOT SEAT BELTS PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
25-10/134 (s)	EXAMINE CREW PILOT SEATBELT PKG 3 REF:	MOS HRS/MSC AFL	12 300				PKG 24-APR-2020 4827:05 4223		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-APR-2020 4827:05 4223		
25-10/294 25.030 OVERHAUL	CREW SEAT BELTS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144		N:1 N:0 N:0		24-APR-2020 4827:05 4223	<b>24-MAR-2032</b>	
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 1 ,3,5,6,7,8,9 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,3,5,6,7,8,9 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 8 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-JUL-2020 4940:25 4324		
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
25-20/295	NO. 1 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144		N:1 N:0 N:0		27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 2 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144		N:1 N:0 N:0		27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 3 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144		N:1 N:0 N:0		27-JUL-2020 4940:25 4324	27-JUN-2032	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 4 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 5 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 6 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295 25.010 OVERHAUL	PASSENGER SEAT BELTS 5-02-2T4718MINI REVB SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	N:1 N:0 N:0	-94		27-JUL-2020 4940:25 4324	25-MAR-2032	
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 1 ,3,5,6,7,8,9 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,3,5,6,7,8,9 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-APR-2020 4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60/231	OPERATIONAL TEST ELT S182502-02 PKG 3 2619367-0048 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021 5127:05	30-MAY-2021 5157:05
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED S182502-02 2619367-0048 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
25-63/23 25.020 DISCARD Expiry Date: 31-AUG-2026	ELT BATTERY 985.13.80.855 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE		N:72 N:2712:15 N:2371		24-APR-2020 4827:05 4223	31-AUG-2026 M	
25-63/434 DISCARD	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) S1825501-02 KA0021338001 REF: GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			29-MAY-2018 3950:50 3440	29-MAY-2028 19950:50	29-NOV-2028 20450:50
250005 25.070	REMOTE CONTROL PANEL 9851380817 2617088-0230 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-APR-2008 0 0		
250010 25.050	EMERGENCY LOCATOR TRANSMITTER S182502-02 2619367-0048 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		16-APR-2013 1685:55 1507		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250015	IPECO PILOT SEAT 959.30.01.145 50976 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:86 N:0				11-JUN-2015	
25.040									
250020	IPECO CO-PILOT SEAT 959.30.01.146 50982 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:86 N:0				11-JUN-2015	
25.040									
250021	NO. 1 PASSENGER SEAT 959.30.01.819 37448 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	
250022	NO. 2 PASSENGER SEAT 959.30.01.820 37449 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	
250023	NO. 3 PASSENGER SEAT 959.30.01.829 37450 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	
250024	NO. 4 PASSENGER SEAT 959.30.01.830 37452 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	
250025	NO. 5 PASSENGER SEAT 959.30.01.833 37451 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	
250026	NO. 6 PASSENGER SEAT 959.30.01.834 37453 REF:	MOS HRS/MSC AFL	O/C					24-APR-2020 4827:05 4223	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE S1825501-02 KA0021338001 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2018 3950:50 3440		
256015	CABLE ,S1825503-01 ASSEMBLY 9851380859 2611902-0036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
25JFL02	PERFORMED FIRST AID KIT INSPECTION  REF:	MOS HRS/MSC AFL	12	+1m/-1m			24-APR-2020 4827:05 4223	13-FEB-2021	M 13-MAR-2021
25JFL04	PERFORM VISUAL INSPECTION LIFE VEST  REF:	MOS HRS/MSC AFL	12	+1m/-1m			24-APR-2020 4827:05 4223	24-APR-2021	24-MAY-2021
<b>CHAPTER 26</b>	<b>FIRE PROTECTION</b>								
26-20/2	COCKPIT FIRE EXTINGUISHER BA51015R-5 94243 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	120	N:0 N:0 N:0		-99	18-MAR-2015 2553:15 2209	09-DEC-2024	
26-20/24	CABIN FIRE EXTINGUISHER CONTENTS CHECK ( EXCEPT MODEL P3APP003010D - P/N 959.08.06.224 )  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348) BA51015R-5 94243 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m			09-MAR-2020	09-MAR-2021	09-APR-2021



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/515	CABIN FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224)	MOS						30-APR-2008	
	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
26-20/515	COCKPIT FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224)	MOS						30-APR-2008	
	BA51015R-5 94243 REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)	MOS						30-APR-2008	
	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)	MOS						30-APR-2008	
	BA51015R-5 94243 REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
260005	FIRE/OVERHEAT DETECTOR	MOS						30-APR-2008	
26.020	9751210012 208678 REF: AMM 26-10-01	HRS/MSC AFL	O/C	N:0 N:0 N:0				0 0 0	
<b>CHAPTER 27</b>	<b>FLIGHT CONTROLS</b>								
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL							PKG	
	PKG 5	MOS						24-APR-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				4827:05 4223	
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES	MOS						30-APR-2008	
27.255	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK								
27.010		MOS	60	+10%/-10%			04-AUG-2017	<b>04-AUG-2022</b>	04-FEB-2023
	REF: AMM 27-00-00	HRS/MSC	4800	+10%/-10%	-3.45		3689:40	<b>8485:55</b>	8965:55
		AFL					3213		
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001)						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
27-10/236 (s)	AILERON CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
27-10/237 (s)	CHECK AILERON CABLE TENSION						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	REF: AMM 27-10-00	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
27-10/238 (s)	FUNCTIONAL TEST AILERONS						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
	REF: AMM 27-10-00	HRS/MSC	2400	+10%/-10%			4381:45		
		AFL					3818		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/394	AILERON CONTROL SYSTEM - EXAMINE	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-10-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-10-09</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-00-01</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-00-01</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-06</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-06</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
27-10/444	FLIGHT CONTROL CABLES, AILERON	MOS					30-APR-2008		
<b>LIFE LIMIT</b>	<b>REF: AMM 27-10-01</b>	HRS/MSC	20000	N:0			0		<b>20000</b>
		AFL	27000	N:0			0		<b>27000</b>





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
<b>LIFE LIMIT</b>	<b>REF: AMM 27-10-02</b>	AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	<b>REF: AMM 27-10-00</b>	AFL					4223		
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	<b>REF: AMM 27-15-00</b>	AFL					3818		
27-20/140 (s)	INSPECTION/CHECK RUDDER						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	<b>REF: AMM 55-40-00</b>	AFL					4223		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	<b>REF: GENERIC NO REF</b>	AFL					3818		
27-20/241 (s)	RUDDER CONTROL - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
27-20/243 (s)	CHECK RUDDER CABLE TENSION						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	<b>REF: AMM 27-20-00</b>	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 9	MOS	24	+10%/-10%			PKG 25-FEB-2019		
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%			4381:45 3818		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 9	MOS	24	+10%/-10%			PKG 25-FEB-2019		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			4381:45 3818		
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					30-APR-2008		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)								
	PN	MOS					30-APR-2008		
	SN-UNKNOWN	HRS/MSC	A/R				0		
	REF: AMM 27-20-00	AFL					0		
27-20/446	FLIGHT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
<b>LIFE LIMIT</b>	REF: AMM 27-20-01	AFL	27000	N:0			0	27000	
27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
<b>LIFE LIMIT</b>	REF: AMM 27-20-02	AFL	27000	N:0			0	27000	
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	REF: GENERIC NO REF	AFL					3818		
27-30/249 (s)	ELEVATOR CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 9	MOS	24	+10%/-10%			PKG 25-FEB-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			4381:45 3818		
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					16-APR-2013		
	REF: AMM 27-30-00	HRS/MSC AFL	O/C				1685:55 1507		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)	PN					30-APR-2008		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R				0 0		
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-30-05	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	<b>32500</b> <b>42000</b>	
27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 27-30-01	PN SN-UNKNOWN AFL	MOS HRS/MSC 27000	20000 27000	N:0 N:0 N:0		30-APR-2008 0 0	<b>20000</b> <b>27000</b>	
27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 27-30-02	PN SN-UNKNOWN AFL	MOS HRS/MSC 27000	20000 27000	N:0 N:0 N:0		30-APR-2008 0 0	<b>20000</b> <b>27000</b>	
27-30/450	STICK PUSHER CABLES								
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	PN SN-UNKNOWN AFL	MOS HRS/MSC 27000	20000 27000	N:0 N:0 N:0		30-APR-2008 0 0	<b>20000</b> <b>27000</b>	
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF:</b> See Workcard								
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)								
27.021		MOS HRS/MSC AFL	12 3000	+10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>7827:05</b>	30-MAY-2021
	<b>REF:</b> AMM 27-40-00								
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF:</b> AMM 27-40-00								
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF:</b> AMM 27-40-01								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/26	OVERHAUL PITCH TRIM ACTUATOR 129.1.1100.02 920	MOS HRS/MSC AFL	84 3400				24-APR-2020 4827:05 4223	24-APR-2027 8227:05	
<b>OVERHAUL</b>	<b>REF: GENERIC NO REF</b>								
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 5	MOS HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF: AMM 27-40-00</b>								
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF: AMM 27-40-00</b>								
27-40/3	REPLACE PITCH TRIM ACTUATOR 129.1.1100.02 920	MOS HRS/MSC AFL	20000 27000				24-APR-2020 4827:05 4223	24827:05 31223	
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>								
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) 978.73.14.203 883	MOS HRS/MSC AFL	10000		N:0 N:0 N:0		30-APR-2008 0 0	10000	
27.036	<b>REF: AMM 27-40-02</b>								
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 1 ,3,5,6,7,8,9	MOS HRS/MSC AFL	A/R				24-APR-2020 4827:05 4223		
	<b>REF: GENERIC NO REF</b>								
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM ESPECIALLY AT THE TOP OF THE FLAP DRIVE ARMS PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF: GENERIC NO REF</b>								
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	<b>REF: GENERIC NO REF</b>								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
27-50/28	FLAP POWER DRIVE UNIT 978.73.20.003	MOS			O:0		25-FEB-2019		
27.030	0953	HRS/MSC	10000	+500/-500	N:10004:05 O:0	-5:25	4381:45	14376:20	14876:20
<b>OVERHAUL</b>	REF: AMM 27-50-01	AFL	13500	+500/-500	N:8816 O:0		3818	17318	17818
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.040	2334	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.041	2281	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.050	2328	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.051	0425	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202205	MOS			N:0		30-APR-2008		
27.060	S6147	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			30-APR-2008		
27.060	S6097	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			30-APR-2008		
27.070	S6153	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			30-APR-2008		
27.070	S6075	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: AMM 27-50-02</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	<b>14000</b>
27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL	39000				0	<b>39000</b>	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					30-APR-2008		
		HRS/MSC	25000				0	25000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL	30000				0	<b>30000</b>	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	39000				0	<b>39000</b>	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	39000				0	<b>39000</b>	
27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	39000				0	<b>39000</b>	





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	30000 39000				0 0	<b>30000</b> <b>39000</b>	
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS		O:0			24-APR-2020		
27.040	9787320309	HRS/MSC	20000	N:5263 O:0			4827:05	<b>19564:05</b>	
<b>DISCARD</b>	<b>REF:</b> AMM 27-50-03	AFL	27000	N:4503 O:0			4223	<b>26720</b>	
27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS		O:0			24-APR-2020		
27.041	9787320309	HRS/MSC	20000	N:5263 O:0			4827:05	<b>19564:05</b>	
<b>DISCARD</b>	<b>REF:</b> AMM 27-50-03	AFL	27000	N:4503 O:0			4223	<b>26720</b>	
27-50/4	RIGHT INBOARD FLAP ACTUATOR	MOS		O:0			24-APR-2020		
27.050	9787320309	HRS/MSC	20000	N:5263 O:0			4827:05	<b>19564:05</b>	
<b>DISCARD</b>	<b>REF:</b> AMM 27-50-03	AFL	27000	N:4503 O:0			4223	<b>26720</b>	
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR	MOS		O:0			24-APR-2020		
27.051	9787320309	HRS/MSC	20000	N:9802:31 O:0			4827:05	<b>15024:34</b>	
<b>DISCARD</b>	<b>REF:</b> AMM 27-50-03	AFL	27000	N:11563 O:0			4223	<b>19660</b>	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		N:128 R:0			22-DEC-2018		
57.060	796-D	HRS/MSC	25000	N:4320 R:0			4320		25000
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL	30000	N:3765 R:0			3765		30000
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			30-APR-2008		
57.060	796P	HRS/MSC	25000	N:0			0		25000
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL	30000	N:0			0		30000
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			24-APR-2020	<b>24-APR-2021</b>	30-MAY-2021
		HRS/MSC	600	+10%/-10%			4827:05	<b>5427:05</b>	5487:05
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL					4223		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	<b>REF: AMM 12-20-07</b>	AFL					4223		
27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL	27000	N:0			0		27000
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR								
	9787320309 PKG 3	MOS	12	+10%/-10%			24-APR-2020	<b>24-APR-2021</b>	30-MAY-2021
27.040	2334	HRS/MSC	300	+10%/-10%			4827:05	<b>5127:05</b>	5157:05
	<b>REF: AMM 27-50-00</b>	AFL					4223		
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR								
	9787320309 PKG 3	MOS	12	+1m/-1m			24-APR-2020	<b>24-APR-2021</b>	24-MAY-2021
27.041	2281	HRS/MSC	300	+10%/-10%			4827:05	<b>5127:05</b>	5157:05
	<b>REF: AMM 27-50-00</b>	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 PKG 3 2328 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021 5127:05	24-MAY-2021 5157:05
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 PKG 3 0425 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021 5127:05	24-MAY-2021 5157:05
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 2334 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 2281 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 2328 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 0425 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
270003	HORIZONTAL TAIL ASSY								
	5551012037 816 REF: AMM 55-10-01	MOS HRS/MSC AFL					30-APR-2008 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012039 829 REF: AMM 55-20-01	MOS HRS/MSC AFL					30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270023	ELEVATOR RH ASSY								
27.023	5552012040 832 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318138 201 REF: AMM 27-25-01	MOS HRS/MSC AFL ACH	O/C	N:0 N:0 N:0			05-DEC-2009 420:40 377		
LIFE LIMIT									
270030	FIN ASSY								
27.031	5553012039 796P REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270033	RUDDER ASSY								
27.033	5554012038 795P REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270035	FLAP CONTROL AND WARNING UNIT								
27.130	9787320017 121897 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270040	FLEXSHAFT,FLAP,OUTB,B70016707.2A								
	9450202206 S6075 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 077086DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 1091 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 077016DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 077060DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1093 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270080	KTA2810,TRIM ADAPTER								
	065-00195-0100 KTA2810-1736 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:35 N:1291:25 N:1104			03-MAR-2016 2977:20 2611		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318132 1685 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 077031DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
274020	PITCH TRIM ACTUATOR								
	129.1.1100.02 920 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	O:0 O:0 O:0			24-APR-2020 4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27JFL01	EXCHANGE RELAYS K161E2 & K161D2	MOS	24	+1m/-1m			25-FEB-2019 4381:45	25-FEB-2021	25-MAR-2021
<b>DISCARD</b>	<b>REF:</b>	AFL					3818		
<b>CHAPTER 28 FUEL</b>									
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF:</b> GENERIC NO REF	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF:</b> GENERIC NO REF	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029	<b>REF:</b> AMM 28-10-01	MOS	2400	+10%/-10%	49:15		13-NOV-2017 3830:20	6279:35	6519:35
		HRS/MSC					3330		
		AFL							
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF:</b> AMM 28-20-07	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF:</b> See Workcard	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N)						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF:</b> GENERIC NO REF	HRS/MSC	600	+10%/-10%			4827:05		
		AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223		
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 9	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			25-FEB-2019 4381:45 3818		
28-20/32	OVERHAUL ENGINE DRIVEN PUMP 968.84.51.108 B34309	MOS							
28.010 OVERHAUL	REF: AMM 28-20-03	HRS/MSC AFL	3500	O:4 O:0		92:20	17-FEB-2017 3407:40 2967	7000	
280005	LOW PRESSURE FUEL PUMP 968.84.51.108 B34309	MOS							
28.120	REF: AMM 28-20-03	HRS/MSC AFL	O/C	O:4 O:0 O:0			30-MAR-2017 3407:40 2967		
280010	FUEL FLOW TRANSMITTER 975.35.12.106 0826-004	MOS							
28.130	REF: AMM 73-30-01	HRS/MSC AFL	O/C	O:0 O:0 O:0			23-SEP-2010 706:30 634		
280015	FIREWALL FUEL,SHUT-OFF VALVE 9638722301 2057	MOS							
28.110	REF: AMM 28-20-08	HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE 9638722301 2058	MOS							
28.110	REF: AMM 28-20-12	HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280025	FUEL FILTER ASSY 9683521001 2007FFT2271	MOS							
28.025	REF: AMM 28-20-01	HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 1514 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B3902 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B4168 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731220 127 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731219 113 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731218 120 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731217 100 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 B6760 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B3864 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B4175 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731217 103 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731218 117 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	975.37.31.219 102 REF: AMM 28-40-01	MOS HRS/MSC AFL ACH FLTS	O/C	R:22 R:0 R:0 R:0 R:0			20-JUL-2011 965:10 866		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731220 2028 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-JUN-2014 2222:50 1943		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 B6738 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280105	TOP CHECK VALVE 9630423105 2000 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280110	BOTTOM CHECK VALVE 9630423105 1998 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS 9753731333 158 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS 9753731333 159 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

## CHAPTER 29 HYDRAULIC POWER

29-10/151 (s)	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE PKG 7 REF: AMM 29-10-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
29-10/153 (s)	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY PKG 3 REF: AMM 29-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	<b>24-APR-2021</b> <b>6027:05</b>	30-MAY-2021 6147:05



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)								
	960.30.01.291	MOS	12	+10%/-10%			24-APR-2020	<b>24-APR-2021</b>	30-MAY-2021
	802	HRS/MSC	1200	+10%/-10%			4827:05	<b>6027:05</b>	6147:05
	REF: AMM 29-10-02	AFL					4223		
29-10/259 (s)	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.								
		MOS	12	+10%/-10%			24-APR-2020	<b>24-APR-2021</b>	30-MAY-2021
		HRS/MSC	300	+10%/-10%			4827:05	<b>5127:05</b>	5157:05
	REF: AMM 29-00-00	AFL					4223		
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED)								
	960.30.01.291	MOS					23-AUG-2017		
29.020	802	HRS/MSC	25000	N:5017:55			3713	<b>23695:05</b>	
<b>LIFE LIMIT</b>	REF: AMM 29-10-02	AFL	30000	N:4360			3233	<b>28873</b>	
29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)								
	960.30.01.291	MOS					30-APR-2008		
	802	HRS/MSC	N/A				0		
	REF: AMM 29-10-02	AFL					0		
290015	PRESSURE GAGE SWITCH								
	9738114304	MOS		N:0			23-FEB-2018		
29.050	1218	HRS/MSC	O/C	N:0			3901:55		
	REF: GENERIC NO REF	AFL		N:0			3390		
290025	SERVICE SELECTOR VALVE								
	891292	MOS					14-OCT-2015		
29.070	G1041034	HRS/MSC	O/C				2897:45		
	REF: AMM 32-30-03	AFL					2535		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290030	PRESSURE GAUGE								
29.080	9656188101 07-0925639 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
290040	HAND PUMP								
29.030	9688582111 819 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	973.81.14.306 1808 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAY-2017 3555:50 3106		
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0410550 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-OCT-2015 2886:20 2527		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS								
	REF:	MOS HRS/MSC AFL	60	+10%/-10%		-62	29-MAY-2018 3950:50 3440	28-MAR-2023	28-SEP-2023
<b>CHAPTER 30</b>	<b>ICE AND RAIN PROTECTION</b>								
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	REF: AMM 30-10-00								
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM						PKG		
	PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
	REF: AMM 30-20-00								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: See Workcard								
30-10/79 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING	MOS HRS/MSC AFL	6	+10%/-10%			24-APR-2020 4827:05 4223	24-OCT-2020	11-NOV-2020
	REF: GENERIC NO REF								
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: GENERIC NO REF								
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: GENERIC NO REF								
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: AMM 30-30-20								
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 9	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
	REF: AMM 30-40-00								
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 7	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 24-APR-2020 4827:05 4223		
	REF: See Workcard								
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 7	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 24-APR-2020 4827:05 4223		
	REF: See Workcard								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300005	PROP DE-ICE CONTROLLER								
30.140	9682913227 U4081 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 N:57:20 R:0 N:32 R:0			17-APR-2019 4448:50 3880		
300010	LPMI LINEAR ACTUATOR								
30.150	9787315302 B51217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N074373 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N074065 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N074066 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N074049 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N074051 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 4215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300050	WATER SEPARATOR								
30.060	9598901010 N075145 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	9598901014 U3709 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	R:0 N:50 R:0 N:122 R:0			17-APR-2019 4448:50 3880		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 122417 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 122424 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	P27S-7D5221-13 NCR8410 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-MAR-2016 3049:50 2671		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NEK8740 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2018 4093:50 3577		
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NFF1920 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-APR-2020 4827:05 4223		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.025 NDK6020 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JUN-2017 3589:15 3128		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300110	LH AOA PLATE TEMP CONTROLLER 9754421417 U1763 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300115	LH INBD-WING DE-ICER BOOT 959.89.01.022 NDD1440 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JUN-2017 3589:15 3128		
300120	LH OUTBD-WING DE-ICER BOOT 959.89.01.024 NDJ3230 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JUN-2017 3589:15 3128		
300125	RH AOA PLATE TEMP CONTROLLER 9754421417 U0233 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C				16-MAR-2009 133:30 137		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH 9738114312 4127 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH 9738114312 4133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH 9738114312 9205 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAR-2019 4411:20 3843		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH 9738114312 9009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:10 N:0 N:0			03-JAN-2018 3887:55 3380		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE 9598901008 N074050 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
30JFL02	PERFORM BLEED SYSTEM AND LEAK TEST OF AIRFOIL DE-ICERS BOOTS (REF. 12-B-30-10-00-00A-903A-A)  REF:	MOS HRS/MSC AFL	300 +10%/-10%				24-APR-2020 4827:05 4223	5127:05	5157:05
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
31-30/421	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)  REF: AMM 31-30-01	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
31-LUX-01	PERFORM READ OUT OF THE FLIGHT DATA RECORDER AND ANALYSIS OF THE PARAMETERS FOR ACCURACY AND RELIABILITY, IN ACCORDANCE WITH ICAO ANNEX 6 PART II REQUIREMENTS.  REF:	MOS HRS/MSC AFL	N/A						
310050 31.040	DIGITAL CLOCK 9996111213 1051550 REF: AMM 31-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER 9859912178 KMC2210-1076 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE 7036410-1904 11128581 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				09-AUG-2019 4692:25 4111		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310077	NO.2 MAU ADVANCED GRAPHIC MODULE 7036410-1902 09010386 REF:	MOS HRS/MSC AFL	O/C				11-JUN-2020 4851:15 4251		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD 985.99.12.231 14016742 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
310085	OVERHEAD CONTROL BASIC PANEL 9728121153 8 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310090	KMC2220 MF CONTOLLER 071-01598-0501 KMC2220-1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-FEB-2010 482:15 424		
310095	PILOT KMC 2210 DISPLAY CONTROLLER 9859912178 KMC2210-1053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE 7028432-1902 0912B312 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-FEB-2010 482:15 424		
310100-2	MAU ACTUATOR I/O PROC MODULE 7028432-1902 1002B420 REF:	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE 7028432-1902 1002B420 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310105	MODULAR AVIONICS ,12SLOT UNIT 9859912147 7122282 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD 985.99.12.231 13126653 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
310115	NO. 1 LH MAU POWER SUPPLY MODULE 9859912143 7119432 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310120	NO. 2 RH MAU POWER SUPPLY MODULE 9859912143 7119438 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310125	MAU DUAL GENERIC I/O MODULE 7038622-1901 14080895 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				09-AUG-2019 4692:25 4111		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT 9859912251 14111503 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-MAR-2015 2553:15 2209		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY 9859912103 1890118853 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY K9321022A00 1890118854 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:482:15 N:424			15-FEB-2010 482:15 424		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY 9859912103 1890119589 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY K9321022A00 1890118856 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:482:15 N:424			15-FEB-2010 482:15 424		
310155	REV CTL PNL,4-POT DISPLAY 9728121141 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE 9858314204 7097393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE 9858314204 7107406 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310175 31.300	REAR CENTRE CONS PNL PC-12 47/E 9728121154 0396 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-SEP-2017 3773:45 3277		
31C011	PC-12E APX100 APEX SYS SOFTWARE 9859912142 10099003 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

## CHAPTER 32 LANDING GEAR



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK	MOS	12	+1m/-1m			24-APR-2020	24-APR-2021	24-MAY-2021
32.010	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			4827:05 4223	7227:05	7467:05
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY 5321012051	MOS					30-APR-2008		
32.070	VLG351	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY 5321012052	MOS					30-APR-2008		
32.070	VLG351	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+10%/-10%			24-APR-2020	<b>24-APR-2021</b>	30-MAY-2021
	<b>REF:</b> See Workcard	HRS/MSC					4827:05		
		AFL					4223		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS					03-MAR-2016		
	<b>REF:</b> See Workcard	HRS/MSC	N/A				2977:20		
		AFL					2611		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS					03-MAR-2016		
	<b>REF:</b> See Workcard	HRS/MSC	N/A				2977:20		
		AFL					2611		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS				72		30-APR-2008	
	REF: AMM 32-10-00	HRS/MSC	N/A					0	
		AFL						0	
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS						30-APR-2008	
	REF: AMM 32-10-00	HRS/MSC	N/A					0	
		AFL						0	
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS						03-MAR-2016	
	REF: AMM 32-10-00	HRS/MSC	N/A					2977:20	
		AFL						2611	
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS						03-MAR-2016	
	REF: AMM 32-10-00	HRS/MSC	N/A					2977:20	
		AFL						2611	
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS						30-APR-2008	
	REF: AMM 32-10-00	HRS/MSC	N/A					0	
		AFL						0	
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS						30-APR-2008	
	REF: AMM 32-10-00	HRS/MSC	N/A					0	
		AFL						0	
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%				24-APR-2020	24-APR-2021 30-MAY-2021
32.030	REF: AMM 12-20-06	HRS/MSC	T/C					4827:05	
		AFL						4223	
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE							PKG	
	PKG 7	MOS	12	+10%/-10%				24-APR-2020	
	REF: AMM 32-20-00	HRS/MSC	600	+10%/-10%				4827:05	
		AFL						4223	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
32-20/335	NOSE LANDING GEAR TORQUE TUBE 5325012064	MOS					29-MAY-2018		
32.190	N/A	HRS/MSC	O/C		N:0		3950:50		
	REF: GENERIC NO REF	AFL			N:0		3440		
32-20/403	NOSE LANDING GEAR - OVERHAUL PN	MOS					30-APR-2008		
32.200	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0		0	25000	25500
OVERHAUL	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0		0	30000	30500
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK 5322012296	MOS					03-FEB-2016		
	N/A	HRS/MSC	25000		N:0		2961:35	27961:35	
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000		N:0		2598	32598	
32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM	MOS	12	+10%/-10%			24-APR-2020	24-APR-2021	30-MAY-2021
	REF: AMM 32-30-00	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223	6027:05	6147:05





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/417	LEFT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
	9603001105	MOS					24-AUG-2017		
32.040	2759H	HRS/MSC	25000	N:142:10			3713:20		28571:10
<b>LIFE LIMIT</b>	<b>REF: AMM 32-30-01</b>	AFL	30000	N:121			3234		33113
32-30/417	RIGHT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
	9603001105	MOS					01-DEC-2017		
32.040	2234H	HRS/MSC	25000	N:2568			3854:30		26286:30
<b>LIFE LIMIT</b>	<b>REF: AMM 32-30-01</b>	AFL	30000	N:2189			3351		31162
	ACH								
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	<b>REF: AMM 32-30-10</b>	AFL					0		
32-30/425	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	<b>REF: GENERIC NO REF</b>	AFL					0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY								
	REF: AMM 32-30-08	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY								
	REF: AMM 32-10-06	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
	REF: See Workcard	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
	REF: See Workcard	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
	REF: See Workcard	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: See Workcard	MOS HRS/MSC AFL	72				03-MAR-2016 2977:20 2611	<b>03-MAR-2022</b>	
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: See Workcard	MOS HRS/MSC AFL	72				03-MAR-2016 2977:20	<b>03-MAR-2022</b>	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	600	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: AMM 12-10-04	AFL					4223		
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	600	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: AMM 12-10-04	AFL					4223		
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: AMM 12-10-02	AFL					4223		
32-50/404	EXAMINE - NLG STEERING MECHANISM								
		MOS					30-APR-2008		
32.230		HRS/MSC	32500	+500/-500			0	32500	33000
	REF: AMM 32-50-00	AFL	42000	+500/-500			0	42000	42500



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320005	PILOT LH BRAKE MASTER CYLINDER HP1457300-2 2047 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:4245:48 R:0 N:3132 R:0			09-AUG-2019 4692:25 4111		
320006	STEREER SELECTOR, LANDING GEAR VALVE 960.30.01.274 0765C REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-FEB-2018 3901:55 3390		
320010	PILOT RH BRAKE MASTER CYLINDER 9594751131 5188 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320015	PARK BRAKE VALVE 9594751121 2586 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320020	NOSE WHEEL 3-1501 0670 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				20-JUL-2018 4093:50 3577		
320021	NOSE LANDING GEAR TIRE 021-327-0 7284S00174 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2018 4093:50 3577		
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY 3-1543-1 1084 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-MAY-2020 4844:05 4243		
320023	LEFT MAIN LANDING GEAR TIRE 025-350-0 9186S00296 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-MAY-2020 4844:05 4243		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY 3-1543-1 1648 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				06-AUG-2020 4958:30 4339		
320025	SHIMMY DAMPER ASSY 5322012215 VLG380 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:72 N:2114:50 N:1852			04-APR-2014 2114:50 1852		
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 8155S00273 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-AUG-2020 4958:30 4339		
320030	COPILOT LH BRAKE MASTER CYLINDER 9594751131 5205 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 9594751131 5206 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY 5322012249 VLG352 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320045	NOSE LANDING GEAR STRUT ASSY 5322012040 VLG352 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320055	RIGHT SHOCK ABSORBER ASSY 5321012211 VLG712 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320060	LH BRAKE ASSY								
32.050	959.56.01.512 1537 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			13-JUL-2018 4090:45 3574		
320074	NOSE LANDING GEAR HYDRAULIC ACTUATOR								
	9603001111 1498A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-OCT-2015 2897:45 2535		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG713 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320085	RH BRAKE ASSY								
32.050	2-1674-1 0973 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-MAY-2017 3551:30 3101		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
	9733033113 241 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
	9733033113 1442 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			30-APR-2008 0 0		
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH								
	973.30.33.116 3921 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-MAY-2015 2630:35 2290		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
	9733033113 223 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH 9733033113 343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320125	MAIN LANDING GEAR 72A74-01 LH "WOW" PROXIMITY SWITCH 9733033113 337 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
<b>CHAPTER 33 LIGHTS</b>									
33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 3 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 3 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 3 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3 REF: AMM 33-44-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223		
330005	DIM UNIT 9750215205	MOS		N:0			30-APR-2008		
33.080	122204 REF: AMM 33-10-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330010	DE-ICE LIGHT ASSY 972.87.67.111	MOS		N:0			21-AUG-2014		
33.010	2742930 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			2371:05 2060		
330015	LH HIDL WING 9728769413	MOS		N:0			30-APR-2008		
33.020	1258852 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330020	RH HIDL WING 972.87.69.413	MOS		N:0			18-MAR-2015		
33.020	2979177 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			2553:15 2209		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787331	MOS		N:0			30-APR-2008		
33.040	18005 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787332	MOS		N:0			30-APR-2008		
33.040	18010 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330035	LH WING POWER SUPPLY UNIT 9728787164	MOS		N:0			30-APR-2008		
33.070	30967 REF: AMM 33-43-03	HRS/MSC AFL	O/C	N:0 N:0			0 0		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 28534030 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-AUG-2015 2832:05 2475		
330045	RH WING POWER SUPPLY UNIT								
33.070	9728787164 30975 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 23741 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-MAR-2011 834:25 741		
330055	NAVIGATION (FC), LED GREEN LIGHT								
33.050	9728787158 30361 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330060	NAVIGATION (FC), LED RED LIGHT								
33.050	9728787157 28961 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT								
33.060	9728787159 27147 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	R:506:20			04-SEP-2014 2406:15 2084		
330070	NOSE LANDING GEAR TAXI LIGHT								
	03-4400-1000 30287001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C				09-AUG-2019 4692:25 4111		
330075	L/H 1X0005287-10 LANDING LIGHT								
	972.87.69.402 29536004 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-MAY-2016 3115:30 2736		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330076	R/H 1X0005287-10 LANDING LIGHT 03-4303-0000 30493001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 4381:45 3818		
<b>CHAPTER 34 NAVIGATION</b>									
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 8 REF: AMM 34-11-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
34-11/343	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT REF: AMM 34-11-12	MOS HRS/MSC AFL	24				24-APR-2020 4827:05 4223	<b>24-APR-2021 M</b>	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11/82	LEAK CHECK STATIC SYSTEM (DAC-AIR 348)								
34.010	REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+10%/-10%		-13	24-APR-2020 4827:05 4223	11-APR-2022	23-JUN-2022
34-14/83	CALIBRATION CHECK ALTIMETER								
	REF:	MOS HRS/MSC AFL	24	+1m/-1m		19	24-APR-2020 4827:05 4223	13-MAY-2022	13-JUN-2022
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348)								
	REF: AMM 34-21-00	MOS HRS/MSC AFL	24	+1m/-1m			24-APR-2020 4827:05 4223	24-APR-2022	24-MAY-2022
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)								
	REF: AMM 34-14-00	MOS HRS/MSC AFL	24	+10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021	06-JUL-2021
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED)								
	REF: AMM 34-26-40	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348)								
34.050	REF: See Workcard	MOS HRS/MSC AFL	24	+1m/-1m		-13	24-APR-2020 4827:05 4223	11-APR-2022	11-MAY-2022
340010	DME/IFF ANTENNA								
34.080	9848110240 261-78218 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C				30-APR-2008 0 0		
340020	MARKER ANTENNA								
34.100	9848110260 101-6568 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C				30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340055	WITH HARM FILTER,KN63 DME								
34.200	066-1070-01 14124 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C				04-AUG-2016 3272:25 2863		
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 2319 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C				22-DEC-2018 4320 3765		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 5709 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-78245 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 A8602 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340100	FRONT KA92 ANTENNA								
34.090	013-00235-00 129258 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-FEB-2017 3407:40 2967		
340101	REAR KA92 GPS ANTENNA								
34.090	013-00235-00 129210 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-FEB-2017 3407:40 2967		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 7620 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 14043 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340135	STANDBY MAGNETIC COMPASS								
34.130	9999880103 AT-821 REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	N:72 N:2114:50 N:1852			04-APR-2014 2114:50 1852		
340140	RADOME								
34.420	9857900005 481 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 531548 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:111 N:3665:15 N:3191			13-JUL-2017 3665:15 3191		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41425 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41426 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 18618 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 18396 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911570 KRA405B-7175 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	9859918009 SN-UNKNOWN REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 7621 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340235	AOA SENSOR RH UNIT								
34.330	0012AC12 1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			20-APR-2016 3055:15 2676		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	9859911505 18797 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340255	AOA SENSOR LH UNIT								
34.330	0012AC11 0333 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-SEP-2014 2406:15 2084		
340265	DME/IFF--ATC DIV. ANTENNA								
	9848110240 261-78231 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340270	LEFT PITOT STATIC TUBE								
	9651112302 862507 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340275	RIGHT PITOT STATIC TUBE 9651112302 AS02179213 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-2017 3795:45 3298		
340280	OUTBOARD KMG 7010 MAGNETOMETER 9859912114 KMG7010-1194 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER 9859912114 KMG7010-1197 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT 0000008480 KMH920-B1176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:25 R:0 R:0			23-SEP-2013 1918:40 1690		
340295	RH COAX SWITCH 9859911371 13232 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340300	LH COAX SWITCH 9859911371 13202 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340305	NO. 1 LH KGS200,GPS SENSOR UNIT 985.99.12.155 KGS200-1281 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				19-MAY-2017 3551:30 3101		
340310	NO. 2 KXP 2290 MODE S TRANSPONDER 066-01198-0102 1425 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 4381:45 3818		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340315	NO. 1 KXP 2290 MODE S TRANSPONDER 066-01198-0102 M1056 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
340320	LH OAT SENSOR 534.13.12.054 2226046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUN-2017 3589:15 3128		
340325	RH OAT SENSOR 534.13.12.054 2212062 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUN-2017 3589:15 3128		
340335	NO. 2 RH KGS200,GPS SENSOR UNIT 985.99.12.155 KGS200-1941 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				19-MAY-2017 3551:30 3101		
340340	STANDBY INSTRUMENT PANEL 9759611244 C16221010895 REF: AMM 34-26-40	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-APR-2008 0 0		
34C012	KSG 7200 DUAL CHANNEL ADAHRS 065-00188-5103 KSG7200-B1864 REF:	MOS HRS/MSC AFL	O/C				22-DEC-2018 4320 3765		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348)  REF:	MOS HRS/MSC AFL	24	+1m/-1m		-8	25-FEB-2019 4381:45 3818	17-FEB-2021	17-MAR-2021
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM)  REF:	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021	30-MAY-2021





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34JFL04	TEST OF PROBE AND PITOT STATIC PORT (INCULDING ALTIMETER,AIRSPPEED INDICATOR, VERTICAL SPEED INDICATOR AND STANDBY INSTRUMENTS TO VERIFY ACCURACY)	MOS HRS/MSC AFL	24					11-APR-2022	M
<b>CHAPTER 35 OXYGEN</b>									
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%				24-APR-2020 4827:05 4223	
	REF: GENERIC NO REF								
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG		
	PKG 5	MOS HRS/MSC AFL	300	+10%/-10%				24-APR-2020 4827:05 4223	
	REF: GENERIC NO REF								
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%				24-APR-2020 4827:05 4223	
	REF: GENERIC NO REF								
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%				24-APR-2020 4827:05 4223	
	REF: AMM 35-00-00								
35-10/6	REAR FUSELAGE OXYGEN CYLINDER								
	895-06077	MOS	180	O:0		-309	03-FEB-2016	31-MAR-2030	
	ALT281-32994	HRS/MSC		O:0			2961:35		
<b>AIRWORTHINESS</b>	REF: AMM 35-10-01	AFL		O:0			2598		
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER								
	895-06077	MOS	60				19-NOV-2015	19-NOV-2020	
	ALT281-32994	HRS/MSC							
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	AFL							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/452	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED)  REF: AMM 35-00-00	MOS HRS/MSC AFL	N/A					30-APR-2008 0 0	
35-20/453	OVERHAUL NO. 1 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 2 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 3 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 4 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 5 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  5352112141 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A					01-APR-2018	
35-20/453	OVERHAUL NO. 6 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)  REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/453	OVERHAUL NO. 7 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)	PN							
		MOS							
		SN-UNKNOWN	HRS/MSC	N/A					
	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 8 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)	PN							
		MOS							
		SN-UNKNOWN	HRS/MSC	N/A					
	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 9 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)	PN							
		MOS							
		SN-UNKNOWN	HRS/MSC	N/A					
	REF: GENERIC NO REF	AFL							
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)								
		MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05	5127:05	5157:05
	REF: AMM 35-00-00	AFL					4223		
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS								
35.010		MOS	36	+10%/-10%	-20		24-APR-2020	04-APR-2023	22-JUL-2023
		HRS/MSC					4827:05		
	REF: AMM 35-20-00	AFL					4223		
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	MC10-06-125	MOS					19-DEC-2013		
	SE13488	HRS/MSC	O/C				2144:20		
	REF: GENERIC NO REF	AFL					1872		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	MC10-06-125	MOS					16-APR-2013		
	SE23133	HRS/MSC	O/C				1685:55		
	REF: GENERIC NO REF	AFL					1507		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350030	PRESSURE,GAGE,OXYGEN SWITCH									
35.050	9738114401 816 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350035	CONTR,3-POSITION,37071-03 VALVE									
35.030	9633211101 2785 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350050	OXYGEN GAGE ASSY									
	535.12.12.085 60399 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2020 4992:40 4366			
350055	OXYGEN PRESS TRANSDUCER									
	9571201184 7427-5-57 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY									
	5352112141 NSN REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2018 3950:50 3440			
<b>CHAPTER 45 CENTRAL MAINT SYSTEM</b>										
45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG			
	PKG 8	MOS	12	+10%/-10%			24-APR-2020			
	REF: AMM 45-45-00	HRS/MSC	1200	+10%/-10%			4827:05			
		AFL					4223			
45JFL01	DOWNLOAD FHDB, ACMF									
	REF:	MOS	300	+10%/-10%			11-JUN-2020	5151:15	5181:15	
		HRS/MSC					4851:15			
		AFL					4251			
<b>CHAPTER 46 INFORMATION SYSTEMS</b>										



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
46-26/320 (s)	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES PKG 3	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES PKG 3	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 46-30-02	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
<b>CHAPTER 52 DOORS</b>									
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-10-00</b>	HRS/MSC	32500				0	<b>32500</b>	
		AFL	42000				0	<b>42000</b>	
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE	MOS					30-APR-2008		
52.100	<b>REF: AMM 52-00-01</b>	HRS/MSC	32500	+500/-500			0	<b>32500</b>	33000
		AFL	42000	+500/-500			0	<b>42000</b>	42500
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN	MOS					30-APR-2008		
52.110	<b>REF: AMM 52-10-01</b>	HRS/MSC	25000	+500/-500			0	<b>25000</b>	25500
		AFL	30000	+500/-500			0	<b>30000</b>	30500
52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)	MOS					30-APR-2008		
	<b>REF: AMM 52-10-06</b>	HRS/MSC	N/A				0		
		AFL					0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%			24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
52.010	<b>REF: See Workcard</b>	HRS/MSC	4000	+10%/-10%	9		4827:05	<b>8827:05</b>	9227:05
		AFL					4223		
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF: GENERIC NO REF</b>	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF: GENERIC NO REF</b>	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-20-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	600	+10%/-10%			4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	600	+10%/-10%			4827:05		
	<b>REF: AMM 52-30-00</b>	AFL					4223		
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 7	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	600	+10%/-10%			4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-30-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE	MOS					30-APR-2008		
52.120		HRS/MSC	32500	+500/-500			0		<b>32500</b> 33000
	<b>REF: AMM 52-30-00</b>	AFL	42000	+500/-500			0		<b>42000</b> 42500



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
52.130		MOS					30-APR-2008		
	REF: AMM 52-30-01	HRS/MSC	25000	+500/-500			0	25000	25500
		AFL	30000	+500/-500			0	30000	30500
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
52.020	PN	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	SN-UNKNOWN	HRS/MSC	13000				0	13000	
	REF: AMM 52-30-07	AFL	17000				0	17000	
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED								
52.030		MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: See Workcard	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	REF: AMM 52-70-00	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
520005	PASSENGER DOOR								
52.050	5520512007	MOS					30-APR-2008		
	796P	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512010	MOS					30-APR-2008		
	796P	HRS/MSC	O/C				0		
	REF: AMM 52-30-01	AFL					0		
520015	EMERGENCY 6 SERIE EXIT								
52.060	5520512009	MOS					30-APR-2008		
	796P	HRS/MSC	O/C				0		
	REF: AMM 52-20-01	AFL					0		

## CHAPTER 53 FUSELAGE





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	REF: GENERIC NO REF	AFL					3818		
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	REF: GENERIC NO REF	AFL					3818		
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	REF: GENERIC NO REF	AFL					3818		
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 8	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	1200	+10%/-10%			4827:05		
	REF: GENERIC NO REF	AFL					4223		
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	AFL					0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24 PKG 8 REF: AMM 53-20-02	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION REF: AMM 53-10-06	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS REF: AMM 53-10-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS REF: AMM 53-20-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43 REF: AMM 53-30-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
53-00/355	EXAMINE - ANTENNA STRUCTURE REF: AMM 53-00-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN REF: AMM 53-00-00	MOS HRS/MSC AFL	28300 37000				30-APR-2008 0 0	28300 37000	
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN REF: AMM 53-00-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-03</b>	HRS/MSC	30000				0	<b>30000</b>	
		AFL	39000				0	<b>39000</b>	
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-20-02</b>	HRS/MSC	30000				0	<b>30000</b>	
		AFL	39000				0	<b>39000</b>	
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	32500				0	<b>32500</b>	
		AFL	42000				0	<b>42000</b>	
53-00/419	EDDY CURRENT INSPECTION - FRAME 40	MOS					30-APR-2008		
53.210	<b>REF: See Workcard</b>	HRS/MSC	32500	+500/-500			0	<b>32500</b>	33000
		AFL	42000	+500/-500			0	<b>42000</b>	42500
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					30-APR-2008		
53.010	<b>REF: GENERIC NO REF</b>	HRS/MSC	20000				0	<b>20000</b>	
<b>AIRWORTHINESS</b>		AFL	27000				0	<b>27000</b>	
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
53.030	<b>REF: GENERIC NO REF</b>	HRS/MSC	4000	+10%/-10%			4827:05	<b>8827:05</b>	9227:05
		AFL					4223		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT, WITH INSULATION REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
53.040	<b>REF: GENERIC NO REF</b>	HRS/MSC	4000	+10%/-10%			4827:05	<b>8827:05</b>	9227:05
		AFL					4223		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
53.070	<b>REF: GENERIC NO REF</b>	HRS/MSC	4000	+10%/-10%			4827:05	<b>8827:05</b>	9227:05
		AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
	REF: AMM 53-30-01	MOS	12	+1m/-1m			24-APR-2020	24-APR-2021	24-MAY-2021
		HRS/MSC					4827:05		
		AFL					4223		
530070	FUSELAGE AB 1003 TEIL1								
	5530512114	MOS					30-APR-2008		
	796P	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
				N:0					
				N:0					
				N:0					
<b>CHAPTER 55</b>	<b>STABILIZERS</b>								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
	REF: GENERIC NO REF	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>		HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
	REF: GENERIC NO REF	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>		HRS/MSC	N/A				0		
		AFL					0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 55-00-00	HRS/MSC AFL	1200	+10%/-10%			24-APR-2020 4827:05 4223		
55-10/415	HORIZONTAL STABILIZER 555.10.12.037 816	MOS		N:0			30-APR-2008		
<b>LIFE LIMIT</b>	REF: AMM 55-10-01	HRS/MSC AFL	25000 30000	N:0			0 0	<b>25000</b> <b>30000</b>	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			4827:05 4223	<b>8827:05</b>	9227:05
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			4827:05 4223	<b>8827:05</b>	9227:05
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
55-20/362	EXAMINE RIGHT WING ELEVATOR	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF: GENERIC NO REF</b>	HRS/MSC	300	+10%/-10%			4827:05		
		AFL					4223		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF: GENERIC NO REF</b>	HRS/MSC	1200	+10%/-10%			4827:05		
		AFL					4223		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-30-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-00-00</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-30-02</b>	HRS/MSC	32500				0		<b>32500</b>
		AFL	42000				0		<b>42000</b>
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					30-APR-2008		
55.190	<b>REF: AMM 55-30-03</b>	HRS/MSC	32500	+500/-500			0		<b>32500</b> 33000
		AFL	42000	+500/-500			0		<b>42000</b> 42500



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40/373	EXAMINE - RUDDER	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-40-00</b>	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-40-05</b>	HRS/MSC AFL	32500 42000				0 0	<b>32500</b> <b>42000</b>	
55-40/410	EXAMINE - RUDDER TRIM TAB	MOS					30-APR-2008		
55.200	<b>REF: AMM 55-40-04</b>	HRS/MSC AFL	32500 42000	+500/-500 +500/-500			0 0	<b>32500</b> <b>42000</b>	33000 42500
<b>CHAPTER 56 WINDOWS</b>									
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
	<b>REF: AMM 56-00-00</b>	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED	MOS					30-APR-2008		
56.020	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	A/R				0 0		
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED	MOS					30-APR-2008		
	<b>REF: AMM 56-00-00</b>	HRS/MSC AFL	A/R				0 0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					30-APR-2008		
	9598110109	HRS/MSC AFL	A/R				0 0		
	07219H5554								
	<b>REF: See Workcard</b>								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110110 07144H7198 REF: See Workcard	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 07219H5554 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110110 07144H7198 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500		10	29-MAY-2018 3950:50 3440	08-JUN-2028 14950:50	08-DEC-2028 15450:50
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED REF: See Workcard	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 3 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
560015	SIDE,LH WINDOW 9598110111 07218H5378 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C				30-APR-2008 0 0		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560020	SIDE,RH WINDOW								
56.090	9598110112 07208H4365 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029 7597 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029 7588 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 7629 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 7628 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 7607 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 7565 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 7576 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 7563 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 7617 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 07334H8156 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	9598110109 07219H5554 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	9598110110 07144H7198 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
<b>CHAPTER 57 WINGS</b>									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: AMM 57-00-00	MOS HRS/MSC AFL	20000 27000				30-APR-2008 0 0	20000 27000	
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: AMM 57-00-00	MOS HRS/MSC AFL	20000 27000				30-APR-2008 0 0	20000 27000	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: GENERIC NO REF								
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS PKG 9	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 25-FEB-2019 4381:45 3818		
	REF: GENERIC NO REF								
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: GENERIC NO REF								
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
	REF: GENERIC NO REF								
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS HRS/MSC AFL	30000 39000				30-APR-2008 0 0	30000 39000	
<b>AIRWORTHINESS</b>	REF: AMM 57-00-00								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS HRS/MSC AFL	30000 39000				30-APR-2008 0 0	30000 39000	
<b>AIRWORTHINESS</b>	REF: AMM 57-00-00								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	30000				0		<b>30000</b>
		AFL	39000				0		<b>39000</b>
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-10	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-10	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-10	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-10	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-05	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>
57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57-20-05	HRS/MSC	25000				0		<b>25000</b>
		AFL	30000				0		<b>30000</b>



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000				0	<b>25000</b>	
		AFL	30000				0	<b>30000</b>	
57-00/412	EXAMINE - WING TIPS	MOS					30-APR-2008		
57.170		HRS/MSC	32500	+500/-500			0	<b>32500</b>	33000
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-33-00</b>	AFL	42000	+500/-500			0	<b>42000</b>	42500
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					30-APR-2008		
57.180		HRS/MSC	25000	+500/-500			0	<b>25000</b>	25500
	<b>REF: AMM 57-20-01</b>	AFL	30000	+500/-500			0	<b>30000</b>	30500
57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					30-APR-2008		
		HRS/MSC	25000	+500/-500			0	<b>25000</b>	25500
	<b>REF: AMM 57-20-01</b>	AFL	30000	+500/-500			0	<b>30000</b>	30500
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	16000				0	<b>16000</b>	
		AFL	22500				0	<b>22500</b>	
57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-APR-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	16000				0	<b>16000</b>	
		AFL	22500				0	<b>22500</b>	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	<b>03-MAY-2024</b>	27-SEP-2024
57.020		HRS/MSC	4000	+10%/-10%			4827:05	<b>8827:05</b>	9227:05
	<b>REF: GENERIC NO REF</b>	AFL					4223		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040		MOS	120	+6m/-6m			29-MAY-2018	08-JUN-2028	08-DEC-2028
	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			3950:50	14950:50	15450:50
		AFL					3440		
57-60/393	EXAMINE - RIGHT WING AILERON								
<b>AIRWORTHINESS</b>	REF: AMM 57-60-00	MOS					30-APR-2008		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/393	EXAMINE -LEFT WING AILERON								
<b>AIRWORTHINESS</b>	REF: AMM 57-60-00	MOS					30-APR-2008		
		HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190		MOS					30-APR-2008		
	REF: AMM 57-60-04	HRS/MSC	32500	+500/-500			0	32500	33000
		AFL	42000	+500/-500			0	42000	42500
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512015	MOS					30-APR-2008		
	2796P	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512018	MOS					30-APR-2008		
	2796P	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570050	L/H WING								
	5570512135	MOS					30-APR-2008		
	796P	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570055	R/H WING 5570512136 796P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
<b>CHAPTER 61 PROPELLERS/PROPULSORS</b>									
61-10/37	PROPELLER 968.29.13.002 KX1250 REF: See Workcard	MOS HRS/MSC AFL	72 4000	N:72 O:0 N:3380:55 O:0			23-JAN-2020 4827:05	<b>23-JAN-2026</b> <b>8827:05</b>	
61.010 <b>OVERHAUL</b>									
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
61PR1	NO. 1 PROPELLER HC-E4A-3D/E10477SK KX1250 REF: See Workcard	MOS HRS/MSC AFL	PP/C	N:3380:55 O:0			24-APR-2020 4827:05 4223		
61.PR1									
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01</b>									
612010	NO. 1 ENGINE - PROPELLER GOVERNOR 8210-137H 15475672 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	<b>(7330:20) 7450:50</b>	7830:20
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 210949 15512024 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	<b>(7330:20) 7450:50</b>	7830:20
<b>PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1250 Part # HC-E4A-3D/E10477SK</b>									
610010	NO. 1 PROPELLER - OVERHAUL REF:	MOS HRS/MSC	72 4000				23-JAN-2020 3380:55	<b>23-JAN-2026</b> <b>(7380:55) 8827:05</b>	
<b>OVERHAUL</b>									



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			23-JAN-2020 3380:55	23-JAN-2021 (3680:55) 5127:05	23-FEB-2021 3710:55
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			23-JAN-2020 3380:55	23-JAN-2021 (3680:55) 5127:05	23-FEB-2021 3710:55
	REF:								
610070	NO. 1 PROPELLER - PRE-FLIGHT CHECKS	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
610080	NO. 1 PROPELLER - OPERATIONAL CHECKS	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
610510	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
	UNSCHEDULED MAINTENANCE CHECK								
610520	NO. 1 PROPELLER - LIGHTNING STRIKE	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
	UNSCHEDULED MAINTENANCE CHECK								
610530	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
	UNSCHEDULED MAINTENANCE CHECK								





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610540	NO. 1 PROPELLER - FIRE/HEAT DAMAGE	MOS						25-MAR-2014	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF:								
610550	NO. 1 PROPELLER - SUDDEN STOPPAGE	MOS						25-MAR-2014	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF:								
610560	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION	MOS						25-MAR-2014	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF:								
610570	NO. 1 PROPELLER - LONG TERM STORAGE	MOS						25-MAR-2014	
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R					0	
	REF:								
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE	MOS						25-MAR-2014	
	9682913023	HRS/MSC	O/C	N:0				0	
	L43786			N:0					
	REF: GENERIC NO REF								
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE	MOS						25-MAR-2014	
	9682913023	HRS/MSC	O/C	N:0				0	
	L43783			N:0					
	REF: GENERIC NO REF								
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE	MOS						25-MAR-2014	
	9682913023	HRS/MSC	O/C	N:0				0	
	L43787			N:0					
	REF: GENERIC NO REF								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913023 L43782 REF: GENERIC NO REF	MOS HRS/MSC O/C		N:0 N:0			25-MAR-2014 0		
<b>CHAPTER 71 POWER PLANT</b>									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
71.010	REF: AMM 71-00-00								
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH 71.040	MOS HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223	5127:05	5157:05
71-00/104	PERFORM COMPRESSOR DESALINATION WASH REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
71-00/105	PERFORM TURBINE WASH REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-APR-2020 4827:05 4223		
71.030	REF: AMM 71-00-03								



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
	571.20.12.036	MOS		N:0			30-APR-2008		
71.050	810	HRS/MSC	20000	N:0			0		20000
<b>AIRWORTHINESS</b>	<b>REF: AMM 71-00-05</b>	AFL	27000	N:0			0		27000
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
		MOS					30-APR-2008		
71.050		HRS/MSC	11000				0		11000
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	<b>REF: AMM 71-00-00</b>	AFL					4223		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	<b>REF: GENERIC NO REF</b>	AFL					3818		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 3	MOS	12	+10%/-10%			24-APR-2020		
		HRS/MSC	300	+10%/-10%			4827:05		
	<b>REF: GENERIC NO REF</b>	AFL					4223		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS.						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					24-APR-2020		
		HRS/MSC	A/R				4827:05		
	<b>REF: AMM 71-00-00</b>	AFL					4223		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY.						PKG		
	PKG 9	MOS	24	+10%/-10%			25-FEB-2019		
		HRS/MSC	2400	+10%/-10%			4381:45		
	<b>REF:</b>	AFL					3818		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.063	9448121409 10633 REF: AMM 71-00-00	MOS HRS/MSC AFL	5000/E/C	+10%/-10%	N:0 N:0 N:0		29-MAY-2018 3950:50 3440	8950:50	9450:50
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.064	9448121409 10647 REF: AMM 71-00-00	MOS HRS/MSC AFL	5000/E/C	+10%/-10%	N:0 N:0 N:0		29-MAY-2018 3950:50 3440	8950:50	9450:50
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
71.061	9448121409 10646 REF: AMM 71-00-00	MOS HRS/MSC AFL	5000/E/C	+10%/-10%	N:0 N:0 N:0		29-MAY-2018 3950:50 3440	8950:50	9450:50
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409 10654 REF: AMM 71-00-00	MOS HRS/MSC AFL	5000/E/C	+10%/-10%	N:0 N:0 N:0		29-MAY-2018 3950:50 3440	8950:50	9450:50
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	9448121409 9585 REF: AMM 71-00-00	MOS HRS/MSC AFL	5000/E/C	+10%/-10%	N:0 N:0 N:0		29-MAY-2018 3950:50 3440	8950:50	9450:50
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
<b>AIRWORTHINESS</b>	REF: AMM 71-00-05	MOS HRS/MSC AFL	26600 35000				30-APR-2008 0 0	<b>26600</b> <b>35000</b>	
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG 24-APR-2020 4827:05 4223		
	PKG 1 ,3,5,6,7,8,9 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R						
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG 24-APR-2020 4827:05 4223		
	PKG 1 ,3,5,6,7,8,9 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R						



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR PKG 1 ,3,5,6,7,8,9 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-APR-2020 4827:05 4223		
710005 71.070	UPPER LH ENGINE VIBRATION ISOLATOR 5712012106 3497 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710015 71.080	UPPER CENTER ENGINE VIBRATION ISOLATOR 5712012106 3519 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710025 71.090	UPPER RH ENGINE VIBRATION ISOLATOR 5712012106 3507 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710035 71.100	LOWER LH ENGINE VIBRATION ISOLATOR 5712012106 3496 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710045 71.110	LOWER RH ENGINE VIBRATION ISOLATOR 5712012106 3522 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710050	ENGINE MOUNT (WELDED) 5712012036 810 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
71EN1 71.EN1	NO. 1 ENGINE PT6A-67P PCE-RY0008 <b>REF:</b> AMM 71-00-00	MOS HRS/MSC AFL	E/C	N:3830:20			29-MAY-2018 3950:50 3440		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
710011	NO. 1 ENGINE - OVERHAUL	MOS					13-APR-2018		
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC ENC	3500	+200			3830:20 3310	<b>(7330:20) 7450:50</b>	7530:20
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE	MOS					24-APR-2020		
	PKG 0	HRS/MSC ENC	300	+10%/-10%			4706:35 4093		
	<b>REF:</b> EMM 72-30-05								
710021	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					13-APR-2018		
	<b>REF:</b> EMM 72-00-00	HRS/MSC ENC	1750	+250			3830:20	<b>(5580:20) 5700:50</b>	5830:20
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					24-APR-2020		
	<b>REF:</b> EMM 72-00-00	HRS/MSC ENC	300	+50			4706:35 4093	<b>(5006:35) 5127:05</b>	5056:35
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					24-APR-2020		
	<b>REF:</b> EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			4706:35 4093	<b>(5006:35) 5127:05</b>	5036:35
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH	MOS					28-AUG-2013		
	<b>REF:</b>	HRS/MSC ENC	A/R				1879:35 1646		
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS					24-APR-2020		
	<b>REF:</b> EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%			4706:35 4093	<b>(5006:35) 5127:05</b>	5036:35



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION PKG 0	MOS	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
	REF: EMM 71-00-00	ENC							
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS	A/R				25-FEB-2019 4261:15 3688		
	REF: EMM 72-00-00	ENC							
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS		O:0			13-APR-2018		
	PN	HRS/MSC	3500	+500			3830:20	(7330:20) 7450:50	7830:20
	SN-UNKNOWN	ENC		O:0					
<b>OVERHAUL</b>	REF: See Workcard	ENC		O:0					
720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER	MOS	A/R				30-APR-2008 0 0		
	REF: EMM 72-00-00	ENC							
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL	MOS	A/R				25-FEB-2019 4261:15 3688		
	REF: EMM 72-00-00	ENC							
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP	MOS	A/R				25-FEB-2019 4261:15 3688		
	REF: EMM 72-60-00	ENC							
720025	NO. 1 ENGINE - OVERTEMPERATURE	MOS	A/R				30-APR-2008 0 0		
	REF: EMM 72-00-00	ENC							



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS  REF: EMM 72-11-00	MOS HRS/MSC ENC	BF/F				25-FEB-2019 4261:15 3688		
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722030	NO. 1 ENGINE - IMMERSION IN WATER  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 EAAB000D438 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 O:0 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA116067 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION  PKG 0 REF: EMM 72-30-04	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 EAAB000E799 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 O:0 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	
723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS  PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000F265	MOS HRS/MSC		N:0 N:3830:20			13-APR-2018 3830:20		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	24000	N:3310			3310	<b>(24000) 24130</b>	
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAB000E462	MOS HRS/MSC		N:0 N:3830:20			13-APR-2018 3830:20		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	24000	N:3310			3310	<b>(24000) 24130</b>	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAB000F043	MOS HRS/MSC		N:0 N:3830:20			13-APR-2018 3830:20		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	24000	N:3310			3310	<b>(24000) 24130</b>	
723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION  <b>REF: See Workcard</b>	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
<b>UNSCHEDULED MAINTENANCE CHECK</b>									
724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS  <b>REF: EMM 72-00-00</b>	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE  <b>REF: EMM 72-00-00</b>	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724020	NO. 1 ENGINE - HIGH OIL PRESSURE  <b>REF: EMM 72-00-00</b>	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS  <b>REF: EMM 72-00-00</b>	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724050	NO. 1 ENGINE - MATERIAL INGESTION  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
725003	NO. 1 ENGINE - OVERSPEED  REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 A002YLE0 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	O:0 N:2490:54 O:0 N:1915			13-APR-2018 3830:20 3310	(9395) 9525	
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES  LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	5000				13-APR-2018 3830:20 3310	(8830:20) 8950:50	
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 0 REF: EMM 72-50-05	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A002AHP4 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:3830:20 N:3310			13-APR-2018 3830:20 3310	(15000) 15130	



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 85A346	MOS HRS/MSC		N:3158:30 O:0			13-APR-2018 3830:20		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	ENC	15000	N:2485			3310	<b>(15825) 15955</b>	
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN	MOS HRS/MSC	3500	+500 O:0			13-APR-2018 3830:30	<b>(7330:30) 7451</b>	7830:30
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	ENC		O:0					
726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE	MOS HRS/MSC	A/R				30-APR-2008 0		
	<b>REF:</b> EMM 72-00-00	ENC					0		
726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE	MOS HRS/MSC	A/R				30-APR-2008 0		
	<b>REF:</b> EMM 72-00-00	ENC					0		
726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING	MOS HRS/MSC	A/R				30-APR-2008 0		
	<b>REF:</b> EMM 72-00-00	ENC					0		
726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN	MOS HRS/MSC	A/R				30-APR-2008 0		
	<b>REF:</b> EMM 72-00-00	ENC					0		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP 825601-5 008755	MOS HRS/MSC	3500	N:120 O:0 N:3830:20 O:0			13-APR-2018 3830:20	<b>(7330:20) 7450:50</b>	
<b>OVERHAUL</b>	<b>REF:</b> EMM 73-10-02	ENC		N:3310 O:0			3310		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731024	NO. 1 ENGINE - FUEL NOZZLE 319855-01 S/N REF:	MOS HRS/MSC ENC	O/C				24-APR-2020 4706:35 4093		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)  REF: EMM 73-11-05	MOS HRS/MSC ENC	300	+50			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5056:35
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3244882-2 C50836 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION  REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				30-APR-2008 0 0		
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 008755 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-APR-2020 4706:35 4093	(5306:35) 5427:05	5366:35
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-APR-2020 4706:35 4093		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 N/A <b>REF:</b> EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			09-AUG-2019 4571:55 3981	(5171:55) 5292:25	5231:55
<b>REPLACE</b>									
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA32002 <b>REF:</b> EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5036:35
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 U0434 <b>REF:</b> EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:30 O:0 N:944 O:0 N:777 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 <b>REF:</b> EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-651 18348024 <b>REF:</b> EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	O:0 O:0 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 <b>REF:</b> EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS <b>TRACKED ITEM</b>								
	PN	MOS		N:0			13-APR-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			3830:20		
	REF: GENERIC NO REF	ENC		N:0			3310		
731100	NO. 1 ENGINE - CLEAN P3 FILTER								
		MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4706:35	(5006:35) 5127:05	5036:35
	REF: EMM 73-10-07	ENC					4093		
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION						PKG		
	PKG 0	MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4706:35		
	REF: EMM 73-10-02	ENC					4093		
731155	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER - DISCARD								
	3059779-01	MOS		N:0			09-AUG-2019		
	N/A	HRS/MSC	H/T	N:0			4571:55		
	REF: EMM 73-10-02	ENC		N:0			3981		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES						PKG		
	PKG 0	MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4706:35		
	REF: EMM 73-20-00	ENC					4093		
733020	NO. 1 ENGINE - REPLACE P3 FILTER								
		MOS					25-FEB-2019		
		HRS/MSC	900	+10%/-10%			4261:15	(5161:15) 5281:45	5251:15
	REF: EMM 73-10-07	ENC					3688		
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY								
		MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4706:35	(5006:35) 5127:05	5036:35
	REF: See Workcard	ENC					4093		

## CHAPTER 74 IGNITION





# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-APR-2020 4827:05 4223		
<b>ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01</b>									
740010	NO. 1 ENGINE - IGNITION EXCITER 3055889 NNA17010023 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:0 N:278:50 N:-	-43	13-APR-2018 3830:20 3310	(7051:30) 7172	7551:30
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5036:35
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG 10390667-1 NNA17250166 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		13-APR-2018 3830:20 3310		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5036:35
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG 10390667-1 NNA17250167 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		13-APR-2018 3830:20 3310		
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5036:35

## CHAPTER 75 AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX010220 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500			13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
<b>CHAPTER 76 ENGINE CONTROLS</b>									
76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223		
76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 5 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			24-APR-2020 4827:05 4223		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 8 REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223		
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES 76.010 REF: AMM 76-10-02	MOS HRS/MSC AFL	12	+10%/-10%			24-APR-2020 4827:05 4223	24-APR-2021 7827:05	30-MAY-2021 8127:05



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760015	MANUAL OVERRIDE CABLE ASSY. 9419411417	MOS		N:0			30-APR-2008		
76.020	20070086 REF: AMM 76-20-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
760020	CONDITION CABLE ASSY. 9419411418	MOS		N:0			30-APR-2008		
76.030	20070091 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
760025	POWER CONTROL CABLE ASSY. 9419411419	MOS		N:0			30-APR-2008		
76.040	20070089 REF: AMM 76-10-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES	MOS					24-APR-2020		
		HRS/MSC	300	+10%/-10%			4706:35	(5006:35) 5127:05	5036:35
	REF: EMM 72-00-00	ENC					4093		

CHAPTER 77 ENGINE INDICATING

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER	MOS					30-APR-2008		
77.010	9752115206 7533-12-18 REF: AMM 77-40-03	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER	MOS					30-MAY-2018		
77.030	975.21.15.212 2946578 REF: GENERIC NO REF	HRS/MSC AFL	O/C				3952:15 3442		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS	MOS					13-APR-2018		
	3043825-01	HRS/MSC	O/C	N:0			3830:20		
	NRA102519 REF: EMM 77-20-01	ENC		N:0			3310		

CHAPTER 78 EXHAUST



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-00/214 (s)	EXAMINE EXHAUST STUBS PKG 3	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
<b>CHAPTER 79 OIL</b>									
79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK PKG 7	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 79-30-06	HRS/MSC AFL	600	+10%/-10%			4827:05 4223		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT PKG 8	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			4827:05 4223		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 3	MOS	12	+10%/-10%			PKG 24-APR-2020		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%			4827:05 4223		
79-20/43	OIL COOLER 9683214102	MOS					29-MAY-2018		
79.010	T1246	HRS/MSC	3500	+10%/-10%	O:0		3950:50	7450:50	7800:50
<b>OVERHAUL</b>	REF: AMM 79-20-02	AFL			O:0		3440		
790005	TEMPERATURE BULB 9751120101	MOS					30-APR-2008		
79.020	151251	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
790020	PRESSURE,GAGE SWITCH 9738114305	MOS					30-APR-2008		
79.030	840	HRS/MSC	O/C		N:0		0		
	REF: AMM 79-30-04	AFL			N:0		0		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790025	THERMAL ACTUATOR								
79.040	9787301002 978 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
790030	POWER ODM,B049913 MODULE								
79.050	9752115240 45219 REF: AMM 79-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
790035	MODUL,ODM,B057185 SENSOR								
79.060	9752115242 45518 REF: AMM 79-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
<b>DISCARD</b>	REF: GENERIC NO REF								
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS HRS/MSC ENC	12 300	+30d/-10% +10%/-10%			24-APR-2020 4706:35 4093	<b>24-APR-2021</b> <b>(5006:35) 5127:05</b>	24-MAY-2021 5036:35
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS HRS/MSC ENC	12 300	+1m/-1m +10%/-10%			24-APR-2020 4706:35 4093	<b>24-APR-2021</b> <b>(5006:35) 5127:05</b>	24-MAY-2021 5036:35
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS HRS/MSC ENC	900	+10%/-10%	23:45		24-APR-2020 4706:35 4093	<b>(5630:20) 5750:50</b>	5720:20



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN  REF: See Workcard	MOS HRS/MSC ENC	300				24-APR-2020 4706:35 4093	(5006:35) 5127:05	
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN  REF: EMM 72-60-00	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	(5006:35) 5127:05	5036:35
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE  REF: EMM 79-20-02	MOS HRS/MSC ENC	A/R				07-JAN-2009 100 103		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING  REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				30-APR-2008 0 0		
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	PKG	
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			24-APR-2020 4706:35 4093	PKG	
<b>CHAPTER 91</b>	<b>-</b>								
240120	BATTERY EXT POWER JUNCTION BOX 974.03.38.142(FE-1561-02) 266 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-JUN-2010 587:55 522		



# Status Report

PC-12/47E S/N 1008 (LX-TAI): 5077:05 HRS, 4428 AFL as of 19-Nov-2020

Owner/Operator: JETFLY AVIATION SA

Report Date: 24-NOV-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910015	KBT 300 TTP BUS RES, A-157 TERMINAL 9859912117 KBT-300-1133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL 9859912117 KBT-300-1138 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL 9859912117 KBT-300-1124 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX 9740338136 128 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
910035	CO-PILOT RIGHT HD POWER, FE1549R JUNCTION BOX 9740338137 130 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
910040	KBT 300 TTP BUS RES, A-156 TERMINAL 9859912117 KBT-300-1132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		