

OWNER: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

OPERATOR: JETFLY AVIATION SA
ADDRESS: 11 RUE JEAN FISCHBACH
LEUDELANGE L-3372
PHONE: +352 26 19 36 36
FAX:

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 1008/LX-TAI **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 30-APR-2008	5134:05 A/C HRS as of 11-FEB-2021	A/C HRS as of ___/___/___
	4481 AFL as of 11-FEB-2021	AFL as of ___/___/___
	1424:24 ACH as of 24-APR-2020	ACH as of ___/___/___
	4340 FLTS as of 11-FEB-2021	FLTS as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-RY0008/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 29-MAY-2018	LAST ACTUALS	CURRENT ACTUAL
3830:20 ENG. HRS 3950:50 A/C HRS	5013:35 ENG. HRS as of 11-FEB-2021	ENG. HRS as of ___/___/___
3310 ENC	4351 ENC as of 11-FEB-2021	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: KX1250/HC-E4A-3D/E10477SK **MODEL:** HC-E4A-3D **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 24-APR-2020	LAST ACTUALS	CURRENT ACTUAL
3380:55 PROP HRS 4827:05 A/C HRS	3687:55 PROP HRS as of 11-FEB-2021	PROP HRS as of ___/___/___



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05200A	JOB SET UP / CLOSE UP PACKAGE								
	PKG 1 in PKG 3,5,6,7,8,9	MOS					22-JAN-2021	PKG	
	REF: See Workcard	HRS/MSC AFL	A/R				5122 4469		
05401A	300 HOUR INSPECTION								
	PKG 5	MOS					22-JAN-2021		
	REF: See Workcard	HRS/MSC AFL	300	+30/-30	5:05		5122 4469	5427:05	5457:05
05402A	300 HOUR OR 12 MONTHS INSPECTION								
	PKG 3	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
	REF: See Workcard	HRS/MSC AFL	300	+30/-30	5:05		5122 4469	5427:05	5457:05
05403A	600 HOUR INSPECTION								
	PKG 6	MOS					22-JAN-2021		
	REF: See Workcard	HRS/MSC AFL	600/-	+30/-30			5122 4469	5722	5752
05404A	600 HOUR OR 12 MONTHS INSPECTION								
	PKG 7	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
	REF: See Workcard	HRS/MSC AFL	600/-	+30/-30			5122 4469	5722	5752



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTH INSPECTION								
	PKG 8	MOS	12				22-JAN-2021	22-JAN-2022	22-FEB-2022
		HRS/MSC	1200/-				5122	6322	6352
	REF: See Workcard	AFL					4469		
05406A	2400 HOUR OR 24 MONTHS INSPECTION								
	PKG 9	MOS	24				22-JAN-2021	22-JAN-2023	22-FEB-2023
		HRS/MSC	2400				5122	7522	7582
	REF: See Workcard	AFL					4469		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0008 Part # 3072955-01									
057010	NO. 1 ENGINE - MINOR INSPECTION								
	PKG 0	MOS					22-JAN-2021		
		HRS/MSC	300/-				5001:30	(5306:35) 5427:05	5336:35
	REF: See Workcard	ENC			5:05		4339		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						22-JAN-2021	
		HRS/MSC	A/R					5122	
	REF: GENERIC NO REF	AFL						4469	
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						11-FEB-2021	
		HRS/MSC	A/R					5134:05	
	REF: GENERIC NO REF	AFL						4481	
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						11-FEB-2021	
		HRS/MSC	A/R					5134:05	
	REF: GENERIC NO REF	AFL						4481	
00JFL2U	PERFORM WORK FOLLOWING AMM PILATUS NO. 02300 LAST REVISION. NOTE : ALL REPORTED WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
		MOS						17-FEB-2021	
		HRS/MSC	-					5134:05	
	REF:	AFL						4481	
00JFL67	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 6 AMDT 7 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION S.A APPROVAL								
		MOS						27-SEP-2018	
		HRS/MSC	-					4242	
	REF:	AFL						3696	
00JFL7.1	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG ED 7 AMDT 1 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION								
		MOS						22-JAN-2021	
		HRS/MSC	-					5122	
	REF:	AFL						4469	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00JFL7.2	PERFORM INSPECTION FOLLOWING JFL AMP PC12 NG R7.2 NOTE : ALL REPORTED WORK AND/OR SUPPLEMENTARY WORK CAN NOT BE DONE WITHOUT JETFLY AVIATION	MOS HRS/MSC - AFL							
	REF:								
P47E-111209	REVIEW AMM PC12/47E CHAPTER 4 & CHAPTER 5 REVISION 6 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
05.150	REQUIREMENT CHANGE FORMS								
	REF: RCF P47E								
P47E-120202	REVIEW PC-12/47E AMM REVISION 7 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF P47E								
P47E-120322	REVIEW PC-12/47E AMM REVISION 8 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					(EBT)		
	REQUIREMENT CHANGE FORMS								
	REF: RCF P47E								
P47E-130309	REVIEW PILATUS PC12/47E AMM CHAPTER 4 & 5 REVISION 9 - CAMP CHANGE FORM	MOS HRS/MSC - AFL					06-MAY-2013		
	REQUIREMENT CHANGE FORMS								
	REF: RCF P47E								
P47E-130805	REVIEW CAMP TO PILATUS CODE NUMBER CONVERSION TABLE	MOS HRS/MSC - AFL					05-AUG-2013		
	REQUIREMENT CHANGE FORMS								
	REF:								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-140305	REVIEW PC12/47E CHAPTER 4 & 5 REVISION NO. 10 - SUMMARY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-140401	REVIEW PC12/47E CHAPTER 4 TR 04-02 - CAMP CHANGE FORM	MOS					04-APR-2014		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-140731	REVIEW 12-B-AM-00-00-00-I, REVISION 11, DATED MAY 22, 2014 CAMP REQUIREMENT CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-150226	REVIEW 12-B-AM-00-00-00-I, 02300, REVISION 12, DATED 13 JAN 2015 RCF	MOS					09-SEP-2015		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-150923	REVIEW PILATUS PC-12/47E (MSN-1001-UP) AIRCRAFT MAINTENANCE MANUAL REVISION 13, DATED 18-AUGUST-2015-RCF	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-160106	REVIEW PC-12/47E, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 (DOCUMENT NUMBER 02300, 12-B-AM-00-00-00-I) REVISION 14, DATED 11/06/15 - CORRECTED VERSION-CAMP CHANGE FORM	MOS					04-MAY-2016		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15	MOS						23-NOV-2016	
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - AFL							
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16	MOS						08-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-170719	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 17	MOS						11-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04	MOS						22-FEB-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18	MOS						08-JUN-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS						24-JUL-2019	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS						20-APR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS						12-AUG-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24	MOS						13-FEB-2021	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-140908	NO. 1 ENGINE - REVIEW DATED JUL 07/2014	PWC, PT6A-67B/-67P	ENGINE MAINTENANCE MANUAL(P/N 3038336 REVISION NO. 41.0					09-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150226	NO. 1 ENGINE - REVIEW 12/2015 RCF	PWC, PT6A-67B / -67P, (P/N 3038336)	ENGINE MAINTENANCE MANUAL REV. 42.0 DATED JAN					(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150404	NO. 1 ENGINE - REVIEW RCF	PWC, PT6A-72-14002	REVISION NO. 22 DATED NOV 16/2012					(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0							09-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25							15-JUL-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0							03-JUN-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26	MOS						01-FEB-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1	MOS						31-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24	MOS						07-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0	MOS						16-JUN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1	MOS						04-SEP-2017	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072-170818	HRS/MSC - ENC							
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0	MOS						30-APR-2008	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC						0 0	
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS						26-MAR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS						13-JAN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS						23-APR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS					10-JUN-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS					13-JAN-2021		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1250 Part # HC-E4A-3D/E10477SK									
P019-150423	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 7, DATED APR 15/15 RCF	MOS					10-SEP-2015 729		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-150901	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER INC, SERVICE LETTER HC-SL-61-61Y REVISION 8, DATED AUG 03/15-RCF	MOS					30-NOV-2015		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160201 (s)	NO. 1 PROPELLER - REVIEW HARTZWELL PROPELLER HC-E4A-3 POM REV 22	MOS					31-JAN-2017		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS					16-SEP-2016		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS HRS/MSC -						22-FEB-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-180301	NO. 1 PROPELLER - REVIEW HARTZELL HC-34A-3 POM 147 REV 14	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-180701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 24	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-190401	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 25	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-191101	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 147 REV 15	MOS HRS/MSC -						13-JAN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF P019								
P019-200301	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL (MANUAL 180) REVISION 32	MOS HRS/MSC -					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P019-200501	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-200501-1	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 147 REV 16	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-200701	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 149 REV 27	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 33	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-200901	NO. 1 PROPELLER - REVIEW HC-E4A-3 POM 147 REV 17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: See Workcard	HRS/MSC -							
P019-200901-1	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV 34	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

P019-210201 NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35
 MOS (EBT)
 HRS/MSC -
REQUIREMENT CHANGE FORMS REF: RCF P019
 NEW REQUIREMENT ADDED ON 11-FEB-2021 (EFFECTIVE: 01-FEB-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.

P019-210304 NO. 1 PROPELLER - REVIEW SERVICE LETTER HC-SL-61-61Y REVISION 13
 MOS (EBT)
 HRS/MSC -
REQUIREMENT CHANGE FORMS REF: RCF P019
 NEW REQUIREMENT ADDED ON 18-MAR-2021 (EFFECTIVE: 04-MAR-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.

CHAPTER 04 LIMITATIONS

040001 AIRCRAFT LIMIT OF VALIDITY
 PN MOS N:0 30-APR-2008
 SN-UNKNOWN HRS/MSC 25000 N:0 0 25000
LIFE LIMIT REF: GENERIC NO REF AFL 30000 N:0 0 30000

040005 AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY
 PN MOS N:0 30-APR-2008
 SN-UNKNOWN HRS/MSC 35000 N:0 0 35000
LIFE LIMIT REF: GENERIC NO REF AFL 43000 N:0 0 43000

040005 AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY
 PN MOS N:0 30-APR-2008
 SN-UNKNOWN HRS/MSC 35000 N:0 0 35000
LIFE LIMIT REF: GENERIC NO REF AFL 43000 N:0 0 43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-01 UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING
 MOS 30-APR-2008
 HRS/MSC A/R 0
 AFL 0
 REF: See Workcard

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER PROPELLER SUDDEN STOPPAGE OR IMPACT	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					30-APR-2008		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					30-APR-2008		
	REF: AMM 05-10-30	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					30-APR-2008		
	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
05JFL11	- AIRWORTHINESS REVIEW CERTIFICATE TRACKED ITEM	MOS					25-JUL-2020	02-AUG-2021 M	
	REF:	HRS/MSC	DUE				4940:30		
		AFL					4324		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05JFL12	- CERTIFICATE OF REGISTRATION	MOS HRS/MSC AFL	A/R						
	REF:								
05JFL13	- NOISE CERTIFICATE	MOS HRS/MSC AFL	A/R						
	REF:								
05JFL14	- AIRCRAFT STATION LICENCE	MOS HRS/MSC AFL	DUE				16-NOV-2018	31-DEC-2021	M
	REF:								

CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS HRS/MSC AFL	A/R				22-JAN-2021	5122	4469
	REF: AMM 06-20-00								
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS HRS/MSC AFL	A/R				22-JAN-2021	5122	4469
	REF: AMM 06-20-00								
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR.						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS HRS/MSC AFL	A/R				22-JAN-2021	5122	4469
	REF: AMM 06-20-00								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOINTHE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						22-JAN-2021	
		HRS/MSC	A/R					5122	
	REF: GENERIC NO REF	AFL						4469	
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						22-JAN-2021	
		HRS/MSC	A/R					5122	
	REF: AMM 07-10-00	AFL						4469	
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS						22-JAN-2021	
		HRS/MSC	A/R					5122	
	REF: AMM 07-10-00	AFL						4469	
CHAPTER 08 LEVELING AND WEIGHING									
08JFL01	WEIGHT AND BALANCE								
		MOS	60	+1m/-1m				22-JAN-2021	22-JAN-2026 22-FEB-2026
		HRS/MSC						5122	
	REF:	AFL						4469	
08JFLSB	WEIGHT AND BALANCE MUST BE RECALCULATED(FILL FORM W&B IN, POH SECTION 6)								
		MOS						24-APR-2020	
		HRS/MSC	A/R					4827:05	
	REF:	AFL						4223	
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 3	MOS	12	+10%/-10%				22-JAN-2021	
		HRS/MSC	300	+10%/-10%				5122	
	REF: GENERIC NO REF	AFL						4469	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 11									
PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 8	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	1200	+10%/-10%			5122		
	REF: See Workcard	AFL					4469		
CHAPTER 12									
SERVICING									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					22-JAN-2021		
		HRS/MSC	A/R				5122		
	REF: AMM 12-20-01	AFL					4469		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
		HRS/MSC	A/R				5134:05		
	REF: AMM 12-20-02	AFL					4481		
12-20/126 (s)	CLEAN COCKPIT AND CABIN						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
		HRS/MSC	A/R				5134:05		
	REF: AMM 12-20-03	AFL					4481		
CHAPTER 20									
STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
20.010		HRS/MSC					5122		
	REF: AMM 20-40-00	AFL					4469		
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
		MOS	6	+10%/-10%			22-JAN-2021	22-JUL-2021	09-AUG-2021
20.011		HRS/MSC	300	+10%/-10%			5122	5422	5452
	REF: AMM 20-40-00	AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20JFL01	PERFORMED DENTS AND BUCKLES CHARTS	MOS					22-JAN-2021		
	REF:	HRS/MSC	300	+10%/-10%		5:05	5122	5427:05	5457:05
		AFL					4469		
CHAPTER 21 AIR CONDITIONING									
21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE						PKG		
	PKG 9	MOS	24	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC	2400	+10%/-10%			5122		
		AFL					4469		
21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
	ALI	HRS/MSC	3000				5122	8122	
	REF: GENERIC NO REF	AFL					4469		
21-30/314	REMOVE/CLEAN PRESSURIZATION SAFETY VALVE								
	PN	MOS	24	+10%/-10%		19	24-APR-2020	13-MAY-2022	25-JUL-2022
	21.030	SN-UNKNOWN	3000	+10%/-10%			4827:05	7827:05	8127:05
	REF: AMM 21-30-02	AFL					4223		
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
	21.045	HRS/MSC	3000				5122	8122	
	ALI	REF: AMM 21-30-00	AFL				4469		
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
	PN	MOS	24	+10%/-10%		19	24-APR-2020	13-MAY-2022	25-JUL-2022
	21.040	SN-UNKNOWN	3000	+10%/-10%			4827:05	7827:05	8127:05
	REF: AMM 21-30-00	AFL					4223		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/463	OPERATIONAL TEST CABIN PRESSURIZATION DUMP CONTROL	MOS						30-APR-2008	
	REF: AMM 21-30-00	HRS/MSC	N/A					0	
		AFL						0	
21-30/464	OPERATIONAL TEST CABIN PRESSURIZATION MANUAL CONTROL	MOS						30-APR-2008	
	REF: AMM 21-30-00	HRS/MSC	N/A					0	
		AFL						0	
21-30/465	FUNCTIONAL TEST CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE	MOS						30-APR-2008	
	REF: AMM 21-30-00	HRS/MSC	N/A					0	
		AFL						0	
21-30/466	CHECK CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND	MOS						30-APR-2008	
	REF: AMM 21-30-02	HRS/MSC	N/A					0	
		AFL						0	
21-30/467	EXAMINE CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE	MOS						30-APR-2008	
	REF: AMM 21-30-05	HRS/MSC	N/A					0	
		AFL						0	
21-30/468	FUNCTIONAL TEST CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION	MOS						30-APR-2008	
	REF: AMM 21-30-00	HRS/MSC	N/A					0	
		AFL						0	
21-30/469	FUNCTIONAL TEST CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING	MOS						30-APR-2008	
	REF: AMM 21-30-00	HRS/MSC	N/A					0	
		AFL						0	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH						PKG		
21.140	PKG 8 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
21-40/331	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH								
21.150	9696781507 PKG 8 529418 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481	11-FEB-2022 6334:05	17-MAR-2022 6454:05
21-40/50	CLEAN WATER SEPARATOR CONDENSER								
21.080	5214112060 PKG 8 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481	11-FEB-2022 6334:05	17-MAR-2022 6454:05
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
21.130	973.81.32.216 0527 REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	-4		29-MAY-2018 3950:50 3440	25-MAY-2023 8750:50	25-NOV-2023 9230:50
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
21.120	9738132214 55 REF: AMM 21-60-05	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%	-4		29-MAY-2018 3950:50 3440	25-MAY-2023 8750:50	25-NOV-2023 9230:50
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 6 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			22-JAN-2021 5122 4469		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 6 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			11-FEB-2021 5134:05 4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT PKG 8	MOS	12	+10%/-10%			PKG	22-JAN-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			5122 4469		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED) 9599022102	MOS					22-JAN-2021		
	883	HRS/MSC	300	+10%/-10%			5122	5422	5452
	REF: See Workcard	AFL					4469		
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED) 9599022102	MOS					30-APR-2008		
	883	HRS/MSC	N/A				0		
	REF: AMM 21-50-03	AFL					0		
		ACH							
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED) 9599022102	MOS					30-APR-2008		
	883	HRS/MSC	N/A				0		
	REF: AMM 21-50-01	AFL					0		
		ACH							
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED) 9599022102	MOS					04-AUG-2017		
21.110	883	HRS/MSC					3689:40		
	REF: AMM 21-50-03	AFL					3213		
		ACH	500	+10%/-10%			1069:30	1569:30	1619:30
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED 9599022102	MOS					04-AUG-2017		
21.100	883	HRS/MSC					3689:40		
	REF: AMM 21-50-01	AFL					3213		
		ACH	500	+10%/-10%	-35:30		1069:30	1534	1584

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210005	OVERPRESSURE SWITCH								
21.340	9738115105 1922 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-AUG-2020 4979:25 4358		
210010	REFRIGERATION PACK								
21.255	9599020111 1453 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1433 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 1633 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1434 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 1426 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210035	WATER SEPARATOR ASSY								
21.220	5214112060 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:153 N:5122 N:4469			22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210040	TEMPCONTROL VALVE								
21.310	9599020136 1421 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022102 883 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	9599022141 0553 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JAN-2021 5122 4469		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 282 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	103898-3 103-898-00312 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C				20-JUL-2018 4093:50 3577		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091132 117-F0012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER 9696781507 21.240 529418 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY 9599022118 21.200 289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210145	CABIN (REAR) ELECTRIC HEATER 9696781507 21.230 529423 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210170	OVERPRESSURE SWITCH 973.81.15.106 21.340 1936 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2020 4992:40 4366		
210175	FLOW CONTROL VALVE ACTUATOR 959.90.20.160 21.175 1426 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C				03-MAR-2016 2977:20 2611		
210180	CABIN PRESSURE CONTROL UNIT 2119232-3 21.180 2119232-00504 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				09-FEB-2018 3900 3388		
210185	INTEG. ECS CONTROL 6130C000-002 959.90.20.129 21.185 0539 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C				03-MAR-2016 2977:20 2611		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210190	FLOOR DUCT TEMP. SENSOR 9599020121 1624 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR 959.90.20.121 3679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
210200	FIREWALL 1415-3 SHUT OFF VALVE 9633011005 62 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH 973.81.32.216 0527 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-APR-2013 1685:55 1507		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH 9738132214 55 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK 9633011105 0714B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK 9633011106 0662B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK 9633011106 0668B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK 9633011106 0682B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR 9599020121 1492 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
210240	INSULATED, WATER SEPERATOR ASSY 521.41.12.060 2568 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
21JFL01	PERFORM STATEMENT HOURS AIR-CONDITIONING REF:	MOS HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469	5422	5452
21JFL02	AIR CONDITIONING -RECOVERY OF REFRIGERANT AND LEAK TEST REF:	MOS HRS/MSC AFL	24	+10%/-10%			22-JAN-2021 5122 4469	22-JAN-2023	03-APR-2023
21JFL03	CLEANING OF SENSORS FOR CABIN HEATING REF:	MOS HRS/MSC AFL	300	+10%/-10%				?	?

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 22	AUTO FLIGHT								
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 9	MOS	24	+10%/-10%			22-JAN-2021		
		HRS/MSC	2400	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
22.010		HRS/MSC	1000	+10%/-10%			5122	6122	6222
	REF: AMM 22-10-00	AFL					4469		
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 22-20-02	AFL					4469		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM						PKG		
	PKG 5	MOS					22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 22-20-00	AFL					4469		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM						PKG		
	PKG 8	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	1200	+10%/-10%			5122		
	REF: AMM 22-20-00	AFL					4469		
220045	STICK PUSHER SERVO								
	9786111103	MOS					30-APR-2008		
22.220	80299	HRS/MSC	O/C				0		
	REF: AMM 22-20-04	AFL					0		
220055	STICK PUSHER CAPSTAN								
	9786111124	MOS					30-APR-2008		
22.140	80304	HRS/MSC	O/C				0		
	REF: AMM 22-20-06	AFL					0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220060	STICK SHAKER								
22.230	9786111143 807 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220070	STICK PUSHER								
22.170	9754423104 122170 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220075	KMC 9200 FLIGHT CONTROLLER								
	071-01597-0401 KMC9200-1206 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
	9859912133 KSM375-1047 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
	9859912133 KSM375-B1040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
	9859912133 KSM375-B1046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
220100	RUDDER KSA 2700 SERVO								
	065-00190-0101 KSA2700-1715 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:9 R:0 R:0			16-NOV-2013 1983:40 1742		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220105	ELEVATOR KSA 2700 SERVO 065-00190-0101 KSA2700-1655 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-MAR-2018 3937:25 3429		
220110	AILERON KSA 2700 SERVO 065-00190-0101 KSA2700-1034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-MAR-2018 3937:25 3429		
CHAPTER 23 COMMUNICATIONS									
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH PKG 9 REF: AMM 23-50-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH PKG 9 REF: AMM 23-12-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
23-LUX-01	EXAMINE OF COCKPIT VOICE RECORDER RECORDED SIGNAL IN ACCORDANCE WITH ICAO ANNEX 6 PART II REQUIREMENTS REF:	MOS HRS/MSC AFL	N/A						
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA 9848110203 310-17351 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C				30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-17330 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
	9848110210 7628 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
	9859912134 1355 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
	9859912134 1405 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
	9859912108 D0136 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
	9859912020 Q02691 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C				29-APR-2020 4832:10 4229		

CHAPTER 24 ELECTRICAL POWER

24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%			22-JAN-2021 5122 4469	22-JAN-2022 8122	27-FEB-2022
AIRWORTHINESS									

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025	PN	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
AIRWORTHINESS	SN-UNKNOWN REF: AMM 71-00-00	HRS/MSC AFL	3000				5122 4469	8122	
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST								
	PKG 9	MOS	24	+10%/-10%			22-JAN-2021		
	REF: AMM 24-40-00	HRS/MSC AFL	2400	+10%/-10%			5122 4469		
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST								
	PKG 8	MOS	12	+10%/-10%			22-JAN-2021		
	REF: AMM 71-00-00	HRS/MSC AFL	1200	+10%/-10%			5122 4469		
24-30/339	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	PN	MOS					30-APR-2008		
	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	N/A				0 0		
24-30/339	REMOVE AND SERVICE NO. 2 NICAD BATTERY								
24.061	PN	MOS					30-APR-2008		
	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	N/A				0 0		
24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
	TRACKED ITEM								
24.010	RG-380E/44	MOS	6	+10%/-10%			22-JAN-2021	22-JUL-2021	09-AUG-2021
	40885352	HRS/MSC	600	+10%/-10%			5122	5722	5782
	REF: AMM 24-30-07	AFL					4469		
24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44	MOS	6	+10%/-10%			22-JAN-2021	22-JUL-2021	09-AUG-2021
	40743113	HRS/MSC	600	+10%/-10%			5122	5722	5782
	REF: AMM 24-30-07	AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/473	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) 978.91.23.407 PKG 6 P1142 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			11-FEB-2021 5134:05 4481	5734:05	5794:05
24-30/474	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407) 978.91.23.407 PKG 6 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			22-JAN-2021 5122 4469	5722	5782
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR 978.91.23.407 P1142 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200				24-APR-2020 4827:05 4223	6027:05	
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200				24-APR-2020 4827:05 4223	6027:05	
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR 978.91.23.407 P1142 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A				24-APR-2020 4827:05 4223		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				24-APR-2020 4827:05 4223		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 9	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			22-JAN-2021 5122 4469		
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 501.1712.02	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
24.050	81999 REF: AMM 24-52-51	HRS/MSC AFL					5122 4469		
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 9	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			22-JAN-2021 5122 4469		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111	MOS			N:0		30-APR-2008		
24.120	P1680 REF: AMM 24-30-05	HRS/MSC AFL	O/C		N:0 N:0		0 0		
240010	GENERATOR 1 300A CONTACTOR 9740338113	MOS			N:0		30-APR-2008		
24.130	N864 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0		0 0		
240015	GENERATOR 2 300A CONTACTOR 9740338113	MOS			N:0		30-APR-2008		
24.130	N815 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0		0 0		
240135	NO. 1 LEAD ACID BATTERY RG-380E/44	MOS			N:41		22-JAN-2021		
24.010	40885352 REF: AMM 24-30-07	HRS/MSC AFL	O/C		N:1432:20 N:1256		5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240140	NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44 40743113 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				22-JAN-2021 5122 4469		
243010	NO. 2 STARTER-GENERATOR								
24.215	978.91.23.407 P1706 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 N:3044:19 O:0 N:3165 O:0			24-APR-2020 4827:05 4223		
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501.1712.02 81999 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				22-JAN-2021 5122 4469		
243160	NO. 1 STARTER GENERATOR								
24.205	978.91.23.407 P1142 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:33 N:3235:55 O:1137:25 N:2706 O:1010			24-APR-2020 4827:05 4223		
243170	110 VOLT STATIC ,SS50 INVERTER								
	9750215107 3663 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER 9755085111 N217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER 9755085111 N208 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
243190	VOLTAGE REGULATOR 9882114111 P1680 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-10/134 (s)	EXAMINE CREW COPILOT SEAT BELTS PKG 3 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
25-10/134 (s)	EXAMINE CREW PILOT SEATBELT PKG 3 REF:	MOS HRS/MSC AFL	12 300				PKG 22-JAN-2021 5122 4469		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 22-JAN-2021 5122 4469		
25-10/294	CREW SEAT BELTS PN 25.030 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	144		N:1 N:0 N:0		24-APR-2020 4827:05 4223	24-MAR-2032	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 1 ,3,5,6,7,8,9 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 11-FEB-2021 5134:05 4481		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,3,5,6,7,8,9 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 11-FEB-2021 5134:05 4481		
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 8 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
25-20/295	NO. 1 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 2 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 3 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 4 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 5 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295	NO. 6 PASSENGER SEAT BELT 5-02-2T4718MINI REVB SN-UNKNOWN REF:	MOS HRS/MSC AFL	144	N:1 N:0 N:0			27-JUL-2020 4940:25 4324	27-JUN-2032	
25-20/295 25.010 OVERHAUL	PASSENGER SEAT BELTS 5-02-2T4718MINI REVB SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	N:1 N:0 N:0	-94		27-JUL-2020 4940:25 4324	25-MAR-2032	
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 1 ,3,5,6,7,8,9 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 11-FEB-2021 5134:05 4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,3,5,6,7,8,9 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 11-FEB-2021 5134:05 4481		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 22-JAN-2021 5122 4469		
25-60/231	OPERATIONAL TEST ELT S182502-02 PKG 3 2619367-0048 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%		5:05	22-JAN-2021 5122 4469	22-JAN-2022 5427:05	27-FEB-2022 5457:05
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED S182502-02 2619367-0048 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
25-63/23 25.020 DISCARD Expiry Date: 31-AUG-2026	ELT BATTERY 985.13.80.855 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE		N:72 N:2712:15 N:2371		24-APR-2020 4827:05 4223	31-AUG-2026 M	
25-63/434 DISCARD	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) S1825501-02 KA0021338001 REF: GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			29-MAY-2018 3950:50 3440	29-MAY-2028 19950:50	29-NOV-2028 20450:50

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250005	REMOTE CONTROL PANEL 9851380817 2617088-0230 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
250010	EMERGENCY LOCATOR TRANSMITTER S182502-02 2619367-0048 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-APR-2013 1685:55 1507		
250015	IPECO PILOT SEAT 959.30.01.145 50976 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:86 N:0			11-JUN-2015		
250020	IPECO CO-PILOT SEAT 959.30.01.146 50982 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:86 N:0			11-JUN-2015		
250021	NO. 1 PASSENGER SEAT 959.30.01.819 37448 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
250022	NO. 2 PASSENGER SEAT 959.30.01.820 37449 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
250023	NO. 3 PASSENGER SEAT 959.30.01.829 37450 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
250024	NO. 4 PASSENGER SEAT 959.30.01.830 37452 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250025	NO. 5 PASSENGER SEAT 959.30.01.833 37451 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
250026	NO. 6 PASSENGER SEAT 959.30.01.834 37453 REF:	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE S1825501-02 KA0021338001 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2018 3950:50 3440		
256015	CABLE ,S1825503-01 ASSEMBLY 9851380859 2611902-0036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
25JFL02	PERFORMED FIRST AID KIT INSPECTION REF:	MOS HRS/MSC AFL	12	+1m/-1m	22		22-JAN-2021 5122 4469	13-FEB-2022	13-MAR-2022
25JFL04	PERFORM VISUAL INSPECTION LIFE VEST REF:	MOS HRS/MSC AFL	12	+1m/-1m			22-JAN-2021 5122 4469	22-JAN-2022	22-FEB-2022
CHAPTER 26	FIRE PROTECTION								
26-20/2	COCKPIT FIRE EXTINGUISHER BA51015R-5 94243 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	120	N:0 N:0 N:0	-99		18-MAR-2015 2553:15 2209	09-DEC-2024	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/24	CABIN FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)	MOS HRS/MSC N/A AFL							
	REF: GENERIC NO REF								
26-20/24	CONTENTS CHECK FIRE EXTINGUISHER (DAC-AIR 348)	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
26.010	BA51015R-5 94243	HRS/MSC AFL							
	REF: GENERIC NO REF								
26-20/515	CABIN FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224)	MOS HRS/MSC N/A AFL					30-APR-2008 0 0		
	REF: GENERIC NO REF								
26-20/515	COCKPIT FIRE EXTINGUISHER CONTENT CHECK (MODEL P3APP003010D - P/N 959.08.06.224)	MOS HRS/MSC N/A AFL					30-APR-2008 0 0		
	REF: GENERIC NO REF								
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)	MOS HRS/MSC N/A AFL					30-APR-2008 0 0		
	REF: GENERIC NO REF								
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)	MOS HRS/MSC N/A AFL					30-APR-2008 0 0		
	REF: GENERIC NO REF								
260005	FIRE/OVERHEAT DETECTOR	MOS					30-APR-2008		
26.020	9751210012 208678	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
	REF: AMM 26-10-01								

CHAPTER 27 FLIGHT CONTROLS

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL PKG 5	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES	MOS							
27.255	REF: GENERIC NO REF	HRS/MSC AFL	N/A				30-APR-2008 0 0		
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK	MOS	60	+10%/-10%					
27.010	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%	-3:45		04-AUG-2017 3689:40 3213	04-AUG-2022 8485:55	04-FEB-2023 8965:55
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001) PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			22-JAN-2021 5122 4469		
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			22-JAN-2021 5122 4469		
27-10/236 (s)	AILERON CONTROL SYSTEM - INSPECTION/ CHECK PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%			22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/237 (s)	CHECK AILERON CABLE TENSION PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
27-10/238 (s)	FUNCTIONAL TEST AILERONS PKG 9	MOS	24	+10%/-10%			PKG		
	REF: AMM 27-10-00	HRS/MSC AFL	2400	+10%/-10%			22-JAN-2021 5122 4469		
27-10/394	AILERON CONTROL SYSTEM - EXAMINE	MOS							
AIRWORTHINESS	REF: AMM 27-10-00	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS							
AIRWORTHINESS	REF: AMM 27-10-09	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS							
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS							
AIRWORTHINESS	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS	MOS							
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS	MOS							
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-60-06	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-10/444	FLIGHT CONTROL CABLES, AILERON	MOS		N:0			30-APR-2008		
LIFE LIMIT	REF: AMM 27-10-01	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	20000 27000	
27-10/445	AUTOPILOT CONTROL CABLE, AILERON	MOS		N:0			30-APR-2008		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	20000 27000	
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS	MOS	12	+10%/-10%			PKG		
	PKG 8	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
	REF: AMM 27-10-00								
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM	MOS	24	+10%/-10%			PKG		
	PKG 9	HRS/MSC AFL	2400	+10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 27-15-00								
27-20/140 (s)	INSPECTION/CHECK RUDDER	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 55-40-00								
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS	MOS	24	+10%/-10%			PKG		
	PKG 9	HRS/MSC AFL	2400	+10%/-10%			22-JAN-2021 5122 4469		
	REF: GENERIC NO REF								
27-20/241 (s)	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK	MOS	12	+10%/-10%			PKG		
	PKG 8	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
	REF: AMM 27-20-00								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 8	MOS	12	+10%/-10%			PKG 11-FEB-2021 5134:05 4481		
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%					
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 9	MOS	24	+10%/-10%			PKG 22-JAN-2021 5122 4469		
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%					
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 9	MOS	24	+10%/-10%			PKG 22-JAN-2021 5122 4469		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%					
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG 11-FEB-2021 5134:05 4481		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 27-20-04	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 27-20-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					30-APR-2008		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)								
	PN	MOS					30-APR-2008		
	SN-UNKNOWN	HRS/MSC	A/R				0		
	REF: AMM 27-20-00	AFL					0		
27-20/446	FLIGHT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-20-01	AFL	27000	N:0			0	27000	
27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-20-02	AFL	27000	N:0			0	27000	
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 9	MOS	24	+10%/-10%			22-JAN-2021		
		HRS/MSC	2400	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
27-30/249 (s)	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: AMM 27-30-00	AFL					4481		
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: AMM 27-30-00	AFL					4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 9 REF: AMM 27-30-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED REF: AMM 27-30-00	MOS HRS/MSC AFL	O/C				16-APR-2013 1685:55 1507		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR) PN SN-UNKNOWN REF: AMM 27-30-00	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE REF: AMM 27-30-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS REF: AMM 27-00-01	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER REF: AMM 27-30-05	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL	27000	N:0			0		27000
27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-02	AFL	27000	N:0			0		27000
27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: See Workcard	AFL					4481		
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
27.021		HRS/MSC	3000				5122	8122	
	REF: AMM 27-40-00	AFL					4469		
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 27-40-00	AFL					4469		
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: AMM 27-40-01	AFL					4481		
27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	129.1.1100.02	MOS	84				24-APR-2020	24-APR-2027	
	920	HRS/MSC	3400				4827:05	8227:05	
OVERHAUL	REF: GENERIC NO REF	AFL					4223		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 5	MOS					PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
27-40/3	REPLACE PITCH TRIM ACTUATOR 129.1.1100.02	MOS					24-APR-2020		
	920	HRS/MSC	20000				4827:05	24827:05	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000				4223	31223	
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) 978.73.14.203	MOS		N:0			30-APR-2008		
27.036	883	HRS/MSC	10000	N:0			0	10000	
	REF: AMM 27-40-02	AFL		N:0			0		
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 1 ,3,5,6,7,8,9	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R				11-FEB-2021 5134:05 4481		
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM ESPECIALLY AT THE TOP OF THE FLAP DRIVE ARMS PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
27-50/28	FLAP POWER DRIVE UNIT 978.73.20.003	MOS					25-FEB-2019		
27.030	0953	HRS/MSC	10000	+500/-500			4381:45	14376:20	14876:20
OVERHAUL	REF: AMM 27-50-01	AFL	13500	+500/-500		-5:25	3818	17318	17818
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.040	2334	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.041	2281	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.050	2328	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR 9787320309	MOS					24-APR-2020		
27.051	0425	HRS/MSC	5000	+10%/-10%			4827:05	9827:05	10327:05
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			4223	11223	11723
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202205	MOS					30-APR-2008		
27.060	S6147	HRS/MSC	10000	+500/-500			0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500			0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202206	MOS					30-APR-2008		
27.060	S6097	HRS/MSC	10000	+500/-500			0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500			0	13500	14000

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			30-APR-2008		
27.070	S6153	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			30-APR-2008		
27.070	S6075	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					30-APR-2008		
		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	30000				0	30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS								
		MOS					30-APR-2008		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	30000 39000				0 0	30000 39000	
27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS					24-APR-2020		
27.040	9787320309	HRS/MSC	20000	O:0			4827:05	19564:05	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:5263 O:0 N:4503 O:0			4223	26720	
27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS					24-APR-2020		
27.041	9787320309	HRS/MSC	20000	O:0			4827:05	19564:05	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:5263 O:0 N:4503 O:0			4223	26720	
27-50/4	RIGHT INBOARD FLAP ACTUATOR	MOS					24-APR-2020		
27.050	9787320309	HRS/MSC	20000	O:0			4827:05	19564:05	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:5263 O:0 N:4503 O:0			4223	26720	
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR	MOS					24-APR-2020		
27.051	9787320309	HRS/MSC	20000	O:0			4827:05	15024:34	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:9802:31 O:0 N:11563 O:0			4223	19660	
27-50/414	LEFT HAND FLAP	MOS					22-DEC-2018		
57.060	557.50.12.003	HRS/MSC	25000	N:128 R:0			4320	25000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:4320 R:0 N:3765 R:0			3765	30000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/414	RIGHT HAND FLAP 5575012004	MOS		N:0			30-APR-2008		
57.060	796P	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0	30000	
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	600	+10%/-10%			5122	5722	5782
		AFL					4469		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 12-20-07	AFL					4469		
27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0	27000	
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
		HRS/MSC	A/R				5134:05		
	REF: GENERIC NO REF	AFL					4481		
27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR								
	9787320309 PKG 3	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
27.040	2334	HRS/MSC	300	+10%/-10%	5:05		5122	5427:05	5457:05
	REF: AMM 27-50-00	AFL					4469		
27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR								
	9787320309 PKG 3	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
27.041	2281	HRS/MSC	300	+10%/-10%	5:05		5122	5427:05	5457:05
	REF: AMM 27-50-00	AFL					4469		
27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR								
	9787320309 PKG 3	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
27.050	2328	HRS/MSC	300	+10%/-10%	5:05		5122	5427:05	5457:05
	REF: AMM 27-50-00	AFL					4469		



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 PKG 3 0425 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%		5:05	22-JAN-2021 5122 4469	22-JAN-2022 5427:05	22-FEB-2022 5457:05
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 2334 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 2281 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 2328 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 0425 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			24-APR-2020 4827:05 4223	24-APR-2022 7227:05 7423	06-JUL-2022 7467:05 7743
270003	HORIZONTAL TAIL ASSY								
	5551012037 816 REF: AMM 55-10-01	MOS HRS/MSC AFL					30-APR-2008 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012039 829 REF: AMM 55-20-01	MOS HRS/MSC AFL					30-APR-2008 0 0		
270023	ELEVATOR RH ASSY								
27.023	5552012040 832 REF: AMM 55-20-01	MOS HRS/MSC AFL					30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270025	RUDDER TRIM LINEAR ACTUATOR								
	9787318138	MOS		N:0			05-DEC-2009		
27.090	201	HRS/MSC	O/C	N:0			420:40		
LIFE LIMIT	REF: AMM 27-25-01	AFL		N:0			377		
	ACH								
270030	FIN ASSY								
	5553012039	MOS		N:0			30-APR-2008		
27.031	796P	HRS/MSC	O/C	N:0			0		
	REF: AMM 55-30-01	AFL		N:0			0		
270033	RUDDER ASSY								
	5554012038	MOS		N:0			30-APR-2008		
27.033	795P	HRS/MSC	O/C	N:0			0		
	REF: AMM 55-40-01	AFL		N:0			0		
270035	FLAP CONTROL AND WARNING UNIT								
	9787320017	MOS		N:0			30-APR-2008		
27.130	121897	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-05	AFL		N:0			0		
270040	FLEXSHAFT,FLAP,OUTB,B70016707.2A								
	9450202206	MOS		N:0			30-APR-2008		
	S6075	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		
270045	LH INBOARD TRANSMITTER								
	9787320021	MOS		N:0			30-APR-2008		
27.100	077086DW	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-06	AFL		N:0			0		
270050	LH ROTATION TRANSMITTER								
	9787320602	MOS		N:0			30-APR-2008		
27.120	1091	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-06	AFL		N:0			0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 077016DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 077060DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1093 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270080	KTA2810,TRIM ADAPTER								
	065-00195-0100 KTA2810-1736 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:35 N:1291:25 N:1104			03-MAR-2016 2977:20 2611		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318132 1685 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 077031DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
274020	PITCH TRIM ACTUATOR								
	129.1.1100.02 920 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	O:0 O:0 O:0			24-APR-2020 4827:05 4223		
27JFL01	EXCHANGE RELAYS K161E2 & K161D2								
DISCARD	REF:	MOS HRS/MSC AFL	N/A				22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 28	FUEL								
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS					13-NOV-2017		
		HRS/MSC	2400	+10%/-10%	49:15		3830:20	6279:35	6519:35
	REF: AMM 28-10-01	AFL					3330		
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 28-20-07	AFL					4469		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: See Workcard	AFL					4469		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N)						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
28-20/32 28.010 OVERHAUL	OVERHAUL ENGINE DRIVEN PUMP 968.84.51.108 B34309 REF: AMM 28-20-03	MOS HRS/MSC AFL	3500	O:4 O:0		92:20	17-FEB-2017 3407:40 2967	7000	
280005 28.120	LOW PRESSURE FUEL PUMP 968.84.51.108 B34309 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	O:4 O:0 O:0			30-MAR-2017 3407:40 2967		
280010 28.130	FUEL FLOW TRANSMITTER 975.35.12.106 0826-004 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-SEP-2010 706:30 634		
280015 28.110	FIREWALL FUEL,SHUT-OFF VALVE 9638722301 2057 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280020 28.110	MAINTENANCE FUEL SHUT-OFF VALVE 9638722301 2058 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280025 28.025	FUEL FILTER ASSY 9683521001 2007FFT2271 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280030 28.100	FUEL LOW PRESSURE SWITCH 9738114102 1514 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B3902 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B4168 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731220 127 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731219 113 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731218 120 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731217 100 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 B6760 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B3864 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B4175 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731217 103 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731218 117 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	975.37.31.219 102 REF: AMM 28-40-01	MOS HRS/MSC AFL ACH FLTS	O/C	R:22 R:0 R:0 R:0 R:0			20-JUL-2011 965:10 866		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731220 2028 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-JUN-2014 2222:50 1943		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 B6738 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280105	TOP CHECK VALVE								
	9630423105 2000 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280110	BOTTOM CHECK VALVE 9630423105 1998 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS 9753731333 158 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS 9753731333 159 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
CHAPTER 29 HYDRAULIC POWER									
29-10/151 (s)	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE PKG 7 REF: AMM 29-10-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
29-10/153 (s)	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY PKG 3 REF: AMM 29-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469	22-JAN-2022 6322	27-FEB-2022 6442
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED) 960.30.01.291 802 REF: AMM 29-10-02	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469	22-JAN-2022 6322	27-FEB-2022 6442

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/259 (s)	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL						PKG		
	PKG 8	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	1200	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.								
		MOS	12	+10%/-10%				22-JAN-2021	
		HRS/MSC	300	+10%/-10%		5:05		5122	22-JAN-2022
	REF: AMM 29-00-00	AFL						4469	27-FEB-2022
									5457:05
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED)								
	960.30.01.291	MOS						23-AUG-2017	
29.020	802	HRS/MSC	25000	N:5017:55				3713	23695:05
LIFE LIMIT	REF: AMM 29-10-02	AFL	30000	N:4360				3233	28873
29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)								
	960.30.01.291	MOS						30-APR-2008	
	802	HRS/MSC	N/A					0	
	REF: AMM 29-10-02	AFL						0	
290015	PRESSURE GAGE SWITCH								
	9738114304	MOS						23-FEB-2018	
29.050	1218	HRS/MSC	O/C	N:0				3901:55	
	REF: GENERIC NO REF	AFL		N:0				3390	
290025	SERVICE SELECTOR VALVE								
	891292	MOS						14-OCT-2015	
29.070	G1041034	HRS/MSC	O/C					2897:45	
	REF: AMM 32-30-03	AFL						2535	
290030	PRESSURE GAUGE								
	9656188101	MOS						30-APR-2008	
29.080	07-0925639	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290040	HAND PUMP								
29.030	9688582111 819 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	973.81.14.306 1808 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAY-2017 3555:50 3106		
291010	HYDRAULIC POWER PACK								
29.010	9603001154 G0410550 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-OCT-2015 2886:20 2527		
29JFL01	HYDRAULIC FLUID INDICATOR CLEAN THE SIGHT GLASS								
	REF:	MOS HRS/MSC AFL	60	+10%/-10%	-62		29-MAY-2018 3950:50 3440	28-MAR-2023	28-SEP-2023
CHAPTER 30	ICE AND RAIN PROTECTION								
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 30-10-00								
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM						PKG		
	PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 30-20-00								
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
	REF: See Workcard								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING								
30.010	REF: GENERIC NO REF	MOS HRS/MSC AFL	6	+10%/-10%			22-JAN-2021 5122 4469	22-JUL-2021	09-AUG-2021
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED						PKG		
	PKG 3	MOS HRS/MSC AFL	12	+10%/-10%			22-JAN-2021 5122 4469		
	REF: GENERIC NO REF		300	+10%/-10%					
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001						PKG		
	PKG 8	MOS HRS/MSC AFL	12	+10%/-10%			11-FEB-2021 5134:05 4481		
	REF: GENERIC NO REF		1200	+10%/-10%					
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM						PKG		
	PKG 7	MOS HRS/MSC AFL	12	+10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 30-30-20		600	+10%/-10%					
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM						PKG		
	PKG 9	MOS HRS/MSC AFL	24	+10%/-10%			22-JAN-2021 5122 4469		
	REF: AMM 30-40-00		2400	+10%/-10%					
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM						PKG		
	PKG 7	MOS HRS/MSC AFL	12	+1m/-1m			22-JAN-2021 5122 4469		
	REF: See Workcard		600	+30/-30					
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM						PKG		
	PKG 7	MOS HRS/MSC AFL	12	+1m/-1m			11-FEB-2021 5134:05 4481		
	REF: See Workcard		600	+30/-30					
300005	PROP DE-ICE CONTROLLER								
30.140	9682913227 U4081 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 N:57:20 R:0 N:32 R:0			17-APR-2019 4448:50 3880		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300010	LPMI LINEAR ACTUATOR								
30.150	9787315302 B51217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N074373 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N074065 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N074066 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N074049 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N074051 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 4215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N075145 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300055	DE-ICING SYSTEM TIMER								
30.100	9598901014 U3709 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	R:0 N:50 R:0 N:122 R:0			17-APR-2019 4448:50 3880		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 122417 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 122424 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	P27S-7D5221-13 NCR8410 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-MAR-2016 3049:50 2671		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NEK8740 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2018 4093:50 3577		
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NFF1920 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-APR-2020 4827:05 4223		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	95989010040 NFJ4560 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JAN-2021 5122 4469		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U1763 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.022 NDD1440 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JUN-2017 3589:15 3128		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.024 NDJ3230 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JUN-2017 3589:15 3128		
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U0233 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C				16-MAR-2009 133:30 137		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
	9738114312 4127 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
	9738114312 4133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
	9738114312 9205 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAR-2019 4411:20 3843		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
	9738114312 9009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:10 N:0 N:0			03-JAN-2018 3887:55 3380		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
	9598901008 N074050 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30JFL02	PERFORM BLEED SYSTEM AND LEAK TEST OF AIRFOIL DE-ICERS BOOTS (REF. 12-B-30-10-00-00A-903A-A)	MOS					22-JAN-2021		
	REF:	HRS/MSC AFL	300	+10%/-10%			5122 4469	5422	5452
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-30/421	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)	MOS					30-APR-2008		
	REF: AMM 31-30-01	HRS/MSC AFL	N/A				0 0		
31-LUX-01	PERFORM READ OUT OF THE FLIGHT DATA RECORDER AND ANALYSIS OF THE PARAMETERS FOR ACCURACY AND RELIABILITY, IN ACCORDANCE WITH ICAO ANNEX 6 PART II REQUIREMENTS.	MOS							
	REF:	HRS/MSC AFL	N/A						
310050	DIGITAL CLOCK	MOS					30-APR-2008		
31.040	9996111213 1051550 REF: AMM 31-20-12	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER	MOS					30-APR-2008		
	9859912178 KMC2210-1076 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE	MOS					22-JAN-2021		
	7036410-1904 1804F461 REF: AMM 31-42-00	HRS/MSC AFL	O/C				5122 4469		
310077	NO.2 MAU ADVANCED GRAPHIC MODULE	MOS					11-JUN-2020		
	7036410-1902 09010386 REF:	HRS/MSC AFL	O/C				4851:15 4251		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD 985.99.12.231 14016742 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
310085	OVERHEAD CONTROL BASIC PANEL 9728121153 8 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310090	KMC2220 MF CONTOLLER 071-01598-0501 KMC2220-1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-FEB-2010 482:15 424		
310095	PILOT KMC 2210 DISPLAY CONTROLLER 9859912178 KMC2210-1053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE 7028432-1902 0912B312 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-FEB-2010 482:15 424		
310100-2	MAU ACTUATOR I/O PROC MODULE 7028432-1902 1002B420 REF:	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		
310102 31.230	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE 7028432-1902 1002B420 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				30-APR-2014 2161:30 1886		
310105	MODULAR AVIONICS ,12SLOT UNIT 9859912147 7122282 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD 985.99.12.231 13126653 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2014 2114:50 1852		
310115	NO. 1 LH MAU POWER SUPPLY MODULE 9859912143 7119432 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310120	NO. 2 RH MAU POWER SUPPLY MODULE 9859912143 7119438 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310125	MAU DUAL GENERIC I/O MODULE 7038622-1901 14080895 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				09-AUG-2019 4692:25 4111		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT 9859912251 14111503 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-MAR-2015 2553:15 2209		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY 9859912103 1890118853 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY K9321022A00 1890118854 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:482:15 N:424			15-FEB-2010 482:15 424		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY 9859912103 1890119589 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY K9321022A00 1890118856 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:482:15 N:424			15-FEB-2010 482:15 424		
310155	REV CTL PNL,4-POT DISPLAY 9728121141 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE 9858314204 7097393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE 9858314204 7107406 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
310175	REAR CENTRE CONS PNL PC-12 47/E 9728121154 0396 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-SEP-2017 3773:45 3277		
31C011	PC-12E APX100 APEX SYS SOFTWARE 9859912142 10099003 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
CHAPTER 32	LANDING GEAR								
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 7	MOS	12	+10%/-10%			22-JAN-2021		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 7	MOS	12	+10%/-10%			PKG 22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			5122 4469		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 7	MOS	12	+10%/-10%			PKG 22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			5122 4469		
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 7	MOS	12	+10%/-10%			PKG 22-JAN-2021		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			5122 4469		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 8	MOS	12	+10%/-10%			PKG 11-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			5134:05 4481		
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
32.010	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			5122 4469	7522	7762
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY 5321012051	MOS			N:0		30-APR-2008		
32.070	REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0		0 0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY 5321012052	MOS			N:0		30-APR-2008		
32.070	REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0		0 0		
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF:	HRS/MSC AFL	25000 30000				0 0	25000 30000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
	REF: See Workcard	HRS/MSC					5122		
		AFL					4469		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS					03-MAR-2016		
	REF: See Workcard	HRS/MSC	N/A				2977:20		
		AFL					2611		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS					03-MAR-2016		
	REF: See Workcard	HRS/MSC	N/A				2977:20		
		AFL					2611		
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS				72	30-APR-2008		
	REF: AMM 32-10-00	HRS/MSC	N/A				0		
		AFL					0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS					30-APR-2008		
	REF: AMM 32-10-00	HRS/MSC	N/A				0		
		AFL					0		
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS					03-MAR-2016		
	REF: AMM 32-10-00	HRS/MSC	N/A				2977:20		
		AFL					2611		
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS					03-MAR-2016		
	REF: AMM 32-10-00	HRS/MSC	N/A				2977:20		
		AFL					2611		
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS					30-APR-2008		
	REF: AMM 32-10-00	HRS/MSC	N/A				0		
		AFL					0		
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS					30-APR-2008		
	REF: AMM 32-10-00	HRS/MSC	N/A				0		
		AFL					0		
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
32.030	REF: AMM 12-20-06	HRS/MSC	T/C				5122		
		AFL					4469		
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE	MOS	12	+10%/-10%			11-FEB-2021		
	PKG 7	HRS/MSC	600	+10%/-10%			5134:05		
	REF: AMM 32-20-00	AFL					4481		
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR	MOS	12	+10%/-10%			22-JAN-2021		
	PKG 7	HRS/MSC	600	+10%/-10%			5122		
	REF: AMM 12-20-04	AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING.						PKG		
	PKG 7	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	600	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT						PKG		
	PKG 7	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	600	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS						PKG		
	PKG 8	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	1200	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
32-20/335	NOSE LANDING GEAR TORQUE TUBE								
	5325012064	MOS		N:0				29-MAY-2018	
32.190	N/A	HRS/MSC	O/C	N:0				3950:50	
	REF: GENERIC NO REF	AFL		N:0				3440	
32-20/403	NOSE LANDING GEAR - OVERHAUL								
	PN	MOS		N:0				30-APR-2008	
32.200	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0			0	25000
OVERHAUL	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0			0	30500
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
	5322012296	MOS		N:0				03-FEB-2016	
	N/A	HRS/MSC	25000	N:0				2961:35	27961:35
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	N:0				2598	32598
32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM								
		MOS	12	+10%/-10%				22-JAN-2021	22-JAN-2022
		HRS/MSC	1200	+10%/-10%				5122	6322
	REF: AMM 32-30-00	AFL						4469	6442
32-30/417	LEFT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
	9603001105	MOS						24-AUG-2017	
32.040	2759H	HRS/MSC	25000	N:142:10				3713:20	28571:10
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:121				3234	33113

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/417	RIGHT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
	9603001105	MOS					01-DEC-2017		
32.040	2234H	HRS/MSC	25000	N:2568			3854:30		26286:30
LIFE LIMIT	REF: AMM 32-30-01	AFL	30000	N:2189			3351		31162
	ACH								
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-30/423	ACTUATOR ELECTRO MECHANICAL LANDING GEAR P/N 959.56.01.821 / 822 OR 959.56.01.823 / 824								
	PN	MOS		N:0			30-APR-2008		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	REF: AMM 32-30-10	AFL					0		
32-30/425	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	REF: AMM 32-30-08	AFL					0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY	MOS						30-APR-2008	
	REF: AMM 32-10-06	HRS/MSC	N/A				0		
		AFL					0		
32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS						30-APR-2008	
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72					03-MAR-2016	03-MAR-2022
	REF: See Workcard	HRS/MSC					2977:20		
		AFL					2611		
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72					03-MAR-2016	03-MAR-2022
	REF: See Workcard	HRS/MSC					2977:20		
		AFL							
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS	6					30-NOV-2020	31-MAY-2021
REPLACE	REF: GENERIC NO REF	HRS/MSC	300				5082:55		5382:55
		AFL							

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE								
		MOS	6				30-NOV-2020	31-MAY-2021	
REPLACE	REF: GENERIC NO REF	HRS/MSC	300				5082:55	5382:55	
		AFL							
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 12-10-04	AFL					4469		
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 12-10-04	AFL					4469		
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: GENERIC NO REF	AFL					4469		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 12-10-02	AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230	REF: AMM 32-50-00	MOS HRS/MSC AFL	32500 42000	+500/-500 +500/-500			30-APR-2008 0 0	32500 42000	33000 42500
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	HP1457300-2 2047 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:4245:48 R:0 N:3132 R:0			09-AUG-2019 4692:25 4111		
320006	STEREER SELECTOR, LANDING GEAR VALVE								
29.040	960.30.01.274 0765C REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-FEB-2018 3901:55 3390		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751131 5188 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320015	PARK BRAKE VALVE								
32.140	9594751121 2586 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320020	NOSE WHEEL								
32.150	3-1501 0670 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				20-JUL-2018 4093:50 3577		
320021	NOSE LANDING GEAR TIRE								
32.155	021-327-0 8092S00137 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JAN-2021 5122 4469		
320022	LEFT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.160	3-1543-1 1084 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-MAY-2020 4844:05 4243		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 9186S00296 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-MAY-2020 4844:05 4243		
320024	RIGHT MAIN LANDING GEAR WHEEL & COVER ASSY								
32.165	3-1543-1 1648 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				06-AUG-2020 4958:30 4339		
320025	SHIMMY DAMPER ASSY								
32.100	5322012215 VLG380 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:72 N:2114:50 N:1852			04-APR-2014 2114:50 1852		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	025-350-0 0036T00255 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2020 5089:25 4439		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751131 5205 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751131 5206 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012249 VLG352 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012040 VLG352 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG712 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320060	LH BRAKE ASSY								
32.050	959.56.01.512 1537 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			13-JUL-2018 4090:45 3574		
320074	NOSE LANDING GEAR HYDRAULIC ACTUATOR								
	9603001111 1498A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-OCT-2015 2897:45 2535		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG713 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320085	RH BRAKE ASSY								
32.050	2-1674-1 0973 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-MAY-2017 3551:30 3101		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
	9733033113 241 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
	9733033113 1442 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			30-APR-2008 0 0		
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH								
	973.30.33.116 3921 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-MAY-2015 2630:35 2290		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH 9733033113 223 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH 9733033113 343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
320125	MAIN LANDING GEAR 72A74-01 LH "WOW" PROXIMITY SWITCH 9733033113 337 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

CHAPTER 33

LIGHTS

33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 3 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 3 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 3 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	22-JAN-2021	
	REF: AMM 33-44-00	HRS/MSC AFL	300	+10%/-10%			5122 4469		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3	MOS	12	+10%/-10%			PKG	22-JAN-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			5122 4469		
330005	DIM UNIT 9750215205	MOS		N:0				30-APR-2008	
33.080	122204	HRS/MSC	O/C	N:0				0	
	REF: AMM 33-10-04	AFL		N:0				0	
330010	DE-ICE LIGHT ASSY 972.87.67.111	MOS		N:0				21-AUG-2014	
33.010	2742930	HRS/MSC	O/C	N:0				2371:05	
	REF: GENERIC NO REF	AFL		N:0				2060	
330015	LH HIDL WING 972.87.69.413	MOS		N:0				22-JAN-2021	
33.020	4855075	HRS/MSC	O/C	N:0				5122	
	REF: GENERIC NO REF	AFL		N:0				4469	
330020	RH HIDL WING 972.87.69.413	MOS		N:0				18-MAR-2015	
33.020	2979177	HRS/MSC	O/C	N:0				2553:15	
	REF: GENERIC NO REF	AFL		N:0				2209	
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787331	MOS		N:0				30-APR-2008	
33.040	18005	HRS/MSC	O/C	N:0				0	
	REF: AMM 33-46-00	AFL		N:0				0	
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787332	MOS		N:0				30-APR-2008	
33.040	18010	HRS/MSC	O/C	N:0				0	
	REF: AMM 33-46-00	AFL		N:0				0	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330035	LH WING POWER SUPPLY UNIT								
33.070	9728787164 30967 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 28534030 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-AUG-2015 2832:05 2475		
330045	RH WING POWER SUPPLY UNIT								
33.070	9728787164 30975 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 23741 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-MAR-2011 834:25 741		
330055	NAVIGATION (FC), LED GREEN LIGHT								
33.050	9728787158 30361 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330060	NAVIGATION (FC), LED RED LIGHT								
33.050	9728787157 28961 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT								
33.060	9728787159 27147 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	R:506:20			04-SEP-2014 2406:15 2084		
330070	NOSE LANDING GEAR TAXI LIGHT								
	03-4400-1000 30287001 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C				09-AUG-2019 4692:25 4111		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330075	L/H 1X0005287-10 LANDING LIGHT 972.87.69.402 29536004 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-MAY-2016 3115:30 2736		
330076	R/H 1X0005287-10 LANDING LIGHT 03-4303-0000 30493001 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 4381:45 3818		
CHAPTER 34 NAVIGATION									
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 8 REF: AMM 34-11-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 11-FEB-2021 5134:05 4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11/343	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT REF: AMM 34-11-12	MOS HRS/MSC AFL	24				22-JAN-2021 5122 4469	22-JAN-2023	
34-11/82 34.010	LEAK CHECK STATIC SYSTEM (DAC-AIR 348) REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+10%/-10%		-13	24-APR-2020 4827:05 4223	11-APR-2022	23-JUN-2022
34-14/83	CALIBRATION CHECK ALTIMETER REF:	MOS HRS/MSC AFL	24	+1m/-1m		19	24-APR-2020 4827:05 4223	13-MAY-2022	13-JUN-2022
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (DAC-AIR 348) REF: AMM 34-21-00	MOS HRS/MSC AFL	24	+1m/-1m			24-APR-2020 4827:05 4223	24-APR-2022	24-MAY-2022
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM) REF: AMM 34-14-00	MOS HRS/MSC AFL	24	+10%/-10%			22-JAN-2021 5122 4469	22-JAN-2023	03-APR-2023
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED) REF: AMM 34-26-40	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
34-54/86 34.050	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) (DAC-AIR 348) REF: See Workcard	MOS HRS/MSC AFL	24	+1m/-1m		-13	24-APR-2020 4827:05 4223	11-APR-2022	11-MAY-2022
340010 34.080	DME/IFF ANTENNA 9848110240 261-78218 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C				30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340020	MARKER ANTENNA								
34.100	9848110260 101-6568 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340055	WITH HARM FILTER,KN63 DME								
34.200	066-1070-01 14124 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C				04-AUG-2016 3272:25 2863		
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 2319 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C				22-DEC-2018 4320 3765		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 5709 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-78245 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 A8602 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340100	FRONT KA92 ANTENNA								
34.090	013-00235-00 129258 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-FEB-2017 3407:40 2967		
340101	REAR KA92 GPS ANTENNA								
34.090	013-00235-00 129210 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-FEB-2017 3407:40 2967		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340105	LH NAV/GS ANTENNA								
34.380	9848110280 7620 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 14043 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340135	STANDBY MAGNETIC COMPASS								
34.130	9999880103 AT-821 REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	N:72 N:2114:50 N:1852			04-APR-2014 2114:50 1852		
340140	RADOME								
34.420	9857900005 481 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 531548 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:111 N:3665:15 N:3191			13-JUL-2017 3665:15 3191		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41425 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-41426 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 18618 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 18396 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911570 KRA405B-7175 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	9859918009 SN-UNKNOWN REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 7621 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340235	AOA SENSOR RH UNIT								
34.330	0012AC12 1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			20-APR-2016 3055:15 2676		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	9859911505 18797 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340255	AOA SENSOR LH UNIT								
34.330	0012AC11 0333 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-SEP-2014 2406:15 2084		
340265	DME/IFF--ATC DIV. ANTENNA								
	9848110240 261-78231 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340270	LEFT PITOT STATIC TUBE 9651112302 862507 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340275	RIGHT PITOT STATIC TUBE 9651112302 AS02179213 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-2017 3795:45 3298		
340280	OUTBOARD KMG 7010 MAGNETOMETER 9859912114 KMG7010-1194 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER 9859912114 KMG7010-1197 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT 0000008480 KMH920-B1176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:25 R:0 R:0			23-SEP-2013 1918:40 1690		
340295	RH COAX SWITCH 9859911371 13232 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340300	LH COAX SWITCH 9859911371 13202 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
340305	NO. 1 LH KGS200,GPS SENSOR UNIT 066-01201-0105 KGS200-1281 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				19-MAY-2017 3551:30 3101		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340310	NO. 2 KXP 2290 MODE S TRANSPONDER 066-01198-0102 1425 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				25-FEB-2019 4381:45 3818		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER 066-01198-0102 M1056 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				24-APR-2020 4827:05 4223		
340320	LH OAT SENSOR 534.13.12.054 2226046 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUN-2017 3589:15 3128		
340325	RH OAT SENSOR 534.13.12.054 2212062 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUN-2017 3589:15 3128		
340335	NO. 2 RH KGS200,GPS SENSOR UNIT 066-01201-0105 KGS200-1020 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				22-JAN-2021 5122 4469		
340340	STANDBY INSTRUMENT PANEL 9759611244 C16221010895 REF: AMM 34-26-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
34C012	KSG 7200 DUAL CHANNEL ADAHRS 065-00188-5103 KSG7200-B1217 REF:	MOS HRS/MSC AFL	O/C				11-DEC-2020 5089:25 4439		
34JFL02	PERFORM AVIONIC RAMP TEST (DAC-AIR 348) REF:	MOS HRS/MSC AFL	24	+1m/-1m		26	22-JAN-2021 5122 4469	17-FEB-2023	17-MAR-2023

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34JFL03	CHECK TAWS FUNCTION - ENSURE THAT AVIONICS EQUIPMENTS ARE NOT INHIBED OR DISABLED (SIB NO.2017-14 TERRAIN AWARENESS WARNING SYSTEM)	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
	REF:	HRS/MSC					5122		
		AFL					4469		
34JFL04	TEST OF PROBE AND PITOT STATIC PORT (INCULding ALTIMETER,AIRSPED INDICATOR, VERTICAL SPEED INDICATOR AND STANDBY INSTRUMENTS TO VERIFY ACCURACY)	MOS	24	+10%/-10%				11-APR-2022	M 23-JUN-2022
	REF:	HRS/MSC							
		AFL							
CHAPTER 35	OXYGEN								
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			5122		
		AFL					4469		
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG		
	PKG 5	MOS					22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			5122		
		AFL					4469		
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			5134:05		
		AFL					4481		
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
	REF: AMM 35-00-00	HRS/MSC	1200	+10%/-10%			5134:05		
		AFL					4481		
35-10/6	REAR FUSELAGE OXYGEN CYLINDER								
	895-06077	MOS	180		O:28		03-NOV-2020	03-JUL-2033	
	C07011053	HRS/MSC			O:0		5058:50		
AIRWORTHINESS	REF: AMM 35-10-01	AFL			O:0		4420		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER 895-06077 C07011053 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				21-MAY-2020	21-MAY-2025	
AIRWORTHINESS									
35-20/452	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED) REF: AMM 35-00-00	MOS HRS/MSC AFL	N/A				30-APR-2008 0 0		
35-20/453	OVERHAUL NO. 1 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 2 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 3 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 4 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 5 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 5352112141 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				01-APR-2018		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/453	OVERHAUL NO. 6 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 7 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 8 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/453	OVERHAUL NO. 9 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED) REF: AMM 35-00-00	MOS HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469	5422	5452
35-20/87 35.010	INSPECTION/CHECK PASSENGER OXYGEN MASKS REF: AMM 35-20-00	MOS HRS/MSC AFL	36	+10%/-10%	-20		24-APR-2020 4827:05 4223	04-APR-2023	22-JUL-2023
350020 35.040	PILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125 B130787 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY									
35.040	MC10-06-125 SE23133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-APR-2013 1685:55 1507			
350030	PRESSURE,GAGE,OXYGEN SWITCH									
35.050	9738114401 816 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350035	CONTR,3-POSITION,37071-03 VALVE									
35.030	9633211101 2785 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350050	OXYGEN GAGE ASSY									
	535.12.12.085 60399 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2020 4992:40 4366			
350055	OXYGEN PRESS TRANSDUCER									
	9571201184 7427-5-57 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0			
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY									
	5352112141 NSN REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2018 3950:50 3440			
CHAPTER 45	CENTRAL MAINT SYSTEM									
45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG			
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021			
		HRS/MSC	1200	+10%/-10%			5134:05			
	REF: AMM 45-45-00	AFL					4481			

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45JFL01	DOWNLOAD FHDB, ACMF	MOS					22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122	5422	5452
	REF:	AFL					4469		
CHAPTER 46 INFORMATION SYSTEMS									
46-26/320 (s)	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: See Workcard	AFL					4469		
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
		HRS/MSC	300	+10%/-10%			5122		
	REF: AMM 46-30-02	AFL					4469		
CHAPTER 52 DOORS									
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			11-FEB-2021		
		AFL					5134:05		
							4481		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 52-10-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE	MOS					30-APR-2008		
52.100	REF: AMM 52-00-01	HRS/MSC	32500	+500/-500			0	32500	33000
		AFL	42000	+500/-500			0	42000	42500
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN	MOS					30-APR-2008		
52.110	REF: AMM 52-10-01	HRS/MSC	25000	+500/-500			0	25000	25500
		AFL	30000	+500/-500			0	30000	30500
52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)	MOS					30-APR-2008		
	REF: AMM 52-10-06	HRS/MSC	N/A				0		
		AFL					0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
52.010	REF: See Workcard	HRS/MSC	4000	+10%/-10%	9		4827:05	8827:05	9227:05
		AFL					4223		
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED) PKG 8	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			11-FEB-2021		
		AFL					5134:05		
							4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
		MOS					30-APR-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 52-20-00	AFL	42000				0		42000
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: AMM 52-30-00	AFL					4481		
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	600	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: GENERIC NO REF	AFL					4481		
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS					30-APR-2008		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000				0		42000

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
52.120		MOS					30-APR-2008		
		HRS/MSC	32500	+500/-500			0	32500	33000
	REF: AMM 52-30-00	AFL	42000	+500/-500			0	42000	42500
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
52.130		MOS					30-APR-2008		
		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 52-30-01	AFL	30000	+500/-500			0	30000	30500
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
52.020	PN	MOS			N:0		30-APR-2008		
	SN-UNKNOWN	HRS/MSC	13000		N:0		0	13000	
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000		N:0		0	17000	
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED								
52.030		MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
		HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
	REF: See Workcard	AFL					4223		
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM						PKG		
	PKG 8	MOS	12	+10%/-10%			11-FEB-2021		
		HRS/MSC	1200	+10%/-10%			5134:05		
	REF: AMM 52-70-00	AFL					4481		
520005	PASSENGER DOOR								
52.050	5520512007	MOS			N:0		30-APR-2008		
	796P	HRS/MSC	O/C		N:0		0		
	REF: See Workcard	AFL			N:0		0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512010	MOS			N:0		30-APR-2008		
	796P	HRS/MSC	O/C		N:0		0		
	REF: AMM 52-30-01	AFL			N:0		0		
520015	EMERGENCY 6 SERIE EXIT								
52.060	5520512009	MOS			N:0		30-APR-2008		
	796P	HRS/MSC	O/C		N:0		0		
	REF: AMM 52-20-01	AFL			N:0		0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 53	FUSELAGE								
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 3	MOS	12	+10%/-10%				22-JAN-2021	
		HRS/MSC	300	+10%/-10%				5122	
	REF: GENERIC NO REF	AFL						4469	
53-00/276	EXAMINE REAR PRESSURE BULKHEAD								
	PKG 8	MOS	12					11-FEB-2021	11-FEB-2022
		HRS/MSC	1200					5134:05	6334:05
	REF: GENERIC NO REF	AFL						4481	
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 8	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	1200	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 9	MOS	24	+10%/-10%				22-JAN-2021	
		HRS/MSC	2400	+10%/-10%				5122	
	REF: GENERIC NO REF	AFL						4469	
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 9	MOS	24	+10%/-10%				22-JAN-2021	
		HRS/MSC	2400	+10%/-10%				5122	
	REF: GENERIC NO REF	AFL						4469	
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 8	MOS	12	+10%/-10%				11-FEB-2021	
		HRS/MSC	1200	+10%/-10%				5134:05	
	REF: GENERIC NO REF	AFL						4481	
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						30-APR-2008	
		HRS/MSC	N/A					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24 PKG 8	MOS	12	+10%/-10%			PKG	11-FEB-2021	
	REF: AMM 53-20-02	HRS/MSC	1200	+10%/-10%			5134:05		
		AFL					4481		
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-10-06	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-20-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
53-00/419	EDDY CURRENT INSPECTION - FRAME 40	MOS					30-APR-2008		
53.210	REF: See Workcard	HRS/MSC	32500	+500/-500			0	32500	33000
		AFL	42000	+500/-500			0	42000	42500
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					30-APR-2008		
53.010	REF: GENERIC NO REF	HRS/MSC	20000				0	20000	
AIRWORTHINESS		AFL	27000				0	27000	
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
53.030	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
53.040	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED	MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
53.070	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%			24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			4827:05	8827:05	9227:05
		AFL					4223		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
	REF: AMM 53-30-01	MOS	12	+1m/-1m			22-JAN-2021	22-JAN-2022	22-FEB-2022
		HRS/MSC					5122		
		AFL					4469		
530070	FUSELAGE AB 1003 TEIL1								
	5530512114	MOS			N:0		30-APR-2008		
	796P	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
CHAPTER 55	STABILIZERS								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
	REF: GENERIC NO REF	MOS					30-APR-2008		
AIRWORTHINESS		HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
	REF: GENERIC NO REF	MOS					30-APR-2008		
AIRWORTHINESS		HRS/MSC	N/A				0		
		AFL					0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			5122		
		AFL					4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 8	MOS	12	+10%/-10%			PKG		
	REF: AMM 55-00-00	HRS/MSC AFL	1200	+10%/-10%			11-FEB-2021 5134:05 4481		
55-10/415	HORIZONTAL STABILIZER 555.10.12.037 816	MOS		N:0			30-APR-2008		
LIFE LIMIT	REF: AMM 55-10-01	HRS/MSC AFL	25000 30000	N:0 N:0			0 0	25000 30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			4827:05 4223	8827:05	9227:05
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%		9	24-APR-2020	03-MAY-2024	27-SEP-2024
	REF: GENERIC NO REF	HRS/MSC AFL	4000	+10%/-10%			4827:05 4223	8827:05	9227:05
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/362	EXAMINE RIGHT WING ELEVATOR	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC	300	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	AFL					5122		
							4469		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS	MOS	12	+10%/-10%			PKG		
	PKG 8	HRS/MSC	1200	+10%/-10%			11-FEB-2021		
	REF: GENERIC NO REF	AFL					5134:05		
							4481		
55-30/369	EXAMINE - VERTICAL STABILIZER	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS					30-APR-2008		
55.190		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 55-30-03	AFL	42000	+500/-500			0		42000 42500

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40/373	EXAMINE - RUDDER	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC AFL	32500 42000				0 0	32500 42000	
55-40/410	EXAMINE - RUDDER TRIM TAB	MOS					30-APR-2008		
55.200	REF: AMM 55-40-04	HRS/MSC AFL	32500 42000	+500/-500 +500/-500			0 0	32500 42000	33000 42500
CHAPTER 56 WINDOWS									
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%			5122 4469		
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED	MOS					30-APR-2008		
56.020	REF: GENERIC NO REF	HRS/MSC AFL	A/R				0 0		
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED	MOS					30-APR-2008		
	REF: AMM 56-00-00	HRS/MSC AFL	A/R				0 0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)	MOS					30-APR-2008		
	9598110109	HRS/MSC AFL	A/R				0 0		
	07219H5554								
	REF: See Workcard								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110110 07144H7198 REF: See Workcard	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 07219H5554 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110110 07144H7198 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-APR-2008 0 0		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500		10	29-MAY-2018 3950:50 3440	08-JUN-2028 14950:50	08-DEC-2028 15450:50
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED REF: See Workcard	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
56-14/517 (s)	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200				PKG 11-FEB-2021 5134:05 4481		
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 3 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560015	SIDE,LH WINDOW								
56.090	9598110111 07218H5378 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560020	SIDE,RH WINDOW								
56.090	9598110112 07208H4365 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029 7597 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029 7588 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 7629 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 7628 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 7607 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 7565 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 7576 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 7563 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 7617 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 07334H8156 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010	9598110109 07219H5554 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
AIRWORTHINESS									
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
56.010	9598110110 07144H7198 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
AIRWORTHINESS									
CHAPTER 57	WINGS								
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010		MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC AFL	20000 27000				0 0	20000 27000	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE	MOS					30-APR-2008		
57.010		HRS/MSC	20000				0		20000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	27000				0		27000
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC	300	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	AFL					5122		
							4469		
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS	MOS	24	+10%/-10%			PKG		
	PKG 9	HRS/MSC	2400	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	AFL					5122		
							4469		
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED	MOS	12	+10%/-10%			PKG		
	PKG 8	HRS/MSC	1200	+10%/-10%			11-FEB-2021		
	REF: GENERIC NO REF	AFL					5134:05		
							4481		
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE	MOS	12	+10%/-10%			PKG		
	PKG 8	HRS/MSC	1200	+10%/-10%			11-FEB-2021		
	REF: GENERIC NO REF	AFL					5134:05		
							4481		
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					30-APR-2008		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					30-APR-2008		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					30-APR-2008		
		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0		39000

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-APR-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-APR-2008		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-APR-2008		
		HRS/MSC	25000				0		25000
AIRWORTHINESS	REF: AMM 57-20-05	AFL	30000				0		30000
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					30-APR-2008		
		HRS/MSC	25000				0		25000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0		30000
57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					30-APR-2008		
		HRS/MSC	25000				0		25000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0		30000
57-00/412	EXAMINE - WING TIPS								
		MOS					30-APR-2008		
57.170		HRS/MSC	32500	+500/-500			0		32500 33000
AIRWORTHINESS	REF: AMM 57-33-00	AFL	42000	+500/-500			0		42000 42500
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES								
		MOS					30-APR-2008		
57.180		HRS/MSC	25000	+500/-500			0		25000 25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0		30000 30500
57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES								
		MOS					30-APR-2008		
		HRS/MSC	25000	+500/-500			0		25000 25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0		30000 30500
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-APR-2008		
		HRS/MSC	16000				0		16000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0		22500
57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-APR-2008		
		HRS/MSC	16000				0		16000
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0		22500

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)								
57.020	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		9	24-APR-2020 4827:05 4223	03-MAY-2024 8827:05	27-SEP-2024 9227:05
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		9	24-APR-2020 4827:05 4223	03-MAY-2024 8827:05	27-SEP-2024 9227:05
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040	REF: AMM 57-00-00	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500		10	29-MAY-2018 3950:50 3440	08-JUN-2028 14950:50	08-DEC-2028 15450:50
57-60/393	EXAMINE - RIGHT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
57-60/393	EXAMINE -LEFT WING AILERON								
AIRWORTHINESS	REF: AMM 57-60-00	MOS HRS/MSC AFL	32500 42000				30-APR-2008 0 0	32500 42000	
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190	REF: AMM 57-60-04	MOS HRS/MSC AFL	32500 42000	+500/-500 +500/-500			30-APR-2008 0 0	32500 42000	33000 42500
570005	AILERON LH 10A SERIE ASSY								
57.050	REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
570010	AILERON RH 10A SERIE ASSY								
57.050	REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570050	L/H WING 5570512135 796P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
570055	R/H WING 5570512136 796P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

CHAPTER 61 PROPELLERS/PROPULSORS

61-10/37	PROPELLER 968.29.13.002 KX1250 REF: See Workcard	MOS HRS/MSC AFL	72 4000	N:72 O:0 N:3380:55 O:0			23-JAN-2020 4827:05	23-JAN-2026 8827:05	
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
61PR1 61.PR1	NO. 1 PROPELLER HC-E4A-3D/E10477SK KX1250 REF: See Workcard	MOS HRS/MSC AFL	PP/C	N:3380:55 O:0			24-APR-2020 4827:05 4223		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

612010	NO. 1 ENGINE - PROPELLER GOVERNOR 8210-137H 15475672 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 210949 15512024 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20

PROPELLER NO. 1 Model : HC-E4A-3D Serial # KX1250 Part # HC-E4A-3D/E10477SK

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	72 4000				23-JAN-2020 3380:55	23-JAN-2026 (7380:55) 8827:05	
OVERHAUL	REF:								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%			22-JAN-2021 3675:50	22-JAN-2022 (3975:50) 5422	22-FEB-2022 4005:50
	REF:								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER	MOS HRS/MSC	12 300	+1m/-1m +10%/-10%	1 5:05		22-JAN-2021 3675:50	23-JAN-2022 (3980:55) 5427:05	23-FEB-2022 4010:55
	REF:								
610070	NO. 1 PROPELLER - PRE-FLIGHT CHECKS	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
610080	NO. 1 PROPELLER - OPERATIONAL CHECKS	MOS HRS/MSC	A/R				25-MAR-2014 0		
	REF:								
610510	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								
610520	NO. 1 PROPELLER - LIGHTNING STRIKE	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610530	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								
610540	NO. 1 PROPELLER - FIRE/HEAT DAMAGE	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								
610550	NO. 1 PROPELLER - SUDDEN STOPPAGE	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								
610560	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION	MOS HRS/MSC	A/R				25-MAR-2014 0		
UNSCHEDULED MAINTENANCE CHECK	REF:								
610570	NO. 1 PROPELLER - LONG TERM STORAGE	MOS HRS/MSC	A/R				25-MAR-2014 0		
REF:									
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE 9682913023 L43786	MOS HRS/MSC	O/C	N:0 N:0			25-MAR-2014 0		
REF:	GENERIC NO REF								
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE 9682913023 L43783	MOS HRS/MSC	O/C	N:0 N:0			25-MAR-2014 0		
REF:	GENERIC NO REF								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE 9682913023 L43787 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			25-MAR-2014 0		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913023 L43782 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			25-MAR-2014 0		
CHAPTER 71 POWER PLANT									
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 7 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 7 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
71-00/103	PERFORM COMPRESSOR & TURBINE WASH						22-JAN-2021		
71.040	REF: AMM 71-00-00	MOS HRS/MSC AFL	300	+10%/-10%	5:05		5122 4469	5427:05	5457:05
71-00/104	PERFORM COMPRESSOR DESALINATION WASH						30-APR-2008		
	REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				0 0		
71-00/105	PERFORM TURBINE WASH						30-APR-2008		
	REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 7	MOS	12	+10%/-10%			11-FEB-2021		
	REF: AMM 71-00-03	HRS/MSC	600	+10%/-10%			5134:05		
		AFL					4481		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	571.20.12.036	MOS		N:0			30-APR-2008		
	810	HRS/MSC	20000	N:0			0		20000
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000	N:0			0		27000
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050		MOS					30-APR-2008		
	REF: GENERIC NO REF	HRS/MSC	11000				0		11000
AIRWORTHINESS		AFL					0		
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
	REF: AMM 71-00-00	HRS/MSC	A/R				5134:05		
		AFL					4481		
71-00/205	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP								
	PKG 8	MOS	12				11-FEB-2021		11-FEB-2022
	REF: GENERIC NO REF	HRS/MSC	1200				5134:05		6334:05
		AFL					4481		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 3	MOS	12	+10%/-10%			22-JAN-2021		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			5122		
		AFL					4469		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS.						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
	REF: AMM 71-00-00	HRS/MSC	A/R				5134:05		
		AFL					4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/301	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY.								
	PKG 8	MOS	12				11-FEB-2021	11-FEB-2022	
		HRS/MSC	1200				5134:05	6334:05	
	REF:	AFL					4481		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			29-MAY-2018		
71.063	10633	HRS/MSC	5000/E/C	+10%/-10%	N:0		3950:50	8950:50	9450:50
	REF: AMM 71-00-00	AFL		N:0			3440		
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			29-MAY-2018		
71.064	10647	HRS/MSC	5000/E/C	+10%/-10%	N:0		3950:50	8950:50	9450:50
	REF: AMM 71-00-00	AFL		N:0			3440		
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			29-MAY-2018		
71.061	10646	HRS/MSC	5000/E/C	+10%/-10%	N:0		3950:50	8950:50	9450:50
	REF: AMM 71-00-00	AFL		N:0			3440		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			29-MAY-2018		
71.060	10654	HRS/MSC	5000/E/C	+10%/-10%	N:0		3950:50	8950:50	9450:50
	REF: AMM 71-00-00	AFL		N:0			3440		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			29-MAY-2018		
71.062	9585	HRS/MSC	5000/E/C	+10%/-10%	N:0		3950:50	8950:50	9450:50
	REF: AMM 71-00-00	AFL		N:0			3440		
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
		MOS					30-APR-2008		
		HRS/MSC	26600				0	26600	
AIRWORTHINESS	REF: AMM 71-00-05	AFL	35000				0	35000	
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 1 ,3,5,6,7,8,9	MOS					11-FEB-2021		
		HRS/MSC	A/R				5134:05		
	REF: GENERIC NO REF	AFL					4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001 PKG 1 ,3,5,6,7,8,9 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				11-FEB-2021 5134:05 4481	PKG	
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR PKG 1 ,3,5,6,7,8,9 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				11-FEB-2021 5134:05 4481	PKG	
710005	UPPER LH ENGINE VIBRATION ISOLATOR 5712012106 3497 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR 5712012106 3519 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR 5712012106 3507 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710035	LOWER LH ENGINE VIBRATION ISOLATOR 5712012106 3496 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710045	LOWER RH ENGINE VIBRATION ISOLATOR 5712012106 3522 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		
710050	ENGINE MOUNT (WELDED) 5712012036 810 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P PCE-RY0008 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C	N:3830:20			29-MAY-2018 3950:50 3440		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			13-APR-2018 3830:20 3310	(7330:20) 7450:50	7530:20
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE						PKG		
	PKG 0 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339		
710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			13-APR-2018 3830:20	(5580:20) 5700:50	5830:20
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+50			22-JAN-2021 5001:30 4339	(5301:30) 5422	5351:30
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%	5:05		22-JAN-2021 5001:30 4339	(5306:35) 5427:05	5336:35
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH								
	REF:	MOS HRS/MSC ENC	A/R				28-AUG-2013 1879:35 1646		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
	REF:								
+ 710053	NO. 1 ENGINE - EXTERNAL ENGINE WASH	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
	REF:								
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS HRS/MSC ENC	300	+10%/-10%	5:05		22-JAN-2021 5001:30 4339	(5306:35) 5427:05	5336:35
	REF: EMM 72-00-00								
710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
	REF: EMM 71-00-00								
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS HRS/MSC ENC	A/R				25-FEB-2019 4261:15 3688		
	REF: EMM 72-00-00								
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE	PN SN-UNKNOWN ENC	3500	+500	O:0 O:0 O:0		13-APR-2018 3830:20	(7330:20) 7450:50	7830:20
	OVERHAUL	REF: See Workcard							
720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
	REF: EMM 72-00-00								

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-FEB-2019 4261:15 3688		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	A/R				25-FEB-2019 4261:15 3688		
720025	NO. 1 ENGINE - OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 22-JAN-2021 5001:30 4339		
720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 22-JAN-2021 5001:30 4339		
720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS REF: EMM 72-11-00	MOS HRS/MSC ENC	BF/F				25-FEB-2019 4261:15 3688		
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 22-JAN-2021 5001:30 4339		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 0 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 22-JAN-2021 5001:30 4339		
722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
722030	NO. 1 ENGINE - IMMERSION IN WATER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 EAAB000D438 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 O:0 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA116067 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 0 REF: EMM 72-30-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 22-JAN-2021 5001:30 4339		
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 EAAB000E799 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000	N:0 N:3830:20 O:0 N:3310			13-APR-2018 3830:20 3310	(24000) 24130	

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE REF: EMM 72-00-00	MOS HRS/MSC A/R ENC					30-APR-2008 0 0		
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339	PKG	
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAB000F265 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000			N:0 N:3830:20 N:3310	13-APR-2018 3830:20 3310		(24000) 24130
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAB000E462 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000			N:0 N:3830:20 N:3310	13-APR-2018 3830:20 3310		(24000) 24130
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAB000F043 REF: GENERIC NO REF	MOS HRS/MSC ENC	24000			N:0 N:3830:20 N:3310	13-APR-2018 3830:20 3310		(24000) 24130
723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION REF: See Workcard	MOS HRS/MSC A/R ENC					30-APR-2008 0 0		
724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS REF: EMM 72-00-00	MOS HRS/MSC A/R ENC					30-APR-2008 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724020	NO. 1 ENGINE - HIGH OIL PRESSURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724050	NO. 1 ENGINE - MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
725003	NO. 1 ENGINE - OVERSPEED REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				30-APR-2008 0 0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 A002YLE0 REF: GENERIC NO REF	MOS HRS/MSC ENC		O:0 N:2490:54 O:0 N:1915			13-APR-2018 3830:20 3310		(9395) 9525

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					13-APR-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	5000				3830:20 3310	(8830:20) 8950:50	
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 0	MOS					22-JAN-2021		
	REF: EMM 72-50-05	HRS/MSC ENC	300	+10%/-10%			5001:30 4339		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312	MOS					13-APR-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	15000		N:0 N:3830:20 N:3310		3830:20 3310	(15000) 15130	
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313	MOS					13-APR-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	15000		N:3158:30 O:0 N:2485		3830:20 3310	(15825) 15955	
726020	NO. 1 ENGINE - POWER SECTION MODULE PN	MOS					13-APR-2018		
OVERHAUL	REF: GENERIC NO REF	HRS/MSC ENC	3500	+500	O:0 O:0 O:0		3830:30	(7330:30) 7451	7830:30
726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE	MOS					30-APR-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE	MOS					30-APR-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING	MOS					30-APR-2008		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN	MOS					30-APR-2008		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP	MOS					13-APR-2018		
	825601-5	HRS/MSC	3500	N:120 O:0			3830:20	(7330:20) 7450:50	
	008755	ENC		N:3830:20 O:0			3310		
	REF: EMM 73-10-02			N:3310 O:0					
OVERHAUL									
731024	NO. 1 ENGINE - FUEL NOZZLE	MOS					22-JAN-2021		
	319855-01	HRS/MSC	O/C				5001:30		
	S/N	ENC					4339		
	REF:								
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS					22-JAN-2021		
		HRS/MSC	300	+50			5001:30	(5301:30) 5422	5351:30
	REF: EMM 73-11-05	ENC					4339		
731030	NO. 1 ENGINE - OVERTORQUE LIMITER	MOS					13-APR-2018		
	3244882-2	HRS/MSC	3500	+500	N:120 O:0		3830:20	(7330:20) 7450:50	7830:20
	C50836	ENC			N:3830:20 O:0		3310		
	REF: GENERIC NO REF				N:3310 O:0				
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE	MOS					22-JAN-2021		
	PKG 0	HRS/MSC	300	+10%/-10%			5001:30		
	REF: EMM 73-10-02	ENC					4339		
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION	MOS					30-APR-2008		
		HRS/MSC	N/A				0		
	REF: EMM 73-10-02	ENC					0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 825601-5 008755 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			22-JAN-2021 5001:30 4339	(5601:30) 5722	5661:30
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 0 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339		
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			22-JAN-2021 5001:30 4339	(5601:30) 5722	5661:30
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			11-FEB-2021 5013:35 4351		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 10585K WA32002 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			22-JAN-2021 5001:30 4339	(5301:30) 5422	5331:30
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 26130-2 U0434 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:30 O:0 N:944 O:0 N:777 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 8063-651 18348024 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500			13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 0 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS TRACKED ITEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				13-APR-2018 3830:20 3310		
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%		5:05	22-JAN-2021 5001:30 4339	(5306:35) 5427:05	5336:35
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 0 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
731155	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER - DISCARD 3059779-01 N/A REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T				22-JAN-2021 5001:30 4339		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 0 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			22-JAN-2021 5001:30 4339	(5901:30) 6022	5991:30
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%	5:05		22-JAN-2021 5001:30 4339	(5306:35) 5427:05	5336:35
CHAPTER 74 IGNITION									
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 22-JAN-2021 5122 4469		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
740010	NO. 1 ENGINE - IGNITION EXCITER 3055889 NNA17010023 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:0 N:278:50 N:-	-43	13-APR-2018 3830:20 3310	(7051:30) 7172	7551:30
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339	(5301:30) 5422	5331:30
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG 10390667-1 NNA17250166 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		13-APR-2018 3830:20 3310		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339	(5301:30) 5422	5331:30

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG 10390667-1 NNA17250167 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			13-APR-2018 3830:20 3310		
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	300	+10%/-10%			22-JAN-2021 5001:30 4339	(5301:30) 5422	5331:30

CHAPTER 75

AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX010220 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:120 O:0 N:3830:20 O:0 N:3310 O:0		13-APR-2018 3830:20 3310	(7330:20) 7450:50	7830:20
--------	---	-----------------------	------	------	--	--	--------------------------------	-------------------	---------

CHAPTER 76

ENGINE CONTROLS

76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			11-FEB-2021 5134:05 4481		
76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			22-JAN-2021 5122 4469		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 5 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 8 REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%			11-FEB-2021 5134:05 4481		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			22-JAN-2021 5122 4469		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES	MOS	12	+10%/-10%			22-JAN-2021	22-JAN-2022	27-FEB-2022
76.010	REF: AMM 76-10-02	HRS/MSC AFL	3000	+10%/-10%			5122 4469	8122	8422
760015	MANUAL OVERRIDE CABLE ASSY.	MOS					30-APR-2008		
76.020	9419411417 20070086 REF: AMM 76-20-00	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
760020	CONDITION CABLE ASSY.	MOS					30-APR-2008		
76.030	9419411418 20070091 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
760025	POWER CONTROL CABLE ASSY.	MOS					30-APR-2008		
76.040	9419411419 20070089 REF: AMM 76-10-04	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES	MOS					22-JAN-2021		
	REF: EMM 72-00-00	HRS/MSC ENC	300	+10%/-10%		5:05	5001:30 4339	(5306:35) 5427:05	5336:35
CHAPTER 77 ENGINE INDICATING									
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER	MOS					30-APR-2008		
77.010	9752115206 7533-12-18 REF: AMM 77-40-03	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	975.21.15.212 2946578 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-MAY-2018 3952:15 3442		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NRA102519 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			13-APR-2018 3830:20 3310		
CHAPTER 78 EXHAUST									
78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
CHAPTER 79 OIL									
79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK						PKG		
	PKG 7	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 8	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-FEB-2021 5134:05 4481		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			22-JAN-2021 5122 4469		
79-20/43	OIL COOLER								
79.010	9683214102 T1246 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+10%/-10%	O:0 O:0 O:0		29-MAY-2018 3950:50 3440	7450:50	7800:50
OVERHAUL									

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790005	TEMPERATURE BULB 9751120101	MOS		N:0			30-APR-2008		
79.020	151251 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
790020	PRESSURE,GAGE SWITCH 9738114305	MOS		N:0			30-APR-2008		
79.030	840 REF: AMM 79-30-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
790025	THERMAL ACTUATOR 9787301002	MOS		N:0			30-APR-2008		
79.040	978 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
790030	POWER ODM,B049913 MODULE 9752115240	MOS		N:0			30-APR-2008		
79.050	45219 REF: AMM 79-30-05	HRS/MSC AFL	O/C	N:0 N:0			0 0		
790035	MODUL,ODM,B057185 SENSOR 9752115242	MOS		N:0			30-APR-2008		
79.060	45518 REF: AMM 79-30-05	HRS/MSC AFL	O/C	N:0 N:0			0 0		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0008 Part # 3072955-01									
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					30-APR-2008		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			22-JAN-2021	22-JAN-2022	21-FEB-2022
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%	5:05		5001:30 4339	(5306:35) 5427:05	5336:35

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 300	+1m/-1m +10%/-10%			22-JAN-2021 5001:30 4339	22-JAN-2022 (5301:30) 5422	22-FEB-2022 5331:30
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT REF: EMM 79-20-02	MOS HRS/MSC ENC	900	+10%/-10%	23:45		24-APR-2020 4706:35 4093	(5630:20) 5750:50	5720:20
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN REF: See Workcard	MOS HRS/MSC ENC	300				22-JAN-2021 5001:30 4339	(5301:30) 5422	
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN REF: EMM 72-60-00	MOS HRS/MSC ENC	300	+10%/-10%	5:05		22-JAN-2021 5001:30 4339	(5306:35) 5427:05	5336:35
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE REF: EMM 79-20-02	MOS HRS/MSC ENC	A/R				07-JAN-2009 100 103		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				30-APR-2008 0 0		
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 0 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 11-FEB-2021 5013:35 4351		

Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79JFL01	NO. 1 ENGINE - ENGINE OIL ANALYSIS	MOS		+10%/-10%					
	REF:	HRS/MSC	300	+10%/-10%				? ?	
		ENC							
CHAPTER 91 -									
240120	BATTERY EXT POWER JUNCTION BOX								
	974.03.38.142(FE-1561-02)	MOS					10-JUN-2010		
	266	HRS/MSC	O/C				587:55		
	REF: GENERIC NO REF	AFL					522		
910015	KBT 300 TTP BUS RES, A-157 TERMINAL								
	9859912117	MOS		N:0			30-APR-2008		
	KBT-300-1133	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL								
	9859912117	MOS		N:0			30-APR-2008		
	KBT-300-1138	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL								
	9859912117	MOS		N:0			30-APR-2008		
	KBT-300-1124	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX								
	9740338136	MOS		N:0			30-APR-2008		
	128	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
910035	CO-PILOT RIGHT HD POWER, FE1549R JUNCTION BOX								
	9740338137	MOS		N:0			30-APR-2008		
	130	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



Status Report

PC-12/47E S/N 1008 (LX-TAI): 5134:05 HRS, 4481 AFL as of 11-Feb-2021

Owner/Operator: JETFLY AVIATION SA

Report Date: 22-MAR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
	9859912117	MOS		N:0			30-APR-2008		
	KBT-300-1132	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		