

OWNER: OSCAR KILO AVIATION AB
ADDRESS: SVEANVAGEN 21
STOCKHOLM 11134
PHONE:
FAX:

OPERATOR: GRAFAIR FLIGHT MANAGEMENT AB
ADDRESS: STOCKHOLM CITY AIRPORT
BROMMA SE-168 67
PHONE: +46 8 982600 (MAIN)
FAX: +46 8 288844

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 1731/SE-MIX **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 30-AUG-2017	850:18 A/C HRS	as of 09-MAR-2021	_____ A/C HRS	as of ____/____/____
MANUFACTURER DATE: 01-AUG-2017	851 AFL	as of 09-MAR-2021	_____ AFL	as of ____/____/____
	108:30 ACH	as of 29-OCT-2020	_____ ACH	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: PCE-RY0793/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 26-JUL-2017	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	850:18 ENG. HRS	as of 09-MAR-2021	_____ ENG. HRS	as of ____/____/____
0 ENC	851 ENC	as of 09-MAR-2021	_____ ENC	as of ____/____/____

PROPELLER NOSERIAL/PART: SA237/HC-E5A-3A/NC10245B **MODEL:** HC-E5A-3A **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 26-JUL-2017	LAST ACTUALS		CURRENT ACTUAL	
0 PROP HRS 0 A/C HRS	850:18 PROP HRS	as of 09-MAR-2021	_____ PROP HRS	as of ____/____/____



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 15 in PKG 16,17,18,19,20,21	MOS HRS/MSC AFL	A/R			04-SEP-2020 767:06 778	PKG	
	REF: See Workcard							
05401A	300 HOUR INSPECTION							
+	PKG 16	MOS HRS/MSC AFL	300	+30/-30	-21:48	06-FEB-2020 621:48	900	930
	REF: See Workcard							
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 17	MOS HRS/MSC AFL	12 300	+1m/-1m +30/-30	-5	04-SEP-2020 767:06 778	30-AUG-2021 1067:06	30-SEP-2021 1097:06
	REF: See Workcard							
05403A	600 HOUR INSPECTION							
+	PKG 18	MOS HRS/MSC AFL	600	+60/-60	-21:48	06-FEB-2020 621:48	1200	1260
	REF: See Workcard							
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 19	MOS HRS/MSC AFL	12 600	+1m/-1m +60/-60	-5	04-SEP-2020 767:06 778	30-AUG-2021 1367:06	30-SEP-2021 1427:06
	REF: See Workcard							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTH INSPECTION							
+								
	PKG 20	MOS	12	+1m/-1m	-5	04-SEP-2020	30-AUG-2021	30-SEP-2021
		HRS/MSC	1200	+120/-120		767:06	1967:06	2087:06
	REF: See Workcard	AFL				778		
<hr/>								
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+								
	PKG 21	MOS	24	+1m/-1m	-7	06-SEP-2019	30-AUG-2021	30-SEP-2021
		HRS/MSC	2400	+60/-60		526:24	2926:24	2986:24
	REF: See Workcard	AFL				533		
<hr/>								
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0793 Part # 3072955-01								
057010	NO. 1 ENGINE - MINOR INSPECTION							
+								
	PKG 2	MOS				06-FEB-2020		
		HRS/MSC	300	+10%/-10%		621:48	(921:48) 921:48	951:48
	REF: See Workcard	ENC						

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
+ 00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: GENERIC NO REF	AFL					778		
+ 00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: GENERIC NO REF	AFL					778		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: GENERIC NO REF	AFL					778		
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04								
		MOS					30-AUG-2017		
		HRS/MSC	-				0		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL					0		
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19								
		MOS					30-JUL-2018		
		HRS/MSC	-				292:36		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL					331		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS					30-AUG-2017		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL					0 0		
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0	MOS					10-MAY-2017		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC					0 0		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS					30-JUL-2018		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC					292:36 331		
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA237 Part # HC-E5A-3A/NC10245B									
PE5A-180301	NO. 1 PROPELLER - REVIEW PROPELLER OWNER'S MANUAL NO. 147 REVISION 14	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PE5A-191101	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM NO. 147 REV 15	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
PE5A-200501	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 16	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
PE5A-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 33	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
PE5A-200901	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 34	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
PE5A-200901-1	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
PE5A-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

PE5A-210304	NO. 1 PROPELLER - REVIEW SL HC-SL-61-61Y REV 13	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
	NEW REQUIREMENT ADDED ON 15-MAR-2021 (EFFECTIVE: 04-MAR-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

PE5A-210401	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 TR-011	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC	-						
	NEW REQUIREMENT ADDED ON 15-APR-2021 (EFFECTIVE: 01-APR-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER 04 LIMITATIONS

+ 040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
LIFE LIMIT	REF: GENERIC NO REF	AFL	60000	N:0			0		60000

+ 040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

+ 050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)								
		MOS					30-AUG-2017		
		HRS/MSC	25000				0		25000
	REF: AMM 05-10-30	AFL	30000				0		30000

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION								
		MOS					30-AUG-2017		
		HRS/MSC	25000				0		25000
	REF: GENERIC NO REF	AFL	30000				0		30000

CHAPTER 06 DIMENSIONS AND AREAS

+ 06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: AMM 06-20-00	AFL					778		

+ 06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: AMM 06-20-00	AFL					778		

+ 06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR.						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: AMM 06-20-00	AFL					778		

+ 06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTION THE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: GENERIC NO REF	AFL					778		

CHAPTER 07 LIFTING AND SHORING

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				04-SEP-2020 767:06 778		
+ 07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				04-SEP-2020 767:06 778		
CHAPTER 08 LEVELING AND WEIGHING									
+ 080000	WEIGHT CHECK AIRCRAFT 08.005 REF: AMM 08-10-00	MOS HRS/MSC AFL	48				30-AUG-2017 0 0	30-AUG-2021	
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
CHAPTER 12 SERVICING									
+ 12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-01	MOS HRS/MSC AFL	A/R				04-SEP-2020 767:06 778		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 04-SEP-2020 767:06 778		
+ 12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 04-SEP-2020 767:06 778		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
+ 00-00/45A 20.010	PERFORM CORROSION INSPECTION (INTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+1m/-1m	-34		04-SEP-2020 767:06 778	01-AUG-2021	01-SEP-2021
+ 00-00/45B 20.011	PERFORM CORROSION INSPECTION (EXTERNAL) REF: AMM 20-40-00	MOS HRS/MSC AFL	6	+10%/-10%	-5		22-DEC-2020 832:12 835	17-JUN-2021	05-JUL-2021
CHAPTER 21 AIR CONDITIONING									
+ 21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+10%/-10%			06-SEP-2019 526:24 533		
+ 21-20/317 AIRWORTHINESS	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%	-5		04-SEP-2020 767:06 778	30-AUG-2021 3767:06	06-OCT-2021

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-30/463	OPERATIONAL TEST CABIN PRESSURIZATION DUMP CONTROL	MOS	12	+10%/-10%		-5	04-SEP-2020	30-AUG-2021	06-OCT-2021
	REF: AMM 21-30-00	HRS/MSC	600				767:06	1367:06	
		AFL					778		
+ 21-30/464	OPERATIONAL TEST CABIN PRESSURIZATION MANUAL CONTROL	MOS	12	+10%/-10%		-5	04-SEP-2020	30-AUG-2021	06-OCT-2021
	REF: AMM 21-30-00	HRS/MSC	600				767:06	1367:06	
		AFL					778		
+ 21-30/465	FUNCTIONAL TEST CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE	MOS	48	+10%/-10%			30-AUG-2017	30-AUG-2021	23-JAN-2022
	REF: AMM 21-30-00	HRS/MSC	4800				0	4800	
		AFL					0		
+ 21-30/466 (s)	CHECK CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
	REF: AMM 21-30-02	HRS/MSC	2400	+10%/-10%			526:24		
		AFL					533		
+ 21-30/467	EXAMINE CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE	MOS	48	+10%/-10%			30-AUG-2017	30-AUG-2021	23-JAN-2022
	REF: AMM 21-30-05	HRS/MSC	4800	+10%/-10%			0	4800	5280
		AFL					0		
+ 21-30/468	FUNCTIONAL TEST CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION	MOS	48				30-AUG-2017	30-AUG-2021	
	REF: AMM 21-30-00	HRS/MSC	4800				0	4800	
		AFL					0		
+ 21-30/469	FUNCTIONAL TEST CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING	MOS	48				30-AUG-2017	30-AUG-2021	
	REF: AMM 21-30-00	HRS/MSC	4800				0	4800	
		AFL					0		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH	MOS					30-AUG-2017		
	REF: AMM 21-43-00	HRS/MSC AFL	N/A				0 0		
+ 21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH	MOS	12	+10%/-10%			PKG 04-SEP-2020		
21.140	PKG 20	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
	REF: See Workcard								
+ 21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH	MOS	12	+10%/-10%			PKG 04-SEP-2020		
21.150	9696781507 PKG 20 586279	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
	REF: See Workcard								
+ 21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER	MOS	12	+10%/-10%			PKG 04-SEP-2020		
21.080	PN PKG 20 SN-UNKNOWN	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
	REF: AMM 21-40-03								
+ 21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%			01-AUG-2017	01-AUG-2022	01-FEB-2023
21.130	9738132216 1136	HRS/MSC AFL	4800	+10%/-10%			0 0	4800	5280
	REF: AMM 21-40-06								
+ 21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH	MOS	60	+10%/-10%			30-AUG-2017	30-AUG-2022	28-FEB-2023
21.120	9738132214 1071	HRS/MSC AFL	4800	+10%/-10%			0 0	4800	5280
	REF: AMM 21-60-05								
+ 21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT	MOS					PKG 06-FEB-2020		
21.060	PKG 18	HRS/MSC AFL	600	+10%/-10%			621:48		
	REF: AMM 21-40-02								



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 18	MOS					06-FEB-2020		
	REF: AMM 21-40-02	HRS/MSC	600	+10%/-10%			621:48		
		AFL							
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		
+ 21-50/433 (s)	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)						PKG		
	9599022140 PKG 17	MOS	12	+1m/-1m			04-SEP-2020		
	2012	HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 21-40-03	AFL					778		
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022140	MOS					30-AUG-2017		
	2012	HRS/MSC					0		
	REF: AMM 21-50-03	AFL					0		
		ACH	600	+10%/-10%			0	600	660
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022140	MOS					30-AUG-2017		
	2012	HRS/MSC					0		
	REF: AMM 21-50-01	AFL					0		
		ACH	600	+10%/-10%			0	600	660
+ 21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	9599022140	MOS							
	2012	HRS/MSC	N/A						
	REF: AMM 21-50-03	AFL							
		ACH					0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	9599022140 2012 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH	N/A				0		
210005	OVERPRESSURE SWITCH								
21.340	9738115105 1979 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-MAR-2021 843:36 849		
210010	REFRIGERATION PACK								
21.255	9599020111 2209 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210015	WATER INJECTOR								
21.370	9599020141 2175 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 4830 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 2167 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210030	HP SHUT OFF VALVE								
21.280	9599020131 2184 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210035	WATER SEPARATOR ASSY								
21.220	PN SN-UNKNOWN REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 2184 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022140 2012 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 1077 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 1221 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210060	CABIN PRESSURE OUTFLOW VALVE								
	9599091125	MOS		N:0			30-AUG-2017		
21.250	65053598-00025	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-30-03	AFL		N:0			0		
210065	CABIN PRESSURE RELIEVE VALVE								
	9599091132	MOS		N:0			30-AUG-2017		
21.270	27-F0746	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
210090	OUTFLOW VALVE CONTROLLER								
	9599091147	MOS		N:0			30-AUG-2017		
21.430	65000052-00027	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
	9696781507	MOS		N:0			30-AUG-2017		
21.240	586279	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-40-01	AFL		N:0			0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
	9599022118	MOS		N:0			30-AUG-2017		
21.200	1195	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
210145	CABIN (REAR) ELECTRIC HEATER								
	9696781507	MOS		N:0			30-AUG-2017		
21.230	586286	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-40-15	AFL		N:0			0		
210170	OVERPRESSURE SWITCH								
	9738115106	MOS		N:0			30-AUG-2017		
21.340	1577	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-40-07	AFL		N:0			0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	9599020160 1778 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210185	INTEG. ECS CONTROL UNIT								
21.540	9599020129 0786 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210190	FLOOR DUCT TEMP. SENSOR								
21.550	9599020121 4863 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR								
21.560	9599020121 4859 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	9633011005 0946 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	9738132216 1136 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	9738132214 1071 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	9633011105 1620B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2832B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2833B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	9633011106 2823B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR								
21.600	9599020121 4875 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 22 AUTO FLIGHT									
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: GENERIC NO REF	AFL					533		
+ 22-10/60	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-34	04-SEP-2020	01-AUG-2021	01-SEP-2021
		HRS/MSC	1000	+10%/-10%			767:06	1767:06	1867:06
	REF: AMM 22-10-00	AFL					778		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-10/60	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-34	04-SEP-2020	01-AUG-2021	01-SEP-2021
		HRS/MSC	1000	+10%/-10%			767:06	1767:06	1867:06
	REF: AMM 22-10-00	AFL					778		
+ 22-10/60	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		-34	04-SEP-2020	01-AUG-2021	01-SEP-2021
		HRS/MSC	1000	+10%/-10%			767:06	1767:06	1867:06
	REF: AMM 22-10-00	AFL					778		
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 22-20-02	AFL					778		
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM						PKG		
	PKG 16	MOS					06-FEB-2020		
		HRS/MSC	300	+10%/-10%			621:48		
	REF: AMM 22-20-00	AFL							
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: AMM 22-20-00	AFL					778		
220045	STICK PUSHER SERVO								
	9786111103	MOS					30-AUG-2017		
22.220	81066	HRS/MSC	O/C				0		
	REF: AMM 22-20-04	AFL					0		
220055	STICK PUSHER CAPSTAN								
	9786111124	MOS					30-AUG-2017		
22.140	81023	HRS/MSC	O/C				0		
	REF: AMM 22-20-06	AFL					0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220060	STICK SHAKER								
22.230	9786111143 1576 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220070	STICK PUSHER								
22.170	9754423104 137341 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3420 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3419 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220100	RUDDER KSA 2700 SERVO								
22.260	9859912275 KSA2700-3471 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220105	ELEVATOR KSA 2700 SERVO								
22.250	9859912275 KSA2700-3476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220110	AILERON KSA 2700 SERVO								
22.240	9859912275 KSA2700-3414 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
220115	KMC 9200 VNAV FLIGHT CONTROLLER								
	9859912204 KMC-9200-2034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 23 COMMUNICATIONS									
+ 23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
	REF: AMM 23-50-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
+ 23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
	REF: AMM 23-12-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203 310-30186 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-30184 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
23.070	9848110210 430-15058 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.090	9859912254 4717 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.080	069-01037-0102 2740 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-NOV-2020 818:30 827		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	9859912108 N02050 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	9859912108 N02037 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 24 ELECTRICAL POWER									
+ 24-30/309	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437)								
24.210	9789123407 P2588 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				08-MAY-2018 193:48 254		
+ 24-30/310	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.437)								
24.026	9789123407 P2591 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				08-MAY-2018 193:48 254		
+ 24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-5	04-SEP-2020 767:06 778	30-AUG-2021 3767:06	06-OCT-2021
AIRWORTHINESS									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025	PN	MOS	12	+10%/-10%			04-SEP-2020	30-AUG-2021	06-OCT-2021
AIRWORTHINESS	SN-UNKNOWN	HRS/MSC	3000				767:06	3767:06	
	REF: AMM 71-00-00	AFL					778		
+ 24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
	REF: AMM 24-40-00	HRS/MSC	2400	+10%/-10%			526:24		
		AFL					533		
+ 24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
	REF: AMM 71-00-00	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		
+ 24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
24.010	RG-380E/44	MOS	6	+10%/-10%			09-MAR-2021	09-SEP-2021	27-SEP-2021
	70005573	HRS/MSC	600	+10%/-10%			850:18	1450:18	1510:18
	REF: AMM 24-30-07	AFL					851		
+ 24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
24.010	RG-380E/44	MOS	6	+10%/-10%			05-FEB-2021	05-AUG-2021	23-AUG-2021
	40638891	HRS/MSC	600	+10%/-10%			837:06	1437:06	1497:06
	REF: AMM 24-30-07	AFL					840		
+ 24-30/473	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407)								
	9789123407 PKG 18	MOS					06-FEB-2020		
	P2588	HRS/MSC	600	+10%/-10%			621:48	1221:48	1281:48
	REF: AMM 24-30-01	AFL							
+ 24-30/474	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407)								
	9789123407 PKG 18	MOS					06-FEB-2020		
	P2591	HRS/MSC	600	+10%/-10%			621:48	1221:48	1281:48
	REF: AMM 24-30-01	AFL							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR 9789123407 P2588 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	+10%/-10%			30-AUG-2017 0 0	1200	1320
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR 9789123407 P2591 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+10%/-10%			30-AUG-2017 0 0	1200	1320
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR 9789123407 P2588 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR 9789123407 P2591 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 06-SEP-2019 526:24 533		
+ 24-50/70 24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 9858314953 83754 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%	-34		04-SEP-2020 767:06 778	01-AUG-2021	07-SEP-2021

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 21	MOS	24	+10%/-10%			PKG	06-SEP-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111	MOS		N:0			30-AUG-2017		
24.120	P4338	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-05	AFL		N:0			0		
240010	GENERATOR 1 300A CONTACTOR 9740338113	MOS		N:0			30-AUG-2017		
24.130	620	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240015	GENERATOR 2 300A CONTACTOR 9740338113	MOS		N:0			30-AUG-2017		
24.130	590	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240135	NO. 1 LEAD ACID BATTERY RG-380E/44	MOS					09-MAR-2021		
24.010	70005573	HRS/MSC	O/C				850:18		
	REF: AMM 24-30-07	AFL					851		
240140	NO. 2 LEAD ACID BATTERY RG-380E/44	MOS					05-FEB-2021		
24.010	40638891	HRS/MSC	O/C				837:06		
	REF: AMM 24-30-07	AFL					840		
243010	NO. 2 STARTER-GENERATOR 9789123407	MOS		N:0			30-AUG-2017		
24.215	P2591	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-01	AFL		N:0			0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	9858314953 83754 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	N:767:06 N:778			04-SEP-2020 767:06 778		
243160	NO. 1 STARTER GENERATOR								
24.205	9789123407 P2588 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	9750215107 7725 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	9755085111 N4361 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	9755085111 N4345 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243190	VOLTAGE REGULATOR 9882114111 P4324 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS PKG 17 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 06-FEB-2020 621:48		
+ 25-10/294 25.030	CREW SEAT BELTS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
+ 25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 04-SEP-2020 767:06 778		
+ 25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 04-SEP-2020 767:06 778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
	REF: AMM 25-10-01	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 25-20/295	PASSENGER SEAT BELTS PN	MOS					30-AUG-2017		
25.010	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
+ 25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: See Workcard	HRS/MSC AFL	A/R				767:06 778		
+ 25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: See Workcard	HRS/MSC AFL	A/R				767:06 778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			06-FEB-2020 621:48		
+ 25-60/231 (s)	OPERATIONAL TEST ELT 9851380882 PKG 17 LX1100461068 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
+ 25-63/23 25.020 DISCARD	ELT BATTERY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE					01-NOV-2023 M	
+ 25-63/434 DISCARD	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) 9851380881 LX1100461007 REF: GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			30-AUG-2017 0 0	30-AUG-2027 16000	29-FEB-2028 16500
25-63/477	CLEAN UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/478	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
25-63/479	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON BATTERY VOLTAGE (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
25-63/480	DISCARD UNDERWATER LOCATOR BEACON (IF INSTALLED) PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
250005 25.070	REMOTE CONTROL PANEL 9851380817 TM0000097772 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250010 25.050	EMERGENCY LOCATOR TRANSMITTER 9851380882 LX1100461068 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250021 25.120	L/H NO. 1 AFSS PASSENGER SEAT 9593001821 62472 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250022	R/H NO. 2 AFSS PASSENGER SEAT								
25.125	9593001822 62473 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250023	L/H NO. 3 FFSS PASSENGER SEAT								
25.130	9593001835 62474 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250024	R/H NO. 4 FFSS PASSENGER SEAT								
25.135	9593001836 62475 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250025	L/H NO. 5 FFSS PASSENGER SEAT								
25.140	9593001837 62476 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250026	R/H NO. 6 FFSS PASSENGER SEAT								
25.145	9593001838 62477 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
250027	L/H NO. 7 STANDARD PASSENGER SEAT								
25.150	5252212011 1998 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE								
25.060	9851380881 LX1100461007 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
256020	LH BLACK PILOT SEAT								
25.090	9593001165 87138 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
256025	RH BLACK CO-PILOT SEAT								
25.100	9593001166 87084 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
256050	UNDERWATER LOCATOR BEACON								
NOT INSTALLED	PN NOT INSTALLED REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			30-AUG-2017 0 0		
+ 258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)								
25.110	REF: AMM 25-63-00	MOS HRS/MSC AFL	12		-5		04-SEP-2020 767:06 778	30-AUG-2021	
25CUS01	FIRST AID KIT								
	725075 040417-008LEW REF:	MOS HRS/MSC AFL	A/R				21-DEC-2018 384:30 428		
25CUS02	INSPECTION FIRST AID KIT								
	725075 040417-008LEW REF:	MOS HRS/MSC AFL	12				04-SEP-2020 767:06 778	04-SEP-2021	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25CUS03	NO. 1 LIFE VEST 904.92.17.913 L36663051 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS04	NO. 2 LIFE VEST 904.92.17.913 L36663047 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS05	NO. 3 LIFE VEST 904.92.17.913 L36663053 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS06	NO. 4 LIFE VEST 904.92.17.913 L36663056 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS07	NO. 5 LIFE VEST 904.92.17.913 L36663061 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS08	NO. 6 LIFE VEST 904.92.17.913 L36663055 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									
25CUS09	NO. 7 LIFE VEST 904.92.17.913 L36663525 REF:	MOS HRS/MSC AFL	DUE					20-FEB-2027	M
DISCARD									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25CUS10	NO. 8 LIFE VEST 904.92.17.913 L36663052	MOS HRS/MSC	DUE					20-FEB-2027	M
DISCARD	REF:	AFL							
25CUS11	NO. 9 LIFE VEST 904.92.17.913 L36663050	MOS HRS/MSC	DUE					20-FEB-2027	M
DISCARD	REF:	AFL							
25CUS12	NO. 10 LIFE VEST 904.92.17.913 L36663058	MOS HRS/MSC	DUE					20-FEB-2027	M
DISCARD	REF:	AFL							
CHAPTER 26 FIRE PROTECTION									
26-20/2	CABIN FIRE EXTINGUISHER 1.5 KG BA51015R-5 104294	MOS HRS/MSC	120	N:9			06-NOV-2017	24-DEC-2026	M
26.030	REF: GENERIC NO REF	AFL		N:0			50		
LIFE LIMIT				N:0			122		
	Manufacture Date: 14-FEB-2017								
+ 26-20/2	COCKPIT FIRE EXTINGUISHER 9590806219 104222	MOS HRS/MSC	120	N:0			01-FEB-2017	01-FEB-2027	
26.010	REF: GENERIC NO REF	AFL		N:0					
LIFE LIMIT				N:0					
	Manufacture Date: 01-FEB-2017								
26-20/24	CABIN FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224) BA51015R-5 104294	MOS HRS/MSC	12	+1m/-1m	3		04-SEP-2020	07-SEP-2021	07-OCT-2021
	REF: GENERIC NO REF	AFL					767:06		
							778		
+ 26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224) 9590806219 104222	MOS HRS/MSC	12	+1m/-1m	-5		04-SEP-2020	30-AUG-2021	30-SEP-2021
26.010	REF: GENERIC NO REF	AFL					767:06		
							778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
260005	FIRE/OVERHEAT DETECTOR									
26.020	9751210012 215430 REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0			
CHAPTER 27 FLIGHT CONTROLS										
+ 27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL						PKG			
	PKG 16	MOS					06-FEB-2020			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			621:48			
+ 27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES									
27.255		MOS					30-AUG-2017			
	REF: GENERIC NO REF	HRS/MSC AFL	32500 42000	+500/-500 +500/-500			0 0	32500 42000	33000 42500	
+ 27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK									
27.010		MOS	60	+10%/-10%			01-AUG-2017	01-AUG-2022	01-FEB-2023	
	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%			0	4800	5280	
+ 27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001)						PKG			
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778			
+ 27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						PKG			
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778			
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG			
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778			

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/236 (s)	AILERON CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS PKG 21	MOS	24	+10%/-10%			PKG 06-SEP-2019		
	REF: AMM 27-10-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
+ 27-10/394	AILERON CONTROL SYSTEM - EXAMINE	MOS					30-AUG-2017		
27.155		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-10-00	AFL	42000				0	42000	
+ 27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					30-AUG-2017		
27.160		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-10-09	AFL	42000				0	42000	
+ 27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS					30-AUG-2017		
27.165		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0	42000	
+ 27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS					30-AUG-2017		
27.170		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0	42000	
+ 27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS	MOS					30-AUG-2017		
27.175		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: See Workcard	AFL	42000				0	42000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
		MOS					30-AUG-2017		
27.215		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 57-60-06	AFL	42000				0		42000
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
		MOS					30-AUG-2017		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 57-60-06	AFL	42000				0		42000
+ 27-10/444	FLIGHT CONTROL CABLES, AILERON								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-01	AFL	27000	N:0			0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: AMM 27-10-00	AFL					778		
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: AMM 27-15-00	AFL					533		
+ 27-20/140 (s)	INSPECTION/CHECK RUDDER						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 55-40-00	AFL					778		
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: GENERIC NO REF	AFL					533		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/241 (s)	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 21	MOS	24	+10%/-10%			PKG 06-SEP-2019		
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 21	MOS	24	+10%/-10%			PKG 06-SEP-2019		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					30-AUG-2017		
27.180		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-00	AFL	42000				0	42000	
+ 27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					30-AUG-2017		
27.185		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-04	AFL	42000				0	42000	
+ 27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					30-AUG-2017		
27.190		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-05	AFL	42000				0	42000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					07-SEP-2018		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				310 345		
+ 27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					07-SEP-2018		
	REF: AMM 27-20-00	HRS/MSC AFL	A/R				310 345		
+ 27-20/446	FLIGHT CONTROL CABLES, RUDDER	MOS		N:0			30-AUG-2017		
	REF: AMM 27-20-01	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	20000 27000	
LIFE LIMIT									
+ 27-20/447	AUTOPILOT CONTROL CABLES, RUDDER	MOS		N:0			30-AUG-2017		
	REF: AMM 27-20-02	HRS/MSC AFL	20000 27000	N:0 N:0			0 0	20000 27000	
LIFE LIMIT									
+ 27-30/141 (s)	EXAMINE ELEVATORS	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778		
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS	MOS	24	+10%/-10%			PKG 06-SEP-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			526:24 533		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/249 (s)	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 21	MOS	24	+10%/-10%			PKG 06-SEP-2019		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			526:24 533		
+ 27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					07-SEP-2018		
27.150	REF: AMM 27-30-00	HRS/MSC AFL	O/C				310 345		
+ 27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR) PN	MOS					07-SEP-2018		
	REF: AMM 27-30-00	HRS/MSC AFL	A/R				310 345		
+ 27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE	MOS					30-AUG-2017		
27.195	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000				0 0	32500 42000	
AIRWORTHINESS									
+ 27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS					30-AUG-2017		
27.200	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000				0 0	32500 42000	
AIRWORTHINESS									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
		MOS					30-AUG-2017		
27.205		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
+ 27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
		MOS					30-AUG-2017		
27.210		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-30-05	AFL	42000				0		42000
+ 27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL	27000	N:0			0		27000
+ 27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-02	AFL	27000	N:0			0		27000
+ 27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: See Workcard	AFL					778		
+ 27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)								
		MOS	12	+10%/-10%		-5	04-SEP-2020	30-AUG-2021	06-OCT-2021
27.021		HRS/MSC	3000				767:06	3767:06	
AIRWORTHINESS	REF: AMM 27-40-00	AFL					778		
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 27-40-00	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: AMM 27-40-01	HRS/MSC AFL	1200	+10%/-10%					
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR 9787314203 1752	MOS	60				30-AUG-2017 0 0	30-AUG-2022 5000	
OVERHAUL	REF: GENERIC NO REF	HRS/MSC AFL	5000						
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 16	MOS					PKG 06-FEB-2020 621:48		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%					
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%					
+ 27-40/3	REPLACE PITCH TRIM ACTUATOR 9787314203 1752	MOS					30-AUG-2017 0 0	20000 27000	
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	20000 27000						
+ 27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) PN	MOS		N:0			30-AUG-2017 0 0	10000	
27.036	SN-UNKNOWN	HRS/MSC	10000	N:0					
LIFE LIMIT	REF: AMM 27-40-02	AFL		N:0					
+ 27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R						
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 17	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 27-50/28	FLAP POWER DRIVE UNIT 9787320003	MOS		N:0			30-AUG-2017		
27.030	1572	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
OVERHAUL	REF: AMM 27-50-01	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 9787320309	MOS					30-AUG-2017		
27.040	6180	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
+ 27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 9787320309	MOS					30-AUG-2017		
27.041	6204	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
+ 27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR 9787320309	MOS					30-AUG-2017		
27.050	6232	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
+ 27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR 9787320309	MOS					30-AUG-2017		
27.051	6238	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			30-AUG-2017		
27.060	S7899	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			30-AUG-2017		
27.060	S7874	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			30-AUG-2017		
27.070	S7895	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			30-AUG-2017		
27.070	S7878	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					30-AUG-2017		
27.220		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	39000				0	39000	
+ 27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					30-AUG-2017		
27.225		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	30000				0	30000	
+ 27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					30-AUG-2017		
27.230		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
+ 27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					30-AUG-2017		
27.235		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM	MOS					30-AUG-2017		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS	MOS					30-AUG-2017		
27.240		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS	MOS					30-AUG-2017		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS	MOS					30-AUG-2017		
27.245		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
+ 27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS	MOS					30-AUG-2017		
27.250		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
+ 27-50/4	LEFT INBOARD FLAP ACTUATOR	MOS					30-AUG-2017		
27.040	9787320309	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000
+ 27-50/4	LEFT OUTBOARD FLAP ACTUATOR	MOS					30-AUG-2017		
27.041	9787320309	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000
+ 27-50/4	RIGHT INBOARD FLAP ACTUATOR	MOS					30-AUG-2017		
27.050	9787320309	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			30-AUG-2017		
27.051	6238	HRS/MSC	20000	N:0			0	20000	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0	27000	
<hr/>									
+ 27-50/414	LEFT HAND FLAP								
	5570512025	MOS		N:0			30-AUG-2017		
57.060	7008	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0	30000	
<hr/>									
+ 27-50/414	RIGHT HAND FLAP								
	5570512026	MOS		N:0			30-AUG-2017		
57.060	7008	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0	30000	
<hr/>									
+ 27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%	3		04-SEP-2020	07-SEP-2021	13-OCT-2021
		HRS/MSC	600	+10%/-10%			767:06	1367:06	1427:06
AIRWORTHINESS	REF: AMM 27-51-00	AFL					778		
<hr/>									
+ 27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 12-20-07	AFL					778		
<hr/>									
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0	27000	
<hr/>									
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
		HRS/MSC	A/R				767:06		
	REF: GENERIC NO REF	AFL					778		
<hr/>									
+ 27-50/74	LUBRICATE LEFT INBOARD FLAP ACTUATOR								
	9787320309 PKG 17	MOS	12	+10%/-10%	3		04-SEP-2020	07-SEP-2021	13-OCT-2021
27.040	6180	HRS/MSC	300	+10%/-10%			767:06	1067:06	1097:06
	REF: AMM 27-50-00	AFL					778		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/74	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 PKG 17 6204 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%	3		04-SEP-2020 767:06 778	07-SEP-2021 1067:06	07-OCT-2021 1097:06
+ 27-50/74	LUBRICATE RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 PKG 17 6232 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%	3		04-SEP-2020 767:06 778	07-SEP-2021 1067:06	07-OCT-2021 1097:06
+ 27-50/74	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 PKG 17 6238 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%	3		04-SEP-2020 767:06 778	07-SEP-2021 1067:06	07-OCT-2021 1097:06
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 6180 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-36		06-SEP-2019 526:24 533	01-AUG-2021 2926:24 3733	13-OCT-2021 3166:24 4053
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 6204 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-36		06-SEP-2019 526:24 533	01-AUG-2021 2926:24 3733	13-OCT-2021 3166:24 4053
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 6232 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-36		06-SEP-2019 526:24 533	01-AUG-2021 2926:24 3733	13-OCT-2021 3166:24 4053
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 6238 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	-36		06-SEP-2019 526:24 533	01-AUG-2021 2926:24 3733	13-OCT-2021 3166:24 4053
270003	HORIZONTAL TAIL ASSY								
	5551012037 1558 REF: AMM 55-10-01	MOS HRS/MSC AFL					30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270015	ELEVATOR LH ASSY								
27.015	5552012041 1643 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270023	ELEVATOR RH ASSY								
27.023	5552012042 1638 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318138 1617 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270033	RUDDER ASSY								
27.033	5554012040 7008 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270035	FLAP CONTROL AND WARNING UNIT								
27.130	9787320017 137108 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 1720012DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 2565 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 1720044DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 1720015DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 2569 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270080	KTA2810,TRIM ADAPTER								
22.135	9859912249 KTA2810-2346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318138 1622 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 1720042DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
+ 274020	PITCH TRIM ACTUATOR								
	9787314203 1752 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 28	FUEL								
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			04-SEP-2020 767:06 778		
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE	MOS		+10%/-10%					
28.029	REF: AMM 28-10-01	HRS/MSC AFL	2400	+10%/-10%			0	2400	2640
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 17	MOS	12	+10%/-10%			PKG		
	REF: AMM 28-20-07	HRS/MSC AFL	300	+10%/-10%			04-SEP-2020 767:06 778		
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 17	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			04-SEP-2020 767:06 778		
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N) PKG 19	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			04-SEP-2020 767:06 778		
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			04-SEP-2020 767:06 778		
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 21	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			06-SEP-2019 526:24 533		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-20/32	OVERHAUL ENGINE DRIVEN PUMP								
28.010	9688451108 B6189 REF: AMM 28-20-03	MOS HRS/MSC AFL	3500 +10%/-10%	N:0 N:0 N:0			30-AUG-2017 0 0	3500	3850
280005	LOW PRESSURE FUEL PUMP								
28.120	9688451108 B6189 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280010	FUEL FLOW TRANSMITTER								
28.130	9753512108 AAR0472 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280012	FUEL CONTROL MONITORING UNIT								
28.155	9753731336 925 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301 3787 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301 3782 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280025	FUEL FILTER ASSY								
28.025	9683521001 2017FFT0518 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 2893 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B6300 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B6057 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731253 2613 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731252 2588 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731251 2560 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731250 2558 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 C-807 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B6311 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B6059 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731250 2554 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731251 2542 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	9753731252 2569 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731253 2625 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 C-808 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280105	TOP CHECK VALVE								
28.150	9630423105 3955 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280110	BOTTOM CHECK VALVE								
28.150	9630423105 3921 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1842 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1811 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 29 HYDRAULIC POWER									
29-10/151	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE								
		MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
	REF: AMM 29-10-04								
29-10/153	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY								
		MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
	REF: AMM 29-00-00								
29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED								
		MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
	REF: GENERIC NO REF								
29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)								
	PN SN-UNKNOWN REF: AMM 29-10-02	MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
29-10/259	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL								
		MOS HRS/MSC AFL	N/A				30-AUG-2017 0 0		
	REF: GENERIC NO REF								



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.	MOS					30-AUG-2017		
	REF: AMM 29-00-00	HRS/MSC AFL	N/A				0 0		
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED)	MOS		N:0			30-AUG-2017		
29.020	PN SN-UNKNOWN REF: AMM 29-10-02	HRS/MSC AFL	N/A	N:0 N:0			0 0		
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS					30-AUG-2017		
	PN SN-UNKNOWN REF: AMM 29-10-02	HRS/MSC AFL	N/A				0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	PKG 17 REF: AMM 30-10-00	HRS/MSC AFL	300	+10%/-10%			767:06 778		
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	PKG 19 REF: AMM 30-20-00	HRS/MSC AFL	600	+10%/-10%			767:06 778		
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	PKG 20 REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1	MOS	6	+10%/-10%			22-DEC-2020	17-JUN-2021	05-JUL-2021
30.010	REF: GENERIC NO REF	HRS/MSC AFL			-5		832:12 835		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 19 REF: AMM 30-30-20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 21 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 06-SEP-2019 526:24 533		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 19 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 04-SEP-2020 767:06 778		
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 19 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 04-SEP-2020 767:06 778		
300005	PROP DE-ICE CONTROLLER 9682913227 30.140 U3902 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300010	LPMI LINEAR ACTUATOR 9787315302 30.150 D82454 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N170397 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N170918 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N170917 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N170930 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N170931 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 8847 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N170503 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	4E3163-2 U3902 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C				18-OCT-2018		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 137223 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 137225 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	9598901041 NDU1780 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NEK8760 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:2 N:0 N:0			25-MAY-2018 203:12 274	05-MAR-2023 M	
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NDU6550 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	9598901040 NDV2690 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421418 UF946 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	9598901037 NDV9970 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NDV4060 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421418 06147 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 8889 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 8888 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 8855 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 8861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	9598901008 N170934 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

CHAPTER 31 INDICATING/RECORDING SYSTEMS

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-30/421	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED) 9859920146 PKG 20 001215342 REF: AMM 31-30-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%		2	04-SEP-2020 767:06 778	06-SEP-2021 1967:06	12-OCT-2021 2087:06
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER 9859912178 KMC2210-2965 REF: GENERIC NO REF	MOS HRS/MSC AFL					30-AUG-2017 0 0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE 9859912292 1702E433 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE 9859912292 1702E441 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD 9859912231 1503C165 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
310085	OVERHEAD CONTROL BASIC PANEL 9728121155 0773 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
310090	KMC2220 MF CONTOLLER 9859912189 KMC2220-2110 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
310095	PILOT KMC 2210 DISPLAY CONTROLLER 9859912178 KMC2210-2977 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1703P139 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1703P150 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	9859912147 17039214 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	9859912231 1503B942 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	9859912346 17035307 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	9859912346 17035314 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	9859912252 17011908 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	9859912251 17031931 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	9859912103 2890002307 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	9859912103 2890000954 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 2890002081 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 2890000891 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310155	REV CTL PNL,4-POT DISPLAY								
31.130	9728121120 0132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40502492 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40502497 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310167	CC-500 CONTROL UNIT								
31.280	9859912202 31444 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310170	CCD INTERNAL ELECTRICAL ASSEMBLY								
31.290	9859912328 0073 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310175	REAR CENTRE CONS PNL PC-12 47/E								
31.300	9728121154 0761 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310177	MIDDLE CENTRE CONS PANEL								
	9728121146 0746 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310180	COCKPIT AREA MICROPHONE								
	9859920137 001216449 REF: AMM 31-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT								
	9859920146 001215342 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

CHAPTER 32

LANDING GEAR

+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: AMM 12-20-04	AFL					778		
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: AMM 32-10-00	AFL					778		
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK								
32.010		MOS	12	+1m/-1m		-34	04-SEP-2020	01-AUG-2021	01-SEP-2021
		HRS/MSC	2400	+10%/-10%			767:06	3167:06	3407:06
	REF: See Workcard	AFL					778		
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	5321012055	MOS		N:0			30-AUG-2017		
	VLG1143	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	5321012056	MOS		N:0			30-AUG-2017		
	VLG1143	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
AIRWORTHINESS	REF:	MOS					30-AUG-2017		
		HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
32.215		MOS					30-AUG-2017		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-AUG-2017		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					30-AUG-2017		
32.220		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	30000				0	30000	
+ 32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+10%/-10%		-5	04-SEP-2020	30-AUG-2021	06-OCT-2021
		HRS/MSC					767:06		
	REF: See Workcard	AFL					778		
+ 32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				30-AUG-2017	30-AUG-2023	
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
+ 32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				30-AUG-2017	30-AUG-2023	
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
+ 32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
		HRS/MSC					0		
	REF: AMM 32-10-00	AFL					0		
+ 32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
		HRS/MSC					0		
	REF: AMM 32-10-00	AFL					0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		
+ 32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		
+ 32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS	120				30-AUG-2017	30-AUG-2027	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		
+ 32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS	120				30-AUG-2017	30-AUG-2027	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		
+ 32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS	MOS	12	+1m/-1m			04-SEP-2020	04-SEP-2021	04-OCT-2021
	532.45.12.065	HRS/MSC	T/C				767:06		
	3739/3722	AFL					778		
	REF: AMM 12-20-06								
+ 32-10/80	LUBRICATE NOSE WHEEL BEARINGS	MOS	12	+1m/-1m		-34	04-SEP-2020	01-AUG-2021	01-SEP-2021
	9595602302	HRS/MSC	T/C				767:06		
	1679	AFL					778		
	REF: AMM 12-20-06								
+ 32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS	MOS	12	+1m/-1m		3	04-SEP-2020	07-SEP-2021	07-OCT-2021
	532.45.12.066	HRS/MSC	T/C				767:06		
	3931	AFL					778		
	REF: AMM 12-20-06								
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE	MOS	12	+10%/-10%			PKG		
	PKG 19	HRS/MSC	600	+10%/-10%			04-SEP-2020		
	REF: AMM 32-20-00	AFL					767:06		
							778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			767:06 778		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			767:06 778		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			767:06 778		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 32-20/403	NOSE LANDING GEAR - OVERHAUL PN	MOS					30-AUG-2017		
32.200	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0		0	25000	25500
OVERHAUL	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0		0	30000	30500
+ 32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK PN	MOS					30-AUG-2017		
32.225	SN-UNKNOWN	HRS/MSC	25000		N:0		0	25000	
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000		N:0		0	30000	
+ 32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM MOS						12-JAN-2018		
	REF: AMM 32-30-00	HRS/MSC AFL	N/A				105:06 170		
+ 32-30/423	LEFT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR 9595601823	MOS					30-AUG-2017		
	601	HRS/MSC			N:0		0		
LIFE LIMIT	REF: See Workcard	AFL	30000		N:0		0	30000	



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30/423	NOSE LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR 9595601824 299	MOS HRS/MSC AFL		N:0 N:0 N:0			30-AUG-2017 0 0		
LIFE LIMIT	REF: See Workcard		30000					30000	
+ 32-30/423	RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR 9595601823 599	MOS HRS/MSC AFL		N:0 N:0 N:0			30-AUG-2017 0 0		
LIFE LIMIT	REF: See Workcard		30000					30000	
+ 32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY	MOS HRS/MSC AFL	12 2000	+10%/-10%		-5	04-SEP-2020 767:06 778	30-AUG-2021 2767:06	06-OCT-2021
	REF: AMM 32-30-10								
+ 32-30/425 (s)	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS PKG 19	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
	REF: GENERIC NO REF								
+ 32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY	MOS HRS/MSC AFL	12 2000	+10%/-10%		-5	04-SEP-2020 767:06 778	30-AUG-2021 2767:06	06-OCT-2021
	REF: AMM 32-30-08								
+ 32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY	MOS HRS/MSC AFL	12 2000	+10%/-10%		-5	04-SEP-2020 767:06 778	30-AUG-2021 2767:06	06-OCT-2021
	REF: AMM 32-10-06								
+ 32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS HRS/MSC AFL		+500/-500 +500/-500			0		12000 12500
DISCARD	REF: See Workcard		12000						

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS		+500/-500					
DISCARD	REF: See Workcard	HRS/MSC AFL	12000	+500/-500			0	12000	12500
+ 32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS	MOS		+500/-500					
DISCARD	REF: See Workcard	HRS/MSC AFL	12000	+500/-500			0	12000	12500
+ 32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
	REF: See Workcard	HRS/MSC AFL					0 0		
+ 32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				30-AUG-2017	30-AUG-2023	
	REF: See Workcard	HRS/MSC AFL					0 0		
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS					30-AUG-2017		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS					30-AUG-2017		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
+ 32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			767:06 778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE PKG 17 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 17 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 17 REF: AMM 12-10-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 32-50/404	EXAMINE - NLG STEERING MECHANISM 32.230 REF: AMM 32-50-00	MOS HRS/MSC AFL	32500 42000	+500/-500 +500/-500			30-AUG-2017 0 0	32500 42000	33000 42500
320005	PILOT LH BRAKE MASTER CYLINDER 32.130 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751131 7140 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320015	PARK BRAKE VALVE								
32.140	9594751121 3037 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320020	NOSE WHEEL								
32.150	9595602302 1679 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				06-SEP-2019 526:24 533		
320022	LEFT MAIN LANDING GEAR WHEEL								
32.160	532.45.12.065 3739/3722 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:526:24 N:533			06-SEP-2019 526:24 533		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 9129S00321 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-JUL-2020		
320024	RIGHT MAIN LANDING GEAR WHEEL								
32.165	532.45.12.066 3931 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:526:24 N:533			06-SEP-2019 526:24 533		
320025	SHIMMY DAMPER ASSY								
32.100	5322012215 SI-0483 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	025-350-0 9129S0330 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-JUL-2020		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751131 7146 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751131 7147 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012305 SI-0096 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012044 SI-1143 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012230 VLG1480 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320060	LH BRAKE ASSY								
32.050	9595601517 3482 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	9595601503 3722 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320066	OUTER LEFT WHEEL & COVER ASSY								
32.205	9595601503 3739 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012230 VLG1481 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320085	RH BRAKE ASSY								
32.050	959.56.01.517 2077 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:25 O:0 O:0			25-APR-2018 187 250		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	9595601503 3726 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320091	OUTER RIGHT WHEEL & COVER ASSY								
32.210	9595601503 3745 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
32.170	9733033116 6369 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
32.170	9733033116 6385 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH								
32.175	9733033116 6393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320125	MAIN LANDING GEAR 72A74-01 LH "WOW" PROXIMITY SWITCH								
32.180	9733033116 6333 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320140	INTERMEDIATE CABLE ASSY 9595601816 00296 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320140	MAIN GEAR CABLE ASSY 9595601814 00311 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320140	NOSE GEAR CABLE ASSY 9595601815 00301 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320145	EXTENSION GEAR EMERGENCY HANDLE 9595601838 00308 REF: AMM 32-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320150	FRONT HIGH CURRENT RELAY 9740926112 749 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320150	REAR HIGH CURRENT RELAY 9740926112 730 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320155	LEFT HAND SPRING PACK ASSY 5323412120 535 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320155	RIGHT HAND SPRING PACK ASSY 5323412120 526 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320160	MLG L/H WOW NLG UP SWITCH ASSY 5326921026 2490 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
320160	MLG R/H WOW NLG UP SWITCH ASSY 5326921026 2456 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 33 LIGHTS									
+ 33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 17 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 17 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 17 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 17 REF: AMM 33-44-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 17	MOS	12	+10%/-10%			PKG	04-SEP-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778		
330005	DIM UNIT 9750215205	MOS		N:0			30-AUG-2017		
33.080	137363 REF: AMM 33-10-04	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330010	DE-ICE LIGHT ASSY 9728767111	MOS		N:0			30-AUG-2017		
33.010	3798586 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS		N:0			30-AUG-2017		
33.040	187596-6-25 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS		N:0			30-AUG-2017		
33.040	187596-6-19 REF: AMM 33-46-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY 03-0001-0100	MOS		N:0			06-SEP-2019		
33.030	209682-3-42 REF: AMM 33-43-02	HRS/MSC AFL	O/C	N:0 N:0			526:24 533		
330045	RH WING POWER SUPPLY UNIT 9728787179	MOS		N:0			30-AUG-2017		
33.070	184888-2-30 REF: AMM 33-43-03	HRS/MSC AFL	O/C	N:0 N:0			0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY 9728787345	MOS		N:0			30-AUG-2017		
33.030	184888-4-1 REF: AMM 33-43-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330070	NOSE LANDING GEAR TAXI LIGHT								
33.090	9728769429 186617-7-24 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
330075	L/H 1X0005287-10 LANDING LIGHT								
33.090	9728769427 184198-4-28 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
330076	R/H 1X0005287-10 LANDING LIGHT								
33.110	9728769427 184198-4-35 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
330085	LEFT HAND RECOGNITION LED LIGHT								
	9728769428 180966-10-8 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
330085	RIGHT HAND RECOGNITION LED LIGHT								
	9728769428 180966-10-10 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

CHAPTER 34

NAVIGATION

+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: GENERIC NO REF	AFL					533		
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/185 (s)	EXAMINE PITOT TUBE PKG 17	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778		
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 17	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			767:06 778		
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020		
	REF: AMM 34-11-00	HRS/MSC AFL	1200	+10%/-10%			767:06 778		
+ 34-11/343 34.565	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT REF: AMM 34-11-12	MOS HRS/MSC AFL	24		-7		06-SEP-2019 526:24 533	30-AUG-2021	
+ 34-11/82 34.010	LEAK CHECK STATIC SYSTEM REF: AMM 34-11-00	MOS HRS/MSC AFL	24				22-JAN-2021 832:12 835	22-JAN-2023	
+ 34-25/344 34.570	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM) REF: AMM 34-14-00	MOS HRS/MSC AFL	24				22-JAN-2021 832:12 835	22-JAN-2023	
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED) REF: AMM 34-26-40	MOS HRS/MSC AFL	24				17-OCT-2019 534 541	17-OCT-2021	
+ 34-54/86 34.050	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS) REF: See Workcard	MOS HRS/MSC AFL	24		-7		06-SEP-2019 526:24 533	30-AUG-2021	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340010	DME/IFF ANTENNA								
34.080	9848110240 261-124992 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340020	MARKER ANTENNA								
34.100	9848110260 101-8475 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340055	WITH HARM FILTER,KN63 DME								
34.200	9859911101 39597 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340065	WX-RADAR RT UNIT								
34.360	9859911507 15662 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 8456 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-125012 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 KA44B-A94862 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340100	FRONT KA92 ANTENNA								
34.090	9859911200 49310785 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340101	REAR KA92 GPS ANTENNA								
34.090	9859911200 49310794 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 19778 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340135	STANDBY MAGNETIC COMPASS								
34.130	PN NOT INSTALLED REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340140	RADOME								
34.420	9857900005 600 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 8971 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-83641 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-83649 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 31186 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 30900 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911524 KRA405B-18972 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	9859918006 102703 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1932 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340255	AOA SENSOR LH UNIT								
34.330	9754421423 1836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	9848110240 261-125020 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-4904 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-4876 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	9859911887 KMH920-B1969 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340310	NO. 2 KXP 2290 MODE S TRANSPONDER								
34.540	9859912269 KXP2290A-3625 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER								
34.540	9859912269 KXP2290A-3621 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340320	LH OAT SENSOR								
34.525	5341312025 06153 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340325	RH OAT SENSOR								
34.525	5341312025 UF942 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT								
34.505	065-00188-5104 KSG7200-B2904 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			22-JAN-2021 832:12 835		
340355	LH NAV/WHITE ANTENNA								
	9848110280 168-11782 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
340357	RH NAV/WHITE ANTENNA								
	9848110280 168-11783 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341035	NO. 1 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-3072 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
341037	NO. 2 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-3048 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
341039	MAG-3100 MAGNETOMETER 9859003058 80895 REF: AMM 34-26-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
341045	ESI-1000 STANDBY SYSTEM 9759611247 3343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
34CUS01	ADJUSTMENT/TEST AIRSPEED INDICATION REF:	MOS HRS/MSC AFL	24				22-JAN-2021 832:12 835	22-JAN-2023	
CHAPTER 35	OXYGEN								
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 06-FEB-2020 621:48		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM PKG 20 REF: AMM 35-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 35-10/6	REAR FUSELAGE OXYGEN CYLINDER 9571212212 C16110925 REF: AMM 35-10-01 Manufacture Date: 01-SEP-2016	MOS HRS/MSC AFL	180	N:0 N:0 N:0			01-SEP-2016	01-SEP-2031	
+ 35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER 9571212212 C16110925 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				01-SEP-2016	01-SEP-2021	
35-20/452	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED) REF: AMM 35-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		2	04-SEP-2020 767:06 778	06-SEP-2021 3767:06	12-OCT-2021
35-20/453	OVERHAUL NO. 1 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16100158 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
35-20/453	OVERHAUL NO. 2 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070113 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/453	OVERHAUL NO. 3 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070370 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 4 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070122 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 5 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070374 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 6 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070125 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 7 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070388 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 8 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070126 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									
35-20/453	OVERHAUL NO. 9 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 9571201215 D16070393 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			30-AUG-2017	30-AUG-2023	29-FEB-2024
OVERHAUL									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)	MOS						30-AUG-2017	
	REF: AMM 35-00-00	HRS/MSC AFL	N/A					0 0	
+ 35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS	36	+10%/-10%		-34		04-SEP-2020	01-AUG-2023 19-NOV-2023
35.010	REF: AMM 35-20-00	HRS/MSC AFL						767:06 778	
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY	MOS						30-AUG-2017	
35.040	9571201210 B121594 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY	MOS						30-AUG-2017	
35.040	9571201210 B121741 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
350030	PRESSURE,GAGE,OXYGEN SWITCH	MOS						30-AUG-2017	
35.050	9738114401 1585 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
350035	CONTR,3-POSITION,37071-03 VALVE	MOS						30-AUG-2017	
35.030	9633211102 0565 REF: AMM 35-20-04	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
350050	OXYGEN GAGE ASSY	MOS						30-AUG-2017	
35.060	5351212085 60278 REF: AMM 35-20-05	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
350055	OXYGEN PRESS TRANSDUCER	MOS						30-AUG-2017	
35.070	9571201184 8192-6-207 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350067	OXYGEN SHUT-OFF VALVE 9571212232 000137816 REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350071	NO. 1 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16100158 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350072	NO. 2 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070113 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350073	NO. 3 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070370 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350074	NO. 4 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070122 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070374 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350076	NO. 6 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070125 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	
350077	NO. 7 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070388 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				30-AUG-2017 0 0	



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350078	NO. 8 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070126 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0			
350079	NO. 9 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16070393 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0			
CHAPTER 45 CENTRAL MAINT SYSTEM										
+ 45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG			
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020			
		HRS/MSC	1200	+10%/-10%			767:06			
	REF: AMM 45-45-00	AFL					778			
CHAPTER 46 INFORMATION SYSTEMS										
+ 46-26/320	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES									
	PKG 17	MOS	12	+10%/-10%	3		04-SEP-2020	07-SEP-2021	13-OCT-2021	
		HRS/MSC	300	+10%/-10%			767:06	1067:06	1097:06	
	REF: See Workcard	AFL					778			
+ 46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES						PKG			
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020			
		HRS/MSC	300	+10%/-10%			767:06			
	REF: AMM 46-30-02	AFL					778			
460105	WIRELESS DATA LOADING DEVICE 9759632456 2843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0			
CHAPTER 52 DOORS										
+ 52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK						PKG			
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020			
		HRS/MSC	600	+10%/-10%			767:06			
	REF: GENERIC NO REF	AFL					778			

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 19	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 20	MOS	12	+10%/-10%			PKG 04-SEP-2020 767:06 778		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS					30-AUG-2017		
52.070		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 52-10-00	AFL	42000				0	42000	
+ 52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE	MOS					30-AUG-2017		
52.100		HRS/MSC	32500	+500/-500			0	32500	33000
	REF: AMM 52-00-01	AFL	42000	+500/-500			0	42000	42500
+ 52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN	MOS					30-AUG-2017		
52.110		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 52-10-01	AFL	30000	+500/-500			0	30000	30500



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)								
		MOS					30-AUG-2017		
		HRS/MSC	N/A				0		
	REF: AMM 52-10-06	AFL					0		
+ 52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
52.010		HRS/MSC	4000	+10%/-10%			0	4000	4400
	MODERATE CORROSION ZONE	AFL							
	REF: See Workcard								
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
		MOS					30-AUG-2017		
52.080		HRS/MSC	32500				0	32500	
	AIRWORTHINESS	AFL	42000				0	42000	
	REF: AMM 52-20-00								
+ 52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: AMM 52-30-00	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS					30-AUG-2017		
52.090		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000				0	42000	
+ 52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
		MOS					30-AUG-2017		
52.120		HRS/MSC	32500	+500/-500			0	32500	33000
	REF: AMM 52-30-00	AFL	42000	+500/-500			0	42000	42500
+ 52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
		MOS					30-AUG-2017		
52.130		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 52-30-01	AFL	30000	+500/-500			0	30000	30500
+ 52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
	PN	MOS			N:0		30-AUG-2017		
52.020	SN-UNKNOWN	HRS/MSC	13000		N:0		0	13000	
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000		N:0		0	17000	
+ 52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
52.030		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: See Workcard	AFL							



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM PKG 20	MOS	12	+10%/-10%			PKG	04-SEP-2020	
	REF: AMM 52-70-00	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		
520005	PASSENGER DOOR 5520512043	MOS		N:0			30-AUG-2017		
52.050	7006	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY 5520512044	MOS		N:0			30-AUG-2017		
52.040	7008	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-30-01	AFL		N:0			0		
520015	EMERGENCY 6 SERIE EXIT 5520512038	MOS		N:0			30-AUG-2017		
52.060	7008	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-20-01	AFL		N:0			0		
CHAPTER 53 FUSELAGE									
+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS. PKG 17	MOS	12	+10%/-10%			PKG	04-SEP-2020	
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			767:06		
		AFL					778		
+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD PKG 20	MOS	12	+10%/-10%			PKG	06-SEP-2019	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			526:24		
		AFL					533		
+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED PKG 20	MOS	12	+10%/-10%			PKG	04-SEP-2020	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: GENERIC NO REF	AFL					533		
+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019		
		HRS/MSC	2400	+10%/-10%			526:24		
	REF: GENERIC NO REF	AFL					533		
+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: AMM 53-20-02	AFL					778		
+ 53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION								
		MOS					30-AUG-2017		
53.100		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-06	AFL	42000				0		42000
+ 53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS								
		MOS					30-AUG-2017		
53.110		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000				0		42000
+ 53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS								
		MOS					30-AUG-2017		
53.120		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 53-20-00	AFL	42000				0		42000

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
53.130		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 53-00/355	EXAMINE - ANTENNA STRUCTURE								
53.140		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN								
53.150		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	28300				0		28300
		AFL	37000				0		37000
+ 53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN								
53.160		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 53-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION								
53.180		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION								
53.190		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 53-20-02	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
+ 53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION								
53.200		MOS					30-AUG-2017		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
+ 53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210		MOS					30-AUG-2017		
	REF: See Workcard	HRS/MSC	32500	+500/-500			0		32500 33000
		AFL	42000	+500/-500			0		42000 42500

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE								
		MOS					30-AUG-2017		
53.010		HRS/MSC	20000				0	20000	
AIRWORTHINESS	REF: GENERIC NO REF	AFL	27000				0	27000	
+ 53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
53.030		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT, WITH INSULATION REMOVED)								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
53.040		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
53.070		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
53.050		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
		MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
53.060		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
		MOS	12	+1m/-1m		-5	04-SEP-2020	30-AUG-2021	30-SEP-2021
34.575		HRS/MSC					767:06		
	REF: AMM 53-30-01	AFL					778		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
530070	FUSELAGE AB 1003 TEIL1								
53.090	5530512029 7008 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
CHAPTER 55 STABILIZERS									
+ 55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000 27000				30-AUG-2017 0 0	20000 27000	
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE						PKG		
	PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT						PKG		
	PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
+ 55-10/415	HORIZONTAL STABILIZER								
55.090	PN SN-UNKNOWN REF: AMM 55-10-01	MOS HRS/MSC AFL	25000 30000	N:0 N:0 N:0			30-AUG-2017 0 0	25000 30000	
LIFE LIMIT									
+ 55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
MODERATE CORROSION ZONE	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%			01-AUG-2017 0	01-AUG-2021 4000	25-DEC-2021 4400
+ 55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
MODERATE CORROSION ZONE	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%			30-AUG-2017 0 0	30-AUG-2021 4000	23-JAN-2022 4400

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20/362	EXAMINE LEFT WING ELEVATOR								
		MOS					30-AUG-2017		
55.100		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-00	AFL	42000				0		42000
+ 55-20/362	EXAMINE RIGHT WING ELEVATOR								
		MOS					30-AUG-2017		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-00	AFL	42000				0		42000
+ 55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
		MOS					30-AUG-2017		
55.110		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0		42000
+ 55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
		MOS					30-AUG-2017		
55.120		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0		42000
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
		MOS					30-AUG-2017		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-20-01	AFL	42000				0		42000
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		
+ 55-30/369	EXAMINE - VERTICAL STABILIZER								
		MOS					30-AUG-2017		
55.130		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-30-00	AFL	42000				0		42000

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
		MOS					30-AUG-2017		
55.140		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: See Workcard	AFL	42000				0		42000
+ 55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
		MOS					30-AUG-2017		
55.150		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-00-00	AFL	42000				0		42000
+ 55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
		MOS					30-AUG-2017		
55.160		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-30-02	AFL	42000				0		42000
+ 55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
		MOS					30-AUG-2017		
55.190		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 55-30-03	AFL	42000	+500/-500			0		42000 42500
+ 55-40/373	EXAMINE - RUDDER								
		MOS					30-AUG-2017		
55.170		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-40-00	AFL	42000				0		42000
+ 55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
		MOS					30-AUG-2017		
55.180		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 55-40-05	AFL	42000				0		42000
+ 55-40/410	EXAMINE - RUDDER TRIM TAB								
		MOS					30-AUG-2017		
55.200		HRS/MSC	32500	+500/-500			0		32500 33000
	REF: AMM 55-40-04	AFL	42000	+500/-500			0		42000 42500

CHAPTER 56 WINDOWS

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH PKG 17 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 56-11/12 56.020 AIRWORTHINESS	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		
+ 56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED REF: AMM 56-00-00	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		
+ 56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110109 15226H2077 REF: See Workcard	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		
+ 56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110110 15356H6346 REF: See Workcard	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		
+ 56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 15226H2077 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		
+ 56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110110 15356H6346 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				30-AUG-2017 0 0		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS								
56.100		MOS	120	+6m/-6m			30-AUG-2017	30-AUG-2027	29-FEB-2028
		HRS/MSC	11000	+500/-500			0	11000	11500
	REF: AMM 56-11-02	AFL					0		
+ 56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED								
56.110		MOS					30-AUG-2017		
AIRWORTHINESS		HRS/MSC	32500				0	32500	
	REF: See Workcard	AFL	42000				0	42000	
56-14/517 (s)	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND						PKG		
	PKG 20	MOS	12				30-AUG-2017		
		HRS/MSC	1200				0		
	REF: GENERIC NO REF	AFL					0		
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: AMM 56-00-00	AFL					778		
560015	SIDE,LH WINDOW								
56.090	9598110111	MOS			N:0		30-AUG-2017		
	15300H9615	HRS/MSC	O/C		N:0		0		
	REF: AMM 56-11-02	AFL			N:0		0		
560020	SIDE,RH WINDOW								
56.090	9598110112	MOS			N:0		30-AUG-2017		
	15318H2451	HRS/MSC	O/C		N:0		0		
	REF: AMM 56-11-02	AFL			N:0		0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029	MOS			N:0		30-AUG-2017		
	0002462622-012	HRS/MSC	O/C		N:0		0		
	REF: AMM 56-20-01	AFL			N:0		0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029	MOS			N:0		30-AUG-2017		
	0002462622-011	HRS/MSC	O/C		N:0		0		
	REF: AMM 56-20-01	AFL			N:0		0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 0002462622-008 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 0002488194-006 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 0002488194-005 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 0002462622-005 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 0002462622-004 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 0002462622-003 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 0002462622-002 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 17045H8803 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
561010	LEFT HAND WINDSHIELD ASSY, (LH)									
	9598110109	MOS		N:0			30-AUG-2017			
56.010	15226H2077	HRS/MSC	O/C	N:0			0			
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0			
561011	RIGHT HAND WINDSHIELD ASSY, (LH)									
	9598110110	MOS		N:0			30-AUG-2017			
56.010	15356H6346	HRS/MSC	O/C	N:0			0			
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0			
CHAPTER 57 WINGS										
+ 57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE									
		MOS					30-AUG-2017			
57.010		HRS/MSC	20000				0		20000	
AIRWORTHINESS	REF: AMM 57-00-00	AFL	27000				0		27000	
+ 57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE									
		MOS					30-AUG-2017			
57.010		HRS/MSC	20000				0		20000	
AIRWORTHINESS	REF: AMM 57-00-00	AFL	27000				0		27000	
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG			
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020			
		HRS/MSC	300	+10%/-10%			767:06			
	REF: GENERIC NO REF	AFL					778			
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG			
	PKG 21	MOS	24	+10%/-10%			06-SEP-2019			
		HRS/MSC	2400	+10%/-10%			526:24			
	REF: GENERIC NO REF	AFL					533			
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG			
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020			
		HRS/MSC	1200	+10%/-10%			767:06			
	REF: GENERIC NO REF	AFL					778			

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 20	MOS	12	+10%/-10%			PKG	04-SEP-2020	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					30-AUG-2017		
57.100		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0	39000	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					30-AUG-2017		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0	39000	
+ 57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					30-AUG-2017		
57.110		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
+ 57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-AUG-2017		
57.120		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					30-AUG-2017		
		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
+ 57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-AUG-2017		
57.130		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					30-AUG-2017		
		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
57.140		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
57.150		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
+ 57-00/412	EXAMINE - WING TIPS								
57.170		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-33-00	HRS/MSC	32500	+500/-500			0	32500	33000
		AFL	42000	+500/-500			0	42000	42500
+ 57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES								
57.180		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-01	HRS/MSC	25000	+500/-500			0	25000	25500
		AFL	30000	+500/-500			0	30000	30500
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES								
		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-01	HRS/MSC	25000	+500/-500			0	25000	25500
		AFL	30000	+500/-500			0	30000	30500

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
+ 57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
57.020		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%			01-AUG-2017	01-AUG-2021	25-DEC-2021
57.030		HRS/MSC	4000	+10%/-10%			0	4000	4400
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL							
+ 57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m			30-AUG-2017	30-AUG-2027	29-FEB-2028
57.040		HRS/MSC	11000	+500/-500			0	11000	11500
	REF: AMM 57-00-00	AFL					0		
+ 57-60/393	EXAMINE - RIGHT WING AILERON	MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 57-60/393	EXAMINE -LEFT WING AILERON	MOS					30-AUG-2017		
57.160		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 57-60-00	AFL	42000				0	42000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60/411	EXAMINE - AILERON TRIM TAB								
57.190		MOS					30-AUG-2017		
	REF: AMM 57-60-04	HRS/MSC	32500	+500/-500			0	32500	33000
		AFL	42000	+500/-500			0	42000	42500
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512041	MOS		N:0			30-AUG-2017		
	7008	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512042	MOS		N:0			30-AUG-2017		
	7008	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570050	L/H WING								
57.080	5570512049	MOS		N:0			30-AUG-2017		
	7008	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
570055	R/H WING								
57.090	5570512050	MOS		N:0			30-AUG-2017		
	7008	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
CHAPTER 61	PROPELLERS/PROPULSORS								
+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			767:06		
		AFL					778		
+ 61PR1	NO. 1 PROPELLER								
61.PR1	HC-E5A-3A/NC10245B	MOS							
	SA237	HRS/MSC	PP/C						
	REF: See Workcard	AFL							
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 612010	NO. 1 ENGINE - PROPELLER GOVERNOR 3049558-01 20844751 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
OVERHAUL									
+ 612020	NO. 1 ENGINE - OVERSPEED GOVERNOR PN SN-UNKNOWN REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
OVERHAUL									
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA237 Part # HC-E5A-3A/NC10245B									
+ 610010	NO. 1 PROPELLER - OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC	72 4000				19-JUN-2017 0	19-JUN-2023 (4000) 4000	
OVERHAUL									
+ 610020	NO. 1 PROPELLER - ACCOMPLISH A DETAIL INSPECTION REF: POM 61-00-47	MOS HRS/MSC	12 400				04-SEP-2020 767:06	04-SEP-2021 (1167:06) 1167:06	
OVERHAUL									
+ 610030	NO. 1 PROPELLER - LUBRICATE PROPELLER REF: POM 61-00-47	MOS HRS/MSC	12 400				10-JUN-2020 720	10-JUN-2021 (1120) 1120	
OVERHAUL									
+ 610050	NO. 1 PROPELLER - INSPECT BLADE USING COIN-TAP REF: RMM 61-13-70	MOS HRS/MSC	1200				19-JUN-2017 0	(1200) 1200	
OVERHAUL									
+ 610060	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP REF: RMM 61-13-70	MOS HRS/MSC	600				22-JAN-2020 602:42	(1202:42) 1202:42	
OVERHAUL									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611501	NO. 1 PROPELLER - NO. 1 BLADE 9682913024 B5494 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			19-JUN-2017 0		
611502	NO. 1 PROPELLER - NO. 2 BLADE 9682913024 B5308 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			19-JUN-2017 0		
611503	NO. 1 PROPELLER - NO. 3 BLADE 9682913024 B5332 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			19-JUN-2017 0		
611504	NO. 1 PROPELLER - NO. 4 BLADE 9682913024 B5404 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			19-JUN-2017 0		
611505	NO. 1 PROPELLER - NO. 5 BLADE 9682913024 B5306 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			19-JUN-2017 0		

CHAPTER	71	POWER PLANT
+ 71-00/101 (s)		OPERATIONAL TEST POWER PLANT TORQUE LIMITER
	71.010	PKG 19 MOS 12 +10%/-10% HRS/MSC 600 +10%/-10% REF: AMM 71-00-00 AFL
		PKG 04-SEP-2020 767:06 778
+ 71-00/102 (s)		OPERATIONAL TEST POWER PLANT PERFORMANCE
		PKG 19 MOS 12 +10%/-10% HRS/MSC 600 +10%/-10% REF: AMM 71-00-00 AFL
		PKG 04-SEP-2020 767:06 778

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/103	PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH								
71.040		MOS					30-AUG-2017		
	REF: AMM 71-00-00	HRS/MSC	A/R				0		
		AFL					0		
+ 71-00/104	PERFORM COMPRESSOR DESALINATION WASH								
		MOS					07-FEB-2019		
	REF: AMM 71-00-00	HRS/MSC	A/R				396:36		
		AFL					437		
+ 71-00/105	PERFORM TURBINE WASH								
		MOS					07-SEP-2018		
	REF: AMM 71-00-00	HRS/MSC	A/R				310		
		AFL					345		
+ 71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
	REF: AMM 71-00-03	HRS/MSC	600	+10%/-10%			767:06		
		AFL					778		
+ 71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN	MOS			N:0		30-AUG-2017		
	SN-UNKNOWN	HRS/MSC	20000		N:0		0		20000
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000		N:0		0		27000
+ 71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050		MOS					30-AUG-2017		
	REF: GENERIC NO REF	HRS/MSC	11000				0		11000
AIRWORTHINESS		AFL					0		
+ 71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: AMM 71-00-00	HRS/MSC	A/R				767:06		
		AFL					778		
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 20	MOS	12	+10%/-10%			06-SEP-2019		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			526:24		
		AFL					533		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES. REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION AND DO THE 100 HOUR AND MINOR INSPECTION ITEMS PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				04-SEP-2020 767:06 778		
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
+ 71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS. PKG 15 ,16,17,18,19,20,21 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				04-SEP-2020 767:06 778		
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. PKG 20 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			06-SEP-2019 526:24 533		
+ 71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 71.063 OVERHAUL	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		30-AUG-2017 0 0	3500	3850
+ 71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 71.064 OVERHAUL	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		30-AUG-2017 0 0	3500	3850
+ 71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY 9448121409 71.061 OVERHAUL	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		30-AUG-2017 0 0	3500	3850

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409	MOS		N:0			30-AUG-2017		
OVERHAUL	9934	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	9448121409	MOS		N:0			30-AUG-2017		
OVERHAUL	9947	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
71.130		MOS					30-AUG-2017		
AIRWORTHINESS	REF: AMM 71-00-05	HRS/MSC	26600				0	26600	
		AFL	35000				0	35000	
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				767:06		
		AFL					778		
+ 71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				767:06		
		AFL					778		
+ 71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					04-SEP-2020		
	REF: GENERIC NO REF	HRS/MSC	A/R				767:06		
		AFL					778		
710050	(WELDED) ENGINE MOUNT								
71.120	5712012036	MOS		N:0			30-AUG-2017		
	1577	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-00-05	AFL		N:0			0		
+ 71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P	MOS							
	PCE-RY0793	HRS/MSC	E/C						
	REF: AMM 71-00-00	AFL							

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									
+ 710011	NO. 1 ENGINE - OVERHAUL	MOS					10-MAY-2017		
		HRS/MSC	3500	+200			0	(3500) 3500	3700
OVERHAUL	REF: GENERIC NO REF	ENC					0		
+ 710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE	MOS					PKG		
	PKG 2	HRS/MSC	300	+10%/-10%			06-FEB-2020		
	REF: EMM 72-30-05	ENC					621:48		
+ 710021	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					10-MAY-2017		
		HRS/MSC	1750	+250			0	(1750) 1750	2000
	REF: EMM 72-00-00	ENC					0		
+ 710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					04-SEP-2020		
		HRS/MSC	400	+10%/-10%		32:54	767:06	(1200) 1200	1240
	REF: EMM 72-00-00	ENC					778		
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					10-MAY-2017		
		HRS/MSC	N/A				0		
	REF: EMM 72-00-00	ENC					0		
+ 710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH	MOS					12-JAN-2018		
		HRS/MSC	A/R				105:06		
	REF: EMM 71-00-00	ENC					170		
+ 710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH	MOS					10-MAY-2017		
		HRS/MSC	A/R				0		
	REF: EMM 71-00-00	ENC					0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS						10-MAY-2017	
	REF: EMM 72-00-00	HRS/MSC ENC	A/R					0 0	
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION	MOS						PKG	
	PKG 2	HRS/MSC ENC	300	+10%/-10%				06-FEB-2020 621:48	
	REF: EMM 71-00-00								
+ 710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS						10-MAY-2017	
	REF: EMM 72-00-00	HRS/MSC ENC	A/R					0 0	
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									
+ 720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS						10-MAY-2017	
	PN	HRS/MSC	3500	+200				0	(3500) 3500 3700
	SN-UNKNOWN	ENC						0	
	REF: See Workcard								
	OVERHAUL								
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL	MOS						06-FEB-2020	
	REF: EMM 72-00-00	HRS/MSC ENC	BF/F					621:48	
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP	MOS						06-FEB-2020	
	REF: EMM 72-60-00	HRS/MSC ENC	BF/F					621:48	
+ 720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT	MOS						PKG	
	PKG 2	HRS/MSC	300	+10%/-10%				06-FEB-2020	
	REF: GENERIC NO REF	ENC						621:48	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
	REF: GENERIC NO REF								
+ 720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
	REF: GENERIC NO REF								
+ 720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
	REF: GENERIC NO REF								
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS HRS/MSC ENC	BF/F				06-FEB-2020 621:48		
	REF: EMM 72-11-00								
+ 722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
	REF: See Workcard								
+ 722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
	REF: EMM 72-20-00								
+ 723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 MCAKAXRK196	MOS HRS/MSC ENC					10-MAY-2017 0		
	REF: GENERIC NO REF		24000				0	(24000) 24000	
LIFE LIMIT									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA708811	MOS HRS/MSC		N:0 N:0			10-MAY-2017 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
+ 723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 2	MOS HRS/MSC	300	+10%/-10%			06-FEB-2020 621:48	PKG	
	REF: EMM 72-30-04	ENC							
+ 723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 FRAEPUTU95	MOS HRS/MSC		N:0 N:0			10-MAY-2017 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
+ 723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS PKG 2	MOS HRS/MSC	300	+10%/-10%			06-FEB-2020 621:48	PKG	
	REF: See Workcard	ENC							
+ 723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 FRAEPUTK134	MOS HRS/MSC		N:0 N:0			10-MAY-2017 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
+ 723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAE000C777	MOS HRS/MSC		N:0 N:0			10-MAY-2017 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
+ 723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 FRAEPWAH39	MOS HRS/MSC		N:0 N:0			10-MAY-2017 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS					10-MAY-2017		
	UNSCCHEDULED MAINTENANCE CHECK	HRS/MSC A/R					0		
	REF: See Workcard	ENC					0		
+ 725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS		N:0			10-MAY-2017		
	3053740-01	HRS/MSC		N:0			0		
	YUAB001H840	ENC	8000	N:0			0	(8000) 8000	
	LIFE LIMIT	REF: GENERIC NO REF							
+ 725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					10-MAY-2017		
		HRS/MSC	5000				0	(5000) 5000	
	LIFE LIMIT	REF: GENERIC NO REF					0		
+ 725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS					PKG		
	PKG 2	HRS/MSC	300	+10%/-10%			06-FEB-2020		
	REF: EMM 72-50-05	ENC					621:48		
+ 725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS		N:0			10-MAY-2017		
	3037312	HRS/MSC		N:0			0		
	A0041TK4	ENC	15000	N:0			0	(15000) 15000	
	LIFE LIMIT	REF: GENERIC NO REF							
+ 725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS		N:0			10-MAY-2017		
	3037313	HRS/MSC		N:0			0		
	YUAB001H853	ENC	15000	N:0			0	(15000) 15000	
	LIFE LIMIT	REF: GENERIC NO REF							
+ 726020	NO. 1 ENGINE - POWER SECTION MODULE	MOS		N:0			10-MAY-2017		
	PN	HRS/MSC	3500	+200			0	(3500) 3500	3700
	SN-UNKNOWN	ENC		N:0			0		
	OVERHAUL	REF: GENERIC NO REF							

CHAPTER 73 ENGINE FUEL AND CONTROL

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731010	NO. 1 ENGINE - FUEL PUMP 3040760 015262 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	N:0 N:0 N:0			10-MAY-2017 0 0	(3500) 3500	
OVERHAUL									
+ 731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: EMM 73-11-05	MOS HRS/MSC ENC	400	+10%/-10%		32:54	04-SEP-2020 767:06 778	(1200) 1200	1240
+ 731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51696 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
OVERHAUL									
+ 731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
+ 731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	1750				10-MAY-2017 0 0	(1750) 1750	
+ 731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 015262 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			06-FEB-2020 621:48	(1221:48) 1221:48	1281:48
+ 731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 2 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			06-SEP-2019 526:24 533	(1126:24) 1126:24	1186:24
REPLACE									
+ 731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		
+ 731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA55514 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
+ 731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			29-JAN-2020 602:42	(902:42) 902:42	932:42
+ 731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0779 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
+ 731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		
+ 731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-10 20864605 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
OVERHAUL									
+ 731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		



Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%		7:18	29-JAN-2020 602:42	(910) 910	940
+ 731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		
+ 731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T				06-SEP-2019 526:24 533		
+ 732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			06-FEB-2020 621:48		
+ 733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			10-MAY-2017 0 0	(900) 900	990
+ 733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%		7:18	29-JAN-2020 602:42	(910) 910	940
CHAPTER 74	IGNITION								
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 17 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			04-SEP-2020 767:06 778		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA17090364 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
+ 740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%			06-FEB-2020 621:48	(1021:48) 1021:48	1061:48
+ 740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			06-FEB-2020 621:48	(1021:48) 1021:48	1061:48
+ 742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			06-FEB-2020 621:48	(1021:48) 1021:48	1061:48
CHAPTER 75 AIR									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									
+ 750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX1001128 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		10-MAY-2017 0 0	(3500) 3500	4000
CHAPTER 76 ENGINE CONTROLS									
+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 16 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 06-FEB-2020 621:48		
+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 04-SEP-2020 767:06 778		
+ 76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+10%/-10% +10%/-10%		-34	04-SEP-2020 767:06 778	01-AUG-2021 3767:06	07-SEP-2021 4067:06
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 9419411417 00114 REF: AMM 76-20-00	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
760020 76.030	CONDITION CABLE ASSY. 9419411418 00125 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		
760025 76.040	POWER CONTROL CABLE ASSY. 9419411419 00121 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C				30-AUG-2017 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES								
		MOS	12	+30d/-10%		3	04-SEP-2020	07-SEP-2021	07-OCT-2021
		HRS/MSC	300	+10%/-10%			767:06	(1067:06) 1067:06	1097:06
	REF: EMM 72-00-00	ENC					778		

CHAPTER 77 ENGINE INDICATING

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
	9752115206	MOS		N:0			30-AUG-2017		
77.010	8032-2-366	HRS/MSC	O/C	N:0			0		
	REF: AMM 77-40-03	AFL		N:0			0		
770025	DIFFERENTIAL PRESSURE TRANSDUCER								
	9752115219	MOS		N:0			30-AUG-2017		
	10535477	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01

771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01	MOS		N:0			10-MAY-2017		
	NRA101409	HRS/MSC	O/C	N:0			0		
	REF: EMM 77-20-01	ENC		N:0			0		

CHAPTER 78 EXHAUST

+ 78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 17	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	300	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		

CHAPTER 79 OIL

+ 79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK						PKG		
	PKG 19	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	600	+10%/-10%			767:06		
	REF: AMM 79-30-06	AFL					778		
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			04-SEP-2020		
		HRS/MSC	1200	+10%/-10%			767:06		
	REF: GENERIC NO REF	AFL					778		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 17	MOS	12	+10%/-10%			PKG		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%			04-SEP-2020 767:06 778		
+ 79-20/43	OIL COOLER 9683214102	MOS					30-AUG-2017		
79.010	T1762	HRS/MSC	3500	+10%/-10%			0	3500	3850
OVERHAUL	REF: AMM 79-20-02	AFL					0		
790005	TEMPERATURE BULB 9751120101	MOS					30-AUG-2017		
79.020	218330	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
790020	PRESSURE,GAGE SWITCH 9738114305	MOS					30-AUG-2017		
79.030	1655	HRS/MSC	O/C				0		
	REF: AMM 79-30-04	AFL					0		
790025	THERMAL ACTUATOR 9787301002	MOS					30-AUG-2017		
79.040	1926	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0793 Part # 3072955-01									
+ 790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					10-MAY-2017		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
+ 790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			11-FEB-2021	11-FEB-2022	13-MAR-2022
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			840:30 842	(1140:30) 1140:30	1170:30

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR REF: EMM 79-20-02	MOS HRS/MSC ENC	12 600	+1m/-1m +10%/-10%		-5	11-FEB-2021 840:30 842	06-FEB-2022 (1440:30) 1440:30	06-MAR-2022 1500:30
+ 790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT REF: EMM 79-20-02	MOS HRS/MSC ENC	900	+10%/-10%			10-MAY-2017 0 0	(900) 900	990
+ 790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN REF: EMM 79-20-02	MOS HRS/MSC ENC	300				22-JAN-2020 602:42 572	(902:42) 902:42	
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN REF: EMM 72-60-00	MOS HRS/MSC ENC	1000	+10%/-10%			10-MAY-2017 0 0	(1000) 1000	1100
+ 790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE REF: EMM 79-20-02	MOS HRS/MSC ENC	100	+10%/-10%		-4:48	09-OCT-2020 797:36 813	(892:48) 892:48	902:48
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING REF: EMM 72-00-00	MOS HRS/MSC ENC	12 300	+10%/-10%			18-MAY-2020 692:48 686	18-MAY-2021 (992:48) 992:48	1022:48
+ 790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		
+ 790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 06-FEB-2020 621:48		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 9752115214 8292-5-376 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			10-MAY-2017 0 0		
CHAPTER 91 -									
240120	BATTERY EXT POWER JUNCTION BOX 9740338152 1015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
910010	LEFT HD POWER JCT BOX 9740338144 1017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
910015	KBT 300 TTP BUS RES, A-157 TERMINAL 9859912117 KBT300-4308 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL 9859912117 KBT300-4313 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL 9859912117 KBT300-4327 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		
910035	CO-PILOT RIGHT HD POWER,FE1549R JUNCTION BOX 9740338145 889 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-AUG-2017 0 0		

Status Report

PC-12/47E S/N 1731 (SE-MIX): 850:18 HRS, 851 AFL as of 09-Mar-2021

Owner: OSCAR KILO AVIATION AB Operator: GRAFAIR FLIGHT MANAGEMENT AB

Report Date: 22-APR-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
	9859912117	MOS		N:0			30-AUG-2017		
90.010	KBT300-4297	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		