

OWNER: HI FIVE FLY SASU
ADDRESS: -
PHONE:
FAX:

OPERATOR: FLY 7 FINLAND OY
ADDRESS: LIIKELENTOTIE 8
 VANTAA 01530
PHONE: +358 40 594 3022
FAX:

OPERATOR: FLY 7 EXECUTIVE AVIATION SA
ADDRESS: AEROPORT DE LAUSANNE
 LAUSANNE CH-1018
PHONE: +41 21 648 21 42 (OPS)
FAX: +41 21 648 21 43

ANALYST: ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS;

AIRCRAFT SERIAL/REGNO: 1767/OH-DNG **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 25-JAN-2018	658:06 A/C HRS as of 10-APR-2022	A/C HRS as of ___/___/___
MANUFACTURER DATE: 31-JAN-2018	686 AFL as of 10-APR-2022	AFL as of ___/___/___
	186:54 ACH as of 22-NOV-2021	ACH as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-RY0832/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 21-DEC-2017	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS	658:06 ENG. HRS as of 10-APR-2022	ENG. HRS as of ___/___/___
0 ENC	625 ENC as of 10-APR-2022	ENC as of ___/___/___

PROPELLER NOSERIAL/PART: SA264/HC-E5A-3A **MODEL:** HC-E5A-3A **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 21-DEC-2017	LAST ACTUALS	CURRENT ACTUAL
0 PROP HRS 0 A/C HRS	658:06 PROP HRS as of 10-APR-2022	PROP HRS as of ___/___/___



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 15 in PKG 16,17,18,19,20,21	MOS				24-JAN-2022	PKG	
		HRS/MSC	A/R			581:29		
	REF: AMM 05-20-00	AFL				628		
<hr/>								
05401A	300 HOUR INSPECTION							
	PKG 16	MOS				24-JAN-2022		
		HRS/MSC	300	+30/-30		581:29	881:29	911:29
	REF: AMM 05-40-01	AFL				628		
<hr/>								
05402A	300 HOUR OR 12 MONTHS INSPECTION							
	PKG 17	MOS	12	+1m/-1m		24-JAN-2022	24-JAN-2023	24-FEB-2023
		HRS/MSC	300	+30/-30		581:29	881:29	911:29
	REF: AMM 05-40-01	AFL				628		
<hr/>								
05403A	600 HOUR INSPECTION							
	PKG 18	MOS				24-JAN-2022		
		HRS/MSC	600	+60/-60	18:31	581:29	1200	1260
	REF: AMM 05-40-01	AFL				628		
<hr/>								
05404A	600 HOUR OR 12 MONTHS INSPECTION							
	PKG 19	MOS	12	+1m/-1m	-9	24-JAN-2022	15-JAN-2023	15-FEB-2023
		HRS/MSC	600	+60/-60		581:29	1181:29	1241:29
	REF: AMM 05-40-01	AFL				628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTH INSPECTION							
	PKG 20	MOS	12	+1m/-1m	-9	24-JAN-2022	15-JAN-2023	15-FEB-2023
		HRS/MSC	1200	+120/-120		581:29	1781:29	1901:29
	REF: AMM 05-40-01	AFL				628		
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
	PKG 21	MOS	24	+1m/-1m	-9	24-JAN-2022	15-JAN-2024	15-FEB-2024
		HRS/MSC	2400	+60/-60		581:29	2981:29	3041:29
	REF: AMM 05-40-01	AFL				628		
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0832 Part # 3072955-01								
057010	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 2	MOS				24-JAN-2022		
		HRS/MSC	300	+10%/-10%		581:29	(881:29) 881:29	911:29
	REF: See Workcard	ENC				567		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: GENERIC NO REF	AFL					628		
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: GENERIC NO REF	AFL					628		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: GENERIC NO REF	AFL					628		
P47E-170906	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-04								
		MOS					25-JAN-2018		
		HRS/MSC	-				0		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL					0		
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF P47E	AFL							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS					25-JAN-2018		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL					0		0
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS					11-JUN-2020		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24	MOS					18-DEC-2020		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-210716	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 25	MOS					05-AUG-2021		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-181029 (s)	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0								
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0							11-MAY-2020	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1							11-MAY-2020	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2							04-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20							01-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29							01-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	MOS HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS						20-OCT-2020	
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-210412	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 53.0	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-210806	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 27	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-210913	NO. 1 ENGINE - REVIEW SB PT6A-72-14603 REV 30	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-211011	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 54.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC -							
<hr/>									
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA264 Part # HC-E5A-3A									
PE5A-200501	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 16	MOS						04-JUN-2020	
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
<hr/>									
PE5A-200801	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 33	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
<hr/>									
PE5A-200901	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 34	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
<hr/>									
PE5A-200901-1	NO. 1 PROPELLER - REVIEW HC-E5A-3A POM 147 REV 17	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
<hr/>									
PE5A-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PE5A-210304	NO. 1 PROPELLER - REVIEW SL HC-SL-61-61Y REV 13	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
PE5A-210401	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 TR-011	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
PE5A-210601	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 36	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							
PE5A-210707	NO. 1 PROPELLER - REVIEW HC-SL-61-61Y REV 14	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF PE5A	HRS/MSC -							

CHAPTER 04	LIMITATIONS
------------	-------------

040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
LIFE LIMIT	REF: GENERIC NO REF	AFL	60000	N:0			0		60000
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)								
		MOS					25-JAN-2018		
		HRS/MSC	N/A				0		
	REF: AMM 05-10-30	AFL					0		

050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION								
		MOS					25-JAN-2018		
		HRS/MSC	25000				0		25000
	REF: GENERIC NO REF	AFL	30000				0		30000

05ARC00	AIRWORTHINESS REVIEW CERTIFICATE (ARC)								
		MOS	12				19-JAN-2022		27-JAN-2023 M
		HRS/MSC							
	REF:	AFL							

CHAPTER 06 DIMENSIONS AND AREAS

06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: AMM 06-20-00	AFL					628		

06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: AMM 06-20-00	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR.						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						24-JAN-2022	
	REF: AMM 06-20-00	HRS/MSC	A/R					581:29	
		AFL						628	
<hr/>									
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOIN THE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC	A/R					581:29	
		AFL						628	
<hr/>									
CHAPTER 07	LIFTING AND SHORING								
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						24-JAN-2022	
	REF: AMM 07-10-00	HRS/MSC	A/R					581:29	
		AFL						628	
<hr/>									
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						24-JAN-2022	
	REF: AMM 07-10-00	HRS/MSC	A/R					581:29	
		AFL						628	
<hr/>									
CHAPTER 08	LEVELING AND WEIGHING								
080000	WEIGHT CHECK AIRCRAFT								
08.005		MOS	48	+10%/-10%		1		24-JAN-2022	25-JAN-2026 18-JUN-2026
	REF: AMM 08-10-00	HRS/MSC						581:29	
		AFL						628	
<hr/>									
CHAPTER 10	PARKING, MOORING, STORE AND RET TO SERV								



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
CHAPTER 11 PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: See Workcard	AFL					628		
CHAPTER 12 SERVICING									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: AMM 12-20-01	AFL					628		
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: AMM 12-20-02	AFL					628		
12-20/126 (s)	CLEAN COCKPIT AND CABIN						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
		HRS/MSC	A/R				581:29		
	REF: AMM 12-20-03	AFL					628		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
		MOS	12	+1m/-1m			24-JAN-2022	15-JAN-2023	15-FEB-2023
20.010		HRS/MSC				-9	581:29		
	REF: AMM 20-40-00	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
20.011	REF: AMM 20-40-00	MOS HRS/MSC AFL	6	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JUL-2022	02-AUG-2022
CHAPTER 21 AIR CONDITIONING									
21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE						PKG		
	PKG 21	MOS HRS/MSC AFL	24	+10%/-10%			24-JAN-2022 581:29 628		
	REF: GENERIC NO REF		2400	+10%/-10%					
21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK								
		MOS HRS/MSC AFL	12	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JAN-2023 3581:29	20-FEB-2023
AIRWORTHINESS	REF: GENERIC NO REF								
21-30/314 (s)	PRESSURIZATION SAFETY VALVE - CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND						PKG		
	CMT ITEM								
21.030	PN PKG 21	MOS HRS/MSC AFL	24	+10%/-10%			24-JAN-2022 581:29 628		
	SN-UNKNOWN		2400	+10%/-10%					
	REF: AMM 21-30-02								
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
21.045		MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
	REF: AMM 21-30-00								
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
	CMT ITEM								
21.040	PN	MOS HRS/MSC AFL	N/A				31-JAN-2018 0		
	SN-UNKNOWN								
	REF: AMM 21-30-00								



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/463	OPERATIONAL TEST CABIN PRESSURIZATION DUMP CONTROL	MOS	12	+10%/-10%			24-JAN-2022	15-JAN-2023	20-FEB-2023
	REF: AMM 21-30-00	HRS/MSC	600				581:29	1181:29	
		AFL					628		
21-30/464	OPERATIONAL TEST CABIN PRESSURIZATION MANUAL CONTROL	MOS	12	+10%/-10%			24-JAN-2022	15-JAN-2023	20-FEB-2023
	REF: AMM 21-30-00	HRS/MSC	600				581:29	1181:29	
		AFL					628		
21-30/465	FUNCTIONAL TEST CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE CMT ITEM	MOS	48	+10%/-10%		1	24-JAN-2022	25-JAN-2026	18-JUN-2026
	REF: AMM 21-30-00	HRS/MSC	4800				581:29	5381:29	
		AFL					628		
21-30/467	EXAMINE CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE	MOS	48	+10%/-10%		1	24-JAN-2022	25-JAN-2026	18-JUN-2026
	REF: AMM 21-30-05	HRS/MSC	4800	+10%/-10%			581:29	5381:29	5861:29
		AFL					628		
21-30/468	FUNCTIONAL TEST CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION	MOS	48				24-JAN-2022	24-JAN-2026	
	REF: AMM 21-30-00	HRS/MSC	4800				581:29	5381:29	
		AFL					628		
21-30/469	FUNCTIONAL TEST CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING	MOS	48				24-JAN-2022	24-JAN-2026	
	REF: AMM 21-30-00	HRS/MSC	4800				581:29	5381:29	
		AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH	MOS						15-JAN-2020	
	REF: AMM 21-43-00	HRS/MSC	N/A					6	
		AFL						7	
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH							PKG	
	PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
21.140	REF: See Workcard	HRS/MSC	1200	+10%/-10%				581:29	
		AFL						628	
21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH							PKG	
	9696781507 PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
21.150	REF: See Workcard	HRS/MSC	1200	+10%/-10%				581:29	
		AFL						628	
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER							PKG	
	PN PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
21.080	REF: AMM 21-40-03	HRS/MSC	1200	+10%/-10%				581:29	
		AFL						628	
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
	9738132216	MOS	60	+10%/-10%				31-JAN-2018	31-JAN-2023
21.130	REF: AMM 21-40-06	HRS/MSC	4800	+10%/-10%				0	4800
		AFL						0	5280
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
	9738132214	MOS	60	+10%/-10%				25-JAN-2018	25-JAN-2023
21.120	REF: AMM 21-60-05	HRS/MSC	4800	+10%/-10%				0	4800
		AFL						0	5280



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 18	MOS					24-JAN-2022		
	REF: AMM 21-40-02	HRS/MSC	600	+10%/-10%			581:29		
		AFL					628		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 18	MOS					24-JAN-2022		
	REF: AMM 21-40-02	HRS/MSC	600	+10%/-10%			581:29		
		AFL					628		
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			581:29		
		AFL					628		
21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)								
	9599022140 PKG 17	MOS	12	+1m/-1m			24-JAN-2022	24-JAN-2023	24-FEB-2023
	2066	HRS/MSC	300	+10%/-10%			581:29	881:29	911:29
	REF: AMM 21-40-03	AFL					628		
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022140	MOS					25-JAN-2018		
	2066	HRS/MSC					0		
	REF: AMM 21-50-03	AFL					0		
		ACH	600	+10%/-10%			0	600	660
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022140	MOS					25-JAN-2018		
	2066	HRS/MSC					0		
	REF: AMM 21-50-01	AFL					0		
		ACH	600	+10%/-10%			0	600	660



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	9599022140 2066 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH		+10%/-10%			0	500	550
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	9599022140 2066 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH		+10%/-10%			0	500	550
210005	OVERPRESSURE SWITCH								
21.340	9738115105 2070 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-JAN-2022 581:29 628		
210010	REFRIGERATION PACK								
21.255	9599020111 2238 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210015	WATER INJECTOR								
21.370	9599020141 2212 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 5006 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 2215 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 2222 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210035	WATER SEPARATOR ASSY								
21.220	PN SN-UNKNOWN REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020137 2226 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022140 2066 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 1108 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 1269 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091125 65053598-00068 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091132 77-F0781 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	9599091147 65000052-00053 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 587917 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	9599022118 1227 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 587924 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 1619 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	9599020160 1815 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210185	INTEG. ECS CONTROL UNIT								
21.540	9599020129 0831 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210190	FLOOR DUCT TEMP. SENSOR								
21.550	9599020121 5003 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR								
21.560	9599020121 4997 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	9633011005 1008 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	9738132216 1193 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	9738132214 1096 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	9633011105 1659B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2973B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 2984B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	9633011106 2993B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR								
21.600	9599020121 5049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 22		AUTO FLIGHT							
22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES							PKG	
	PKG 21	MOS	24	+10%/-10%			24-JAN-2022		
		HRS/MSC	2400	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
22-10/60 (s)	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK							PKG	
	PKG 20	MOS	12	+1m/-1m			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: AMM 22-10-00	AFL					628		
22-10/60 (s)	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK							PKG	
	PKG 20	MOS	12	+1m/-1m			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: AMM 22-10-00	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10/60 (s)	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK PKG 20 REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1200	+1m/-1m +10%/-10%			PKG 24-JAN-2022 581:29 628		
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 17 REF: AMM 22-20-02	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 16 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-JAN-2022 581:29 628		
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 20 REF: AMM 22-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
220045 22.220	STICK PUSHER SERVO 978611103 81107 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220055 22.140	STICK PUSHER CAPSTAN 978611124 81054 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220060	STICK SHAKER								
22.230	9786111143 1627 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220070	STICK PUSHER								
22.170	9754423104 137688 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3540 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3539 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B3528 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220100	RUDDER KSA 2700 SERVO								
22.260	9859912275 KSA2700-3592 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220105	ELEVATOR KSA 2700 SERVO								
22.250	9859912275 KSA2700-3595 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220110	AILERON KSA 2700 SERVO								
22.240	9859912275 KSA2700-3588 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
220115	KMC 9200 VNAV FLIGHT CONTROLLER								
	9859912204 KMC9200-2078 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 23 COMMUNICATIONS									
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH						PKG		
	PKG 21	MOS	24	+10%/-10%			24-JAN-2022		
	HRS/MSC	2400	+10%/-10%				581:29		
	REF: AMM 23-50-00	AFL					628		
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH						PKG		
	PKG 21	MOS	24	+10%/-10%			24-JAN-2022		
	HRS/MSC	2400	+10%/-10%				581:29		
	REF: AMM 23-12-00	AFL					628		
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	9848110203 310-30993 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	9848110203 310-30994 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
23.070	9848110210 430-15253 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.090	9859912254 4807 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.080	9859912254 4822 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	9859912108 N02146-P REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	9859912108 N02135-P REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 24 ELECTRICAL POWER



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/309	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437) CMT ITEM 9789123407 P2658 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				0		
24.210									
24-30/310	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.437) CMT ITEM 9789123407 P2660 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				0		
24.026									
24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JAN-2023 3581:29	20-FEB-2023
24.015 AIRWORTHINESS									
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JAN-2023 3581:29	20-FEB-2023
24.025 AIRWORTHINESS									
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST PKG 21 REF: AMM 24-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/339	REMOVE AND SERVICE NO. 1 NICAD BATTERY CMT ITEM								
24.060	31406-002 11701206 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	24-JAN-2023 981:29	01-MAR-2023 1021:29
24-30/339	REMOVE AND SERVICE NO. 2 NICAD BATTERY CMT ITEM								
24.061	31406-002 11701208 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	24-JAN-2023 981:29	01-MAR-2023 1021:29
24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY CMT ITEM								
24.010	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY CMT ITEM								
24.010	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
24-30/473 (s)	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) CMT ITEM								
	9789123407 PKG 18 P2658 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			24-JAN-2022 581:29 628		
24-30/474 (s)	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407) CMT ITEM								
	9789123407 PKG 18 P2660 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR			(P/N 978.9123.407)					
	9789123407	MOS					25-JAN-2018		
	P2658	HRS/MSC	1200				0		1200
OVERHAUL	REF: AMM 05-10-10	AFL					0		
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR			(P/N 978.9123.407)					
	9789123407	MOS					25-JAN-2018		
	P2660	HRS/MSC	1200				0		1200
OVERHAUL	REF: AMM 24-30-01	AFL					0		
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR			(P/N 978.9123.437)					
	9789123407	MOS					25-JAN-2018		
	P2658	HRS/MSC	N/A				0		
	REF: AMM 05-10-10	AFL					0		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR			(P/N 978.9123.437)					
	9789123407	MOS					25-JAN-2018		
	P2660	HRS/MSC	N/A				0		
	REF: AMM 24-30-01	AFL					0		
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE						PKG		
	PKG 21	MOS	24	+10%/-10%			24-JAN-2022		
		HRS/MSC	2400	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY								
	CMT ITEM								
	501-1712-02	MOS	12	+10%/-10%			24-JAN-2022	24-JAN-2023	01-MAR-2023
24.050	83823	HRS/MSC					581:29		
	REF: AMM 24-52-51	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			581:29 628		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 9882114111	MOS		N:0			25-JAN-2018		
24.120	P4430	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-05	AFL		N:0			0		
240010	GENERATOR 1 300A CONTACTOR 9740338113	MOS		N:0			25-JAN-2018		
24.130	730	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240015	GENERATOR 2 300A CONTACTOR 9740338113	MOS		N:0			25-JAN-2018		
24.130	750	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
240135	NO. 1 LEAD ACID BATTERY PN	MOS		N:0			25-JAN-2018		
24.010	NOT INSTALLED	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-07	AFL		N:0			0		
240140	NO. 2 LEAD ACID BATTERY PN	MOS		N:0			25-JAN-2018		
24.010	NOT INSTALLED	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-07	AFL		N:0			0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243010	NO. 2 STARTER-GENERATOR								
24.215	9789123407 P2660 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 83823 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C	N:48 R:0 N:581:29 R:0 N:628 R:0			24-JAN-2022 581:29 628		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11701206 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:48 N:581:29 N:628			24-JAN-2022 581:29 628		
243105	NO. 2 NICAD BATTERY								
24.061	31406-002 11701208 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:48 N:581:29 N:628			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243160	NO. 1 STARTER GENERATOR								
24.205	9789123407 P2658 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	9750215107 7894 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	9755085111 N4540 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	9755085111 N4622 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
243190	VOLTAGE REGULATOR								
	9882114111 P4451 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: AMM 25-10-01	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 16	MOS					PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				581:29 628	
+ 25-10/294	CO-PILOT SEAT BELT PN	MOS						25-JAN-2018	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	
25-10/294	CREW SEAT BELTS PN	MOS						25-JAN-2018	
25.030	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	
+ 25-10/294	PILOT SEAT BELT PN	MOS						25-JAN-2018	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG	24-JAN-2022	
	REF: AMM 25-10-01	HRS/MSC AFL	A/R					581:29 628	
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG	24-JAN-2022	
	REF: AMM 25-10-01	HRS/MSC AFL	A/R					581:29 628	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 20 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	PKG	
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	PKG	
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	PKG	
25-20/295	NO. 1 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		25-JAN-2018 0 0		
25-20/295	NO. 2 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		25-JAN-2018 0 0		
25-20/295	NO. 3 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/295	NO. 4 PASSENGER SEAT BELT								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
25-20/295	NO. 5 PASSENGER SEAT BELT								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
25-20/295	NO. 6 PASSENGER SEAT BELT								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 7 PASSENGER SEAT BELT								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-20/295	NO. 8 PASSENGER SEAT BELT								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
25-20/295	PASSENGER SEAT BELTS								
25.010	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 24-JAN-2022 581:29 628		
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 24-JAN-2022 581:29 628		
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-JAN-2022 581:29 628		
25-60/231 (s)	OPERATIONAL TEST ELT 9851380882 PKG 17 LX1101931328 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 9851380882 LX1101931328 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				03-NOV-2021 537:42 594		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63/23	ELT BATTERY PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL		DUE			03-NOV-2021 537:42 594	31-MAR-2028 M	
25.020	Expiry Date: 31-MAR-2028								
25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED) 9851380881 LX1100496476 REF: GENERIC NO REF	MOS HRS/MSC AFL	120 16000	+6m/-6m +500/-500			25-JAN-2018 0 0	25-JAN-2028 16000	25-JUL-2028 16500
25-63/477	CLEAN UNDERWATER LOCATOR BEACON (IF INSTALLED) PN SN-UNKNOWN REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				15-JAN-2020 6 7		
25-63/478	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (IF INSTALLED) PN SN-UNKNOWN REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				15-JAN-2020 6 7		
25-63/479	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON BATTERY VOLTAGE (IF INSTALLED) PN SN-UNKNOWN REF: AMM 25-63-04	MOS HRS/MSC AFL	N/A				15-JAN-2020 6 7		
25-CUS-01	INSPECT LIFE VESTS REF:	MOS HRS/MSC AFL	12	+1m/-1m			24-JAN-2022 581:29 628	24-JAN-2023	24-FEB-2023
250005	REMOTE CONTROL PANEL 9851380817 TM0000107290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250010	EMERGENCY LOCATOR TRANSMITTER								
25.050	9851380882 LX1101931328 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-NOV-2021 537.42 594		
250021	L/H NO. 1 AFSS PASSENGER SEAT								
25.120	9593001821 63033 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250022	R/H NO. 2 AFSS PASSENGER SEAT								
25.125	9593001822 63034 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250023	L/H NO. 3 FFSS PASSENGER SEAT								
25.130	9593001835 63035 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250024	R/H NO. 4 FFSS PASSENGER SEAT								
25.135	9593001836 63036 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250025	L/H NO. 5 FFSS PASSENGER SEAT								
25.140	9593001837 63037 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250026	R/H NO. 6 FFSS PASSENGER SEAT								
25.145	9593001838 63038 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250027	L/H NO. 7 STANDARD PASSENGER SEAT								
25.150	5252212011 2056 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250028	R/H NO. 8 STANDARD PASSENGER SEAT								
25.155	5252212012 2074 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE								
25.060	9851380881 LX1100496476 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
256020	LH BLACK PILOT SEAT								
25.090	9593001165 88157 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
256025	RH BLACK CO-PILOT SEAT								
25.100	9593001166 88158 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)								
25.110	REF: AMM 25-63-00	MOS HRS/MSC AFL	N/A				15-JAN-2020 6 7		
258020	RENEW NOAA 406 MHZ ELT REGISTRATION								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				03-NOV-2021 537:42 594		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C001	FIRST AID KIT AFAK.CAT.IDE.A.220 MX546 REF:	MOS HRS/MSC AFL	A/R				24-JAN-2022 581:29 628	16-DEC-2022 M	
25C002	FIRST AID KIT INSPECTION AFAK.CAT.IDE.A.220 MX546 REF:	MOS HRS/MSC AFL	12	+10%/-10%			24-JAN-2022 581:29 628	23-JAN-2023 M 28-FEB-2023	
CHAPTER 26 FIRE PROTECTION									
+ 26-20/2	CABIN FIRE EXTINGUISHER 1.5 KG								
26.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
26-20/2	COCKPIT FIRE EXTINGUISHER								
26.010	9590806219 106748 REF: GENERIC NO REF Manufacture Date: 01-JAN-2018	MOS HRS/MSC AFL	120		N:0 N:0 N:0		01-JAN-2018	01-JAN-2028	
26-20/24	CABIN FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)								
26.010	9590806219 106748 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m	-9		24-JAN-2022 581:29 628	15-JAN-2023	15-FEB-2023
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224)								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20/516	LIFE LIMIT (MODEL P3APP003010D - P/N 959.08.06.224) 9590806219 106748 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
260005 26.020	FIRE/OVERHEAT DETECTOR 9751210012 215578 REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 27 FLIGHT CONTROLS									
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-JAN-2022 581:29 628		
27-00/402 27.255	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-00/71 27.010	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK REF: AMM 27-00-00	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%			31-JAN-2018 0	31-JAN-2023 4800	31-JUL-2023 5280
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%				581:29 628	
27-10/236 (s)	AILERON CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%				581:29 628	
27-10/237 (s)	CHECK AILERON CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG	03-FEB-2022	
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+10%/-10%				584:21 631	
27-10/238 (s)	FUNCTIONAL TEST AILERONS PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-10-00	HRS/MSC AFL	2400	+10%/-10%				581:29 628	
27-10/394	AILERON CONTROL SYSTEM - EXAMINE	MOS						25-JAN-2018	
27.155	REF: AMM 27-10-00	HRS/MSC AFL	N/A					0 0	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS						25-JAN-2018	
27.160	REF: AMM 27-10-09	HRS/MSC AFL	N/A					0 0	
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS						25-JAN-2018	
27.165	REF: AMM 27-00-01	HRS/MSC AFL	N/A					0 0	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
27.170	REF: AMM 27-00-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS								
27.175	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
27.215	REF: AMM 57-60-06	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
	REF: AMM 57-60-06	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-10/444	FLIGHT CONTROL CABLES, AILERON								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-10-01	AFL	27000	N:0			0	27000	
27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL	27000	N:0			0	27000	
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: AMM 27-10-00	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-15-00	HRS/MSC AFL	2400	+10%/-10%				581:29 628	
27-20/140 (s)	INSPECTION/CHECK RUDDER PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 55-40-00	HRS/MSC AFL	300	+10%/-10%				581:29 628	
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%				581:29 628	
27-20/241 (s)	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%				581:29 628	
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG	03-FEB-2022	
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%				584:21 631	
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%				581:29 628	
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%				581:29 628	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					25-JAN-2018		
27.180	REF: AMM 27-20-00	HRS/MSC AFL	N/A				0 0		
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					25-JAN-2018		
27.190	REF: AMM 27-20-05	HRS/MSC AFL	N/A				0 0		
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					15-JAN-2020		
	REF: AMM 27-20-00	HRS/MSC AFL	O/C				6 7		
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS							
	PN SN-UNKNOWN REF: AMM 27-20-00	HRS/MSC AFL	A/R				0		
27-20/446	FLIGHT CONTROL CABLES, RUDDER	MOS					25-JAN-2018		
	PN SN-UNKNOWN REF: AMM 27-20-01	HRS/MSC AFL	20000 27000		N:0 N:0 N:0		0 0 0		20000 27000
27-20/447	AUTOPILOT CONTROL CABLES, RUDDER	MOS					25-JAN-2018		
	PN SN-UNKNOWN REF: AMM 27-20-02	HRS/MSC AFL	20000 27000		N:0 N:0 N:0		0 0 0		20000 27000



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/575	REPLACE RUDDER BELLCRANK PN SN-UNKNOWN REF: AMM 27-20-04	MOS HRS/MSC AFL	20000 27000				25-JAN-2018 0 0	20000 27000	
27-30/141 (s)	EXAMINE ELEVATORS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
27-30/249 (s)	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK PKG 20 REF: AMM 27-30-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 20 REF: AMM 27-30-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 03-FEB-2022 584:21 631		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 21 REF: AMM 27-30-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED								
27.150	REF: AMM 27-30-00	MOS HRS/MSC AFL	O/C				15-JAN-2020 6 7		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)								
	REF: AMM 27-30-00	PN SN-UNKNOWN AFL	A/R				0		
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE								
27.195	REF: AMM 27-30-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS								
27.200	REF: AMM 27-00-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
27.205	REF: AMM 27-00-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
27.210	REF: AMM 27-30-05	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	REF: AMM 27-30-01	PN SN-UNKNOWN AFL	20000 27000	N:0 N:0 N:0			25-JAN-2018 0 0	20000 27000	
LIFE LIMIT									



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-02	AFL	27000	N:0			0		27000
27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: AMM 55-20-01	AFL					628		
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (CMR)								
27.021		MOS	12	+10%/-10%	-9		24-JAN-2022	15-JAN-2023	20-FEB-2023
AIRWORTHINESS	REF: AMM 27-40-00	HRS/MSC	3000				581:29	3581:29	
		AFL					628		
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: AMM 27-40-00	AFL					628		
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: AMM 27-40-01	AFL					628		
27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	978.73.14.203	MOS	84				25-JAN-2018	25-JAN-2025	
	1786	HRS/MSC	3400				0	3400	
OVERHAUL	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 16	MOS					PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	300	+10%/-10%			24-JAN-2022 581:29 628		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 27-40-00	HRS/MSC AFL	1200	+10%/-10%			24-JAN-2022 581:29 628		
27-40/3	REPLACE PITCH TRIM ACTUATOR 978.73.14.203	MOS					25-JAN-2018		
	1786	HRS/MSC	20000				0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000				0		27000
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) PN	MOS					25-JAN-2018		
	27.036 SN-UNKNOWN	HRS/MSC	10000		N:0		0		10000
LIFE LIMIT	REF: AMM 27-40-02	AFL			N:0		0		
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R				24-JAN-2022 581:29 628		
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 17	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			24-JAN-2022 581:29 628		
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST CMT ITEM PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: AMM 27-50-00	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
27-50/28	FLAP POWER DRIVE UNIT 9787320003	MOS			N:0		25-JAN-2018		
27.030	1615	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
OVERHAUL	REF: AMM 27-50-01	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202205	MOS			N:0		25-JAN-2018		
27.060	S7982	HRS/MSC	10000		N:0		0	10000	
DISCARD	REF: AMM 27-50-02	AFL	13500		N:0		0	13500	
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202206	MOS			N:0		25-JAN-2018		
27.060	S7961	HRS/MSC	10000		N:0		0	10000	
DISCARD	REF: AMM 27-50-02	AFL	13500		N:0		0	13500	
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202205	MOS			N:0		25-JAN-2018		
27.070	S7984	HRS/MSC	10000		N:0		0	10000	
DISCARD	REF: AMM 27-50-02	AFL	13500		N:0		0	13500	
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT 9450202206	MOS			N:0		25-JAN-2018		
27.070	S7957	HRS/MSC	10000		N:0		0	10000	
DISCARD	REF: AMM 27-50-02	AFL	13500		N:0		0	13500	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/386	FLAP MECHANISM - EXAMINE								
27.220	REF: AMM 27-51-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
27.225	REF: AMM 27-51-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
27.230	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
27.235	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS								
27.240	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS								
	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
27.245		MOS					25-JAN-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
27.250		MOS					25-JAN-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
27-50/414	LEFT HAND FLAP								
57.060	5570512025	MOS		N:0			25-JAN-2018		
	7014	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
27-50/414	RIGHT HAND FLAP								
57.060	5570512026	MOS		N:0			25-JAN-2018		
	7014	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			24-JAN-2022	15-JAN-2023	20-FEB-2023
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	600	+10%/-10%	-9		581:29	1181:29	1241:29
		AFL					628		
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES								
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: AMM 12-20-07	HRS/MSC	300	+10%/-10%			581:29		
		AFL					628		
27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-JAN-2022 581:29 628		
27-50/485 27.040 DISCARD	LEFT INBOARD FLAP ACTUATOR 9787320309 6367 REF: AMM 27-50-03	MOS HRS/MSC AFL	20000 27000	N:0 N:0 N:0			25-JAN-2018 0 0	20000 27000	
27-50/485 27.041 DISCARD	LEFT OUTBOARD FLAP ACTUATOR 9787320309 6378 REF: AMM 27-50-03	MOS HRS/MSC AFL	20000 27000	N:0 N:0 N:0			25-JAN-2018 0 0	20000 27000	
27-50/485 27.050 DISCARD	RIGHT INBOARD FLAP ACTUATOR 9787320309 6352 REF: AMM 27-50-03	MOS HRS/MSC AFL	20000 27000	N:0 N:0 N:0			25-JAN-2018 0 0	20000 27000	
27-50/485 27.051 DISCARD	RIGHT OUTBOARD FLAP ACTUATOR 9787320309 6364 REF: AMM 27-50-03	MOS HRS/MSC AFL	20000 27000	N:0 N:0 N:0			25-JAN-2018 0 0	20000 27000	
+ 27-50/495 27.040	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR 9787320309 6367 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	7		24-JAN-2022 581:29 628	31-JAN-2024 2981:29 3828	12-APR-2024 3221:29 4148
+ 27-50/495 27.041	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR 9787320309 6378 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	7		24-JAN-2022 581:29 628	31-JAN-2024 2981:29 3828	12-APR-2024 3221:29 4148



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/495	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 6352 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	7		24-JAN-2022 581:29 628	31-JAN-2024 2981:29 3828	12-APR-2024 3221:29 4148
+ 27-50/495	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 6364 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%	7		24-JAN-2022 581:29 628	31-JAN-2024 2981:29 3828	12-APR-2024 3221:29 4148
+ 27-50/506	OVERHAUL LEFT INBOARD FLAP ACTUATOR								
27.040 OVERHAUL	9787320309 6367 REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			25-JAN-2018 0 0	5000 7000	
+ 27-50/506	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR								
27.041 OVERHAUL	9787320309 6378 REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			25-JAN-2018 0 0	5000 7000	
+ 27-50/506	OVERHAUL RIGHT INBOARD FLAP ACTUATOR								
27.050 OVERHAUL	9787320309 6352 REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			25-JAN-2018 0 0	5000 7000	
+ 27-50/506	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR								
27.051 OVERHAUL	9787320309 6364 REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			25-JAN-2018 0 0	5000 7000	
+ 27-50/576 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 PKG 17 6367 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/576 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR						PKG		
27.041	9787320309 PKG 17 6378 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
+ 27-50/576 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR						PKG		
27.050	9787320309 PKG 17 6352 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			24-JAN-2022 581:29 628		
+ 27-50/576 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR						PKG		
27.051	9787320309 PKG 17 6364 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			24-JAN-2022 581:29 628		
270003	HORIZONTAL TAIL ASSY								
	5551012037 1595 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012041 1682 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270023	ELEVATOR RH ASSY								
27.023	5552012042 1677 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318138 1695 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270033	RUDDER ASSY								
27.033	5554012040 1454M REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270035	FLAP CONTROL AND WARNING UNIT								
27.130	9787320017 137487 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 1750046DZ REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 2648 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 1750106DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 1750087DX REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 2651 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270080	KTA2810,TRIM ADAPTER								
22.135	9859912249 KTA2810-2431 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270090	AILERON LINEAR ACTUATOR								
27.140	9787318138 1701 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 1750089DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
274020	PITCH TRIM ACTUATOR								
	978.73.14.203 1786 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 28 FUEL									
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: AMM 28-10-02	HRS/MSC AFL	300	+10%/-10%			581:29 628		
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS		+10%/-10%					
	REF: AMM 28-10-01	HRS/MSC AFL	2400	+10%/-10%			0	2400	2640



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 17 REF: AMM 28-20-07	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT CMT ITEM PKG 17 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N) PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP CMT ITEM PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
28-20/256 (s)	FUEL SYSTEM COMPONENTS - EXAMINE AS FAR AS POSSIBLE WITH THOSE ACCESS PANELS OPENED / REMOVED IN THIS INSPECTION PACKAGE PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
28-20/32	OVERHAUL ENGINE DRIVEN PUMP 9688451108 B6211 REF: AMM 28-20-03	MOS HRS/MSC AFL	3500		N:0 N:0 N:0		25-JAN-2018 0 0	3500	
280005	LOW PRESSURE FUEL PUMP 9688451108 B6211 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280010	FUEL FLOW TRANSMITTER								
28.130	9753512108 AAR0535 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280012	FUEL CONTROL MONITORING UNIT								
28.155	975.37.31.336 871 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2020 166:54 234		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301 3874 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301 3879 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280025	FUEL FILTER ASSY								
28.025	9683521001 2017FFT2008 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 2963 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B6449 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B6135 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731253 2694 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731252 2661 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731251 2622 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731250 2632 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 C-911 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B6446 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B6144 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731250 2631 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731251 2623 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	9753731252 2662 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731253 2693 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 C-826 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280105	TOP CHECK VALVE								
28.150	9630423105 4031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280110	BOTTOM CHECK VALVE								
28.150	9630423105 4029 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1785 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	9753731335 1891 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: AMM 30-10-00	AFL					628		
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM						PKG		
	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	600	+10%/-10%			581:29		
	REF: AMM 30-20-00	AFL					628		
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: See Workcard	AFL					628		
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1								
30.010		MOS	6	+10%/-10%		-9	24-JAN-2022	15-JUL-2022	02-AUG-2022
		HRS/MSC					581:29		
	REF: GENERIC NO REF	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED CMT ITEM PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 19	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 30-30-20	HRS/MSC AFL	600	+10%/-10%			581:29 628		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 21	MOS	24	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 30-40-00	HRS/MSC AFL	2400	+10%/-10%			581:29 628		
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 19	MOS	12	+1m/-1m			PKG	24-JAN-2022	
	REF: See Workcard	HRS/MSC AFL	600	+30/-30			581:29 628		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 19	MOS	12	+1m/-1m			PKG	24-JAN-2022	
	REF: See Workcard	HRS/MSC AFL	600	+30/-30			581:29 628		
300005	PROP DE-ICE CONTROLLER 9682913227	MOS		N:0				25-JAN-2018	
30.140	U4008	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300010	LPMI LINEAR ACTUATOR								
30.150	9787315302 D86990 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300015	REGULATOR-RELIEVER ASSY								
30.160	9598901012 N170799 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	9598901008 N172066 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N172067 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N172073 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N172074 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 9149 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300050	WATER SEPARATOR								
30.060	9598901010 N172129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	9598901044 UA143 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 137833 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 137834 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	9598901041 NEB2080 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	9598901042 NEB7460 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300100	RH INBD-WING DE-ICER BOOT								
30.040	9598901038 NEB5810 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	9598901040 NEC1300 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421418 UG282 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	9598901037 NEB5780 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	9598901039 NEB3030 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421418 UG276 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 9057 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 9056 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 9092 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 9093 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	9598901008 N172467 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-30/421 (s)	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)						PKG		
	9859920146 PKG 20 001242650 REF: AMM 31-30-01	MOS HRS/MSC AFL	12	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	9859912178 KMC2210-3063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE								
31.240	9859912292 1708E696 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE								
31.270	9859912292 1708E697 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD								
31.160	9859912231 1703H818 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310085	OVERHEAD CONTROL BASIC PANEL								
31.260	9728121155 0806 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310090	KMC2220 MF CONTOLLER								
31.170	9859912189 KMC2220-2163 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310095	PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	9859912178 KMC2210-3053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1706P464 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1706P467 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	9859912147 17099477 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	9859912231 1703H816 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	9859912346 17055550 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	9859912346 17075702 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	9859912252 17061960 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	9859912251 17081989 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	9859912103 2890005175 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	9859912103 2890005378 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 2890005810 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 2890005376 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310155	REV CTL PNL,4-POT DISPLAY								
31.130	9728121120 0166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40505182 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40505192 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310167	CC-500 CONTROL UNIT								
31.280	9859912202 33349 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310170	CCD INTERNAL ELECTRICAL ASSEMBLY								
31.290	9859912328 0118 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310175	REAR CENTRE CONS PNL PC-12 47/E								
31.300	9728121154 0783 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310177	MIDDLE CENTRE CONS PANEL								
	9728121146 0780 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310180	COCKPIT AREA MICROPHONE								
	9859920137 001241975 REF: AMM 31-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT								
	9859920146 001242650 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
CHAPTER 32	LANDING GEAR								
32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 19 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS						PKG		
	PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS						PKG		
	PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 19	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%			581:29 628		
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK	MOS	12	+1m/-1m			24-JAN-2022	15-JAN-2023	15-FEB-2023
32.010	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%	-9		581:29 628	2981:29	3221:29
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY 5321012055	MOS		N:0			25-JAN-2018		
32.070	REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY 5321012056	MOS		N:0			25-JAN-2018		
32.070	REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
	REF:	HRS/MSC AFL	N/A				0 0		
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
32.215	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
32.220	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+10%/-10%		-9	24-JAN-2022	15-JAN-2023	20-FEB-2023
	REF: See Workcard	HRS/MSC					581:29		
		AFL					628		
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				25-JAN-2018	25-JAN-2024	
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				25-JAN-2018	25-JAN-2024	
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				25-JAN-2018	25-JAN-2024	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				25-JAN-2018	25-JAN-2024	
	REF: AMM 32-10-00	HRS/MSC					0		
		AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS REF: AMM 32-10-00	MOS HRS/MSC AFL	72				25-JAN-2018 0 0	25-JAN-2024	
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS REF: AMM 32-10-00	MOS HRS/MSC AFL	72				25-JAN-2018 0 0	25-JAN-2024	
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS REF: AMM 32-10-00	MOS HRS/MSC AFL	120				25-JAN-2018 0 0	25-JAN-2028	
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS REF: AMM 32-10-00	MOS HRS/MSC AFL	120				25-JAN-2018 0 0	25-JAN-2028	
+ 32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS PN SN-UNKNOWN REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m			24-JAN-2022 581:22 567	24-JAN-2023	24-FEB-2023
+ 32-10/80	LUBRICATE NOSE WHEEL BEARINGS 9595602302 1732 REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m			24-JAN-2022 581:22 567	24-JAN-2023	24-FEB-2023
+ 32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS PN 3841/3823 REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m			24-JAN-2022 581:22 567	24-JAN-2023	24-FEB-2023



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 19	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: AMM 32-20-00	HRS/MSC AFL	600	+10%/-10%			581:29 628		
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 19	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			581:29 628		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 19	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 19	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
32-20/335	NOSE LANDING GEAR TORQUE TUBE PN	MOS	120		N:0		25-JAN-2018	25-JAN-2028	
32.190	SN-UNKNOWN	HRS/MSC	11000		N:0		0	11000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	15000		N:0		0	15000	
32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK PN	MOS					25-JAN-2018		
32.195	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF:	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/403	NOSE LANDING GEAR - OVERHAUL								
	PN	MOS		N:0			25-JAN-2018		
32.200	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0		0	25000	25500
OVERHAUL	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0		0	30000	30500
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
	PN	MOS		N:0			25-JAN-2018		
32.225	SN-UNKNOWN	HRS/MSC	25000		N:0		0	25000	
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000		N:0		0	30000	
32-30/170	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM								
	CMT ITEM								
		MOS					26-JAN-2021		
		HRS/MSC	N/A				210:53		
	REF: AMM 32-30-00	AFL					287		
32-30/423	LEFT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601823	MOS		N:0			25-JAN-2018		
	667	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000		N:0		0	30000	
32-30/423	NOSE LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601824	MOS		N:0			25-JAN-2018		
	337	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000		N:0		0	30000	
32-30/423	RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	9595601823	MOS		N:0			25-JAN-2018		
	662	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000		N:0		0	30000	
32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
	CMT ITEM								
		MOS	12	+10%/-10%		-9	24-JAN-2022	15-JAN-2023	20-FEB-2023
		HRS/MSC	2000				581:29	2581:29	
	REF: AMM 32-30-10	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/425 (s)	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS CMT ITEM PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY CMT ITEM REF: AMM 32-30-08	MOS HRS/MSC AFL	12 2000	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JAN-2023 2581:29	20-FEB-2023
32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY REF: AMM 32-10-06	MOS HRS/MSC AFL	12 2000	+10%/-10%		-9	24-JAN-2022 581:29 628	15-JAN-2023 2581:29	20-FEB-2023
32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS DISCARD REF: See Workcard	MOS HRS/MSC AFL	12000				0	12000	
32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS DISCARD REF: See Workcard	MOS HRS/MSC AFL	12000				0	12000	
32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS DISCARD REF: See Workcard	MOS HRS/MSC AFL	12000				0	12000	
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS REF: See Workcard	MOS HRS/MSC AFL	72				25-JAN-2018 0 0	25-JAN-2024	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				25-JAN-2018	25-JAN-2024	
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS					25-JAN-2018		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS					25-JAN-2018		
	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			581:29		
		AFL					628		
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: AMM 12-10-04	HRS/MSC	300	+10%/-10%			581:29		
		AFL					628		
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			581:29		
		AFL					628		
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: AMM 12-10-04	HRS/MSC	300	+10%/-10%			581:29		
		AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: AMM 12-10-02	AFL					628		
32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230		MOS					25-JAN-2018		
		HRS/MSC	N/A				0		
	REF: AMM 32-50-00	AFL					0		
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	9594751131	MOS		N:0			25-JAN-2018		
	7207	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-04	AFL		N:0			0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	9594751131	MOS		N:0			25-JAN-2018		
	7208	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-04	AFL		N:0			0		
320015	PARK BRAKE VALVE								
32.140	9594751121	MOS		N:0			25-JAN-2018		
	3070	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-40-05	AFL		N:0			0		
320020	NOSE WHEEL								
32.150	9595602302	MOS		N:48			24-JAN-2022		
	1732	HRS/MSC	O/C	N:581:22			581:22		
	REF: AMM 32-40-02	AFL		N:567			567		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320022	LEFT MAIN LANDING GEAR WHEEL								
32.160	PN SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:48 N:581:22 N:567			24-JAN-2022 581:22 567		
320023	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 0067T00289 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-JAN-2021 210:53 287		
320024	RIGHT MAIN LANDING GEAR WHEEL								
32.165	PN 3841/3823 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				24-JAN-2022 581:22 567		
320025	SHIMMY DAMPER ASSY								
32.100	5322012215 943 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320026	RIGHT MAIN LANDING GEAR TIRE								
32.165	025-350-0 0358T00334 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2021 456:30 514		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	9594751131 7210 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751131 7211 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012305 VLG120 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012044 VLG1158 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012230 VLG1516 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320060	LH BRAKE ASSY								
32.050	9595601517 3580 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	9595601503 3815 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320066	OUTER LEFT WHEEL & COVER ASSY								
32.205	9595601503 3833 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012230 VLG1517 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320085	RH BRAKE ASSY								
32.050	9595601517 4197 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-SEP-2021 456:30 514		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	9595601503 3823 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320091	OUTER RIGHT WHEEL & COVER ASSY								
32.210	9595601503 3841 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
32.170	9733033116 6655 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
32.175	9733033116 6631 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH								
32.180	9733033116 6634 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
32.170	9733033116 6656 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320140	INTERMEDIATE CABLE ASSY 9595601816 00368 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320140	MAIN GEAR CABLE ASSY 9595601814 00385 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320140	NOSE GEAR CABLE ASSY 9595601815 00332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320145	EXTENSION GEAR EMERGENCY HANDLE 9595601838 00283 REF: AMM 32-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320150	FRONT HIGH CURRENT RELAY 9740926112 833 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320150	REAR HIGH CURRENT RELAY 9740926112 830 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320155	LEFT HAND SPRING PACK ASSY 5323412120 596 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320155	RIGHT HAND SPRING PACK ASSY 5323412120 599 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320160	MLG L/H WOW NLG UP SWITCH ASSY 5326921026 2695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
320160	MLG R/H WOW NLG UP SWITCH ASSY 5326921026 2692 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 33 LIGHTS

33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 17 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 17 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 17 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 33-44-00	HRS/MSC AFL	300	+10%/-10%			581:29 628		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
330005	DIM UNIT 9750215205	MOS						25-JAN-2018	
33.080	137711	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-10-04	AFL		N:0			0		
330010	DE-ICE LIGHT ASSY 9728767111	MOS						25-JAN-2018	
33.010	3977884	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS						25-JAN-2018	
33.040	193183-4-8	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-46-00	AFL		N:0			0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 9728787347	MOS						25-JAN-2018	
33.040	193183-4-2	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-46-00	AFL		N:0			0		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY 9728787344	MOS						25-JAN-2018	
33.030	189536-4-16	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-43-02	AFL		N:0			0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330045	RH WING POWER SUPPLY UNIT								
33.070	9728787179 192551-4-11 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	9728787345 192551-5-15 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330070	NOSE LANDING GEAR TAXI LIGHT								
33.090	9728769429 189952-3-8 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330075	L/H 1X0005287-10 LANDING LIGHT								
33.090	9728769427 191113-1-10 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330076	R/H 1X0005287-10 LANDING LIGHT								
33.110	9728769427 191113-1-13 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330085	LEFT HAND RECOGNITION LED LIGHT								
	9728769428 189952-2-10 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
330085	RIGHT HAND RECOGNITION LED LIGHT								
	9728769428 189952-2-7 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 34 NAVIGATION



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS PKG 21	MOS	24	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			581:29 628		
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 17	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
34-11/185 (s)	EXAMINE PITOT TUBE PKG 17	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
34-11/186 (s)	EXAMINE STATIC PORTS PKG 17	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			581:29 628		
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: AMM 34-11-00	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
34-11/343	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT	MOS	24				24-JAN-2022	15-JAN-2024	
34.565	REF: AMM 34-11-12	HRS/MSC AFL			-9		581:29 628		
34-11/82	LEAK CHECK STATIC SYSTEM	MOS	24				24-JAN-2022	15-JAN-2024	
34.010	REF: AMM 34-11-00	HRS/MSC AFL			-9		581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED)								
34.560	REF: AMM 34-21-00	MOS HRS/MSC AFL	N/A				15-JAN-2020 6 7		
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)								
34.570	REF: AMM 34-14-00	MOS HRS/MSC AFL	24	+10%/-10%	-6		24-JAN-2022 581:29 628	18-JAN-2024	30-MAR-2024
34-26/484	CHECK SWING ESIS MAGNETIC HEADING REFERENCE SYSTEM (IF INSTALLED)								
	REF: AMM 34-26-40	MOS HRS/MSC AFL	24	+10%/-10%	1		24-JAN-2022 581:29 628	25-JAN-2024	06-APR-2024
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)								
34.050	REF: See Workcard	MOS HRS/MSC AFL	24		-9		24-JAN-2022 581:29 628	15-JAN-2024	
340010	DME/IFF ANTENNA								
34.080	9848110240 261-126035 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340020	MARKER ANTENNA								
34.100	9848110260 101-8535 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340055	WITH HARM FILTER,KN63 DME								
34.200	9859911101 39831 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340065	WX-RADAR RT UNIT								
34.360	9859911507 15727 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 8528 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-126037 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 KA44B-A95069 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340100	FRONT KA92 ANTENNA								
34.090	9859911200 49310944 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	9859911200 49310945 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 19900 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340140	RADOME								
34.420	9857900005 644 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 9032 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-88529 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-88530 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 30967 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 30963 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911524 KRA405B-19303 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	9859918006 103279 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1980 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340255	AOA SENSOR LH UNIT								
34.330	975.44.21.423 1450 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			01-SEP-2021 456:30 514		
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	9848110240 261-126044 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-5063 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-5062 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	9859911887 KMH920-B2001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340310	NO. 2 KXP 2290 MODE S TRANSPONDER								
34.540	9859912269 KXP2290H-3686 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER								
34.540	9859912269 KXP2290H-3692 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340320	LH OAT SENSOR								
34.525	5341312025 06189 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340325	RH OAT SENSOR								
34.525	5341312025 06338 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT								
34.505	9859912272 KSG7200-B2939 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340355	LH NAV/WHITE ANTENNA								
	9848110280 168-11893 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
340357	RH NAV/WHITE ANTENNA								
	9848110280 168-11894 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341035	NO. 1 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-3160 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
341037	NO. 2 KGS200,SBAS GNSSU UNIT 9859912253 KGS200-3148 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
341039	MAG-3100 MAGNETOMETER 9859003058 80940 REF: AMM 34-26-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
341045	ESI-1000 STANDBY SYSTEM 9759611247 3458 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 35	OXYGEN								
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-JAN-2022 581:29 628		
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
+ 35-10/6	OXYGEN BOTTLE PN 35.010 SN-UNKNOWN N/A EQUIPMENT NOT INSTALLED REF: AMM 35-10-01	MOS HRS/MSC AFL	N/A						
35-10/6	REAR FUSELAGE OXYGEN CYLINDER CMT ITEM 9571212212 C17100403 AIRWORTHINESS REF: AMM 35-10-01 Manufacture Date: 01-AUG-2017	MOS HRS/MSC AFL	180	N:0 N:0 N:0			25-JAN-2018 0 0	01-AUG-2032	
+ 35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE PN 35.010 SN-UNKNOWN N/A EQUIPMENT NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER CMT ITEM 9571212212 C17100403 AIRWORTHINESS REF: GENERIC NO REF	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
35-20/452	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED) REF: AMM 35-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%	-9		24-JAN-2022 581:29 628	15-JAN-2023 3581:29	20-FEB-2023
35-20/453	OVERHAUL NO. 1 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 957.12.01.215 D16091349 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	72				25-JAN-2018	25-JAN-2024	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/453	OVERHAUL NO. 2 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091361	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 3 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091365	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 4 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091371	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 5 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091386	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 6 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091394	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 7 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091402	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/453	OVERHAUL NO. 8 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	9571201215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091406	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/453	OVERHAUL NO. 9 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	9571201215	MOS	72				25-JAN-2018	25-JAN-2024	
	D16091407	HRS/MSC							
OVERHAUL	REF: GENERIC NO REF	AFL							
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)								
		MOS					25-JAN-2018		
		HRS/MSC	N/A				0		
	REF: AMM 35-00-00	AFL					0		
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS								
35.010		MOS	36	+10%/-10%		5	26-JAN-2021	31-JAN-2024	18-MAY-2024
		HRS/MSC					210:53		
	REF: AMM 35-20-00	AFL					287		
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210	MOS					25-JAN-2018		
	B127337	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	9571201210	MOS					25-JAN-2018		
	B127415	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	9738114401	MOS					25-JAN-2018		
	1623	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350035	CONTR,3-POSITION,37071-03 VALVE								
35.030	9633211102 0591 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350050	OXYGEN GAGE ASSY								
35.060	5351212085 60288 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350055	OXYGEN PRESS TRANSDUCER								
35.070	9571201184 8362-2-305 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350067	OXYGEN SHUT-OFF VALVE								
	9571212232 000239179 REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350071	NO. 1 PASSENGER OXYGEN MASK ASSEMBLY								
	957.12.01.215 D16091349 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350072	NO. 2 PASSENGER OXYGEN MASK ASSEMBLY								
	957.12.01.215 D16091361 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350073	NO. 3 PASSENGER OXYGEN MASK ASSEMBLY								
	957.12.01.215 D16091365 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350074	NO. 4 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D16091371 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D16091386 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350076	NO. 6 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D16091394 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350077	NO. 7 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D16091402 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350078	NO. 8 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16091406 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
350079	NO. 9 PASSENGER OXYGEN MASK ASSEMBLY 9571201215 D16091407 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 45 CENTRAL MAINT SYSTEM

45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG	
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022	
	REF: AMM 45-45-00	HRS/MSC AFL	1200	+10%/-10%			581:29 628	

CHAPTER 46 INFORMATION SYSTEMS



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
46-26/320 (s)	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			581:29 628		
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 46-30-02	HRS/MSC AFL	300	+10%/-10%			581:29 628		
460105	WIRELESS DATA LOADING DEVICE 9759632456	MOS						25-JAN-2018	
	2907	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	
CHAPTER 52 DOORS									
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK PKG 19	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 19	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS PKG 19	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 19	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR	MOS					25-JAN-2018		
52.070	REF: AMM 52-10-00	HRS/MSC AFL	N/A				0 0		
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE	MOS					25-JAN-2018		
52.100	REF: AMM 52-00-01	HRS/MSC AFL	N/A				0 0		
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN	MOS					25-JAN-2018		
52.110	REF: AMM 52-10-01	HRS/MSC AFL	N/A				0 0		
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED	MOS	48	+10%/-10%			24-JAN-2022	31-JAN-2026	24-JUN-2026
52.010	REF: See Workcard	HRS/MSC AFL	4000	+10%/-10%	7		581:29 628	4581:29	4981:29
	MODERATE CORROSION ZONE								
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED) PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK PKG 20	MOS	12	+10%/-10%			PKG 24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
52.080	REF: AMM 52-20-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 19	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
	REF: GENERIC NO REF								
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						PKG		
	PKG 19	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
	REF: AMM 52-30-00								
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
	REF: GENERIC NO REF								
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
	REF: GENERIC NO REF								
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
52.090	REF: AMM 52-30-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
52.120	REF: AMM 52-30-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
52.130	REF: AMM 52-30-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
52.020	REF: AMM 52-30-07	PN SN-UNKNOWN AFL		N:0 13000 17000			25-JAN-2018 0 0	13000 17000	
AIRWORTHINESS									
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
52.030	REF: See Workcard	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		7	24-JAN-2022 581:29 628	31-JAN-2026 4581:29	24-JUN-2026 4981:29
MODERATE CORROSION ZONE									
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM								
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
	REF: AMM 52-70-00	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
520005	PASSENGER DOOR								
52.050	REF: See Workcard	5520512043 1454M AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	REF: AMM 52-30-01	5520512044 1453M AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
520015	EMERGENCY 6 SERIE EXIT								
52.060	REF: AMM 52-20-01	5520512038 1453M AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

CHAPTER 53 FUSELAGE



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 17	MOS	12	+10%/-10%				24-JAN-2022	
		HRS/MSC	300	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
		HRS/MSC	1200	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
		HRS/MSC	1200	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 21	MOS	24	+10%/-10%				24-JAN-2022	
		HRS/MSC	2400	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%				24-JAN-2022	
		HRS/MSC	2400	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 20	MOS	12	+10%/-10%				24-JAN-2022	
		HRS/MSC	1200	+10%/-10%				581:29	
	REF: GENERIC NO REF	AFL						628	
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						25-JAN-2018	
		HRS/MSC	N/A					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24 PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 53-20-02	HRS/MSC AFL	1200	+10%/-10%			581:29 628		
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
53.100	REF: AMM 53-10-06	HRS/MSC AFL	N/A				0 0		
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					25-JAN-2018		
53.110	REF: AMM 53-10-00	HRS/MSC AFL	N/A				0 0		
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					25-JAN-2018		
53.120	REF: AMM 53-20-00	HRS/MSC AFL	N/A				0 0		
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					25-JAN-2018		
53.130	REF: AMM 53-30-00	HRS/MSC AFL	N/A				0 0		
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					25-JAN-2018		
53.140	REF: AMM 53-00-00	HRS/MSC AFL	N/A				0 0		
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					25-JAN-2018		
53.150	REF: AMM 53-00-00	HRS/MSC AFL	N/A				0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN								
53.160	REF: AMM 53-00-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION								
53.180	REF: AMM 57-00-03	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION								
53.190	REF: AMM 53-20-02	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION								
53.200	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		7	24-JAN-2022 581:29 628	31-JAN-2026 4581:29	24-JUN-2026 4981:29
MODERATE CORROSION ZONE									
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT, WITH INSULATION REMOVED)								
53.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%		7	24-JAN-2022 581:29 628	31-JAN-2026 4581:29	24-JUN-2026 4981:29
MODERATE CORROSION ZONE									



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%			24-JAN-2022	31-JAN-2026	24-JUN-2026
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
		AFL					628		
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%			24-JAN-2022	31-JAN-2026	24-JUN-2026
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
		AFL					628		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%			24-JAN-2022	31-JAN-2026	24-JUN-2026
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
		AFL					628		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
34.575		MOS	12	+1m/-1m			24-JAN-2022	15-JAN-2023	15-FEB-2023
	REF: AMM 53-30-01	HRS/MSC					581:29		
		AFL					628		
530070	FUSELAGE AB 1003 TEIL1								
53.090	5530512029	MOS					25-JAN-2018		
	1453M	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
CHAPTER 55	STABILIZERS								
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
		MOS					25-JAN-2018		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			581:29		
		AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 20	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 55-00-00	HRS/MSC	1200	+10%/-10%			581:29		
		AFL					628		
55-10/415	HORIZONTAL STABILIZER PN	MOS		N:0			25-JAN-2018		
55.090	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 55-10-01	AFL	30000	N:0			0	30000	
+ 55-10/638	HORIZONTAL STABILIZER - EXAMINE WITH BOROSCOPE	MOS	240				25-JAN-2018	25-JAN-2038	
	REF: AMM 55-10-01	HRS/MSC	10000				0	10000	
		AFL					0		
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)	MOS	48	+10%/-10%	1		24-JAN-2022	25-JAN-2026	18-JUN-2026
MODERATE CORROSION ZONE	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
		AFL					628		
55-20/362	EXAMINE LEFT WING ELEVATOR	MOS					25-JAN-2018		
55.100	REF: AMM 55-20-00	HRS/MSC	N/A				0		
		AFL					0		
55-20/362	EXAMINE RIGHT WING ELEVATOR	MOS					25-JAN-2018		
	REF: AMM 55-20-00	HRS/MSC	N/A				0		
		AFL					0		
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER	MOS					25-JAN-2018		
55.110	REF: AMM 55-20-01	HRS/MSC	N/A				0		
		AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
55.120	REF: AMM 55-20-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
	REF: AMM 55-20-01	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. PKG 17	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS PKG 20	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
55-30/369	EXAMINE - VERTICAL STABILIZER								
55.130	REF: AMM 55-30-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
55.140	REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
55.150	REF: AMM 55-00-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
55.160	REF: AMM 55-30-02	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
55.190	REF: AMM 55-30-03	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-40/373	EXAMINE - RUDDER								
55.170	REF: AMM 55-40-00	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
55.180	REF: AMM 55-40-05	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200	REF: AMM 55-40-04	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		
CHAPTER 56 WINDOWS									
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED								
56.020	REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		
AIRWORTHINESS									
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED								
	REF: AMM 56-00-00	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110109 16270H5901 REF: AMM 56-11-01	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110110 16049H2236 REF: AMM 56-11-01	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 16270H5901 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110110 16049H2236 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				25-JAN-2018 0 0		
56-11/200 (s)	EXAMINE WINDSHIELD LH AND RH PKG 17 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS 56.100 REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500			25-JAN-2018 0 0	25-JAN-2028 11000	25-JUL-2028 11500
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED 56.110 REF: See Workcard	MOS HRS/MSC AFL	N/A				25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/517 (s)	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND PKG 20	MOS	12				PKG 24-JAN-2022 581:29 628		
	REF: GENERIC NO REF	HRS/MSC AFL	1200						
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 17	MOS	12	+10%/-10%			PKG 24-JAN-2022 581:29 628		
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%					
560015	SIDE,LH WINDOW 9598110111	MOS					25-JAN-2018		
56.090	16035H0554	HRS/MSC	O/C	N:0			0		
	REF: AMM 56-11-02	AFL		N:0			0		
560020	SIDE,RH WINDOW 9598110112	MOS					25-JAN-2018		
56.090	16264H5403	HRS/MSC	O/C	N:0			0		
	REF: AMM 56-11-02	AFL		N:0			0		
560025	RH NO 1 CABIN WINDOW 5562012029	MOS					25-JAN-2018		
56.060	0002595910-005	HRS/MSC	O/C	N:0			0		
	REF: AMM 56-20-01	AFL		N:0			0		
560030	RH NO 2 CABIN WINDOW 5562012029	MOS					25-JAN-2018		
56.060	0002595910-004	HRS/MSC	O/C	N:0			0		
	REF: AMM 56-20-01	AFL		N:0			0		
560035	RH NO 3 CABIN WINDOW 5562012029	MOS					25-JAN-2018		
56.070	0002595908-009	HRS/MSC	O/C	N:0			0		
	REF: AMM 56-20-01	AFL		N:0			0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 0002595909-002 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 0002595910-009 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 0002595909-012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 0002595909-011 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 0002595910-012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 0002595908-008 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 17242H5288 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
	9598110109	MOS		N:0			25-JAN-2018		
56.010	16270H5901	HRS/MSC	O/C	N:0			0		
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0		
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
	9598110110	MOS		N:0			25-JAN-2018		
56.010	16049H2236	HRS/MSC	O/C	N:0			0		
AIRWORTHINESS	REF: AMM 56-11-01	AFL		N:0			0		
CHAPTER 57 WINGS									
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			24-JAN-2022		
		HRS/MSC	2400	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)								
		MOS					25-JAN-2018		
		HRS/MSC	N/A				0		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					25-JAN-2018		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					25-JAN-2018		
57.100		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0	39000	
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-00-00	HRS/MSC	30000				0	30000	
		AFL	39000				0	39000	
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS					25-JAN-2018		
57.110		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					25-JAN-2018		
57.120		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					25-JAN-2018		
57.130		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-JAN-2018		
57.140		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-05	AFL	30000				0	30000	
57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					25-JAN-2018		
57.150		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
57-00/412	EXAMINE - WING TIPS	MOS					25-JAN-2018		
57.170		HRS/MSC	N/A				0		
	REF: AMM 57-33-00	AFL					0		
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					25-JAN-2018		
57.180		HRS/MSC	N/A				0		
	REF: AMM 57-20-01	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					25-JAN-2018		
		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0	30000	30500
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%	7		24-JAN-2022	31-JAN-2026	24-JUN-2026
57.020		HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL					628		
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%	7		24-JAN-2022	31-JAN-2026	24-JUN-2026
57.030		HRS/MSC	4000	+10%/-10%			581:29	4581:29	4981:29
MODERATE CORROSION ZONE	REF: GENERIC NO REF	AFL					628		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m			25-JAN-2018	25-JAN-2028	25-JUL-2028
57.040		HRS/MSC	11000	+500/-500			0	11000	11500
	REF: AMM 57-00-00	AFL					0		
57-60/393	EXAMINE - RIGHT WING AILERON	MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60/393	EXAMINE -LEFT WING AILERON								
57.160		MOS					25-JAN-2018		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190		MOS					25-JAN-2018		
	REF: AMM 57-60-04	HRS/MSC	32500	+500/-500			0		32500 33000
		AFL	42000	+500/-500			0		42000 42500
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512041	MOS		N:0			25-JAN-2018		
	3455M	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512042	MOS		N:0			25-JAN-2018		
	3455M	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570050	L/H WING								
57.080	5570512049	MOS		N:0			25-JAN-2018		
	1453M	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
570055	R/H WING								
57.090	5570512050	MOS		N:0			25-JAN-2018		
	1455M	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
CHAPTER 61	PROPELLERS/PROPULSORS								
61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	CMT ITEM								
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E5A-3A SA264 REF: See Workcard	MOS HRS/MSC AFL	PP/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	3049558-01 21008790 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-SEP-2017 0 0	(3500) 3500	4000
OVERHAUL									
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
	3079148-01 20991715 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-SEP-2017 0 0	(3500) 3500	4000
OVERHAUL									
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA264 Part # HC-E5A-3A									
610010	NO. 1 PROPELLER - OVERHAUL								
		MOS HRS/MSC	72 4000				13-NOV-2017 0	13-NOV-2023 (4000) 4000	
OVERHAUL	REF: GENERIC NO REF								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAIL INSPECTION								
		MOS HRS/MSC	12 400	+1m/-1m +10%/-10%		-9 29:24	24-JAN-2022 581:29	15-JAN-2023 (1010:53) 1010:53	15-FEB-2023 1050:53
	REF: POM 61-00-47								
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER								
		MOS HRS/MSC	12 400	+1m/-1m		-9	24-JAN-2022 581:29	15-JAN-2023 (981:29) 981:29	15-FEB-2023
	REF: POM 61-00-47								
+ 610050	NO. 1 PROPELLER - INSPECT BLADE USING COIN-TAP CMT ITEM								
		MOS HRS/MSC	1200	+10%/-10%			13-NOV-2017 0	(1200) 1200	1320
	REF: RMM 61-13-70								



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610060	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP CMT ITEM	MOS					24-JAN-2022		
	REF: RMM 61-13-70	HRS/MSC	600	+10%/-10%			581:29	(1181:29) 1181:29	1241:29
610070	NO. 1 PROPELLER - RESISTANCE CHECK "P" STATIC BONDING	MOS					13-NOV-2017		
	REF:	HRS/MSC	N/A				0		
611501	NO. 1 PROPELLER - NO. 1 BLADE NC10245B	MOS		N:0			13-NOV-2017		
	B6705 REF: GENERIC NO REF	HRS/MSC	O/C	N:0			0		
611502	NO. 1 PROPELLER - NO. 2 BLADE NC10245B	MOS		N:0			13-NOV-2017		
	B6587 REF: GENERIC NO REF	HRS/MSC	O/C	N:0			0		
611503	NO. 1 PROPELLER - NO. 3 BLADE NC10245B	MOS		N:0			13-NOV-2017		
	B6668 REF: GENERIC NO REF	HRS/MSC	O/C	N:0			0		
611504	NO. 1 PROPELLER - NO. 4 BLADE NC10245B	MOS		N:0			13-NOV-2017		
	B6673 REF: GENERIC NO REF	HRS/MSC	O/C	N:0			0		
611505	NO. 1 PROPELLER - NO. 5 BLADE NC10245B	MOS		N:0			13-NOV-2017		
	B6659 REF: GENERIC NO REF	HRS/MSC	O/C	N:0			0		

CHAPTER 71 POWER PLANT



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
	HRS/MSC		600	+10%/-10%			581:29		
	REF: AMM 71-00-00	AFL					628		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
	HRS/MSC		600	+10%/-10%			581:29		
	REF: AMM 71-00-00	AFL					628		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
	HRS/MSC		600	+10%/-10%			581:29		
	REF: AMM 71-00-03	AFL					628		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN	MOS		N:0			25-JAN-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000	N:0			0		27000
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050		MOS					25-JAN-2018		
		HRS/MSC	11000				0		11000
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
	HRS/MSC		A/R				581:29		
	REF: AMM 71-00-00	AFL					628		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
	HRS/MSC		1200	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES. REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION AND DO THE 100 HOUR AND MINOR INSPECTION ITEMS PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				24-JAN-2022 581:29 628		
71-00/209 (s)	ENGINE DRAIN MAST AND TANK - EXAMINE THE DRAIN MAST FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN THE COLLECTOR TANK PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS. PKG 15 ,16,17,18,19,20,21 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				24-JAN-2022 581:29 628		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. PKG 20 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		
71-00/327	ENGINE (POST SB 04-009) MOUNTING FRAME PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		25-JAN-2018 0 0	25000 30000	
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 10262 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		25-JAN-2018 0 0	3500 3850	
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 9448121409 10299 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		25-JAN-2018 0 0	3500 3850	



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
71.061	9448121409	MOS		N:0			25-JAN-2018		
OVERHAUL	10279	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	9448121409	MOS		N:0			25-JAN-2018		
OVERHAUL	10267	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	9448121409	MOS		N:0			25-JAN-2018		
OVERHAUL	10293	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
71.130		MOS					25-JAN-2018		
	REF: AMM 71-00-05	HRS/MSC	N/A				0		
		AFL					0		
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	A/R				581:29		
		AFL					628		
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	A/R				581:29		
		AFL					628		
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC	A/R				581:29		
		AFL					628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710055	(WELDED) ENGINE MOUNT								
71.120	5712012036 1519 REF: AMM 71-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P PCE-RY0832 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			27-SEP-2017 0 0	(3500) 3500	3700
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 2 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
710021	NO. 1 ENGINE - HOT SECTION INSPECTION CMT ITEM								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			27-SEP-2017 0 0	(1750) 1750	2000
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	600	+10%/-10%			24-JAN-2022 581:29 567	(1181:29) 1181:29	1241:29
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	4000	+100/-100			27-SEP-2017 0 0	(4000) 4000	4100



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	6 300	+10%/-10% +10%/-10%		2	24-JAN-2022 581:29 567	26-JUL-2022 (881:29) 881:29	13-AUG-2022 911:29
710051	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	6 300	+10%/-10% +10%/-10%		2	24-JAN-2022 581:29 567	26-JUL-2022 (881:29) 881:29	13-AUG-2022 911:29
710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				27-SEP-2017 0 0		
710053	NO. 1 ENGINE - EXTERNAL ENGINE WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	6 300	+10%/-10% +10%/-10%		2	24-JAN-2022 581:29 567	26-JUL-2022 (881:29) 881:29	13-AUG-2022 911:29
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM) REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567	(881:29) 881:29	911:29
710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION PKG 2 REF: EMM 71-00-00	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				27-SEP-2017 0 0		

CHAPTER 72 ENGINE

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720010	NO. 1 ENGINE - GAS GENERATOR MODULE								
	PN	MOS		N:0			27-SEP-2017		
	SN-UNKNOWN	HRS/MSC	3500	+200			0	(3500) 3500	3700
OVERHAUL	REF: See Workcard	ENC		N:0			0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL								
		MOS					26-JAN-2021		
		HRS/MSC	BF/F				210:53		
	REF: EMM 72-00-00	ENC					234		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP								
		MOS					26-JAN-2021		
		HRS/MSC	BF/F				210:53		
	REF: EMM 72-60-00	ENC					234		
720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT						PKG		
	PKG 2	MOS					24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	ENC					567		
720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION						PKG		
	PKG 2	MOS					24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	ENC					567		
720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES						PKG		
	PKG 2	MOS					24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	ENC					567		
720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE						PKG		
	PKG 2	MOS					24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: GENERIC NO REF	ENC					567		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES	MOS						27-SEP-2017	
	REF: EMM 72-00-00	HRS/MSC ENC	A/R					0 0	
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS						26-JAN-2021	
	REF: EMM 72-11-00	HRS/MSC ENC	BF/F					210:53 234	
722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS	MOS						PKG	
	PKG 2	HRS/MSC	300	+10%/-10%				24-JAN-2022	
	REF: See Workcard	ENC						581:29 567	
+ 722011	NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR	MOS						27-SEP-2017	
	3037719	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	ENC		N:0				0	
	REF: GENERIC NO REF			N:0					
722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION	MOS						PKG	
	PKG 2	HRS/MSC	300	+10%/-10%				24-JAN-2022	
	REF: EMM 72-20-00	ENC						581:29 567	
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR	MOS						27-SEP-2017	
	3042701	HRS/MSC		N:0				0	
	MCAKAXRR178	ENC		N:0				0	
	REF: GENERIC NO REF	ACCCYC	24000	N:0					
	LIFE LIMIT								
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT	MOS						27-SEP-2017	
	3043063	HRS/MSC		N:0				0	
	PKAAA729678	ENC		N:0				0	
	REF: GENERIC NO REF	ACCCYC	24000	N:0					
	LIFE LIMIT								



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION						PKG		
	PKG 2	MOS						24-JAN-2022	
		HRS/MSC	300	+10%/-10%				581:29	
	REF: EMM 72-30-04	ENC						567	
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR								
	3040942	MOS						27-SEP-2017	
	MCAKAXRR181	HRS/MSC						0	
LIFE LIMIT	REF: GENERIC NO REF	ENC						0	
		ACCCYC	24000						
723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						PKG		
	PKG 2	MOS						24-JAN-2022	
		HRS/MSC	300	+10%/-10%				581:29	
	REF: See Workcard	ENC						567	
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR								
	3040933	MOS						27-SEP-2017	
	MCAKAXRR206	HRS/MSC						0	
LIFE LIMIT	REF: GENERIC NO REF	ENC						0	
		ACCCYC	24000						
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR								
	3040944	MOS						27-SEP-2017	
	EAAE000F119	HRS/MSC						0	
LIFE LIMIT	REF: GENERIC NO REF	ENC						0	
		ACCCYC	24000						
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER								
	3036898	MOS						27-SEP-2017	
	CRAZAFAE031	HRS/MSC						0	
LIFE LIMIT	REF: GENERIC NO REF	ENC						0	
		ACCCYC	24000						



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS						27-SEP-2017	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC A/R					0		
		ENC					0		
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS						27-SEP-2017	
LIFE LIMIT	3053740-01	HRS/MSC		N:0			0		
	YUAB001J798	ENC		N:0			0		
	REF: GENERIC NO REF	ACCCYC 8000		N:0					
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS						27-SEP-2017	
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC 5000					0	(5000) 5000	
		ENC					0		
725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION	MOS						PKG	
	PKG 2	HRS/MSC 300	+10%/-10%					24-JAN-2022	
	REF: EMM 72-50-05	ENC					581:29		
							567		
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK	MOS						27-SEP-2017	
LIFE LIMIT	3037312	HRS/MSC		N:0			0		
	A00446WH	ENC		N:0			0		
	REF: GENERIC NO REF	ACCCYC 15000		N:0					
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK	MOS						27-SEP-2017	
LIFE LIMIT	3037313	HRS/MSC		N:0			0		
	YUAB001J574	ENC		N:0			0		
	REF: GENERIC NO REF	ACCCYC 15000		N:0					
725122	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE	MOS						27-SEP-2017	
	3056693-01	HRS/MSC H/T		N:0			0		
	SN-UNKNOWN	ENC		N:0			0		
	REF: GENERIC NO REF			N:0					



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 1 ENGINE - ACCESSORY GEARBOX 3059343-01 PKAAA724902 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-SEP-2017 0 0		
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200 N:0 N:0 N:0			27-SEP-2017 0 0	(3500) 3500	3700
OVERHAUL									
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP 3040760 015670 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	N:0 N:0 N:0			27-SEP-2017 0 0	(3500) 3500	
OVERHAUL									
731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: See Workcard	MOS HRS/MSC ENC	N/A				27-SEP-2017 0 0		
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) CMT ITEM REF: EMM 73-11-05	MOS HRS/MSC ENC	600	+10%/-10%			24-JAN-2022 581:29 567	(1181:29) 1181:29	1241:29
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51744 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500 N:0 N:0 N:0			27-SEP-2017 0 0	(3500) 3500	4000
OVERHAUL									
731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	1750	+10%/-10%			27-SEP-2017 0 0	(1750) 1750	1925
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN CMT ITEM 3040760 015670 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-JAN-2022 581:29 567	(1181:29) 1181:29	1241:29
731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 2 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-JAN-2022 581:29 567		
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 015670 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				27-SEP-2017 0 0		
731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				27-SEP-2017 0 0		
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER CMT ITEM 3059779-01 NSN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			03-NOV-2021 537:42 533	(1137:42) 1137:42	1197:42
REPLACE									



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2	MOS					PKG	24-JAN-2022	
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			581:29 567		
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA56154	MOS					27-SEP-2017		
	REF: EMM 73-10-01	HRS/MSC ENC	3500	+500	N:0 N:0 N:0		0 0 0	(3500) 3500	4000
731065	NO. 1 ENGINE - EXAMINE FILTER BOWL	MOS					24-JAN-2022		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%			581:29 567	(881:29) 881:29	911:29
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0849	MOS					27-SEP-2017		
	REF: EMM 73-10-04	HRS/MSC ENC	3500	+500	N:0 N:0 N:0		0 0 0	(3500) 3500	4000
731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 2	MOS					PKG	24-JAN-2022	
	REF: EMM 73-10-06	HRS/MSC ENC	300	+10%/-10%			581:29 567		
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-10 21019892	MOS					27-SEP-2017		
OVERHAUL	REF: EMM 73-20-00	HRS/MSC ENC	3500	+500	N:0 N:0 N:0		0 0 0	(3500) 3500	4000
731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2	MOS					PKG	24-JAN-2022	
	REF: EMM 73-10-04	HRS/MSC ENC	300	+10%/-10%			581:29 567		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A	N:0 N:0 N:0			27-SEP-2017 0 0		
731100	NO. 1 ENGINE - CLEAN P3 FILTER CMT ITEM REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567	(881:29) 881:29	911:29
731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 3059779-01 NSN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T	N:0 N:0 N:0			03-NOV-2021 537:42 533		
732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
733020	NO. 1 ENGINE - REPLACE P3 FILTER CMT ITEM REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			27-SEP-2017 0 0	(900) 900	990
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567	(881:29) 881:29	911:29

CHAPTER 74 IGNITION



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM CMT ITEM PKG 17	MOS	12	+10%/-10%			PKG	24-JAN-2022	
	REF: AMM 74-00-00	HRS/MSC AFL	300	+10%/-10%			581:29 628		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01

740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA17340130 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-SEP-2017 0 0	(3500) 3500	4000
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%		29:24	24-JAN-2022 581:29 567	(1010:53) 1010:53	1050:53
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION CMT ITEM REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%		29:24	24-JAN-2022 581:29 567	(1010:53) 1010:53	1050:53
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%		29:24	24-JAN-2022 581:29 567	(1010:53) 1010:53	1050:53

CHAPTER 75 AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX1001234 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-SEP-2017 0 0	(3500) 3500	4000
--------	--	-----------------------	------	------	-------------------	--	-----------------------	-------------	------

CHAPTER 76 ENGINE CONTROLS



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. CMT ITEM PKG 16 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 24-JAN-2022 581:29 628		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE CMT ITEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-JAN-2022 581:29 628		
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES CMT ITEM	MOS HRS/MSC AFL	12 3000	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628	15-JAN-2023 3581:29	20-FEB-2023 3881:29
76.010	REF: AMM 76-10-02								
760015	MANUAL OVERRIDE CABLE ASSY. 9419411417 00122 REF: AMM 76-20-00	MOS HRS/MSC AFL	O/C				25-JAN-2018 0 0		
76.020									



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760020	CONDITION CABLE ASSY.								
76.030	9419411418 00171 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419 00157 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES								
		MOS HRS/MSC ENC	12 300	+30d/-10% +10%/-10%			24-JAN-2022 581:29 567	24-JAN-2023 (881:29) 881:29	23-FEB-2023 911:29
	REF: EMM 72-00-00								

CHAPTER 77 ENGINE INDICATING									
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	9752115206 8032-2-549 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
770025	DIFFERENTIAL PRESSURE TRANSDUCER								
	9752115219 10692836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01									
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NRA102284 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-SEP-2017 0 0		

CHAPTER 78 EXHAUST									
78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-JAN-2022 581:29 628		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 79	OIL								
79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK						PKG		
	CMT ITEM								
	PKG 19	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	600	+10%/-10%			581:29		
	REF: AMM 79-30-06	AFL					628		
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	1200	+10%/-10%			581:29		
	REF: GENERIC NO REF	AFL					628		
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						PKG		
	CMT ITEM								
	PKG 17	MOS	12	+10%/-10%			24-JAN-2022		
		HRS/MSC	300	+10%/-10%			581:29		
	REF: AMM 79-30-01	AFL					628		
79-20/43	OIL COOLER								
	9683214102	MOS			N:0		25-JAN-2018		
79.010	T1792	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
OVERHAUL	REF: AMM 79-20-02	AFL			N:0		0		
790005	TEMPERATURE BULB								
	9751120101	MOS			N:0		25-JAN-2018		
79.020	234779	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
790020	PRESSURE,GAGE SWITCH								
	9738114305	MOS			N:0		25-JAN-2018		
79.030	1700	HRS/MSC	O/C		N:0		0		
	REF: AMM 79-30-04	AFL			N:0		0		
790025	THERMAL ACTUATOR								
	9787301002	MOS			N:0		25-JAN-2018		
79.040	2003	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0832 Part # 3072955-01



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					27-SEP-2017		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	A/R				0 0		
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			24-JAN-2022	24-JAN-2023	23-FEB-2023
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			581:29 567	(881:29) 881:29	911:29
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR CMT ITEM	MOS	12	+1m/-1m		-9	24-JAN-2022	15-JAN-2023	15-FEB-2023
	REF: EMM 79-20-02	HRS/MSC ENC	600	+10%/-10%			581:29 567	(1181:29) 1181:29	1241:29
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT CMT ITEM	MOS					27-SEP-2017		
	REF: EMM 79-20-02	HRS/MSC ENC	900	+10%/-10%			0 0	(900) 900	990
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN CMT ITEM	MOS					24-JAN-2022		
	REF: EMM 79-20-02	HRS/MSC ENC	300	+10%/-10%			581:29 567	(881:29) 881:29	911:29
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					27-SEP-2017		
	REF: EMM 72-60-00	HRS/MSC ENC	1000	+10%/-10%			0 0	(1000) 1000	1100
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					15-JAN-2020		
	REF: EMM 79-20-02	HRS/MSC ENC	N/A				6 7		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 2	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			24-JAN-2022 581:29 567		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 9752115214	MOS						27-SEP-2017	
	8359-3-758	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
CHAPTER 91 -									
240120	BATTERY EXT POWER JUNCTION BOX 9740338152	MOS						25-JAN-2018	
90.005	1054	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910010	LEFT HD POWER JCT BOX 9740338144	MOS						25-JAN-2018	
	1046	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910015	KBT 300 TTP BUS RES, A-157 TERMINAL 9859912117	MOS						25-JAN-2018	
90.015	KBT300-4457	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL 9859912117	MOS						25-JAN-2018	
90.025	KBT300-4487	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1767 (OH-DNG): 658:06 HRS, 686 AFL as of 10-Apr-2022

Owner: HI FIVE FLY SASU Operator: FLY 7 FINLAND OY

Report Date: 11-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910025	KBT 300 TTP BUS RES, A-174 TERMINAL								
90.020	9859912117 KBT300-4491 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
910035	CO-PILOT RIGHT HD POWER,FE1549R JUNCTION BOX								
90.030	9740338145 931 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
90.010	9859912117 KBT300-4446 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JAN-2018 0 0		