



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
00-ARC-RENEW	EXTEND/RENEW AIRWORTHINESS REVIEW CERTIFICATE	ELLX	MTH	25-Oct-2019 HRS 2772:45 LDG 2496		12		25-Oct-2020	4 m 1 d
00-RVSM-RENEW	CHECK MONITORING RESULTS		MTH	17-Jun-2019		24		17-Jun-2021	11 m 24 d
CJ02-141126	REVIEW CHAPTER 5 MM REVISION 16, DATED SEP 1/2014 - CAMP CHANGE FORM		MTH	15-Dec-2014		-			
CJ02-151209	REVIEW 525A CHAPTER 5 MAINTENANCE MANUAL REVISION 17		MTH			-			
CJ02-160901	REVIEW MODEL 525A CITATION CJ02 TIME LIMITS MAINTENANCE CHECKS (CH 5) REV. 18, DATED 01 SEPTEMBER 2016		MTH			-			
CJ02-170221	REVIEW CITATION CJ02 (525A) AIRWORTHINESS LIMITATIONS (CH 4) REV. 10, DATED 21 FEBRUARY 2017		MTH			-			
CJ02-170301	REVIEW MODEL 525A CITATION CJ02 TIME LIMITS MAINTENANCE CHECKS (CH 5) REV. 19, DATED 01 MARCH 2017					-			
CJ02-171003	REVIEW AUDIT SUMMARY CHANGE FORM					-			
E064-141208 E1	REVIEW FJ44-2C LMM REV.30 DATED SEP 2/14 - CAMP CHANGE FORM		MTH	22-Dec-2014		-			
E064-141208 E2	REVIEW FJ44-2C LMM REV.30 DATED SEP 2/14 - CAMP CHANGE FORM		MTH	22-Dec-2014		-			
E064-150204 E1	REVIEW WILLIAMS INTERNATIONAL, SERVICE BULLETIN FJ44-79-015, DATED FEB. 24/2015 - CAMP CHANGE FORM		MTH			-			
E064-150204 E2	REVIEW WILLIAMS INTERNATIONAL, SERVICE BULLETIN FJ44-79-015, DATED FEB. 24/2015 - CAMP CHANGE FORM		MTH			-			
E064-150206 E1	REVIEW CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL REVISION NO.31 DATED DEC 18/2014		MTH			-			
E064-150206 E2	REVIEW CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL REVISION NO.31 DATED DEC 18/2014		MTH			-			
E064-150501 E1	REVIEW CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL REVISION NO. 32, DATED APR 13/2015		MTH			-			
E064-150501 E2	REVIEW CAMP CHANGE FORM - WILLIAMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL REVISION NO. 32, DATED APR 13/2015		MTH			-			
E064-151014 E1	REVIEW CAMP INFORMATION LETTER (WILLIAMS CODE CONVERSION)		MTH			-			
E064-151014 E2	REVIEW CAMP INFORMATION LETTER (WILLIAMS CODE CONVERSION)		MTH			-			
E064-160107 E1	REVIEW FJ44-2C LMM, REVISION NO. 34, DATED DEC 11/15 - CAMP CHANGE FORM		MTH			-			
E064-160107 E2	REVIEW FJ44-2C LMM, REVISION NO. 34, DATED DEC 11/15 - CAMP CHANGE FORM		MTH			-			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
E064-160412 E1	REVIEW LMM REVISION NO. 33 - CAMP CHANGE FORM			MTH		-			
E064-160412 E2	REVIEW LMM REVISION NO. 33 - CAMP CHANGE FORM			MTH		-			
E064-160425 E1	REVIEW WILLAIMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL (PN 64135) REVISION NO. 35, DATED MAR 18/16 - CAMP CHANGE FORM			MTH		-			
E064-160425 E2	REVIEW WILLAIMS INTERNATIONAL, FJ44-2C LINE MAINTENANCE MANUAL (PN 64135) REVISION NO. 35, DATED MAR 18/16 - CAMP CHANGE FORM			MTH		-			
E064-160920 E1	REVIEW FJ44-2C LM REV 37			MTH		-			
E064-160920 E2	REVIEW FJ44-2C LM REV 37			MTH		-			
E064-161216 E1	REVIEW FJ44-2C LMM REV 38			MTH		-			
E064-161216 E2	REVIEW FJ44-2C LMM REV 38			MTH		-			
E064-170316 E1	REVIEW WILLIAMS INTERNATIONAL FJ44-2C LMM REV 39			MTH		-			
E064-170316 E2	REVIEW WILLIAMS INTERNATIONAL FJ44-2C LMM REV 39			MTH		-			
E064-170621 E1	REVIEW FJ44-2C LMM REV 40			MTH	12-Jun-2002	-			
E064-170621 E2	REVIEW FJ44-2C LMM REV 40			MTH	12-Jun-2002	-			
E064-170922 E1	REVIEW FJ44-2C LMM REV 41			MTH		-			
E064-170922 E2	REVIEW FJ44-2C LMM REV 41			MTH		-			
E064-171212 E1	REVIEW FJ44-2C LMM REV 42			MTH		-			
E064-171212 E2	REVIEW FJ44-2C LMM REV 42			MTH		-			
E064-180322 E1	REVIEW FJ44-2C LMM REV 43			MTH		-			
E064-180322 E2	REVIEW FJ44-2C LMM REV 43			MTH		-			
E064-180621 E1	REVIEW FJ44-2C LMM REV 44			MTH		-			
E064-180621 E2	REVIEW FJ44-2C LMM REV 44			MTH		-			
E064-180921 E1	REVIEW FJ44-2C LMM REV 45			MTH		-			
E064-180921 E2	REVIEW FJ44-2C LMM REV 45			MTH		-			
E064-181213 E1	REVIEW FJ44-2C LMM REV 46			MTH		-			
E064-181213 E2	REVIEW FJ44-2C LMM REV 46			MTH		-			
E064-190312 E1	REVIEW FJ44-2C LMM REV 47			MTH		-			
E064-190312 E2	REVIEW FJ44-2C LMM REV 47			MTH		-			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
E064-190618 E1	REVIEW FJ44-2C LMM REV 48			MTH		-			
E064-190618 E2	REVIEW FJ44-2C LMM REV 48			MTH		-			
E064-190923 E1	REVIEW FJ44-2C LMM REV 49			MTH		-			
E064-190923 E2	REVIEW FJ44-2C LMM REV 49			MTH		-			
E064-191217 E1	REVIEW FJ44-2C LMM REV 50			MTH		-			
E064-191217 E2	REVIEW FJ44-2C LMM REV 50			MTH		-			
E064-200319 E1	REVIEW FJ44-2C LMM REV 51 LFOQ			MTH HRS LDG	12-May-2020 2798:30 2519	-			
E064-200319 E2	REVIEW FJ44-2C LMM REV 51 LFOQ			MTH HRS LDG	12-May-2020 2798:30 2519	-			
5-12-01 0512001	INSPECTION DOCUMENT 1 (INTERVAL 1A) LFOQ			MTH HRS LDG	07-Mar-2019 2724:05 2452		300	3024:05	225:35
5-12-02 0512002	INSPECTION DOCUMENT 2 (INTERVAL 1C) LFOQ			MTH HRS LDG	06-May-2020 2798:30 2519		12	06-May-2021	10 m 12 d
5-12-04	INSPECTION DOCUMENT 4 (INTERVAL 3C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	10-Sep-2018 2691:50 2422		36		
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE : INSPECTION DOCUMENT 4 (INTERVAL 3C) LFOQ		40005320-2 3455	MTH	01-Jul-2018		36	01-Jul-2021	12 m 7 d
5-12-05	INSPECTION DOCUMENT 5 (INTERVAL 5C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	01-Apr-2016 2442:45 2179		60		
B262002 LEFT ENGINE 0512005 : L	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C) LFOQ		30401102-2 61552B1	MTH	31-Dec-2019		60	31-Dec-2024	54 m 7 d
B262002 RIGHT ENGINE 0512005 : R	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C) LFOQ		30401102-2 56117B1	MTH	31-Dec-2019		60	31-Dec-2024	54 m 7 d
5-12-06	INSPECTION DOCUMENT 6 (INTERVAL 6C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	10-Sep-2018 2691:50 2422		72		
A262201 CABIN 0512006 : CABIN	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 6 (INTERVAL 6C) LFOQ		C352TS E-92813308	MTH	04-Sep-2018		72	04-Sep-2024	50 m 11 d
A262201 COCKPIT 0512006	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 6 (INTERVAL 6C) LFOQ		C352TS E-92813309	MTH	04-Sep-2018		72	04-Sep-2024	50 m 11 d
5-12-07	INSPECTION DOCUMENT 7 (INTERVAL 12C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH	12-Jun-2002		144		
B262202 CABIN 0512007 : CABIN	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 7 (INTERVAL 12C) LFOQ		C352TS E-92813308	MTH	04-Sep-2018		144	04-Sep-2030	122 m 11 d



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262202 COCKPIT 0512007	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 7 (INTERVAL 12C)	LFOQ	C352TS E-92813309	MTH 04-Sep-2018		144		04-Sep-2030	122 m 11 d
5-12-08 0512008	INSPECTION DOCUMENT 8 (INTERVAL 1A/2C)	LFOQ		MTH 07-Mar-2019 HRS 2724:05 LDG 2452		24 300		07-Mar-2021 3024:05	8 m 11 d 225:35
5-12-10 0512010	INSPECTION DOCUMENT 10 (INTERVAL 4A/3C)	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		36 1200		06-May-2023 3998:30	34 m 12 d 1200
5-12-11 0512011	INSPECTION DOCUMENT 11 (INTERVAL 8A/6C)	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		36 1200		06-May-2023 3998:30	34 m 12 d 1200
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12		06-May-2021	10 m 12 d
5-12-13	INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	LFOQ		MTH 07-Mar-2019 HRS 2724:05 LDG 2452		24		07-Mar-2021	8 m 11 d
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 12-Jun-2002		A/R			
A324103 LEFT MAIN GEAR 0512014C : L	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14		3-1601-3 1185	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		T/C			
A324103 NOSE LANDING GEAR 0512014C : NOSE	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14		3-1418 4421	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		T/C			
A324103 RIGHT MAIN GEAR 0512014C : R	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14		3-1601-2 0225	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		T/C			
5-12-17	INSPECTION DOCUMENT 17 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12 100		06-May-2021 2898:30	10 m 12 d 100
5-12-18 0512018	INSPECTION DOCUMENT 18	LFOQ		MTH 04-Oct-2019 HRS 2772:45 LDG 2496		150		2922:45	124:15
5-12-19	INSPECTION DOCUMENT 19			MTH 12-Jun-2002 HRS 0		5000		5000	2201:30
5-12-21 0512021	INSPECTION DOCUMENT 21 (INTERVAL 2A/2C)	LFOQ		MTH 04-Oct-2019 HRS 2772:45 LDG 2496		24 600		04-Oct-2021 3372:45	15 m 10 d 574:15
5-12-22 0512022	INSPECTION DOCUMENT 22 (NOT CURRENTLY USED)	*CF		MTH 12-Jun-2002		N/R			
5-12-23 0512023	INSPECTION DOCUMENT 23 (NOT CURRENTLY USED)	*CF		MTH 12-Jun-2002		N/R			
5-12-24 0512024	INSPECTION DOCUMENT 24 (INTERVAL 1A/1C)	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12 300		06-May-2021 3098:30	10 m 12 d 300



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-25	INSPECTION DOCUMENT 25		MTH	12-Jun-2002					
			HRS	0		4000		4000	1201:30
5-12-26	INSPECTION DOCUMENT 26 LFOQ		MTH	06-May-2020		6		06-Nov-2020	4 m 13 d
			HRS	2798:30					
			LDG	2519					
5-12-MA 05120MA	INSPECTION DOCUMENT MA (CHAPTER 4) LFOQ		MTH	07-Mar-2019					
			HRS	2724:05		300		3024:05	225:35
			LDG	2452					
5-12-MC 05120MC	INSPECTION DOCUMENT MC (CHAPTER 4)		MTH	23-Jun-2015					
			HRS	2381:15		1200		3581:15	782:45
			LDG	2116					
5-12-MD 05120MD	INSPECTION DOCUMENT MD (CHAPTER 4) LFOQ		MTH	04-Oct-2019					
			HRS	2772:45		1425		4197:45	1399:15
			LDG	2496					
5-12-ME 05120ME	INSPECTION DOCUMENT ME (CHAPTER 4) *CF		MTH	12-Jun-2002					
			LDG	0		5000		5000	2481
5-12-MF 05120MF	INSPECTION DOCUMENT MF (CHAPTER 4)		MTH	01-Apr-2016					
			HRS	2442:45		2550		4992:45	2194:15
			LDG	2179					
5-12-MG 05120MG	INSPECTION DOCUMENT MG (CHAPTER 4) LFOQ		MTH	04-Oct-2019					
			HRS	2772:45		2800		5572:45	2774:15
			LDG	2496					
5-12-MH 05120MH	INSPECTION DOCUMENT MH (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		3100		3100	301:30
5-12-MI 05120MI	INSPECTION DOCUMENT MI (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		4950		4950	2151:30
5-12-MJ 05120MJ	INSPECTION DOCUMENT MJ (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		5000		5000	2201:30
5-12-MK 05120MK	INSPECTION DOCUMENT MK (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		5050		5050	2251:30
5-12-ML 05120ML	INSPECTION DOCUMENT ML (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		5050		5050	2251:30
5-12-MM 05120MM	INSPECTION DOCUMENT MM (CHAPTER 4) *CF		MTH	12-Jun-2002					
			HRS	0		6000		6000	3201:30
5-12-MP	INSPECTION DOCUMENT MP (CHAPTER 4)		MTH	12-Jun-2002					
			HRS	0		8628		8628	5829:30
052001 E1	FJ44 CHECK 1	LFOQ	MTH	06-May-2020					
			HRS	2798:30		300		(3098:30)3098:30	300
			LDG	2519					
052001 E2	FJ44 CHECK 1	LFOQ	MTH	06-May-2020					
			HRS	2798:30		300		(2992)3098:30	300
			LDG	2519					
052002 E1	FJ44 CHECK 2	LFOQ	MTH	06-May-2020					
			HRS	2798:30		600		(3398:30)3398:30	600
			LDG	2519					
052002 E2	FJ44 CHECK 2	LFOQ	MTH	06-May-2020					
			HRS	2798:30		600		(3292)3398:30	600
			LDG	2519					
052003 E1	FJ44 CHECK 3	EDDW	MTH	19-Feb-2013					
			HRS	1997:18		2500		(4497:18)4497:18	1698:48
			LDG	1843					



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052003 E2	FJ44 CHECK 3		MTH HRS LDG	11-Mar-2013 2104:30 1892		2500		(4498)4604:30	1806
052004 E1	FJ44 CHECK 4		MTH HRS	12-Jun-2002 0		5000		(5000)5000	2201:30
052004 E2	FJ44 CHECK 4		MTH HRS	12-Jun-2002 106:30		5000		(5000)5106:30	2308
052005 E1	FJ44 CHECK 5		MTH HRS	12-Jun-2002 0		2500		(7500)7500	4701:30
052005 E2	FJ44 CHECK 5		MTH HRS	12-Jun-2002 106:30		2500		(7500)7606:30	4808
052006 E1	FJ44 CHECK 6		MTH HRS	12-Jun-2002 0		5000		(10000)10000	7201:30
052006 E2	FJ44 CHECK 6		MTH HRS	12-Jun-2002 106:30		5000		(10000)10106:30	7308
052007 E1	FJ44 CHECK 7		MTH HRS	12-Jun-2002 0		2500		(12500)12500	9701:30
052007 E2	FJ44 CHECK 7		MTH HRS	12-Jun-2002 106:30		2500		(12500)12606:30	9808
052008 E1	FJ44 CHECK 8		MTH HRS	12-Jun-2002 0		5000		(15000)15000	12201:30
052008 E2	FJ44 CHECK 8		MTH HRS	12-Jun-2002 106:30		5000		(15000)15106:30	12308
052009 E1	FJ44 CHECK 9		MTH HRS	12-Jun-2002 0		2500		(17500)17500	14701:30
052009 E2	FJ44 CHECK 9		MTH HRS	12-Jun-2002 106:30		2500		(17500)17606:30	14808
052010 E1	FJ44 CHECK 10		MTH HRS	12-Jun-2002 0		5000		(20000)20000	17201:30
052010 E2	FJ44 CHECK 10		MTH HRS	12-Jun-2002 106:30		5000		(20000)20106:30	17308
E082100	REWEIGH AIRCRAFT	LFOQ	MTH HRS LDG	01-Oct-2015 2404:30 2140		60		01-Oct-2020	3 m 7 d
21-00-08-21-001	COMPRESSOR DRIVE MODULE AND CONDENSER BLOWER INSPECTION		MTH HRS LDG ACH	29-Nov-2012 1953:54 1814 509		500		1009	197:36
21-00-08-21-002	FORWARD AND AFT EVAPORATOR MODULE INSPECTION AND CONDENSER MODULE INSPECTION	LFOQ	MTH HRS LDG	06-May-2020 2798:30 2519		12		06-May-2021	10 m 12 d
A21500F	INSPECT FORWARD EVAPORATOR BLOWER MOTOR BRUSHES		ACH	0		1000		1000	188:36
A215010	CHECK AIR CONDITIONNER HOURMETER HOURS		MTH HRS LDG	20-Apr-2017 2548:40 2280		300		2848:40	50:10
233401	RADIO NAVIGATION AND RADIO COMMUNICATION RADIATION GLOBAL TEST ON GROUND	LFOQ	MTH HRS LDG	07-Mar-2019 2724:05 2452		24		07-Mar-2021	8 m 11 d
349001	INSPECT LPV CONVERTER ASSOCIATED SWITCHES WIRING HARNESS CIRCUIT BREAKER(S) ASR-2014-032-ICA-11	LFOQ	MTH HRS LDG	06-May-2020 2798:30 2519		12		06-May-2021	10 m 12 d



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
349002	PERFORM ADS-B OUT TEST IAW SMM 190-00734-11 CHAPTER 8.4.3 ANYTIME GPS POSITION SOUREC IS REPLACED								
						A/R			
349003	INSPECTION VISUAL INSPECT GTX330D MOUNT RACK IAW ICA 190-00734-11 CHAPTER 4.5	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12		06-May-2021	10 m 12 d
349004	VISUAL INSPECT GTX 330D XPDRS ANTENNAS IAW ICA 190-00734-11 CHAPTER 4.5	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12		06-May-2021	10 m 12 d
349005	GTX 330D ELECTRICAL BONDING TEST IAW ICA 190-00734-11 CHAPTER 4.6			MTH 07-Mar-2019 HRS 2724:05 LDG 2452		120 2000		07-Mar-2029 4724:05	104 m 11 d 1925:35
D345049	REPLACE FMS UNIT INTERNAL BATTERY	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		36		06-May-2023	34 m 12 d
351005 <i>0512004 : OXY</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER (DOT3HT1850 OR DOT3FC1850 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-8162)- OXYGEN BOTTLE AND REGULATOR ASSEMBLY	LFOQ	176274-22 869765701	MTH 22-Jun-2018		60		22-Jun-2023	35 m 29 d
351006 PORTABLE	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE (DOT3AA)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY		PN SN-UNKNOWN			N/R			
351007	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER OXYGEN BOTTLE (PART NUMBER 4444018-50 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-10945 OR SP10945)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY		176274-22 869765701	MTH		N/R			
510001	VISUAL INSPECT GA 35 ANTENNAS FOOT AND SEALER FROM AIRPLANE OUTSIDE	LFOQ		MTH 06-May-2020 HRS 2798:30 LDG 2519		12		06-May-2021	10 m 12 d
542085 047103	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH 12-Jun-2002 HRS 0	12		15000	15012	12213:30
542090 047103	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH 12-Jun-2002 HRS 0	12		15000	15012	12213:30
542095 047104	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH 12-Jun-2002 HRS 0	12		12000	12012	9213:30
542100 047104	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH 12-Jun-2002 HRS 0	12		12000	12012	9213:30
542105 047107	INSPECT LEFT ENGINE AFT ENGINE MOUNT	*CF		MTH 12-Jun-2002 HRS 0	12		15000	15012	12213:30
542110 047107	INSPECT RIGHT ENGINE AFT ENGINE MOUNT	*CF		MTH 12-Jun-2002 HRS 0	12		15000	15012	12213:30
544005 047101	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90	*CF		MTH 12-Jun-2002 HRS 0			8628	8628	5829:30
544010 047101	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90	*CF		MTH 12-Jun-2002 HRS 0			8628	8628	5829:30
544015 047102	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56	*CF		MTH 12-Jun-2002 HRS 0	12		15000	15012	12213:30

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
544020 047102	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
544035 047105	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
544040 047105	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
544045 047106	INSPECT LEFT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
544050 047106	INSPECT RIGHT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
551010 045501	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,MAIN SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1	*CF	MTH 12-Jun-2002	HRS 0	12	15000		15012	12213:30
551020 045502	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,REAR SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1	*CF	MTH 12-Jun-2002	HRS 0		11250		11250	8451:30
A55CP01	RUDDER COVE AREA GENERAL VISUAL INSPECTION (CORROSION INSPECTION)	LFOQ	MTH 06-May-2020	HRS 2798:30 LDG 2519		6		06-Nov-2020	4 m 13 d
A55CP02	ELEVATOR COVE AREA GENERAL VISUAL INSPECTION (CORROSION INSPECTION)	LFOQ	MTH 06-May-2020	HRS 2798:30 LDG 2519		6		06-Nov-2020	4 m 13 d
A57CP02	FLAP COVE AREA GENERAL VISUAL INSPECTION (CORROSION INSPECTION)	LFOQ	MTH 06-May-2020	HRS 2798:30 LDG 2519		6		06-Nov-2020	4 m 13 d
571010 045701	INSPECT LEFT WING FRONT SPAR , WS 88.50	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571015 045701	INSPECT RIGHT WING FRONT SPAR, WS 88.50	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571020 045702	INSPECT LEFT WING MAIN SPAR, WS 61.50	*CF	MTH 12-Jun-2002	HRS 0		12500		12500	9701:30
571025 045702	INSPECT RIGHT WING MAIN SPAR, WS 61.50	*CF	MTH 12-Jun-2002	HRS 0		12500		12500	9701:30
571030 045703	INSPECT LEFT WING MAIN SPAR, WS 102.00	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571035 045703	INSPECT RIGHT WING MAIN SPAR, WS 102.00	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571040 045704	INSPECT LEFT WING MAIN SPAR, WS 154.00	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571045 045704	INSPECT RIGHT WING MAIN SPAR, WS 154.00	*CF	MTH 12-Jun-2002	HRS 0		12000		12000	9201:30
571050 045705	INSPECT LEFT WING MAIN SPAR, WS 171.00 (INBOARD)	*CF	MTH 12-Jun-2002	HRS 0		13000		13000	10201:30



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
571055 045705	INSPECT RIGHT WING MAIN SPAR, WS 171.00 (INBOARD)	*CF	MTH	12-Jun-2002					
			HRS	0		13000		13000	10201:30
571060 045706	INSPECT LEFT WING REAR SPAR, WS 136.65	*CF	MTH	12-Jun-2002					
			HRS	0		13000		13000	10201:30
571065 045706	INSPECT RIGHT WING REAR SPAR, WS 136.65	*CF	MTH	12-Jun-2002					
			HRS	0		13000		13000	10201:30
571070 045707	INSPECT LEFT WING REAR SPAR, WS 154.00	*CF	MTH	12-Jun-2002					
			HRS	0		13000		13000	10201:30
571075 045707	INSPECT RIGHT WING REAR SPAR, WS 154.00	*CF	MTH	12-Jun-2002					
			HRS	0		13000		13000	10201:30
571080 045708	INSPECT LEFT WING MAIN SPAR SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
571085 045708	INSPECT RIGHT WING MAIN SPAR SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
571090 045709	INSPECT LEFT WING REAR SPAR SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
571095 045709	INSPECT RIGHT WING REAR SPAR SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
571100 045710	INSPECT LEFT WING FRONT STRINGER SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
571105 045710	INSPECT RIGHT WING FRONT STRINGER SPLICE, WS 111.00	*CF	MTH	12-Jun-2002					
			HRS	0		12000		12000	9201:30
A57CP01	SPEED BRAKE COVE AREA GENERAL VISUAL INSPECTION (CORROSION INSPECTION)	LFOQ	MTH	06-May-2020					
			HRS	2798:30		6		06-Nov-2020	4 m 13 d
			LDG	2519					



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211001 LEFT	PRESSURE SHUTOFF VALVE	EGCN		5253-00-3 1799A	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		O/C	2 0 0		
211001 RIGHT	PRESSURE SHUTOFF VALVE	SZR		5253-00-1 2648	MTH 13-Aug-2009 HRS 1376		O/C	0		
211002 LEFT	VARIABLE VALVE	EGCN		2601-21EX 1099	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		O/C	2 0 0		
211002 RIGHT	VARIABLE VALVE	SZR		2601-21 0807	MTH 13-Aug-2009 HRS 1376		O/C	0		
211003	PRESSURE HEAT EXCHANGER	EGCN		10840A 1220	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		O/C	0 0 0		
211005	EMERGENCY PRESSURE SHUTOFF VALVE	SZR		9912422-2 2601-23 1063	MTH 05-Feb-2009 HRS 1262		O/C	0		
212001	BAGGAGE COMPARTMENT BLOWER	*CF	A	0113-12 0634	MTH 12-Jun-2002		O/C			
212003	(STO29) TEMPERATURE SWITCH	*CF		1173T42-1 3167	MTH 12-Jun-2002		O/C			
212302	WINDSHIELD AIR BLOWER MOTOR			7003-200 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
213001	PRIMARY OUTFLOW VALVE	EGCN		9912409-20 899	MTH 20-Jul-2011 HRS 1702 LDG 1645		O/C	3		
213002	SECONDARY OUTFLOW VALVE	*CF	A	52772-116 819	MTH 12-Jun-2002		O/C			
213003	PRESSURE CONTROLLER	EGCN	E	52770-116 1651	MTH 20-Jul-2011 HRS 1702 LDG 1645		O/C	1		
213005	DIFFERENTIAL PRESSURE INDICATOR	*CF		C668511-0106 3001J73 22133	MTH 12-Jun-2002		O/C			
213008	MANUAL PRESSURE SWITCH	*CF	A	52773-001 9912409-4 1250	MTH 12-Jun-2002		O/C			
215000 AFT	EVAPORATOR BLOWER MOTOR	SZR		1133210-7 1160	MTH 13-Aug-2009		O/C			
215000 FORWARD	EVAPORATOR BLOWER MOTOR	*CF		1260185-1 NSN	MTH 12-Jun-2002		O/C			
215001	FORWARD EVAPORATOR	*CF		1134300-3 9912583-9 208	MTH 12-Jun-2002		O/C			
215002	AFT EVAPORATOR	SZR		1134820-15 9912583-10 897	MTH 13-Aug-2009 ACH 452		O/C	0		
215003	VAPOR CYCLE COMPRESSOR DRIVE MOTOR			1134146-1 975A	MTH 20-Apr-2017 ACH 754:04		3000	57	3697:04	2885:40
215004	COMPRESSOR DRIVE	*CF		1134610-1 9912583-6 203	MTH 12-Jun-2002		O/C			
215005	CONDENSOR ASSEMBLY	*CF		1134620-3 9912583-7 196	MTH 12-Jun-2002		O/C			
215006	BINARY SWITCH	*CF		1250232-10 SN-UNKNOWN	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215007	RECEIVER DRYER ASSEMBLY 9912583-3	*CF		1134275-1 SN-UNKNOWN	MTH 12-Jun-2002		A/R			
215008	COMPRESSOR ASSEMBLY	*CF		1134130-5 146	MTH 12-Jun-2002		O/C			
215009	VANE AXIAL BLOWER ASSY HUR			1250435-5 2363	MTH 22-Nov-2005 ACH 154		O/C	0		
215010	AIR CONDITIONING FLIGHT HOURMETER			PN SN-UNKNOWN	MTH 20-Apr-2017 HRS 2548:40 LDG 2280		O/C	0 0 0		
215011	COMPRESSOR DRIVE BELT *CF			225L100 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
215012	VAPOR CYCLE COMPRESSOR DRIVE MOTOR BRUSHES EGKB			1251171 SN-UNKNOWN	MTH 29-Nov-2012 HRS 1953:54 LDG 1814 ACH 509			0 0 0 0	1309	497:36
216001	RAM AIR MODULATING VALVE ICT			27241287-24 11BA93	MTH 07-Aug-2014 HRS 2293:06 LDG 2032		O/C			
216002	TEMPERATURE CONTROLLER *CF			1E58-7 1AV5	MTH 12-Jun-2002		O/C			
216003 AFT	(TC007) SENSOR 9912085-3	*CF		27221274 12AU647	MTH 12-Jun-2002		O/C			
216003 FORWARD	(UT006) SENSOR 9912085-3	*CF		27221274 1AV59	MTH 12-Jun-2002		O/C			
221002 AILERON	SERVO MOUNT *CF		1	622-5735-021 J6GN	MTH 12-Jun-2002		O/C			
221002 ELEVATOR	SERVO MOUNT *CF		1	622-5735-022 J6FP	MTH 12-Jun-2002		O/C			
221002 RUDDER	SERVO MOUNT *CF		1	622-5735-022 J77W	MTH 12-Jun-2002		O/C			
221003 AILERON	SERVO SVO-3000	*CF		822-1168-002 YY2Y	MTH 12-Jun-2002		O/C			
221003 ELEVATOR	SERVO SVO-3000	*CF		822-1168-001 JC8F	MTH 12-Jun-2002		O/C			
221003 RUDDER	SERVO SVO-3000	*CF		822-1168-001 J72G	MTH 12-Jun-2002		O/C			
221004	AUTOPILOT PANEL APP-85	*CF	8	622-6208-227 HP5T	MTH 12-Jun-2002		O/C			
231007 BOTTOM	COMM 2 ANTENNA *CF			17-40-02W 0501	MTH 12-Jun-2002		O/C			
231007 TOP	COMM 1 ANTENNA			18-50-01 1213	MTH 12-Dec-2014 HRS 2314:30 LDG 2046		O/C	0 0 0		
235001 LEFT	AUDIO AMPLIFIER S3100-64	EGGW	C	5646-1 126	MTH 08-Dec-2010 HRS 1591:24 LDG 1578		O/C			
235001 RIGHT	AUDIO AMPLIFIER S3100-64	*CF	C	5646-1 583	MTH 12-Jun-2002		O/C			
243001	BATTERY TEMP INDICATOR *CF			1229-1 2867	MTH 12-Jun-2002		O/C			
243003 LEFT	GENERATOR CONTROL UNIT SZR			51525-001F 95018	MTH 05-May-2008 HRS 1111		O/C	5365		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243003 RIGHT	GENERATOR CONTROL UNIT HUR			51525-001F 97288	MTH HRS		O/C		1925	
243004	BATTERY TEMP MONITOR- *CF			1529-1-1 3707	MTH		O/C			
243006 LEFT	GENERATOR LOAD AMMETER *CF			C662501-0107 B22356	MTH		O/C			
243006 RIGHT	GENERATOR LOAD AMMETER *CF			C662501-0107 B22358	MTH		O/C			
243007	BATTERY 9914058-6	KICT		30978-002 10104140	MTH HRS LDG		O/C			
243008	BATTERY RELAY *CF			A931F CM99878	MTH		O/C			
243011	DC POWER VOLTMETER *CF			C662502-0101 B22381	MTH		O/C			
245001 LEFT	START CONTROL P.C.B. *CF			6318324-6 SN-UNKNOWN	MTH		O/C			
245001 RIGHT	START CONTROL P.C.B. *CF			6318324-6 SN-UNKNOWN	MTH		O/C			
245002 LEFT	FUEL CONTROL P.C.B. *CF			6318341-6 0313	MTH		O/C			
245002 RIGHT	FUEL CONTROL P.C.B. HUR			6318341-6 0215	MTH HRS		O/C	0		
245003 LEFT	IGNITOR CONTROL P.C.B. *CF			6318322-3 SN-UNKNOWN	MTH		O/C			
245004 LEFT	ANTI-ICE P.C.B. ICT			6318343-6 0334	MTH HRS		O/C	0		
245004 RIGHT	ANTI-ICE P.C.B. *CF			6318343-6 SN-UNKNOWN	MTH		O/C			
245005 LEFT	PCB ATTENUATOR *CF			6318346-1 SN-UNKNOWN	MTH		O/C			
245005 RIGHT	PCB ATTENUATOR *CF			6318346-1 SN-UNKNOWN	MTH		O/C			
245006	ENVIRONMENTAL P.C.B. *CF			6318356-2 SN-UNKNOWN	MTH		O/C			
245007	HYDRAULIC P.C.B. *CF			6318344-1 SN-UNKNOWN	MTH		O/C			
245008	TRIM RELAY P.C.B. *CF			6518351-9 SN-UNKNOWN	MTH		O/C			
245009	DIMMING P.C.B. *CF			6518353-4 SN-UNKNOWN	MTH		O/C			
245010	GEAR LOGIC 1 P.C.B. *CF			6318345-1 SN-UNKNOWN	MTH		O/C			
245012	SPEEDBRAKE P.C.B. *CF			6318347-1 SN-UNKNOWN	MTH		O/C			
245013 LEFT	IDLE CONTROL P.C.B. *CF			6318348-11 SN-UNKNOWN	MTH		O/C			
245013 RIGHT	IDLE CONTROL P.C.B. *CF			6318348-11 SN-UNKNOWN	MTH		O/C			
245014	GEAR LOGIC 2 P.C.B. *CF			6318392-1 SN-UNKNOWN	MTH		O/C			
245015	GEAR MONITOR P.C.B. *CF			6318394-1 SN-UNKNOWN	MTH		O/C			
245016	TAIL DEICE P.C.B *CF			6318395-1 SN-UNKNOWN	MTH		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245020	OVERVOLTAGE DETECTOR *CF			1645-1-3 2915	MTH 12-Jun-2002		O/C			
256001	ELT TRANSMITTER C406-2	EGCN		453-5000-999 01848	MTH 26-Nov-2010 HRS 1581 LDG 1568		O/C			
256002	ELT BEACON BATTERY PACK			452-0133 371039-011	MTH 14-Sep-2016 HRS 2491:40 LDG 2227		60	1 0 0	01-Oct-2021	15 m 7 d
Manufacture Date: 26-Aug-2016										
256003	REMOTE SWITCH	*CF		452-0010 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
256004	ELT ANTENNA	*CF		110-328-01 2883	MTH 12-Jun-2002		O/C			
256006 NO. 1	LIFE VEST	LFOQ		P01074-103 16102260226	MTH 10-Sep-2018 HRS 2691:50 LDG 2422		60	0	01-Nov-2021	16 m 8 d
256006 NO. 2	LIFE VEST	LFLY		P01074-103 19041720132	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	1	01-May-2024	46 m 7 d
256006 NO. 3	LIFE VEST	LFLY		P01074-103 19030260128	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	4	13-Mar-2024	44 m 18 d
256006 NO. 4	LIFE VEST	LFLY		P01074-103 19030260127	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	4	13-Mar-2024	44 m 18 d
256006 NO. 5	LIFE VEST	LFLY		P01074-103 19041720131	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	1	01-May-2024	46 m 7 d
256006 NO. 6	LIFE VEST	LFLY		P01074-103 19041720130	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	1	01-May-2024	46 m 7 d
256006 NO. 7	LIFE VEST	LFLY		P01074-103 19030260129	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	4	13-Mar-2024	44 m 18 d
256006 NO. 8	LIFE VEST	LFLY		P01074-103 19030260130	MTH 08-Aug-2019 HRS 2767:25 LDG 2491		60	4	13-Mar-2024	44 m 18 d
256006 NO. 9	LIFE VEST			P01074-201 17022140046	MTH 20-Oct-2017		120	0	01-May-2021	10 m 7 d
256007	DIGITAL GPS INTERFACE UNIT *CF	J		453-6500 01408	MTH 12-Jun-2002		O/C			
261001 LEFT	FIRE DETECTOR SENSOR 9912416-1	*CF		3001-212-1004/455-9 204252	MTH 12-Jun-2002		O/C			
261001 RIGHT	FIRE DETECTOR SENSOR 9912416-1	*CF		3001-212-1004/455-9 204254	MTH 12-Jun-2002		O/C			
262001 LEFT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	LFOQ		30401102-2 61552B1	MTH 06-May-2020 HRS 2798:30 LDG 2519		O/C	3 0		
262001 RIGHT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	LFOQ		30401102-2 56117B1	MTH 06-May-2020 HRS 2798:30 LDG 2519		O/C	3 0		
262003 CABIN	PORTABLE FIRE EXTINGUISHER LFOQ			C352TS E-92813308	MTH 10-Sep-2018 HRS 2691:50 LDG 2422		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER LFOQ			C352TS E-92813309	MTH 10-Sep-2018 HRS 2691:50 LDG 2422		O/C	0 0		
262010 LEFT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE LFOQ			13083-5 BATCH ESD19M779-001	MTH 06-May-2020 HRS 2798:30 LDG 2519		72		31-Dec-2025	66 m 7 d
<i>262002 : L1</i>										
REMOVED PART NO: 13083-5 REMOVED SERIAL NO: ESD15D590-001. Manufacture Date: 31-Dec-2019										
262011 LEFT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE LFOQ			13083-5 BATCH ESD19M779-001	MTH 06-May-2020 HRS 2798:30 LDG 2519		72		31-Dec-2025	66 m 7 d
<i>262002 : L2</i>										
REMOVED PART NO: 13083-5 REMOVED SERIAL NO: ESD15D590-001. Manufacture Date: 31-Dec-2019										
262012 RIGHT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE LFOQ			13083-5 BATCH ESD19M779-001	MTH 06-May-2020 HRS 2798:30 LDG 2519		72		31-Dec-2025	66 m 7 d
<i>262002 : R1</i>										
REMOVED PART NO: 13083-5 REMOVED SERIAL NO: ESD15D590-001. Manufacture Date: 31-Dec-2019										
262013 RIGHT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE LFOQ			13083-5 BATCH ESD19M779-001	MTH 06-May-2020 HRS 2798:30 LDG 2519		72		31-Dec-2025	66 m 7 d
<i>262002 : R2</i>										
REMOVED PART NO: 13083-5 REMOVED SERIAL NO: ESD15D590-001. Manufacture Date: 31-Dec-2019										
272001	RUDDER BIAS VALVE *CF			5307-1 0360C	MTH 12-Jun-2002		O/C			
273001	SHAKER CONTROL *CF	A		201 5504	MTH 12-Jun-2002		O/C			
273002	ELEVATOR TRIM SERVO *CF	4		44430-3548 T725	MTH 12-Jun-2002		O/C			
275001	SHUTOFF VALVE *CF			4083-1 209	MTH 12-Jun-2002		O/C			
275002 LEFT	FLAP ACTUATOR 9912365-5 *CF			1542000-7 1203	MTH 12-Jun-2002		O/C			
275002 RIGHT	FLAP ACTUATOR 9912365-5 *CF			1542000-7 1208	MTH 12-Jun-2002		O/C			
276001 LEFT	SPEED BRAKE ACTUATOR 9912375-4 *CF			1542100-5 1221	MTH 12-Jun-2002		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912375-4 *CF			1542100-5 1218	MTH 12-Jun-2002		O/C			
281001 LEFT	SURGE TANK FLOAT VALVE 9912016-2 *CF			35C10D 2340	MTH 12-Jun-2002		O/C			
281001 RIGHT	SURGE TANK FLOAT VALVE 9912016-2 *CF			35C10D 2387	MTH 12-Jun-2002		O/C			
282001 LEFT	FUEL BOOST PUMP 9912017-4 *CF			1C7-13 1AV7	MTH 12-Jun-2002		O/C			
282001 RIGHT	FUEL BOOST PUMP EGCN			9912017-4 6AV100	MTH 22-Apr-2013 HRS 2071:12 LDG 1884		O/C	76 0 0		
282002 LEFT	EJECTOR FUEL AFT PUMP 9912190-2 *CF			RG45310 B8497	MTH 12-Jun-2002		O/C			
282002 RIGHT	EJECTOR FUEL AFT PUMP 9912190-2 *CF			RG45310 B8437	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282003 LEFT	SOLENOID VALVE 9914470-3	*CF		527700-103 0174	MTH 12-Jun-2002		O/C			
282003 RIGHT	SOLENOID VALVE 9914470-3	*CF		527700-103 0178	MTH 12-Jun-2002		O/C			
282004 LEFT	FUEL MOTOR VALVE 9912014-3	*CF		EM9014-3 1240	MTH 12-Jun-2002		O/C			
282004 RIGHT	FUEL MOTOR VALVE 9912014-3	*CF		EM9014-3 1221	MTH 12-Jun-2002		O/C			
282005 LEFT	EJECTOR FUEL FORWARD PUMP 9912190-2	*CF		RG45310 B8409	MTH 12-Jun-2002		O/C			
282005 RIGHT	EJECTOR FUEL FORWARD PUMP 9912190-2	*CF		RG45310 B8520	MTH 12-Jun-2002		O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 20108165	MTH 12-Jun-2002		O/C			
284001 LEFT	#5 FUEL PROBE 9912589-5	*CF		10664T05Y00 0672	MTH 12-Jun-2002		O/C			
284001 RIGHT	#5 FUEL PROBE 9912589-5	*CF		10664T05Y00 0674	MTH 12-Jun-2002		O/C			
284002 LEFT	#6 FUEL PROBE 9912589-6	*CF		10664T06Y00 0673	MTH 12-Jun-2002		O/C			
284002 RIGHT	#6 FUEL PROBE 9912589-6	*CF		10664T06Y00 0669	MTH 12-Jun-2002		O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER 9912589-9	*CF		10663B01Y02 02010598	MTH 12-Jun-2002		O/C			
284004 LEFT	#3 FUEL PROBE 9912589-3	*CF		10664T03Y00 0668	MTH 12-Jun-2002		O/C			
284004 RIGHT	#3 FUEL PROBE 9912589-3	*CF		10664T03Y00 0684	MTH 12-Jun-2002		O/C			
284005 LEFT	LEFT #4 INBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0858	MTH 12-Jun-2002		O/C			
284005 RIGHT	RIGHT #4 INBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0876	MTH 12-Jun-2002		O/C			
284006 LEFT	#2 FUEL PROBE 9912589-2	*CF		10664T02Y00 0690	MTH 12-Jun-2002		O/C			
284006 RIGHT	#2 FUEL PROBE 9912589-2	*CF		10664T02Y00 0687	MTH 12-Jun-2002		O/C			
284007 LEFT	#1 FUEL PROBE 9912589-1	*CF		10664T01Y00 0678	MTH 12-Jun-2002		O/C			
284007 RIGHT	#1 FUEL PROBE 9912589-1	*CF		10664T01Y00 0680	MTH 12-Jun-2002		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH *CF			L16H-9 SN-UNKNOWN	MTH 22-Oct-2002		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH *CF			L16H-9 SN-UNKNOWN	MTH 22-Oct-2002		O/C			
284009 LEFT	LEFT #4 OUTBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0812	MTH 12-Jun-2002		O/C			
284009 RIGHT	RIGHT #4 OUTBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0883	MTH 12-Jun-2002		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 190	MTH 12-Jun-2002		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 194	MTH 12-Jun-2002		O/C			
291006	LOADING VALVE 9912423-39	*CF		4134-4 218	MTH 12-Jun-2002		O/C			
291007	PRESSURE SWITCH GAUGE 9912373-4	LSZR		GPP1250-58 827400	MTH 19-Apr-2010 HRS 1513 LDG 1507		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291008	HYDRAULIC MANIFOLD ASSY 9912423-40	*CF		8184-12 556	MTH 12-Jun-2002		O/C			
291009	RELIEF VALVE 9912423-38	*CF		2576-1 202	MTH 12-Jun-2002		O/C			
291010 LEFT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 U17599	MTH 12-Jun-2002		O/C			
291010 RIGHT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 U17602	MTH 12-Jun-2002		O/C			
291011 LEFT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 527	MTH 12-Jun-2002		O/C			
291011 RIGHT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 557	MTH 12-Jun-2002		O/C			
291012	SPEEDBRAKE DUMP VALVE 9912423-33	*CF		4082-6 159	MTH 12-Jun-2002		O/C			
291014	GEAR VALVE 9912423-35	*CF		4051-3 156	MTH 12-Jun-2002		O/C			
291015	LANDING GEAR VALVE 9912423-36	*CF		9504-1 156	MTH 12-Jun-2002		O/C			
291016 LEFT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 311	MTH 12-Jun-2002		O/C			
291016 RIGHT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 312	MTH 12-Jun-2002		O/C			
291017	THERMAL RELIEF VALVE 9912423-32	*CF		2577-1 156	MTH 12-Jun-2002		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 159	MTH 12-Jun-2002		O/C			
291019 LEFT	ATTENUATOR VALVE 9912423-28	*CF		4107-3 156	MTH 12-Jun-2002		O/C			
291019 RIGHT	ATTENUATOR VALVE 9912423-27	*CF		4107-4 156	MTH 12-Jun-2002		O/C			
291020	SPEED BRAKE VALVE *CF			4052-5 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
291021	FLAP VALVE 9912423-29	*CF		4052-4 112	MTH 12-Jun-2002		O/C			
301001	ISOLATION VALVE 9912403-2	*CF		2602-36 0725	MTH 12-Jun-2002		O/C			
301002 LEFT	PRESSURE SWITCH *CF			1106P55-1 1912A	MTH 12-Jun-2002		O/C			
301002 RIGHT	PRESSURE SWITCH *CF			1106P55-1 1878A	MTH 12-Jun-2002		O/C			
301003 LEFT	PRESS REGULATOR VALVE EGCN			9912495-5 3950A	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		O/C	6 0 0		
301003 RIGHT	PRESS REGULATOR VALVE 9912495-5	ICT		1962-00-9 1601	MTH 16-Jul-2002 HRS 13		O/C	0		
301004 LEFT	TEMPERATURE SWITCH *CF			1173T42-4 1796	MTH 12-Jun-2002		O/C			
301004 RIGHT	TEMPERATURE SWITCH *CF			1173T42-4 1814	MTH 12-Jun-2002		O/C			
301005 LEFT	SOLENOID VALVE *CF			3D2353-06 N17935	MTH 12-Jun-2002		O/C			
301005 RIGHT	SOLENOID VALVE *CF			3D2353-06 N19400	MTH 12-Jun-2002		O/C			
301006 LEFT	HORIZONTAL STABILIZER BOOT HUR			29S4D5244-15 MYDNTYO	MTH 22-Jul-2005 HRS 499		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301006 RIGHT	HORIZONTAL STABILIZER BOOT	SZR		29S4D5244-16 MYPV 760	MTH 23-Jan-2007 HRS 827		O/C	0		
302001 LEFT	PRESS REG VALVE	*CF		5285-00-3 183	MTH 12-Jun-2002		O/C			
302001 RIGHT	PRESS REG VALVE	*CF		5285-00-3 184	MTH 12-Jun-2002		O/C			
302002 LEFT	INLET TEMP SWITCH	*CF		1173T0759 1596	MTH 12-Jun-2002		O/C			
302002 RIGHT	INLET TEMP SWITCH	*CF		1173T0759 1602	MTH 12-Jun-2002		O/C			
303002 LEFT	TUBE PITOT	*CF		PH502 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
303002 RIGHT	TUBE PITOT	HUR		PH502 SN-UNKNOWN	MTH 12-Jan-2006 HRS 599		O/C	0		
304001	B/A TEMP MONITOR-	*CF		1169-1 3258	MTH 12-Jun-2002		O/C			
304002	HEAT EXCHANGER	*CF		10653A 9912041-3 1338	MTH 12-Jun-2002		O/C			
304003	PRESSURE REGULATING CHECK VALVE	*CF		1962-00-3 1415	MTH 12-Jun-2002		O/C			
304004 AFT	FLOORBOARD TF006 SENSOR	*CF		27221274 12AU608	MTH 12-Jun-2002		O/C			
304004 FORWARD	T/C TT002 SENSOR	*CF		27221274 1AV60	MTH 12-Jun-2002		O/C			
304005	TEMP CONTROLLER	*CF		1E58-1 10AU184	MTH 12-Jun-2002		O/C			
304006	TEMP CONTROL VALVE	*CF		27241287 2AU4	MTH 12-Jun-2002		O/C			
304007	ALCOHOL PUMP ASSY	*CF		476411 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
304008 LEFT	W/S BLEED AIR VALVE	*CF		1403-25 2914	MTH 12-Jun-2002		O/C			
304008 RIGHT	W/S BLEED AIR VALVE	*CF		1403-25 2899	MTH 12-Jun-2002		O/C			
304009	PRESSURE SWITCH	*CF		1115P25 3739AB	MTH 12-Jun-2002		O/C			
304010 LEFT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 4712	MTH 12-Jun-2002		O/C			
304010 RIGHT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 4717	MTH 12-Jun-2002		O/C			
304013 LEFT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 NSN	MTH 12-Jun-2002		O/C			
304013 RIGHT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 NSN	MTH 12-Jun-2002		O/C			
312001 LEFT	DIGITAL CLOCK	LFOQ		M877A5V 24993	MTH 04-Oct-2019 HRS 2772:45 LDG 2496		O/C	1 0		
313001	FLIGHT HOUR METER	*CF		C664503-0104 85071 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
315001	CABIN ALT SWITCH			9910095-6 1711436	MTH 20-Apr-2017 HRS 2548:40 LDG 2280		O/C	0 0 0		
315002	MASTER ANNUNCIATOR	E		9912586-2 586000126	MTH 12-Jun-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321001 LEFT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR *CF			6341200-7 9	MTH 12-Jun-2002		O/C			
321001 RIGHT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR *CF			6341200-8 7	MTH 12-Jun-2002		O/C			
321003 LEFT MAIN GEAR	TRUNNION EGCN			6341221-7 24060895	MTH 29-May-2014 HRS 2260:30 LDG 2018		39991	0	42009	39490
321003 RIGHT MAIN GEAR <i>321004 : R</i>	TRUNNION EGCN			6341221-8 23959774H	MTH 29-May-2014 HRS 2260:30 LDG 2018		39991	0	42009	39490
321004 LEFT MAIN GEAR	FORK AND PISTON ASSEMBLY *CF			6342200-4 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		12500	0	12500	9981
321005 LEFT MAIN GEAR	OLEO ASSEMBLY SZR			6341201-1 170	MTH 12-Jun-2002 LDG 0		28075	0	28075	25556
321005 RIGHT MAIN GEAR	OLEO ASSEMBLY EGCN			6341201-1 0179	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		28075	2018	28075	25556
321007 LEFT	TRAILING LINK AND AXLE ASSEMBLY EGCN			6341241-3 24055306	MTH 29-May-2014 HRS 2260:30 LDG 2018		41666	0	43684	41165
321007 RIGHT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341241-2 NSN	MTH 12-Jun-2002 LDG 0		41666	0	41666	39147
321011 LEFT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL *CF			6341135-3 NSN	MTH 12-Jun-2002 LDG 0		16224	0	16224	13705
321011 RIGHT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL *CF			6341135-3 NSN	MTH 12-Jun-2002 LDG 0		16224	0	16224	13705
321012 LEFT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY *CF			6341133-9 NSN	MTH 12-Jun-2002 LDG 0		19713	0	19713	17194
321012 RIGHT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY *CF			6341133-9 NSN	MTH 12-Jun-2002 LDG 0		19713	0	19713	17194
322001 LEFT MAIN GEAR	NOSE LANDING GEAR SHIMMY DAMPER LFOQ			6343001-10 066-10X	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C	1 0		
322002 LEFT MAIN GEAR	NOSE LANDING GEAR STRUT ASSY(AND ATTACHING HARDWARE) ASSEMBLY *CF			6342200-3 82	MTH 12-Jun-2002 LDG 0		22500	0	22500	19981
322005 LEFT MAIN GEAR	NOSE LANDING GEAR ASSEMBLY *CF			6342200-2 82	MTH 12-Jun-2002		O/C			
323001 LEFT MAIN GEAR	SIDE BRACE ACTUATOR EGGW			9912573-2 0178	MTH 11-Jul-2013 HRS 2126:24 LDG 1817		41666	1814	41669	39150
323001 RIGHT MAIN GEAR	SIDE BRACE ACTUATOR 9912573-2 *CF			1556700-3 0179	MTH 12-Jun-2002 LDG 0		41666	0	41666	39147
323002 LEFT MAIN GEAR	UPLOCK *CF			6327504-6 379	MTH 12-Jun-2002		O/C			
323002 RIGHT MAIN GEAR	UPLOCK *CF			6327504-6 378	MTH 12-Jun-2002		O/C			
323004 LEFT MAIN GEAR	NOSE GEAR ACTUATOR ASSEMBLY SZR			9912370-4 0626	MTH 06-Dec-2002 LDG 0		12000	0	12000	9481
323005 LEFT MAIN GEAR	NOSE LANDING GEAR UPLOCK ACTUATOR *CF			6327504-7 166	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323020	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912368-2	LFOQ		40005320-2 3455	MTH 10-Sep-2018 HRS 2691:50 LDG 2422		288	201	01-Feb-2026	67 m 8 d
Manufacture Date: 01-Feb-2002										
323021	EMERGENCY GEAR BOTTLE GAUGE SZR			18225901 042906	MTH 20-Aug-2007 HRS 954		O/C	0		
324001	WHEEL ASSEMBLY LEFT MAIN GEAR 9912743-6			3-1601-3 1185	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C	88 1070:37		
324001	WHEEL ASSEMBLY RIGHT MAIN GEAR 9912743-4			3-1601-2 0225	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C	45 334:40		
324002	WHEEL ASSEMBLY NOSE LANDING GEAR			3-1418 4421	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C			
324003	TIRE LEFT MAIN GEAR 9912576-1			277K28-1 71792342	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C			
324003	TIRE RIGHT MAIN GEAR 9912576-1			277K28-1 71792254	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C			
324004	NOSE LANDING GEAR TIRE			184F68-1 61642095	MTH 21-Sep-2017 HRS 2595:10 LDG 2325		O/C			
324005	BRAKE ASSEMBLY LEFT MAIN GEAR 9912743-5	ICT		2-1651-1 0396	MTH 07-Aug-2014 HRS 2293:06 LDG 2032		O/C			
324005	BRAKE ASSEMBLY RIGHT MAIN GEAR 9912743-5	ICT		2-1651-1 0552	MTH 07-Aug-2014 HRS 2293:06 LDG 2032		O/C			
324101	BRAKE ANTISKID VALVE 9912575-4	*CF		38-861-1 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
324102	ANTISKID TRANSDUCER LEFT 9912305-2	*CF		40-955 5946	MTH 12-Jun-2002		O/C			
324102	ANTISKID TRANSDUCER RIGHT 9912305-2	*CF		40-955 5934	MTH 12-Jun-2002		O/C			
324103	DIGITAL BOX 9912575-3	*CF		142-031-1 192	MTH 12-Jun-2002		O/C			
324104	BRAKE PRESSURE SWITCH *CF			GPP1250-77 0145022	MTH 12-Jun-2002		O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 0584A	MTH 12-Jun-2002		O/C			
324106	HYDRAULIC PUMP MOTOR *CF			MP50B1 2236	MTH 12-Jun-2002		O/C			
324107	BRAKE ANTISKID ACCUMULATOR *CF			57C57663 0609	MTH 12-Jun-2002		O/C			
324108	LOW PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 0132585	MTH 12-Jun-2002		O/C			
324109	BRAKE PRESSURE PUMP 9912364-2	*CF		640929 1491	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324110	EMERGENCY BRAKE VALVE 9912387-3	*CF		878208-03 V217	MTH 12-Jun-2002		O/C			
324111	FAULT DISPLAY UNIT 9912305-9	*CF		42-92750 1048A	MTH 12-Jun-2002		O/C			
324113	RELIEF VALVE	*CF		1785-1 630	MTH 12-Jun-2002		O/C			
326001	UPLOCK SWITCH LEFT MAIN GEAR	*CF		65-430087 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
326001	UPLOCK SWITCH NOSE LANDING GEAR	*CF		65-430087 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
326001	UPLOCK SWITCH RIGHT MAIN GEAR	*CF		65-430087 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
331001	LIGHT DIMMER CENTER	*CF		273-1 0150205	MTH 12-Jun-2002		O/C			
331001	LIGHT DIMMER LEFT	*CF		273-1 0150176	MTH 12-Jun-2002		O/C			
331001	LIGHT DIMMER RIGHT	*CF		273-1 0140179	MTH 12-Jun-2002		O/C			
331002	ELECTRICAL PANEL INVERTER	*CF		EM2044-1 3676A	MTH 12-Jun-2002		O/C			
332001	FORWARD LEFT INVERTER L1	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	MID FORWARD INVERTER L2	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	MID LEFT INVERTER L3	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	AFT MID INVERTER L4	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	AFT LEFT INVERTER L5	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	FORWARD RIGHT INVERTER R1	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	MID FORWARD INVERTER R2	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	MID RIGHT INVERTER R3	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	AFT MID INVERTER R4	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
332001	AFT RIGHT INVERTER R5	*CF		AL750PS SN-UNKNOWN	MTH 12-Jun-2002		O/C			
334001	GROUND RECOGNITION RED LIGHT SZR			90033-13 010539	MTH 15-Sep-2008 HRS 1195		O/C		0	
334003	COLLISION LIGHT POWER SUPPLY LEFT	*CF	1	04-1502-1408 18139	MTH 12-Jun-2002		O/C			
334003	COLLISION LIGHT POWER SUPPLY RIGHT	*CF	1	04-1502-1408 18138	MTH 12-Jun-2002		O/C			
334005	COLLISION LIGHT ASSEMBLY LEFT	*CF	1	03-1302-0003 18078	MTH 12-Jun-2002		O/C			
334005	COLLISION LIGHT ASSEMBLY RIGHT	*CF	1	03-1302-0004 17157	MTH 12-Jun-2002		O/C			
335000	EMERGENCY EXIT LIGHT BATTERY LEFT	*CF		CBS28 866	MTH 12-Jun-2002		O/C	0		
341001	AIR DATA COMPUTER LEFT		HUR	822-1109-004 NG7Y	MTH 12-Jan-2006 HRS 599		O/C		0	
341002	ALTIMETER/AIRSPEED INDICATOR STANDBY	*CF	11	WL102AMS6 AN794	MTH 12-Jun-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341006	AOA INDICATOR	*CF		C12405-1 697	MTH 12-Jun-2002		O/C			
341007	AOA SENSOR			C-12717-1 413	MTH 19-Mar-2018 HRS 2639:40 LDG 2367		O/C			
341008	BAROMETRIC SWITCH	*CF		GBC300-156 0207091	MTH 12-Jun-2002		O/C			
341010 AFT	RADIO ALT ANTENNA	*CF		S67-2002 24121	MTH 12-Jun-2002		O/C			
341010 FORWARD	RADIO ALT ANTENNA	*CF		S67-2002 24114	MTH 12-Jun-2002		O/C			
341011	RADIO ALTIMETER TRANSMITTER ALT-55	*CF	11	622-2855-011 NFPW	MTH 12-Jun-2002		O/C			
341012	RADIO ALT CONVERTER RAC-870	*CF	5	622-7209-002 J3DX	MTH 12-Jun-2002		O/C			
341030	TEMPERATURE PROBE SENSOR ICT			0129G B18024	MTH 07-Oct-2014 HRS 2301:42 LDG 2040		O/C	0 0		
341031	COPILOT AIRSPEED INDICATOR 9912446-5	*CF		37277-1525 9945	MTH 12-Jun-2002		O/C			
341033 RIGHT	ADC ALTIMETER AM-250	*CF		70251N01D02 01030307C	MTH 12-Jun-2002		O/C			
341101	IAPS CARD CAGE ICC-3001	*CF		822-1459-001 YXCY	MTH 12-Jun-2002		O/C			
341102 LEFT	IO PROCESSOR CARD ICO-3000	*CF		822-1130-151 01LB	MTH 12-Jun-2002		O/C			
341102 RIGHT	IO PROCESSOR CARD IOC-3000	*CF		822-1130-151 01KY	MTH 12-Jun-2002		O/C			
341103 NO. 1	CONFIGURATION CONTROL STRAPPING UNIT	*CF		822-1363-002 HYHN	MTH 12-Jun-2002		O/C			
341103 NO. 2	CONFIGURATION CONTROL STRAPPING UNIT	*CF		822-1363-002 HYHL	MTH 12-Jun-2002		O/C			
342001	MAGNETIC COMPASS C2400-L4V2W-5B	ZRH		C660501-0301 SN-UNKNOWN	MTH 22-Jan-2007 HRS 827		O/C	0		
342002 LEFT	AHRS COMPUTER AHC-3000	*CF	1	822-1110-002 HN4V	MTH 12-Jun-2002		O/C			
342002 RIGHT	AHRS COMPUTER AHC-3000	*CF	1	822-1110-002 YXNP	MTH 12-Jun-2002		O/C			
342003 RIGHT	HSI INDICATOR S3100-303	SZR		2855-01-1 509	MTH 15-Oct-2007 HRS 998		O/C	1311		
342003	STANDBY HSI INDICATOR S3100-303	HUR		2855-01-1 208	MTH 08-Aug-2005 HRS 503		O/C	1375		
342004	ATT DIRECTOR INDICATOR SZR			2802-01-1 077	MTH 03-Aug-2007 HRS 941		O/C	135		
342005 LEFT	FLIGHT GUIDANCE COMPUTER FGC-3000	HUR		822-1108-122 12DPY	MTH 02-Mar-2004 HRS 298		O/C	0		
342005 RIGHT	FLIGHT GUIDANCE COMPUTER FGC-3000	HUR		822-1108-122 127XV	MTH 02-Mar-2004 HRS 298		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342006 LEFT	FLUX DETECTION UNIT FDU-3000	*CF		822-1193-001 26744	MTH 12-Jun-2002		O/C			
342006 RIGHT	FLUX DETECTION UNIT FDU-3000	*CF		822-1193-001 26742	MTH 12-Jun-2002		O/C			
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 J8DC	MTH 12-Jun-2002		O/C			
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 J6TM	MTH 12-Jun-2002		O/C			
342007	COMPENSATION-EXTERNAL -- ZRH			822-1200-998 28MMC	MTH 22-Jan-2007 HRS 827		O/C	0		
342008 LEFT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 J88X	MTH 12-Jun-2002		O/C			
342008 RIGHT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 J9YV	MTH 12-Jun-2002		O/C			
342009	ENVIRONMENTAL CONTROL IEC-3001	*CF	2	822-1167-001 HK5Y	MTH 12-Jun-2002		O/C			
342010 LEFT	OPERATION CONFIGURATION MODULE OCM-3100	*CF		822-1484-201 J1YM	MTH 12-Jun-2002		O/C			
342010 RIGHT	OPERATION CONFIGURATION MODULE OCM-3100	*CF		822-1484-201 J1YN	MTH 12-Jun-2002		O/C			
342021	VERTICAL SPEED INDICATOR *CF			C661006-0101 355789	MTH 12-Jun-2002		O/C			
342030	STANDBY GYRO AI-300AE	*CF		501-1568-56 4051	MTH 12-Jun-2002		O/C			
342031	STANDBY GYRO POWER SUPPLY PS-834A	EGGW	5	501-1682-01 1562	MTH 06-Sep-2012 HRS 1913:30 LDG 1788		O/C			
342057	AFD-CRSR CONTROL PANEL CCP-3000	ZRH		822-1746-102 2D1DM	MTH 22-Jan-2007 HRS 827		O/C	0		
342301 LEFT	MODE SELECTOR MSP-85	*CF	10	622-6209-019 JCBG	MTH 12-Jun-2002		O/C			
342302 CENTER	ADAPTIVE FLT DISPLAY AFD-3010E	ZRH		822-1753-220 OOTF	MTH 22-Jan-2007 HRS 827		O/C	0		
342302 LEFT	ADAPTIVE FLT DISPLAY *CF		4	822-1084-206 00TF	MTH 12-Jun-2002		O/C			
342304 LEFT	DISPLAY CONTROL PANEL DCP-3000	*CF	1	822-1134-102 J1YW	MTH 12-Jun-2002		O/C			
342305	COURSE/HEADING PANEL CHP-3000	*CF		822-1279-002 J72V	MTH 12-Jun-2002		O/C			
343000	MARKER BEACON RECEIVER KMR-675	*CF	1	066-01044-0001 1656	MTH 12-Jun-2002		O/C			
343001	MARKER BEACON ANTENNA			31-10-01 5287	MTH 12-Dec-2014 HRS 2314:30 LDG 2046		O/C	0 0 0		
343002	DUAL GLIDESCOPE COUPLER *CF			82-70-01 1277	MTH 12-Jun-2002		O/C			
343003	GLIDESCOPE ANTENNA *CF			44-70-01 A8323	MTH 12-Jun-2002		O/C			
344001	EGPWS COMPUTER S2800-497	*CF	8	965-0976-040-213-213 13268	MTH 12-Jun-2002		O/C			
344002	RADAR TRANSCEIVER RTA-800	*CF	33	822-1050-004 J42J	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345001 AFT	DME 2 ANTENNA 85226	*CF		DMNI50-2-2 83337	MTH 12-Jun-2002		O/C			
345001 FORWARD	DME 1 ANTENNA	*CF		56-80-01 8153	MTH 12-Jun-2002		O/C			
345002 LEFT	DME 1 TRANSCEIVER KN-63	*CF	6	066-01070-0001 27244	MTH 12-Jun-2002		O/C			
345002 RIGHT	DME 2 TRANSCEIVER		2	066-01107-12 31530	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C			
345003 LEFT	DME INDICATOR KDI-574	LFOQ		066-01069-0014 72080	MTH 06-May-2020 HRS 2798:30 LDG 2519		O/C	2 0		
345003 RIGHT	DME INDICATOR KDI-575	*CF		066-01069-0015 2552	MTH 12-Jun-2002		O/C	0		
345004 LEFT	DME CONVERTER KDA-689	*CF	1	071-01227-0001 10989	MTH 12-Jun-2002		O/C			
345004 RIGHT	DME CONVERTER KDA-689	*CF	1	071-01227-0001 10991	MTH 12-Jun-2002		O/C			
345005 LEFT	NAVIGATION ANTENNA	*CF		22-37-14 2868	MTH 12-Jun-2002		O/C			
345005 RIGHT	NAVIGATION ANTENNA	*CF		22-37-14 2867	MTH 12-Jun-2002		O/C			
345020 TOP	ADF 1 ANTENNA KA-44B	*CF		071-01234-0002 77290	MTH 12-Jun-2002		O/C			
345021	ADF 1 RECEIVER KR-87	ZRH		066-01072-0007 76390	MTH 22-Jan-2007 HRS 827		O/C	0		
345040 AFT	TRANSPONDER 2 ANTENNA 85226	*CF		DMNI50-2-2 82395	MTH 12-Jun-2002		O/C			
345040 FORWARD	TRANSPONDER 1 ANTENNA 85226	*CF		DMNI50-2-2 83715	MTH 12-Jun-2002		O/C			
345040 LEFT TOP	-DIVERSITY TRANSPONDER ANTENNA ZRH			DMNI50-2-2 91382	MTH 22-Jan-2007 HRS 827		O/C	0		
345040 RIGHT TOP	-DIVERSITY TRANSPONDER ANTENNA ZRH			DMNI50-2-2 91410	MTH 22-Jan-2007 HRS 827		O/C	0		
345041 NO. 1	TRANSPONDER	LFOQ		011-00455-90 / GTX330D ES 84405672	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C	2 0		
345041 NO. 2	TRANSPONDER	LFOQ		011-0455-90 GTX330D ES 84405673	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C	2 0		
345049	FMS NAV COMPUTER UNS1K S3100-175	LFOQ		1116-40-1110 2205	MTH 06-May-2020 HRS 2798:30 LDG 2519		O/C	0 0		
345050	GPS FMS DISPLAY S3100-241			1117-1-104 6216	MTH 03-Apr-2018 HRS 2643 LDG 2371		O/C			
345051 NO. 1	GPS FMS ANTENNA	*CF		10706 7509	MTH 12-Jun-2002		O/C			
345052	FMS CONFIGURATION MODULE	*CF		11921 4358	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345053 NO. 1	GNS COM/NAV/GPS UNIT LFOQ			010-00890-50 GTN750MTH 1ZA210690	07-Mar-2019 HRS 2724:05 LDG 2452		O/C	0 0		
345053 NO. 2	GNS COM/NAV/GPS UNIT LFOQ			010-00889-50 1Z8210639	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C	0 0		
345053	DATA TRANSFER UNIT PERMANENT DTU-100 *CF		1	1406-01-1 1737	MTH 12-Jun-2002		O/C			
345068	FLIGHT SIMULATOR UNIT FSU-5010	ZRH		822-1543-101 2DDLG	MTH 22-Jan-2007 HRS 827		O/C	0		
346050	E.L. PANEL	*CF		050-03104-0000 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
350006	OXYGEN CYLINDER 9912057-19	LFOQ		176274-22 869765701	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		180	36	01-Mar-2031	128 m 5 d
Manufacture Date: 01-Mar-2016										
350007	OXYGEN PRESSURE GAUGE MD-97	*CF	B	C668512-0101 B22366	MTH 12-Jun-2002		O/C			
351001	OXYGEN 3 POSITION VALVE 9912057-21	*CF		110081-06 0786	MTH 12-Jun-2002		O/C			
351002 COPILOT	OXYGEN MASK	LFOQ		MC-10-16-101 100248	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		72	1	07-Feb-2025	55 m 14 d
351002 PILOT	OXYGEN MASK	LFOQ		MC-10-16-101 118274	MTH 04-Oct-2019 HRS 2772:45 LDG 2496		72	162	29-Jul-2025	61 m 5 d
351003	OXYGEN PRESSURE SWITCH HUR			P24032 0923	MTH 22-Jul-2005 HRS 499		O/C	0		
361001 LEFT	PRECOOL TEMPERATURE SENSOR 9912584-3	*CF		27431501-10 1AV3	MTH 12-Jun-2002		O/C			
361001 RIGHT	PRECOOL TEMPERATURE SENSOR 9912584-3	*CF		27431501-10 12AU103	MTH 12-Jun-2002		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY LFOQ			9914402-4 S4883T1373	MTH 02-Oct-2015 HRS 2404:30 LDG 2140 ACH 737:30		108 3500	1 0	02-Sep-2024 5904:30	50 m 9 d 3106
361002 RIGHT	B/A PRECOOLER ASSEMBLY LFOQ			9914402-4 S4883T1390	MTH 02-Oct-2015 HRS 2404:30 LDG 2140 ACH 737:30		108 3500	1 0	02-Sep-2024 5904:30	50 m 9 d 3106
361003 LEFT	MODULATING VALVE 9912584-1	*CF		1H139-1 1AV4	MTH 12-Jun-2002		O/C			
361003 RIGHT	MODULATING VALVE 9912584-2	*CF		1H139-2 1AV8	MTH 12-Jun-2002		O/C			
361005	PRESSURE SWITCH	*CF		P18M30 2951	MTH 12-Jun-2002		O/C			
361006 LEFT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 2846	MTH 12-Jun-2002		O/C			
361006 RIGHT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 2864	MTH 12-Jun-2002		O/C			
361007	B/A PRESSURE REGULATOR 9912510-1	*CF		1H75-18 12AV163	MTH 12-Jun-2002		O/C			
521001	CABIN DOOR ASSEMBLY			PN SN-UNKNOWN	MTH 12-Jun-2002		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
522001	INFLATABLE DOOR SEAL	EGGW		9912075-4 N/A	MTH 19-Jun-2013 HRS 2107:18 LDG 1806		O/C	0 0 0		
522002	SECONDARY SEAL	EGSC		R881515 SN-UNKNOWN	MTH 07-Dec-2013 HRS 2224:12 LDG 1985		O/C	0 0 0		
530000	RADOME ASSEMBLY	*CF		6313101-47-1 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
531000 LEFT	TRUNNION SUPPORT FITTING	*CF		5513056-5 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		22500	0	22500	19981
531000 RIGHT	TRUNNION SUPPORT FITTING	*CF		5513056-6 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		22500	0	22500	19981
531001	NOSE LANDING GEAR ACTUATOR FITTING	*CF		6511105-1 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		23900	0	23900	21381
561001 LEFT	WINDSHIELD ASSY, (LH)	*CF		E149000-101 6951	MTH 12-Jun-2002		O/C			
561001 RIGHT	WINDSHIELD ASSY, (LH)	*CF		P00042-2 113	MTH 12-Jun-2002		O/C			
561002 L1	CABIN DOOR WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 L2	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 L3	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 L4	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 L5	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 L6	CABIN DOOR WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R1	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R2	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R3	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R4	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R5	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561002 R6	CABIN DOOR WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
561003 LEFT	PILOT SIDE WINDOW	*CF		6311065-27 0709	MTH 12-Jun-2002		O/C			
561004 RIGHT	CO-PILOT SIDE WINDOW	*CF		6311065-26 0726	MTH 12-Jun-2002		O/C			
571000 LEFT	AFT TRUNNION ATTACH FITTING	*CF		6321070-5 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		20480	0	20480	17961
571000 RIGHT	AFT TRUNNION ATTACH FITTING	*CF		6321070-6 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		20480	0	20480	17961
571001 LEFT	FORWARD TRUNNION ATTACH FITTING	*CF		6321060-5 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		20480	0	20480	17961
571001 RIGHT	FORWARD TRUNNION ATTACH FITTING	*CF		6321060-6 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		20480	0	20480	17961

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
571002 LEFT	SIDE BRACE FITTING	*CF		6321080-1 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		35000	0	35000	32481
571002 RIGHT	SIDE BRACE FITTING	*CF		6321080-2 SN-UNKNOWN	MTH 12-Jun-2002 LDG 0		35000	0	35000	32481
712001 LEFT ENGINE FORWARD BOTTOM	MOUNT ASSEMBLY 9912410-3	*CF		LM601SA5 2789	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
712001 LEFT ENGINE FORWARD TOP	MOUNT ASSEMBLY 9912410-3	*CF		LM601SA5 3021	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
712001 RIGHT ENGINE FORWARD BOTTOM	MOUNT ASSEMBLY 9912410-3	*CF		LM601SA5 2722	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
712001 RIGHT ENGINE FORWARD TOP	MOUNT ASSEMBLY 9912410-3	*CF		LM601SA5 3198	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
712002 LEFT ENGINE AFT	MOUNT ASSEMBLY 9912410-2	*CF		LM601SA4 SN-UNKNOWN	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
712002 RIGHT ENGINE AFT	MOUNT ASSEMBLY 9912410-2	*CF		LM601SA4 SN-UNKNOWN	MTH 12-Jun-2002 HRS 0		5000	0	5000	2201:30
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE FJ44-2C	*CF		60500 126033	MTH 12-Jun-2002					
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE FJ44-2C	KICT		60500 126030	MTH 06-Aug-2014 HRS 2293:06 LDG 2032				E/C 2186:36	
720001 E1	FAN ROTOR	*CF		65502 AU00049	MTH 12-Jun-2002 LDG 0		10000	0	(10000)10000	7481
720001 E2	FAN ROTOR	*CF		65502 AU00024	MTH 12-Jun-2002 LDG 41		10000	0	(10000)10041	7522
720002 E1	IP COMPRESSOR ROTOR	*CF		61968 AU01378	MTH 12-Jun-2002 LDG 0		8000	0	(8000)8000	5481
720002 E2	IP COMPRESSOR ROTOR	*CF		61968 AU01365	MTH 12-Jun-2002 LDG 41		8000	0	(8000)8041	5522
720003 E1	COMPLETE LP SHAFT ASSEMBLY	*CF		64257 RXISN8941	MTH 12-Jun-2002				O/C	
720003 E2	COMPLETE LP SHAFT ASSEMBLY	*CF		64257 RXISN8928	MTH 12-Jun-2002				O/C	
720004 E1	HIGH PRESSURE SHAFT	*CF		64711 AU00600	MTH 12-Jun-2002				O/C	
720004 E2	HIGH PRESSURE SHAFT	*CF		64711 AU00596	MTH 12-Jun-2002				O/C	
720005 E1	HP COMPRESSOR COVER	*CF		65593 AU01706	MTH 12-Jun-2002				O/C	
720005 E2	HP COMPRESSOR COVER	*CF		65593 AU01642	MTH 12-Jun-2002				O/C	
720006 E1	DIFFUSER CASE ASSEMBLY	*CF		67894 AU01430	MTH 12-Jun-2002				O/C	
720006 E2	DIFFUSER CASE ASSEMBLY	*CF		67894 AU01498	MTH 12-Jun-2002				O/C	
720007 E1	1ST LP TURBINE NOZZLE	*CF		60240 AU01391	MTH 12-Jun-2002				O/C	
720007 E2	1ST LP TURBINE NOZZLE			115316 AU02191	MTH 11-Mar-2013 HRS 2104:30 LDG 1892				O/C 1997:24 1716	



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720008 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY	BRE		78823 AU00250	MTH 02-Jan-2013 HRS 1997:18 LDG 1843		O/C	849 694		
720008 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY			68615 WL01314	MTH 11-Mar-2013 HRS 2104:30 LDG 1892		O/C	1997:11 1843		
723037 E1	FAN STATOR VANE ASSEMBLY	BRE		116640 AU01178	MTH 02-Jan-2013 HRS 1997:18 LDG 1843		O/C	1047:18 859		
724036 E1	COMBUSTION COVER ASSEMBLY	BRE		68413 NSN	MTH 02-Jan-2013 HRS 1997:18 LDG 1843		O/C	0 0 0		
724045 E2	SEAL AND FUEL SLINGER ASSEMBLY	UNK		57882 AU21127	MTH 09-Jul-2014 HRS 2293:06 LDG 2032		O/C			
725101 E1	HP COMPRESSOR ROTOR	*CF		61964 HW12178	MTH 12-Jun-2002 LDG 0		6000	0	(6000)6000	3481
725101 E2	HP COMPRESSOR ROTOR	*CF		61964 HW12799	MTH 12-Jun-2002 LDG 41		6000	0	(6000)6041	3522
725102 E1	HP TURBINE ROTOR	*CF		64411 RRL0304	MTH 12-Jun-2002		O/C			
725102 E2	HP TURBINE ROTOR	*CF		74038 RRL0317	MTH 12-Dec-2013		O/C			
725103 E1	HP TURBINE DISK	*CF		59387 RRL7LD12039	MTH 12-Jun-2002 LDG 0		8000	0	(8000)8000	5481
725103 E2	HP TURBINE DISK	*CF		59387 RRL7LD12046	MTH 07-Feb-2014 LDG 2032		8000	1392	(8599)8640	6121
725501 E1	1ST LP TURBINE DISK	*CF		55531 RRL7S01775	MTH 12-Jun-2002 LDG 0		10000	0	(10000)10000	7481
725501 E2	1ST LP TURBINE DISK	*CF		55531 RRL7S01788	MTH 12-Jun-2002 LDG 41		10000	0	(10000)10041	7522
725502 E1	2ND LP TURBINE DISK	*CF		55534 RRL7S01944	MTH 12-Jun-2002 LDG 0		10000	0	(10000)10000	7481
725502 E2	2ND LP TURBINE DISK	*CF		55534 RRL7S01900	MTH 12-Jun-2002 LDG 41		10000	0	(10000)10041	7522
730001 LEFT	FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
730001 RIGHT	FUEL PRESSURE SWITCH 9912033-2	SZR		1103P0448 7644	MTH 17-Apr-2009 HRS 1301		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITER 9912417-1	*CF		1573-4 1239	MTH 12-Jun-2002		O/C			
733001 RIGHT	FUEL FLOW TRANSMITER 9912417-1	*CF		1573-4 1246	MTH 12-Jun-2002		O/C			
730002 E1	FUEL NOZZLE ASSEMBLY	SZR		50817 BCC1BBP0463	MTH 23-Jun-2009 HRS 1350		O/C	0		
730002 E2	FUEL NOZZLE ASSEMBLY	LEVC		50817 SN-UNKNOWN	MTH 05-Jun-2013 HRS 2113:48 LDG 1858		O/C	0 0 0		
730003 E1	SEAL AND FUEL SLINGER	BRE		55608 AU21130	MTH 02-Jan-2013 HRS 1997:18 LDG 1843		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
730003 E2	SEAL AND FUEL SLINGER *CF			55608 AU02632	MTH 12-Jun-2002		O/C			
731046 E1	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 12-Jun-2002		O/C	0		
731046 E2	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 12-Jun-2002		O/C	0		
732101 E1	INTEGRATED FUEL CONTROL UNIT *CF			66313 RF13207980	MTH 12-Jun-2002 HRS 0		4000	0	(4000)4000	1201:30
732101 E2	INTEGRATED FUEL CONTROL UNIT UNK			115003 RF13444119	MTH 09-Jul-2014 HRS 2293:06 LDG 2032		4000	0	(6186:36)6293:06	3494:36
732301 E1	FUEL FILTER ELECTRICAL INDICATOR BRE			57847 GE0795	MTH 02-Jan-2013 HRS 1997:18 LDG 1843		O/C			
732301 E2	FUEL FILTER ELECTRICAL INDICATOR HUR			57847 SN-UNKNOWN	MTH 12-Jan-2006 HRS 705:30		O/C	0		
741001 E1 INBOARD	IGNITION EXCITER *CF			CH92007 CK0200071	MTH 12-Jun-2002		O/C			
741001 E1 OUTBOARD	IGNITION EXCITER *CF			CH92007 CK0200110	MTH 12-Jun-2002		O/C			
741001 E2 INBOARD	IGNITION EXCITER SZR			CH92007-1 CK0300506	MTH 15-Sep-2008 HRS 1301:30		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER *CF			CH92007 CK0200011	MTH 12-Jun-2002		O/C			
741002 E1	SHORT IGNITER LEAD *CF			53279 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
741002 E2	SHORT IGNITER LEAD SZR			53279 SN-UNKNOWN	MTH 23-Jun-2009 HRS 1456:30		O/C	0		
741003 E1	LONG IGNITER LEAD LSZR			53221 UKN	MTH 25-Mar-2010 HRS 1501 LDG 1497		O/C	0	0	
741003 E2	LONG IGNITER LEAD *CF			53221 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
741004 E1 INBOARD	IGNITOR KICT			68032 CK-1400976	MTH 07-Oct-2014 HRS 2301:42 LDG 2040		O/C	0	0	
741004 E1 OUTBOARD	IGNITOR LSZR			CH31956 CK0900018	MTH 25-Mar-2010 HRS 1501 LDG 1497		O/C	0	0	
741004 E2 INBOARD	IGNITOR EGCN			CH31956 10029941	MTH 26-Nov-2010 HRS 1687:30 LDG 1609		O/C	0	0	
741004 E2 OUTBOARD	IGNITOR SZR			CH31956 CK0800604	MTH 23-Jun-2009 HRS 1456:30		O/C	0		
761001	ENGINE SYNC CONTROLLER EGCN			213693 12286240	MTH 11-Jun-2014 HRS 2260:30 LDG 2018		O/C	37	0	



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
761002	ENGINE SYNC ACTUATOR	EGKB		5485-066 SN00051	MTH 04-Mar-2013 HRS 2010:12 LDG 1851		O/C	0 0 0		
772001 LEFT NO. 1	ITT PROBE	*CF		62141 YYF006834	MTH 12-Jun-2002		O/C			
772001 LEFT NO. 2	ITT PROBE	*CF		62141 YYF006835	MTH 12-Jun-2002		O/C			
772001 LEFT NO. 3	ITT PROBE	*CF		62141 YYF006836	MTH 12-Jun-2002		O/C			
772001 LEFT NO. 4	ITT PROBE	*CF		62141 YYF006837	MTH 12-Jun-2002		O/C			
772001 LEFT NO. 5	ITT PROBE	*CF		62141 YYF006838	MTH 12-Jun-2002		O/C			
772001 LEFT NO. 6	ITT PROBE	*CF		62141 YYF006839	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 1 <i>772001 : E2-1</i>	ITT PROBE	*CF		62141 YYF006858	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 2 <i>772001 : E2-2</i>	ITT PROBE	*CF		62141 YYF006866	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 3 <i>772001 : E2-3</i>	ITT PROBE	*CF		62141 YYF006867	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 4 <i>772001 : E2-4</i>	ITT PROBE	*CF		62141 YYF006883	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 5 <i>772001 : E2-5</i>	ITT PROBE	*CF		62141 YYF006884	MTH 12-Jun-2002		O/C			
772002 RIGHT NO. 6 <i>772001 : E2-6</i>	ITT PROBE	*CF		62141 YYF006885	MTH 12-Jun-2002		O/C			
774001	N1 STANDBY INDICATOR	LFOQ		10645N01R02 0375A	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		O/C	3 0		
774002 LEFT AFT <i>774002A : L</i>	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
774002 LEFT FORWARD	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
774002 RIGHT AFT <i>774002A : R</i>	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
774002 RIGHT FORWARD	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
774003	N1 COMPUTER	*CF	A	C-13232-1 569	MTH 12-Jun-2002		O/C			
771001 E1	N1 SPEED PICKUP	*CF		50867 YYV1086	MTH 12-Jun-2002		O/C			
771001 E2	N1 SPEED PICKUP	*CF		50867 YYV1094	MTH 12-Jun-2002		O/C			
771002 E1	N2 SPEED PICKUP	*CF		50866 YYV969	MTH 12-Jun-2002		O/C			
771002 E2	N2 SPEED PICKUP	*CF		50866 YYV985	MTH 12-Jun-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
783000 LEFT	T/R DEPLOY SWITCH *CF			602EN602-6 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
783000 RIGHT	T/R DEPLOY SWITCH *CF			602EN602-6 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
783001 LEFT	T/R STOW SWITCH *CF			602EN602-6 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
783001 RIGHT	T/R STOW SWITCH *CF			602EN602-6 SN-UNKNOWN	MTH 12-Jun-2002		O/C			
783003 LEFT	ATTENUATOR ACTUATOR *CF			6317105-13 00453	MTH 12-Jun-2002		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR *CF			6317105-13 00447	MTH 12-Jun-2002		O/C			
793002 LEFT ENGINE	OIL PRESSURE SWITCH 9912178-4 *CF			S1103P89-3 1325	MTH 12-Jun-2002		O/C			
793002 RIGHT ENGINE	OIL PRESSURE SWITCH 9912178-4 *CF			S1103P89-3 1334	MTH 12-Jun-2002		O/C			
793003 LEFT ENGINE	OIL PRESSURE TRANSMITTER *CF			APTE-304-200G 6671985	MTH 12-Jun-2002		O/C			
793003 RIGHT ENGINE	OIL PRESSURE TRANSMITTER *CF			APTE-304-200G 66719100	MTH 12-Jun-2002		O/C			
792201 E1	LUBE OIL COOLER *CF			59857 FC0276	MTH 12-Jun-2002		O/C			
792201 E2	LUBE OIL COOLER			110718 PP1144	MTH 11-Mar-2013 HRS 2104:30 LDG 1892		O/C	0		
792401 E1	LUBE AND SCAVENGE PUMP *CF			63123 WL01332	MTH 12-Jun-2002 HRS 0		4000	0	(4000)4000	1201:30
792401 E2	LUBE AND SCAVENGE PUMP			110487 WL20377	MTH 11-Mar-2013 HRS 2104:30 LDG 1892		4000	892 852	(5106)5212:30	2414
801101 LEFT ENGINE	STARTER GENERATOR 9912125-2			300SGL129Q 4333XL2	MTH 23-May-2018 HRS 2662:20 LDG 2389		1000	0	3662:20	863:50
801101 RIGHT ENGINE	STARTER GENERATOR 9912125-2			300SGL129Q 2786XL2	MTH 01-Apr-2016 HRS 2442:45 LDG 2179		1000	3 0 0	3442:45	644:15



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525A-99-01 R04	CESCOM PRICES (THIS SL CANCELS SL525A-99-01 R3 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525A-99-03	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525A-99-04	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525A-03-01 R01	SUPPLEMENTAL TYPE CERTIFICATION (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL 525A-99-06	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525A-05-02	PRECOOLER LIFE LIMIT	LFOQ		INFORMATIONAL	MTH 02-Oct-2015 HRS 2404:30 LDG 2140		-			Complete
	MOC :									
SL 525A-05-03 R01	TIME LIMITS/MAINTENANCE CHECKS - NEW CABIN DOOR ASSEMBLY HINGE PIN REPLACEMENT INTERVAL IMPLEMENTATION GRACE PERIOD			CANCELLED			-			
	MOC :									
SL 525A-05-03	TIME LIMITS/MAINTENANCE CHECKS - NEW CABIN DOOR ASSEMBLY HINGE PIN REPLACEMENT INTERVAL IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
MOC :										
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
MOC :										
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
SL WI-05-1016 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1016 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SB 525A-11-02 <i>11SB-02</i>	ENGINE OIL QUANTITY PLACARD REPLACEMENT			MTH 02-Mar-2004 HRS 298			-			Complete
MOC : COMPLIED WITH										
SB 525A-11-04 <i>11SB-04</i>	GEAR EXTEND SPEED REDUCTION			MANDATORY MTH 16-Oct-2006 HRS 782			A/R			Complete
MOC : COMPLIED WITH										
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 525A-20-01 R09	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 525A-20-03	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 525A-21-05 21SB-05	TEMPERATURE SENSOR RELOCATION	SZR		OPTIONAL	MTH 10-Aug-2009 HRS 1376		A/R			Complete
	MOC :			COMPLIED WITH						
SB 525A-21-06	AIR CONDITIONING - AFT EVAPORATOR DRAIN HOSE IMPROVEMENT			DISCRETIONARY			A/R			
	MOC :									
SB 525A-21-08	AIR CONDITIONING - MAX COOL RELAY INSTALLATION			MTH 06-Aug-2013 MANDATORY			-			N/A
	MOC :			NOT APPLICABLE - N/A BY TYPE INSTALLED						
SL 525A-21-03	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 525A-23-03 23SB-03	GARMIN RADIO MODIFICATION	HUR		RECOMMENDED	MTH 02-Mar-2004 HRS 298		-			Complete
	MOC :			COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED						
SB 525A-23-04 23SB-04	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE	HUR		RECOMMENDED	MTH 02-Mar-2004 HRS 298		-			Complete
	MOC :			COMPLIED WITH						
SB 525A-23-05 23SB-05	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SB 525A-23-07 23SB-07	GARMIN GTX330/330D TRANSPONDER SOFTWARE VERSION 3.03 UPGRADE	HUR		MANDATORY	MTH 14-Jan-2005 HRS 424		-			N/A
	MOC :			NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED						
SL 525A-23-01 R01 23SL-01 : 525A1	TRANSMITTAL OF GARMIN SERVICE BULLETIN 0218, NEW SOFTWARE VERSION 3.00 (MAIN) FOR 400/500 SERIES UNITS AND 3.00(GPS) FOR 400/500 SERIES UNITS			OPTIONAL	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-23-02	COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA			INFORMATIONAL			-			
	MOC :									
SB 525A-24-02 24SB-02	AFT CABIN WIRE BUNDLE PROTECTION	HUR		RECOMMENDED	MTH 22-Jul-2005 HRS 499		-			Complete
	MOC : COMPLIED WITH									
SB 525A-24-03 24SB-03	AVIONICS EMERGENCY BUS RELAY IMPROVEMENT	EGCN		DISCRETIONARY	MTH 20-Jul-2011 HRS 1702 LDG 1645		A/R			Complete
	MOC : COMPLIED WITH									
SB 525A-24-06	GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING	EGSC		MANDATORY	MTH 07-Dec-2013 HRS 2224:12 LDG 1985		-			Complete
	MOC : COMPLIED WITH - CARRIED OUT									
SL 525A-24-02 24SL-02	WIRE BUNDLE INSPECTION	SZR		RECOMMENDED	MTH 10-Aug-2009 HRS 1376		A/R			Complete
	MOC : COMPLIED WITH									
SB 525A-25-03 25SB-03	EMERGENCY LOCATOR TRANSMITTER (ELT) WIRING MODIFICATION	EGCN		OPTIONAL	MTH 20-Jul-2011 HRS 1702 LDG 1645		-			Complete
	MOC : COMPLIED WITH - SB525A-25-03 C/O SATIS.									
SB 525A-25-04 R01	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB 525A-25-04 25SB-04	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525A-25-05 R01 25SB-05 : 525A1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SB 525A-25-06 25SB-06	AFT CABIN INSULATION MODIFICATION			OPTIONAL	MTH		-			
	MOC :									
SB 525A-25-07 25SB-07	AIRCELL ANTENA INSTALLATION IMPROVEMENT			OPTIONAL	MTH		-			
	MOC :									
SB 525A-25-08 25SB-08	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION			OPTIONAL			-			
	MOC :									
SL 525A-25-01 25SL-01	TRANSMITIAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	SZR		MANDATORY	MTH 15-Sep-2008 HRS 1195		A/R			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE BY TYPE MANUFACTURER									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-25-02 25SL-02	INSPECTION OF THE BACKREST LATCH PLATES	SZR		MANDATORY	MTH 07-May-2010 HRS 1524 LDG 1514		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-25-04	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION OPTIONAL						-			
MOC :										
SB 525A-26-02 26SB-02	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION	HUR		MANDATORY	MTH 22-Jul-2005 HRS 499		-			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	LFOQ		MANDATORY	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		-			Complete
MOC : COMPLIED WITH										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
MOC :										
SB 525A-27-01 R02	STEEP APPROACH CERTIFICATION			OPTIONAL			A/R			
MOC :										
SB 525A-27-01 R03	STEEP APPROACH CERTIFICATION			OPTIONAL			-			
MOC :										
SB 525A-27-03 R01 27SB-03 : 525A1	FLAP OVERRIDE SWITCH INSTALLATION	HUR		RECOMMENDED	MTH 02-Mar-2004 HRS 298		-			Complete
MOC : COMPLIED WITH										
SB 525A-27-04 27SB-04	AILERON CABLE AND FAIRLEAD TUBE REPLACEMENT	SZR		RECOMMENDED	MTH 11-Aug-2009 HRS 1376		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-27-07 27SB-07	ELEVATOR TRIM POINTER IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525A-27-08 27SB-08	RUDDER BIAS SIMPLIFICATION			OPTIONAL	MTH		A/R			
MOC :										
SB 525A-27-09 27SB-09	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT	EGCN		OPTIONAL	MTH 20-Jul-2011 HRS 1702 LDG 1645		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-27-10 27SB-10	INSPECTION OF TAILCONE WIRE BUNDLE	EGCN		RECOMMENDED	MTH 20-Jul-2011 HRS 1702 LDG 1645		36 1200			Complete
MOC : COMPLIED WITH										
SB 525A-27-13 R01	VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION			MANDATORY	MTH		A/R			Complete
MOC : COMPLIED WITH - BY COMPLIANCE WITH SB INITIAL ISSUE										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525A-27-13	FLIGHT CONTROLS - VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	EGCN	MANDATORY	MTH 20-Jul-2011 HRS 1702 LDG 1645		A/R			Complete
MOC : COMPLIED WITH									
SL 525A-27-03 27SL-03	RUDDER BIAS PNEUMATIC LINE CLAMP INSPECTION	HUR	RECOMMENDED	MTH 22-Jul-2005 HRS 499		-			Complete
MOC : COMPLIED WITH									
SL 525A-27-05 R01 27SL-05 : 525A1	FLAP PUSHROD SAFETY WIRE INSPECTION	SZR	RECOMMENDED	MTH 26-Jan-2009 HRS 1260		A/R			Complete
MOC : COMPLIED WITH									
SL 525A-27-07	FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT OPTIONAL					-			
MOC :									
SB 525A-28-02 28SB-02	FUEL BOOST PUMP ANNUNCIATION IMPROVEMENT		DISCRETIONARY	MTH		-			
MOC :									
SB 525A-28-03 28SB-03	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	HUR	MANDATORY	MTH 04-Feb-2005 HRS 430		-			Complete
MOC : COMPLIED WITH									
SB 525A-28-04 28SB-04	FIREWALL SHUTOFF VALVE REPLACEMENT AND FIREWALL SHUTOFF VALVE BRACKET MODIFICATION		OPTIONAL	MTH		A/R			
MOC :									
SL 525A-28-02 28SL-02	FUEL LINE CLEARANCE IMPROVEMENT	SZR	MANDATORY	MTH 16-Mar-2009 HRS 1267		A/R			Complete
MOC : COMPLIED WITH									
SB 525A-29-04 R02 29SB-04 : 525R2	HYDRAULIC RELIEF VALVE INLET NUT INSPECTION/REPLACEMENT		CANCELLED			A/R			
MOC :									
SB 525A-29-06 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	EDDW	MANDATORY	MTH 19-Feb-2013 HRS 1997:18 LDG 1843		A/R			Complete
MOC : COMPLIED WITH									
SB 525A-29-07	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION OPTIONAL					A/R			
MOC :									
SL 525A-29-03	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION	LFOQ	RECOMMENDED	MTH 06-May-2020 HRS 2798:30 LDG 2519		-			Complete
MOC : COMPLIED WITH - BOTH SIDES INSPECTED AND FOUND COMPLIANT									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES INFORMATIONAL					-			
MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL					-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-31-01 <i>31SL-01</i>	TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 12 REVISION 2, AFD-3010 ADAPTIVE FLIGHT DISPLAY	HUR	MANDATORY	MTH 06-Jan-2003 HRS 100		-			Complete
MOC : COMPLIED WITH									
SB 525A-32-07 <i>32SB-07</i>	BEARING REPLACEMENT	HUR	MANDATORY	MTH 08-Aug-2005 HRS 503		-			Complete
MOC : COMPLIED WITH									
SB 525A-32-10 <i>32SB-10</i>	MAIN LANDING GEAR ACTUATOR EXTEND HOSE IMPROVEMENT	SZR	RECOMMENDED	MTH 26-Jan-2009 HRS 1260		A/R			Complete
MOC : COMPLIED WITH									
SB 525A-32-11 <i>32SB-11</i>	BRAKE HYDRAULIC AND PNEUMATIC TUBE IMPROVEMENT	SZR	MANDATORY	MTH 23-Jan-2007 HRS 827		A/R			Complete
MOC : COMPLIED WITH									
SB 525A-32-12 <i>32SB-12</i>	IMPROVEMENT TO THE PUSHROD ASSEMBLY ON THE MAIN LANDING GEAR DOOR	SZR	MANDATORY	MTH 03-Dec-2007 HRS 1025		A/R			Complete
MOC : COMPLIED WITH									
ASL 525A-32-11 R01 <i>32SLA11 : 525A1</i>	MAIN LANDING GEAR DOOR PUSHROD INSPECTION	SZR	MANDATORY	MTH 23-Jan-2007 HRS 827		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL		INFORMATIONAL			-			
MOC :									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION		RECOMMENDED	MTH 30-Jan-2015 HRS 2325:45 LDG 2060		-			Complete
MOC : COMPLIED WITH - CHECKED AND INSTALLATION FOUND COMPLIANT									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION		INFORMATIONAL			-			
MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION		INFORMATIONAL			-			
MOC :									
SL 525A-32-03 <i>32SL-03</i>	HYDRAULIC TUBE INSPECTION	ICT	RECOMMENDED	MTH 12-Jun-2002 HRS 12		-			Complete
MOC : COMPLIED WITH									
SL 525A-32-07 <i>32SL-07</i>	BRAKE SUPPLY LINE FILTER INSPECTION	SZR	RECOMMENDED	MTH 23-Jan-2007 HRS 827		A/R			Complete
MOC : COMPLIED WITH									
SL 525A-32-08 R01 <i>32SL-08 : 525A1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION		OPTIONAL	MTH		-			
MOC :									
SL 525A-32-09	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1601-32-2 LANDING GEAR - MAIN WHEEL - P/N 3-1601-2 - CESSNA CJ2 - INTRODUCTION OF NEW SIDE RIM		INFORMATIONAL			A/R			Complete
MOC : COMPLIED WITH - PARTIALLY AT COMPL. RIGHT SIDE ONLY									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-32-12 32SL-12	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	SZR		RECOMMENDED	MTH 02-May-2008 HRS 1111		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-32-13 R01 32SL-13 : 525A1	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	SZR		RECOMMENDED	MTH 10-Aug-2009 HRS 1376		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-32-14 R01 32SL-14 : 525A1	AUXILIARY BRAKE TUBE INSPECTION	EGCN		RECOMMENDED	MTH 20-Jul-2011 HRS 1702 LDG 1645		300			Complete
MOC : COMPLIED WITH										
SL 525A-32-15	TRANSMITTAL OF GOODRICH SERVICE LETTER SL2060, LANDING GEAR - MAIN WHEEL ASSEMBLY - INTRODUCTION OF AN IMPROVED OPTIONAL THERMAL RELIEF PLUG ASSEMBLY			INFORMATIONAL			A/R			Complete
MOC : COMPLIED WITH - PARTIALLY AT COMPL. RIGHT SIDE ONLY										
SL 525A-32-17 R02 32SL-17 : 525A1	EMERGENCY GEAR RELEASE INSPECTION	EGCN		MANDATORY	MTH 20-Jul-2011 HRS 1702 LDG 1645		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-32-18	LANDING GEAR- TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1651-32-2, LANDING GEAR- BRAKE ASSEMBLY- REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS	EGKB		MANDATORY	MTH 29-Nov-2012 HRS 1953:54 LDG 1814		-			Complete
MOC : COMPLIED WITH										
SB 525A-33-02 33SB-02	WING TIP ANTICOLLISION LIGHT MODIFICATION	HUR		RECOMMENDED	MTH 22-Jul-2005 HRS 499		-			Complete
MOC : COMPLIED WITH										
SB 525A-33-03 33SB-03	CHART LIGHT MODIFICATION			OPTIONAL	MTH		-			
MOC :										
SB 525A-33-06	LIGHTS - WING TIP LED LIGHT MODIFICATION			OPTIONAL			-			
MOC :										
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
MOC :										
SB 525A-34-01 34SB-01	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	ICT		OPTIONAL	MTH 13-Jun-2002 HRS 12		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT FACTORY OR IS A FACTORY OPTION.										
SB 525A-34-04 34SB-04	FLIGHT GUIDANCE COMPUTER VOR IMPROVEMENT	HUR		RECOMMENDED	MTH 02-Mar-2004 HRS 298		-			Complete
MOC : COMPLIED WITH										
SB 525A-34-09 34SB-09	ATTITUDE INDICATOR AND HORIZONTAL SITUATION INDICATOR MODIFICATION	HUR		RECOMMENDED	MTH 08-Aug-2005 HRS 503		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525A-34-11 R01 <i>34SB-11 : 525R1</i>	RADIO ALTIMETER CONVERTER UPGRADE				MTH		A/R			
	DISCRETIONARY									
	MOC :									
SB 525A-34-14 <i>34SB-14</i>	GARMIN GNS-530A RADIOS/FMS & GTX-330D TRANSPONDER INSTALLATION	ZRH		OPTIONAL	MTH 22-Jan-2007 HRS 827		-			Complete
	MOC : COMPLIED WITH									
SB 525A-34-15 <i>34SB-15</i>	MST-67A DIVERSITY TRANSPONDER INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SB 525A-34-16 <i>34SB-16</i>	GARMIN GTX-330D TRANSPONDER INSTALLATION UPGRADE			OPTIONAL	MTH		A/R			
	MOC :									
SB 525A-34-17 <i>34SB-17</i>	GARMIN GTX-330(D) TRANSPONDER SOFTWARE UPGRADE TO 4.01	SZR		OPTIONAL	MTH 03-Aug-2007 HRS 941		A/R			Complete
	MOC : COMPLIED WITH									
SB 525A-34-18 <i>34SB-18</i>	UNIVERSAL UNS-1K SOFTWARE UPGRADE TO 604.7			OPTIONAL	MTH		A/R			
	MOC :									
SB 525A-34-19 R01 <i>34SB-19 : 525A1</i>	TERRAIN AWARENESS WARNING SYSTEM (TAWS) UPGRADE TO SOFTWARE LEVEL 1.13			OPTIONAL	MTH		A/R			
	MOC :									
SB 525A-34-20 R01 <i>34SB-20 : 525A1</i>	FILE SERVER INSTALLATION AND MULTIFUNCTION DISPLAY (MFD) UPDATE FOR CHARTS AND XM SATELLITE WEATHER	ZRH		OPTIONAL	MTH 22-Jan-2007 HRS 827		A/R			Complete
	MOC : COMPLIED WITH									
SB 525A-34-36 R03	NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES			OPTIONAL			-			
	MOC :									
SB 525A-34-38	NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) SOFTWARE 7.1 UPGRADE			OPTIONAL	MTH 06-Aug-2013		-			N/A
	MOC : NOT APPLICABLE - N/A BY S/N									
SB 525A-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SB 525A-34-41 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525A-34-41	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525A-34-42	NAVIGATION - ADS-B OUT WIRING MODIFICATION			MANDATORY	MTH		-			
	MOC :									
SB CIB-34-04	ROCKWELL COLLINS ADAPTIVE FLIGHT DISPLAY UPGRADE			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-34-02 R01 <i>34SL-02 : 525A1</i>	GNS-XLS FMS MOD 7 SOFTWARE UPGRADE	HUR		RECOMMENDED	MTH 28-Oct-2002 HRS 86		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SL 525A-34-14	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION			INFORMATIONAL			-			
MOC :										
SL CIL-35-01	TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01	EGCN		MANDATORY	MTH 29-May-2014 HRS 2260:30 LDG 2018		-			N/A
MOC : NOT APPLICABLE - DUE TO DIFFERENT SMOKE GOGGLES FITTED										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001			MANDATORY	DAYS 10-Feb-2017		-			N/A
MOC : NOT APPLICABLE - BECAUSE THE P/N FITTED ARE NOT CONCERNED										
SL 525A-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	EDDW		MANDATORY	MTH 19-Feb-2013 HRS 1997:18 LDG 1843		-			Complete
MOC : COMPLIED WITH - SL525-35-02R2 COMPLIED WITH IN ACCORDANCE WITH EASA AD 2011-0090R1										
SB 525A-36-04	PNEUMATIC - MOISTURE TRAP INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525A-38-01 <i>38SB-01</i>	PILOT'S RELIEF TUBE IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525A-52-03 R01 <i>52SB-03 : 525R1</i>	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION			OPTIONAL			A/R			
MOC :										
ASL 525A-52-01 <i>52SLA01</i>	EMERGENCY DOOR INSPECTION			MANDATORY	MTH 07-Jan-2008 HRS 1046		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	EGSC		MANDATORY	MTH 07-Dec-2013 HRS 2224:12 LDG 1985		-			Complete
MOC : COMPLIED WITH - CARRIED OUT										
SB 525A-53-01 <i>53SB-01</i>	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	SZR		MANDATORY	MTH 20-Aug-2007 HRS 954		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
ASL 525A-53-04 <i>53SLA04</i>	RELIEF TUBE CORROSION	SZR		MANDATORY	MTH 23-Jan-2007 HRS 827		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 525A-53-09 <i>53SL-09</i>	INTERCOSTAL DRAINAGE PATH INSPECTION	LSZR		RECOMMENDED	MTH 25-Mar-2010 HRS 1501 LDG 1497		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525A-53-10	UPPER TAILCONE SKIN INSPECTION EGCN			MANDATORY	MTH 26-Nov-2010 HRS 1581 LDG 1568		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-54-01 R01	FIREWALL BOX	LFOQ		RECOMMENDED	MTH 04-Oct-2019 HRS 2772:45 LDG 2496		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ON R/H SIDE PYLON DUE TO A CRACK ON SKNI DISCOVERED AT INSP DOC 18										
SB 525A-54-01 54SB-01	FIREWALL BOX REPAIR			RECOMMENDED			-			
MOC :										
SB 525A-57-01 57SB-01	CENTER WING NOISE REDUCTION IMPROVEMENT			DISCRETIONARY	MTH		-			
MOC :										
SL 525A-57-01 57SL-01	ACCESS DOOR DRAINAGE IMPROVEMENT SZR			RECOMMENDED	MTH 23-Jan-2007 HRS 827		-			Complete
MOC : COMPLIED WITH										
SB 525A-71-02 R01 71SB-02 : 525A1	UPPER ENGINE COWL SUPPORT MODIFICATION			OPTIONAL	MTH		-			
MOC :										
SL CIL-71-02 LEFT ENGINE	TRANSMITTAL OF WILLIAMS INTERNATIONAL FJ44 SERVICE BULLETIN FJ44-72-128, ENGINE - SPLIT INNER RING BALL BEARING - REPLACE			MANDATORY	MTH		-			
MOC :										
SL CIL-71-02 RIGHT ENGINE	TRANSMITTAL OF WILLIAMS INTERNATIONAL FJ44 SERVICE BULLETIN FJ44-72-128,ENGINE - SPLIT INNER RING BALL BEARING - REPLACE			MANDATORY	MTH		-			
MOC :										
SL 525A-71-03 R01	POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT			MANDATORY			-			
MOC :										
SL 525A-71-03 R02	POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT			MANDATORY			-			
MOC :										
SL 525A-71-03	POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT			MANDATORY			-			
MOC :										
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-71-002 R02 E1	ENGINE - HP COMPRESSOR - BORESCOPE INSPECTION			MANDATORY			-			N/A
	MOC : NOT APPLICABLE - ENGINE SERIAL NO. NOT AFFECTED									
SB FJ44-71-002 R02 E2	ENGINE - HP COMPRESSOR - BORESCOPE INSPECTION			MANDATORY			-			N/A
	MOC : NOT APPLICABLE - ENGINE SERIAL NO. NOT AFFECTED									
SB FJ44-72-022 R02 E1	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
	MOC :									
SB FJ44-72-022 R02 E2	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
	MOC :									
SB FJ44-72-042 R06 E1	INSTALL REAR MOUNT SLEEVE			OPTIONAL			A/R			
	MOC :									
SB FJ44-72-042 R06 E2	INSTALL REAR MOUNT SLEEVE			OPTIONAL			A/R			
	MOC :									
SB FJ44-72-051 R03 E1	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R03 E2	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R04 E1	REWORK NAMEPLATE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R04 E2	REWORK NAMEPLATE			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-054 R04 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R04 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R05 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R05 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED	MTH 11-Mar-2013 HRS 2104:30 LDG 1892		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-054 R06 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED	HRS		-		(3997)3997	1198:30
MOC :										
SB FJ44-72-054 R06 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
MOC :										
SB FJ44-72-062 R03 E1	ENGINE - GEARBOX - INSPECTION			MANDATORY	MTH 13-Sep-2019		-			N/A
MOC : NOT APPLICABLE										
SB FJ44-72-062 R03 E2	ENGINE - GEARBOX - INSPECTION			MANDATORY	MTH 13-Sep-2019		-			N/A
MOC : NOT APPLICABLE										
SB FJ44-72-064 R02 E1	CANCELLED - ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REWORK OR REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-064 R02 E2	CANCELLED - ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REWORK OR REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-066 R03 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-72-066 R03 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-72-066 R06 E1	CARBON RING SEAL AND BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-066 R06 E2	CARBON RING SEAL AND BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-068 R03 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-068 R03 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-068 R04 E1	CANCELLED - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY SB FJ44-72-104 R01)			CANCELLED			-			
MOC :										
SB FJ44-72-068 R04 E2	CANCELLED - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY SB FJ44-72-104 R01)			CANCELLED			-			
MOC :										
SB FJ44-72-075 R01 E1	ENGINE - GEARBOX P/N 78823 - INSPECTION			MANDATORY	MTH 13-Sep-2019		-			N/A
MOC : NOT APPLICABLE										
SB FJ44-72-075 R01 E2	ENGINE - GEARBOX P/N 78823 - INSPECTION			MANDATORY	MTH 13-Sep-2019		-			N/A
MOC : NOT APPLICABLE										
SB FJ44-72-077 R02 E1	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R02 E2	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R03 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R03 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R04 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL	MTH HRS		DUE DUE DUE		(4000)4000	1201:30
MOC :										
SB FJ44-72-077 R04 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL	MTH HRS		DUE DUE DUE		(4000)4106:30	1308
MOC :										
SB FJ44-72-079 R02 E1	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
MOC :										
SB FJ44-72-079 R02 E2	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-085 R05 E1	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED	HRS		DUE DUE		(4000)4000	1201:30
MOC :										
SB FJ44-72-085 R05 E2	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED	HRS		DUE DUE		(4000)4106:30	1308
MOC :										
SB FJ44-72-085 R06 E1	IP BLEED VALVE - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4000	1201:30
MOC :										
SB FJ44-72-085 R06 E2	IP BLEED VALVE - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4106:30	1308
MOC :										
SB FJ44-72-086 R03 E1	ENGINE ¿ BLEED VALVE SHAFT ¿ REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R03 E2	ENGINE ¿ BLEED VALVE SHAFT ¿ REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-104 R01 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R02)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R01 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R02)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R02 E1	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R02 E2	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R04 E1	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R04 E2	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-104 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R02 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-105 R02 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R04 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R04 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-106 R01 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-106 R01 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-106 E1	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-106 R01)			RECOMMENDED	MTH 12-Feb-2015		-			N/A
MOC : NOT APPLICABLE - BY ENGINE S/N										
SB FJ44-72-106 E2	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-106 R01)			RECOMMENDED	MTH 12-Feb-2015		-			N/A
MOC : NOT APPLICABLE - BY ENGINE S/N										
SB FJ44-72-107 R01 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R02)			RECOMMENDED	HRS			DUE DUE	(4000)4000	1201:30
MOC :										
SB FJ44-72-107 R02 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-107 R02 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-107 R03 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED	MTH HRS			CSI CSI CSI	(4000)4000	1201:30
MOC :										
SB FJ44-72-107 R03 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-107 E1	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		(4000)4000	1201:30
MOC :										
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		(4000)4106:30	1308
MOC :										
SB FJ44-72-119 E1	HP COMPRESSOR ROTOR - REWORK			RECOMMENDED	MTH HRS		DUE DUE DUE		(3997:18)3997:18	1198:48
MOC :										
SB FJ44-72-119 E2	HP COMPRESSOR ROTOR - REWORK			RECOMMENDED	MTH HRS		DUE DUE DUE		(3998)4104:30	1306
MOC :										
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-126 E1	HP SHAFT - REPLACE			MANDATORY	MTH 12-Feb-2015		-			N/A
MOC : NOT APPLICABLE - BY ENGINE S/N										
SB FJ44-72-126 E2	HP SHAFT - REPLACE			MANDATORY	MTH 12-Feb-2015		-			N/A
MOC : NOT APPLICABLE - BY ENGINE S/N										
SB FJ44-72-129 R01 E1	INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			MANDATORY	MTH 15-Feb-2019		-			N/A
MOC : NOT APPLICABLE - ENGINE S/N NOT AFFECTED										
SB FJ44-72-129 R01 E2	INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			MANDATORY			-			N/A
MOC : NOT APPLICABLE - ENGINE SERIAL NOT AFFECTED										
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-134 E1	1ST LP TURBINE NOZZLE HEATSHIELD HOUSING ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(3997:18)3997:18	1198:48
MOC :										
SB FJ44-72-134 E2	1ST LP TURBINE NOZZLE HEATSHIELD HOUSING ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			N/A			N/A
MOC : NOT APPLICABLE - ENGINE SERIAL NO. NOT AFFECTED										
SB FJ44-72-140 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			N/A			N/A
MOC : NOT APPLICABLE - ENGINE SERIAL NO. NOT AFFECTED										
SB FJ44-72-142 R01 E1	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	2201:30
MOC :										
SB FJ44-72-142 R01 E2	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED			-			N/A
MOC : NOT APPLICABLE - ENGINE SERIAL NOT AFFECTED										
SB FJ44-72-142 E2	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-143 R01 E1	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-143 R01 E2	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-143 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-143 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-147 E1	DIFFUSER CASE ASSEMBLY - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-147 E2	DIFFUSER CASE ASSEMBLY - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 R01 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE						-			N/A
	MOC :			NOT APPLICABLE - ENGINE SERIAL NO NOT AFFECTED						
SB FJ44-72-149 R01 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE						-			N/A
	MOC :			NOT APPLICABLE - ENGINE SERIAL NO NOT AFFECTED						
SB FJ44-72-149 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R01 E1	LP REAR BEARING SEAL RETAINER - REPLACE			SUPERSEDED			-			
	MOC :									
SB FJ44-72-150 R01 E2	LP REAR BEARING SEAL RETAINER - REPLACE			SUPERSEDED			-			
	MOC :									
SB FJ44-72-150 R02 E1	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R02 E2	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R03 E1	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			N/A
	MOC :			NOT APPLICABLE - ENGINE SERIAL NO. NOT AFFECTED						
SB FJ44-72-150 R03 E2	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			N/A
	MOC :			NOT APPLICABLE - ENGINE SERIAL NO NOT AFFECTED						
SB FJ44-72-150 E1	LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 E2	LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01)			RECOMMENDED			-			
	MOC :									
SB WI-72-1032 R01 E1	HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY			-			
	MOC :									
SB WI-72-1032 R01 E2	HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-72-1032 E1	R02 HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY			-			
	MOC :									
SB WI-72-1032 E2	R02 HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY			-			
	MOC :									
SB WI-72-1032 E1	HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY	MTH 25-Mar-2020		-			N/A
	MOC :									
SB WI-72-1032 E2	HIGH PRESSURE TURBINE DISK - REPLACE			MANDATORY	MTH 25-Mar-2020		-			N/A
	MOC :									
SB WI-72-1033 E1	HP TURBINE ROTOR BLADES - INSPECTION			RECOMMENDED			-			N/A
	MOC :									
SB WI-72-1033 E2	HP TURBINE ROTOR BLADES - INSPECTION			RECOMMENDED			-			N/A
	MOC :									
SB WI-72-1037 E1	R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		CSI CSI			New Req
	MOC :									
SB WI-72-1037 E2	R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		CSI CSI			New Req
	MOC :									
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED	MTH		MPI MPI			New Req
	MOC :									
SB WI-72-1041 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED	MTH		MPI MPI			New Req
	MOC :									
SL WI-72-1080 E1	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1080 E2	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-018 R03 E1	REPLACE INTEGRATED FUEL CONTROL UNIT (SUPERSEDED BY FJ44-73-018 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-73-018 R03 E2	REPLACE INTEGRATED FUEL CONTROL UNIT (SUPERSEDED BY FJ44-73-018 R04)	UNK		RECOMMENDED	MTH 09-Jul-2014 HRS 2293:06 LDG 2032		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-018 R04 E1	INTEGRATED FUEL CONTROL UNIT - REPLACE (SUPERSEDED BY FJ44-73-018 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-018 R04 E2	INTEGRATED FUEL CONTROL UNIT - REPLACE (SUPERSEDED BY FJ44-73-018 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-018 R05 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4000	1201:30
MOC :										
SB FJ44-73-018 R05 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-73-130 R03 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT	LFOQ		MANDATORY	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-130 R03 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT	LFOQ		MANDATORY	MTH 07-Mar-2019 HRS 2724:05 LDG 2452		-			Complete
MOC : COMPLIED WITH										
SB WI-73-1004 -CN E1	R02 CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1004 -CN E2	R02 CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1004 E1	R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
MOC :										
SB WI-73-1004 E2	R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
MOC :										
SB WI-73-1004 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
MOC :										
SB WI-73-1004 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-73-1011-CN E1	CANCELED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1011-CN E2	CANCELED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1011 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1011 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1012 E1	ENGINE FUEL AND CONTROL - FCU/FUEL HEATER FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	2201:30
MOC :										
SB WI-73-1012 E2	ENGINE FUEL AND CONTROL - FCU/FUEL HEATER FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5106:30	2308
MOC :										
SB WI-73-1015 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH		CSI CSI			
MOC :										
SB WI-73-1015 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH		CSI CSI			
MOC :										
SB WI-75-1000 E1	AIR - LOOP CLAMP - INSTALL			RECOMMENDED	MTH HRS		DUE DUE DUE		(3997:18)3997:18	1198:48
MOC :										
SB WI-75-1000 E2	AIR - LOOP CLAMP - INSTALL			RECOMMENDED	MTH HRS		DUE DUE DUE		(3998)4104:30	1306
MOC :										
SB WI-75-1002 R01 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1002 R01 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1002 R02 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH		CSI CSI			
MOC :										
SB WI-75-1002 R02 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH		CSI CSI			
MOC :										
SB WI-75-1002 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1002 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
MOC :										
SB 525A-78-02 R01	THRUST ATTENUATOR PADDLE IMPROVEMENT			MTH MANDATORY	25-Mar-2010 1501		-			Complete
MOC : COMPLIED WITH										
ASL 525A-78-01 78SLA01	THRUST ATTENUATOR PADDLE INSPECTION	LSZR		MTH MANDATORY	25-Mar-2010 1501 LDG 1497		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-79-02 79SB-02	ENGINE GEARBOX BREATHER LINE INSTALLATION			MTH DISCRETIONARY			-			
MOC : - SERVICE BULLETIN ON HOLD.										
SB FJ44-79-007 R04 E1	ENGINE - LUBE PUMP - REWORK TO P/N 110487			RECOMMENDED			-			
MOC :										
SB FJ44-79-007 R04 E2	ENGINE - LUBE PUMP - REWORK TO P/N 110487			RECOMMENDED			-			
MOC :										
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		MPI MPI MPI		(4000)4000	1201:30
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		MPI MPI MPI		(4000)4106:30	1308
MOC :										
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-012 R01 E2	OIL - LUBE OIL COOLER - REWORK OR REPLACE			MTH RECOMMENDED			DUE DUE DUE		(3998)4104:30	1306
MOC :										
SB FJ44-79-012 E2	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1999-08-21 35AD-01 : 525	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEMS CO. ICT		MANDATORY	MTH 12-Jun-2002 HRS 12		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY DATE OF MANUFACTURE									
FAA 2001-23-17 34AD-03	APPLIANCE AD - GARMIN GNS 430 ICT		MANDATORY	MTH 12-Jun-2002 HRS 12		A/R			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED									
FAA 2003-13-08 34AD-01	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS HUR		MANDATORY	MTH 21-Jul-2003 HRS 173		A/R			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED									
FAA 2004-08-15 34AD-02	TAWS 8000 TERRAIN AWARENESS HUR		MANDATORY	MTH 01-Apr-2004 HRS 303		A/R			N/A
MOC : NOT APPLICABLE - TAWS 8000 NOT FITTED									
FAA 2017-06-03	APPLIANCE AD - HEATING SYSTEM - ACCOMPLISH REPETATIVE DETAILED INSPECTIONS AND PRESSURE DECAY TESTS OF THE COMBUSTION HEATER AND DISABLE / REMOVE IF NECESSARY		MANDATORY	MTH 06-Apr-2017		-			N/A
MOC : NOT APPLICABLE - THERE IS NO COMBUSTION CABIN HEATER FITTED ON THIS A/C									
EASA 2005-0021 23AD-15	EASA AD2005-0021 HUR			MTH 08-Nov-2005 HRS 570		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT		MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED WITH CVR									
EASA 2012-0038	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEAT BACKREST LINK - INSPECTION / REPLACEMENT		EASA	MTH 06-Aug-2013		-			N/A
MOC : NOT APPLICABLE - N/A BY TYPE INSTALLED									
EASA 2013-0020 R01	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	LEVC	MANDATORY	MTH 05-Jun-2013 HRS 2084:30 LDG 1893		-			Complete
MOC : COMPLIED WITH									
EASA 2013-0020 R02	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT		MANDATORY	MTH 07-Oct-2013		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY ACCOMPLISHED BY REV 1 ON 5 JUNE 2013									
EASA 2013-0020 R03 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER		MANDATORY	MTH 30-Apr-2014		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH BY REVISION 1									
EASA 2013-0020 R03	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT		MANDATORY	MTH 30-Apr-2014		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH BY REVISION 1									
EASA 2013-0020 R04 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER		MANDATORY	MTH 13-Nov-2014		DUE DUE			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH BY REVISION 1									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY	MTH 13-Nov-2014		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH BY REVISION 1										
EASA 2013-0020	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINTS SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY	MTH 05-Jun-2013		-			Complete
MOC : COMPLIED WITH - C/W AD REV 1										
EASA 2014-0019	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY EASA 2014-0095)			MANDATORY	MTH 30-Apr-2014		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED										
EASA 2014-0095 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED										
EASA 2014-0095	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED										
EASA 2014-0125	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT; AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED										
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / REPLACEMENT			MANDATORY	MTH 12-Dec-2014 HRS 2314:30 LDG 2046		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT EQUIPPED WITH AFFECTED SEATS										
EASA 2014-0279	APPLIANCE AD - EQUIPMENT / FURNISHING - RESTRAINT SYSTEM ROTARY BUCKLE SUBASSEMBLY - IDENTIFICATION / REPLACEMENT			MANDATORY	MTH 30-Jan-2015 HRS 2325:45 LDG 2060		-			N/A
MOC : NOT APPLICABLE - BY TYPE										
EASA 2016-0210	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT			MANDATORY	MTH 08-Nov-2016		-			N/A
MOC : NOT APPLICABLE - DUE TO PILOTS SEAT										
EASA 2016-0256	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOT SEATS - MODIFICATION (SUPERSEDED BY EASA AD 2018-0262)			MANDATORY	MTH 20-Apr-2017 HRS 2548:40 LDG 2280		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED										
EASA 2017-0001	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION			MANDATORY	MTH 01-Feb-2017		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT FITTED WITH CABIN ATTENDANT SEATS										
EASA 2017-0225	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEMS - AFM AMENDMENT / MODIFICATION			MANDATORY	MTH 19-Mar-2018 HRS 2639:40 LDG 2367		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT EQUIPPED WITH AFFECTED RESTRAINT SYSTEM MODEL										



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT	LFBO	MANDATORY	MTH 09-Oct-2019 HRS 2772:45 LDG 2496		-			N/A
	MOC : NOT APPLICABLE - RECORD REVIEWED AND FOUND THAT THE INSTALLED ELT WAS THE ORIGINAL ONE THAT WAS FITTED NEW AT FACTORY. THIS EQUIPMENT HAS NEVER BEEN INSTALLED IN AN HELICOPTER. IN ADDITION, THE -999 PART NUMBER IS SPECIFIC TO CESSNA FIWED WING APPLICATIONS								
FAA 2012-08-07	SICMA AERO SEAT PASSENGER SEAT ASSEMBLIES			MTH 06-Aug-2013		-			N/A
	MOC : NOT APPLICABLE - AIRCRAFT NOT EQUIPPED WITH AFFECTED SEAT ASSEMBLIES								
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS		MANDATORY	MTH 21-Jun-2017		-			N/A
	MOC : NOT APPLICABLE - DUE TO PASSENGERS SEATS FITTED								
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS		MANDATORY	MTH 25-Sep-2017		-			N/A
	MOC : NOT APPLICABLE - DUE TO ELT FITTED								
EASA 2012-0037	APPLIANCE AD - HAND FIRE EXT.			MTH 06-Aug-2013		-			N/A
	MOC : NOT APPLICABLE - N/A BY P/N								
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT		MANDATORY	MTH 01-Apr-2016 HRS 2442:45 LDG 2179		-			N/A
	MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - AIRCRAFT NOT EQUIPPED WITH AFFECTED EQUIPMENT								
FAA 2005-17-11 26AD-02	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES	HUR	MANDATORY	MTH 12-Jan-2006 HRS 599		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.								
FAA 2017-19-05	APPLIANCE AD - APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT		MANDATORY	MTH 27-Sep-2017		-			N/A
	MOC : NOT APPLICABLE - NO SMOKE DETECTOR FITTED ON A/C								
EASA 2019-0086 R01	FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - AFFECTED STC NOT INSTALLED								
EASA 2019-0086-E	APPLIANCE/EMERGENCY AD - FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT		MANDATORY	MTH 13-Jun-2019		-			N/A
	MOC : NOT APPLICABLE - AFFECTED STC NO INSTALLED								
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT		MANDATORY			-			N/A
	MOC : NOT APPLICABLE - AFFECTED STC NOT INSTALLED								



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION		MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED									
FAA 1998-25-02 34AD-02 : 525	APPLIANCE AD - NAVIGATION - BFGOODRICH SKYWATCH SKY497 - INCORPORATE INFORMATION INTO THE AFM THAT SPECIFIES VERIFYING CORRECT ANTENNA CONFIGURATION EACH TIME AIRCRAFT EQUIPPED WITH A TOP-MOUNTED ANTENNA IS POWERED-UP		MANDATORY	MTH 12-Jun-2002 HRS 12		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT PART NUMBER.									
FAA 2002-20-09 31AD-01	APPLIANCE AD - NAVIGATION - COLLINS AFD-3010 AFD UNITS - INSPECT AND MODIFY CERTAIN AFD-3010 AFD UNITS	HUR	MANDATORY	MTH 06-Jan-2003 HRS 100		A/R			Complete
MOC : COMPLIED WITH									
FAA 2012-02-08	AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS			MTH 06-Aug-2013		-			N/A
MOC : NOT APPLICABLE - N/A BY EQUIPMENT INSTALLED									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH 13-Nov-2014		-			N/A
MOC : NOT APPLICABLE - A/C NOT EQUIPED									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.		MANDATORY			-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY	MTH 03-Jun-2015		DUE DUE			N/A
MOC : NOT APPLICABLE - N/A BY TYPE OF EQUIPMENT									
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS		MANDATORY	MTH 19-Mar-2018 HRS 2639:40 LDG 2367		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED									
FAA 2018-03-04	NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC		MANDATORY	MTH 14-Mar-2018 HRS 2639:40 LDG 2367		-			N/A
MOC : NOT APPLICABLE - PART CANNOT BE FITTED IN ACCORDANCE WITH IPC									
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS		MANDATORY	MTH 10-Jun-2020		N/A			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT EQUIPPED WITH COLLINS FMS									
EASA 2011-0090 R1	APPLIANCE AD - OXYGEN <i>iii</i> OXYGEN MASK REGULATOR INFLATABLE HARNESS <i>iii</i> IDENTIFICATION / REPLACEMENT			MTH 19-Feb-2013 HRS 1997:18 LDG 1843		-			Complete
MOC : COMPLIED WITH - ATLAS AG BREMEN									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT	EGPK	MANDATORY	MTH 16-Jan-2013 HRS 1997:18 LDG 1843		-			N/A
MOC : NOT APPLICABLE - N/A BY PART NUMBER									
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT		MANDATORY	MTH 06-Aug-2013		-			N/A
MOC : NOT APPLICABLE - N/A BY P/N									
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT		MANDATORY	MTH 12-Dec-2014 HRS 2314:30 LDG 2046		-			N/A
MOC : NOT APPLICABLE									
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT		MANDATORY	MTH 01-Apr-2016 HRS 2442:45 LDG 2179		-			N/A
MOC : NOT APPLICABLE - BY PART NUMBER OF EQUIPMENT INSTALLED									
FAA 2011-04-09	ATA 35 - SUPERSEDED BY 2012-11-09 - NOT ADOPTED BY EASA			MTH 13-Nov-2014 HRS 2314:30 LDG 2046		-			N/A
MOC : NOT APPLICABLE - NOT ADOPTED BY EASA									
FAA 2011-14-08	B/E AEROSPACE CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY	ICT	MANDATORY	MTH 07-Aug-2014 HRS 2293:06 LDG 2032			A/R		Complete
MOC : COMPLIED WITH - ACCOMPLISHED FAA AD 2011-14-08 B/E AEROSPACE CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY, EFFECTIVE DATE AUGUST 19, 2011.									
FAA 2012-11-09	ATA 35 NOT ADOPTED BY EASA			MTH 13-Nov-2014 HRS 2314:30 LDG 2046		-			N/A
MOC : NOT APPLICABLE - AD NOT ADOPTED BY EASA									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. (SUPERSEDED BY FAA AD 2017-18-12)		MANDATORY	MTH 14-Sep-2016 HRS 2491:40 LDG 2227		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES		MANDATORY	MTH 13-Sep-2017		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT NOT FITTED WITH ANY PBE									
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016		MANDATORY	MTH 20-Apr-2017 HRS 2548:40 LDG 2280		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
<i>FAA 2008-03-10</i> <i>53AD-01</i>	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	SZR	AIRWORTHINESS	MTH 02-May-2008 HRS 1111		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
<i>FAA 2010-12-01</i>	DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS, AND CRACKS IN THRUST ATTENUATOR PADDLES	LSZR	MANDATORY	MTH 25-Mar-2010 HRS 1501 LDG 1497		A/R			Complete
MOC : COMPLIED WITH									
<i>FAA 2009-24-13</i> <i>78AD-01</i>	DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS AND CRACKS IN THE THRUST ATTENUATOR PADDLES - SUPERSEDED BY AD 2010-12-01	LSZR	SUPERSEDED	MTH 25-Mar-2010 HRS 1501 LDG 1497		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **GEIE AIR LAVO**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0082**
 Unit: **0082** Reg No: **LX-JCL**
 Airworthiness: **12-Jun-2002**
 Print Date: **24-Jun-2020 6:21AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2798:30	2519	25-Feb-2020	0:05
ENG 1	2798:30	2519	25-Feb-2020	0:05
ENG 2	2692	2478	25-Feb-2020	0:05
AIR COND	811:24		25-Feb-2020	0:54

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
24FO186K <i>24FO186 : K</i>	BATTERY-44A HOUR FACTORY OPTION	*CF		186K FO	MTH 12-Jun-2002		-			
25FO122T <i>25FO122 : T</i>	COAT ROD, AFT FLUSH MOUNTED RETRACTABLE FACTORY OPTION	*CF		122T FO	MTH 12-Jun-2002		-			
25FO130D <i>25FO130 : D</i>	TOLIET, FLUSHING-LH BELTED FACTORY OPTION	*CF		130D FO	MTH 12-Jun-2002		-			
25FO50G <i>25FO50 : G</i>	LIGHTING-INDIRECT FACTORY OPTION	*CF		50G FO	MTH 12-Jun-2002		-			
25FO720C	VINYL W/CENTER COAT ROD FACTORY OPTION	*CF		720C FO	MTH 12-Jun-2002		-			
25FO728D	BEIGE COLORED CKP & CBN DR TRM FACTORY OPTION	*CF		728D FO	MTH 12-Jun-2002		-			
28FO-36	FUEL CAPS-LOCKING FACTORY OPTION	*CF		36 FO	MTH 12-Jun-2002		-			
34FO677	RVSM FOR STANDARD PACKAGE NON COPILOTS DISPLAY OPTION FACTORY OPTION	*CF		677 FO	MTH 12-Jun-2002		-			
34FO691B <i>34FO691 : B</i>	EGPWS-AMERICAN DATA BASE FACTORY OPTION	*CF		691B FO	MTH 12-Jun-2002		-			
34FO697E <i>34FO697 : E</i>	UNS-1K GPS-W/PERMANENT DTU FACTORY OPTION	*CF		697E FO	MTH 12-Jun-2002		-			
77FO680	N1 COMPUTER-SAFE FLIGHT FACTORY OPTION	*CF		680 FO	MTH 12-Jun-2002		-			